

APPENDIX



AUBURNDALE

Streets | Terraces



Looking West - SW 27th Avenue



Looking West - SW 29th Avenue



Looking East - SW 37th Avenue



Looking West - SW 33rd Avenue



Looking East - SW 29th Avenue



Looking West - SW 30th Court



Looking West- SW 32nd Avenue



Looking West - SW 27th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 1st Street	3	Auburndale	4	60	2800	No	No	Yes	2	City	Yes	Yes	10	Some	Some	Both sides, mainly south	Smaller street has no curbs,sidewalks,or swales. Gravel swales
SW 2nd Street	3	Auburndale	4	60	5400	No	No	Yes	2	City	Few	Yes	8	Some	Yes	Both sides	Gravel, paved and grass swales.

SW 1st Street
TYPOLOGY C

SW 2nd Street
TYPOLOGY C

Street Tree Inventory

SW 1st Street

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 1ST ST	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 1ST ST	Weeping Fig	31-40"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Limb Damage - Major	Sprouting
SW 1ST ST	Weeping Fig	21-30"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Limb Damage - Major	Sprouting
SW 1ST ST	Weeping Fig	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Moderate	Sprouting
SW 1ST ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 1ST ST	Black Olive	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 1ST ST	Mahogany	31-40"	No	55'	Poor (21% to 40%)		Reduced Canopy - Major	Dead Wood	Decay Observed
SW 1ST ST	Strangler Fig	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 1ST ST	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 1ST ST	Umbrella Tree	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Constricted Roots
SW 1ST ST	Umbrella Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Pygmy Date Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Oriental Arborvitae	16-20"	Yes	15'	Fair (41% to 60%)		Dead Wood	Decay Observed	
SW 1ST ST	Oriental Arborvitae	16-20"	Yes	15'	Fair (41% to 60%)		Dead Wood	Decay Observed	
SW 1ST ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Cavities
SW 1ST ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Restricted Canopy	Dead Wood	
SW 1ST ST	Weeping Fig	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	
SW 1ST ST	Queen Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 1ST ST	Queen Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 1ST ST	Queen Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 1ST ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 1ST ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 1ST ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Royal Poinciana	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Cavities
SW 1ST ST	Powderpuff Tree	1-5"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Powderpuff Tree	1-5"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 1ST ST	Horseradish Tree	11-15"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	
SW 1ST ST	Slash Pine	1-5"	No	5'	Good (61% to 80%)				
SW 1ST ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 1ST ST	Hong Kong Orchid	11-15"	No	15'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 1ST ST	Royal Poinciana	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Dead Wood
SW 1ST ST	Hong Kong Orchid	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 1ST ST	Woman's Tongue	31-40"	No	40'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low	Trunk Damage - Major	Decay Observed
SW 1ST ST	Java Plum	21-30"	No	40'	Poor (21% to 40%)		Reduced Canopy - Moderate	Limb Damage - Major	Sprouting
SW 1ST ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 1st Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 1ST ST	Earleaf Acacia	21-30"	No	10'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Leaning - Major	Sprouting
SW 1ST ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 1ST ST	Coconut Palm	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 1ST ST	Spindle Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 1ST ST	Sea Grape	21-30"	No	25'	Fair (41% to 60%)		Multi-Trunk Form - Not Downgraded for Structure	Stubs with Sprouts	
SW 1ST ST	Weeping Fig	16-20"	No	20'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	Dead Wood
SW 1ST ST	Weeping Fig	16-20"	No	20'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	Dead Wood
SW 1ST ST	Weeping Fig	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 1ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Root Damage/Decay	

SW 2nd Street

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 2ND ST	Live Oak	21-30"	No	45'	Good (61% to 80%)		Trunk Damage - Minor	Dead Wood	Sprouting
SW 2ND ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 2ND ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 2ND ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 2ND ST	Oriental Arborvitae	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Oriental Arborvitae	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 2ND ST	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 2ND ST	Silver Buttonwood	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Sprouting	
SW 2ND ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 2ND ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Nutrient Deficiency
SW 2ND ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 2ND ST	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 2ND ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 2ND ST	Royal Poinciana	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 2ND ST	Pitch Apple	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Restricted Canopy	
SW 2ND ST	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 2ND ST	Lead Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 2ND ST	East Palatka Holly	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Dahoon Holly	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Improperly Mulched	Suppressed Canopy	
SW 2ND ST	Yellow Poinciana	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Utility Pruned	Dead Wood
SW 2ND ST	African Tulip Tree	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Sprouting
SW 2ND ST	Horseflesh Mahogany	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Dead Wood	
SW 2ND ST	Spanish Stopper	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 2ND ST	Pigeon Plum	1-5"	Yes	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Lopsided/Moderately Reduced Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 2nd Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 2ND ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Sprouting
SW 2ND ST	Black Olive	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 2ND ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 2ND ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 2ND ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Minor	Codominant Leaders/Included Bark
SW 2ND ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 2ND ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 2ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Codominant Leaders/Included Bark	Sprouting
SW 2ND ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 2ND ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 2ND ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 2ND ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 2ND ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 2ND ST	Black Olive	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Root Damage/Decay	Reduced Canopy - Major	Sprouting
SW 2ND ST	Live Oak	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 2ND ST	Black Olive	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 2ND ST	Paradise Tree	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Girdling Roots	Trunk Damage - Moderate	Dead Wood
SW 2ND ST	Paradise Tree	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 2ND ST	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 2ND ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 2ND ST	Mahogany	31-40"	No	35'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 2ND ST	Mahogany	16-20"	No	20'	Poor (21% to 40%)	Utility Lines Above	Lopsided/Significantly Reduced Canopy	Sprouting	
SW 2ND ST	Mahogany	21-30"	No	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 2ND ST	Mahogany	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 2ND ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 2ND ST	Mahogany	21-30"	No	15'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 2ND ST	Mahogany	21-30"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	Decay Observed
SW 2ND ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 2ND ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 2ND ST	Peregrina	1-5"	No	5'	Good (61% to 80%)				
SW 2ND ST	Java Bishopwood	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Restricted Canopy	Sprouting
SW 2ND ST	Java Bishopwood	16-20"	No	20'	Poor (21% to 40%)		Basal Co-Dominant	Restricted Canopy	Apical Dieback
SW 2ND ST	Java Bishopwood	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Apical Dieback	Codominant Leaders/No Included Bark
SW 2ND ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 2ND ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting

Streets | Terraces



Looking East - SW 37th Avenue



Looking East - SW 24th Avenue



Looking West - SW 27th Avenue



Looking West - SW 32nd Avenue



Looking East - SW 32nd Court Road



Looking East - SW 29th Avenue



Looking East - SW 33rd Avenue



Looking East - SW 37th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 3rd Street	3	Auburndale	4	60	3800	No	No	Yes	2	City	Few	Few	5	Some	Yes	Both sides, mainly south	Paved and grass swales - Curbs from 34th Ave to 32nd Ave
SW 4th Street	3	Auburndale	4	50	5400	No	No	Yes	2	City	Few	Few	5	No	Yes	South side	Paved Swales

SW 3rd Street

TYPOLOGY C

SW 4th Street

TYPOLOGY B

Street Tree Inventory

SW 3rd Street

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 3RD ST	Live Oak	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 3RD ST	Weeping Fig	31-40"	No	30'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 3RD ST	Weeping Fig	41-50"	No	55'	Poor (21% to 40%)		Reduced Canopy - Moderate	Trunk Damage - Major	Decay Observed
SW 3RD ST	Mahogany	51-60"	No	60'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Dead Wood
SW 3RD ST	Royal Poinciana	21-30"	No	35'	Very Poor/Critical (6% to 20%)		Lopsided/Moderately Reduced Canopy	Trunk Damage - Major	Decay Observed
SW 3RD ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 3RD ST	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 3RD ST	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 3RD ST	Areca Palm	1-5"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major		
SW 3RD ST	Black Olive	16-20"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 3RD ST	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 3RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 3RD ST	Live Oak	41-50"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 3RD ST	Weeping Fig	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 3RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 3RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 3RD ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 3RD ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 3RD ST	Coconut Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 3RD ST	Coconut Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 3RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Coconut Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 3RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Royal Poinciana	31-40"	No	50'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 3RD ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 3RD ST	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 3RD ST	Yellow Poinciana	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Grafted Branches	Dead Wood
SW 3RD ST	Coconut Palm	11-15"	No	5'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Nutrient Deficiency	
SW 3RD ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 3RD ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 3RD ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Reduced Canopy - Minor	
SW 3RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 3RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 3RD ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Bottle Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 3RD ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Fishtail Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 3RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 3RD ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 3RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 3rd Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 3RD ST	Yellow Tabebuia	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Stubs with Sprouts		
SW 3RD ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate	
SW 3RD ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Dead Wood
SW 3RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 3RD ST	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark	Suppressed Canopy	
SW 3RD ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 3RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 3RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 3RD ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 3RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			

SW 4th Street

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Cavities
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Crepe Myrtle	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 4TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 4TH ST	Montgomery Palm	16-20"	Yes	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 4TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Broken Branches
SW 4TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 4TH ST	Mahogany	16-20"	No	35'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 4TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 4TH ST	Mahogany	6-10"	No	15'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Sprouting
SW 4TH ST	Tamarind	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant		
SW 4TH ST	Montgomery Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 4TH ST	Kapok	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 4TH ST	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Sprouting	
SW 4TH ST	Gumbo Limbo	6-10"	No	10'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 4TH ST	Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Solitaire Palm	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 4th Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 4TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned		
SW 4TH ST	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned		
SW 4TH ST	Areca Palm	41-50"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 4TH ST	BV UNID 1	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Leaning - Major	Trunk Damage - Major	Sprouting
SW 4TH ST	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	White Frangipani	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 4TH ST	White Frangipani	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Moderate	Trunk Damage - Major	
SW 4TH ST	Starburst Clerodendron	16-20"	Yes	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	Over Pruned
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Over Pruned	Nutrient Deficiency	
SW 4TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Over Pruned		
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 4TH ST	Royal Poinciana	1-5"	No	15'	Fair (41% to 60%)		Leader - Bent		
SW 4TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Bottle Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Cavities
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Crepe Myrtle	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 4th Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 4TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 4TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 4TH ST	Montgomery Palm	16-20"	Yes	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 4TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Broken Branches
SW 4TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 4TH ST	Mahogany	16-20"	No	35'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 4TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 4TH ST	Mahogany	6-10"	No	15'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Sprouting
SW 4TH ST	Tamarind	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant		
SW 4TH ST	Montgomery Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 4TH ST	Kapok	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 4TH ST	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Sprouting	
SW 4TH ST	Gumbo Limbo	6-10"	No	10'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 4TH ST	Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Solitaire Palm	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned		
SW 4TH ST	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned		
SW 4TH ST	Areca Palm	41-50"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 4TH ST	BV UNID 1	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Leaning - Major	Trunk Damage - Major	Sprouting
SW 4TH ST	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	White Frangipani	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 4TH ST	White Frangipani	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Moderate	Trunk Damage - Major	
SW 4TH ST	Starburst Clerodendron	16-20"	Yes	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	Over Pruned
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Over Pruned	Nutrient Deficiency	
SW 4TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Over Pruned		
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 4th Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 4TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 4TH ST	Royal Poinciana	1-5"	No	15'	Fair (41% to 60%)		Leader - Bent		
SW 4TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		

Streets | Terraces



Looking East - SW 37th Avenue



Looking East - SW 32nd Avenue



Looking East - SW 37th Avenue



Looking East - Between 37th and 36th Avenue



Looking East - SW 30th Avenue



Looking West - SW 27th Avenue



Looking West - SW 36th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 5th Street	3	Auburndale	4	50	5200	No	No	Yes	2	City	Few	Few	5	No	Yes	South side	Roundabout at 31st Ave (Coral Nook Park)
SW 5th Terrace	3	Auburndale	4	50	700	No	No	Yes	2	City	Few	Few	10	No	Yes	South side	Gravel, paved and grass swales.

SW 5th Street

TYPOLOGY B

SW 5th Terrace

TYPOLOGY A

Street Tree Inventory

SW 5th Street

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 5TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	Dead Wood
SW 5TH ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark		
SW 5TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 5TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 5TH ST	Mango	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark		
SW 5TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 5TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 5TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Minor	Trunk Damage - Major	Decay Observed
SW 5TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 5TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 5TH ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 5TH ST	Yellow Tabebuia	1-5"	No	5'	Fair (41% to 60%)		Leader - Bent	Strap Constricting Tree	
SW 5TH ST	Pitch Apple	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 5TH ST	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 5TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Yellow Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Yellow Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 5TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Crepe Myrtle	11-15"	Yes	15'	Good (61% to 80%)				
SW 5TH ST	Gumbo Limbo	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 5TH ST	Jacaranda	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/No Included Bark		
SW 5TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 5TH ST	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 5TH ST	Weeping Fig	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	
SW 5TH ST	Mahogany	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	
SW 5TH ST	Weeping Fig	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 5TH ST	Weeping Fig	11-15"	No	15'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Trunk Damage - Major	Codominant Leaders/No Included Bark
SW 5TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Weeping Fig	21-30"	No	25'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 5TH ST	Weeping Fig	11-15"	No	15'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Trunk Damage - Major	Sprouting
SW 5TH ST	Weeping Fig	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Moderate	Trunk Damage - Major	Sprouting
SW 5TH ST	Weeping Fig	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Minor	Trunk Damage - Moderate	Stubs
SW 5TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 5TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 5th Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Peregrina	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 5TH ST	Peregrina	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Black Olive	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Ficus Growing on Tree
SW 5TH ST	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 5TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 5TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 5TH ST	Neem Tree	21-30"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Ficus Growing on Tree
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Neem Tree	21-30"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Ficus Growing on Tree
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Norfolk Pine	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 5TH ST	Japanese Blueberry	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 5TH ST	Norfolk Pine	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 5TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 5TH ST	Strangler Fig	51-60"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Mahogany	21-30"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 5TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Live Oak	1-5"	No	15'	Poor (21% to 40%)		Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate	
SW 5TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 5TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Restricted Canopy	Sprouting	Codominant Leaders/Included Bark
SW 5TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Decay Observed
SW 5TH ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 5TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Root Damage/Decay
SW 5TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 5th Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH ST	Weeping Fig	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Dead Wood	
SW 5TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Dead Wood
SW 5TH ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 5TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			

SW 5th Terrace

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 5TH TER	Slash Pine	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH TER	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 5TH TER	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 5TH TER	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 5TH TER	Crepe Myrtle	11-15"	Yes	15'	Good (61% to 80%)				
SW 5TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor	Strap Constricting Tree	Stubs
SW 5TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH TER	Strangler Fig	51-60"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH TER	Umbrella Tree	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant with Adjacent Tree(s)	Suppressed Canopy	Codominant Leaders/Included Bark
SW 5TH TER	Black Olive	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Significantly Reduced Canopy	Basal Co-Dominant with Adjacent Tree(s)	
SW 5TH TER	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy		
SW 5TH TER	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy		
SW 5TH TER	Christmas Palm	31-40"	Yes	15'	Good (61% to 80%)	Utility Lines Above			

Streets | Terraces



Looking West - SW 27th Avenue



Looking East - SW 32nd Avenue



Looking West - SW 27th Avenue



Looking East - SW 32nd Avenue



Looking East - SW 35th Avenue



Looking West - SW 36th Court



Looking East - SW 34th Avenue



Looking East - SW 37th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 6th Street	3	Auburndale	4	55	5200	No	No	Yes	2	City	Yes	Few	10	No	Yes	South side	Roundabout at 31st Ave, Large trees between 31st Ave and 30th Ave
SW 7th Street	3	Auburndale	4	60	5400	No	No	Yes	2	City	Yes	Few	6	Some	Yes	South side	Large Driveways

SW 6th Street

TYPOLOGY A

SW 7th Street

TYPOLOGY C

Street Tree Inventory

SW 6th Street

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 6TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 6TH ST	Live Oak	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 6TH ST	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	Broken Branches
SW 6TH ST	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	Sprouting
SW 6TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 6TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 6TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Cavities
SW 6TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Rubber Tree	51-60"	No	45'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 6TH ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)				
SW 6TH ST	Silver Buttonwood	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Codominant Leaders/Included Bark	
SW 6TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor	Codominant Leaders/Included Bark	
SW 6TH ST	Silver Buttonwood	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Leaning - Major	
SW 6TH ST	Silver Buttonwood	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Uprooted - Mostly	
SW 6TH ST	Silver Buttonwood	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	
SW 6TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Green Buttonwood	1-5"	Yes	5'	Good (61% to 80%)				
SW 6TH ST	Mahogany	41-50"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 6TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 6TH ST	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 6TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 6TH ST	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)	Utility Line Conflict	Disease	Reduced Canopy - Moderate	
SW 6TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 6TH ST	Wax Jasmine	6-10"	Yes	10'	Good (61% to 80%)				
SW 6TH ST	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)				
SW 6TH ST	Wax Jasmine	6-10"	Yes	10'	Good (61% to 80%)				
SW 6TH ST	Starburst Clerodendron	1-5"	Yes	5'	Good (61% to 80%)				
SW 6TH ST	Melaleuca	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Ficus Growing on Tree
SW 6TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 6th Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 6TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 6TH ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 6TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Sprouting	
SW 6TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 6TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 6TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 6TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 6TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Suppressed Canopy		
SW 6TH ST	Mahogany	41-50"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 6TH ST	Black Olive	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 6TH ST	Black Olive	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	
SW 6TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Mahogany	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 6TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 6TH ST	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 6TH ST	Unidentified Dead Tree (Deoliated)	11-15"	No	15'	Dead (0% to 5%)				
SW 6TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	Dead Wood
SW 6TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	Dead Wood
SW 6TH ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 6TH ST	Mahogany	21-30"	No	15'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 6TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 6TH ST	Mahogany	21-30"	No	15'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 6TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 6TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 6TH ST	Black Olive	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 6TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Ficus Growing on Tree		
SW 6TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)		Ficus Growing on Tree		
SW 6TH ST	Live Oak	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	Broken Branches
SW 6TH ST	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Solitaire Palm	11-15"	Yes	5'	Dead (0% to 5%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Mahogany	31-40"	No	35'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 6TH ST	Green Buttonwood	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 6TH ST	Green Buttonwood	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 6TH ST	Green Buttonwood	1-5"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 6TH ST	Green Buttonwood	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 6TH ST	Mahogany	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 6TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		

Street Tree Inventory

SW 7th Street

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 7TH ST	Strangler Fig	51-60"	No	45'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 7TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Trunk Damage - Minor
SW 7TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Restricted Canopy	Root Damage/Decay	Codominant Leaders/Included Bark
SW 7TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Restricted Canopy	Constricted Roots	Codominant Leaders/Included Bark
SW 7TH ST	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 7TH ST	Mahogany	16-20"	No	25'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Stubs
SW 7TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 7TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 7TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 7TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 7TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 7TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 7TH ST	Montgomery Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 7TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 7TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Mahogany	16-20"	No	50'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 7TH ST	Mahogany	16-20"	No	50'	Poor (21% to 40%)		Constricted Roots	Codominant Leaders/Included Bark	Broken Branches
SW 7TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs
SW 7TH ST	Black Olive	16-20"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 7TH ST	Indian Laurel Fig	51-60"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sprouting
SW 7TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Utility Pruned
SW 7TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Utility Pruned
SW 7TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Utility Pruned
SW 7TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Utility Pruned
SW 7TH ST	Weeping Fig	11-15"	Yes	15'	Fair (41% to 60%)		Basal Co-Dominant		
SW 7TH ST	Weeping Fig	11-15"	Yes	15'	Fair (41% to 60%)		Basal Co-Dominant		
SW 7TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 7TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 7TH ST	Weeping Fig	31-40"	No	15'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 7TH ST	Weeping Fig	16-20"	No	10'	Dead (0% to 5%)	Utility Lines Above			
SW 7TH ST	Weeping Fig	21-30"	No	15'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 7TH ST	Weeping Fig	16-20"	No	20'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 7TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 7TH ST	Black Olive	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Major
SW 7TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 7TH ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 7TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 7TH ST	Bottlebrush	16-20"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 7TH ST	Umbrella Tree	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 7TH ST	Lead Tree	16-20"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Dead Wood
SW 7TH ST	Royal Poinciana	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 7TH ST	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 7TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 7th Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 7TH ST	Mahogany	21-30"	No	30'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 7TH ST	Mahogany	21-30"	No	25'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 7TH ST	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 7TH ST	Weeping Fig	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 7TH ST	Weeping Fig	11-15"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub	Dead Wood	
SW 7TH ST	Weeping Fig	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub	Dead Wood	
SW 7TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Royal Poinciana	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor	Codominant Leaders/No Included Bark	
SW 7TH ST	Tamarind	31-40"	No	25'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 7TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 7TH ST	Gumbo Limbo	16-20"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	Dead Wood
SW 7TH ST	Gumbo Limbo	21-30"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Trunk Damage - Major	Decay Observed	Dead Wood
SW 7TH ST	Cinnamon Bark	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Starburst Clerodendron	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Starburst Clerodendron	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Starburst Clerodendron	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Starburst Clerodendron	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Starburst Clerodendron	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 7TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Italian Cypress	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 7TH ST	Frangipani	1-5"	No	10'	Good (61% to 80%)		Damaged Fronds	Fungus on Leaves	
SW 7TH ST	Mahogany	31-40"	No	35'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 7TH ST	Gumbo Limbo	21-30"	No	40'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 7TH ST	Oriental Arborvitae	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Oriental Arborvitae	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 7TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 7TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 7TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 7TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 7TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 7TH ST	Coconut Palm	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Over Pruned	Nutrient Deficiency
SW 7TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 7TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			

(Continued on Next Page)

Street Tree Inventory

SW 7th Street (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 7TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 7TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 7TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 7TH ST	Bottlebrush	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	Constricted Roots
SW 7TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	
SW 7TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor	Sprouting	
SW 7TH ST	Silver Buttonwood	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Strap Constricting Tree	
SW 7TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Girdling Roots	
SW 7TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure	Suppressed Canopy	
SW 7TH ST	Silver Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure	Strap Constricting Tree	
SW 7TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	
SW 7TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 7TH ST	Norfolk Pine	1-5"	No	10'	Good (61% to 80%)				

Bordering Streets



Looking West - SW 27th Avenue



Looking West - SW 31st Avenue



Looking West- SW 27th Avenue




Looking East - SW 29th Avenue



Looking West - SW 32nd Court Road



Looking East - SW 37th Avenue



Looking East- SW 34th Avenue



Looking East - SW 21st Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
W. Flagler Street	3	Auburndale	4	70	5400	Yes	No	No	5	State	Yes	Few	0	Yes	Yes	No	Main street, no bike lanes. Intermittent trees and palms
SW 8th Street	3	Auburndale/ La Pastorita	4	70	5400	No	No	No	4	State	Few	Some	0	Yes	Yes	No	Main street, no bike lanes. Intermittent trees and palms

West Flagler Street

TYPOLOGY I

SW 8th Street

TYPOLOGY E

Street Tree Inventory

West Flagler Street

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
W FLAGLER ST	Live Oak	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy		
W FLAGLER ST	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
W FLAGLER ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
W FLAGLER ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
W FLAGLER ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
W FLAGLER ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
W FLAGLER ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No		Dead (0% to 5%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Minor		
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Minor		
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
W FLAGLER ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
W FLAGLER ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
W FLAGLER ST	Yellow Tabebuia	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood

Street Tree Inventory

SW 8th Street

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 8TH ST	Cabbage Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 8TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Cabbage Palm	11-15"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 8TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)		Over Pruned		
SW 8TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)		Over Pruned		
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned		
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned		
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned		
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned		
SW 8TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)		Over Pruned		
SW 8TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)		Over Pruned		
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				

Avenues | Courts



Looking South - Ponce de Leon Boulevard




Looking North - SW 2nd Street



Looking South - W. Flagler Street



Looking South - SW 3rd Street



Looking South - SW 6th Street



Looking North - SW 8th Street



Looking South - SW 7th Street



Looking North - SW 25th Terrace

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 36th Court	3	Auburndale	4	60-50	1050	No	No	Yes	2	City	Few	Few	10 (btw 6th - 7th Street)	Some	Yes	West side	Gravel, paved and grass swales. 60' ROW and paved on-street parking between SW 2nd St. and Ponce de Leon Blvd
SW 36th Avenue	3	Auburndale	4	60	2700	No	No	Yes	2	City	Some	No	8	No	Yes	West side	Gravel, paved and grass swales.

SW 36th Court

TYPOLOGY C

SW 36th Avenue

TYPOLOGY D

Street Tree Inventory

SW 36th Court

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 36TH CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 36TH CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 36TH CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 36TH CT	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 36TH CT	Royal Palm	21-30"	No	20'	Good (61% to 80%)				
SW 36TH CT	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 36TH CT	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Limb Damage - Moderate	Dead Wood	Sprouting
SW 36TH CT	Date Palm	16-20"	No	30'	Good (61% to 80%)				
SW 36TH CT	Date Palm	16-20"	No	25'	Good (61% to 80%)				
SW 36TH CT	Date Palm	16-20"	No	25'	Good (61% to 80%)				
SW 36TH CT	Date Palm	16-20"	No	25'	Good (61% to 80%)				
SW 36TH CT	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 36TH CT	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 36TH CT	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 36TH CT	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 36TH CT	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 36TH CT	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 36TH CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 36TH CT	Peregrina	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		

SW 36th Avenue

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 36TH AVE	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Trunk Damage - Moderate
SW 36TH AVE	Black Olive	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	Sprouting
SW 36TH AVE	Black Olive	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 36TH AVE	Black Olive	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Utility Pruned
SW 36TH AVE	Black Olive	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Uprooted - Mostly	Crown Density - Excessive (Due to Epicormic Growth)
SW 36TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 36TH AVE	Avocado	21-30"	No	35'	Poor (21% to 40%)		Suppressed Canopy	Cavities	Ficus Growing on Tree
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Poor (21% to 40%)		Over Pruned		
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Poor (21% to 40%)	Utility Lines Above	Over Pruned		
SW 36TH AVE	Sapodilla	16-20"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Dead Wood	
SW 36TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Live Oak	1-5"	No	10'	Poor (21% to 40%)	Utility Lines Above	Basal Co-Dominant		
SW 36TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Mahogany	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 36TH AVE	Umbrella Tree	6-10"	No	15'	Fair (41% to 60%)		Suppressed Canopy		
SW 36TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 36TH AVE	Mahogany	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 36TH AVE	Mahogany	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 36TH AVE	Mahogany	41-50"	No	60'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 36TH AVE	Mahogany	41-50"	No	55'	Poor (21% to 40%)		Constricted Roots	Stubs	Dead Wood

Avenues | Courts



Looking South - W. Flagler Street



Looking South - SW 4th Street



Looking South - W. Flagler Street



Looking North - SW 4th Street



Looking South - SW 6th Street



Looking North - SW 8th Street



Looking North - SW 6th Street



Looking North - SW 8th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 35th Avenue	3	Auburndale	4	60-50	2700	No	No	Yes	2	City	Few	Few	8	No	Yes	West side	Gravel, paved and grass swales. 60' ROW between W Flagler and SW 2nd St.
SW 34th Avenue	3	Auburndale	4	55-50	2700	No	No	Yes	2	City	Yes	Few	8	No	Yes	Both sides, mainly west	Gravel, paved and grass swales. ROW 55 between W Flagler and SW 4th St.

SW 35th Avenue

TYPOLOGY C

SW 34th Avenue

TYPOLOGY C

Street Tree Inventory

SW 35th Avenue

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 35TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 35TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 35TH AVE	Umbrella Tree Sp.	1-5"	No	5'	Good (61% to 80%)				
SW 35TH AVE	Solitaire Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 35TH AVE	Solitaire Palm	1-5"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major		
SW 35TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 35TH AVE	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				

SW 34th Avenue

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 34TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Cabbage Palm	16-20"	No	15'	Good (61% to 80%)	Utility Lines Above	Ficus Growing on Tree		
SW 34TH AVE	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Codominant Leaders/Included Bark
SW 34TH AVE	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 34TH AVE	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 34TH AVE	Spanish Stopper	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Leaning - Moderate	Strap Constricting Tree
SW 34TH AVE	Spanish Stopper	1-5"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 34TH AVE	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH AVE	Tropical Almond	11-15"	No	30'	Fair (41% to 60%)		Trunk Damage - Moderate	Sprouting	
SW 34TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 34TH AVE	Hong Kong Orchid	11-15"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 34TH AVE	Live Oak	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Over Pruned	Sprouting
SW 34TH AVE	Weeping Fig	16-20"	No	15'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Dead Wood	Decay Observed
SW 34TH AVE	Indian Laurel Fig	31-40"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 34TH AVE	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 34TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Over Pruned		
SW 34TH AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)	Utility Lines Above	Over Pruned		
SW 34TH AVE	Weeping Fig	21-30"	No	45'	Poor (21% to 40%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy	Dead Wood	Constricted Roots
SW 34TH AVE	Weeping Fig	31-40"	No	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Lopsided/Significantly Reduced Canopy	Dead Wood	Constricted Roots
SW 34TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Norfolk Pine	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	
SW 34TH AVE	Mango	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 34TH AVE	Sapodilla	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 34TH AVE	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Girdling Roots	
SW 34TH AVE	Pink Tabebuia	16-20"	No	30'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 34TH AVE	Mahogany	11-15"	No	30'	Good (61% to 80%)	Utility Lines Above	Girdling Roots	Reduced Canopy - Major	Sprouting
SW 34TH AVE	Umbrella Tree	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Limb Damage - Moderate	Sprouting	
SW 34TH AVE	Mahogany	16-20"	No	30'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 34TH AVE	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Stubs	Sprouting
SW 34TH AVE	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 34TH AVE	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Limb Damage - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 34TH AVE	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Limb Damage - Moderate	Stubs with Sprouts	Dead Wood
SW 34TH AVE	Silver Buttonwood	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 34th Avenue (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 34TH AVE	Silver Buttonwood	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	Sprouting
SW 34TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 34TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 34TH AVE	Solitaire Palm	11-15"	Yes	20'	Good (61% to 80%)				
SW 34TH AVE	Solitaire Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 34TH AVE	Umbrella Tree	31-40"	No	20'	Poor (21% to 40%)		Basal Co-Dominant	Trunk Damage - Moderate	Sprouting
SW 34TH AVE	Christmas Palm	11-15"	Yes	20'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				

Avenues | Courts



Looking South - W. Flagler Street



Looking South - SW 23rd Street



Looking South - W. Flagler Street



Looking South - SW 2nd Street



Looking South - SW 25th Street



Looking South - SW 8th Street



Looking North - SW 4th Street



Looking North - SW 6th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 33rd Avenue	3	Auburndale	4	70-50	2700	Yes	No	Yes	2	City	Yes	Few	8	Yes	Yes	West side	Medians with trees between 3rd st. to 8th st.. 70' ROW in areas with, median
SW 32nd Avenue	3	Auburndale	4	50	2700	No	No	Yes	2	City	Yes	Few	6	Some	Yes	West side	Large trees between 4th st. and 2nd st.

SW 33rd Avenue

TYPOLOGY G/B

SW 32nd Avenue

TYPOLOGY A

Street Tree Inventory

SW 33rd Avenue

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 33RD AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD AVE	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 33RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Tropical Almond	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Disease (Leaf Spots)		
SW 33RD AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 33RD AVE	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 33RD AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 33RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 33RD AVE	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 33RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 33RD AVE	Key Lime Tree	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Basal Co-Dominant		
SW 33RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD AVE	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 33RD AVE	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 33RD AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 33RD AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 33RD AVE	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 33RD AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 33RD AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Over Pruned		
SW 33RD AVE	Tamarind	21-30"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 33RD AVE	Tamarind	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 33RD AVE	Tamarind	16-20"	No	40'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Dead Wood	
SW 33RD AVE	Tamarind	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	Epicormic Growth
SW 33RD AVE	Tamarind	16-20"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 33RD AVE	Tamarind	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	Sprouting
SW 33RD AVE	Tamarind	16-20"	No	30'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Crown Density - Low	Dead Wood
SW 33RD AVE	Tamarind	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Epicormic Growth	
SW 33RD AVE	Tamarind	16-20"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Broken Branches	
SW 33RD AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Queen Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Tamarind	16-20"	No	30'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood	Codominant Leaders/Included Bark
SW 33RD AVE	Tamarind	16-20"	No	30'	Good (61% to 80%)		Epicormic Growth	Dead Wood	Codominant Leaders/Included Bark
SW 33RD AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 33RD AVE	Tamarind	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Sprouting	
SW 33RD AVE	Live Oak	16-20"	No	30'	Poor (21% to 40%)		Trunk Damage - Major	Restricted Canopy	Sprouting
SW 33RD AVE	Tamarind	11-15"	No	25'	Fair (41% to 60%)		Suppressed Canopy	Codominant Leaders/Included Bark	Sprouting
SW 33RD AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Cavities
SW 33RD AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Sprouting
SW 33RD AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 33RD AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 33RD AVE	Queen Palm	16-20"	Yes	25'	Good (61% to 80%)				
SW 33RD AVE	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 33RD AVE	Queen Palm	11-15"	No	25'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 33rd Avenue (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 33RD AVE	Weeping Fig	6-10"	Yes	15'	Fair (41% to 60%)		Basal Co-Dominant		
SW 33RD AVE	Weeping Fig	1-5"	No	10'	Good (61% to 80%)				
SW 33RD AVE	Sapodilla	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Stubs	Dead Wood
SW 33RD AVE	Sapodilla	16-20"	No	40'	Fair (41% to 60%)		Plunged	Stubs	Dead Wood
SW 33RD AVE	Sapodilla	16-20"	No	40'	Good (61% to 80%)		Stubs	Dead Wood	Codominant Leaders/No Included Bark
SW 33RD AVE	Sapodilla	16-20"	No	35'	Good (61% to 80%)		Stubs	Dead Wood	Codominant Leaders/No Included Bark
SW 33RD AVE	Sapodilla	11-15"	No	25'	Poor (21% to 40%)		Trunk Damage - Moderate	Leader - Broken	Dead Wood
SW 33RD AVE	Sapodilla	16-20"	No	35'	Poor (21% to 40%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Galls
SW 33RD AVE	Sapodilla	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 33RD AVE	Sapodilla	16-20"	No	35'	Poor (21% to 40%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Sloughing Bark
SW 33RD AVE	Weeping Fig	51-60"	No	50'	Poor (21% to 40%)		Constricted Roots	Stubs	Dead Wood
SW 33RD AVE	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 33RD AVE	Black Olive	11-15"	No	35'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 33RD AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 33RD AVE	Black Olive	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Sprouting
SW 33RD AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	
SW 33RD AVE	Black Olive	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Suppressed Canopy	Constricted Roots	
SW 33RD AVE	Black Olive	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 33RD AVE	Sapodilla	16-20"	No	30'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Dead Wood

SW 32nd Avenue

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 32ND AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 32ND AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 32ND AVE	Christmas Palm	16-20"	Yes	10'	Good (61% to 80%)				
SW 32ND AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 32ND AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 32ND AVE	Black Olive	41-50"	No	50'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 32ND AVE	Black Olive	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 32ND AVE	Black Olive	41-50"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 32ND AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 32ND AVE	Black Olive	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 32ND AVE	Black Olive	21-30"	No	30'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 32ND AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 32ND AVE	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 32ND AVE	Starburst Clerodendron	1-5"	Yes	5'	Good (61% to 80%)				
SW 32ND AVE	Unidentified Dead Tree (Defoliated)	6-10"	No	10'	Dead (0% to 5%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 32nd Avenue (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 32ND AVE	Norfolk Pine	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	
SW 32ND AVE	Norfolk Pine	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	
SW 32ND AVE	Norfolk Pine	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	
SW 32ND AVE	Hong Kong Orchid	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	
SW 32ND AVE	Mahogany	31-40"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 32ND AVE	Mahogany	21-30"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 32ND AVE	Mahogany	21-30"	No	35'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 32ND AVE	Mahogany	21-30"	No	35'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 32ND AVE	Mahogany	31-40"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 32ND AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 32ND AVE	Mahogany	41-50"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 32ND AVE	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Major
SW 32ND AVE	Mahogany	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Broken Branches
SW 32ND AVE	Mahogany	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Ficus Growing on Tree

Avenues | Courts



Looking South - W. Flagler Street



Looking South - Between W. Flagler and 2nd Street



Looking South - W. Flagler Street



Looking South - SW 4th Street



Looking South - SW 2nd Street



Looking North - SW 4th Street



Looking North - SW 5th Street



Looking North - SW 8th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 31st Court	3	Auburndale	4	50	2700	No	No	Yes	2	City	Yes	Yes	10	No	Yes	West side	Medians with trees between 3rd st. to 8th st.. 70' ROW in areas with, median
SW 31st Avenue	3	Auburndale	4	50	2700	No	No	Yes	2	City	Few	Few	10	No	Yes	Both sides	Gravel, paved, and grass swales

SW 31st Court

TYPOLOGY C

SW 31st Avenue

TYPOLOGY C

Street Tree Inventory

SW 31st Court

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 31ST CT	Fishtail Palm	31-40"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 31ST CT	Coconut Palm	21-30"	Yes	25'	Good (61% to 80%)	Utility Line Conflict	Over Pruned		
SW 31ST CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST CT	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 31ST CT	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate		
SW 31ST CT	Weeping Fig	31-40"	No	35'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed

SW 31st Avenue

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 31ST AVE	Sapodilla	16-20"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Root Damage/Decay	Codominant Leaders/Included Bark
SW 31ST AVE	Sapodilla	11-15"	No	30'	Fair (41% to 60%)		Girdling Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Minor
SW 31ST AVE	Sapodilla	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Sprouting
SW 31ST AVE	Sapodilla	11-15"	No	25'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	Sprouting
SW 31ST AVE	Sapodilla	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Root Damage/Decay
SW 31ST AVE	Sapodilla	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Minor	Utility Pruned	Root Damage/Decay
SW 31ST AVE	Sapodilla	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Root Damage/Decay	Sprouting
SW 31ST AVE	Sapodilla	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Codominant Leaders/Included Bark	Lopsided/Moderately Reduced Canopy
SW 31ST AVE	Tamarind	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 31ST AVE	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Broken Branches	Sprouting
SW 31ST AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Weeping Fig	6-10"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 31ST AVE	Weeping Fig	1-5"	Yes	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 31ST AVE	Weeping Fig	1-5"	Yes	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 31ST AVE	Pygmy Date Palm	1-5"	No	10'	Good (61% to 80%)				
SW 31ST AVE	Umbrella Tree	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Sprouting
SW 31ST AVE	Umbrella Tree	16-20"	No	15'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 31ST AVE	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Minor	Codominant Leaders/Included Bark	Sprouting
SW 31ST AVE	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)				
SW 31ST AVE	Christmas Palm	21-30"	Yes	20'	Good (61% to 80%)				
SW 31ST AVE	Weeping Fig	11-15"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 31ST AVE	Weeping Fig	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 31ST AVE	Weeping Fig	11-15"	No	20'	Good (61% to 80%)		Suppressed Canopy	Codominant Leaders/Included Bark	
SW 31ST AVE	Weeping Fig	16-20"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Stubs	Sprouting
SW 31ST AVE	Neem Tree	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Apical Dieback	Trunk Damage - Major	Sprouting
SW 31ST AVE	Jacaranda	16-20"	No	20'	Very Poor/Critical (6% to 20%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 31ST AVE	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 31ST AVE	Mahogany	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 31ST AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 31ST AVE	Royal Poinciana	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 31ST AVE	Southern Magnolia	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 31ST AVE	Southern Magnolia	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 31ST AVE	African Tulip Tree	41-50"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 31ST AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				

Avenues | Courts



Looking South - W. Flagler Street



Looking South - SW 1st Street



Looking South - W. Flagler Street



Looking South - SW 4th Street



Looking South - SW 2nd Street



Looking North - End of Road South of 2nd Street



Looking South - SW 6th Street



Looking North - SW 8th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 30th Court	3	Auburndale	4	50	1300	No	No	Yes	2	City	Yes	Few	8	Some	Yes	West side	Gravel, paved and grass swales.
SW 30th Avenue	3	Auburndale	4	50	2700	No	No	Yes	2	City	Yes	Few	10	No	Yes	Both sides	Gravel, paved, and grass swales. Large trees between 2nd street and w... Flagler st.. and between 4th st. and 5th st.. and between 2nd st.. and Flagler. Large rocks on swale at the corner of SW 7th street.

SW 30th Court

TYPOLOGY C

SW 30th Avenue

TYPOLOGY C

Street Tree Inventory

SW 30th Court

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 30TH CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict			
SW 30TH CT	Black Olive	16-20"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Sprouting
SW 30TH CT	Mango	21-30"	Yes	25'	Poor (21% to 40%)		Basal Co-Dominant	Constricted Roots	Lopsided/Moderately Reduced Canopy
SW 30TH CT	Canary Island Date Palm	16-20"	Yes	25'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 30TH CT	Sapodilla	16-20"	No	30'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Sprouting	
SW 30TH CT	Java Plum	21-30"	No	35'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Sprouting
SW 30TH CT	Pongam	21-30"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 30TH CT	Java Plum	31-40"	No	45'	Poor (21% to 40%)		Reduced Canopy - Moderate	Limb Damage - Major	Sprouting
SW 30TH CT	Java Plum	21-30"	No	45'	Poor (21% to 40%)		Reduced Canopy - Moderate	Limb Damage - Major	Sprouting
SW 30TH CT	Java Plum	21-30"	No	35'	Poor (21% to 40%)		Reduced Canopy - Moderate	Limb Damage - Major	Sprouting
SW 30TH CT	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Restricted Canopy	Sprouting	
SW 30TH CT	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Restricted Canopy	Dead Wood	Sprouting
SW 30TH CT	Java Plum	31-40"	No	35'	Poor (21% to 40%)		Reduced Canopy - Moderate	Limb Damage - Major	Sprouting
SW 30TH CT	Java Plum	31-40"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Limb Damage - Major	Sprouting
SW 30TH CT	Java Plum	31-40"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Limb Damage - Major	Sprouting
SW 30TH CT	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs	Sprouting
SW 30TH CT	Black Olive	6-10"	No	15'	Poor (21% to 40%)		Suppressed Canopy	Codominant Leaders/Included Bark	Sprouting
SW 30TH CT	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Suppressed Canopy	Codominant Leaders/Included Bark	Girdling Roots
SW 30TH CT	Java Plum	31-40"	No	35'	Poor (21% to 40%)		Reduced Canopy - Moderate	Limb Damage - Major	Sprouting
SW 30TH CT	Java Plum	21-30"	No	30'	Poor (21% to 40%)		Reduced Canopy - Moderate	Limb Damage - Major	Sprouting
SW 30TH CT	Java Plum	31-40"	No	35'	Poor (21% to 40%)		Reduced Canopy - Moderate	Limb Damage - Major	Sprouting
SW 30TH CT	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Reduced Canopy - Moderate	Limb Damage - Major	Sprouting
SW 30TH CT	Black Olive	6-10"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Codominant Leaders/Included Bark	Sprouting
SW 30TH CT	Java Plum	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Major	Sprouting
SW 30TH CT	Java Plum	31-40"	No	35'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	Sprouting
SW 30TH CT	Weeping Fig	6-10"	No	15'	Good (61% to 80%)		Pruned Into Shrub		
SW 30TH CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Starburst Clerodendron	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Gumbo Limbo	1-5"		5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 30TH CT	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 30TH CT	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 30TH CT	Coconut Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 30TH CT	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy	Strap Constricting Tree	
SW 30TH CT	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 30TH CT	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 30TH CT	Christmas Palm	6-10"	No	5'	Good (61% to 80%)				
SW 30TH CT	Papaya	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Stubs	Restricted Canopy	
SW 30TH CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 30TH CT	Orange Geiger	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	
SW 30TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 30TH CT	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				

Street Tree Inventory

SW 30th Avenue

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 30TH AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Black Olive	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	
SW 30TH AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Girdling Roots
SW 30TH AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 30TH AVE	Black Olive	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Moderate	Trunk Damage - Major	Decay Observed
SW 30TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 30TH AVE	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Black Olive	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Melaleuca	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Constricted Roots	Reduced Canopy - Major
SW 30TH AVE	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Mahogany	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 30TH AVE	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Christmas Palm	16-20"	No	15'	Good (61% to 80%)				
SW 30TH AVE	Spindle Palm	16-20"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH AVE	Queen Palm	11-15"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Weeping Fig	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 30TH AVE	Desert Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Desert Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned		
SW 30TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 30TH AVE	Weeping Fig	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 30TH AVE	Weeping Fig	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Tropical Almond	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	
SW 30TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 30TH AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 30TH AVE	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Limb Damage - Minor	Codominant Leaders/No Included Bark	
SW 30TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 30TH AVE	Black Olive	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Major
SW 30TH AVE	Black Olive	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 30TH AVE	Umbrella Tree	16-20"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	
SW 30TH AVE	Queen Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 30TH AVE	African Tulip Tree	6-10"	No	15'	Good (61% to 80%)				
SW 30TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 30TH AVE	Mahogany	51-60"	No	60'	Fair (41% to 60%)		Constricted Roots	Root Damage/Decay	Dead Wood
SW 30TH AVE	Green Buttonwood	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Green Buttonwood	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Green Buttonwood	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Green Buttonwood	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Green Buttonwood	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Green Buttonwood	1-5"	Yes	5'	Good (61% to 80%)				

Avenues | Courts



Looking South - SW 4th Street



Looking North - SW 4th Street



Looking South - W. Flagler Street



Looking South - SW 3rd Street



Looking South - SW 6th Street



Looking North - SW 8th Street



Looking South - SW 4th Street



Looking North - SW 8th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 29th Court	3	Auburndale	4	50	1300	No	No	Yes	2	City	Yes	Yes	10	No	Yes	No	Turfblock swale on the South side of 4th st..
SW 29th Avenue	3	Auburndale	4	50	2700	No	No	Yes	2	City	Yes	Yes	10	Some	Yes	West side	Gravel and grass swales.

SW 29th Court

TYPOLOGY C

SW 29th Avenue

TYPOLOGY C

Street Tree Inventory

SW 29th Court

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 29TH CT	Christmas Palm	11-15"	Yes	10'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Moderate	
SW 29TH CT	Christmas Palm	6-10"	No	5'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major		
SW 29TH CT	Rubber Tree	60+"	No	65'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 29TH CT	Coconut Palm	60+"	No	20'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Over Pruned		
SW 29TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 29TH CT	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 29TH CT	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 29TH CT	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 29TH CT	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 29TH CT	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 29TH CT	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 29TH CT	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 29TH CT	Weeping Fig	11-15"	No	15'	Good (61% to 80%)		Pruned Into Shrub		
SW 29TH CT	Weeping Fig	11-15"	Yes	15'	Good (61% to 80%)		Pruned Into Shrub		
SW 29TH CT	Pygmy Date Palm	16-20"	Yes	15'	Good (61% to 80%)		Pruned Into Shrub		
SW 29TH CT	Pygmy Date Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 29TH CT	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 29TH CT	Pink Tabebuia	16-20"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Over Pruned	
SW 29TH CT	Avocado	11-15"	Yes	15'	Poor (21% to 40%)		Basal Co-Dominant		
SW 29TH CT	Gumbo Limbo	11-15"	Yes	20'	Poor (21% to 40%)		Basal Co-Dominant	Trunk Damage - Moderate	
SW 29TH CT	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 29TH CT	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)		Frizzled Fronds	Nutrient Deficiency	Trunk Damage - Minor
SW 29TH CT	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 29TH CT	Black Olive	21-30"	No	15'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH CT	Weeping Fig	16-20"	No	30'	Fair (41% to 60%)		Basal Co-Dominant with Adjacent Tree(s)		
SW 29TH CT	Brazilian Pepper	6-10"	No	10'	Fair (41% to 60%)		Basal Co-Dominant with Adjacent Tree(s)	Suppressed Canopy	
SW 29TH CT	Weeping Fig	6-10"	Yes	10'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Trunk Damage - Major
SW 29TH CT	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Codominant Leaders/No Included Bark	Dead Wood	Trunk Damage - Moderate
SW 29TH CT	Weeping Fig	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Dead Wood	Trunk Damage - Major
SW 29TH CT	Weeping Fig	6-10"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Dead Wood	Trunk Damage - Major
SW 29TH CT	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	
SW 29TH CT	Java Bishopwood	1-5"	No	10'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	
SW 29TH CT	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	Limb Damage - Major
SW 29TH CT	Royal Poinciana	21-30"	No	20'	Dead (0% to 5%)				
SW 29TH CT	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Dead Wood		
SW 29TH CT	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Dead Wood		
SW 29TH CT	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Dead Wood		
SW 29TH CT	Strangler Fig	51-60"	No	55'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	

SW 29th Avenue

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 29TH AVE	Coconut Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Over Pruned		
SW 29TH AVE	Gumbo Limbo	11-15"	No	10'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	
SW 29TH AVE	Gumbo Limbo	11-15"	No	10'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed

(Continued on Next Page)

Street Tree Inventory

SW 29th Avenue (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 29TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Gumbo Limbo	16-20"	Yes	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	
SW 29TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Gumbo Limbo	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 29TH AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 29TH AVE	Gumbo Limbo	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 29TH AVE	Gumbo Limbo	11-15"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 29TH AVE	Umbrella Tree	16-20"	No	10'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 29TH AVE	Christmas Palm	16-20"	Yes	20'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	16-20"	Yes	20'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 29TH AVE	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 29TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 29TH AVE	Weeping Fig	16-20"	No	25'	Fair (41% to 60%)		Restricted Canopy	Trunk Damage - Moderate	Decay Observed
SW 29TH AVE	Weeping Fig	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Stubs	
SW 29TH AVE	Wax Jasmine	1-5"	No	5'	Good (61% to 80%)				
SW 29TH AVE	Java Bishopwood	11-15"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Crown Density - Low	Sloughing Bark
SW 29TH AVE	Umbrella Tree	21-30"	No	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 29TH AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Suppressed Canopy	Stubs with Sprouts	
SW 29TH AVE	Weeping Fig	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 29TH AVE	Black Olive	11-15"	No	5'	Dead (0% to 5%)				
SW 29TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 29TH AVE	Umbrella Tree	16-20"	No	30'	Fair (41% to 60%)		Leaning - Moderate	Suppressed Canopy	
SW 29TH AVE	Weeping Fig	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 29TH AVE	Weeping Fig	31-40"	No	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 29TH AVE	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 29TH AVE	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 29TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 29TH AVE	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 29TH AVE	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 29TH AVE	Fishtail Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Weeping Fig	31-40"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Fishtail Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Fishtail Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Fishtail Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Fishtail Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Strangler Fig	21-30"	No	40'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 29TH AVE	Crepe Myrtle	11-15"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	

Avenues | Courts



Looking South - W. Flagler Street



Looking South - SW 1st Street



Looking South - W. Flagler Street



Looking North - Between W. Flagler Street and SW 36th Court



Looking North - SW 3rd Street



Looking North - SW 36th Court



Looking North - SW 8th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 32th Court Road	3	Auburndale	4	70	1200	Yes	No	Yes	2	City	Yes	Yes	5	No	Yes	North side	No curb around the median and cars parked in median
Ponce de Leon Boulevard	3	Auburndale	4	100	100	Intermittently	No	Yes	4	City	Few	Yes	0	Yes	Yes	East side	Loading zone for stores on the west side of the street between SW 36th Ct and SW 37th Ave. SW 36th Ct intersects the street at an angle with a triangular median seperating the two.

SW 32nd Court Road

TYPOLOGY F

Ponce de Leon Boulevard

TYPOLOGY D

Street Tree Inventory

SW 32nd Court Road

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 32ND CT RD	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 32ND CT RD	Areca Palm	21-30"	No	15'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 32ND CT RD	Areca Palm	21-30"	No	15'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 32ND CT RD	Coconut Palm	11-15"	No	10'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Moderate	Utility Pruned	Nutrient Deficiency
SW 32ND CT RD	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT RD	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 32ND CT RD	Queen Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy	Reduced Canopy - Moderate	
SW 32ND CT RD	Hong Kong Orchid	21-30"	No	20'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	Sprouting
SW 32ND CT RD	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Constricted Roots	Dead Wood
SW 32ND CT RD	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Restricted Canopy	Constricted Roots	Dead Wood
SW 32ND CT RD	Canary Island Date Palm	16-20"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 32ND CT RD	Tamarind	11-15"	No	20'	Fair (41% to 60%)		Epicormic Growth	Dead Wood	
SW 32ND CT RD	Tamarind	11-15"	No	20'	Fair (41% to 60%)		Epicormic Growth	Dead Wood	Trunk Damage - Moderate
SW 32ND CT RD	Tamarind	6-10"	No	20'	Fair (41% to 60%)		Epicormic Growth	Dead Wood	Broken Branches
SW 32ND CT RD	Tamarind	11-15"	No	25'	Fair (41% to 60%)		Epicormic Growth	Dead Wood	
SW 32ND CT RD	Tamarind	6-10"	No	15'	Fair (41% to 60%)		Epicormic Growth	Dead Wood	Trunk Damage - Minor
SW 32ND CT RD	Tamarind	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Epicormic Growth	
SW 32ND CT RD	Tamarind	6-10"	No	20'	Fair (41% to 60%)		Epicormic Growth	Apical Dieback	Constricted Roots
SW 32ND CT RD	Canary Island Date Palm	21-30"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 32ND CT RD	Canary Island Date Palm	21-30"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 32ND CT RD	Canary Island Date Palm	16-20"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 32ND CT RD	Seaside Mahoe	1-5"	Yes	20'	Poor (21% to 40%)		Basal Co-Dominant	Dead Wood	
SW 32ND CT RD	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 32ND CT RD	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 32ND CT RD	Canary Island Date Palm	16-20"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Tapered Trunk	
SW 32ND CT RD	Pink Tabebuia	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 32ND CT RD	Royal Poinciana	6-10"	No	15'	Fair (41% to 60%)		Leader - Bent	Restricted Canopy	
SW 32ND CT RD	Canary Island Date Palm	21-30"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 32ND CT RD	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 32ND CT RD	Brazilian Beauty Leaf	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 32ND CT RD	Willow Bustic	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Epicormic Growth	Dead Wood
SW 32ND CT RD	Jacaranda	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 32ND CT RD	Yellow Poinciana	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	Dead Wood
SW 32ND CT RD	Green Buttonwood	6-10"	Yes	10'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 32ND CT RD	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 32ND CT RD	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 32ND CT RD	Tamarind	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood
SW 32ND CT RD	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Dead Wood
SW 32ND CT RD	Tamarind	11-15"	No	30'	Fair (41% to 60%)		Restricted Canopy	Dead Wood	Codominant Leaders/Included Bark
SW 32ND CT RD	Tamarind	6-10"	No	15'	Very Poor/Critical (6% to 20%)	Utility Lines Adjacent (laterally)	Trunk Damage - Major	Decay Observed	Leaning - Moderate
SW 32ND CT RD	Tamarind	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	
SW 32ND CT RD	Tamarind	11-15"	No	20'	Poor (21% to 40%)		Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 32nd Court Road (Continued)

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 32ND CT RD	Royal Poinciana	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Root Damage/Decay	Sprouting
SW 32ND CT RD	Live Oak	31-40"	No	75'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 32ND CT RD	Areca Palm	21-30"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency	Guy Wire Conflict	
SW 32ND CT RD	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 32ND CT RD	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			

Ponce de Leon Boulevard

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
PONCE DE LEON BLVD	Simpson's Stopper	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
PONCE DE LEON BLVD	Simpson's Stopper	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
PONCE DE LEON BLVD	Simpson's Stopper	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
PONCE DE LEON BLVD	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
PONCE DE LEON BLVD	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
PONCE DE LEON BLVD	Date Palm	16-20"	No	30'	Good (61% to 80%)				
PONCE DE LEON BLVD	Date Palm	16-20"	No	30'	Good (61% to 80%)				
PONCE DE LEON BLVD	Date Palm	16-20"	No	30'	Good (61% to 80%)				
PONCE DE LEON BLVD	Date Palm	16-20"	No	30'	Good (61% to 80%)				

Bordering Avenues



Looking North - SW 8th Street



Looking North - SW 4th Street



Looking South - W. Flagler Street




Looking South - SW 3rd Street




Looking North - SW 2nd Street



Looking South - W. Flagler Street



Looking South - SW 7th Street



Looking North - SW 8th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 27th Avenue	3	Auburndale	4	100	2700	Yes	No	No	6	State	Yes	Yes	0	Yes	Yes	No	No curb around the median and cars parked in median
SW 37th Avenue	3	Auburndale/ La Pastorita	4	70	2700	No	No	No	4	County	No	No	0	Yes	Yes	No	Main street, no bike lanes. Intermittent trees and palms

SW 27th Avenue

TYPOLOGY E

SW 37th Avenue

TYPOLOGY E

Street Tree Inventory

SW 37th Avenue

SPECIES_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 37TH AVE	Simpson's Stopper	1-5"	No	10'	Good (61% to 80%)				
SW 37TH AVE	Simpson's Stopper	1-5"	No	10'	Good (61% to 80%)				
SW 37TH AVE	Simpson's Stopper	1-5"	No	10'	Good (61% to 80%)				
SW 37TH AVE	Simpson's Stopper	1-5"	No	10'	Good (61% to 80%)				
SW 37TH AVE	Simpson's Stopper	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 37TH AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)				

*Note SW 27th Avenue has no trees



LA PASTORITA

Avenues | Courts




Looking South - SW 11th Street




Looking South - SW 12th Street



Looking North - SW 11th Street




Looking North - SW 9th Street



Looking North - SW 9th Street



Looking South - SW 9th Terrace



Roundabout at SW 9th Terrace



At SW 8th Street - North End

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 36th Court	3	La Pastorita	4	50	1300	No	Only bet. 8th and 9th st. Pay to park		2	City	Some	Few	6	Bet. 8th and 9th st. and at 14th st and	Yes	Some on East	
SW 36th Avenue	3	La Pastorita	4	50	2700	No	Bet. 9th and 8th st.		2	City	Some	Some	8	Bet. 8th and 9th st. and at 14th st and	Yes	Some on East	Large trees between 8th and 9th

SW 36th Court

TYPOLOGY C

SW 36th Avenue

TYPOLOGY A

Street Tree Inventory

SW 36th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 36TH CT	Live Oak	6-10"	No	10'	Good (61% to 80%)				
SW 36TH CT	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 36TH CT	Live Oak	1-5"	No	10'	Good (61% to 80%)		Sprouting		
SW 36TH CT	Live Oak	1-5"	No	10'	Good (61% to 80%)		Sprouting		
SW 36TH CT	Areca Palm	16-20"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 36TH CT	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 36TH CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 36TH CT	Christmas Palm	6-10"	Yes		Good (61% to 80%)				
SW 36TH CT	Christmas Palm	6-10"	Yes		Good (61% to 80%)				
SW 36TH CT	Bottlebrush	16-20"	Yes		Poor (21% to 40%)		Recumbent	Decay Observed	Basal Co-Dominant
SW 36TH CT	Gumbo Limbo	6-10"	No		Good (61% to 80%)		Codominant Leaders/Included Bark	Adjacent Light Pole	
SW 36TH CT	Mahogany	31-40"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 36TH CT	Mahogany	31-40"	No	40'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 36TH CT	Mahogany	16-20"	No	20'	Poor (21% to 40%)	Utility Lines Above	Basal Co-Dominant		

SW 36th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 36TH AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 36TH AVE	Coconut Palm	6-10"	No	10'	Poor (21% to 40%)		Nutrient Deficiency	Reduced Canopy - Major	
SW 36TH AVE	Coconut Palm	6-10"	No	5'	Dead (0% to 5%)		No Canopy		
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	White Fly	
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	White Fly	
SW 36TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Broken Branches
SW 36TH AVE	Mahogany	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Restricted Canopy
SW 36TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Broken Branches
SW 36TH AVE	Mahogany	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Restricted Canopy
SW 36TH AVE	Mahogany	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Sidewalk Damage	Restricted Canopy
SW 36TH AVE	Mahogany	41-50"	No	40'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 36TH AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 36TH AVE	Mahogany	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 36TH AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 36TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 36TH AVE	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Disease	
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 36TH AVE	Mahogany	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 36TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 36TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 36TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 36TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Support to be Removed		
SW 36TH AVE	Weeping Fig	16-20"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	
SW 36TH AVE	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken		
SW 36TH AVE	Green Buttonwood	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken		
SW 36TH AVE	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Utility Pruned
SW 36TH AVE	Coconut Palm	11-15"	No	35'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 36TH AVE	Starburst Clerodendro	11-15"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	

(Continued on Next Page)

Street Tree Inventory

SW 36th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 36TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 36TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Utility Pruned
SW 36TH AVE	Black Olive	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Utility Pruned
SW 36TH AVE	Black Olive	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Utility Pruned	Reduced Canopy - Major	Stubs with Sprouts
SW 36TH AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)		Leader - Bent	Strap Constricting Tree	
SW 36TH AVE	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 36TH AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 36TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Limb Damage - Moderate	Reduced Canopy - Minor	Strap Constricting Tree
SW 36TH AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Minor	Strap Constricting Tree	
SW 36TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Disease		
SW 36TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Podocarpus	1-5"	No	5'	Good (61% to 80%)				
SW 36TH AVE	Mahogany	1-5"	No	5'	Poor (21% to 40%)		Leaning - Major	Codominant Leaders/Included Bark	
SW 36TH AVE	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)				
SW 36TH AVE	Green Buttonwood	16-20"	No	20'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 36TH AVE	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)				
SW 36TH AVE	Green Buttonwood	16-20"	No	20'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 36TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 36TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 36TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			

Avenues



Looking South - SW 11th Street




Looking South - SW 12th Street



Looking South - SW 13th Street



Looking North - SW 9th Terrace



Looking North - SW 9th Street



Looking South - SW 9th Terrace



At SW 8th Street - North end



At SW 16th Street - South end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 35th Avenue	3	La Pastorita	4	50	1500	No	No	Only bet. 8th and 9th st. Pay to park	2	City	Some	Few	8	Only on west side bet. 16th and 11th st	Except at one house bt. 12th and 13th	West Side	Large trees between 12th and 13th
SW 34th Avenue	3	La Pastorita	4	50	2700	No	No	Only bet. 8th and 9th st. Pay to park	2	City	Some	Some	8	On East Side	Only on west side bet. 16th and 11th st	West Side	

SW 35th Avenue

TYPOLOGY C

SW 34th Avenue

TYPOLOGY 50 A

Street Tree Inventory


SW 35th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 35TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 35TH AVE	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 35TH AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Sprouting
SW 35TH AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 35TH AVE	Mahogany	31-40"	No	25'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 35TH AVE	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	Decay Observed
SW 35TH AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Dead Wood
SW 35TH AVE	Mahogany	31-40"	No	35'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	Sprouting
SW 35TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	Decay Observed
SW 35TH AVE	Mahogany	31-40"	No	35'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Decay Observed

SW 34th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 34TH AVE	Tamarind	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 34TH AVE	Weeping Fig	16-20"	No	40'	Good (61% to 80%)		Constricted Roots	Stubs with Sprouts	
SW 34TH AVE	Spanish Lime	6-10"	No	20'	Poor (21% to 40%)		Basal Co-Dominant		
SW 34TH AVE	Pygmy Date Palm	1-5"	No	5'	Poor (21% to 40%)		Nutrient Deficiency	Suppressed Canopy	
SW 34TH AVE	Strangler Fig	16-20"	No	35'	Good (61% to 80%)		Constricted Roots	Codominant Leaders/Included Bark	Adjacent Light Pole
SW 34TH AVE	Tamarind	21-30"	No	45'	Good (61% to 80%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 34TH AVE	Avocado	16-20"	No	35'	Fair (41% to 60%)		Insect Damage Leaves	Decay Observed	Codominant Leaders/Included Bark
SW 34TH AVE	Mango	16-20"	No	30'	Good (61% to 80%)		Stubs with Sprouts	Codominant Leaders/No Included Bark	Dead Wood
SW 34TH AVE	Mango	16-20"	No	35'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Restricted Canopy
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 34TH AVE	Silver Buttonwood	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 34TH AVE	Silver Buttonwood	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 34TH AVE	Silver Buttonwood	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 34TH AVE	Silver Buttonwood	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 34TH AVE	Silver Buttonwood	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 34TH AVE	Live Oak	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Sprouting
SW 34TH AVE	Royal Poinciana	21-30"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Trunk Damage - Major
SW 34TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Desert Cassia	1-5"	Yes	10'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 34TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 34TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark	Strap Constricting Tree	
SW 34TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Plunged	
SW 34TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Plunged	
SW 34TH AVE	Mahogany	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Sprouting
SW 34TH AVE	Mahogany	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Trunk Damage - Major
SW 34TH AVE	Mahogany	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 34TH AVE	Mahogany	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	

Avenues







At SW 8th Street - North end



At SW 11th Street - South end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 33rd Avenue	3	La Pastorita	4	50	1100	Yes	No	No	2	City	Yes	No	8	On median and east side	On west side only	East Side	One way for one block at 8th street - Bike Lanes both sides of road

SW 33rd Avenue

TYPOLOGY G

Street Tree Inventory

SW 33rd Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 33RD AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 33RD AVE	Unidentified Dead Tre	11-15"	No	25'	Dead (0% to 5%)				Uprooted - Mostly
SW 33RD AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Dead Wood
SW 33RD AVE	Pink Tabebuia	6-10"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Restricted Canopy	
SW 33RD AVE	Mahogany	31-40"	No	40'	Good (61% to 80%)		Stubs	Dead Wood	Broken Branches
SW 33RD AVE	Pink Tabebuia	6-10"	No	10'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	Dead Wood
SW 33RD AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	Dead Wood
SW 33RD AVE	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 33RD AVE	Mahogany	16-20"	No	5'	Dead (0% to 5%)				
SW 33RD AVE	Pink Tabebuia	11-15"	No	15'	Poor (21% to 40%)		Basal Co-Dominant		
SW 33RD AVE	Spanish Stopper	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 33RD AVE	Spanish Stopper	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 33RD AVE	Spanish Stopper	11-15"	No	10'	Fair (41% to 60%)		Restricted Canopy	Basal Co-Dominant	
SW 33RD AVE	Live Oak	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Utility Pruned	Stubs with Sprouts	Dead Wood
SW 33RD AVE	Mulberry Tree	11-15"	No	10'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	Sprouting
SW 33RD AVE	Mulberry Tree	16-20"	No	15'	Poor (21% to 40%)		Dead Wood	Decay Observed	Sprouting
SW 33RD AVE	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 33RD AVE	Pink Tabebuia	6-10"	No	10'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 33RD AVE	Pink Tabebuia	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Sprouting
SW 33RD AVE	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	Sprouting
SW 33RD AVE	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Basal Co-Dominant	Utility Pruned	Stubs with Sprouts
SW 33RD AVE	Strangler Fig	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Growing on Wall	
SW 33RD AVE	Green Buttonwood	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant	Utility Pruned	
SW 33RD AVE	Green Buttonwood	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 33RD AVE	Green Buttonwood	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant	Utility Pruned	
SW 33RD AVE	Green Buttonwood	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 33RD AVE	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Sprouting		
SW 33RD AVE	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Sprouting	Strap Constricting Tree	
SW 33RD AVE	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Sprouting	Strap Constricting Tree	Dead Wood
SW 33RD AVE	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Sprouting	Strap Constricting Tree	
SW 33RD AVE	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Sprouting	Strap Constricting Tree	
SW 33RD AVE	Spanish Stopper	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Sprouting	
SW 33RD AVE	Guiana Chestnut	21-30"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Decay Observed	Basal Co-Dominant with Adjacent Tree(s)
SW 33RD AVE	Live Oak	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Dead Wood	Basal Co-Dominant with Adjacent Tree(s)
SW 33RD AVE	Sapodilla	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Stubs with Sprouts	Galls	Dead Wood
SW 33RD AVE	Sapodilla	16-20"	No	35'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Dead Wood	
SW 33RD AVE	Pink Tabebuia	16-20"	No	30'	Poor (21% to 40%)		Basal Co-Dominant	Dead Wood	Stubs with Sprouts
SW 33RD AVE	Sapodilla	11-15"	No	25'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Dead Wood	Stubs with Sprouts
SW 33RD AVE	Sapodilla	16-20"	No	35'	Poor (21% to 40%)		Crown Density - Low	Dead Wood	
SW 33RD AVE	Sapodilla	16-20"	No	40'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	
SW 33RD AVE	Sapodilla	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 33RD AVE	Sapodilla	16-20"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	Stubs with Sprouts
SW 33RD AVE	Sapodilla	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	Sprouting
SW 33RD AVE	Sapodilla	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 33RD AVE	Sapodilla	11-15"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Decay Observed	Sprouting
SW 33RD AVE	Sapodilla	16-20"	No	40'	Fair (41% to 60%)		Leader - Broken	Stubs	Dead Wood
SW 33RD AVE	Sapodilla	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/Included Bark	Stubs	Dead Wood
SW 33RD AVE	Sapodilla	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Stubs	Dead Wood
SW 33RD AVE	Sapodilla	21-30"	No	55'	Good (61% to 80%)		Codominant Leaders/Included Bark	Stubs	Dead Wood
SW 33RD AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			



At SW 37th Avenue - West end



At SW 33rd Avenue - East end



At SW 8th Street - North end



At SW 11th Street - South end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 9th Street	3	La Pastorita	4	50	1400	No	between 35th and 36th avenue		2	City	Few	Yes	9	Some	Yes	North Side - some - between 34th and 33rd avenues	Some paved swales, multiple driveways
SW 9th Terrace	3	La Pastorita	4	50	1400	No	No	No	2	City	1	No	9	Few	Yes	North Side - some - between 34th and 33rd avenues	Roundabout at 36th avenue - No official parking, but cars parked in swale entire length of street both sides.

SW 9th Street

TYPOLOGY C & A

SW 9th Terrace

TYPOLOGY C

Street Tree Inventory

SW 9th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 9TH ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Utility Pruned	Nutrient Deficiency	
SW 9TH ST	Coconut Palm	6-10"	No	5'	Poor (21% to 40%)	Utility Line Conflict	Utility Pruned	Reduced Canopy - Major	
SW 9TH ST	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 9TH ST	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 9TH ST	Areca Palm	31-40"	Yes	15'	Good (61% to 80%)				
SW 9TH ST	Christmas Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 9TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 9TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 9TH ST	Hong Kong Orchid	16-20"	Yes	10'	Dead (0% to 5%)				
SW 9TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 9TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 9TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 9TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 9TH ST	Yellow Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Major	Reduced Canopy - Moderate	Stubs with Sprouts
SW 9TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 9TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

SW 9th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 9TH TER	Cabbage Palm	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Utility Pruned	Stubs with Sprouts	Reduced Canopy - Moderate
SW 9TH TER	Live Oak	6-10"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 9TH TER	Live Oak	11-15"	No	35'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Stubs with Sprouts	
SW 9TH TER	Live Oak	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Sprouting	
SW 9TH TER	Sea Grape	21-30"	No	25'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Dead Wood
SW 9TH TER	Strangler Fig	16-20"	No	30'	Good (61% to 80%)		Constricted Roots	Codominant Leaders/Included Bark	Lateral Branching - None
SW 9TH TER	Pygmy Date Palm	6-10"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 9TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 9TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				



At SW 37th Avenue - West end



At SW 33rd Avenue - East end



At SW 37th Avenue - West end



At SW 33rd Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 10th Street	3	La Pastorita	4	50	1400	No	No	No	2	City	1	No	9	No	Yes	North Side - some - between 34th and 33rd avenues	No official parking, but cars parked in swale entire length of street both sides.swale paved between 33rd and 34th ave
SW 11th Street	3	La Pastorita	4	70	1400	Yes	No	No	2	City	Yes - in median - a few in swale	No	6	Only on median bet. 33rd and 34th ave	Yes	North Side - some - between 34th and 33rd avenues	Bike Lanes both sides of road

SW 10th Street

TYPOLOGY C

SW 11th Street

TYPOLOGY G

Street Tree Inventory

SW 11th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 11TH ST	Sapodilla	16-20"	No	30'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Codominant Leaders/Included Bark
SW 11TH ST	Sapodilla	21-30"	No	35'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Sprouting
SW 11TH ST	Sapodilla	16-20"	No	30'	Good (61% to 80%)		Sprouting	Stubs	Decay Observed
SW 11TH ST	Sapodilla	16-20"	No	30'	Good (61% to 80%)		Stubs with Sprouts	Codominant Leaders/Included Bark	
SW 11TH ST	Sapodilla	16-20"	No	25'	Good (61% to 80%)		Sprouting		
SW 11TH ST	Sapodilla	16-20"	No	30'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Sprouting
SW 11TH ST	Live Oak	21-30"	No	45'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 11TH ST	Royal Poinciana	16-20"	No	15'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	
SW 11TH ST	Sapodilla	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Decay Observed	Sprouting
SW 11TH ST	Sapodilla	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 11TH ST	Live Oak	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Dead Wood	
SW 11TH ST	Live Oak	11-15"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Leader - Bent	Vine Cover - Heavy
SW 11TH ST	Live Oak	11-15"	No	35'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark		
SW 11TH ST	Green Buttonwood	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 11TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 11TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)				
SW 11TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 11TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 11TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 11TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Stubs with Sprouts
SW 11TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 11TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Sprouting
SW 11TH ST	Java Plum	16-20"	No	25'	Poor (21% to 40%)		Reduced Canopy - Moderate	Sloughing Bark	Sprouting
SW 11TH ST	Strangler Fig	60+"	No	60'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 11TH ST	Java Plum	16-20"	No	25'	Poor (21% to 40%)		Reduced Canopy - Moderate	Sloughing Bark	Sprouting
SW 11TH ST	Strangler Fig	60+"	No	60'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 11TH ST	Strangler Fig	31-40"	No	45'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Dead Wood
SW 11TH ST	Java Plum	16-20"	No	30'	Fair (41% to 60%)		Restricted Canopy	Dead Wood	Broken Branches
SW 11TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 11TH ST	Christmas Palm	1-5"	No	50'	Good (61% to 80%)				
SW 11TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 11TH ST	Black Olive	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Root Damage/Decay
SW 11TH ST	Java Plum	21-30"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	
SW 11TH ST	Java Plum	31-40"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 11TH ST	Java Plum	31-40"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	
SW 11TH ST	Java Plum	31-40"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	
SW 11TH ST	Java Plum	21-30"	No	30'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	Sprouting
SW 11TH ST	Java Plum	21-30"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	Sloughing Bark
SW 11TH ST	Java Plum	21-30"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 11TH ST	Java Plum	16-20"	No	30'	Fair (41% to 60%)		Trunk Damage - Major	Decay Observed	Sloughing Bark
SW 11TH ST	Java Plum	16-20"	No	25'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate	Decay Observed
SW 11TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Codominant Leaders/Included Bark



At SW 37th Avenue - West end



At SW 33rd Avenue - East end



Speed Hump between SW 37th and SW 36th Avenues



Speed Hump between SW 36th and SW 35th Avenues



At SW 37th Avenue - West end



At SW 33rd Avenue - East end



At SW 37th Avenue - West end



At SW 33rd Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 12th Street	3	La Pastorita	4	50	1300	No			2	City	few	No	9	Only at sw side at 37th ave	Yes	North Side	60' ROW bet. 36th Ct and 37th ave
SW 13th Street	3	La Pastorita	4	50	1300	No	No	No	2	City	Yes	Few	9	No	Yes	South Side	Speed Hump between 37th and 36th avenues

SW 12th Street
TYPOLOGY A

SW 13th Street
TYPOLOGY A

Street Tree Inventory

SW 12th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 12TH ST	Royal Poinciana	16-20"	No	55'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	Sprouting
SW 12TH ST	Royal Poinciana	16-20"	No	25'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Utility Pruned	Decay Observed
SW 12TH ST	Jacaranda	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Dead Wood	Decay Observed
SW 12TH ST	Weeping Fig	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	
SW 12TH ST	Norfolk Pine	21-30"	No	20'	Poor (21% to 40%)		Basal Co-Dominant		
SW 12TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 12TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Royal Poinciana	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Crown Density - Moderate	Dead Wood	Codominant Leaders/No Included Bark
SW 12TH ST	Royal Poinciana	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Root Damage/Decay	Decay Observed
SW 12TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 12TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	Sprouting
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			

Street Tree Inventory

SW 13th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 13TH ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)				
SW 13TH ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)				
SW 13TH ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)				
SW 13TH ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)				
SW 13TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Stubs with Sprouts
SW 13TH ST	Jacaranda	1-5"	No	10'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Stubs with Sprouts
SW 13TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 13TH ST	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 13TH ST	Areca Palm	6-10"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 13TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Bottlebrush	6-10"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	
SW 13TH ST	Mahogany	16-20"	No	35'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	
SW 13TH ST	Sapodilla	11-15"	No	20'	Poor (21% to 40%)		Basal Co-Dominant	Lopsided/Moderately Reduced Canopy	
SW 13TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Black Olive	31-40"	No	35'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Trunk Damage - Major	Decay Observed	Root Damage/Decay
SW 13TH ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Moderate	Decay Observed	Constricted Roots
SW 13TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Trunk Damage - Moderate
SW 13TH ST	Mahogany	31-40"	No	45'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Trunk Damage - Major
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Mahogany	21-30"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Mahogany	21-30"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 13TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 13TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Plunged	Sprouting
SW 13TH ST	Mahogany	11-15"	No	25'	Good (61% to 80%)		Compromised Tension Roots - Due to Adjace		
SW 13TH ST	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	
SW 13TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Sprouting
SW 13TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage	Decay Observed
SW 13TH ST	Mahogany	21-30"	No	45'	Good (61% to 80%)		Stubs with Sprouts	Dead Wood	Codominant Leaders/Included Bark
SW 13TH ST	Mahogany	21-30"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Stubs with Sprouts
SW 13TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Stubs with Sprouts
SW 13TH ST	Silver Buttonwood	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Apical Dieback	Strap Constricting Tree	
SW 13TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 13TH ST	Mahogany	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Sprouting
SW 13TH ST	Mahogany	31-40"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Decay Observed
SW 13TH ST	Silver Buttonwood	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Trunk Damage - Major	Strap Constricting Tree	
SW 13TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts

Street | Terraces



At SW 37th Avenue - West end



At SW 33rd Avenue - East end



Raised decorative sidewalk at SW 36th Avenue





At SW 37th Avenue - West end



At SW 33rd Avenue - East end



At SW 37th Avenue - West end



At SW 33rd Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 13th Terrace	3	La Pastorita	4	50	1300	No	No	No	2	City	Some	No	9	No	Yes	North Side	No official parking, but cars parked in swale entire length of street both sides - some paved swales
SW 14th Street	3	La Pastorita	4	50	1300	No	No	No	2	City	Few	No	12	No	Yes	North Side	swale paved both side bet. 34th and 36th ave.

SW 13th Terrace
TYPOLOGY C

SW 14th Street
TYPOLOGY C

Street Tree Inventory

SW 13th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 13TH TER	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Constricted Roots
SW 13TH TER	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Decay Observed
SW 13TH TER	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 13TH TER	Orange Geiger	1-5"	No	10'	Poor (21% to 40%)	Utility Lines Above	Leader - Bent	Leaning - Moderate	
SW 13TH TER	Umbrella Tree	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant		
SW 13TH TER	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 13TH TER	Mango	16-20"	No	30'	Poor (21% to 40%)		Restricted Canopy	Trunk Damage - Major	Dead Wood

SW 14th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 14TH ST	Umbrella Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 14TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Green Buttonwood	1-5"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 14TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 14TH ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict			
SW 14TH ST	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Sprouting	
SW 14TH ST	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Strap Constricting Tree	Sprouting
SW 14TH ST	Silver Buttonwood	1-5"	No	5'	Dead (0% to 5%)	Utility Lines Above			
SW 14TH ST	Desert Cassia	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 14TH ST	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Stubs with Sprouts	Codominant Leaders/No Included Bark	
SW 14TH ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 14TH ST	Crepe Myrtle	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Crown Density - Moderate	
SW 14TH ST	Crepe Myrtle	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Crown Density - Moderate	
SW 14TH ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 14TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Adjacent Light Pole		
SW 14TH ST	Starburst Clerodendrd	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Utility Pruned	
SW 14TH ST	Golden Rain Tree	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant	Sprouting	
SW 14TH ST	Golden Rain Tree	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant	Sprouting	
SW 14TH ST	Golden Rain Tree	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant	Sprouting	

Street| Terraces



SW 15th Street



Speed Hump between SW 36th and SW 34th Avenues



At SW 37th Avenue - West end



At SW 33rd Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 15th Street	3	La Pastorita	4	50	1300	No	No	No	2	City	Few	No	9	Only at sw side at 37th ave	Yes	North Side	Speed Humps between 37th and 36th avenues and between 34th and 36th avenues. Swales paved in multiple areas

SW 15th Street

TYPOLOGY C

Street Tree Inventory

SW 15th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 15TH ST	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor	Utility Pruned	
SW 15TH ST	Green Buttonwood	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Utility Pruned	
SW 15TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Sprouting
SW 15TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 15TH ST	Golden Rain Tree	11-15"	No	30'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Dead Wood	
SW 15TH ST	Washington Palm	11-15"	No	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Cracks in Trunk	
SW 15TH ST	Coconut Palm	6-10"	No	20'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Nutrient Deficiency		
SW 15TH ST	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 15TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		White Fly		
SW 15TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		White Fly		
SW 15TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	White Fly	
SW 15TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 15TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 15TH ST	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Insect Damage Leaves	Codominant Leaders/Included Bark	
SW 15TH ST	Orange Geiger	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Insect Damage Leaves	Crown Density - Low	
SW 15TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 15TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 15TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 15TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 15TH ST	Japanese Fern Tree	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 15TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Reduced Canopy - Minor	Sprouting

Bordering Streets



At SW 34th Avenue



At SW 35th Avenue



Looking North



Looking South



At SW 36th Avenue



At SW 36th Court



At SW 8th Street - South end



At SW 16th Street - North end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 8th Street - Calle Ocho - SR 41	3	La Pastorita	4	75	2,700	No	No	No	4	State	No	Some- Sabal Palms	0	Yes	Yes	No	Street Lights - Signalized Intersections with Cross-walks
SW 37th Avenue - Douglas Road	3	La Pastorita	4	60	2700	No	No	No	2	City	Some		0	Only at 8th St. & Coral Gate Park	Yes, Except at Trailer Park	No	Street Lights

SW 8th Street - Calle Ocho

TYPOLOGY E

SW 37th Avenue - Douglas Road

TYPOLOGY E

Street Tree Inventory

SW 8th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 8TH ST	Mahogany	41-50"	No	65'	Fair (41% to 60%)		Stubs with Sprouts	Dead Wood	Decay Observed
SW 8TH ST	Mahogany	31-40"	No	45'	Very Poor/Critical (6% to 20%)		Dead Wood	Decay Observed	Sloughing Bark
SW 8TH ST	Mahogany	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 8TH ST	Mahogany	31-40"	No	50'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 8TH ST	Mahogany	41-50"	No	55'	Fair (41% to 60%)		Stubs	Dead Wood	Sprouting
SW 8TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Stubs	
SW 8TH ST	Mahogany	51-60"	No	60'	Good (61% to 80%)		Stubs	Dead Wood	Sprouting
SW 8TH ST	Mahogany	11-15"	No	25'	Good (61% to 80%)		Lopsided/Moderately Reduced Canopy	Dead Wood	Sprouting
SW 8TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Broken Branches	
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)		Over Pruned		
SW 8TH ST	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)		Over Pruned		
SW 8TH ST	Cabbage Palm	6-10"	No	5'	Fair (41% to 60%)		Over Pruned		
SW 8TH ST	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)		Over Pruned		

*No Street Trees on SW 37th Avenue


Bordering Streets



At Coral Gate Park



At SW 11th Street



At SW 34th Avenue



At SW 36th Avenue



At SW 16th Street - South end



At SW 8th Street - North end



At SW 32nd Avenue - East end



At SW 37th Avenue - West end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 32nd Avenue - McDonald Street	3	La Pastorita	4	60	2700	No	No	No	2	City	No	No	7	Only at 8th St. & Coral Gate Park	Yes, Except at Trailer Park	No	Street Lights
SW 16th Street	3	La Pastorita	4	70 Between SW 37th & SW 34th Ave - 60 for rest	2600	No	No	Yes	2	City	Yes	Few	7	Yes	Yes	South Side	Bike Lanes both sides of road - Street tree Golden Shower - no sidewalk at cemetary edge

SW 32nd Avenue - McDonald Street
TYPOLOGY A

SW 16th Street
TYPOLOGY A & B

Street Tree Inventory

*No Street Trees on SW 32nd Avenue

SW 16th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 16TH ST	Golden Shower Tree	16-20"	No	30'	Poor (21% to 40%)		Lopsided/Moderately Reduced Canopy	Dead Wood	Cracks in Trunk
SW 16TH ST	Golden Shower Tree	6-10"	Yes	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Sprouting	
SW 16TH ST	Golden Shower Tree	16-20"	Yes	25'	Poor (21% to 40%)		Basal Co-Dominant	Dead Wood	Decay Observed
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 16TH ST	Golden Shower Tree	16-20"	No	35'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Dead Wood
SW 16TH ST	Golden Shower Tree	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/No Included Bark
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Stubs	Dead Wood
SW 16TH ST	Golden Shower Tree	21-30"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Moderate	Sprouting
SW 16TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 16TH ST	Golden Shower Tree	16-20"	No	30'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic	Codominant Leaders/Included Bark	Sprouting
SW 16TH ST	Java Bishopwood	16-20"	No	30'	Fair (41% to 60%)		Crown Density - Moderate	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 16TH ST	Java Bishopwood	16-20"	No	25'	Poor (21% to 40%)		Reduced Canopy - Major	Dead Wood	Stubs with Sprouts
SW 16TH ST	Black Olive	21-30"	No	40'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 16TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Suppressed Canopy		
SW 16TH ST	Golden Shower Tree	31-40"	No	30'	Dead (0% to 5%)				
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Golden Shower Tree	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Moderate	Sprouting
SW 16TH ST	Golden Shower Tree	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Minor	Sprouting
SW 16TH ST	Golden Shower Tree	16-20"	No	30'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Dead Wood
SW 16TH ST	Golden Shower Tree	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Reduced Canopy - Minor
SW 16TH ST	Golden Shower Tree	16-20"	No	45'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Dead Wood
SW 16TH ST	Golden Shower Tree	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Crown Density - Excessive (Due to Epico	Broken Branches
SW 16TH ST	Black Olive	31-40"	No	45'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Cavities	Sprouting
SW 16TH ST	Paradise Tree	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree (Remove When Esta		
SW 16TH ST	Paradise Tree	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree (Remove When Esta		
SW 16TH ST	Paradise Tree	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree (Remove When Esta		
SW 16TH ST	Paradise Tree	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree (Remove When Esta		



PARKDALE NORTH

Avenues | Courts



At SW 11th Street - South End



Looking North - SW 10th Street



At SW 16th Street - South End



Looking North - towards SW 12th Street



Looking West - Internal Alley in RV Park



At SW 8th Street - North End



At SW 11th Street - Road Jogs to the west



At SW 8th Street - North End

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 31st Court	3	Parkdale North	4	25	1000	No	No	No	2	City	No	No	0	No	East Side	West Side	Trailer Park on west - ROW occupied to edge of street
SW 31st Avenue	3	Parkdale North	4	50	1000	No	Restricted	No	2	City	No	No	9	Only at Home Depot	Yes	West Side	No swales at Home Depot, on-street parking

SW 31st Court

TYPOLOGY A

SW 31st Avenue

TYPOLOGY A

Street Tree Inventory

SW 31st Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 31ST CT	Weeping Fig	11-15"	No	15'	Good (61% to 80%)				
SW 31ST CT	Weeping Fig	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 31ST CT	Weeping Fig	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 31ST CT	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 31ST CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 31ST CT	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)		Basal Co-Dominant	Limb Damage - Moderate	
SW 31ST CT	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Very Low	Sprouting	
SW 31ST CT	Weeping Fig	1-5"	No	10'	Poor (21% to 40%)				
SW 31ST CT	Mahogany	1-5"	No	5'	Fair (41% to 60%)		Basal Co-Dominant		
SW 31ST CT	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Leaning - Minor	Codominant Leaders/Included Bark	
SW 31ST CT	Weeping Fig	11-15"	No	15'	Good (61% to 80%)				

SW 31st Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 31ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 31ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 31ST AVE	Black Olive	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 31ST AVE	Black Olive	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 31ST AVE	Black Olive	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 31ST AVE	Black Olive	31-40"	No	65'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 31ST AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 31ST AVE	Weeping Fig	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Black Olive	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 31ST AVE	Mahogany	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 31ST AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 31ST AVE	Rubber Tree	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 31ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 31ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 31ST AVE	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 31ST AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 31ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		

(Continued on Next Page)

Street Tree Inventory

SW 31st Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 31ST AVE	Starburst Clerodendron	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 31ST AVE	Starburst Clerodendron	6-10"	No	15'	Good (61% to 80%)				
SW 31ST AVE	Starburst Clerodendron	6-10"	Yes	5'	Good (61% to 80%)				
SW 31ST AVE	Weeping Fig	21-30"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 31ST AVE	Weeping Fig	21-30"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 31ST AVE	Yellow Elder	6-10"	No	20'	Fair (41% to 60%)		Leaning - Minor	Codominant Leaders/Included Bark	Trunk Damage - Moderate
SW 31ST AVE	Royal Palm	6-10"	No	15'	Good (61% to 80%)				
SW 31ST AVE	Royal Palm	6-10"	No	15'	Good (61% to 80%)				
SW 31ST AVE	Royal Palm	6-10"	No	15'	Good (61% to 80%)				
SW 31ST AVE	Royal Palm	6-10"	No	15'	Good (61% to 80%)				

Avenues | Courts



Looking South - near SW 15th Street



Looking South - near SW 13th Street



Looking South at SW 10th Street - South End- No Outlet



At South end - No Outlet Street turn around



Looking North - from SW 11th Street



Looking North towards SW 9th Street - North End



Looking South from SW 8th Street



At SW 8th Street - North end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 30th Avenue	3	Parkdale North	4	50	2350	No	One block at 8th St.	No	2	City	Some	Some	10	Only 1 block	Yes	West Side	Ends at SW 9th Street
SW 29th Court	3	Parkdale North	4	50	950	No	No	West Side - entire length: East Side 1 block at 8th St.	2	City	No	No	8	West - entire length and 1 block east at 8th St.	Yes	No	No Outlet at South end. No swale on west side, on-street parking

SW 30th Avenue

TYPOLOGY A

SW 29th Court

TYPOLOGY C & D

Street Tree Inventory

SW 30th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 30TH AVE	Umbrella Tree	41-50"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Trunk Damage - Major	Reduced Canopy - Moderate
SW 30TH AVE	Umbrella Tree	21-30"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Sprouting
SW 30TH AVE	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Codominant Leaders/No Included Bark	Sprouting
SW 30TH AVE	Strangler Fig	41-50"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 30TH AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Black Olive	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Black Olive	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Black Olive	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Foxtail Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency	Frizzled Fronds	
SW 30TH AVE	Foxtail Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH AVE	Foxtail Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH AVE	Umbrella Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Hong Kong Orchid	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Reduced Canopy - Moderate
SW 30TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Over Extended Limb(s)		
SW 30TH AVE	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 30TH AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Mahogany	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Sprouting
SW 30TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 30TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Bismark Palm	16-20"	No	20'	Good (61% to 80%)				
SW 30TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Spindle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Spindle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Dracaena sp.	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 30TH AVE	Mahogany	31-40"	No	35'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Limb Damage - Major	Decay Observed
SW 30TH AVE	Triangle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Triangle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Triangle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Triangle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Yellow Tabebuia	11-15"	No	15'	Fair (41% to 60%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	Limb Damage - Moderate
SW 30TH AVE	Yellow Tabebuia	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 30TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 30TH AVE	Royal Poinciana	16-20"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Decay Observed
SW 30TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 30TH AVE	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots		
								Codominant Leaders/Included	

(Continued on Next Page)

Street Tree Inventory

SW 30th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 30TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Ficus Growing on Tree
SW 30TH AVE	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Topped	Sprouting	
SW 30TH AVE	Melaleuca	16-20"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 30TH AVE	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 30TH AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 30TH AVE	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Topped	Sprouting	Codominant Leaders/Included Bark
SW 30TH AVE	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)				
SW 30TH AVE	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 30TH AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 30TH AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				

SW 30th Place

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 30TH PL	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH PL	Areca Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH PL	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				

SW 30th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 30TH CT	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH CT	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 30TH CT	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH CT	Gumbo Limbo	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Grafted Branches	Dead Wood
SW 30TH CT	Gumbo Limbo	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Grafted Branches	Lopsided/Moderately Reduced Canopy
SW 30TH CT	Royal Poinciana	31-40"	No	50'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts

Avenues | Courts | Place



Looking South - SW 13th Street - South end



Looking North between SW 12th Street & SW 13th Street



Looking South - SW 12th Street - North end



Looking South between SW 12th Street & SW 13th Street



Looking North towards SW 12th Street - North End



Looking South towards SW 12th Street - South End

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 30th Place	3	Parkdale North	4	40	300	No	No	No	2	City	Few	Few	6	No	Yes	West Side	Only one block long between SW 12th and 13th Streets. 9' swales on west side of street
SW 30th Court	3	Parkdale North	4	40	300	No	No	No	2	City	No	Few	6	No	Yes	West Side	Only one block long between SW 12th and 13th Streets

SW 30th Place

TYPOLOGY A

SW 30th Court

TYPOLOGY C

Street Tree Inventory

*Note there are no trees on SW 30th Place or SW 30th Court

Avenues | Courts



At SW 8th Street - North end



Looking South - SW 10th Street



At SW 10th Street - North end Alley



Looking North from SW 10th Street - One Way North



Looking South - SW 14th Street



At SW 16th Street - South end



At SW 10th Street - South end - Alley

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 29th Avenue	3	Parkdale North	4	50	2,700	No	No	Only at SW 8th St.	2	City	Some	Some	8	Only at SW 8th St.	Yes	West Side	Pay to Park at SW 8th St. - no swale Roundabouts at SW 10th, 11th and 14th Streets
SW 28th Avenue	3	Parkdale North	4	25	280	No	No	No	2	City	No	No	8	No	East Only	East Side	No Outlet North & South. One-Way North between 10th Terrace and 10th Street.

SW 29th Avenue

TYPOLOGY A & C

SW 28th Avenue

TYPOLOGY X

Street Tree Inventory

SW 29th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 29TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Weeping Fig	16-20"	No	15'	Poor (21% to 40%)	Utility Lines Above	Topped	Sprouting	Decay Observed
SW 29TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 29TH AVE	Bottlebrush	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Decay Observed	Reduced Canopy - Moderate
SW 29TH AVE	Areca Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Sapodilla	21-30"	No	25'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Black Olive	16-20"	No	25'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Codominant Leaders/Included Bark	Dead Wood
SW 29TH AVE	Live Oak	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Sprouting	Restricted Canopy
SW 29TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 29TH AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Codominant Leaders/Included Bark	
SW 29TH AVE	Live Oak	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Above	Topped	Sprouting	Codominant Leaders/Included Bark
SW 29TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Codominant Leaders/Included Bark	
SW 29TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	BV UNID 5	16-20"	Yes	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Suppressed Canopy	
SW 29TH AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 29TH AVE	Lychee	11-15"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Stubs with Sprouts	Dead Wood
SW 29TH AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Glaucous Cassia	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Decay Observed	Dead Wood	Stubs
SW 29TH AVE	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Over Pruned		
SW 29TH AVE	Senegal Date Palm	21-30"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Indian Rosewood	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Dead Wood	Apical Dieback

(Continued on Next Page)

Street Tree Inventory

SW 29th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 29TH AVE	Weeping Fig	16-20"	No	20'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 29TH AVE	Weeping Fig	16-20"	No	30'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Stubs with Sprouts	Over Extended Limb(s)
SW 29TH AVE	Weeping Fig	11-15"	No	35'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Stubs with Sprouts	Over Extended Limb(s)
SW 29TH AVE	Weeping Fig	11-15"	No	30'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Stubs with Sprouts	
SW 29TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Stubs with Sprouts	
SW 29TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 29TH AVE	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 29TH AVE	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 29TH AVE	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)				
SW 29TH AVE	Strangler Fig	60+"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Decay Observed
SW 29TH AVE	Strangler Fig	60+"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 29TH AVE	Mahogany	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 29TH AVE	Live Oak	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 29TH AVE	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Trunk Damage - Moderate	Codominant Leaders/No Included Bark	Dead Wood
SW 29TH AVE	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 29TH AVE	Black Olive	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 29TH AVE	Black Olive	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 29TH AVE	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 29TH AVE	Royal Poinciana	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 29TH AVE	Tropical Almond	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Disease	Codominant Leaders/Included Bark
SW 29TH AVE	Areca Palm	6-10"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 29TH AVE	Weeping Fig	21-30"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Dead Wood
SW 29TH AVE	Weeping Fig	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs

Streets | Terraces



Looking East between SW 31st Court and SW 31st Avenue



Looking West between SW 31st Court and SW 31st Avenue



Looking East between SW 31st Court and SW 31st Avenue



Looking East at SW 29th Avenue



Looking East between SW 30th Avenue and SW 29th Court



At SW 27th Avenue - East end



Looking East towards SW 27th Avenue



At SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 9th Street	3	Parkdale North	4	50	250, 375	No	No	No	2	City	East/On North Side Only	No	11	West/no-East/Yes	Yes	West/No - East/North	Two separate segments: West between SW 31st Ct. and SW 31st Ave. Has 11' swales. East/between SW 30th Ave. & SW 29th Ave. Has 8' swale on north side only
SW 10th Street	3	Parkdale North	4	50,50,50	250,425, 400	No	No	No	2	City	On North,No, No	On South,No, Couple	11	No - except at Round-about at SW 29th Ave.	Yes	No, No, North	Three separate segments: West/between SW 31st Ct. and SW 31st Ave.(11' swale) Center/between SW 29th Ct. & SW 28th Ave. (8' swale)(Roundabout at SW 29th Ave.) and East/between SW 28th Ave. & SW 27th Ave.(11' swale)

SW 9th Street

TYPOLOGY A & B & C

SW 10th Street

TYPOLOGY A & C

Street Tree Inventory

SW 9th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 9TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 9TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 9TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 9TH ST	Mahogany	31-40"	No	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 9TH ST	Mahogany	21-30"	No	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 9TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 9TH ST	Mahogany	16-20"	No	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 9TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 9TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Broken Branches
SW 9TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 9TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 9TH ST	Frangipani	1-5"	Yes	5'	Good (61% to 80%)				
SW 9TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				

SW 10th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 10TH ST	Chinese Fan Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 10TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)				
SW 10TH ST	Unidentified Dead Tree (Defloiated)	16-20"	No	10'	Dead (0% to 5%)				
SW 10TH ST	Washington Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 10TH ST	Weeping Fig	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots		
SW 10TH ST	Mango	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 10TH ST	Mango	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 10TH ST	Pink Tabebuia	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Topped	Stubs with Sprouts	Apical Dieback
SW 10TH ST	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 10TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 10TH ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 10TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 10th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	15'	Good (61% to 80%)				
SW 10TH ST	Umbrella Tree	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 10TH ST	Umbrella Tree	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	
SW 10TH ST	Umbrella Tree	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	

SW 10th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 10TH TER	Weeping Fig	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Decay Observed

SW 11th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 11TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 11TH ST	Unidentified Dead Tree (Defloiated)	11-15"	No	5'	Dead (0% to 5%)				
SW 11TH ST	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Black Olive	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Stubs	Dead Wood
SW 11TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 11TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 11TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 11TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 11TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 11TH ST	Tropical Almond	21-30"	No	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Trunk Damage - Major	Decay Observed	Lopsided/Moderately Reduced Canopy
SW 11TH ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 11TH ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 11TH ST	Weeping Fig	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 11TH ST	Gumbo Limbo	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark

(Continued on Page After Next)

Streets | Terraces



Looking West at SW 28th Avenue - West end



Looking West from SW 27th Avenue



Looking East from SW 32nd Avenue - West end



Looking East at SW 30th Avenue



At SW 27th Avenue - East end



Looking East at SW 29th Avenue



At SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 10th Terrace	3	Parkdale North	4	50	425	No	No	Yes	2	City	No	No	0	Yes	Yes	North	Pay to park at SW 27th Ave.
SW 11th Street	3	Parkdale North	4	50	2,700	No	No	No- Except at SW 27th Ave.	2	City	Some	Some	9	No - except at Round-abouts & at SW 27th Ave.	Yes	North	Roundabout at SW 29th Ave. Speed Humps between SW 30th and 31st Ave and between SW 31st Ave & SW 31st Ct. Pay to park at SW 27th Ave

SW 10th Terrace

TYPOLOGY D

SW 11th Street

TYPOLOGY A & C

Street Tree Inventory

SW 11th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 11TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 11TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 11TH ST	Areca Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 11TH ST	Christmas Palm	31-40"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 11TH ST	Pygmy Date Palm	16-20"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 11TH ST	Weeping Fig	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 11TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 11TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 11TH ST	Christmas Palm	11-15"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 11TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 11TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 11TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 11TH ST	Bottlebrush	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 11TH ST	African Tulip Tree	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Topped	Crown Density - Very Low	Dead Wood
SW 11TH ST	Black Olive	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 11TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 11TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 11TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 11TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 11TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 11TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 11TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				

Streets | Terraces



At SW 32nd Avenue - West end



Looking West towards SW 30th Avenue



At SW 32nd Avenue - West end



Looking East towards SW 30th Avenue



Looking West towards SW 29th Avenue



At SW 27th Avenue - East end



Looking West towards SW 29th Avenue



At SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 12th Street	3	Parkdale North	4	50	2,700	No	No	No- Except at SW 27th Ave.	2	City	Some	Some	12	No - except at Round-about at SW 31st Ave.	Yes	North	Roundabout at SW 31st Ave, with crosswalks
SW 13th Street	3	Parkdale North	4	50	2,700	No	No	No	2	City	Some	Some	12	No - except at SW 32nd & 27th Aves.	Yes	No	

SW 12th Street
TYPOLOGY A & C

SW 13th Street
TYPOLOGY A & C

Street Tree Inventory

SW 12th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 12TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 12TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 12TH ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Umbrella Tree	6-10"	No	10'	Fair (41% to 60%)		Topped	Sprouting	
SW 12TH ST	Umbrella Tree	11-15"	Yes	15'	Poor (21% to 40%)		Basal Co-Dominant	Topped	Sprouting
SW 12TH ST	Umbrella Tree	21-30"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Topped	Sprouting
SW 12TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 12TH ST	Live Oak	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 12TH ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 12TH ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Sprouting
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Norfolk Pine	6-10"	No	15'	Poor (21% to 40%)		Topped	Trunk Damage - Major	
SW 12TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Crown Density - Moderate	Dead Wood	Limb Damage - Major
SW 12TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Moderate	Dead Wood	Codominant Leaders/Included Bark
SW 12TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 12th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 12TH ST	Mahogany	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 12TH ST	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Brazilian Pepper	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 12TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 12TH ST	Mahogany	41-50"	No	75'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 12TH ST	Black Olive	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 12TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 12TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	
SW 12TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Solitaire Palm	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 12TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Green Buttonwood	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 12TH ST	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 12TH ST	Green Buttonwood	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	
SW 12TH ST	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy		
SW 12TH ST	Green Buttonwood	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Basal Co-Dominant with Adjacent Tree(s)	Lopsided/Significantly Reduced Canopy	
SW 12TH ST	Green Buttonwood	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant with Adjacent Tree(s)	Lopsided/Significantly Reduced Canopy	
SW 12TH ST	Mahogany	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy		
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Cracks in Trunk	
SW 12TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 12th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 12TH ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Mahogany	31-40"	No	25'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Moderate	Decay Observed
SW 12TH ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy	Trunk Damage - Minor	
SW 12TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy		
SW 12TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 12TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 12TH ST	Avocado	21-30"	No	30'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	Dead Wood
SW 12TH ST	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)				
SW 12TH ST	Royal Poinciana	21-30"	No	35'	Poor (21% to 40%)		Girdling Roots	Trunk Damage - Major	Decay Observed
SW 12TH ST	Japanese Fern Tree	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark		
SW 12TH ST	Mango	1-5"	No	Negligible	Good (61% to 80%)				
SW 12TH ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 12TH ST	Queen Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 12TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 12TH ST	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Sprouting	Decay Observed
SW 12TH ST	Sugarberry	6-10"	No	20'	Poor (21% to 40%)		Uprooted - Partially	Basal Co-Dominant	Stubs with Sprouts
SW 12TH ST	Avocado	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Topped	Reduced Canopy - Major	Sprouting
SW 12TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Yellow Tabebuia	6-10"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		

(Continued on Next Page)

Street Tree Inventory

SW 12th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 12TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Southern Magnolia	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Moderate	Loose Trunk	Trunk Damage - Major
SW 12TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH ST	Brazilian Beauty Leaf	1-5"	No	15'	Fair (41% to 60%)		Leader - Broken	Nutrient Deficiency	
SW 12TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 12TH ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Reduced Canopy - Moderate	Trunk Damage - Major	Decay Observed
SW 12TH ST	Weeping Fig	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 12TH ST	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 12TH ST	Royal Poinciana	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Crown Density - Moderate
SW 12TH ST	Live Oak	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 12TH ST	Green Buttonwood	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 12TH ST	Mahogany	21-30"	No	25'	Poor (21% to 40%)	Utility Lines Above	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts	Decay Observed

SW 13th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 13TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 13TH ST	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 13TH ST	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 13TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 13TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 13TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 13TH ST	Black Olive	11-15"	No	15'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 13TH ST	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 13TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 13TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 13TH ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 13TH ST	Mahogany	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 13TH ST	Live Oak	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 13TH ST	Pygmy Date Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 13TH ST	Foxtail Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Foxtail Palm	1-5"	No	10'	Fair (41% to 60%)		Restricted Canopy		
SW 13TH ST	Gumbo Limbo	11-15"	No	20'	Poor (21% to 40%)		Restricted Canopy	Trunk Damage - Major	Decay Observed
SW 13TH ST	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Major
SW 13TH ST	Silver Buttonwood	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 13TH ST	Royal Poinciana	21-30"	No	65'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Cracks in Trunk	Stubs with Sprouts
SW 13TH ST	Yellow Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Dead Wood	
SW 13TH ST	Bamboo Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 13TH ST	Yellow Tabebuia	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 13TH ST	Yellow Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Dead Wood	
SW 13TH ST	Yellow Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 13TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 13TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 13TH ST	Tropical Almond	16-20"	No	40'	Fair (41% to 60%)		Topped	Crown Density - Excessive (Due to Epicormic Growth)	
SW 13TH ST	Peregrina	16-20"	Yes	15'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 13TH ST	Green Buttonwood	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant		
SW 13TH ST	Glaucous Cassia	6-10"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Sprouting
SW 13TH ST	Royal Poinciana	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs
SW 13TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)				
SW 13TH ST	Pink Tabebuia	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Major	Sprouting
SW 13TH ST	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 13TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Pygmy Date Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 13TH ST	Weeping Fig	11-15"	Yes	15'	Good (61% to 80%)				
SW 13TH ST	Weeping Fig	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Weeping Fig	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 13TH ST	Weeping Fig	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 13TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 13TH ST	Norfolk Pine	16-20"	Yes	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant		
SW 13TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 13TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 13TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 13TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 13TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 13TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Rubber Tree	41-50"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 13TH ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Plunged	Leader - Broken	Sprouting
SW 13TH ST	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark		
SW 13TH ST	Pink Tabebuia	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 13TH ST	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Decay Observed	Crown Density - Excessive (Due to Epicormic Growth)
SW 13TH ST	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 13TH ST	Pink Tabebuia	1-5"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Apical Dieback	Trunk Damage - Moderate	Decay Observed
SW 13TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 13TH ST	Tropical Almond	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Lopsided/Moderately Reduced Canopy
SW 13TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Umbrella Tree	6-10"	Yes	10'	Poor (21% to 40%)		Topped	Sprouting	Restricted Canopy
SW 13TH ST	Umbrella Tree	21-30"	Yes	20'	Poor (21% to 40%)	Utility Line Conflict	Topped	Sprouting	Restricted Canopy
SW 13TH ST	Umbrella Tree	16-20"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Cavities	Reduced Canopy - Moderate
SW 13TH ST	BV UNID 1	16-20"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Sprouting	Dead Wood

Street| Terraces



At SW 32nd Avenue - West end



Looking East from SW 31st Avenue



At SW 32nd Avenue - West end



Looking East towards SW 31st Avenue



Looking East towards SW 29th Avenue



At SW 27th Avenue - East end



Looking East towards SW 29th Avenue



At SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 14th Street	3	Parkdale North	4	50	2,700	No	No	No	2	City	Some	Some	12	No - except at SW 32nd & 27th Ave..	Yes	Some on South	Roundabouts at SW 31st and 29th Ave..
SW 15th Street	3	Parkdale North	4	60	2,300	No	No	No	2	City	Some	Some	15	No - except at SW 32nd & 27th Ave..	Yes	Some on South	No Outlet at Coral Gate Park on West

SW 14th Street
TYPOLOGY A & C

SW 15th Street
TYPOLOGY A

Street Tree Inventory

SW 14th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 14TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH ST	Avocado	16-20"	No	35'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	
SW 14TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Weeping Fig	11-15"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	
SW 14TH ST	Live Oak	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 14TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 14TH ST	Mahogany	41-50"	No	75'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 14TH ST	Sapodilla	11-15"	No	20'	Poor (21% to 40%)		Topped	Sprouting	Codominant Leaders/Included Bark
SW 14TH ST	Brazilian Pepper	16-20"	No	20'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 14TH ST	Bottlebrush	11-15"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	Dead Wood
SW 14TH ST	Bottlebrush	21-30"	No	25'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 14TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Mahogany	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 14TH ST	Vera Wood	1-5"	No	5'	Good (61% to 80%)				
SW 14TH ST	Live Oak	1-5"	No	15'	Poor (21% to 40%)	Utility Lines Above	Topped	Reduced Canopy - Major	Sprouting
SW 14TH ST	Live Oak	1-5"	No	15'	Poor (21% to 40%)		Leader - Broken	Crown Density - Moderate	Trunk Damage - Moderate
SW 14TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 14TH ST	Live Oak	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 14TH ST	Live Oak	16-20"	No	40'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Sprouting	
SW 14TH ST	Bottle Palm	11-15"	No	5'	Good (61% to 80%)				
SW 14TH ST	Weeping Fig	16-20"	No	15'	Poor (21% to 40%)		Topped	Trunk Damage - Major	Sprouting
SW 14TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 14TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 14TH ST	Weeping Fig	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 14TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 14TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH ST	Live Oak	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 14TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 14th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 14TH ST	Coconut Palm	6-10"	No	5'	Good (61% to 80%)				
SW 14TH ST	Coconut Palm	6-10"	No	5'	Good (61% to 80%)				
SW 14TH ST	Rubber Tree	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Basal Co-Dominant	Dead Wood
SW 14TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH ST	Golden Rain Tree	31-40"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 14TH ST	Golden Rain Tree	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Dead Wood
SW 14TH ST	Weeping Fig	16-20"	No	15'	Fair (41% to 60%)		Topped	Sprouting	
SW 14TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				
SW 14TH ST	Bamboo (Cluster)	21-30"	No	15'	Fair (41% to 60%)		Apical Dieback		
SW 14TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				
SW 14TH ST	Royal Palm	51-60"	Yes	30'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 14TH ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 14TH ST	Bamboo (Cluster)	21-30"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 14TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 14TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH ST	Bottlebrush	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 14TH ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Grafted Branches
SW 14TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 14TH ST	Royal Poinciana	11-15"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 14TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				

Street Tree Inventory

SW 15th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 15TH ST	Hong Kong Orchid	16-20"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Cavities	Sprouting
SW 15TH ST	Loquat	1-5"	No	5'	Good (61% to 80%)				
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 15TH ST	Christmas Palm	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 15TH ST	Jacaranda	1-5"	No	10'	Fair (41% to 60%)		Plunged		
SW 15TH ST	Live Oak	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Moderate	Apical Dieback	Plunged
SW 15TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 15TH ST	Black Olive	6-10"	No	25'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 15TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 15TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 15TH ST	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Crown Density - Excessive (Due to Epicormic Growth)	
SW 15TH ST	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 15TH ST	Live Oak	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	Dead Wood
SW 15TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 15TH ST	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 15TH ST	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 15TH ST	Pink Tabebuia	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 15TH ST	Royal Poinciana	11-15"	No	35'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Moderate	Decay Observed
SW 15TH ST	Weeping Fig	16-20"	No	25'	Poor (21% to 40%)		Reduced Canopy - Major	Limb Damage - Major	Sprouting
SW 15TH ST	Golden Rain Tree	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Dead Wood
SW 15TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Sprouting	
SW 15TH ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 15TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 15TH ST	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 15TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 15TH ST	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 15TH ST	Brazilian Beauty Leaf	6-10"	No	20'	Poor (21% to 40%)		Topped	Crown Density - Excessive (Due to Epicormic Growth)	Trunk Damage - Moderate
SW 15TH ST	Black Olive	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 15TH ST	Black Olive	1-5"	No	15'	Good (61% to 80%)				

Street Tree Inventory

SW 15th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 15TH ST	Weeping Fig	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 15TH ST	Weeping Fig	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 15TH ST	Rubber Tree	21-30"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Topped	Sprouting
SW 15TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Strap Growing in Trunk		
SW 15TH ST	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 15TH ST	Royal Poinciana	21-30"	No	45'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Dead Wood	
SW 15TH ST	Royal Poinciana	21-30"	No	60'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Dead Wood	
SW 15TH ST	Jacaranda	6-10"	No	20'	Fair (41% to 60%)		Leaning - Minor	Codominant Leaders/No Included Bark	
SW 15TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 15TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 15TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 15TH ST	Royal Poinciana	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 15TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 15TH ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)				
SW 15TH ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)				
SW 15TH ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)				
SW 15TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Stubs with Sprouts

Bordering Streets



At SW 32nd Avenue



At SW 30th Avenue




At SW 8th Street - North end



At SW 10th Street



At SW 31st Court



At SW 27th Avenue



At SW 12th Street



At SW 16th Street - South end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 8th Street - Calle Ocho - SR 41	3	Parkdale North	4	75	2,700	No	No	No	4	State	No	Some- Sabal Palms	0	Yes	Yes	No	Street Lights - Signalized Intersections with Cross-walks
SW 27th Avenue - Unity Boulevard - SR 9	3	Parkdale North	4	100	2,700	Some - Yes		Yes - Not continu-ous	4	State	In Median	In Median and swales	4	Yes	Yes	No	Street Lights - Signalized Intersections with Cross-walks. Swales: 4' & some 10' bump-outs at sides. 14' median in places

SW 8th Street - Calle Ocho

TYPOLOGY E

SW 27th Avenue - Unity Boulevard

TYPOLOGY E & I

Street Tree Inventory

SW 27th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Royal Palm	6-10"	No	20'	Good (61% to 80%)				
SW 27TH AVE	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Royal Palm	11-15"	No	10'	Poor (21% to 40%)		Cracks in Trunk	Tapered Trunk	Reduced Canopy - Moderate
SW 27TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)				
SW 27TH AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Trunk Damage - Moderate	
SW 27TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 27TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Stubs with Sprouts	
SW 27TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 27TH AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Leader - Bent	Restricted Canopy	Codominant Leaders/Included Bark
SW 27TH AVE	Royal Poinciana	11-15"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	Limb Damage - Minor
SW 27TH AVE	Live Oak	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Live Oak	1-5"	No	10'	Poor (21% to 40%)		Leaning - Major	Uprooted - Partially	
SW 27TH AVE	Live Oak	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 27TH AVE	Royal Poinciana	11-15"	No	40'	Good (61% to 80%)		Trunk Damage - Minor	Codominant Leaders/No Included Bark	Dead Wood
SW 27TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 27TH AVE	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/No Included Bark	
SW 27TH AVE	Royal Palm	16-20"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 27TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 27TH AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Sprouting

Bordering Streets



At SW 16th Avenue - Coral Gate Park



Looking South from SW 8th Street



At SW 32nd Avenue - West end



Looking West



At SW 11th Street



At SW 8th Street - North end



At SW 30th Avenue - Looking West



At SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 32nd Avenue - McDonald Street	3	Parkdale North	4	60	2700	No	No	No	2	City	Some		8	Only at 8th St. & Coral Gate Park	Yes, Except at Trailer Park	No	Street Lights - Some swales are 18' width
SW 16th Street	3	Parkdale North	4	60	2,700	No	No	Yes- Except between SW 27th and 29th Ave..	2	City	No	No	0	Yes	Yes	North	No Bike lane on this section - Share the Road- Full Lane Markings

SW 32nd Avenue - McDonald Road
TYPOLOGY A

SW 16th Street
TYPOLOGY B

Street Tree Inventory

SW 32nd Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 32ND AVE	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Girdling Roots	Lopsided/Moderately Reduced Canopy	
SW 32ND AVE	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)				
SW 32ND AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 32ND AVE	Gumbo Limbo	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 32ND AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Sprouting
SW 32ND AVE	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	
SW 32ND AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 32ND AVE	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 32ND AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 32ND AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Suppressed Canopy	Codominant Leaders/Included Bark
SW 32ND AVE	Gumbo Limbo	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 32ND AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Broken Branches
SW 32ND AVE	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 32ND AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 32ND AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting

*Note there are no trees on SW 16th Street



PARKDALE SOUTH

Avenues | Courts



Looking South from SW 20th Street - South End



Looking North - near SW 19th Terrace



Looking South from SW 20th Street - South End



Looking North - towards SW 18th Street



Looking North near SW 19th Street



Looking North near SW 16th Terrace



Looking North near SW 17th Street



Looking North near SW 16th Terrace

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 29th Avenue	3	Parkdale South	4	50	2000	No	No	No	2	City	Few	Some	9	No	Yes	West	Roundabouts at SW 18th and 19th Streets, Decorative Crosswalk at SW 20th Street. No Outlet at south end
SW 30th Avenue	3	Parkdale South	4	50	2000	No	No	No	2	City	Few	Some	9	No	Yes	West	Roundabout at SW 16th Terrace

SW 29th Avenue

TYPOLOGY A & C

SW 30th Avenue

TYPOLOGY A & C

Street Tree Inventory

SW 29th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 29TH AVE	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Constricted Roots	Sprouting
SW 29TH AVE	Weeping Fig	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 29TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Leaning - Minor		
SW 29TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 29TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 29TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 29TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 29TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 29TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 29TH AVE	Podocarpus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 29TH AVE	Podocarpus	6-10"	Yes	5'	Good (61% to 80%)				
SW 29TH AVE	Podocarpus	6-10"	Yes	5'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 29TH AVE	Podocarpus	6-10"	Yes	5'	Good (61% to 80%)				
SW 29TH AVE	Beauty Berry	1-5"	Yes	5'	Poor (21% to 40%)		Reduced Canopy - Major		
SW 29TH AVE	Beauty Berry	11-15"	Yes	10'	Good (61% to 80%)		Dead Wood		
SW 29TH AVE	Slash Pine	1-5"	No	10'	Good (61% to 80%)				
SW 29TH AVE	Mahogany	1-5"	No	15'	Good (61% to 80%)		Leaning - Major	Limb Damage - Minor	
SW 29TH AVE	Mahogany	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 29TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 29TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 29TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 29TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 29TH AVE	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Major		
SW 29TH AVE	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Major	Dead Wood	
SW 29TH AVE	Sapodilla	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major	Limb Damage - Moderate	Dead Wood
SW 29TH AVE	Sapodilla	6-10"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Leader - Broken	Dead Wood
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Crepe Myrtle	1-5"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Basal Co-Dominant		

(Continued on Next Page)

Street Tree Inventory

SW 29th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 29TH AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 29TH AVE	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 29TH AVE	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 29TH AVE	Royal Poinciana	6-10"	Yes	15'	Fair (41% to 60%)	Utility Lines Above	Girdling Roots	Limb Damage - Moderate	
SW 29TH AVE	Spindle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 29TH AVE	Spindle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 29TH AVE	Spindle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 29TH AVE	Spindle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 29TH AVE	Spindle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Spindle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 29TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy	Basal Co-Dominant with Adjacent Tree(s)	
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Basal Co-Dominant with Adjacent Tree(s)	Nutrient Deficiency	
SW 29TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 29TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting

Street Tree Inventory

SW 30th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 30TH AVE	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 30TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 30TH AVE	Orange Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 30TH AVE	Queen Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 30TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Dead Wood		
SW 30TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 30TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	
SW 30TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 30TH AVE	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Limb Damage - Major	Sprouting
SW 30TH AVE	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Limb Damage - Major	Sprouting
SW 30TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 30TH AVE	Weeping Fig	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 30TH AVE	Akee Tree	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 30TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 30TH AVE	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Mahogany	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Leader - Broken	Sprouting
SW 30TH AVE	Weeping Fig	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 30TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Suppressed Canopy	Nutrient Deficiency	
SW 30TH AVE	Mahogany	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 30TH AVE	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Moderate	
SW 30TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 30TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Tapered Trunk		
SW 30TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 30TH AVE	Hibiscus	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Hibiscus	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Orange Jasmine	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 30TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 30th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 30TH AVE	Bottle Palm	11-15"	No	10'	Poor (21% to 40%)		Trunk Damage - Major	Nutrient Deficiency	Suppressed Canopy
SW 30TH AVE	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Trunk Damage - Minor	Nutrient Deficiency	
SW 30TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 30TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 30TH AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Dead Wood	Sprouting
SW 30TH AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 30TH AVE	Mango	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 30TH AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Major	Sprouting	
SW 30TH AVE	Dahoon Holly	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 30TH AVE	Spanish Stopper	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Spanish Stopper	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Spanish Stopper	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Spanish Stopper	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Spanish Stopper	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Spanish Stopper	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Spanish Stopper	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Spanish Stopper	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Spanish Stopper	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)				
SW 30TH AVE	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Desert Cassia	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 30TH AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 30TH AVE	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 30TH AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 30TH AVE	Mahoe	60+"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Sprouting
SW 30TH AVE	Golden Shower Tree	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Limb Damage - Major	Sprouting
SW 30TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 30TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Dead Wood		
SW 30TH AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 30TH AVE	Bougainvillea	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major		
SW 30TH AVE	Mahogany	31-40"	No	35'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 30th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 30TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 30TH AVE	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Line Conflict	Suppressed Canopy		
SW 30TH AVE	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)	Utility Line Conflict	Suppressed Canopy		
SW 30TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 30TH AVE	Avocado	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Leader - Broken	Reduced Canopy - Major
SW 30TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Live Oak	11-15"	No	40'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Limb Damage - Moderate	Sprouting
SW 30TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 30TH AVE	Live Oak	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 30TH AVE	Umbrella Tree	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major	Basal Co-Dominant	
SW 30TH AVE	Umbrella Tree	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Basal Co-Dominant	Constricted Roots
SW 30TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Major	Constricted Roots	Sprouting
SW 30TH AVE	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH AVE	Live Oak	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Leader - Broken	Sprouting
SW 30TH AVE	Weeping Fig	21-30"	No	30'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Constricted Roots	Sprouting
SW 30TH AVE	Weeping Fig	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Significantly Reduced Canopy	Constricted Roots	Sprouting
SW 30TH AVE	Banana Tree	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 30TH AVE	Royal Poinciana	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Minor	

Avenues | Courts



Looking North at SW 21st Street



Looking North at SW 21st Terrace



Looking South from SW 16th Street



Looking South at SW 18th Street



Looking North - from Coral Way



Looking South near SW 19th Street



Looking South towards Coral Way

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 30th Court	3	Parkdale South	4	50	500	No	No	Yes	2	City	Few	Some	6	Yes	Yes	East	
SW 31st Avenue	3	Parkdale South	4	50	2500	No	No	No	2	City	No	No	9	Only Between SW 21st and 22nd Streets	Yes	West	Roundabouts at SW 18th and 19th Streets, Decorative Crosswalk at SW 20th Street. No Outlet at south end. 6' swale on south side

SW 30th Court

TYPOLOGY B

SW 31st Avenue

TYPOLOGY B

Street Tree Inventory

SW 30th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 30TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 30TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leaning - Moderate	
SW 30TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leaning - Moderate	
SW 30TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 30TH CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 30TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 30TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Tapered Trunk	Nutrient Deficiency	
SW 30TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 30TH CT	Christmas Palm	1-5"	No	10'	Poor (21% to 40%)		Nutrient Deficiency	Frizzled Fronds	
SW 30TH CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 30TH CT	Black Olive	31-40"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 30TH CT	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 30TH CT	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)				
SW 30TH CT	Loquat	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Dead Wood
SW 30TH CT	Yellow Tabebuia	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Dead Wood	Codominant Leaders/Included Bark

SW 31st Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 31ST AVE	Black Olive	16-20"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 31ST AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Areca Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Dead Wood	Sprouting
SW 31ST AVE	Black Olive	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 31ST AVE	Live Oak	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	Crown Density - Excessive (Due to Epicormic Growth)
SW 31ST AVE	Live Oak	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	Crown Density - Excessive (Due to Epicormic Growth)
SW 31ST AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy		
SW 31ST AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy		
SW 31ST AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy		
SW 31ST AVE	Live Oak	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	Crown Density - Excessive (Due to Epicormic Growth)
SW 31ST AVE	Weeping Fig	16-20"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 31ST AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 31ST AVE	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 31ST AVE	Christmas Palm	21-30"	No	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 31st Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 31ST AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 31ST AVE	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 31ST AVE	Mahogany	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Sprouting	Limb Damage - Minor
SW 31ST AVE	Weeping Fig	31-40"	No	40'	Poor (21% to 40%)		Reduced Canopy - Major	Constricted Roots	Limb Damage - Major
SW 31ST AVE	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 31ST AVE	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Line Conflict	Pruned Into Shrub		
SW 31ST AVE	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 31ST AVE	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 31ST AVE	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 31ST AVE	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 31ST AVE	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 31ST AVE	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 31ST AVE	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 31ST AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 31ST AVE	Oriental Arborvitae	1-5"	Yes	5'	Good (61% to 80%)				
SW 31ST AVE	Oriental Arborvitae	1-5"	Yes	5'	Good (61% to 80%)				
SW 31ST AVE	Oriental Arborvitae	1-5"	Yes	5'	Good (61% to 80%)				
SW 31ST AVE	Areca Palm	31-40"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Buccaneer Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 31ST AVE	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 31ST AVE	Pigeon Plum	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy	Codominant Leaders/No Included Bark	
SW 31ST AVE	Crepe Myrtle	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 31ST AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Umbrella Tree	21-30"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders - Multi	
SW 31ST AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 31ST AVE	Desert Cassia	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Dead Wood	Insect Damage Leaves
SW 31ST AVE	Desert Cassia	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Dead Wood	Insect Damage Leaves
SW 31ST AVE	Desert Cassia	1-5"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Dead Wood	Insect Damage Leaves
SW 31ST AVE	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Minor	Dead Wood
SW 31ST AVE	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Umbrella Tree	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	
SW 31ST AVE	Umbrella Tree	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	
SW 31ST AVE	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 31ST AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 31ST AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 31st Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 31ST AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Desert Cassia	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Black Olive	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 31ST AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 31ST AVE	Bottle Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 31ST AVE	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 31ST AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 31ST AVE	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 31ST AVE	Bamboo Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	Starburst Clerodendron	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Starburst Clerodendron	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Dead Wood		
SW 31ST AVE	Dracaena sp.	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Prickly Pear Cactus	11-15"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Simpson's Stopper	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 31ST AVE	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 31ST AVE	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 31ST AVE	Red Maple	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 31ST AVE	Cycad	6-10"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 31ST AVE	Red Maple	6-10"	Yes	10'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Dead Wood
SW 31ST AVE	Live Oak	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	
SW 31ST AVE	Live Oak	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	Codominant Leaders/Included Bark
SW 31ST AVE	Live Oak	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Dead Wood		

(Continued on Next Page)

Street Tree Inventory

SW 31st Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 31ST AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Sprouting	Dead Wood	
SW 31ST AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Reduced Canopy - Minor	
SW 31ST AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Sprouting	Suppressed Canopy
SW 31ST AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 31ST AVE	Mango	6-10"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 31ST AVE	Ackee	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major	Dead Wood	Codominant Leaders/Included Bark
SW 31ST AVE	Vera Wood	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 31ST AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 31ST AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Dead Wood	
SW 31ST AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 31ST AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Neem Tree	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Leader - Broken	Basal Co-Dominant
SW 31ST AVE	Bald Cypress	6-10"	No	20'	Good (61% to 80%)		Limb Damage - Minor	Sprouting	
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Tamarind	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood



Looking North at SW 21st Terrace



Looking South towards Coral Way

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 31st Court	3	Parkdale South	4	50	500	No	No	Yes	2	City	Few	Some	6	Yes	Yes	No	6' swale - only on West between SW 21st Street & SW 21st Terrace

*There are no trees on this street

SW 31st Court

TYPOLOGY B



Looking East towards SW 27th Avenue



Looking West near SW 29th Avenue



Looking East towards SW 27th Avenue



Looking East near SW 29th Avenue



Looking West near SW 31st Avenue



Looking West towards SW 32nd Avenue



Looking East near SW 31st Avenue



Looking West towards SW 32nd Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale(ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 16th Terrace	3	Parkdale South	4	50	2600	No	No	Yes- Except between SW 27th and 29th Ave..		City	Some	Some	0	Yes	Yes	North	Paved Swales, some curbed bump-outs, Major transmission lines on North to Power station at SW 27th Avenue. Roundabout at SW 30th Avenue
SW 17th Street	3	Parkdale South	4	50	2600	No	No	No	2	City	Some	Some	9	Yes	Yes	North	Some porous asphalt swales.

SW 16th Terrace

TYPOLOGY C

SW 17th Street

TYPOLOGY C & A

Street Tree Inventory

SW 16th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 16TH TER	Glaucous Cassia	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Leader - Broken	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 16TH TER	Weeping Fig	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure	Trunk Damage - Minor	
SW 16TH TER	Weeping Fig	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Constricted Roots	Dead Wood
SW 16TH TER	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	
SW 16TH TER	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 16TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 16TH TER	Live Oak	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH TER	Live Oak	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 16TH TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Sprouting
SW 16TH TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 16TH TER	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Limb Damage - Minor
SW 16TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 16TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 16TH TER	Foxtail Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH TER	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 16TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Moderate	
SW 16TH TER	Orange Geiger	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Limb Damage - Major	Trunk Damage - Moderate	Sprouting
SW 16TH TER	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Limb Damage - Moderate	Trunk Damage - Minor	Suppressed Canopy
SW 16TH TER	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Dead Wood	
SW 16TH TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 16TH TER	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Glaucous Cassia	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Leader - Broken	Reduced Canopy - Major	Sprouting
SW 16TH TER	Indian Laurel Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 16TH TER	Indian Laurel Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 16TH TER	Indian Laurel Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 16TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	

(Continued on Next Page)

Street Tree Inventory

SW 16th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 16TH TER	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)				
SW 16TH TER	Foxtail Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH TER	Silver Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 16TH TER	Silver Buttonwood	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict			

SW 17th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 17TH ST	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Gumbo Limbo	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Moderate		
SW 17TH ST	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Limb Damage - Minor	
SW 17TH ST	White Frangipani	1-5"	No	Negligible	Dead (0% to 5%)		Leader - Broken	Reduced Canopy - Major	
SW 17TH ST	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)				
SW 17TH ST	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)				
SW 17TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Limb Damage - Minor
SW 17TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Reduced Canopy - Minor
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		One Dead Trunk		
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Mahogany	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Leader - Broken	Constricted Roots
SW 17TH ST	Montgomery Palm	6-10"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 17TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			

(Continued on Next Page)

Street Tree Inventory

SW 17th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 17TH ST	Queen Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Solitaire Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 17TH ST	Spindle Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 17TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Yellow Tabebuia	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 17TH ST	Yellow Tabebuia	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Yellow Tabebuia	1-5"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 17TH ST	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 17TH ST	Weeping Fig	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	
SW 17TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Sprouting	
SW 17TH ST	Dracaena sp.	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 17TH ST	Dracaena sp.	6-10"	Yes	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Leader - Broken	Sprouting
SW 17TH ST	Black Olive	6-10"	No	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Leader - Broken	Sprouting
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Live Oak	11-15"	No	30'	Good (61% to 80%)		Lopsided/Moderately Reduced Canopy	Sprouting	
SW 17TH ST	Weeping Fig	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Constricted Roots	Sprouting
SW 17TH ST	Hibiscus	6-10"	Yes	5'	Good (61% to 80%)				

Streets | Terraces



Looking East towards SW 27th Avenue



Looking West near SW 29th Avenue



Looking East towards SW 27th Avenue



Looking West near SW 29th Avenue



Looking West near SW 30th Avenue



Looking West towards SW 32nd Avenue



Looking West near SW 30th Avenue



Looking West towards SW 32nd Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 18th Street	3	Parkdale South	4	50	2600	No	No	No	2	City	Some	Some	9	Yes	Yes	North	Some porous asphalt swales. Roundabouts at SW 29th and 31st Avenues
SW 19th Street	3	Parkdale South	4	50	2600	No	No	No	2	City	Some	Some	9	Some	Yes	North	Some porous asphalt swales. Roundabouts at SW 29th and 31st Avenues

SW 18th Street
TYPOLOGY C

SW 19th Street
TYPOLOGY A & C

Street Tree Inventory

SW 18th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Foxtail Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 18TH ST	Solitaire Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Solitaire Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Solitaire Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Silver Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Montgomery Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Strangler Fig	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 18TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 18TH ST	Mahogany	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy	Leader - Bent	
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	One Dead Trunk		
SW 18TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Podocarpus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 18TH ST	Podocarpus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 18TH ST	Podocarpus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			

(Continued on Next Page)

Street Tree Inventory

SW 18th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 18TH ST	Podocarpus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 18TH ST	Black Olive	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Sprouting
SW 18TH ST	Sapodilla	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 18TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 18TH ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots		
SW 18TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 18TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate	Dead Wood	
SW 18TH ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Live Oak	21-30"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Sprouting
SW 18TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Black Olive	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH ST	Mahogany	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	31-40"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	31-40"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	31-40"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Dracaena sp.	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Dracaena sp.	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 18TH ST	Live Oak	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Solitaire Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			

(Continued on Next Page)

Street Tree Inventory

SW 18th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 18TH ST	Solitaire Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 18TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)				
SW 18TH ST	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)				
SW 18TH ST	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Podocarpus	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Mahogany	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Insect Damage Leaves	Limb Damage - Minor	

SW 19th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH ST	Desert Cassia	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Insect Damage Leaves		
SW 19TH ST	Desert Cassia	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Insect Damage Leaves		
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Date Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Mahogany	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Sprouting	Constricted Roots
SW 19TH ST	Date Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Minor	
SW 19TH ST	Royal Poinciana	11-15"	No	20'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	Limb Damage - Major
SW 19TH ST	Date Palm	11-15"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH ST	Foxtail Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH ST	Date Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 19TH ST	Date Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 19TH ST	Hibiscus sp.	1-5"	No	10'	Good (61% to 80%)		Basal Co-Dominant with Adjacent Tree(s)		
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Nutrient Deficiency	
SW 19TH ST	Bamboo Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH ST	Weeping Fig	41-50"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	
SW 19TH ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Disease	Reduced Canopy - Moderate
SW 19TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	Reduced Canopy - Minor
SW 19TH ST	Areca Palm	31-40"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH ST	Montgomery Palm	1-5"	No	10'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Dead Meristem	Damaged Fronds	

(Continued on Next Page)

Street Tree Inventory

SW 19th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Mandevilla sp.	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 19TH ST	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Yellow Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Major	Leaning - Moderate	Sprouting
SW 19TH ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH ST	Mahogany	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Mahogany	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH ST	Mahogany	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH ST	Mahogany	31-40"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 19TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Limb Damage - Moderate	Sprouting
SW 19TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 19TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Mahogany	41-50"	No	55'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 19TH ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 19TH ST	Royal Poinciana	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant with Adjacent Tree(s)	Sprouting
SW 19TH ST	Montgomery Palm	6-10"	Yes	15'	Good (61% to 80%)		Suppressed Canopy	Basal Co-Dominant with Adjacent Tree(s)	
SW 19TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Basal Co-Dominant with Adjacent Tree(s)	
SW 19TH ST	Mahogany	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH ST	Live Oak	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 19TH ST	Mahogany	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 19TH ST	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 19TH ST	Mahogany	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Pink Tabebuia	1-5"	No	15'	Fair (41% to 60%)		Basal Co-Dominant with Adjacent Tree(s)	Insect Damage Leaves	

(Continued on Next Page)

Street Tree Inventory

SW 19th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH ST	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)		Basal Co-Dominant with Adjacent Tree(s)	Suppressed Canopy	Nutrient Deficiency
SW 19TH ST	Shoebutton Ardisia	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH ST	Shoebutton Ardisia	1-5"	No	5'	Good (61% to 80%)				
SW 19TH ST	Shoebutton Ardisia	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH ST	Unidentified Citrus Species	1-5"	No	5'	Good (61% to 80%)				
SW 19TH ST	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH ST	Date Palm	6-10"	No	15'	Good (61% to 80%)				
SW 19TH ST	Date Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)				
SW 19TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	
SW 19TH ST	Spindle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Spindle Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Spindle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		

Streets | Terraces



Looking East towards SW 27th Avenue



Looking West near SW 29th Avenue




Looking West near SW 30th Avenue



Looking West towards SW 32nd Avenue



Looking East towards SW 27th Avenue



Looking West near SW 29th Avenue



Looking West near SW 31st Avenue



Looking West towards SW 32nd Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 19th Terrace	3	Parkdale South	4	50	2600	No	No	No	2	City	Some	Some	9	Some	Yes	South	Some porous asphalt swales.
SW 20th Street	3	Parkdale South	4	50	2600	No	No	No	2	City	Some	Some	9	Some	Yes	South	Some porous asphalt swales. Decorative Crosswalk intersection at SW 29th and 31st Avenues

SW 19th Terrace

TYPOLOGY A & C

SW 20th Street

TYPOLOGY A

Street Tree Inventory

SW 19th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH TER	Live Oak	11-15"	No	25'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	
SW 19TH TER	Live Oak	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	
SW 19TH TER	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Reduced Canopy - Minor
SW 19TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	White Geiger	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	
SW 19TH TER	White Geiger	1-5"	No	10'	Good (61% to 80%)				
SW 19TH TER	White Geiger	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Major	Dead Wood	
SW 19TH TER	Buccaneer Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Live Oak	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 19TH TER	Live Oak	11-15"	No	30'	Good (61% to 80%)		Dead Wood		
SW 19TH TER	Live Oak	11-15"	No	35'	Good (61% to 80%)		Dead Wood		
SW 19TH TER	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Reduced Canopy - Moderate
SW 19TH TER	Weeping Fig	31-40"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 19TH TER	White Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Girdling Roots	
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Dracaena sp.	11-15"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Slash Pine	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 19th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH TER	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Royal Poinciana	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 19TH TER	Buccaneer Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Dead Wood	
SW 19TH TER	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Leaning - Major	Sprouting
SW 19TH TER	Live Oak	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 19TH TER	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 19TH TER	Buccaneer Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Bougainvillea	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Gumbo Limbo	11-15"	No	40'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 19TH TER	Mahogany	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Starburst Clerodendron	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH TER	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy	Nutrient Deficiency	
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Starburst Clerodendron	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Glaucous Cassia	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH TER	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)				
SW 19TH TER	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Buccaneer Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Buccaneer Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Weeping Fig	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Dead Wood	Sprouting
SW 19TH TER	Weeping Fig	41-50"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Constricted Roots	Dead Wood
SW 19TH TER	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Constricted Roots	Dead Wood
SW 19TH TER	Buccaneer Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Orange Geiger	1-5"	No	10'	Good (61% to 80%)		Insect Damage Leaves		
SW 19TH TER	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Insect Damage Leaves		
SW 19TH TER	Christmas Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 19th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH TER	Hibiscus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Hibiscus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Hibiscus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH TER	Weeping Fig	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 19TH TER	Mahogany	41-50"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 19TH TER	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 19TH TER	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Mahogany	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH TER	Starburst Clerodendron	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Basal Co-Dominant		
SW 19TH TER	Glaucous Cassia	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH TER	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH TER	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor		
SW 19TH TER	Banana Tree	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	White Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH TER	Gumbo Limbo	11-15"	No	40'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 19TH TER	Mahogany	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Starburst Clerodendron	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH TER	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy	Nutrient Deficiency	
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Starburst Clerodendron	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Glaucous Cassia	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH TER	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 19th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH TER	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Buccaneer Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Buccaneer Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Weeping Fig	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Dead Wood	Sprouting
SW 19TH TER	Weeping Fig	41-50"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Constricted Roots	Dead Wood
SW 19TH TER	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Constricted Roots	Dead Wood
SW 19TH TER	Buccaneer Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Orange Geiger	1-5"	No	10'	Good (61% to 80%)		Insect Damage Leaves		
SW 19TH TER	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Insect Damage Leaves		
SW 19TH TER	Christmas Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 19TH TER	Hibiscus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Hibiscus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Hibiscus	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH TER	Weeping Fig	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 19TH TER	Mahogany	41-50"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 19TH TER	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 19TH TER	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Mahogany	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH TER	Starburst Clerodendron	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Basal Co-Dominant		
SW 19TH TER	Glaucous Cassia	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH TER	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor		
SW 19TH TER	Banana Tree	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	White Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			

Street Tree Inventory

SW 20th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Leaning - Moderate	
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 20TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Leaning - Moderate	Tapered Trunk	Suppressed Canopy
SW 20TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Tapered Trunk		
SW 20TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Date Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Date Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Date Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Basal Co-Dominant with Adjacent Tree(s)		
SW 20TH ST	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Royal Poinciana	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant with Adjacent Tree(s)	Leader - Bent	Lopsided/Moderately Reduced Canopy
SW 20TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Umbrella Tree	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Gumbo Limbo	16-20"	No	35'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 20TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 20TH ST	Cycad	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 20TH ST	Japanese Privet	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Dead Wood		
SW 20TH ST	Cycad	6-10"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 20TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 20TH ST	Cycad	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 20TH ST	Calamondin sp.	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 20TH ST	Cycad	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 20TH ST	Indian Laurel Fig	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Limb Damage - Major	Sprouting
SW 20TH ST	Live Oak	11-15"	No	40'	Good (61% to 80%)		Dead Wood		
SW 20TH ST	Mango	6-10"	No	20'	Fair (41% to 60%)		Leaning - Major	Suppressed Canopy	
SW 20TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Limb Damage - Moderate	
SW 20TH ST	Spindle Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 20th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 20TH ST	Spindle Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 20TH ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)		Dead Wood		
SW 20TH ST	Vera Wood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Simpson's Stopper	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 20TH ST	Gumbo Limbo	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Minor	
SW 20TH ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Crepe Myrtle	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots		
SW 20TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Dead Wood		
SW 20TH ST	Weeping Fig	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Leader - Broken	Basal Co-Dominant
SW 20TH ST	Weeping Fig	41-50"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Significantly Reduced Canopy	Constricted Roots	Leaning - Major
SW 20TH ST	Weeping Fig	31-40"	No	45'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Major	Constricted Roots	Sprouting
SW 20TH ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)		Reduced Canopy - Major	Constricted Roots	Sprouting
SW 20TH ST	Weeping Fig	16-20"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Constricted Roots	Sprouting
SW 20TH ST	Black Olive	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Constricted Roots	Sprouting
SW 20TH ST	Black Olive	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Constricted Roots	Sprouting
SW 20TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Constricted Roots	Sprouting
SW 20TH ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Constricted Roots	Sprouting
SW 20TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Constricted Roots	Sprouting
SW 20TH ST	Weeping Fig	16-20"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Sprouting	Leader - Broken
SW 20TH ST	Mahogany	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Constricted Roots	Sprouting
SW 20TH ST	Mahogany	41-50"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Constricted Roots	Dead Wood
SW 20TH ST	Ixora	6-10"	Yes	5'	Good (61% to 80%)				
SW 20TH ST	Yucca sp.	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Washington Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 20TH ST	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 20TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 20TH ST	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Strangler Fig	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Sacred Fig	1-5"	No	5'	Good (61% to 80%)		Basal Co-Dominant with Adjacent Tree(s)		
SW 20TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Longan	1-5"	No	5'	Good (61% to 80%)				
SW 20TH ST	Spindle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 20th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 20TH ST	Washington Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 20TH ST	Washington Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Spindle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Spindle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Spindle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 20TH ST	Mahogany	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Dead Wood	
SW 20TH ST	Live Oak	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 20TH ST	Weeping Fig	51-60"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Indian Laurel Fig	41-50"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 20TH ST	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Dead Wood	
SW 20TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Leaning - Moderate		
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 20TH ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Orange Geiger	6-10"	No	10'	Good (61% to 80%)		Insect Damage Leaves		
SW 20TH ST	Orange Geiger	1-5"	No	5'	Fair (41% to 60%)		Insect Damage Leaves		
SW 20TH ST	Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			

Street| Terraces



Looking East from SW 30th Court - No Outlet



Looking West near SW 30th Court



Bend to SW 21st Terrace



Looking East towards bend to SW 21st Terrace



Looking West near SW 31st Court



Looking East at SW 31st Court



Looking west from SW 27th Avenue



Looking East at SW 27th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 21st Street-West	3	Parkdale South	4	50	1200	No	No	No	2	City	Few	Few	6	Yes	Yes	North	No Outlet at East end
SW 21st Street-East	3	Parkdale South	4	50	1200	No	No	No	2	City	Few	Few	9	No	Yes	North	Turns into SW 21st Terrace (East)

SW 21st Street-West

TYPOLOGY B

SW 21st Street -East

TYPOLOGY B

Street Tree Inventory

SW 21st Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 21ST ST	Orange Geiger	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Insect Damage Leaves	
SW 21ST ST	Pigeon Plum	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Leaning - Moderate		
SW 21ST ST	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 21ST ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 21ST ST	Tropical Almond	1-5"	No	5'	Good (61% to 80%)				
SW 21ST ST	Horseradish Tree	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 21ST ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Mango	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Neem Tree	11-15"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Dead Wood	Limb Damage - Moderate
SW 21ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 21ST ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Limb Damage - Moderate	Dead Wood
SW 21ST ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots		
SW 21ST ST	Royal Poinciana	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 21ST ST	Triangle Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Triangle Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Leaning - Moderate	
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Leaning - Moderate	
SW 21ST ST	Rubber Tree	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Leaning - Moderate		
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Leaning - Moderate		
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Leaning - Moderate		
SW 21ST ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots		
SW 21ST ST	Bamboo Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Moderate		
SW 21ST ST	Sandbox Tree	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST ST	Papaya Tree	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 21ST ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Basal Co-Dominant	Limb Damage - Moderate	
SW 21ST ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 21st Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Weeping Fig	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 21ST ST	Woman's Tongue	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 21ST ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Basal Co-Dominant	Reduced Canopy - Minor	
SW 21ST ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 21ST ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 21ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate	Dead Wood	
SW 21ST ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 21ST ST	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 21ST ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST ST	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST ST	Areca Palm	16-20"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST ST	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST ST	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST ST	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Hibiscus	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above			
SW 21ST ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant with Adjacent Tree(s)	Suppressed Canopy	
SW 21ST ST	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant with Adjacent Tree(s)	Reduced Canopy - Moderate	
SW 21ST ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Reduced Canopy - Minor
SW 21ST ST	Bottlebrush	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Dead Wood	Leaning - Moderate

Street| Terraces



Rounding the bend from SW 21st Street



Looking East from SW 31st Avenue



At SW 32nd Avenue - West end



Looking West near SW 31st Court



Looking East towards SW 27th Avenue



Looking East at SW 27th Avenue - East end



Looking West near SW 31st Avenue



Looking East towards SW 30th Court

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 21st Terrace -West	3	Parkdale South	4	50	1200	No	No	Yes	2	City	Few	Few	6	Yes	Yes	North	
SW 21st Terrace - East	3	Parkdale South	4	50	1200	No	Some on South	No	2	City	Few	Few	12	Some on South	Yes	North	Turns into SW 21st Street (East). No swale on South side

SW 21st Terrace-West

TYPOLOGY A

SW 21st Terrace -East

TYPOLOGY E

Street Tree Inventory

SW 21st Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 21ST TER	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Leaning - Moderate		
SW 21ST TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Minor
SW 21ST TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 21ST TER	Weeping Fig	21-30"	No	Negligible	Dead (0% to 5%)				
SW 21ST TER	Weeping Fig	16-20"	No	Negligible	Dead (0% to 5%)				
SW 21ST TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leaning - Moderate	
SW 21ST TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 21ST TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Pink Tabebuia	11-15"	No	Negligible	Dead (0% to 5%)				
SW 21ST TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 21ST TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Mahogany	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 21ST TER	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Leader - Broken	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 21ST TER	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 21ST TER	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Leaning - Moderate
SW 21ST TER	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 21ST TER	Black Olive	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST TER	Norfolk Pine	16-20"	No	10'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	
SW 21ST TER	Norfolk Pine	11-15"	No	10'	Fair (41% to 60%)		Constricted Roots		
SW 21ST TER	Norfolk Pine	16-20"	No	15'	Fair (41% to 60%)		Constricted Roots		
SW 21ST TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency	Leaning - Moderate	
SW 21ST TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Leaning - Moderate	
SW 21ST TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 21st Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 21ST TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Washington Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 21ST TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 21ST TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 21ST TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 21ST TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 21ST TER	Oriental Arborvitae	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Royal Poinciana	11-15"	No	20'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Leader - Broken
SW 21ST TER	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	
SW 21ST TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	
SW 21ST TER	Royal Poinciana	11-15"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 21ST TER	Weeping Fig	21-30"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST TER	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST TER	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Silver Buttonwood	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 21ST TER	Silver Buttonwood	6-10"	No	15'	Good (61% to 80%)		Basal Co-Dominant		
SW 21ST TER	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SW 21ST TER	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Leaning - Moderate		
SW 21ST TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 21ST TER	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Basal Co-Dominant		
SW 21ST TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Oleander	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Oleander	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Oleander	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 21st Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Date Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Date Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Date Palm	11-15"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 21ST TER	Live Oak	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 21ST TER	Live Oak	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Basal Co-Dominant	Suppressed Canopy	
SW 21ST TER	Live Oak	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Suppressed Canopy		
SW 21ST TER	Brazilian Pepper	1-5"	Yes	15'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Suppressed Canopy		
SW 21ST TER	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Shaving Brush Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Bordering Streets



At SW 32nd Avenue



At SW 22nd Avenue



At SW 16th Street - North end



Looking North near SW 18th Street



At SW 29th Ave



At SW 27th Avenue



Looking South near SW 20th Street



At SW Coral Way - South end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 22nd Street - Coral Way	3	Parkdale South	4	60	2,700	No	No	Yes- Except between SW 27th and 29th Ave..	4	State	No	No	0	Yes	Yes	North	No Bike lane on this section - Share the Road- Full Lane Markings
SW 27th Avenue -Unity Boulevard - SR 9	3	Parkdale South	4	100	2700	Some	No	Intermittent	4	State	Some in Median	Some in Median	0	Yes	Yes	No	Street Lights-Signalized at SW 22nd Avenue and SW 16th Avenue

SW 22nd Street - Coral Way

TYPOLOGY E

SW 27th Avenue - Unity Boulevard - SR 9

TYPOLOGY A

Street Tree Inventory

SW 27th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 27TH AVE	Montgomery Palm	1-5"	No	5'	Fair (41% to 60%)		Pencil Top		
SW 27TH AVE	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	1-5"	No	5'	Fair (41% to 60%)		Pencil Top		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Moderate		
SW 27TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Royal Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Royal Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Royal Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Royal Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 27TH AVE	Montgomery Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		

Bordering Streets



Looking South at SW 16th Avenue



Looking South near SW




At SW 32nd Avenue - West end



Looking East near SW 30th Ave



Looking North near SW 19th Street



Looking North towards Coral Way



Looking East near SW 29th Ave



At SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 32nd Avenue - McDonald Street	3	Parkdale South	4	60	2700	No	No	No	2	City	Some		16	Some	Yes	No	Street Lights - Signalized at SW 22nd Avenue and SW 16th Avenue. Some on-street parking
SW 16th Street	3	Parkdale South	4	60	2,700	No	No	Yes	2	City	No	No	0	Yes	Yes	North	No Bike lane on this section - Share the Road- Full Lane Markings

SW 32nd Avenue - McDonald Street

TYPOLOGY A

SW 16th Street

TYPOLOGY B

Street Tree Inventory

SW 32nd Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 32ND AVE	Royal Palm	16-20"	No	10'	Fair (41% to 60%)		Crown Density - Moderate	Tapered Trunk	Nutrient Deficiency
SW 32ND AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)		Dead Wood		
SW 32ND AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 32ND AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Major	Dead Wood	
SW 32ND AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Major	Dead Wood	
SW 32ND AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 32ND AVE	Live Oak	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 32ND AVE	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 32ND AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 32ND AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 32ND AVE	Date Palm	6-10"	No	10'	Good (61% to 80%)				
SW 32ND AVE	Royal Poinciana	11-15"	No	35'	Poor (21% to 40%)		Leaning - Major	Lopsided/Significantly Reduced Canopy	Suppressed Canopy
SW 32ND AVE	Date Palm	6-10"	No	15'	Good (61% to 80%)				
SW 32ND AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 32ND AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 32ND AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 32ND AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 32ND AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			

*Note there are no trees on SW 16th Street



CORAL GATE

Avenues | Courts | Places



Looking South from SW 16th Terrace - north end



Looking North - at SW 18th Street



Looking North from SW 20th Street - South End



Looking North mid block




Looking South near SW 32nd Place



Looking south near SW 20th Street - south end



Looking North towards SW 32nd Court



Looking east towards SW 32nd Court - north end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 32nd Court	3	Coral Gate	4	60	1500	No	No	No	2	City	Some	Few	12	No	Yes	No	Roundabout at SW 18th Street - Pedestrian Light Poles on East
SW 32nd Place	3	Coral Gate	4	60	600	No	No	No	2	City	Some	Few	12(East side) 15(West side)	No	Yes	No	Pedestrian Light Poles on West

SW 32nd Court

TYPOLOGY A

SW 32nd Place

TYPOLOGY A

Street Tree Inventory

SW 32nd Court

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 32ND CT	Avocado	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Sprouting	
SW 32ND CT	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting	
SW 32ND CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 32ND CT	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)					
SW 32ND CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 32ND CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 32ND CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 32ND CT	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 32ND CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 32ND CT	Coconut Palm	6-10"	No	15'	Good (61% to 80%)					
SW 32ND CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 32ND CT	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency			
SW 32ND CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)					
SW 32ND CT	Coconut Palm	11-15"	No	20'	Good (61% to 80%)					
SW 32ND CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)					
SW 32ND CT	Crepe Myrtle	11-15"	No	20'	Good (61% to 80%)					
SW 32ND CT	Crepe Myrtle	16-20"	Yes	20'	Good (61% to 80%)					
SW 32ND CT	Gumbo Limbo	11-15"	No	15'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/No Included Bark		
SW 32ND CT	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Crown Density - Moderate	Epicormic Growth	Codominant Leaders/Included Bark	
SW 32ND CT	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Improperly Mulched	Crown Density - Low	Epicormic Growth	
SW 32ND CT	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Moderate	Epicormic Growth		
SW 32ND CT	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Moderate	Epicormic Growth	
SW 32ND CT	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Moderate	Epicormic Growth	
SW 32ND CT	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Crown Density - Moderate	Epicormic Growth		
SW 32ND CT	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
SW 32ND CT	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Epicormic Growth	Codominant Leaders/Included Bark	Codominant Leaders/Included Bark	
SW 32ND CT	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 32ND CT	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Apical Dieback	Epicormic Growth	Codominant Leaders/No Included Bark	
SW 32ND CT	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND CT	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Limb Damage - Moderate	Sprouting	
SW 32ND CT	Mahogany	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy			
SW 32ND CT	Mahogany	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 32ND CT	Mahogany	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 32ND CT	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	Codominant Leaders/Included Bark	
SW 32ND CT	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 32ND CT	Melaleuca	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood	
SW 32ND CT	Paradise Tree	6-10"	No	15'	Good (61% to 80%)					
SW 32ND CT	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate			
SW 32ND CT	Queen Palm	6-10"	No	20'	Good (61% to 80%)					
SW 32ND CT	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Dead Wood	Crown Density - Moderate	
SW 32ND CT	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 32ND CT	Royal Poinciana	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 32ND CT	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND CT	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 32ND CT	Royal Poinciana	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 32ND CT	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Dead Wood	Sprouting	
SW 32ND CT	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched			
SW 32ND CT	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)					
SW 32ND CT	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)					
SW 32ND CT	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)					
SW 32ND CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
SW 32ND CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
SW 32ND CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy			
SW 32ND CT	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy			
SW 32ND CT	Tamarind	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 32ND CT	Tamarind	6-10"	No	15'	Good (61% to 80%)					
SW 32ND CT	Tropical Almond	16-20"	No	50'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting	
SW 32ND CT	Umbrella Tree	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting	
SW 32ND CT	Umbrella Tree	21-30"	No	15'	Poor (21% to 40%)		Constricted Roots	Topped	Trunk Damage - Major	
SW 32ND CT	Weeping Fig	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting	

(Continued on Next Page)

Street Tree Inventory

SW 32nd Court (Continued)


Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 32ND CT	White Geiger	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched			
SW 32ND CT	Yellow Tabebuia	1-5"	No	5'	Poor (21% to 40%)		Restricted Canopy	Nutrient Deficiency		

Street Tree Inventory

SW 32nd Place

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 32ND PL	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Reduced Canopy - Minor	Stubs with Sprouts	Codominant Leaders/Included Bark	
SW 32ND PL	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 32ND PL	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 32ND PL	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark		
SW 32ND PL	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
SW 32ND PL	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Epicormic Growth	
SW 32ND PL	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood			
SW 32ND PL	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Epicormic Growth		
SW 32ND PL	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark		
SW 32ND PL	Live Oak	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Limb Damage - Minor	Sprouting	
SW 32ND PL	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark		
SW 32ND PL	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
SW 32ND PL	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
SW 32ND PL	Live Oak	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 32ND PL	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 32ND PL	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting	
SW 32ND PL	Live Oak	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Sprouting		
SW 32ND PL	Live Oak	11-15"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 32ND PL	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Moderate	Epicormic Growth	Dead Wood	
SW 32ND PL	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Moderate	Epicormic Growth	Codominant Leaders/No Included Bark	
SW 32ND PL	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark		
SW 32ND PL	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 32ND PL	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 32ND PL	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Minor	Sprouting	
SW 32ND PL	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark		
SW 32ND PL	Orange Geiger	6-10"	No	10'	Poor (21% to 40%)		Topped	Insect Damage Leaves		
SW 32ND PL	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND PL	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting	
SW 32ND PL	Royal Poinciana	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Sprouting	Limb Damage - Minor	
SW 32ND PL	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND PL	Royal Poinciana	11-15"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 32ND PL	Silk Floss Tree	6-10"	No	10'	Good (61% to 80%)		Seasonal Defoliation/Discolored Foliage			
SW 32ND PL	Slash Pine	6-10"	No	15'	Good (61% to 80%)					
SW 32ND PL	Solitaire Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 32ND PL	Weeping Fig	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		

Avenues | Courts | Places



Looking South towards Coral Way - south end



Looking South at SW 21st Street roundabout



Looking North at SW 18th Street - North end



Looking North mid block



Looking south towards SW 20th Street mid block



Looking South towards SW 20th Street - jog in road



Looking North toward south end of street



Looking North from SW 20th Street - south end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 33rd Avenue	3	Coral Gate	4	60	1200	No	No	No	2	City	Some	Few	15	No	Yes	No	Pedestrian Light Poles on East
SW 33rd Court	3	Coral Gate	4	60	1200	No	No	No	2	City	Some	Few	15	No	Yes	No	Pedestrian Light Poles on East

SW 33rd Avenue

TYPOLOGY A

SW 33rd Court

TYPOLOGY A

Street Tree Inventory

SW 33rd Avenue

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 33RD AVE	Bismark Palm	16-20"	No	20'	Good (61% to 80%)					
SW 33RD AVE	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Sprouting		
SW 33RD AVE	Black Olive	11-15"	No	15'	Poor (21% to 40%)		Apical Dieback	Basal Co-Dominant		
SW 33RD AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting	
SW 33RD AVE	Christmas Palm	11-15"	No	10'	Good (61% to 80%)					
SW 33RD AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)					
SW 33RD AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)					
SW 33RD AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 33RD AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 33RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 33RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 33RD AVE	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)					
SW 33RD AVE	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)					
SW 33RD AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)					
SW 33RD AVE	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)					
SW 33RD AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency			
SW 33RD AVE	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Over Pruned	Nutrient Deficiency		
SW 33RD AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)					
SW 33RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)					
SW 33RD AVE	Earleaf Acacia	21-30"	No	30'	Poor (21% to 40%)		Girdling Roots	Topped	Sprouting	
SW 33RD AVE	Frangipani	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Crown Density - Very Low		
SW 33RD AVE	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Codominant Leaders/Included Bark		
SW 33RD AVE	Gumbo Limbo	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 33RD AVE	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Suppressed Canopy		
SW 33RD AVE	Hong Kong Orchid	1-5"	No	10'	Poor (21% to 40%)		Basal Co-Dominant	Disease		
SW 33RD AVE	Hong Kong Orchid	1-5"	No	10'	Poor (21% to 40%)		Basal Co-Dominant	Disease		
SW 33RD AVE	Hong Kong Orchid	1-5"	No	10'	Poor (21% to 40%)		Basal Co-Dominant	Disease		
SW 33RD AVE	Hong Kong Orchid	1-5"	No	10'	Poor (21% to 40%)		Basal Co-Dominant	Disease		
SW 33RD AVE	Italian Cypress	1-5"	No	5'	Good (61% to 80%)		Discolored Foliage			
SW 33RD AVE	Jacaranda	1-5"	No	5'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy			
SW 33RD AVE	Japanese Privet	1-5"	No	10'	Good (61% to 80%)					
SW 33RD AVE	Lead Tree	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Moderate	Dead Wood	
SW 33RD AVE	Live Oak	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark	
SW 33RD AVE	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 33RD AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched			
SW 33RD AVE	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Apical Dieback		
SW 33RD AVE	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 33RD AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)					
SW 33RD AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 33RD AVE	Live Oak	11-15"	No	20'	Poor (21% to 40%)		Plunged	Crown Density - Very Low	Epicormic Growth	
SW 33RD AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 33RD AVE	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 33RD AVE	Live Oak	16-20"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	Codominant Leaders/Included Bark	
SW 33RD AVE	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 33RD AVE	Live Oak	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 33RD AVE	Mahogany	16-20"	No	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting	
SW 33RD AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting	
SW 33RD AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict				
SW 33RD AVE	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 33RD AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above				
SW 33RD AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above				
SW 33RD AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above				
SW 33RD AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above				
SW 33RD AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above				
SW 33RD AVE	Montgomery Palm	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above				
SW 33RD AVE	Neem Tree	11-15"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Dead Wood	
SW 33RD AVE	Neem Tree	16-20"	No	20'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Crown Density - Very Low	Dead Wood	
SW 33RD AVE	Paradise Tree	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 33rd Avenue (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 33RD AVE	Paradise Tree	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor	Reduced Canopy - Minor		
SW 33RD AVE	Paradise Tree	1-5"	No	5'	Good (61% to 80%)					
SW 33RD AVE	Royal Poinciana	6-10"	No	15'	Fair (41% to 60%)		Cracks in Trunk	Lopsided/Moderately Reduced Canopy		
SW 33RD AVE	Royal Poinciana	6-10"	No	20'	Fair (41% to 60%)		Leader - Bent	Reduced Canopy - Moderate		
SW 33RD AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)					
SW 33RD AVE	Spicewood	6-10"	No	10'	Fair (41% to 60%)		Basal Co-Dominant	Restricted Canopy		
SW 33RD AVE	Umbrella Tree	11-15"	No	10'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting	
SW 33RD AVE	Umbrella Tree	16-20"	No	10'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting	
SW 33RD AVE	Umbrella Tree	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed	
SW 33RD AVE	Unid 3	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency			
SW 33RD AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)					
SW 33RD AVE	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)		Reduced Canopy - Moderate	Sprouting	Dead Wood	

Street Tree Inventory

SW 33rd Court

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 33RD CT	Black Olive	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting	
SW 33RD CT	Black Olive	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood	
SW 33RD CT	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting	
SW 33RD CT	Black Olive	16-20"	No	15'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed	
SW 33RD CT	Black Olive	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 33RD CT	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 33RD CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 33RD CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 33RD CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 33RD CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)					
SW 33RD CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 33RD CT	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 33RD CT	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 33RD CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)					
SW 33RD CT	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency			
SW 33RD CT	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency			
SW 33RD CT	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned	Suppressed Canopy		
SW 33RD CT	Crepe Myrtle	6-10"	No	20'	Good (61% to 80%)					
SW 33RD CT	Crepe Myrtle	6-10"	No	20'	Good (61% to 80%)					
SW 33RD CT	Crepe Myrtle	16-20"	No	20'	Good (61% to 80%)					
SW 33RD CT	Crepe Myrtle	6-10"	No	15'	Good (61% to 80%)					
SW 33RD CT	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Restricted Canopy		
SW 33RD CT	Gumbo Limbo	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 33RD CT	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Codominant Leaders/Included Bark	
SW 33RD CT	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 33RD CT	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Moderate	Epicormic Growth	
SW 33RD CT	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Improperly Mulched	Crown Density - Very Low		
SW 33RD CT	Live Oak	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting		
SW 33RD CT	Live Oak	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 33RD CT	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 33RD CT	Live Oak	1-5"	No	15'	Good (61% to 80%)					
SW 33RD CT	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 33RD CT	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 33RD CT	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Moderate			
SW 33RD CT	Loquat	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Sprouting		
SW 33RD CT	Narrow Leaf Ficus	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency			
SW 33RD CT	Pink Tabebuia	11-15"	No	10'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting	
SW 33RD CT	Pink Tabebuia	21-30"	No	20'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 33RD CT	Pink Tabebuia	16-20"	No	20'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	
SW 33RD CT	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	Sprouting	
SW 33RD CT	Pink Tabebuia	21-30"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Codominant Leaders/No Included Bark	
SW 33RD CT	Pink Tabebuia	11-15"	No	15'	Poor (21% to 40%)		Codominant Leaders/Included Bark	Trunk Damage - Major	Decay Observed	
SW 33RD CT	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 33RD CT	Queen Palm	11-15"	No	25'	Good (61% to 80%)					
SW 33RD CT	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 33RD CT	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting	
SW 33RD CT	Royal Poinciana	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 33RD CT	Royal Poinciana	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	Dead Wood	
SW 33RD CT	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts		
SW 33RD CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)					
SW 33RD CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)					
SW 33RD CT	Starburst Clerodendron	11-15"	Yes	10'	Good (61% to 80%)					
SW 33RD CT	Tropical Almond	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 33RD CT	Weeping Fig	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Broken Branches	
SW 33RD CT	Weeping Fig	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Broken Branches	
SW 33RD CT	Wild/Cuban Tamarind	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 33RD CT	Wild/Cuban Tamarind	11-15"	No	25'	Good (61% to 80%)		Root Damage/Decay	Codominant Leaders/No Included Bark		
SW 33RD CT	Yellow Poinciana	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting	

Avenues | Courts | Places



Looking South towards Coral Way - south end



Looking South at SW 21st Street roundabout



Lookingnorth towards SW 17th Street roundabout



LookingNorth from SW 17th Street



Looking South from SW 20th Street roundabout



Looking north towards SW 18th Street



Looking North towards SW 16th Terrace roundabout



Looking North from SW 16th Terrace - north end - no outlet

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
Coral Gate Drive	3	Coral Gate	4	60	2800	Only at Coral Way	No	No	2	City	Some	Few	15	Only at Coral Way	Yes	No	Roundabouts at SW 21st St., SW 17th St., and SW 16th Terrace.estricted turn /Roundabout at SW 20th St. Pedestrian Light Poles on West

Coral Gate Drive

TYPOLOGY A

Street Tree Inventory

Coral Gate Drive

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
CORAL GATE DR	Bismark Palm	16-20"	No	25'	Good (61% to 80%)					
CORAL GATE DR	Bismark Palm	21-30"	No	25'	Good (61% to 80%)					
CORAL GATE DR	Black Olive	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark			
CORAL GATE DR	Black Olive	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy		
CORAL GATE DR	Black Olive	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark			
CORAL GATE DR	Black Olive	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark			
CORAL GATE DR	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
CORAL GATE DR	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting	
CORAL GATE DR	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting	
CORAL GATE DR	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting	
CORAL GATE DR	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
CORAL GATE DR	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
CORAL GATE DR	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
CORAL GATE DR	Black Olive	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
CORAL GATE DR	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
CORAL GATE DR	Cabbage Palm	6-10"	No	5'	Good (61% to 80%)					low can recent install
CORAL GATE DR	Cabbage Palm	6-10"	No	5'	Good (61% to 80%)					low can recent install
CORAL GATE DR	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict				
CORAL GATE DR	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict				
CORAL GATE DR	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)	Utility Line Conflict				
CORAL GATE DR	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict				
CORAL GATE DR	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)	Utility Line Conflict				
CORAL GATE DR	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict				
CORAL GATE DR	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict				
CORAL GATE DR	Canary Island Date Palm	21-30"	No	20'	Fair (41% to 60%)		Nutrient Deficiency			
CORAL GATE DR	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)					
CORAL GATE DR	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
CORAL GATE DR	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)					
CORAL GATE DR	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
CORAL GATE DR	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
CORAL GATE DR	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
CORAL GATE DR	Christmas Palm	16-20"	Yes	10'	Good (61% to 80%)					
CORAL GATE DR	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
CORAL GATE DR	Coconut Palm	6-10"	No	15'	Good (61% to 80%)					
CORAL GATE DR	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency			
CORAL GATE DR	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency			
CORAL GATE DR	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency			
CORAL GATE DR	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
CORAL GATE DR	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
CORAL GATE DR	Crepe Myrtle	16-20"	No	25'	Fair (41% to 60%)		Epicormic Growth			
CORAL GATE DR	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)					
CORAL GATE DR	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)					
CORAL GATE DR	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)					
CORAL GATE DR	Crepe Myrtle	6-10"	No	20'	Good (61% to 80%)					
CORAL GATE DR	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)					
CORAL GATE DR	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched	Trunk Damage - Minor		
CORAL GATE DR	Crepe Myrtle	21-30"	Yes	20'	Good (61% to 80%)					
CORAL GATE DR	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)					
CORAL GATE DR	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched			
CORAL GATE DR	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched			
CORAL GATE DR	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)					
CORAL GATE DR	Frangipani	1-5"	No	10'	Good (61% to 80%)		Seasonal Defoliation/Discolored Foliage			
CORAL GATE DR	Frangipani	6-10"	No	15'	Good (61% to 80%)		Seasonal Defoliation/Discolored Foliage			
CORAL GATE DR	Golden Shower Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark			
CORAL GATE DR	Golden Shower Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
CORAL GATE DR	Golden Shower Tree	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs	Dead Wood	
CORAL GATE DR	Golden Shower Tree	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Dead Wood	
CORAL GATE DR	Golden Shower Tree	11-15"	No	25'	Fair (41% to 60%)		Girdling Roots	Restricted Canopy	Dead Wood	
CORAL GATE DR	Gumbo Limbo	16-20"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark			

(Continued on Next Page)

Street Tree Inventory

Coral Gate Drive (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
CORAL GATE DR	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Codominant Leaders/No Included Bark	Galls	
CORAL GATE DR	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/No Included Bark		
CORAL GATE DR	Gumbo Limbo	6-10"	No	5'	Fair (41% to 60%)		Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy		
CORAL GATE DR	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
CORAL GATE DR	Hong Kong Orchid	11-15"	No	30'	Poor (21% to 40%)		Topped	Sprouting	Codominant Leaders/No Included Bark	
CORAL GATE DR	Java Bishopwood	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting	
CORAL GATE DR	Live Oak	1-5"	No	5'	Good (61% to 80%)					
CORAL GATE DR	Live Oak	1-5"	No	5'	Good (61% to 80%)					
CORAL GATE DR	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
CORAL GATE DR	Live Oak	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood	
CORAL GATE DR	Live Oak	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
CORAL GATE DR	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting	
CORAL GATE DR	Live Oak	1-5"	No	10'	Poor (21% to 40%)		Plunged	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy	
CORAL GATE DR	Live Oak	16-20"	No	20'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Epicormic Growth		
CORAL GATE DR	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Plunged	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark	
CORAL GATE DR	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Epicormic Growth		
CORAL GATE DR	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Epicormic Growth		
CORAL GATE DR	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
CORAL GATE DR	Live Oak	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark			
CORAL GATE DR	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
CORAL GATE DR	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/No Included Bark	Dead Wood	
CORAL GATE DR	Live Oak	1-5"	No	15'	Good (61% to 80%)					
CORAL GATE DR	Live Oak	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
CORAL GATE DR	Live Oak	1-5"	No	5'	Good (61% to 80%)					
CORAL GATE DR	Live Oak	6-10"	No	15'	Poor (21% to 40%)		Crown Density - Low	Epicormic Growth		air plants
CORAL GATE DR	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
CORAL GATE DR	Live Oak	21-30"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Sprouting		
CORAL GATE DR	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
CORAL GATE DR	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting	
CORAL GATE DR	Live Oak	6-10"	No	20'	Good (61% to 80%)					
CORAL GATE DR	Live Oak	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
CORAL GATE DR	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
CORAL GATE DR	Live Oak	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
CORAL GATE DR	Live Oak	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Girdling Roots		
CORAL GATE DR	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
CORAL GATE DR	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed	
CORAL GATE DR	Mahogany	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts	
CORAL GATE DR	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Restricted Canopy		
CORAL GATE DR	Mahogany	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched			
CORAL GATE DR	Mahogany	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched			
CORAL GATE DR	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting	
CORAL GATE DR	Mahogany	16-20"	No	25'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed	
CORAL GATE DR	Mahogany	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting	
CORAL GATE DR	Mahogany	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting	
CORAL GATE DR	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting	
CORAL GATE DR	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Limb Damage - Moderate	
CORAL GATE DR	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting	
CORAL GATE DR	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood	large overhang dead branch
CORAL GATE DR	Mahogany	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Ficus Growing on Tree	Codominant Leaders/Included Bark	
CORAL GATE DR	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood	
CORAL GATE DR	Mahogany	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting	
CORAL GATE DR	Mahogany	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting	
CORAL GATE DR	Mahogany	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting	
CORAL GATE DR	Melaleuca	31-40"	No	10'	Poor (21% to 40%)	Utility Lines Above	Basal Co-Dominant	Topped	Strap Constricting Tree	
CORAL GATE DR	Melaleuca	41-50"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Topped	Sprouting	
CORAL GATE DR	Melaleuca	51-60"	No	20'	Poor (21% to 40%)		Basal Co-Dominant with Adjacent Tree(s)	Topped	Sprouting	
CORAL GATE DR	Peregrina	11-15"	Yes	10'	Good (61% to 80%)		Restricted Canopy			

(Continued on Next Page)

Street Tree Inventory

Coral Gate Drive (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
CORAL GATE DR	Peregrina	6-10"	Yes	15'	Fair (41% to 60%)		Basal Co-Dominant			
CORAL GATE DR	Pink Tabebuia	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting	
CORAL GATE DR	Pink Tabebuia	11-15"	No	15'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting	
CORAL GATE DR	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Sprouting		
CORAL GATE DR	Pink Tabebuia	16-20"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Adjacent Light Pole		
CORAL GATE DR	Queen Palm	6-10"	No	15'	Good (61% to 80%)					
CORAL GATE DR	Red Cassia	11-15"	No	15'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Apical Dieback	Codominant Leaders/Included Bark	
CORAL GATE DR	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Decay Observed	
CORAL GATE DR	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts	
CORAL GATE DR	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
CORAL GATE DR	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
CORAL GATE DR	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
CORAL GATE DR	Southern Magnolia	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark			
CORAL GATE DR	Tamarind	11-15"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark			
CORAL GATE DR	Tropical Almond	21-30"	No	60'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Topped	
CORAL GATE DR	Unid 1	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Topped	Strap Constricting Tree	see pics
CORAL GATE DR	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Improperly Mulched			
CORAL GATE DR	Vera Wood	1-5"	No	15'	Poor (21% to 40%)		Plunged	Crown Density - Excessive (Due to Epicormic Growth)		
CORAL GATE DR	Vera Wood	6-10"	No	15'	Fair (41% to 60%)		Crown Density - Moderate	Codominant Leaders/Included Bark		
CORAL GATE DR	Weeping Fig	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting		
CORAL GATE DR	Weeping Fig	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
CORAL GATE DR	Weeping Fig	6-10"	No	15'	Poor (21% to 40%)		Basal Co-Dominant			
CORAL GATE DR	Wild/Cuban Tamarind	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
CORAL GATE DR	Wild/Cuban Tamarind	16-20"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark			
CORAL GATE DR	Wild/Cuban Tamarind	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
CORAL GATE DR	Yellow Poinciana	6-10"	No	15'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Apical Dieback		



SW 35th Ct. - Looking South from SW 17th Street



SW 36th Ave -(North) - From SW 16th Terr. no outlet to south



Looking north from SW 20th Street



Looking North mid-block



SW 35th Ct. - Looking North from SW 17th Terrace



SW 36th Ave -(Central) - From SW 17th St. no outlet to south



Looking North towards SW 18th Terrace

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale(ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 35th Court	3	Coral Gate	4	40	150	No	No	No	2	City	No	Few	10 (West) 4 (East)	No	Yes	East	One block- No outlet. Circular turn around
SW 36th Avenue - North	3	Coral Gate	4	50	150	No	No	No	2	City	No	One	10	No	Yes	West	One block, turns into SW 17th Terrace
SW 36th Avenue - Central	3	Coral Gate	4	40	150	No	No	No	2	City	One	No	10 (West) 4 (East)	No	Yes	West	One block, turns into SW 17th Terrace
SW 36th Avenue - South	3	Coral Gate	4	60	600	No	No	No	2	City	Some	Few	15	No	Yes	No	Pedestrian Light Poles on West

SW 35th Court & SW 36th Avenue (North & Central)

TYPOLOGY A

SW 36th Avenue (South)

TYPOLOGY A

Street Tree Inventory

SW 35th Court

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 35TH CT	Queen Palm	6-10"	No	10'	Good (61% to 80%)					
SW 35TH CT	Queen Palm	6-10"	No	15'	Good (61% to 80%)					

SW 36th Avenue

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 36TH AVE		31-40"	Yes	15'	Good (61% to 80%)					spanish bayonet
SW 36TH AVE		11-15"	Yes	15'	Good (61% to 80%)					spanish bayonet
SW 36TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Cavities	
SW 36TH AVE	Black Olive	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting	
SW 36TH AVE	Christmas Palm	6-10"	No	5'	Good (61% to 80%)					
SW 36TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 36TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 36TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)					
SW 36TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 36TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)					
SW 36TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)					
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)					
SW 36TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)					
SW 36TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)					
SW 36TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)					
SW 36TH AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 36TH AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 36TH AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 36TH AVE	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Improperly Mulched		
SW 36TH AVE	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Improperly Mulched		
SW 36TH AVE	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Low	Epicormic Growth	Improperly Mulched	
SW 36TH AVE	Live Oak	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 36TH AVE	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark	
SW 36TH AVE	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 36TH AVE	Live Oak	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Reduced Canopy - Minor		
SW 36TH AVE	Live Oak	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 36TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark		
SW 36TH AVE	Mahogany	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Reduced Canopy - Minor		
SW 36TH AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark			
SW 36TH AVE	Pink Tabebuia	21-30"	No	20'	Poor (21% to 40%)		Basal Co-Dominant	Decay Observed		
SW 36TH AVE	Pongam	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Fungus on Leaves		
SW 36TH AVE	Queen Palm	6-10"	No	20'	Good (61% to 80%)					
SW 36TH AVE	Queen Palm	6-10"	No	20'	Good (61% to 80%)					
SW 36TH AVE	Royal Palm	16-20"	No	Negligible	Dead (0% to 5%)					
SW 36TH AVE	Royal Palm	11-15"	No	5'	Poor (21% to 40%)		Frizzled Fronds			
SW 36TH AVE	Royal Poinciana	21-30"	No	50'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 36TH AVE	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 36TH AVE	Royal Poinciana	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 36TH AVE	Sapodilla	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Sprouting	Codominant Leaders/No Included Bark	
SW 36TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
SW 36TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)					
SW 36TH AVE	Strangler Fig	31-40"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting	
SW 36TH AVE	Unid 2	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy			
SW 36TH AVE	Washington Palm	11-15"	No	10'	Good (61% to 80%)					
SW 36TH AVE	Weeping Fig	11-15"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed		

Streets | Terraces | Places



Looking South towards SW 20th Street



Ashton Court - looking South



Looking North towards SW 18th Terrrace

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 36th Court	3	Coral Gate	4	60	500	No	No	No	2	City	Some	Few	12	No	Yes	No	Pedestrian Light Poles on West
Ashton Court	3	Coral Gate	4	20	500	No	No	No	1	City	No	No	0	No	No	No	Looks like an alley - only 11' drive aisle. Houses only 25' apart face to face

SW 36th Court & Ashton Court

TYPOLOGY A & TYPOLOGY X

Street Tree Inventory

SW 36th Court

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 36TH CT	Coconut Palm	11-15"	No	20'	Good (61% to 80%)					
SW 36TH CT	Guiana Chestnut	1-5"	No	15'	Fair (41% to 60%)		Girdling Roots			
SW 36TH CT	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts		
SW 36TH CT	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 36TH CT	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 36TH CT	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 36TH CT	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Restricted Canopy		
SW 36TH CT	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 36TH CT	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts		
SW 36TH CT	Melaleuca	21-30"	No	30'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Ficus Growing on Tree	
SW 36TH CT	Melaleuca	11-15"	No	15'	Poor (21% to 40%)		Girdling Roots	Trunk Damage - Major	Strap Constricting Tree	
SW 36TH CT	Pitch Apple	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub			
SW 36TH CT	Pitch Apple	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub			
SW 36TH CT	Pongam	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting	
SW 36TH CT	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Grafted Branches	Dead Wood	
SW 36TH CT	Royal Poinciana	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood	
SW 36TH CT	Weeping Fig	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 36TH CT	Weeping Fig	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 36TH CT	Yellow Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Adjacent Light Pole	

Streets | Terraces | Lanes



Looking West towards SW 37th Avenue



Looking Westfrom SW 36th Avenue



Looking West towards Coral Gate Drive



Looking West mid block



Looking East near Coral Gate Drive



Looking East towards SW 32nd Court



Looking West from SW 32nd Court

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 16th Terrace	3	Coral Gate	4	50/60	2400	No	North at SW 37th Ave	No	2	City	Some	Some	12	Only at SW 37th Ave	Yes	North (only bet. SW 37th Ave & Coral gate Dr.)	60' ROW between Coral Gate Drive and SW 32nd Ct. Roundabout at Coral Gate Drive
SW 16th Lane	3	Coral Gate	4	50	1000	No	No	No	2	City	Some	Some	10	No	Yes	No	Pedestrian Light poles on north side

SW 16th Terrace

TYPOLOGY A

SW 16th Lane

TYPOLOGY A

Street Tree Inventory

SW 16th Terrace

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 16TH TER	Areca Palm	16-20"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency			
SW 16TH TER	Areca Palm	1-5"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Nutrient Deficiency			
SW 16TH TER	Areca Palm	6-10"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency			
SW 16TH TER	Avocado	6-10"	No	15'	Good (61% to 80%)					
SW 16TH TER	Black Olive	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting	
SW 16TH TER	Black Olive	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting	
SW 16TH TER	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 16TH TER	Black Olive	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 16TH TER	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting	
SW 16TH TER	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above				
SW 16TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 16TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above				
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict				
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict				
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict				
SW 16TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy			
SW 16TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor			
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)					
SW 16TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 16TH TER	Coconut Palm	16-20"	No	20'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy			
SW 16TH TER	Coconut Palm	6-10"	No	30'	Good (61% to 80%)		Nutrient Deficiency			
SW 16TH TER	Coconut Palm	11-15"	No	25'	Good (61% to 80%)					
SW 16TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)					
SW 16TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency			
SW 16TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)					
SW 16TH TER	Coconut Palm	11-15"	No	10'	Dead (0% to 5%)					
SW 16TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy			
SW 16TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)					
SW 16TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Suppressed Canopy			
SW 16TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)					
SW 16TH TER	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 16TH TER	Crepe Myrtle	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Low	Improperly Mulched		
SW 16TH TER	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)					
SW 16TH TER	Florida Privet	1-5"	No	5'	Good (61% to 80%)					
SW 16TH TER	Guiana Chestnut	1-5"	Yes	5'	Fair (41% to 60%)		Basal Co-Dominant	Nutrient Deficiency		
SW 16TH TER	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)					
SW 16TH TER	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)					rocks on trunk
SW 16TH TER	Java Plum	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 16TH TER	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 16TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 16TH TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		

(Continued on Next Page)

Street Tree Inventory

SW 16th Terrace (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 16TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 16TH TER	Live Oak	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 16TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 16TH TER	Live Oak	11-15"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 16TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 16TH TER	Live Oak	6-10"	No	20'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting	
SW 16TH TER	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark		
SW 16TH TER	Live Oak	1-5"	No	10'	Good (61% to 80%)		Improperly Mulched			
SW 16TH TER	Live Oak	1-5"	No	15'	Good (61% to 80%)		Improperly Mulched			
SW 16TH TER	Live Oak	11-15"	No	30'	Good (61% to 80%)					
SW 16TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 16TH TER	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Very Low	Improperly Mulched		
SW 16TH TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Improperly Mulched		
SW 16TH TER	Live Oak	11-15"	No	20'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH TER	Live Oak	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Sprouting		
SW 16TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 16TH TER	Live Oak	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 16TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)					
SW 16TH TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Improperly Mulched		
SW 16TH TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Moderate	Improperly Mulched		
SW 16TH TER	Live Oak	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Epicormic Growth	Improperly Mulched		
SW 16TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 16TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 16TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 16TH TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Improperly Mulched		
SW 16TH TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Moderate	Epicormic Growth	Improperly Mulched	
SW 16TH TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Moderate	Epicormic Growth	Improperly Mulched	
SW 16TH TER	Mahogany	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Limb Damage - Minor		
SW 16TH TER	Orange Geiger	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy			
SW 16TH TER	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Improperly Mulched		
SW 16TH TER	Pygmy Date Palm	6-10"	No	10'	Good (61% to 80%)					
SW 16TH TER	Pygmy Date Palm	1-5"	No	10'	Good (61% to 80%)					
SW 16TH TER	Queen Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 16TH TER	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)		Apical Dieback	Dead Wood		
SW 16TH TER	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed	
SW 16TH TER	Sapodilla	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting	
SW 16TH TER	Sapodilla	16-20"	No	35'	Fair (41% to 60%)		Codominant Leaders/Included Bark			
SW 16TH TER	Silver Buttonwood	16-20"	No	15'	Fair (41% to 60%)		Basal Co-Dominant			
SW 16TH TER	Strangler Fig	16-20"	No	20'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Dead Wood	Decay Observed	
SW 16TH TER	Tropical Almond	11-15"	No	30'	Fair (41% to 60%)		Apical Dieback	Insect Damage Leaves		
SW 16TH TER	Umbrella Tree	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting	
SW 16TH TER	Vera Wood	1-5"	No	5'	Fair (41% to 60%)		Loose Trunk			fix support
SW 16TH TER	Washington Palm	11-15"	No	10'	Good (61% to 80%)					
SW 16TH TER	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark			
SW 16TH TER	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Codominant Leaders/Included Bark		
SW 16TH TER	Weeping Fig	16-20"	No	30'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Dead Wood	Decay Observed	
SW 16TH TER	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Dead Wood	Decay Observed	
SW 16TH TER	Weeping Fig	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 16TH TER	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 16TH TER	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 16TH TER	Weeping Fig	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 16TH TER	White Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict				
SW 16TH TER	White Geiger	1-5"	No	5'	Good (61% to 80%)					
SW 16TH TER	White Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 16TH TER	White Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 16TH TER	White Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 16TH TER	Woman's Tongue	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			

(Continued on Next Page)

Street Tree Inventory

SW 16th Terrace (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 16TH TER	Yellow Poinciana	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 16TH TER	Yellow Poinciana	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Minor	Codominant Leaders/Included Bark	
SW 16TH TER	Yellow Poinciana	6-10"	No	25'	Good (61% to 80%)					
SW 16TH TER	Yellow Tabebuia	11-15"	No	15'	Good (61% to 80%)					

SW 16th Lane

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 16TH LN	Areca Palm	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Nutrient Deficiency		
SW 16TH LN	Areca Palm	16-20"	No	15'	Fair (41% to 60%)		Nutrient Deficiency			
SW 16TH LN	Areca Palm	31-40"	No	15'	Good (61% to 80%)					
SW 16TH LN	Black Olive	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	
SW 16TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 16TH LN	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 16TH LN	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 16TH LN	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 16TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 16TH LN	Gumbo Limbo	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 16TH LN	Hong Kong Orchid	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Suppressed Canopy		
SW 16TH LN	Japanese Blueberry	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots			
SW 16TH LN	Java Bishopwood	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate	
SW 16TH LN	Java Bishopwood	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Dead Wood	
SW 16TH LN	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark		
SW 16TH LN	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 16TH LN	Live Oak	1-5"	No	15'	Good (61% to 80%)					
SW 16TH LN	Live Oak	6-10"	No	15'	Poor (21% to 40%)		Crown Density - Low	Lopsided/Moderately Reduced Canopy		
SW 16TH LN	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting	
SW 16TH LN	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 16TH LN	Live Oak	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)		
SW 16TH LN	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
SW 16TH LN	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
SW 16TH LN	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
SW 16TH LN	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Low	Epicormic Growth		
SW 16TH LN	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark		
SW 16TH LN	Live Oak	11-15"	No	35'	Good (61% to 80%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 16TH LN	Melaleuca	21-30"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Dead Wood		
SW 16TH LN	Norfolk Pine	21-30"	Yes	15'	Fair (41% to 60%)		Basal Co-Dominant			
SW 16TH LN	Queen Palm	6-10"	No	15'	Good (61% to 80%)					
SW 16TH LN	Queen Palm	6-10"	No	20'	Good (61% to 80%)					
SW 16TH LN	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)		Basal Co-Dominant	Limb Damage - Moderate	Decay Observed	
SW 16TH LN	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 16TH LN	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 16TH LN	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)					
SW 16TH LN	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)					
SW 16TH LN	Umbrella Tree	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 16TH LN	Umbrella Tree	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 16TH LN	Umbrella Tree	11-15"	No	15'	Poor (21% to 40%)		Basal Co-Dominant			
SW 16TH LN	Washington Palm	11-15"	No	10'	Good (61% to 80%)					
SW 16TH LN	Washington Palm	11-15"	No	15'	Good (61% to 80%)					
SW 16TH LN	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub			
SW 16TH LN	Weeping Fig	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate		
SW 16TH LN	Weeping Fig	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 16TH LN	Weeping Fig	11-15"	No	25'	Good (61% to 80%)		Adjacent Light Pole	Codominant Leaders/Included Bark		

Street| Terraces | Lanes



Looking East at SW 37th Avenue



Looking East near SW 37th Avenue



Looking East from Coral Gate Drive



Looking East towards Coral Gate Drive



Looking East at SW 36th Terrace



St. Raymond Catholic Church



SW 17th Terrace - Looking East



SW 17th Terrace - Looking West

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 17th Street	3	Coral Gate	4	50	2200	No	North at SW 37th Ave	No	2	City	Some	Some	10	Only at SW 37th Ave	Yes	North	Roundabout at Coral Gate Drive
SW 17th Terrace	3	Coral Gate	4	40	150	No	No	No	2	City	No	One	9	No	10' on North Only	No	Only one block long. Swale only on north side

SW 17th Street & SW 17th Terrace

TYPOLOGY A & TYPOLOGY X

Street Tree Inventory

SW 17th Street

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 17TH ST		1-5"	No	5'	Dead (0% to 5%)					
SW 17TH ST		1-5"	No	5'	Dead (0% to 5%)					
SW 17TH ST	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency			
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict				
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict				
SW 17TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict				
SW 17TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict				
SW 17TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict				
SW 17TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict				
SW 17TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict				
SW 17TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Fungus on Leaves		
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 17TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency			
SW 17TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency			
SW 17TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency			
SW 17TH ST	Coconut Palm	11-15"	No	15'	Poor (21% to 40%)		Nutrient Deficiency	Reduced Canopy - Minor		
SW 17TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency			
SW 17TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above	Over Pruned			
SW 17TH ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)					
SW 17TH ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)					
SW 17TH ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)					
SW 17TH ST	Crepe Myrtle	6-10"	No	10'	Good (61% to 80%)					
SW 17TH ST	Crepe Myrtle	1-5"	No	10'	Poor (21% to 40%)		Crown Density - Low			
SW 17TH ST	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 17TH ST	Hong Kong Orchid	11-15"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Reduced Canopy - Major	
SW 17TH ST	Hong Kong Orchid	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting	
SW 17TH ST	Hong Kong Orchid	11-15"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Topped	
SW 17TH ST	Horseradish Tree	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark			
SW 17TH ST	Indian Laurel Fig	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Topped	Stubs with Sprouts	
SW 17TH ST	Japanese Privet	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Japanese Privet	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Japanese Privet	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Japanese Privet	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Japanese Privet	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Japanese Privet	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Japanese Privet	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Japanese Privet	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Japanese Privet	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Japanese Privet	6-10"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Moderate	Dead Wood		

(Continued on Next Page)

Street Tree Inventory

SW 17th Street (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 17TH ST	Japanese Privet	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above				
SW 17TH ST	Japanese Privet	6-10"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Dead Wood			
SW 17TH ST	Japanese Privet	11-15"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate			
SW 17TH ST	Japanese Privet	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor			
SW 17TH ST	Japanese Privet	6-10"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Moderate		
SW 17TH ST	Java Bishopwood	16-20"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Trunk Damage - Major	Sprouting	
SW 17TH ST	Laurel Oak	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low			

SW 17th Terrace

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 17TH TER	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency			
SW 17TH TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)					

Street| Terraces



Looking West at Coral Gate Drive



Looking East near SW 33rd Court



Looking West from SW 32nd Court



Looking east at Coral Gate Drive



Looking East at SW 32nd Court



Looking East near SW 36th Avenue



Looking East towards SW 36th Court

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 18th Street	3	Coral Gate	4	60	1200	No	No	No	2	City	Some	Few	12	No	Yes	No	Roundabout at SW 32nd Ct.- No outlet at east end. 14' swales on south side
SW 18th Terrace - West	3	Coral Gate	4	60	1200	No	No	No	2	City	Some	Few	12	No	Yes	No	
SW 18th Terrace - East	3	Coral Gate	4	60	250	No	No	No	2	City	Some	Few	12	No	Yes	No	One block

SW 18th Street

TYPOLOGY A

SW 18th Terrace

TYPOLOGY A

Street Tree Inventory

SW 18th Street

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 18TH ST	Areca Palm	1-5"	Yes	10'	Good (61% to 80%)		Suppressed Canopy			
SW 18TH ST	Bismark Palm	16-20"	No	25'	Good (61% to 80%)					
SW 18TH ST	Black Olive	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Suppressed Canopy		
SW 18TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Decay Observed	
SW 18TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 18TH ST	Black Olive	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 18TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood	
SW 18TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)					
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)					
SW 18TH ST	Christmas Palm	16-20"	Yes	10'	Good (61% to 80%)					
SW 18TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)					
SW 18TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)					
SW 18TH ST	Crepe Myrtle	11-15"	No	20'	Good (61% to 80%)					
SW 18TH ST	Crepe Myrtle	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy			
SW 18TH ST	Gumbo Limbo	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting		
SW 18TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 18TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/No Included Bark		
SW 18TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/No Included Bark		
SW 18TH ST	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Stubs with Sprouts		
SW 18TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Crown Density - Excessive (Due to Epicormic Growth)		
SW 18TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 18TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark			broken support
SW 18TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 18TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Reduced Canopy - Minor		
SW 18TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Girdling Roots	Improperly Mulched		
SW 18TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 18TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 18TH ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Low	Epicormic Growth		
SW 18TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 18TH ST	Live Oak	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Restricted Canopy		
SW 18TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Girdling Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 18TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Restricted Canopy		
SW 18TH ST	Live Oak	6-10"	No	15'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low	Dead Wood		
SW 18TH ST	Live Oak	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 18TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 18TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 18TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 18TH ST	Mahogany	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy			
SW 18TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Codominant Leaders/Included Bark		
SW 18TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy			
SW 18TH ST	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	Root Damage/Decay	
SW 18TH ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Apical Dieback	Dead Wood	
SW 18TH ST	Royal Poinciana	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 18TH ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood	
SW 18TH ST	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood	
SW 18TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)					
SW 18TH ST	Umbrella Tree	21-30"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Decay Observed	
SW 18TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 18TH ST	Vera Wood	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Minor	Reduced Canopy - Moderate	Apical Dieback	
SW 18TH ST	Vera Wood	1-5"	No	5'	Good (61% to 80%)					
SW 18TH ST	Vera Wood	1-5"	No	5'	Good (61% to 80%)					
SW 18TH ST	Vera Wood	1-5"	No	5'	Good (61% to 80%)					
SW 18TH ST	Wild/Cuban Tamarind	21-30"	No	40'	Good (61% to 80%)		Constricted Roots	Codominant Leaders/No Included Bark		

Street Tree Inventory

SW 18th Terrace

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 18TH TER		6-10"	No	20'	Poor (21% to 40%)		Crown Density - Low	Improperly Mulched	Basal Co-Dominant	hog plum
SW 18TH TER		6-10"	No	20'	Poor (21% to 40%)		Crown Density - Low	Improperly Mulched		hog plum
SW 18TH TER		1-5"	No	5'	Poor (21% to 40%)		Crown Density - Low	Plunged	Dead Wood	hog plum
SW 18TH TER		11-15"	No	25'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low			hog plum
SW 18TH TER		6-10"	No	10'	Dead (0% to 5%)					hog plum
SW 18TH TER		6-10"	No	15'	Poor (21% to 40%)		Crown Density - Low			hog plum
SW 18TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 18TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor			
SW 18TH TER	Christmas Palm	11-15"	No	10'	Good (61% to 80%)		Restricted Canopy			
SW 18TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 18TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 18TH TER	Christmas Palm	6-10"	No	5'	Good (61% to 80%)					
SW 18TH TER	Christmas Palm	16-20"	No	15'	Good (61% to 80%)					
SW 18TH TER	Christmas Palm	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major			
SW 18TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 18TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)					
SW 18TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 18TH TER	Coconut Palm	6-10"	No	5'	Poor (21% to 40%)		Nutrient Deficiency	Reduced Canopy - Major		
SW 18TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency			
SW 18TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 18TH TER	Coconut Palm	11-15"	No	25'	Good (61% to 80%)					
SW 18TH TER	Coconut Palm	11-15"	No	25'	Good (61% to 80%)					
SW 18TH TER	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Moderate		
SW 18TH TER	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)					
SW 18TH TER	Crepe Myrtle	6-10"	No	15'	Good (61% to 80%)					
SW 18TH TER	Crepe Myrtle	16-20"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)	
SW 18TH TER	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)					
SW 18TH TER	Earleaf Acacia	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Moderate	
SW 18TH TER	Gumbo Limbo	16-20"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Stubs with Sprouts		
SW 18TH TER	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 18TH TER	Gumbo Limbo	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Reduced Canopy - Minor	Stubs with Sprouts	
SW 18TH TER	Horseradish Tree	11-15"	No	10'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed		
SW 18TH TER	Jelly Palm	16-20"	No	25'	Fair (41% to 60%)		Basal Co-Dominant			
SW 18TH TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 18TH TER	Live Oak	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 18TH TER	Live Oak	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 18TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 18TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub			
SW 18TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 18TH TER	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 18TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 18TH TER	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 18TH TER	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Plunged	Epicormic Growth		
SW 18TH TER	Live Oak	1-5"	No	10'	Poor (21% to 40%)		Crown Density - Low	Epicormic Growth	Decay Observed	
SW 18TH TER	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Sprouting	
SW 18TH TER	Live Oak	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 18TH TER	Live Oak	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Improperly Mulched	Epicormic Growth	
SW 18TH TER	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 18TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 18TH TER	Live Oak	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 18TH TER	Live Oak	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 18TH TER	Live Oak	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 18TH TER	Live Oak	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 18TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)					
SW 18TH TER	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy			
SW 18TH TER	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub			
SW 18TH TER	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 18TH TER	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	

(Continued on Next Page)

Street Tree Inventory

SW 18th Terrace (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 18TH TER	Tamarind	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 18TH TER	Umbrella Tree	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Basal Co-Dominant with Adjacent Tree(s)		
SW 18TH TER	Umbrella Tree	31-40"	No	20'	Poor (21% to 40%)		Basal Co-Dominant	Trunk Damage - Moderate	Decay Observed	
SW 18TH TER	Umbrella Tree	16-20"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Sprouting	
SW 18TH TER	Washington Palm	6-10"	No	10'	Good (61% to 80%)					
SW 18TH TER	Washington Palm	11-15"	No	10'	Good (61% to 80%)					
SW 18TH TER	Washington Palm	11-15"	No	10'	Good (61% to 80%)					
SW 18TH TER	Weeping Fig	11-15"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Dead Wood	
SW 18TH TER	Weeping Fig	16-20"	No	15'	Dead (0% to 5%)					fallen
SW 18TH TER	Weeping Fig	16-20"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate		
SW 18TH TER	Wild/Cuban Tamarind	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark			

Street| Terraces



Looking West at SW 36th Court



Looking West mid block



Looking East at SW 32nd Court



Looking East at SW 32nd Court



Looking East at SW 36th Avenue



Looking East near SW 32nd Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 19th Street	3	Coral Gate	4	60	600	No	No	No	2	City	Some	Few	15	No	Yes	No	Pedestrian Light poles on south side
SW 19th Terrace	3	Coral Gate	4	60	190	No	No	No	2	City	Some	Few	15	No	Yes	South	One block- No outlet.

SW 19th Street

TYPOLOGY A

SW 19th Terrace

TYPOLOGY A

Street Tree Inventory

SW 19th Street

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 19TH ST		1-5"	No	10'	Good (61% to 80%)					corn plant
SW 19TH ST		6-10"	No	5'	Good (61% to 80%)					spanish bayonet
SW 19TH ST		6-10"	Yes	5'	Good (61% to 80%)					spanish bayonet
SW 19TH ST		1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate			spanish bayonet
SW 19TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)					
SW 19TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate			
SW 19TH ST	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy			
SW 19TH ST	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 19TH ST	Jamaica Caper	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy			
SW 19TH ST	Lancepod	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Epicormic Growth		
SW 19TH ST	Live Oak	16-20"	Yes	15'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Moderate	Restricted Canopy	
SW 19TH ST	Live Oak	16-20"	Yes	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts	
SW 19TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 19TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 19TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 19TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
SW 19TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 19TH ST	Live Oak	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 19TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 19TH ST	Melaleuca	16-20"	No	20'	Fair (41% to 60%)		Root Damage/Decay	Codominant Leaders/No Included Bark	Dead Wood	
SW 19TH ST	Montgomery Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 19TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)					
SW 19TH ST	Montgomery Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 19TH ST	Pigeon Plum	6-10"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Sprouting		
SW 19TH ST	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy			
SW 19TH ST	Starfruit	1-5"	No	5'	Good (61% to 80%)					
SW 19TH ST	Wild/Cuban Tamarind	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 19TH ST	Yellow Poinciana	16-20"	No	40'	Poor (21% to 40%)		Root Damage/Decay	Lopsided/Moderately Reduced Canopy	Dead Wood	

SW 19th Terrace

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 19TH TER	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark		
SW 19TH TER	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	
SW 19TH TER	Black Olive	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting	
SW 19TH TER	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency			
SW 19TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency			
SW 19TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency			
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 19TH TER	Coconut Palm	6-10"	No	20'	Poor (21% to 40%)		Nutrient Deficiency	Reduced Canopy - Major		
SW 19TH TER	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Crown Density - Moderate	Epicormic Growth		
SW 19TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 19TH TER	Mahogany	41-50"	No	40'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Decay Observed	
SW 19TH TER	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				

Street| Terraces


Looking West at SW 37th Avenue


Looking east near SW 36th Avenue


Looking West at SW 37th Avenue - no outlet


Looking East from Coral Gate Drive


Looking East near SW 33rd Avenue


Looking West towards Coral Gate Drive roundabout


Looking East near SW 33rd Avenue


Looking East at eastern end - no outlet

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 20th Street	3	Coral Gate	4	60	2500	No	No	No	2	City	Some	Few	15	No	Yes	No	Pedestrian Light poles on south side - No Outlet and Roundabout at Coral Gate Drive
SW 21st Street	3	Coral Gate	4	60	2750	No	No	No	2	City	Some	Few	15	No	Yes	No	Roundabout at Coral Gate Drive and at SW 33rd Avenue

SW 20th Street

TYPOLOGY A

SW 21st Street

TYPOLOGY A

Street Tree Inventory

SW 20th Street

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 20TH ST		6-10"	No	5'	Dead (0% to 5%)					unid deade tree
SW 20TH ST	Banyan	60+"	No	60'	Good (61% to 80%)		Dead Wood	Cavities		
SW 20TH ST	Black Olive	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Restricted Canopy		
SW 20TH ST	Black Olive	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Restricted Canopy		
SW 20TH ST	Black Olive	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Restricted Canopy		
SW 20TH ST	Black Olive	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Suppressed Canopy		
SW 20TH ST	Black Olive	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Stubs with Sprouts		
SW 20TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 20TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 20TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood	
SW 20TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 20TH ST	Black Olive	16-20"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	Codominant Leaders/No Included Bark	
SW 20TH ST	Black Olive	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 20TH ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Topped	Strap Constricting Tree	
SW 20TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Broken Branches	Codominant Leaders/Included Bark	
SW 20TH ST	Black Olive	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed	
SW 20TH ST	Brazilian Pepper	6-10"	No	15'	Poor (21% to 40%)		Suppressed Canopy	Topped	Sprouting	
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy			
SW 20TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Restricted Canopy			
SW 20TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Restricted Canopy			
SW 20TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy			
SW 20TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Restricted Canopy			
SW 20TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)		Restricted Canopy			
SW 20TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate			
SW 20TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency			
SW 20TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)					
SW 20TH ST	Coconut Palm	11-15"	No	10'	Fair (41% to 60%)		Over Pruned			
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)					
SW 20TH ST	Crepe Myrtle	6-10"	No	15'	Good (61% to 80%)					
SW 20TH ST	Crepe Myrtle	11-15"	Yes	10'	Good (61% to 80%)					
SW 20TH ST	Crepe Myrtle	6-10"	No	15'	Good (61% to 80%)					
SW 20TH ST	Crepe Myrtle	11-15"	Yes	10'	Good (61% to 80%)					
SW 20TH ST	Crepe Myrtle	6-10"	Yes	5'	Good (61% to 80%)					
SW 20TH ST	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)					
SW 20TH ST	Crepe Myrtle	11-15"	No	20'	Good (61% to 80%)					
SW 20TH ST	Dahoon Holly	6-10"	No	10'	Fair (41% to 60%)		Basal Co-Dominant	Restricted Canopy		
SW 20TH ST	Golden Shower Tree	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 20TH ST	Golden Shower Tree	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 20TH ST	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Restricted Canopy		
SW 20TH ST	Gumbo Limbo	11-15"	No	15'	Fair (41% to 60%)		Leader - Bent			
SW 20TH ST	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Vine Cover - Heavy		
SW 20TH ST	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Restricted Canopy		
SW 20TH ST	Gumbo Limbo	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy		
SW 20TH ST	Hong Kong Orchid	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major	
SW 20TH ST	Hong Kong Orchid	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Limb Damage - Moderate	Decay Observed	
SW 20TH ST	Japanese Blueberry	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor			
SW 20TH ST	Lignum Vitae	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate			
SW 20TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy	
SW 20TH ST	Live Oak	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Restricted Canopy		
SW 20TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Moderate	Epicormic Growth	
SW 20TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)					
SW 20TH ST	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Improperly Mulched	Crown Density - Low		
SW 20TH ST	Live Oak	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 20TH ST	Live Oak	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 20TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Moderate		
SW 20TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 20TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 20TH ST	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/No Included Bark		
SW 20TH ST	Live Oak	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark	
SW 20TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)					
SW 20TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Moderate	Epicormic Growth	

(Continued on Next Page)

Street Tree Inventory

SW 20th Street (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 20TH ST	Live Oak	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Epicormic Growth		
SW 20TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark			
SW 20TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Moderate		
SW 20TH ST	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Epicormic Growth	
SW 20TH ST	Loblolly Bay	11-15"	No	35'	Good (61% to 80%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 20TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)					
SW 20TH ST	Mahogany	1-5"	No	10'	Good (61% to 80%)					
SW 20TH ST	Mahogany	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts	
SW 20TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Codominant Leaders/Included Bark	
SW 20TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts		
SW 20TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Root Damage/Decay	Decay Observed	
SW 20TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 20TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 20TH ST	Mahogany	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 20TH ST	Mahogany	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 20TH ST	Mahogany	21-30"	No	25'	Poor (21% to 40%)		Topped	Sprouting	Decay Observed	
SW 20TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed	
SW 20TH ST	Mahogany	11-15"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Codominant Leaders/Included Bark		
SW 20TH ST	Majesty Palm	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark		
SW 20TH ST	Melaleuca	16-20"	No	15'	Poor (21% to 40%)		Girdling Roots	Codominant Leaders/Included Bark		
SW 20TH ST	Norfolk Pine	11-15"	Yes	15'	Poor (21% to 40%)		Basal Co-Dominant	Topped	Reduced Canopy - Major	
SW 20TH ST	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)					
SW 20TH ST	Pink Tabebuia	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sprouting	
SW 20TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting		
SW 20TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 20TH ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark	
SW 20TH ST	Pink Tabebuia	1-5"	No	15'	Poor (21% to 40%)		Girdling Roots	Codominant Leaders/Included Bark		
SW 20TH ST	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Major	Sprouting	Codominant Leaders/No Included Bark	
SW 20TH ST	Pink Tabebuia	1-5"	No	15'	Poor (21% to 40%)		Girdling Roots	Codominant Leaders/Included Bark		
SW 20TH ST	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Major	Sprouting	Codominant Leaders/No Included Bark	
SW 20TH ST	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Codominant Leaders/Included Bark	Reduced Canopy - Minor	
SW 20TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Vine Cover - Heavy		
SW 20TH ST	Pink Tabebuia	6-10"	No	10'	Poor (21% to 40%)		Girdling Roots	Codominant Leaders/Included Bark		
SW 20TH ST	Pink Tabebuia	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Discolored Foliage	
SW 20TH ST	Pink Tabebuia	16-20"	No	15'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark		
SW 20TH ST	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Broken Branches	
SW 20TH ST	Royal Poinciana	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts	
SW 20TH ST	Royal Poinciana	1-5"	No	10'	Fair (41% to 60%)		Lifting	Codominant Leaders/No Included Bark		
SW 20TH ST	Royal Poinciana	6-10"	No	20'	Fair (41% to 60%)		Limb Damage - Major	Trunk Damage - Moderate	Decay Observed	
SW 20TH ST	Royal Poinciana	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 20TH ST	Royal Poinciana	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting	
SW 20TH ST	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 20TH ST	Royal Poinciana	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Dead Wood	
SW 20TH ST	Silk Floss Tree	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 20TH ST	Silver Buttonwood	6-10"	Yes	10'	Fair (41% to 60%)		Basal Co-Dominant			
SW 20TH ST	Silver Buttonwood	6-10"	Yes	10'	Fair (41% to 60%)		Basal Co-Dominant			
SW 20TH ST	Silver Buttonwood	6-10"	Yes	10'	Fair (41% to 60%)		Basal Co-Dominant			
SW 20TH ST	Silver Buttonwood	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate			
SW 20TH ST	Silver Buttonwood	6-10"	Yes	5'	Fair (41% to 60%)		Basal Co-Dominant			
SW 20TH ST	Silver Buttonwood	1-5"	Yes	5'	Fair (41% to 60%)		Basal Co-Dominant			
SW 20TH ST	Silver Buttonwood	1-5"	Yes	5'	Fair (41% to 60%)		Basal Co-Dominant			
SW 20TH ST	Silver Buttonwood	1-5"	Yes	5'	Fair (41% to 60%)		Basal Co-Dominant			
SW 20TH ST	Southern Magnolia	1-5"	No	5'	Good (61% to 80%)					
SW 20TH ST	Spanish Stopper	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy			
SW 20TH ST	Strangler Fig	60+"	No	55'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed	
SW 20TH ST	Sylvester Date Palm	11-15"	No	20'	Good (61% to 80%)					
SW 20TH ST	Washington Palm	16-20"	No	10'	Good (61% to 80%)					
SW 20TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)					

Street Tree Inventory

SW 21st Street

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 21ST ST	Avocado	16-20"	No	20'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	Reduced Canopy - Moderate	
SW 21ST ST	Bismark Palm	21-30"	No	25'	Good (61% to 80%)					
SW 21ST ST	Black Olive	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 21ST ST	Black Olive	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 21ST ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Codominant Leaders/Included Bark	Adjacent Light Pole	
SW 21ST ST	Black Olive	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Codominant Leaders/Included Bark		
SW 21ST ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Cavities	
SW 21ST ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting	
SW 21ST ST	Black Olive	16-20"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Decay Observed	
SW 21ST ST	Black Olive	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 21ST ST	Black Olive	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 21ST ST	Black Olive	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark	
SW 21ST ST	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy		
SW 21ST ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)					
SW 21ST ST	Bottlebrush	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Codominant Leaders/Included Bark	
SW 21ST ST	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)					
SW 21ST ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)					
SW 21ST ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)					
SW 21ST ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 21ST ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 21ST ST	Christmas Palm	16-20"	Yes	10'	Good (61% to 80%)		Suppressed Canopy			
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)					
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 21ST ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy			
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 21ST ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Over Pruned			
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned			
SW 21ST ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Over Pruned			
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned			
SW 21ST ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Suppressed Canopy			
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)					
SW 21ST ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency			
SW 21ST ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)					
SW 21ST ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched			
SW 21ST ST	Frangipani	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Low	Trunk Damage - Major		
SW 21ST ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)					
SW 21ST ST	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)					
SW 21ST ST	Indian Laurel Fig	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed	
SW 21ST ST	Indian Laurel Fig	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood	
SW 21ST ST	Indian Laurel Fig	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed	
SW 21ST ST	Indian Laurel Fig	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed	
SW 21ST ST	Japanese Privet	6-10"	No	10'	Good (61% to 80%)					
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Moderate	Epicormic Growth	
SW 21ST ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Crown Density - Moderate			
SW 21ST ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Crown Density - Moderate			
SW 21ST ST	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark	
SW 21ST ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 21ST ST	Live Oak	1-5"	No	10'	Good (61% to 80%)					
SW 21ST ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 21ST ST	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	1-5"	No	10'	Poor (21% to 40%)		Plunged	Crown Density - Moderate		
SW 21ST ST	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark	

(Continued on Next Page)

Street Tree Inventory

SW 21st Street (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 21ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Crown Density - Moderate	Epicormic Growth		
SW 21ST ST	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Sprouting		
SW 21ST ST	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark	
SW 21ST ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	11-15"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Moderate	Epicormic Growth	
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched			
SW 21ST ST	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Epicormic Growth	Codominant Leaders/No Included Bark	
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Low		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Low		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Low		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)		
SW 21ST ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Moderate		
SW 21ST ST	Loblolly Bay	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
SW 21ST ST	Loblolly Bay	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)			
SW 21ST ST	Mahogany	1-5"	No	5'	Good (61% to 80%)					
SW 21ST ST	Mahogany	1-5"	No	10'	Good (61% to 80%)					
SW 21ST ST	Mahogany	1-5"	No	5'	Good (61% to 80%)					
SW 21ST ST	Mahogany	1-5"	No	10'	Good (61% to 80%)					
SW 21ST ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	
SW 21ST ST	Mahogany	21-30"	No	40'	Good (61% to 80%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts	
SW 21ST ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood	
SW 21ST ST	Mahogany	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched			
SW 21ST ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 21ST ST	Mango	16-20"	No	20'	Fair (41% to 60%)		Codominant Leaders/No Included Bark			
SW 21ST ST	Mango	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub			
SW 21ST ST	Melaleuca	16-20"	No	10'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting	
SW 21ST ST	Melaleuca	21-30"	No	15'	Poor (21% to 40%)		Topped	Sprouting	Ficus Growing on Tree	
SW 21ST ST	Melaleuca	21-30"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Codominant Leaders/Included Bark	
SW 21ST ST	Melaleuca	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood	
SW 21ST ST	Melaleuca	11-15"	No	Negligible	Dead (0% to 5%)					
SW 21ST ST	Montgomery Palm	6-10"	Yes	15'	Good (61% to 80%)					
SW 21ST ST	Montgomery Palm	11-15"	Yes	10'	Good (61% to 80%)					
SW 21ST ST	Montgomery Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 21ST ST	Narrow Leaf Ficus	6-10"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Sprouting	
SW 21ST ST	Oriental Arborvitae	11-15"	No	10'	Good (61% to 80%)					
SW 21ST ST	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)					
SW 21ST ST	Oriental Arborvitae	11-15"	No	15'	Good (61% to 80%)					
SW 21ST ST	Pink Tabebuia	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark		
SW 21ST ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 21ST ST	Royal Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency		
SW 21ST ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)					
SW 21ST ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)					
SW 21ST ST	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 21ST ST	Royal Poinciana	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood	
SW 21ST ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood	
SW 21ST ST	Royal Poinciana	16-20"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark			
SW 21ST ST	Royal Poinciana	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency			
SW 21ST ST	Sapodilla	16-20"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Suppressed Canopy		
SW 21ST ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)					
SW 21ST ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)					
SW 21ST ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate			

(Continued on Next Page)

Street Tree Inventory


SW 21st Street (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 21ST ST	Sylvester Date Palm	11-15"	No	15'	Good (61% to 80%)					
SW 21ST ST	Sylvester Date Palm	11-15"	No	15'	Good (61% to 80%)					
SW 21ST ST	Sylvester Date Palm	6-10"	No	15'	Good (61% to 80%)					
SW 21ST ST	Triangle Palm	6-10"	No	15'	Good (61% to 80%)					
SW 21ST ST	Umbrella Tree	21-30"	Yes	15'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Reduced Canopy - Moderate	
SW 21ST ST	Umbrella Tree	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Decay Observed	
SW 21ST ST	Washington Palm	16-20"	No	Negligible	Dead (0% to 5%)					
SW 21ST ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)					


Bordering Streets



Looking East at SW 37th Avenue - Douglas Road



Looking West near SW 36th Avenue



At SW 16th Street - North end



Looking North at SW 17th Street



Looking West near SW 33rd Avenue



Looking West At SW 27th Avenue



Looking North at SW 20th Street



At SW Coral Way - South end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 22nd Street - Coral Way	4	Coral Gate	2	100	5250	Yes	No	No	4	State	Median	Few	6	Yes	Yes	No	Historic Road. 12' swale on south side
SW 37th Avenue - Douglas Road	3	Coral Gate	4	70	2600	No	No	No	4	County	No	No	0	Yes	Yes	East	Center Turn Lane - Signalized at SW 22nd Avenue, SW 20th Street and SW 16th Street

SW 22nd Street - Coral Way

TYPOLOGY I

SW 37th Avenue - Douglas Road

TYPOLOGY E

Street Tree Inventory

SW 22nd Street - Coral Way

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 22ND ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
SW 22ND ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)					
SW 22ND ST	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)					
SW 22ND ST	Washington Palm	6-10"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	6-10"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	6-10"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	11-15"	No	Negligible	Dead (0% to 5%)					
SW 22ND ST	Washington Palm	11-15"	No	Negligible	Dead (0% to 5%)					
SW 22ND ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	6-10"	No	Negligible	Dead (0% to 5%)					
SW 22ND ST	Washington Palm	6-10"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	6-10"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	16-20"	No	15'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	6-10"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)					
SW 22ND ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)					

*Note there are no trees on SW 37th Avenue


Bordering Streets



Looking South at SW 16th Avenue



Looking South near SW




At SW 34th Avenue



At SW 36th Avenue



Looking North near SW 19th Street



Looking North towards Coral Way



At SW 32nd Avenue - East end



At SW 37th Avenue - West end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 32nd Avenue - McDonald Street	3	Coral Gate	4	60	2700	No	No	No	2	City	Some		16	Some	Yes	West	Street Lights-Signalized at SW 22nd Avenue and SW 16th Avenue
SW 16th Street	3	Coral Gate	4	70 Between SW 37th & SW 34th Ave - 60 for rest	2600	No		Yes	2	City	Yes	Few	6	Yes	Yes	South Side	Bike Lanes both sides of road - Street tree Golden Shower - no sidewalk at cemetary edge

SW 32nd Avenue - McDonald Street

TYPOLOGY A

SW 16th Street

TYPOLOGY B

Street Tree Inventory

SW 32nd Avenue

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 32ND AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting	
SW 32ND AVE	Black Olive	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting	
SW 32ND AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting	
SW 32ND AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting	
SW 32ND AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting	
SW 32ND AVE	Black Olive	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts	
SW 32ND AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting	
SW 32ND AVE	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting	
SW 32ND AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 32ND AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)					
SW 32ND AVE	Java Bishopwood	41-50"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Reduced Canopy - Moderate	
SW 32ND AVE	Mahogany	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting	
SW 32ND AVE	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 32ND AVE	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 32ND AVE	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Dead Wood	
SW 32ND AVE	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND AVE	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND AVE	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND AVE	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND AVE	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND AVE	Royal Poinciana	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Restricted Canopy	Sprouting	
SW 32ND AVE	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 32ND AVE	Royal Poinciana	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting	
SW 32ND AVE	Sylvester Date Palm	16-20"	No	20'	Good (61% to 80%)	Utility Lines Above				

SW 16th Street

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 16TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Suppressed Canopy			
SW 16TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 16TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)					
SW 16TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)					
SW 16TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)					
SW 16TH ST	Golden Rain Tree	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Apical Dieback	Dead Wood	
SW 16TH ST	Golden Rain Tree	1-5"	No	5'	Good (61% to 80%)					
SW 16TH ST	Golden Rain Tree	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Sprouting	
SW 16TH ST	Golden Rain Tree	1-5"	No	5'	Good (61% to 80%)					
SW 16TH ST	Golden Shower Tree	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs	
SW 16TH ST	Golden Shower Tree	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts		
SW 16TH ST	Golden Shower Tree	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting	
SW 16TH ST	Golden Shower Tree	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 16TH ST	Golden Shower Tree	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Sprouting	
SW 16TH ST	Golden Shower Tree	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Cracks in Trunk	Codominant Leaders/Included Bark	
SW 16TH ST	Golden Shower Tree	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Restricted Canopy		
SW 16TH ST	Golden Shower Tree	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark		
SW 16TH ST	Golden Shower Tree	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Crown Density - Low	Reduced Canopy - Major	Dead Wood	
SW 16TH ST	Golden Shower Tree	1-5"	No	10'	Good (61% to 80%)					
SW 16TH ST	Golden Shower Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 16TH ST	Golden Shower Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 16TH ST	Golden Shower Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 16TH ST	Golden Shower Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 16TH ST	Golden Shower Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above				
SW 16TH ST	Golden Shower Tree	1-5"	No	5'	Dead (0% to 5%)	Utility Lines Above				

(Continued on Next Page)

Street Tree Inventory

SW 16th Street (Continued)

Street_Name	Tree_Species	DBH_Class	Multi_Trunk	Spread	Condition	Overhead_Utilities	Observation_1	Observation_2	Observation_3	Notes
SW 16TH ST	Golden Shower Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above				
SW 16TH ST	Golden Shower Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 16TH ST	Golden Shower Tree	11-15"	No	15'	Dead (0% to 5%)	Utility Lines Above				
SW 16TH ST	Golden Shower Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above				
SW 16TH ST	Golden Shower Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor			
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Root Damage/Decay	Reduced Canopy - Major	Apical Dieback	
SW 16TH ST	Golden Shower Tree	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Restricted Canopy		growing on stump
SW 16TH ST	Golden Shower Tree	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood	
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	11-15"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	11-15"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	11-15"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Codominant Leaders/Included Bark	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate	
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	21-30"	No	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Trunk Damage - Major	Decay Observed	Reduced Canopy - Major	
SW 16TH ST	Golden Shower Tree	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	11-15"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark		
SW 16TH ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Crown Density - Moderate	Codominant Leaders/Included Bark	



DOUGLAS PARK

Avenues | Roads | Courts | Places




Looking North towards Bird Road



Looking Southtowards Shipping Avenue



Looking South towards Bird Road



Looking North near SW 29th Street



Looking south from Shipping Avenue



Looking South towards Orange Street



Looking North towards north end



Looking North towards north end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 39th Avenue - South of Bird	4	Douglas Park	2	40	1200	No	Only east side of block near Bird Rd.	No	2	City	Only east side of block near Bird Rd.	No	4	Only east side of block near Bird Rd.	Only east side of block near Bird Rd.	West	Commercial District - one way between Orange Street & San Lorenzo. Swales only bump outs near Bird Road
SW 39th Avenue - North of Bird	4	Douglas Park	2	40	1200	No	No	No	1&2	City	Few	No	6	No	Some	West	One Way north between Bird Rd. & SW 29th St.west side is Coral Gables ROW

SW 39th Avenue - South of Bird Road

TYPOLOGY X

SW 39th Avenue - North of Bird Road

TYPOLOGY X

Street Tree Inventory

SW 39th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 39TH AVE	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)				
SW 39TH AVE	Gumbo Limbo	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 39TH AVE	Gumbo Limbo	6-10"	No	15'	Good (61% to 80%)				
SW 39TH AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 39TH AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 39TH AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 39TH AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 39TH AVE	Mahogany	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Low	Desiccated Foliage	
SW 39TH AVE	Mahogany	1-5"	No	5'	Poor (21% to 40%)		Desiccated Foliage		
SW 39TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 39TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 39TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 39TH AVE	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 39TH AVE	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 39TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)				
SW 39TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)				
SW 39TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)				
SW 39TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)				
SW 39TH AVE	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		

Avenues | Roads | Courts | Places



Looking South towards US 1



Looking South across Bird Road



Looking North towards Bird Road



Looking South near SW 29th Street



Looking North towards Bird Road



Looking South near SW 28th Street



Looking North towards SW 27th Lane

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 38th Avenue - South of Bird	4	Douglas Park	2	60	1200	No	Some east	No	2	City	Few	No	0	Yes	Yes	West	Major transmission line crosses road
SW 38th Avenue - North of Bird	4	Douglas Park	2	50	2000	No	No	No	2	City	Some	Few	9	No	Yes	West	

SW 38th Avenue - South of Bird Road

TYPOLOGY X

SW 38th Avenue - North of Bird Road

TYPOLOGY C & X

Street Tree Inventory

SW 38th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 38TH AVE	Areca Palm	21-30"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 38TH AVE	Areca Palm	11-15"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 38TH AVE	Black Ironwood	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 38TH AVE	Black Ironwood	1-5"	No	10'	Good (61% to 80%)				
SW 38TH AVE	Black Ironwood	1-5"	No	10'	Good (61% to 80%)				
SW 38TH AVE	Black Ironwood	1-5"	No	10'	Good (61% to 80%)				
SW 38TH AVE	Black Ironwood	1-5"	No	10'	Good (61% to 80%)				
SW 38TH AVE	Black Olive	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 38TH AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 38TH AVE	Black Olive	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 38TH AVE	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 38TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 38TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 38TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 38TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 38TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 38TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 38TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 38TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 38TH AVE	Coconut Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 38TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 38TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 38TH AVE	Desert Cassia	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Major	Lopsided/Moderately Reduced Canopy	
SW 38TH AVE	Desert Cassia	1-5"	No	10'	Good (61% to 80%)				
SW 38TH AVE	Desert Cassia	1-5"	No	10'	Good (61% to 80%)				
SW 38TH AVE	Desert Cassia	1-5"	No	5'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 38TH AVE	Desert Cassia	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Low		
SW 38TH AVE	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 38TH AVE	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)		Girdling Roots		
SW 38TH AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Moderate		
SW 38TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 38TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 38TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 38TH AVE	Pygmy Date Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 38TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 38TH AVE	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 38TH AVE	Royal Poinciana	21-30"	Yes	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 38TH AVE	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 38TH AVE	Royal Poinciana	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	
SW 38TH AVE	Solitaire Palm	6-10"	No	10'	Good (61% to 80%)				
SW 38TH AVE	Tropical Almond	1-5"	No	10'	Good (61% to 80%)				
SW 38TH AVE	Tropical Almond	16-20"	No	40'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Codominant Leaders/Included Bark	
SW 38TH AVE	Washington Palm	21-30"	Yes	5'	Good (61% to 80%)				
SW 38TH AVE	Washington Palm	21-30"	Yes	5'	Good (61% to 80%)				
SW 38TH AVE	Weeping Fig	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	



Looking South towards Orange Street



Looking South -near Shipping Avenue



Looking South towards Bird Road



Looking North near Bird Road



Looking North - near Shipping Avenue



Looking North towards SW 28th Street



Looking North near SW 29th Street



Looking North towards North end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 38th Court - South of Bird	4	Douglas Park	2	50	900	No	No	No	2	City	Only one block near Bird Rd.	Only one block near Bird Rd.	4	Only one block near Bird Rd.	Only one block near Bird Rd.	West	Commercial/Industrial District. Swales only bump outs near Bird Road
SW 38th Court - North of Bird	4	Douglas Park	2	50	1200	No	No	No	2	City	Some	Few	0	No	No	West	

SW 38th Court - South of Bird Road

TYPOLOGY X

SW 38th Court - North of Bird Road

TYPOLOGY X

Street Tree Inventory

SW 38th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 38TH CT	Bismark Palm	21-30"	No	20'	Good (61% to 80%)				
SW 38TH CT	Bismark Palm	21-30"	No	15'	Good (61% to 80%)				
SW 38TH CT	Bismark Palm	16-20"	No	20'	Good (61% to 80%)				
SW 38TH CT	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	Trunk Damage - Moderate
SW 38TH CT	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Topped	Sprouting	Codominant Leaders/Included Bark
SW 38TH CT	Chinese Fan Palm	31-40"	Yes	15'	Good (61% to 80%)				
SW 38TH CT	Chinese Fan Palm	21-30"	Yes	15'	Good (61% to 80%)				
SW 38TH CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 38TH CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 38TH CT	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 38TH CT	Dracaena sp.	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 38TH CT	Live Oak	21-30"	No	30'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 38TH CT	Live Oak	41-50"	No	60'	Fair (41% to 60%)		Basal Co-Dominant	Stubs	Dead Wood
SW 38TH CT	Mahogany	16-20"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 38TH CT	Mahogany	21-30"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	
SW 38TH CT	Mango	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Topped	Sprouting	
SW 38TH CT	Mango	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant	Dead Wood	Sprouting
SW 38TH CT	Mango	11-15"	No	20'	Poor (21% to 40%)		Topped	Sprouting	
SW 38TH CT	Manila Tamarind	1-5"	No	10'	Good (61% to 80%)				
SW 38TH CT	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 38TH CT	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 38TH CT	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 38TH CT	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 38TH CT	Pongam	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Topped	Sprouting	Codominant Leaders/Included Bark
SW 38TH CT	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 38TH CT	Sapodilla	1-5"	No	10'	Poor (21% to 40%)		Leader - Broken	Sprouting	
SW 38TH CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)				
SW 38TH CT	Simpson's Stopper	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate		
SW 38TH CT	Simpson's Stopper	1-5"	No	10'	Poor (21% to 40%)		Crown Density - Very Low		
SW 38TH CT	Simpson's Stopper	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Moderate		
SW 38TH CT	Simpson's Stopper	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Moderate		
SW 38TH CT	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 38TH CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy		
SW 38TH CT	Spanish Lime	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 38TH CT	Tamarind	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 38TH CT	Tropical Almond	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark

Avenues | Roads | Courts | Places



Looking North towards Coral Way - North end



Looking South - near SW 22nd Terrace



Looking South - near SW 25th Terrace



Looking south towards Bird Road



Looking South - near SW 23rd Terrace



Looking South - near SW 24th Street



Looking South near Douglas Park - turn around - No Outlet

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 36th Avenue	4	Douglas Park	2	50	4800	No	No	No	2	City	Few	Few	9	Only at Bird Road	Yes	East	

SW 36th Avenue

TYPOLOGY C & A

Street Tree Inventory

SW 36th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 36TH AVE	Avocado	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 36TH AVE	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 36TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Cavities
SW 36TH AVE	Black Olive	16-20"	No	30'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 36TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 36TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	21-30"	Yes	20'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Christmas Palm	6-10"	No	5'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 36TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 36TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 36TH AVE	Coconut Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 36TH AVE	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Reduced Canopy - Major	
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Crepe Myrtle	1-5"	Yes	5'	Fair (41% to 60%)		Crown Density - Moderate		
SW 36TH AVE	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)				
SW 36TH AVE	Crepe Myrtle	1-5"	Yes	10'	Good (61% to 80%)				
SW 36TH AVE	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)				
SW 36TH AVE	Crepe Myrtle	1-5"	Yes	5'	Fair (41% to 60%)		Crown Density - Moderate		
SW 36TH AVE	Crepe Myrtle	1-5"	Yes	5'	Fair (41% to 60%)		Crown Density - Moderate		
SW 36TH AVE	Crepe Myrtle	1-5"	Yes	5'	Fair (41% to 60%)		Crown Density - Moderate		
SW 36TH AVE	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)				
SW 36TH AVE	Crepe Myrtle	1-5"	Yes	10'	Good (61% to 80%)				
SW 36TH AVE	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 36TH AVE	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 36TH AVE	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 36TH AVE	Glaucous Cassia	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Tip Dieback	
SW 36TH AVE	Green Buttonwood	21-30"	Yes	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	
SW 36TH AVE	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 36TH AVE	Green Buttonwood	11-15"	No	20'	Fair (41% to 60%)		Basal Co-Dominant		

(Continued on Next Page)

Street Tree Inventory

SW 36th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 36TH AVE	Japanese Privet	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH AVE	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Sprouting
SW 36TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 36TH AVE	Mahogany	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 36TH AVE	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 36TH AVE	Mahogany	41-50"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 36TH AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 36TH AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Restricted Canopy	Dead Wood
SW 36TH AVE	Mango	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 36TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 36TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 36TH AVE	Moringa	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 36TH AVE	Pongam	41-50"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 36TH AVE	Pygmy Date Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 36TH AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 36TH AVE	Pygmy Date Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 36TH AVE	Pygmy Date Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 36TH AVE	Pygmy Date Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 36TH AVE	Royal Poinciana	31-40"	No	70'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 36TH AVE	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Broken Branches
SW 36TH AVE	Royal Poinciana	31-40"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 36TH AVE	Sapodilla	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Sprouting
SW 36TH AVE	Sapodilla	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 36TH AVE	Sapodilla	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Sprouting
SW 36TH AVE	Sapodilla	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 36TH AVE	Sapodilla	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 36TH AVE	Silver Buttonwood	1-5"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate		
SW 36TH AVE	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 36TH AVE	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 36TH AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 36TH AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 36TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 36TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 36TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 36TH AVE	Spicewood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 36TH AVE	Spicewood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 36TH AVE	Starburst Clerodendron	6-10"	Yes	10'	Good (61% to 80%)				
SW 36TH AVE	Strangler Fig	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 36TH AVE	Washington Palm	11-15"	No	Negligible	Dead (0% to 5%)				
SW 36TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 36TH AVE	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 36TH AVE	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Basal Co-Dominant		
SW 36TH AVE	Weeping Fig	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Trunk Damage - Major	Decay Observed
SW 36TH AVE	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	



Looking South towards Bird Road



Looking South -near SW 29th Street



Looking South towards Bird Road



Looking North near SW 29th Terrace



Looking North - near SW 29th Street



Looking North towards SW 28th Street



Looking North near SW 29th Street



Looking North towards SW 28th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 36th Court	4	Douglas Park	2	50	1200	No	No	No	2	City	Few	Few	9	No	Yes	West	
SW 35th Avenue	4	Douglas Park	2	50	1200	No	No	No	2	City	Few	Few	9	No	Yes	West	

SW 36th Court

TYPOLOGY C

SW 35th Avenue

TYPOLOGY C

Street Tree Inventory

SW 36th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 36TH CT	Areca Palm	16-20"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 36TH CT	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)				
SW 36TH CT	Chinese Fan Palm	11-15"	No	15'	Good (61% to 80%)				
SW 36TH CT	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)				
SW 36TH CT	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 36TH CT	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 36TH CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	One Dead Trunk		
SW 36TH CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	One Dead Trunk		
SW 36TH CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	One Dead Trunk		
SW 36TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 36TH CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 36TH CT	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 36TH CT	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 36TH CT	Christmas Palm	6-10"	No	Negligible	Poor (21% to 40%)	Utility Line Conflict	Over Pruned	Reduced Canopy - Major	
SW 36TH CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 36TH CT	Kapok	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 36TH CT	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 36TH CT	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 36TH CT	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 36TH CT	Paradise Tree	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Dead Wood	
SW 36TH CT	Pink Tabebuia	1-5"	No	5'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate		
SW 36TH CT	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 36TH CT	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 36TH CT	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 36TH CT	Pygmy Date Palm	1-5"	No	5'	Fair (41% to 60%)		Frizzled Fronds		
SW 36TH CT	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 36TH CT	Royal Poinciana	21-30"	No	50'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Dead Wood
SW 36TH CT	Royal Poinciana	16-20"	No	40'	Poor (21% to 40%)		Basal Co-Dominant with Adjacent Tree(s)	Reduced Canopy - Moderate	Stubs with Sprouts
SW 36TH CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 36TH CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 36TH CT	Umbrella Tree	11-15"	No	15'	Poor (21% to 40%)		Suppressed Canopy	Dead Wood	
SW 36TH CT	Umbrella Tree	6-10"	No	10'	Poor (21% to 40%)		Suppressed Canopy	Basal Co-Dominant with Adjacent Tree(s)	Trunk Damage - Major
SW 36TH CT	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Broken Branches		
SW 36TH CT	Weeping Fig	6-10"	No	10'	Poor (21% to 40%)		Over Pruned	Tip Dieback	Suppressed Canopy
SW 36TH CT	Yellow Tabebuia	11-15"	No	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting

SW 35th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 35TH AVE	Black Olive	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 35TH AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Stubs with Sprouts	Decay Observed
SW 35TH AVE	Bottlebrush	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant		
SW 35TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 35TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 35TH AVE	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 35TH AVE	Fishtail Palm	60+"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency	Codominant Leaders/Included Bark	
SW 35TH AVE	Frangipani	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 35TH AVE	Japanese Fern Tree	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 35TH AVE	Mahogany	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 35TH AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 35TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 35TH AVE	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 35TH AVE	Pygmy Date Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 35TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 35TH AVE	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 35TH AVE	Weeping Fig	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 35TH AVE	Weeping Fig	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 35TH AVE	Weeping Fig	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Dead Wood

Avenues | Roads | Courts | Places



Looking North - north end



Looking North at SW 27th Street



Looking North - SW 26th Street - north end



Looking South near SW 27th Street



Looking South near SW 27th Street



Looking South - south end at SW 28th Street



Looking South near SW 28th Terrace



At SW 29th Terrace - South end - Metro Rail

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 34th Court	4	Douglas Park	2	50	1200	No	No	No	2	City	Few	Few	9	No	Yes	No	No Outlet North
SW 33rd Court	4	Douglas Park	2	50	2400	No	No	No	2	City	Some	Few	9	No	None between SW 28th & SW 29th St	West	Jogs at SW 28th Street. No sidewalks south of SW 28th Street

SW 34th Court

TYPOLOGY C

SW 33rd Court

TYPOLOGY C & X

Street Tree Inventory

SW 34th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 34TH CT	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 34TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 34TH CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 34TH CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 34TH CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 34TH CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 34TH CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 34TH CT	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 34TH CT	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 34TH CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 34TH CT	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Sprouting	
SW 34TH CT	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 34TH CT	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 34TH CT	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 34TH CT	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 34TH CT	Paradise Tree	1-5"	No	5'	Good (61% to 80%)				
SW 34TH CT	Paradise Tree	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	Paradise Tree	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 34TH CT	Paradise Tree	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor	Strap Constricting Tree	
SW 34TH CT	Paradise Tree	1-5"	No	5'	Good (61% to 80%)				
SW 34TH CT	Paradise Tree	1-5"	No	10'	Good (61% to 80%)				
SW 34TH CT	Paradise Tree	1-5"	No	5'	Good (61% to 80%)				
SW 34TH CT	Paradise Tree	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 34TH CT	Purple Tabebuia	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Nutrient Deficiency	
SW 34TH CT	Purple Tabebuia	1-5"	No	5'	Good (61% to 80%)				
SW 34TH CT	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 34TH CT	Royal Poinciana	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 34TH CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)				
SW 34TH CT	Spicewood	1-5"	No	5'	Fair (41% to 60%)		Tip Dieback	Strap Constricting Tree	
SW 34TH CT	Spicewood	1-5"	No	5'	Good (61% to 80%)		Tip Dieback		
SW 34TH CT	Spicewood	1-5"	No	5'	Fair (41% to 60%)		Tip Dieback	Broken Support	
SW 34TH CT	Spicewood	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate	Broken Support	
SW 34TH CT	Spicewood	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate	Broken Support	
SW 34TH CT	Spicewood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	Spicewood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	Spicewood	1-5"	No	5'	Dead (0% to 5%)				
SW 34TH CT	Spicewood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	Washington Palm	6-10"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 34TH CT	White Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	White Geiger	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate	Strap Constricting Tree	
SW 34TH CT	White Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	White Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	White Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	White Geiger	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	White Geiger	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	White Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	White Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH CT	White Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		

SW 33rd Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 33RD CT	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 33RD CT	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)		Restricted Canopy		
SW 33RD CT	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 33RD CT	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 33RD CT	Black Olive	1-5"	No	10'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Crown Density - Very Low	Dead Wood	

(Continued on Next Page)

Street Tree Inventory

SW 33rd Court (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 33RD CT	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 33RD CT	Bottlebrush	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 33RD CT	Brazilian Pepper	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Lopsided/Reduced Canopy - Moderate	Basal Co-Dominant with Adjacent Tree(s)
SW 33RD CT	Canary Island Date Palm	21-30"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 33RD CT	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 33RD CT	Christmas Palm	21-30"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	21-30"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 33RD CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	One Dead Trunk		
SW 33RD CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 33RD CT	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 33RD CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 33RD CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 33RD CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 33RD CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 33RD CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 33RD CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 33RD CT	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 33RD CT	Christmas Palm	6-10"	No	5'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	6-10"	No	5'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 33RD CT	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 33RD CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 33RD CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 33RD CT	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 33RD CT	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 33RD CT	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 33RD CT	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	
SW 33RD CT	Gumbo Limbo	6-10"	Yes	10'	Poor (21% to 40%)	Utility Lines Above	Basal Co-Dominant		
SW 33RD CT	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Lopsided/Reduced Canopy - Moderate	Basal Co-Dominant with Adjacent Tree(s)
SW 33RD CT	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Restricted Canopy		
SW 33RD CT	Key Lime Tree	6-10"	Yes	15'	Good (61% to 80%)				
SW 33RD CT	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 33RD CT	Live Oak	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD CT	Live Oak	41-50"	No	50'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Trunk Damage - Major	Sprouting
SW 33RD CT	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 33RD CT	Mahogany	21-30"	Yes	30'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Lateral Branching - None	
SW 33RD CT	Mahogany	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 33RD CT	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 33RD CT	Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Trunk Damage - Minor	
SW 33RD CT	Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Trunk Damage - Minor	
SW 33RD CT	Orange Geiger	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Insect Damage Leaves	
SW 33RD CT	Oriental Arborvitae	16-20"	No	20'	Good (61% to 80%)				
SW 33RD CT	Oriental Arborvitae	16-20"	No	20'	Good (61% to 80%)				
SW 33RD CT	Papaya	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD CT	Royal Poinciana	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Sprouting
SW 33RD CT	Royal Poinciana	6-10"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 33RD CT	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD CT	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken		
SW 33RD CT	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Leaning - Minor		

(Continued on Next Page)

Street Tree Inventory

SW 33rd Court (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 33RD CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD CT	Simpson's Stopper	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Leaning - Minor	Broken Support	
SW 33RD CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Broken Support		
SW 33RD CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 33RD CT	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 33RD CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 33RD CT	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 33RD CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 33RD CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 33RD CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 33RD CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 33RD CT	Strangler Fig	6-10"	Yes	10'	Poor (21% to 40%)	Utility Lines Above	Basal Co-Dominant		
SW 33RD CT	Tropical Almond	1-5"	No	15'	Good (61% to 80%)				
SW 33RD CT	Tropical Almond	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 33RD CT	Weeping Fig	21-30"	No	20'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 33RD CT	Weeping Fig	21-30"	No	35'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Crown Density - Low	Dead Wood
SW 33RD CT	Weeping Fig	31-40"	No	30'	Poor (21% to 40%)		Basal Co-Dominant	Lopsided/Reduced Canopy - Moderate	Trunk Damage - Major
SW 33RD CT	Yellow Poinciana	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 33RD CT	Yellow Poinciana	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	
SW 33RD CT	Yellow Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	

Avenues | Roads | Courts | Places



Looking North towards Coral Way - north end



Looking North near SW 27th Terrace



Looking South near SW 25th Terrace



Looking South near SW 26th Street



Looking South at SW 27th Terrace



Looking South near SW 23rd Street



Looking South near SW 27th Terrace



Looking South towards SW 29th Terrace - South end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 34th Avenue	4	Douglas Park	2	50	2500	No	No	No	2	City	Some	Few	9	No	Yes	West	Jogs at SW 28th Street & SW 26th Street

SW 34th Avenue

TYPOLOGY A & C

Street Tree Inventory

SW 34th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 34TH AVE	Areca Palm	6-10"	Yes	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 34TH AVE	Areca Palm	1-5"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 34TH AVE	Areca Palm	11-15"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 34TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 34TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 34TH AVE	Black Olive	21-30"	No	30'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Sprouting	Decay Observed
SW 34TH AVE	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 34TH AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 34TH AVE	Black Olive	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 34TH AVE	Brazilian Pepper	41-50"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Sprouting
SW 34TH AVE	Canary Island Date Palm	21-30"	No	15'	Good (61% to 80%)				
SW 34TH AVE	Carrotwood	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 34TH AVE	Christmas Palm	11-15"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 34TH AVE	Christmas Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 34TH AVE	Christmas Palm	16-20"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 34TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 34TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 34TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	6-10"	No	5'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 34TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 34TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 34TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 34TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		Sprouting
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 34TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 34TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 34TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 34TH AVE	Crepe Myrtle	6-10"	Yes	15'	Good (61% to 80%)				
SW 34TH AVE	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)				
SW 34TH AVE	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)				
SW 34TH AVE	Day Blooming Jasmine	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 34TH AVE	Dwarf Schefflera	6-10"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy	Trunk Damage - Moderate	Dead Wood
SW 34TH AVE	Dwarf Schefflera	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above			
SW 34TH AVE	Fishtail Palm	51-60"	Yes	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 34TH AVE	Fishtail Palm	41-50"	Yes	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 34TH AVE	Glaucous Cassia	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Sprouting
SW 34TH AVE	Glaucous Cassia	1-5"	No	10'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Sprouting
SW 34TH AVE	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 34TH AVE	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)				
SW 34TH AVE	Green Buttonwood	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	
SW 34TH AVE	Green Buttonwood	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	

(Continued on Next Page)

Street Tree Inventory

SW 34th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 34TH AVE	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 34TH AVE	Green Buttonwood	1-5"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	
SW 34TH AVE	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)		Cavities	Codominant Leaders/Included Bark	
SW 34TH AVE	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)		Leaning - Moderate	Leader - Broken	
SW 34TH AVE	Green Buttonwood	6-10"	Yes	10'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting

Avenues | Roads | Courts | Places



Looking North - north end at SW 26th Street



Looking South near SW 26th Street



Looking South near SW 28th Street



Looking South near SW 28th Terrace



Looking South near SW 27th Street



Looking South - SW 27th Terrace



Looking South at SW 29th Street - South end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 33rd Avenue	4	Douglas Park	2	50	2200	No	No	No	2	City	Some	Few	9	No	None between SW 28th & SW 29th St	West	Jogs at SW 28th Street. No sidewalks south of SW 28th Street

SW 33rd Avenue

TYPOLOGY A & X

Street Tree Inventory

SW 33rd Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 33RD AVE	Bottle Palm	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 33RD AVE	Bottle Palm	6-10"	No	5'	Poor (21% to 40%)	Utility Lines Above	Nutrient Deficiency		
SW 33RD AVE	Bottle Palm	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Nutrient Deficiency		
SW 33RD AVE	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 33RD AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 33RD AVE	Crepe Myrtle	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Dahoon Holly	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Leaning - Minor	
SW 33RD AVE	Dahoon Holly	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Leaning - Minor	
SW 33RD AVE	Foxtail Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 33RD AVE	Glaucous Cassia	6-10"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 33RD AVE	Gumbo Limbo	31-40"	No	35'	Poor (21% to 40%)		Basal Co-Dominant	Constricted Roots	
SW 33RD AVE	Jamaican Dogwood	6-10"	No	10'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 33RD AVE	Live Oak	6-10"	No	15'	Good (61% to 80%)				
SW 33RD AVE	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 33RD AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Reduced Canopy - Minor	Dead Wood
SW 33RD AVE	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 33RD AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Codominant Leaders/Included Bark
SW 33RD AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Codominant Leaders/No Included Bark
SW 33RD AVE	Montgomery Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 33RD AVE	Orange Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Orange Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Pink Tabebuia	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Moderate	Sprouting
SW 33RD AVE	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)				
SW 33RD AVE	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 33RD AVE	Purple Tabebuia	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 33RD AVE	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 33RD AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 33RD AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 33RD AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 33RD AVE	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Sprouting	
SW 33RD AVE	Royal Poinciana	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Dead Wood
SW 33RD AVE	Royal Poinciana	6-10"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Sprouting
SW 33RD AVE	Royal Poinciana	11-15"	No	20'	Poor (21% to 40%)	Utility Lines Above	Lopsided/Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 33RD AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Silver Buttonwood	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Lopsided/Reduced Canopy - Moderate	
SW 33RD AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 33RD AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 33RD AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 33RD AVE	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Spanish Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor		
SW 33RD AVE	Spanish Stopper	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Leaning - Minor	Reduced Canopy - Moderate	
SW 33RD AVE	Spicewood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Spicewood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 33RD AVE	Triangle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 33RD AVE	Tropical Almond	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Limb Damage - Major	Sprouting	Codominant Leaders/Included Bark

Avenues | Roads | Courts | Places



Looking North from SW 27th Street - north end- No Outlet



Looking South from SW 27th Street



Looking South towards SW 27th Terrace



Looking South from SW 27th Terrace - South end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 31st Place	4	Douglas Park	2	50	975	No	No	No	2	City	Few	Few	9	No	Yes	West	Roundabout at SW 27th Terr. - No Outlet North & South

SW 31st Place

TYPOLOGY C

Street Tree Inventory

SW 31st Place

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 31ST PL	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Bottlebrush	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Topped	Reduced Canopy - Major	Sprouting
SW 31ST PL	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST PL	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST PL	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST PL	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 31ST PL	Dracaena sp.	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Dracaena sp.	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Dracaena sp.	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Dracaena sp.	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Dracaena sp.	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Dracaena sp.	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Dracaena sp.	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Sprouting	Dead Wood	
SW 31ST PL	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 31ST PL	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST PL	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST PL	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST PL	Weeping Fig	1-5"	No	10'	Good (61% to 80%)				

Avenues | Roads | Courts | Places



Looking North from SW 27th Street - north end - No Outlet



Looking South from SW 27th Street



Looking North from SW 27th Street - north end



Looking south from SW 27th Street



Looking North from SW 27th Terrace



Looking South from SW 27th Terrace - South End



Looking North from SW 27th Terrace



Looking South from SW 27th Terrace - South End

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 31st Court	4	Douglas Park	2	50	975	No	No	No	2	City	Few	Few	9	No	Yes	West	No Outlet at north end
SW 30th Court	4	Douglas Park	2	50	950	No	No	No	2	City	Some	Few	9	No	Yes	West	No Outlet at north end

SW 31st Court

TYPOLOGY A & C

SW 30th Court

TYPOLOGY C & A

Street Tree Inventory

SW 31st Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 31ST CT	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST CT	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST CT	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST CT	Black Olive	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 31ST CT	Black Olive	16-20"	No	30'	Good (61% to 80%)		Restricted Canopy	Reduced Canopy - Minor	Sprouting
SW 31ST CT	Black Olive	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 31ST CT	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Tapered Trunk	
SW 31ST CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 31ST CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Tapered Trunk	Leader - Bent
SW 31ST CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 31ST CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST CT	Day Blooming Jasmine	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 31ST CT	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Topped	Restricted Canopy	Sprouting
SW 31ST CT	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Topped	Restricted Canopy	Sprouting
SW 31ST CT	Live Oak	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy	Suppressed Canopy	
SW 31ST CT	Neem Tree	6-10"	Yes	15'	Poor (21% to 40%)	Utility Line Conflict	Topped	Suppressed Canopy	Sprouting
SW 31ST CT	Pink Tabebuia	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Dead Wood	
SW 31ST CT	Pink Tabebuia	16-20"	No	30'	Good (61% to 80%)	Utility Line Conflict	Insect Damage Leaves	Dead Wood	
SW 31ST CT	Sea Grape	21-30"	Yes	30'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 31ST CT	Silver Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure		
SW 31ST CT	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 31ST CT	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 31ST CT	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST CT	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			

SW 30th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 30TH CT	Bottlebrush	1-5"	No	10'	Poor (21% to 40%)	Utility Lines Above	Crown Density - Very Low	Dead Wood	Insect Damage Leaves
SW 30TH CT	Brazilian Pepper	6-10"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Topped	Sprouting	
SW 30TH CT	Brazilian Pepper	6-10"	No	Negligible	Dead (0% to 5%)				
SW 30TH CT	Cabbage Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Suppressed Canopy	
SW 30TH CT	Cabbage Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Suppressed Canopy	
SW 30TH CT	Chinese Fan Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Chinese Fan Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency	Trunk Damage - Minor	
SW 30TH CT	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Restricted Canopy	Suppressed Canopy
SW 30TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 30TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	Frizzled Fronds
SW 30TH CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency	Frizzled Fronds	
SW 30TH CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 30TH CT	Gumbo Limbo	1-5"	No	15'	Fair (41% to 60%)		Leader - Broken	Sprouting	Restricted Canopy
SW 30TH CT	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 30TH CT	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 30th Court (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 30TH CT	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 30TH CT	Live Oak	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 30TH CT	Live Oak	1-5"	No	15'	Good (61% to 80%)		Dead Wood		
SW 30TH CT	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Leader - Broken	Leaning - Minor	Dead Wood
SW 30TH CT	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Dead Wood
SW 30TH CT	Live Oak	6-10"	No	15'	Good (61% to 80%)		Sprouting	Dead Wood	
SW 30TH CT	Mahogany	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Minor	Reduced Canopy - Moderate
SW 30TH CT	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 30TH CT	Norfolk Pine	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 30TH CT	Rubber Tree	6-10"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 30TH CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Frizzled Fronds	
SW 30TH CT	Umbrella Tree	21-30"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Sprouting
SW 30TH CT	Umbrella Tree	6-10"	No	5'	Good (61% to 80%)				
SW 30TH CT	Umbrella Tree	21-30"	No	25'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 30TH CT	Washington Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 30TH CT	Washington Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		

Avenues | Roads | Courts | Places



Looking North towards Coral Way - North End



Looking South near SW 23rd Terrace



Looking North from SW 27th Street - North end



Looking South from SW 27th Street



Looking South near SW 24th Terrace



Looking South towards SW 26th Street



Looking North near SW 28th Street



Looking South at US 1

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 31st Avenue	4	Douglas Park	2	50	1750	No	No	No	2	City	Few	Few	10	Only at US 1	Yes	West	No Outlet at north end

SW 31st Avenue

TYPOLOGY C & A

Street Tree Inventory

SW 31st Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 31ST AVE	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Areca Palm	51-60"	Yes	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 31ST AVE	Areca Palm	41-50"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Avocado	16-20"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Moderate	Trunk Damage - Major	Decay Observed
SW 31ST AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Bougainvillea sp.	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Bougainvillea sp.	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Brazilian Beauty Leaf	1-5"	No	Negligible	Dead (0% to 5%)				
SW 31ST AVE	Brazilian Pepper	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Cabbage Palm	11-15"	No	15'	Fair (41% to 60%)		Suppressed Canopy		
SW 31ST AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 31ST AVE	Cabbage Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Major	Tapered Trunk	
SW 31ST AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 31ST AVE	Christmas Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 31ST AVE	Christmas Palm	21-30"	Yes	20'	Good (61% to 80%)				
SW 31ST AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Coconut Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 31ST AVE	Coconut Palm	11-15"	Yes	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 31ST AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 31ST AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 31ST AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 31ST AVE	Day Blooming Jasmine	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	Fishtail Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 31ST AVE	Foxtail Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	Growing on Utility Box
SW 31ST AVE	Gumbo Limbo	31-40"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Decay Observed	Codominant Leaders/Included Bark
SW 31ST AVE	Gumbo Limbo	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Leaning - Moderate	Decay Observed
SW 31ST AVE	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 31ST AVE	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Suppressed Canopy
SW 31ST AVE	Jaimacan Dogwood	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 31ST AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark	
SW 31ST AVE	Live Oak	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 31ST AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Dead Wood		
SW 31ST AVE	Live Oak	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Dead Wood		
SW 31ST AVE	Mahogany	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 31ST AVE	Mahogany	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 31ST AVE	Mahogany	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 31ST AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 31ST AVE	Manilla Tamarind	41-50"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 31ST AVE	Necklace Pod Tree	16-20"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 31ST AVE	Orange Geiger	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Dead Wood		

(Continued on Next Page)

Street Tree Inventory

SW 31st Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 31ST AVE	Oriental Arborvitae	11-15"	No	10'	Good (61% to 80%)				
SW 31ST AVE	Pink Tabebuia	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Sprouting
SW 31ST AVE	Queen Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Restricted Canopy	
SW 31ST AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 31ST AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 31ST AVE	Queen Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 31ST AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor	Nutrient Deficiency	
SW 31ST AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor	Restricted Canopy	Nutrient Deficiency
SW 31ST AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy	Nutrient Deficiency	
SW 31ST AVE	Royal Poinciana	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Sprouting	
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Silver Buttonwood	11-15"	Yes	15'	Good (61% to 80%)				
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	10'	Fair (41% to 60%)		Vine Cover - Heavy	Crown Density - Low	
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Silver Buttonwood	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Restricted Canopy		
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Suppressed Canopy		
SW 31ST AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Suppressed Canopy	Leaning - Moderate	
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Suppressed Canopy		
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	Silver Buttonwood	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	Silver Buttonwood	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Leaning - Minor		
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 31ST AVE	Silver Buttonwood	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	Silver Buttonwood	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	Silver Buttonwood	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Suppressed Canopy		
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Dead Wood		
SW 31ST AVE	Silver Buttonwood	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Dead Wood		
SW 31ST AVE	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 31ST AVE	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 31ST AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 31ST AVE	Strangler Fig	6-10"	Yes	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 31ST AVE	Umbrella Tree	6-10"	Yes	10'	Good (61% to 80%)				
SW 31ST AVE	Vera Wood	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 31ST AVE	Washington Palm	16-20"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 31ST AVE	Weeping Fig	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Crown Density - Moderate	Dead Wood
SW 31ST AVE	Weeping Fig	16-20"	No	30'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure	Dead Wood	
SW 31ST AVE	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 31ST AVE	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 31ST AVE	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 31ST AVE	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 31ST AVE	Woman's Tongue	41-50"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed

Avenues | Roads | Courts | Places



Looking North from SW 27th Street - north end



Looking South from SW 27th Street



SW 29th Place -Looking North from SW 27th Street



SW 29th Court - Looking North from SW 27th Street



Looking South at SW 27th Terrace



Looking South at SW 28th Lane



SW 29th Court - Looking South from SW 27th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 30th Avenue	4	Douglas Park	2	50	1250	No	No	No	2	City	Few	Few	9	No	Some	West	No Outlet at north end
SW 29th Place	4	Douglas Park	2	30	300	No	No	No	2	City	No	Few	0	No	Some	No	No Outlet at north end
SW 29th Court	4	Douglas Park	2	30/50	600	No	No	No	2	City	Few	Few	9	No	Some	Some on West	Roundabout at south end - No Outlet North & South

SW 30th Avenue

TYPOLOGY A & C

SW 29th Place & SW 29th Court

TYPOLOGY A & X

Street Tree Inventory

SW 30th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 30TH AVE	Bougainvillea sp.	6-10"	No	10'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 30TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 30TH AVE	Royal Poinciana	41-50"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 30TH AVE	Umbrella Tree	21-30"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 30TH AVE	Vera Wood	6-10"	No	30'	Good (61% to 80%)		Dead Wood		
SW 30TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		

SW 29th Place

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH PL	Weeping Fig	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub	Crown Density - Moderate	Dead Wood
SW 29TH PL	Weeping Fig	11-15"	No	10'	Fair (41% to 60%)		Multi-Trunk Form - Not Downgraded for Structure	Crown Density - Low	Dead Wood

SW 29th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH CT	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 29TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	Restricted Canopy
SW 29TH CT	Spindle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	Leaning - Minor
SW 29TH CT	Strangler Fig	6-10"	No	20'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 29TH CT	Tamarind	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 29TH CT	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub	Dead Wood	

Avenues | Roads | Courts | Places



Looking North towards Coral Way - north end



Looking North near SW 23rd Terrace



Looking North from SW 27th Street



Looking North towards SW 27th Street



Looking North near SW 25th Street



Looking North near SW 26th Street



Looking South towards SW 27th Terrace



Looking East towards SW 27th Avenue - Metrorail Station

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 29th Avenue - North	4	Douglas Park	2	50	2500	No	No	No	2	City	Few	Few	9	At Coral Way	Yes	West	Coral Way to SW 26th Street
SW 29th Avenue - South	4	Douglas Park	2	30/50	1050	No	No	No	2	City	Some Between SW 28th St and SW 27th Terr.	Few	9	At Metrorail	Yes	Some on West	Guardrail break at SW 27th Terrace - No Outlet North. Typology A only between SW 27th St & SW 27th Terr

SW 29th Avenue - North
TYPOLOGY A & C

SW 29th Avenue - South
TYPOLOGY A & X

Street Tree Inventory

SW 29th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH AVE	Bamboo Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Black Olive	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 29TH AVE	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Black Olive	6-10"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Black Olive	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Black Olive	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Bottle Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Brazilian Pepper	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 29TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 29TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 29TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 29TH AVE	Golden Rain Tree	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy		
SW 29TH AVE	Live Oak	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark		
SW 29TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 29TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 29TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots		
SW 29TH AVE	Mahogany	51-60"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 29TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 29TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 29TH AVE	Mahogany	41-50"	No	65'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 29TH AVE	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 29TH AVE	Mahogany	41-50"	No	65'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Crown Density - Moderate	Dead Wood
SW 29TH AVE	Mahogany	41-50"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Crown Density - Moderate	Dead Wood
SW 29TH AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Minor	Reduced Canopy - Major	Sprouting
SW 29TH AVE	Mahogany	31-40"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	Dead Wood
SW 29TH AVE	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 29TH AVE	Mahogany	41-50"	No	65'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 29TH AVE	Mango	1-5"	No	15'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark		
SW 29TH AVE	Oriental Arborvitae	6-10"	No	15'	Good (61% to 80%)				
SW 29TH AVE	Oriental Arborvitae	11-15"	No	15'	Good (61% to 80%)				
SW 29TH AVE	Oriental Arborvitae	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 29TH AVE	Oriental Arborvitae	11-15"	No	20'	Good (61% to 80%)				
SW 29TH AVE	Oriental Arborvitae	16-20"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 29TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 29TH AVE	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	
SW 29TH AVE	Weeping Fig	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Weeping Fig	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Weeping Fig	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Weeping Fig	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH AVE	Weeping Fig	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor		
SW 29TH AVE	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)				
SW 29TH AVE	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 29th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH AVE	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)				
SW 29TH AVE	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)				
SW 29TH AVE	Woman's Tongue	16-20"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	
SW 29TH AVE	Woman's Tongue	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Dead Wood	
SW 29TH AVE	Woman's Tongue	1-5"	No	5'	Dead (0% to 5%)	Utility Lines Above			
SW 29TH AVE	Woman's Tongue	11-15"	No	15'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Crown Density - Very Low	Sloughing Bark	Dead Wood

Avenues | Roads | Courts | Places



SW 28th Court - Looking North from SW 27th Street



SW 28th Court - Looking South from SW 27th Street



Looking North from SW 27th Street



Looking South from SW 27th Street



SW 28th Avenue - Looking North from SW 27th Street



SW 28th Avenue - Looking South from SW 27th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 28th Court	4	Douglas Park	2	50	650	No	No	No	2	City	No	No	4	No	Some	West	No Outlet North & South
SW 28th Avenue	4	Douglas Park	2	30	650	No	No	No	2	City	No	No	4	No	Some	West	No Outlet North & South
SW 27th Court	4	Douglas Park	2	30	650	No	No	No	2	City	No	No	0	East side one block	East side one block	West	No Outlet North & South

SW 28th Court & SW 28th Avenue

TYPOLOGY X

SW 27th Court

TYPOLOGY X

Street Tree Inventory

SW 28th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 28TH CT	Areca Palm	31-40"	Yes	20'	Good (61% to 80%)		Nutrient Deficiency		

SW 27th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH CT	Bottle Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH CT	Bottle Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH CT	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH CT	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH CT	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH CT	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		

*Note there are no trees on SW 28th Avenue



Looking North - north end at SW 29th Street



Looking South near SW 29th Street



Looking South near SW 27th Terrace



Looking South near SW 27th Street



Looking South - south end at SW 28th Street



Looking South near SW 28th Street



Looking South at SW 29th Street - South end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 32nd Court	4	Douglas Park	2	50	2200	No	No	No	2	City	Some	Few	9	No	Yes	West	Roundabout at SW 28th St.

SW 32nd Court

TYPOLOGY C & A

Street Tree Inventory

SW 32nd Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 32ND CT	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 32ND CT	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 32ND CT	Areca Palm	16-20"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 32ND CT	Bismark Palm	21-30"	No	5'	Fair (41% to 60%)		Over Pruned		
SW 32ND CT	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 32ND CT	Bottle Palm	11-15"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 32ND CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 32ND CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 32ND CT	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 32ND CT	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 32ND CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 32ND CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 32ND CT	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 32ND CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 32ND CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 32ND CT	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 32ND CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 32ND CT	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 32ND CT	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 32ND CT	Crepe Myrtle	6-10"	Yes	5'	Fair (41% to 60%)		Over Pruned	Crown Density - Moderate	
SW 32ND CT	Crepe Myrtle	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 32ND CT	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 32ND CT	Crepe Myrtle	16-20"	Yes	10'	Good (61% to 80%)				
SW 32ND CT	Desert Cassia	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Desert Cassia	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Dracaena sp.	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Glaucous Cassia	6-10"	No	20'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Strap Constricting Tree	Dead Wood
SW 32ND CT	Green Buttonwood	1-5"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Sprouting	Dead Wood	
SW 32ND CT	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 32ND CT	Green Buttonwood	6-10"	No	20'	Good (61% to 80%)				
SW 32ND CT	Green Buttonwood	6-10"	No	20'	Good (61% to 80%)				
SW 32ND CT	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Cavities
SW 32ND CT	Hong Kong Orchid	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 32ND CT	Ixora	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Ixora	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Japanese Privet	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Japanese Privet	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 32ND CT	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 32ND CT	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Sprouting
SW 32ND CT	Montgomery Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Suppressed Canopy		
SW 32ND CT	Oriental Arborvitae	11-15"	No	15'	Good (61% to 80%)				
SW 32ND CT	Oriental Arborvitae	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 32ND CT	Pink Tabebuia	1-5"	No	5'	Poor (21% to 40%)		Strap Constricting Tree	Crown Density - Low	
SW 32ND CT	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Pygmy Date Palm	6-10"	Yes	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 32ND CT	Queen Palm	6-10"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Nutrient Deficiency	
SW 32ND CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 32ND CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 32ND CT	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 32ND CT	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 32ND CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				


(Continued on Next Page)

Street Tree Inventory


SW 32nd Court (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 32ND CT	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 32ND CT	Spicewood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 32ND CT	Strangler Fig	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 32ND CT	Strangler Fig	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Sprouting
SW 32ND CT	Tropical Almond	1-5"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 32ND CT	Weeping Fig	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant		
SW 32ND CT	Weeping Fig	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Over Extended Limb(s)		
SW 32ND CT	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		

Streets | Terraces | Lanes



At SW 37th Avenue - West end



Looking East towards SW 34th Avenue



Looking West towards SW 32nd Avenue



Looking East near SW 31st Avenue



Looking East towards SW 36th Avenue



Looking East at SW32nd Avenue



Looking East near SW 29th Avenue



Looking East towards SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 22nd Terrace	4	Douglas Park	2	50	5,350	No	North Side	No	2	City	Few	No	8	North only	Yes	North	Valley gutter on South side. Some open paver swales on south side. No swale on north side


SW 22nd Terrace

TYPOLOGY A & B

Street Tree Inventory

SW 22nd Terrace


STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND TER	Crepe Myrtle	16-20"	Yes	20'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 22ND TER	Crepe Myrtle	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 22ND TER	Crepe Myrtle	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 22ND TER	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 22ND TER	Crepe Myrtle	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 22ND TER	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 22ND TER	Crepe Myrtle	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 22ND TER	Crepe Myrtle	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 22ND TER	Crepe Myrtle	1-5"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 22ND TER	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 22ND TER	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 22ND TER	Live Oak	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 22ND TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 22ND TER	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 22ND TER	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 22ND TER	Mahogany	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 22ND TER	Norfolk Pine	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 22ND TER	Norfolk Pine	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 22ND TER	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate	Sprouting	Insect Damage Leaves
SW 22ND TER	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor	Sprouting	Insect Damage Leaves
SW 22ND TER	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Sprouting	Leaning - Major
SW 22ND TER	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Leader - Broken	Sprouting	Leaning - Major
SW 22ND TER	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 22ND TER	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Leader - Broken	Sprouting	Dead Wood
SW 22ND TER	Orange Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Minor	Sprouting	Leaning - Moderate
SW 22ND TER	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 22ND TER	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 22ND TER	Sandbox Tree	11-15"	Yes	10'	Poor (21% to 40%)		Reduced Canopy - Major	Dead Wood	Suppressed Canopy
SW 22ND TER	Sandbox Tree	11-15"	Yes	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 22ND TER	Sandbox Tree	6-10"	Yes	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 22ND TER	Sandbox Tree	6-10"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 22ND TER	Silk Oak	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND TER	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 22ND TER	Silver Buttonwood	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken		
SW 22ND TER	Strangler Fig	60+"	No	65'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND TER	Weeping Fig	11-15"	No	15'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 22ND TER	Weeping Fig	1-5"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Codominant Leaders/Included Bark	
SW 22ND TER	Weeping Fig	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Codominant Leaders/No Included Bark	



At SW 37th Avenue - West end




Looking East near SW 34th Avenue




Looking West towards SW 32nd Avenue



Looking West near SW 31st Avenue



Looking East near SW 36th Avenue



Looking East at SW 32nd Avenue



Looking West near SW 29th Avenue



Looking East towards SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 23rd Street	4	Douglas Park	2	70	5,350	No	at SW 37th Ave. Only	No	2	City	Few	Few	18	at SW 37th Ave. Only	Yes	North	Large Swales - 18' on north and 20' on south

SW 23rd Street

TYPOLOGY A

Street Tree Inventory

SW 23rd Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD ST	Areca Palm	31-40"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD ST	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 23RD ST	Australian Pine	51-60"	No	55'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Sprouting
SW 23RD ST	Avocado	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 23RD ST	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 23RD ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 23RD ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 23RD ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 23RD ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 23RD ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Major
SW 23RD ST	Black Olive	31-40"	No	60'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 23RD ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 23RD ST	Black Olive	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 23RD ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Bottlebrush	16-20"	No	25'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 23RD ST	Bottlebrush	6-10"	Yes	15'	Fair (41% to 60%)		Basal Co-Dominant	Lopsided/Moderately Reduced Canopy	Restricted Canopy
SW 23RD ST	Brazilian Beauty Leaf	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Discolored Foliage	
SW 23RD ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 23RD ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 23RD ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 23RD ST	Canary Island Date Palm	21-30"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Line Conflict	Dead Meristem	Nutrient Deficiency	
SW 23RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Christmas Palm	6-10"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Frizzled Fronds	
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	One Missing Trunk		
SW 23RD ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Over Pruned	
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Tapered Trunk	

(Continued on Next Page)

Street Tree Inventory

SW 23rd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Over Pruned		
SW 23RD ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Over Pruned		
SW 23RD ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Over Pruned		
SW 23RD ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD ST	Coconut Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Crepe Myrtle	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Desiccated Foliage		
SW 23RD ST	Cycad	6-10"	No	10'	Good (61% to 80%)				
SW 23RD ST	Cycad	11-15"	No	10'	Good (61% to 80%)				
SW 23RD ST	Cycad	11-15"	No	5'	Good (61% to 80%)				
SW 23RD ST	Fishtail Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency	Fungus on Leaves	
SW 23RD ST	Fishtail Palm	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 23RD ST	Foxtail Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Golden Rain Tree	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 23RD ST	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 23RD ST	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 23RD ST	Green Buttonwood	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant		
SW 23RD ST	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Restricted Canopy	
SW 23RD ST	Hackberry	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	
SW 23RD ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Sprouting	Dead Wood	Reduced Canopy - Minor
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	Reduced Canopy - Minor
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	Reduced Canopy - Minor
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	Reduced Canopy - Minor
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	Reduced Canopy - Minor
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	Reduced Canopy - Minor
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	Reduced Canopy - Minor
SW 23RD ST	Live Oak	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 23RD ST	Live Oak	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 23RD ST	Live Oak	1-5"	No	15'	Poor (21% to 40%)	Utility Lines Above	Plunged	Crown Density - Low	Codominant Leaders/Included Bark
SW 23RD ST	Live Oak	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 23RD ST	Live Oak	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 23RD ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark	
SW 23RD ST	Live Oak	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Topped	Sprouting
SW 23RD ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	Sprouting
SW 23RD ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Crown Density - Excessive (Due to Epicormic Growth)		
SW 23RD ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark	
SW 23RD ST	Live Oak	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark	Sprouting	
SW 23RD ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Trunk Damage - Moderate	Stubs with Sprouts
SW 23RD ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 23RD ST	Live Oak	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Sprouting	
SW 23RD ST	Live Oak	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 23RD ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 23RD ST	Live Oak	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 23RD ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD ST	Mahogany	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Sprouting	
SW 23RD ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD ST	Mahogany	1-5"	No	10'	Poor (21% to 40%)		Leader - Broken		
SW 23RD ST	Mahogany	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 23RD ST	Norfolk Pine	6-10"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 23RD ST	Norfolk Pine	6-10"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			


(Continued on Next Page)

Street Tree Inventory

SW 23rd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD ST	Norfolk Pine	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD ST	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy	Insect Damage Leaves	Codominant Leaders/Included Bark
SW 23RD ST	Orange Geiger	1-5"	No	10'	Poor (21% to 40%)		Limb Damage - Moderate	Sprouting	Strap Constricting Tree
SW 23RD ST	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)		Leaning - Minor	Codominant Leaders/No Included Bark	
SW 23RD ST	Orange Geiger	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant		
SW 23RD ST	Orange Geiger	1-5"	No	10'	Poor (21% to 40%)	Utility Lines Above	Leaning - Moderate	Lopsided/Moderately Reduced Canopy	Strap Constricting Tree
SW 23RD ST	Orange Geiger	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Crown Density - Very Low	Strap Constricting Tree	
SW 23RD ST	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Leaning - Minor		
SW 23RD ST	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Leaning - Minor	
SW 23RD ST	Queen Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)				
SW 23RD ST	Queen Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Damaged Fronds	Nutrient Deficiency
SW 23RD ST	Queen Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 23RD ST	Queen Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 23RD ST	Rainbow Eucalyptus	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Discolored Foliage		
SW 23RD ST	Royal Poinciana	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 23RD ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 23RD ST	Royal Poinciana	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 23RD ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Solitaire Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 23RD ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Solitaire Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Solitaire Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 23RD ST	Starburst Clerodendron	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 23RD ST	Starburst Clerodendron	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy	Codominant Leaders/Included Bark	
SW 23RD ST	Starburst Clerodendron	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 23RD ST	Tropical Almond	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Tropical Almond	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Apical Dieback	
SW 23RD ST	Tropical Almond	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Discolored Foliage	Codominant Leaders/Included Bark
SW 23RD ST	Umbrella Tree	21-30"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	Multi-Trunk Form - Not Downgraded for Structure
SW 23RD ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 23RD ST	Washington Palm	16-20"	No	15'	Good (61% to 80%)				
SW 23RD ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)				
SW 23RD ST	Weeping Fig	21-30"	No	15'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 23RD ST	Weeping Fig	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 23RD ST	Weeping Fig	1-5"	Yes	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Cavities	Codominant Leaders/Included Bark
SW 23RD ST	Weeping Fig	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	
SW 23RD ST	Weeping Fig	6-10"	No	10'	Poor (21% to 40%)		Topped	Sprouting	Decay Observed
SW 23RD ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 23RD ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	One Missing Trunk	

Streets | Terraces | Lanes



At SW 37th Avenue - West end



Looking East near SW 36th Avenue




Looking West towards SW 32nd Avenue



Looking East near SW 31st Avenue



Looking East near SW 34th Avenue



Looking East at SW 32nd Avenue



Looking East near SW 29th Avenue



Looking East towards SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 23rd Terrace	4	Douglas Park	2	50	5,350	No	Only at SW 32nd Ave. south side	No	2	City	Few	Few	12	at SW 37th Ave. & SW 32nd Ave	Most of Street	North	Numerous paved swales

SW 23rd Terrace

TYPOLOGY A & C

Street Tree Inventory

SW 23rd Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD TER	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Areca Palm	11-15"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 23RD TER	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 23RD TER	Black Olive	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 23RD TER	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 23RD TER	Black Olive	21-30"	No	20'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 23RD TER	Bottlebrush	11-15"	No	10'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Moderate	Stubs with Sprouts
SW 23RD TER	Cabbage Palm	16-20"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Cabbage Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Tapered Trunk		
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	6-10"	No	Negligible	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		One Dead Trunk		
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 23RD TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD TER	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)				
SW 23RD TER	Foxtail Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 23RD TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 23RD TER	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Trunk Damage - Minor	
SW 23RD TER	Green Buttonwood	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 23RD TER	Green Buttonwood	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 23RD TER	Green Buttonwood	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Restricted Canopy	
SW 23RD TER	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 23RD TER	Gumbo Limbo	21-30"	No	20'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	
SW 23RD TER	Live Oak	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 23RD TER	Mahogany	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD TER	Mahogany	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD TER	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD TER	Mahogany	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD TER	Mahogany	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 23RD TER	Mahogany	6-10"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Moderate	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD TER	Mahogany	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Moderate	Crown Density - Excessive (Due to Epicormic Growth)

(Continued on Next Page)

Street Tree Inventory

SW 23rd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD TER	Norfolk Pine	1-5"	Yes	5'	Fair (41% to 60%)		Basal Co-Dominant		
SW 23RD TER	Norfolk Pine	1-5"	Yes	5'	Fair (41% to 60%)		Basal Co-Dominant		
SW 23RD TER	Oriental Arborvitae	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 23RD TER	Oriental Arborvitae	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 23RD TER	Rubber Tree	51-60"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 23RD TER	Rubber Tree	11-15"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 23RD TER	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 23RD TER	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 23RD TER	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD TER	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 23RD TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 23RD TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 23RD TER	Travelers Palm	41-50"	Yes	20'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Triangle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Umbrella Tree	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 23RD TER	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 23RD TER	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 23RD TER	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 23RD TER	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 23RD TER	Weeping Fig	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lifting	Stubs



At SW 37th Avenue - West end



Looking East near SW 34th Avenue



Looking West towards SW 32nd Avenue



Looking West near SW 31st Avenue



Looking East near SW 36th Avenue



Looking East at SW 32nd Avenue



Looking West near SW 29th Avenue



Looking East towards SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 24th Street	4	Douglas Park	2	50	5,350	No	No	No	2	City	Few	Few	9	at SW 37th Ave. & SW 32nd Ave	Most of Street	North	Numerous paved swales

SW 24th Street

TYPOLOGY C & A

Street Tree Inventory

SW 24th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH ST	Areca Palm	21-30"	Yes	20'	Good (61% to 80%)				
SW 24TH ST	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Areca Palm	16-20"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH ST	Australian Pine	31-40"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH ST	Banyan	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 24TH ST	Banyan	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Black Olive	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Trunk Damage - Minor	
SW 24TH ST	Black Olive	6-10"	No	20'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Restricted Canopy	Trunk Damage - Major	Sprouting
SW 24TH ST	Black Olive	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 24TH ST	Black Olive	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 24TH ST	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)		Over Pruned		
SW 24TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)		Over Pruned		
SW 24TH ST	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Over Pruned		
SW 24TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Over Pruned		
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Over Pruned		
SW 24TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 24TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 24TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 24TH ST	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Moderate	
SW 24TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH ST	Italian Cypress	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Kapok	60+"	No	75'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH ST	Live Oak	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH ST	Live Oak	11-15"	No	15'	Poor (21% to 40%)		Girdling Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 24TH ST	Live Oak	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Reduced Canopy - Moderate
SW 24TH ST	Mahogany	41-50"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH ST	Mahogany	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant		
SW 24TH ST	Oriental Arborvitae	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH ST	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 24TH ST	Pink Tabebuia	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Lopsided/Moderately Reduced Canopy	
SW 24TH ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH ST	Satin Leaf	1-5"	No	10'	Good (61% to 80%)				
SW 24TH ST	Slash Pine	6-10"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Umbrella Tree	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Lopsided/Moderately Reduced Canopy	Basal Co-Dominant
SW 24TH ST	Umbrella Tree	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 24TH ST	Umbrella Tree	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH ST	Weeping Fig	16-20"	Yes	15'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Restricted Canopy	
SW 24TH ST	Weeping Fig	6-10"	No	10'	Poor (21% to 40%)		Lopsided/Moderately Reduced Canopy	Restricted Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 24th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH ST	Weeping Fig	6-10"	No	10'	Poor (21% to 40%)		Lopsided/Moderately Reduced Canopy	Restricted Canopy	
SW 24TH ST	Weeping Fig	6-10"	No	15'	Poor (21% to 40%)		Lopsided/Moderately Reduced Canopy	Restricted Canopy	
SW 24TH ST	Weeping Fig	6-10"	Yes	10'	Poor (21% to 40%)		Lopsided/Moderately Reduced Canopy	Restricted Canopy	Basal Co-Dominant
SW 24TH ST	Weeping Fig	6-10"	Yes	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Basal Co-Dominant	
SW 24TH ST	Weeping Fig	6-10"	Yes	5'	Poor (21% to 40%)		Lopsided/Moderately Reduced Canopy	Basal Co-Dominant	
SW 24TH ST	Weeping Fig	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 24TH ST	Weeping Fig	1-5"	Yes	5'	Fair (41% to 60%)		Basal Co-Dominant		

Streets | Terraces | Lanes



At SW 37th Avenue - West end



Looking East near SW 36th Avenue



Looking West towards SW 32nd Avenue



Looking West near SW 31st Avenue



Looking East near SW 34th Avenue



Looking East at SW 32nd Avenue



Looking West near SW 29th Avenue



Looking East towards SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 24th Terrace	4	Douglas Park	2	50	5,350	No	No	No	2	City	Few	Few	9	at SW 37th Ave. & SW 32nd Ave	Most of Street	North	Numerous paved swales

SW 24th Terrace

TYPOLOGY C & A

Street Tree Inventory

SW 24th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH TER	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH TER	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH TER	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH TER	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 24TH TER	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Topped	Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH TER	Black Olive	21-30"	No	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Sprouting	
SW 24TH TER	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 24TH TER	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 24TH TER	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH TER	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH TER	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 24TH TER	Cabbage Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 24TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Leader - Bent	
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH TER	Crepe Myrtle	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Crepe Myrtle	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH TER	Leopard Tree	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH TER	Live Oak	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Topped	Reduced Canopy - Major	Stubs with Sprouts
SW 24TH TER	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Apical Dieback	Dead Wood	
SW 24TH TER	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)		
SW 24TH TER	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark	
SW 24TH TER	Live Oak	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Crown Density - Moderate	Dead Wood
SW 24TH TER	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 24TH TER	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders/Included Bark
SW 24TH TER	Mahogany	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 24TH TER	Norfolk Pine	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH TER	Oriental Arborvitae	16-20"	No	15'	Good (61% to 80%)		Dead Wood		
SW 24TH TER	Pink Tabebuia	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 24TH TER	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 24TH TER	Queen Palm	6-10"	No	10'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy		
SW 24TH TER	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 24TH TER	Strangler Fig	21-30"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Sprouting	
SW 24TH TER	Strangler Fig	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Sprouting
SW 24TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Washington Palm	11-15"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH TER	Weeping Fig	21-30"	No	5'	Dead (0% to 5%)				
SW 24TH TER	Weeping Fig	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 24TH TER	Weeping Fig	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Sprouting	

(Continued on Next Page)

Street Tree Inventory

SW 24th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH TER	Weeping Fig	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Crown Density - Moderate	Dead Wood
SW 24TH TER	Weeping Fig	31-40"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Sprouting

Streets | Terraces | Lanes



At SW 37th Avenue - West end



Looking East near SW 36th Avenue



Looking East from SW 32nd Avenue



Looking West near SW 31st Avenue



Looking East near SW 34th Avenue



Looking East at SW 32nd Avenue



Looking West near SW 29th Avenue



Looking East towards SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 25th Street	4	Douglas Park	2	50	5,350	No	No	No	2	City	Few	Few	9	at SW 37th Ave. & SW 32nd Ave	Yes	North	Numerous paved swales

SW 25th Street

TYPOLOGY C & A

Street Tree Inventory

SW 25th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH ST	Bamboo Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 25TH ST	Bamboo Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH ST	Bismark Palm	21-30"	No	20'	Good (61% to 80%)				
SW 25TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Restricted Canopy
SW 25TH ST	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 25TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 25TH ST	Black Olive	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 25TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Bottle Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 25TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 25TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 25TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH ST	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 25TH ST	Japanese Fern Tree	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 25TH ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	Sprouting
SW 25TH ST	Mahogany	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 25TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 25TH ST	Mahogany	16-20"	No	30'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 25TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 25TH ST	Montgomery Palm	1-5"	No	15'	Good (61% to 80%)				
SW 25TH ST	Oleander	1-5"	Yes	5'	Good (61% to 80%)				
SW 25TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 25TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 25TH ST	Oriental Arborvitae	21-30"	No	25'	Good (61% to 80%)				
SW 25TH ST	Oriental Arborvitae	21-30"	No	25'	Good (61% to 80%)				
SW 25TH ST	Oriental Arborvitae	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 25th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Frizzled Fronds	
SW 25TH ST	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 25TH ST	Sapodilla	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Nutrient Deficiency	Codominant Leaders/No Included Bark
SW 25TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Strangler Fig	11-15"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Growing on Rock	
SW 25TH ST	Tamarind	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 25TH ST	Tamarind	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Limb Damage - Minor
SW 25TH ST	Weeping Fig	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 25TH ST	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)				
SW 25TH ST	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)				
SW 25TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Woman's Tongue	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood



At SW 37th Avenue - West end



Looking East near SW 36th Avenue



Looking East from SW 32nd Avenue



Looking West near SW 31st Avenue



Looking East near SW 34th Avenue



Looking East at SW 32nd Avenue



Looking West near SW 29th Avenue



Looking East towards SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 25th Terrace	4	Douglas Park	2	50	5,350	No	At SW 32nd Ave North Side	No	2	City	Few	Few	9	at SW 37th Ave. & SW 32nd Ave	Yes	North	Numerous paved swales

SW 25th Terrace

TYPOLOGY C & A

Street Tree Inventory

SW 25th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH TER	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Black Olive	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 25TH TER	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Limb Damage - Moderate
SW 25TH TER	Black Olive	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Girdling Roots	Reduced Canopy - Major	Dead Wood
SW 25TH TER	Black Olive	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Sprouting
SW 25TH TER	Black Olive	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 25TH TER	Black Olive	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 25TH TER	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 25TH TER	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 25TH TER	Bottlebrush	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Brazilian Pepper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	No	5'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Trunk Damage - Minor	
SW 25TH TER	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Leader - Bent		
SW 25TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Over Pruned		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 25TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Desert Cassia	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 25TH TER	Gumbo Limbo	1-5"	No	Negligible	Dead (0% to 5%)				
SW 25TH TER	Gumbo Limbo	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 25TH TER	Live Oak	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	
SW 25TH TER	Live Oak	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	Dead Wood
SW 25TH TER	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH TER	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 25TH TER	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Major
SW 25TH TER	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Dead Wood
SW 25TH TER	Mahogany	31-40"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 25TH TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Norfolk Pine	16-20"	No	20'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Codominant Leaders/Included Bark	
SW 25TH TER	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)				
SW 25TH TER	Pitch Apple	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH TER	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 25th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Spindle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)				
SW 25TH TER	Vera Wood	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 25TH TER	Vera Wood	1-5"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor	Dead Wood	
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 25TH TER	Vera Wood	1-5"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)				
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)				
SW 25TH TER	Vera Wood	1-5"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Vera Wood	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Vera Wood	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Vera Wood	1-5"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Vera Wood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	
SW 25TH TER	Vera Wood	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Crown Density - Low	Dead Wood
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Crown Density - Moderate		
SW 25TH TER	Vera Wood	1-5"	No	20'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor	Restricted Canopy	
SW 25TH TER	Vera Wood	1-5"	No	20'	Good (61% to 80%)	Utility Lines Above	Crown Density - Moderate		
SW 25TH TER	Vera Wood	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots		
SW 25TH TER	Vera Wood	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Topped	Sprouting
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	
SW 25TH TER	Vera Wood	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Vera Wood	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)		Dead Wood		
SW 25TH TER	Vera Wood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Vera Wood	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Vera Wood	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Vera Wood	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots		
SW 25TH TER	Vera Wood	6-10"	No	30'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Vera Wood	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Vera Wood	1-5"	No	15'	Fair (41% to 60%)		Leader - Broken	Sprouting	
SW 25TH TER	Vera Wood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Crown Density - Moderate	Dead Wood	
SW 25TH TER	Vera Wood	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Leaning - Major	Crown Density - Moderate	
SW 25TH TER	Vera Wood	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)				
SW 25TH TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Weeping Fig	11-15"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	
SW 25TH TER	Weeping Fig	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 25TH TER	Weeping Fig	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 25TH TER	Willow Bustic	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Yellow Poinciana	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH TER	Yellow Poinciana	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting

Streets | Terraces | Lanes



At SW 37th Avenue - West end



Looking East near SW 34th Avenue



Looking West towards SW 32nd Avenue



Looking West near SW 31st Avenue



Looking East near SW 36th Avenue



Looking East at SW 32nd Avenue



Looking West near SW 29th Avenue



Looking East towards SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 26th Street	4	Douglas Park	2	50	5,350	No	At SW 32nd Ave North Side	No	2	City	Few	Few	10	at SW 37th Ave. & SW 32nd Ave	Yes	North	Numerous paved swales

SW 26th Street

TYPOLOGY C & A

Street Tree Inventory

SW 26th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 26TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Areca Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Areca Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Areca Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 26TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 26TH ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 26TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 26TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 26TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 26TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 26TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 26TH ST	Bottle Palm	6-10"	No	5'	Poor (21% to 40%)		Nutrient Deficiency		
SW 26TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 26TH ST	Bottle Palm	6-10"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 26TH ST	Bottle Palm	11-15"	No	5'	Good (61% to 80%)				
SW 26TH ST	Bottle Palm	6-10"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH ST	Brazilian Beauty Leaf	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 26TH ST	Cabbage Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 26TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Christmas Palm	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 26TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major	One Missing Trunk	
SW 26TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)				
SW 26TH ST	Crepe Myrtle	1-5"	Yes	5'	Fair (41% to 60%)		Crown Density - Low		
SW 26TH ST	Crepe Myrtle	1-5"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Crepe Myrtle	6-10"	Yes	5'	Poor (21% to 40%)		Over Pruned	Crown Density - Low	
SW 26TH ST	Crepe Myrtle	6-10"	Yes	5'	Poor (21% to 40%)		Over Pruned	Crown Density - Low	
SW 26TH ST	Crepe Myrtle	6-10"	Yes	5'	Fair (41% to 60%)		Over Pruned	Crown Density - Moderate	
SW 26TH ST	Crepe Myrtle	6-10"	Yes	5'	Fair (41% to 60%)		Over Pruned	Crown Density - Moderate	
SW 26TH ST	Crepe Myrtle	6-10"	Yes	5'	Poor (21% to 40%)		Over Pruned	Crown Density - Very Low	
SW 26TH ST	Crepe Myrtle	6-10"	Yes	5'	Poor (21% to 40%)		Over Pruned	Crown Density - Very Low	
SW 26TH ST	Crepe Myrtle	6-10"	Yes	5'	Poor (21% to 40%)		Over Pruned	Crown Density - Very Low	
SW 26TH ST	Crepe Myrtle	1-5"	Yes	5'	Poor (21% to 40%)		Over Pruned	Crown Density - Low	
SW 26TH ST	Firebush	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Fishtail Palm	51-60"	Yes	15'	Fair (41% to 60%)		Apical Dieback		

(Continued on Next Page)

Street Tree Inventory

SW 26th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 26TH ST	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)				
SW 26TH ST	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)				
SW 26TH ST	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Glaucous Cassia	1-5"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Apical Dieback	
SW 26TH ST	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 26TH ST	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 26TH ST	Hong Kong Orchid	11-15"	No	25'	Poor (21% to 40%)		Topped	Trunk Damage - Major	Sprouting
SW 26TH ST	Hong Kong Orchid	16-20"	No	20'	Very Poor/Critical (6% to 20%)		Topped	Trunk Damage - Major	Decay Observed
SW 26TH ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Major	Reduced Canopy - Moderate	Sprouting
SW 26TH ST	Live Oak	41-50"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 26TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 26TH ST	Mahogany	16-20"	No	30'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Stubs with Sprouts	
SW 26TH ST	Mahogany	41-50"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 26TH ST	Mahogany	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots		
SW 26TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 26TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 26TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 26TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 26TH ST	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 26TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 26TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 26TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 26TH ST	Mahogany	6-10"	No	15'	Poor (21% to 40%)		Girdling Roots	Topped	Sprouting
SW 26TH ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Trunk Damage - Minor	Lopsided/Significantly Reduced Canopy	Sprouting
SW 26TH ST	Mahogany	6-10"	No	30'	Good (61% to 80%)		Trunk Damage - Moderate	Reduced Canopy - Minor	Sprouting
SW 26TH ST	Orange Geiger	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Leaning - Minor		
SW 26TH ST	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Leaning - Minor	
SW 26TH ST	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Moderate		
SW 26TH ST	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Moderate		
SW 26TH ST	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Crown Density - Moderate	Insect Damage Leaves	Dead Wood
SW 26TH ST	Orange Geiger	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Insect Damage Leaves	Leaning - Moderate
SW 26TH ST	Paradise Tree	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 26TH ST	Peregrina	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor	Dead Wood	
SW 26TH ST	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Moderate		
SW 26TH ST	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor		
SW 26TH ST	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Low	Dead Wood	Trunk Damage - Moderate
SW 26TH ST	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor		
SW 26TH ST	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Insect Damage Leaves		
SW 26TH ST	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Insect Damage Leaves	Trunk Damage - Minor	
SW 26TH ST	Pigeon Plum	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Leaning - Major		
SW 26TH ST	Pigeon Plum	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leaning - Major	Restricted Canopy	Suppressed Canopy
SW 26TH ST	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Sprouting	
SW 26TH ST	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Topped	Sprouting	Trunk Damage - Moderate
SW 26TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 26TH ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 26TH ST	Rubber Tree	11-15"	No	10'	Poor (21% to 40%)	Utility Lines Above	Topped	Dead Wood	Sprouting
SW 26TH ST	Rubber Tree	11-15"	No	10'	Poor (21% to 40%)	Utility Lines Above	Topped	Dead Wood	Sprouting
SW 26TH ST	Sapodilla	16-20"	No	25'	Poor (21% to 40%)		Topped	Sprouting	
SW 26TH ST	Simpson's Stopper	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Crown Density - Very Low	Decay Observed	
SW 26TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 26th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 26TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)				
SW 26TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 26TH ST	Strangler Fig	1-5"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Suppressed Canopy
SW 26TH ST	Umbrella Tree	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 26TH ST	Umbrella Tree	6-10"	Yes	5'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Dead Wood
SW 26TH ST	Umbrella Tree	21-30"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 26TH ST	Umbrella Tree	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Girdling Roots	Trunk Damage - Moderate	Topped
SW 26TH ST	Vera Wood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Vera Wood	1-5"	No	5'	Poor (21% to 40%)		Strap Constricting Tree	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major
SW 26TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Vera Wood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Vera Wood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 26TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 26TH ST	Vera Wood	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 26TH ST	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor	Reduced Canopy - Moderate	Sprouting
SW 26TH ST	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 26TH ST	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)		Reduced Canopy - Moderate	Crown Density - Excessive (Due to Epicormic Growth)	
SW 26TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH ST	Weeping Fig	6-10"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Codominant Leaders/Included Bark	
SW 26TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 26TH ST	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			

Streets | Terraces | Lanes



Looking west at SW 37th Avenue - West end



Looking East near SW 34th Avenue



Looking East mid block



Looking East at SW 36th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 26th Terrace	4	Douglas Park	2	50	750	No	At SW 37th. South Side	No	2	City	Few	Few	9	at SW 37th Ave.	Yes	South	Numerous paved swales

SW 26th Terrace

TYPOLOGY C & A

Street Tree Inventory

SW 26th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 26TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 26TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 26TH TER	Crepe Myrtle	6-10"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Dead Wood	
SW 26TH TER	Golden Rain Tree	6-10"	No	25'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Moderate	Decay Observed
SW 26TH TER	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Insect Damage Leaves		
SW 26TH TER	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Topped	Stubs with Sprouts	
SW 26TH TER	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Topped	Stubs with Sprouts	
SW 26TH TER	Java Bishopwood	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 26TH TER	Mahogany	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 26TH TER	Mahogany	11-15"	No	35'	Good (61% to 80%)		Reduced Canopy - Minor	Codominant Leaders/Included Bark	
SW 26TH TER	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 26TH TER	Mahogany	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Codominant Leaders - Multi	Leaning - Minor
SW 26TH TER	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Minor	
SW 26TH TER	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 26TH TER	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 26TH TER	Pink Cassia	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 26TH TER	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 26TH TER	Sapodilla	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Moderate

Streets | Terraces | Lanes



At SW 37th Avenue - West end



Looking East near at No Outlet near Park



Looking West towards SW 32nd Avenue



Looking East near SW 31st Avenue



Looking East near SW 33rd Court



Looking East at SW 32nd Avenue



Looking West near SW 29th Avenue



Looking East towards SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 27th Street - west	4	Douglas Park	2	50	660	No	At SW 37th. South Side	No	2	City	Few	Few	9	at SW 37th Ave.	Yes	North	Numerous paved swales. Valley gutters both sides. Dead end
SW 27th Street - east	4	Douglas Park	2	60	4,500	No	At SW 32nd Ave North Side	No	2	City	Few	Few	15	at SW 37th Ave. & SW 32nd Ave	Yes	North	Numerous paved swales

SW 27th Street - West of SW 32nd Avenue

TYPOLOGY C & A

SW 27th Street - East of SW 32nd Avenue

TYPOLOGY C & A

Street Tree Inventory

SW 27th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH ST	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 27TH ST	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 27TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Sprouting
SW 27TH ST	Black Olive	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 27TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 27TH ST	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Damaged Fronds	
SW 27TH ST	Bottlebrush	16-20"	No	30'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	Dead Wood
SW 27TH ST	Bottlebrush	16-20"	No	25'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 27TH ST	Bottlebrush	21-30"	No	30'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 27TH ST	Bottlebrush	16-20"	No	25'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 27TH ST	Bougainvillea sp.	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Brazilian Pepper	1-5"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Topped	Restricted Canopy	Sprouting
SW 27TH ST	Brazilian Pepper	6-10"	No	5'	Poor (21% to 40%)	Utility Lines Above	Topped	Sprouting	
SW 27TH ST	BV UNID 1	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Dead Wood
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Cabbage Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Canary Island Date Palm	16-20"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 27TH ST	Canary Island Date Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 27TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 27TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Major	Nutrient Deficiency	
SW 27TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	Suppressed Canopy
SW 27TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Christmas Palm	21-30"	Yes	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Leader - Bent	
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH ST	Christmas Palm	6-10"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency	Dead Meristem	
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 27th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Coconut Palm	6-10"	No	15'	Very Poor/Critical (6% to 20%)		Leaning - Major	Uprooted - Mostly	Supported by Other Tree
SW 27TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 27TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 27TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 27TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 27TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Dracaena sp.	11-15"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Ficus Growing on Tree		
SW 27TH ST	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Strap Constricting Tree	
SW 27TH ST	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH ST	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH ST	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH ST	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH ST	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH ST	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH ST	Guiana Chestnut	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 27TH ST	Gumbo Limbo	21-30"	No	35'	Fair (41% to 60%)		Basal Co-Dominant		
SW 27TH ST	Hong Kong Orchid	21-30"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 27TH ST	Live Oak	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Live Oak	11-15"	No	25'	Good (61% to 80%)		Restricted Canopy	Dead Wood	Sprouting
SW 27TH ST	Live Oak	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	Sprouting
SW 27TH ST	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 27TH ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 27TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Dead Wood	Strap Constricting Tree
SW 27TH ST	Loquat	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 27TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)				
SW 27TH ST	Mahogany	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 27TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 27TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Insect Damage Leaves	
SW 27TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH ST	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Trunk Damage - Minor	Insect Damage Leaves	
SW 27TH ST	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Insect Damage Leaves	Limb Damage - Minor	Dead Wood
SW 27TH ST	Pink Tabebuia	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Major	Crown Density - Low	Dead Wood
SW 27TH ST	Pink Tabebuia	6-10"	No	20'	Poor (21% to 40%)		Leader - Broken	Sprouting	Insect Damage Leaves
SW 27TH ST	Pink Tabebuia	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Insect Damage Leaves
SW 27TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 27TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH ST	Queen Palm	6-10"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 27TH ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	Dead Wood
SW 27TH ST	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Dead Wood	Sprouting
SW 27TH ST	Royal Poinciana	11-15"	No	25'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate	Dead Wood	Sprouting
SW 27TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 27TH ST	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 27TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 27TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 27TH ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 27th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH ST	Royal Poinciana	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Major	Leader - Broken
SW 27TH ST	Royal Poinciana	16-20"	No	55'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	Dead Wood
SW 27TH ST	Royal Poinciana	21-30"	No	60'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	Dead Wood
SW 27TH ST	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 27TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 27TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 27TH ST	Royal Poinciana	16-20"	No	50'	Good (61% to 80%)	Utility Line Conflict	Sprouting	Dead Wood	
SW 27TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	Dead Wood
SW 27TH ST	Silver Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 27TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Simpson's Stopper	1-5"	No	5'	Dead (0% to 5%)	Utility Lines Above			
SW 27TH ST	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Simpson's Stopper	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Loose Trunk		
SW 27TH ST	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 27TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 27TH ST	Strangler Fig	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	
SW 27TH ST	Strangler Fig	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Triangle Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 27TH ST	Weeping Fig	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant		
SW 27TH ST	Weeping Fig	31-40"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 27TH ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Stubs with Sprouts	
SW 27TH ST	Weeping Fig	16-20"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots		
SW 27TH ST	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)		Leader - Broken	Lopsided/Significantly Reduced Canopy	Sprouting
SW 27TH ST	Weeping Fig	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub	Multi-Trunk Form - Not Downgraded for Structure	Dead Wood
SW 27TH ST	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Pruned Into Shrub	Crown Density - Low	Dead Wood
SW 27TH ST	Weeping Fig	6-10"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Pruned Into Shrub	Crown Density - Very Low	Dead Wood
SW 27TH ST	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub	Crown Density - Moderate	Dead Wood
SW 27TH ST	Weeping Fig	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub	Multi-Trunk Form - Not Downgraded for Structure	Crown Density - Moderate
SW 27TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 27TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	White Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 27TH ST	White Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 27TH ST	White Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		



Looking East from SW 38th Avenue- West end



Looking East at SW 37th Avenue



Looking West near SW 29th Avenue



Looking West near SW 30th Avenue



Looking West near SW 30th Avenue



Looking East near SW 30th Avenue



Looking West near SW 27th Avenue



Looking East towards SW 27th Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 27th Terrace	4	Douglas Park	2	50	3,675	No	No	No	2	City	Few	Few	10	at SW 37th Ave.	Yes	North	east bound ends at SW 29th Ave. and solitary segment between SW 29thAve. & SW 27th Ave. IS Typology E with no swale

SW 27th Terrace

TYPOLOGY C

Street Tree Inventory

SW 27th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH TER	Bamboo Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH TER	Bamboo Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH TER	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH TER	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 27TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 27TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 27TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 27TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 27TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 27TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 27TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 27TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 27TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 27TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 27TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 27TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 27TH TER	Coconut Palm	16-20"	Yes	35'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH TER	Day Blooming Jasmine	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 27TH TER	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH TER	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH TER	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH TER	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH TER	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 27TH TER	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH TER	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH TER	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 27TH TER	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH TER	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH TER	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH TER	Foxtail Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH TER	Glaucous Cassia	1-5"	No	20'	Poor (21% to 40%)	Utility Lines Above	Leaning - Moderate	Disease	Suppressed Canopy
SW 27TH TER	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 27TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 27TH TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 27TH TER	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark
SW 27TH TER	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 27TH TER	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 27TH TER	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 27TH TER	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 27TH TER	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Crown Density - Moderate	Dead Wood	
SW 27TH TER	Lancewood	1-5"	No	5'	Good (61% to 80%)				
SW 27TH TER	Lancewood	1-5"	No	5'	Good (61% to 80%)				
SW 27TH TER	Lead Tree	1-5"	No	5'	Good (61% to 80%)				
SW 27TH TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 27TH TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 27TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)		Dead Wood		
SW 27TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)		Dead Wood		
SW 27TH TER	Mahogany	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark
SW 27TH TER	Mahogany	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 27TH TER	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 27TH TER	Mahogany	31-40"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Limb Damage - Major
SW 27TH TER	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 27TH TER	Mahogany	11-15"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Leaning - Moderate	Root Damage/Decay	Reduced Canopy - Moderate

(Continued on Next Page)

Street Tree Inventory

SW 27th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH TER	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Limb Damage - Moderate	Reduced Canopy - Moderate	Stubs with Sprouts
SW 27TH TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH TER	Pigeon Plum	6-10"	No	15'	Poor (21% to 40%)		Uprooted - Partially	Basal Co-Dominant	Strap Constricting Tree
SW 27TH TER	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)				
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Simpson's Stopper	1-5"	No	5'	Dead (0% to 5%)	Utility Lines Above			
SW 27TH ST	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Simpson's Stopper	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Loose Trunk		
SW 27TH ST	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 27TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 27TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 27TH ST	Strangler Fig	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	
SW 27TH ST	Strangler Fig	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Triangle Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 27TH ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 27TH ST	Weeping Fig	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant		
SW 27TH ST	Weeping Fig	31-40"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 27TH ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Stubs with Sprouts	
SW 27TH ST	Weeping Fig	16-20"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots		
SW 27TH ST	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)		Leader - Broken	Lopsided/Significantly Reduced Canopy	Sprouting
SW 27TH ST	Weeping Fig	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub	Multi-Trunk Form - Not Downgraded for Structure	Dead Wood
SW 27TH ST	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Pruned Into Shrub	Crown Density - Low	Dead Wood
SW 27TH ST	Weeping Fig	6-10"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Pruned Into Shrub	Crown Density - Very Low	Dead Wood
SW 27TH ST	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub	Crown Density - Moderate	Dead Wood
SW 27TH ST	Weeping Fig	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub	Multi-Trunk Form - Not Downgraded for Structure	Crown Density - Moderate
SW 27TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 27TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH ST	White Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 27TH ST	White Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 27TH ST	White Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		

Streets | Terraces | Lanes



Looking East towards SW 30th Avenue



Looking West towards SW 37th Avenue



Looking East towards SW 31st Avenue



Looking East towards SW 37th Avenue



Looking West towards SW 38th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 27th Lane	4	Douglas Park	2	50	1,800	No	No	No	2	City	Few	Some	8	No	Yes	South	Only exists between SW 31st Ct & SW 31st Ave
SW 27th Way	4	Douglas Park	2	50	200	No	No	No	2	City	Some	No	10	No	Yes	South	Only exists between SW 31st Ct & SW 31st Ave

SW 27th Lane

TYPOLOGY C & A

SW 27th Way

TYPOLOGY C

Street Tree Inventory

SW 27th Lane

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH LN	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 27TH LN	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Damaged Fronds	
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	21-30"		20'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Leaning - Moderate	Trunk Damage - Minor
SW 27TH LN	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 27TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 27TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 27TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 27TH LN	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	Codominant Leaders/No Included Bark
SW 27TH LN	Live Oak	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 27TH LN	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 27TH LN	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH LN	Orange Geiger	1-5"	No	5'	Fair (41% to 60%)		Strap Constricting Tree	Nutrient Deficiency	
SW 27TH LN	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH LN	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 27TH LN	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	Codominant Leaders/Included Bark
SW 27TH LN	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	Codominant Leaders/Included Bark
SW 27TH LN	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 27TH LN	Pink Tabebuia	11-15"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 27TH LN	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 27TH LN	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 27TH LN	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 27TH LN	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 27TH LN	Spindle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH LN	Yellow Tabebuia	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 27TH LN	Yellow Tabebuia	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		

SW 27th Way

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH WAY	Black Olive	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 27TH WAY	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 27TH WAY	Black Olive	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 27TH WAY	Black Olive	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 27TH WAY	Brazilian Beauty Leaf	1-5"	No	Negligible	Dead (0% to 5%)				
SW 27TH WAY	Brazilian Beauty Leaf	1-5"	No	Negligible	Dead (0% to 5%)				
SW 27TH WAY	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 27TH WAY	Dracaena sp.	16-20"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH WAY	Dracaena sp.	11-15"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH WAY	Dracaena sp.	11-15"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH WAY	Dracaena sp.	16-20"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH WAY	Dracaena sp.	6-10"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH WAY	Dracaena sp.	16-20"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		

(Continued on Next Page)

Street Tree Inventory

SW 27th Way (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH WAY	Dracaena sp.	11-15"	Yes	5'	Good (61% to 80%)				
SW 27TH WAY	Dracaena sp.	1-5"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 27TH WAY	Oriental Arborvitae	21-30"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 27TH WAY	Pigeon Plum	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	
SW 27TH WAY	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	
SW 27TH WAY	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	
SW 27TH WAY	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	
SW 27TH WAY	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH WAY	Weeping Fig	1-5"	Yes	5'	Good (61% to 80%)				
SW 27TH WAY	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 27TH WAY	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 27TH WAY	White Frangipani	1-5"	No	5'	Good (61% to 80%)				

Streets | Terraces | Lanes



Looking East towards SW 38th Avenue - West end



Looking East at SW 37th Avenue



Looking West near SW 33rd Court



Looking West near SW 32nd Avenue



Looking West near SW 34th Court



Looking West near SW 34th Avenue



Looking East at SW 32nd Avenue



Looking West towards SW 31st Avenue - East end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 28th Street - west	4	Douglas Park	2	50	2,650	No	No	No	2	City	Few	Some	8	No	Yes	North	Roundabout at SW 32nd Ct
SW 28th Street - east	4	Douglas Park	2	50	400	No	No	No	2	City	Few	Some	0	No	Yes	No	Industrial Area

SW 28th Street - West of SW 32nd Avenue

TYPOLOGY A & C

SW 28th Street - East of SW 32nd Avenue

TYPOLOGY C & A

Street Tree Inventory

SW 28th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 28TH ST	Bismark Palm	21-30"	No	20'	Good (61% to 80%)				
SW 28TH ST	Bismark Palm	6-10"	No	5'	Good (61% to 80%)				
SW 28TH ST	Bismark Palm	6-10"	No	5'	Good (61% to 80%)				
SW 28TH ST	Black Olive	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	Constricted Roots
SW 28TH ST	Canary Island Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 28TH ST	Canary Island Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 28TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 28TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 28TH ST	Dahoon Holly	1-5"	No	10'	Good (61% to 80%)				
SW 28TH ST	Green Buttonwood	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Topped	Sprouting	Lopsided/Moderately Reduced Canopy
SW 28TH ST	Green Buttonwood	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy		
SW 28TH ST	Green Buttonwood	11-15"	Yes	5'	Poor (21% to 40%)		Basal Co-Dominant	Topped	Sprouting
SW 28TH ST	Green Buttonwood	11-15"	Yes	10'	Poor (21% to 40%)		Basal Co-Dominant	Topped	Sprouting
SW 28TH ST	Green Buttonwood	31-40"	Yes	40'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Reduced Canopy - Moderate	Sprouting
SW 28TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Over Pruned	Stubs
SW 28TH ST	Gumbo Limbo	6-10"	No	15'	Good (61% to 80%)				
SW 28TH ST	Gumbo Limbo	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Stubs	
SW 28TH ST	Gumbo Limbo	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 28TH ST	Japanese Privet	11-15"	Yes	10'	Good (61% to 80%)				
SW 28TH ST	Mahogany	31-40"	No	45'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 28TH ST	Mahogany	31-40"	No	45'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 28TH ST	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)				
SW 28TH ST	Paradise Tree	1-5"	No	15'	Good (61% to 80%)				
SW 28TH ST	Paradise Tree	1-5"	No	15'	Good (61% to 80%)				
SW 28TH ST	Pigeon Plum	6-10"	No	15'	Fair (41% to 60%)		Basal Co-Dominant		
SW 28TH ST	Pigeon Plum	6-10"	No	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 28TH ST	Pigeon Plum	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Sprouting
SW 28TH ST	Pigeon Plum	11-15"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Sprouting
SW 28TH ST	Pigeon Plum	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Sprouting
SW 28TH ST	Pongam	16-20"	No	35'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 28TH ST	Pongam	11-15"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Sprouting
SW 28TH ST	Pongam	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Sprouting
SW 28TH ST	Pongam	11-15"	No	5'	Dead (0% to 5%)				
SW 28TH ST	Pongam	11-15"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Sprouting
SW 28TH ST	Pygmy Date Palm	11-15"	Yes	5'	Good (61% to 80%)				
SW 28TH ST	Pygmy Date Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 28TH ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 28TH ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 28TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 28TH ST	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 28TH ST	Royal Poinciana	6-10"	No	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	
SW 28TH ST	Royal Poinciana	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 28TH ST	Weeping Fig	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Dead Wood	Decay Observed
SW 28TH ST	Yellow Poinciana	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 28TH ST	Yellow Poinciana	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Sprouting

Streets | Terraces | Lanes



Looking East from SW 31st Ave -West end


Looking West near SW 30th Avenue


At SW 34th Avenue - West end


Looking East


Looking West near SW 29th Avenue


Looking East at SW 27th Avenue- at Metrorail Station


Looking East at SW 33rd Ct - West end

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 28th Lane - west	4	Douglas Park	2	60	1200	No	No	Yes	2	City	Some	Few	14	No	Yes	South	Three Blocks long - Commercial one side. 14' swale only between SW 30th Ave & SW 29th Ave. rest of street has none
SW 28th Lane - east	4	Douglas Park	2	50	800	No	No	No	2	City	On South	No	8	Yes	North	No	One Way - Bus drop Off for Coconut Grove Metro-rail Station - swale on north side only
SW 28th Terrace	4	Douglas Park	2	50	700	No	No	No	2	City	Some	Some	20	No	No	North	Two Blocks long - 14' road width

SW 28th Lane - West & East

TYPOLOGY B & C

SW 28th Terrace

TYPOLOGY X

Street Tree Inventory

SW 28th Lane

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 28TH LN	Lignum Vitae	1-5"	No	5'	Good (61% to 80%)				
SW 28TH LN	Mahogany	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Trunk Damage - Minor	Dead Wood
SW 28TH LN	Mahogany	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Moderate	Reduced Canopy - Major	Lifting
SW 28TH LN	Mahogany	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Sprouting	
SW 28TH LN	Mahogany	11-15"	No	30'	Good (61% to 80%)		Trunk Damage - Moderate	Reduced Canopy - Minor	Sprouting
SW 28TH LN	Mahogany	11-15"	No	35'	Good (61% to 80%)		Trunk Damage - Minor	Lopsided/Moderately Reduced Canopy	Sprouting
SW 28TH LN	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH LN	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH LN	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Moderate	
SW 28TH LN	Queen Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Frizzled Fronds	
SW 28TH LN	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH LN	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 28TH LN	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Frizzled Fronds	
SW 28TH LN	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 28TH LN	Royal Palm	16-20"	No	Negligible	Dead (0% to 5%)				
SW 28TH LN	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 28TH LN	Royal Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Tapered Trunk	
SW 28TH LN	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 28TH LN	Royal Palm	11-15"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Frizzled Fronds	Leader - Bent
SW 28TH LN	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 28TH LN	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub	Suppressed Canopy	
SW 28TH LN	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub	Suppressed Canopy	

SW 28th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 28TH TER	Canary Island Date Palm	21-30"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 28TH TER	Canary Island Date Palm	21-30"	No	25'	Good (61% to 80%)				
SW 28TH TER	Christmas Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 28TH TER	Christmas Palm	41-50"	Yes	25'	Good (61% to 80%)	Utility Line Conflict	Cluster		
SW 28TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 28TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH TER	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 28TH TER	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Apical Dieback	Codominant Leaders/No Included Bark
SW 28TH TER	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Restricted Canopy	Apical Dieback	Codominant Leaders/No Included Bark
SW 28TH TER	Gumbo Limbo	16-20"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 28TH TER	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 28TH TER	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	Dead Wood
SW 28TH TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 28TH TER	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 28TH TER	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 28TH TER	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 28TH TER	Gumbo Limbo	11-15"	No	20'	Poor (21% to 40%)		Restricted Canopy	Reduced Canopy - Major	Sprouting
SW 28TH TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 28TH TER	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 28TH TER	Gumbo Limbo	11-15"	No	25'	Poor (21% to 40%)		Girdling Roots	Restricted Canopy	Codominant Leaders/No Included Bark
SW 28TH TER	Gumbo Limbo	16-20"	No	25'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 28TH TER	Live Oak	21-30"	No	45'	Poor (21% to 40%)		Girdling Roots	Topped	Sprouting
SW 28TH TER	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 28TH TER	Orange Geiger	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 28TH TER	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 28TH TER	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 28TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 28TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 28TH TER	Strangler Fig	60+"	No	60'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Decay Observed
SW 28TH TER	Strangler Fig	41-50"	No	40'	Fair (41% to 60%)		Constricted Roots	Nutrient Deficiency	Dead Wood
SW 28TH TER	Tropical Almond	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	

Streets | Terraces | Lanes



Looking East from SW 39th Avenue - West end



Looking East at SW 37th Avenue



Looking East near SW 36th Avenue



Looking East at SW 32nd Avenue



Looking East to SW 37th Avenue



Looking East near SW 36th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 29th Street	4	Douglas Park	2	50	4000	No	No	No	2	City	Some	Few	9	No	Yes	North	

SW 29th Street

TYPOLOGY A & X

Street Tree Inventory

SW 29th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH ST	Australian Pine	11-15"	No	20'	Fair (41% to 60%)		Basal Co-Dominant with Adjacent Tree(s)	Leaning - Moderate	
SW 29TH ST	Betel Nut Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Betel Nut Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Betel Nut Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Black Olive	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 29TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 29TH ST	Black Olive	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 29TH ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 29TH ST	Black Olive	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 29TH ST	Black Olive	16-20"	No	60'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 29TH ST	Black Olive	16-20"	No	55'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 29TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 29TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 29TH ST	Black Sapote	21-30"	Yes	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 29TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH ST	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	BV UNID 4	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 29TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 29TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 29TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 29TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 29TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 29TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 29TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 29TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 29TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 29TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 29TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 29TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 29TH ST	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 29TH ST	Eggfruit	16-20"	No	30'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 29TH ST	Eggfruit	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 29TH ST	Florida Thatch Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Gumbo Limbo	21-30"	Yes	25'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Trunk Damage - Moderate	Sprouting
SW 29TH ST	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 29TH ST	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark		
SW 29TH ST	Gumbo Limbo	21-30"	Yes	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Lopsided/Moderately Reduced Canopy
SW 29TH ST	Gumbo Limbo	1-5"	Yes	10'	Poor (21% to 40%)		Restricted Canopy	Lateral Branching - None	Lopsided/Significantly Reduced Canopy
SW 29TH ST	Gumbo Limbo	11-15"	Yes	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 29TH ST	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 29TH ST	Hong Kong Orchid	21-30"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 29TH ST	Hong Kong Orchid	31-40"	No	30'	Poor (21% to 40%)		Basal Co-Dominant	Restricted Canopy	Trunk Damage - Major
SW 29TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 29TH ST	Mahogany	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Major	Growing on Rock
SW 29TH ST	Mahogany	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 29TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 29TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 29TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH ST	Mahogany	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 29TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 29TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Codominant Leaders/Included Bark	
SW 29TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Basal Co-Dominant with Adjacent Tree(s)	Lopsided/Moderately Reduced Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 29th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Basal Co-Dominant with Adjacent Tree(s)	Lopsided/Moderately Reduced Canopy	
SW 29TH ST	Mahogany	21-30"	No	15'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 29TH ST	Moringa	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 29TH ST	Moringa	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 29TH ST	Norfolk Pine	16-20"	Yes	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant		
SW 29TH ST	Oriental Arborvitae	16-20"	No	30'	Good (61% to 80%)				
SW 29TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 29TH ST	Pygmy Date Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Over Pruned		
SW 29TH ST	Pygmy Date Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Over Pruned		
SW 29TH ST	Pygmy Date Palm	6-10"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Over Pruned		
SW 29TH ST	Pygmy Date Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Over Pruned		
SW 29TH ST	Pygmy Date Palm	1-5"	No	10'	Good (61% to 80%)				
SW 29TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 29TH ST	Royal Poinciana	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 29TH ST	Royal Poinciana	31-40"	No	65'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sloughing Bark
SW 29TH ST	Royal Poinciana	16-20"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate	Decay Observed
SW 29TH ST	Sapodilla	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 29TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 29TH ST	Strangler Fig	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Growing on Rock	
SW 29TH ST	Strangler Fig	31-40"	No	40'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 29TH ST	Umbrella Tree	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	
SW 29TH ST	Umbrella Tree	16-20"	Yes	15'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Sprouting
SW 29TH ST	Weeping Fig	11-15"	No	20'	Poor (21% to 40%)		Restricted Canopy	Lopsided/Significantly Reduced Canopy	
SW 29TH ST	Weeping Fig	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 29TH ST	Weeping Fig	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Restricted Canopy	
SW 29TH ST	Weeping Fig	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Minor	Codominant Leaders/Included Bark	
SW 29TH ST	Weeping Fig	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 29TH ST	Weeping Fig	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 29TH ST	Weeping Fig	21-30"	No	35'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Dead Wood	
SW 29TH ST	Weeping Fig	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 29TH ST	Yellow Poinciana	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 29TH ST	Yellow Poinciana	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 29TH ST	Yellow Poinciana	11-15"	No	35'	Poor (21% to 40%)		Girdling Roots	Topped	Sprouting
SW 29TH ST	Yellow Tabebuia	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	

Streets | Terraces | Lanes



Looking West near SW 39th Avenue - West end



Looking East near SW 38th Court



Looking East near SW 39th Avenue



Looking East near SW 38th Court



Looking West near SW 38th Avenue



Looking East at SW 38th Avenue



Looking East at SW 38th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
Shipping Avenue	4	Douglas Park	2	50	600	No	No	No	2	City	No	No	10	No	No	North	Commercial District
Orange Street	4	Douglas Park	2	50	600	No	Some North	No	2	City	No	Some	6	Some	Some	North	Commercial District- swales in some areas

Shipping Avenue

TYPOLOGY C & X

Orange Street

TYPOLOGY X

Street Tree Inventory


Shipping Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SHIPPING AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SHIPPING AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SHIPPING AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SHIPPING AVE	Strangler Fig	21-30"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Sprouting

Orange Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
ORANGE ST	Black Olive	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	
ORANGE ST	Black Olive	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	
ORANGE ST	Black Olive	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	
ORANGE ST	Black Olive	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy	Codominant Leaders/Included Bark	
ORANGE ST	Black Olive	6-10"	No	15'	Poor (21% to 40%)		Restricted Canopy	Trunk Damage - Major	Codominant Leaders/Included Bark
ORANGE ST	Montgomery Palm	16-20"	Yes	15'	Good (61% to 80%)				
ORANGE ST	Montgomery Palm	16-20"	Yes	15'	Good (61% to 80%)				
ORANGE ST	Montgomery Palm	16-20"	Yes	15'	Good (61% to 80%)				
ORANGE ST	Montgomery Palm	16-20"	Yes	15'	Good (61% to 80%)				
ORANGE ST	Montgomery Palm	16-20"	Yes	15'	Good (61% to 80%)				
ORANGE ST	Montgomery Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
ORANGE ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
ORANGE ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
ORANGE ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
ORANGE ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
ORANGE ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
ORANGE ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
ORANGE ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
ORANGE ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				

Streets | Terraces | Lanes




Looking West from SW 37th Avenue



Looking West mid-block



Looking East at US 1



Looking West near SW 36th Court



Looking East from SW 38th Avenue



LookingWest near Douglas Road



Looking East from SW 39th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
Peacock Ave	4	Douglas Park	2	50	600	No	North	No	2	City	on North in grates	No	0	Yes	Yes	North	Commercial District. Some trees in grates
SW 40th Street - Bird Road	4	Douglas Park	2	70	2100	No	No	No	4	State	Some	Some	0	Yes	Yes	No	Center Turn Lane - Signalized

Peacock Avenue

TYPOLOGY X

SW 40th Street - Bird Road

TYPOLOGY E

Street Tree Inventory

Peacock Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
PEACOCK AVE	Brazilian Beauty Leaf	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Apical Dieback	
PEACOCK AVE	Brazilian Beauty Leaf	6-10"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
PEACOCK AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			

*Note there are no trees on SW 40th Street - Bird Road

Bordering Streets



Looking East at SW 37th Avenue - Douglas Road



Looking East near SW 32nd Avenue



Looking north at Coral Way




Looking North near SW 24th Street




Looking East near SW 29th Avenue



Looking West at SW 27th Avenue



Looking North near SW 28th Street



Looking South near SW 40th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 22nd Street - Coral Way	4	Douglas Park	2	100	5250	Yes	No	No	4	State	Median	Few	6	Yes	Yes	No	Historic Road. 12' swale on south side
SW 37th Avenue - Douglas Road	4	Douglas Park	2	70	6200	No	No	No	4	County	No	No	0	Yes	Yes	East	Center Turn Lane - Signalized

SW 22nd Street - Coral Way

TYPOLOGY I

SW 37th Avenue - Douglas Road

TYPOLOGY E

Street Tree Inventory

SW 22nd Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	Dead Wood
SW 22ND ST	Banyan	31-40"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND ST	Banyan	31-40"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Suppressed Canopy	
SW 22ND ST	Banyan	60+"	No	100'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 22ND ST	Banyan	60+"	No	50'	Fair (41% to 60%)		Constricted Roots	Grafted Branches	Dead Wood
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Cavities
SW 22ND ST	Banyan	60+"	No	100'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 22ND ST	Banyan	41-50"	No	55'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Restricted Canopy	
SW 22ND ST	Banyan	41-50"	No	40'	Fair (41% to 60%)		Basal Co-Dominant	Stubs with Sprouts	
SW 22ND ST	Banyan	21-30"	No	40'	Fair (41% to 60%)		Basal Co-Dominant		
SW 22ND ST	Banyan	41-50"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 22ND ST	Banyan	51-60"	No	55'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 22ND ST	Banyan	60+"	No	100'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 22ND ST	Banyan	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 22ND ST	Banyan	31-40"	No	40'	Fair (41% to 60%)		Basal Co-Dominant	Stubs with Sprouts	Trunk Damage - Moderate
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Sprouting	Cavities
SW 22ND ST	Banyan	31-40"	No	30'	Fair (41% to 60%)		Basal Co-Dominant	Trunk Damage - Minor	Decay Observed
SW 22ND ST	Banyan	31-40"	No	35'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	21-30"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Limb Damage - Minor	
SW 22ND ST	Banyan	16-20"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 22ND ST	Banyan	41-50"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Stubs with Sprouts
SW 22ND ST	Banyan	60+"	No	45'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Cavities
SW 22ND ST	Banyan	41-50"	No	30'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Restricted Canopy	Trunk Damage - Moderate
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Stubs	Dead Wood
SW 22ND ST	Banyan	51-60"	No	40'	Fair (41% to 60%)		Basal Co-Dominant	Sprouting	
SW 22ND ST	Banyan	21-30"	No	35'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 22ND ST	Banyan	60+"	No	60'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 22ND ST	Banyan	31-40"	No	35'	Fair (41% to 60%)		Basal Co-Dominant	Sprouting	
SW 22ND ST	Banyan	60+"	No	60'	Fair (41% to 60%)		Constricted Roots	Sprouting	Root Damage/Decay
SW 22ND ST	Banyan	60+"	No	55'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	Cavities
SW 22ND ST	Banyan	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND ST	Banyan	60+"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND ST	Banyan	60+"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 22ND ST	Banyan	60+"	No	105'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 22ND ST	Banyan	51-60"	No	70'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 22ND ST	Banyan	60+"	No	85'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Basal Co-Dominant
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Banyan	41-50"	Yes	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Banyan	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	51-60"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 22ND ST	Banyan	60+"	No	90'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Banyan	60+"	No	75'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Banyan	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 22ND ST	Banyan	60+"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	41-50"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 22ND ST	Banyan	60+"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 22nd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 22ND ST	Banyan	60+"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Basal Co-Dominant
SW 22ND ST	Banyan	60+"	No	100'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	45'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate
SW 22ND ST	Banyan	60+"	No	100'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Black Olive	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 22ND ST	Black Olive	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 22ND ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Trunk Damage - Minor	Sprouting
SW 22ND ST	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Restricted Canopy
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 22ND ST	Black Olive	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 22ND ST	Black Olive	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Sprouting
SW 22ND ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/No Included Bark
SW 22ND ST	Black Olive	6-10"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/No Included Bark
SW 22ND ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/No Included Bark
SW 22ND ST	Black Olive	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Restricted Canopy	
SW 22ND ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Girdling Roots	Trunk Damage - Moderate	Decay Observed
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 22ND ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Sprouting	
SW 22ND ST	Black Olive	6-10"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 22ND ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 22ND ST	Black Olive	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 22ND ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 22ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Major	Decay Observed
SW 22ND ST	Black Olive	1-5"	No	10'	Fair (41% to 60%)		Girdling Roots	Lopsided/Moderately Reduced Canopy	
SW 22ND ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 22ND ST	Black Olive	6-10"	No	20'	Poor (21% to 40%)		Restricted Canopy	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 22ND ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 22ND ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 22ND ST	Black Olive	16-20"	No	20'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Sprouting
SW 22ND ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Codominant Leaders/Included Bark
SW 22ND ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 22ND ST	Black Olive	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Lopsided/Moderately Reduced Canopy
SW 22ND ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Apical Dieback
SW 22ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 22ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 22ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 22ND ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 22ND ST	Black Olive	16-20"	No	30'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 22ND ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Dead Wood
SW 22ND ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Root Damage/Decay	Codominant Leaders/Included Bark
SW 22ND ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Root Damage/Decay	Stubs with Sprouts
SW 22ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Stubs	Dead Wood
SW 22ND ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND ST	Black Olive	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	Sprouting
SW 22ND ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Suppressed Canopy
SW 22ND ST	Black Olive	11-15"	No	15'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Suppressed Canopy	Sprouting
SW 22ND ST	Black Olive	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Codominant Leaders/Included Bark	
SW 22ND ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Suppressed Canopy
SW 22ND ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 22ND ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 22ND ST	Black Olive	16-20"	No	45'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed

(Continued on Next Page)

Street Tree Inventory

SW 22nd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 22ND ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Epicormic Growth	Codominant Leaders/Included Bark	
SW 22ND ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 22ND ST	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 22ND ST	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 22ND ST	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 22ND ST	Brazilian Beauty Leaf	1-5"	No	10'	Fair (41% to 60%)		Desiccated Foliage	Strap Constricting Tree	
SW 22ND ST	Brazilian Beauty Leaf	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 22ND ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 22ND ST	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 22ND ST	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/No Included Bark	
SW 22ND ST	Green Buttonwood	6-10"	No	20'	Fair (41% to 60%)		Strap Constricting Tree	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark
SW 22ND ST	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)				
SW 22ND ST	Gumbo Limbo	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 22ND ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 22ND ST	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Restricted Canopy	
SW 22ND ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 22ND ST	Live Oak	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 22ND ST	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 22ND ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		Cavities
SW 22ND ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Trunk Damage - Minor
SW 22ND ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 22ND ST	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Moderate	Crown Density - Low	
SW 22ND ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 22ND ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 22ND ST	Strangler Fig	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting

*Note there are no trees on SW 37th Avenue - Douglas Road

Bordering Streets



Looking North at SW 22nd Street - Coral Way



Looking South from Coral Way



Looking North from US1 - South end



Looking North at SW 27th Street



Looking South near SW 24th Street



Looking South at US1



Looking South near SW 26th Street



Looking South towards Coral Way

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking one side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (Ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 27th Avenue - SR 9	4	Douglas Park	2	100	3500	Some	Some	No	4	State	Few	Some	4	Yes	Yes	No	Street lights, Turn Lanes. Has some 9' swales as bump outs
SW 32nd Avenue - McDonald Street	4	Douglas Park	2	60	4600	No	No	No	2	City	Some	Few	7	Yes	Yes	West	Signal at SW 27th Street. 15' swale in some locations

SW 27th Avenue - SR 9

TYPOLOGY F

SW 32nd Avenue - McDonald Street

TYPOLOGY A & D

Street Tree Inventory

SW 27th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH AVE	Cabbage Palm	16-20"	No	5'	Fair (41% to 60%)		Strap Constricting Tree	Over Pruned	
SW 27TH AVE	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)		Strap Constricting Tree	Over Pruned	
SW 27TH AVE	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)		Strap Constricting Tree	Over Pruned	
SW 27TH AVE	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)		Strap Constricting Tree	Over Pruned	
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Fair (41% to 60%)		Tapered Trunk		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	1-5"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		White Fly		
SW 27TH AVE	Pigeon Plum	1-5"	No	Negligible	Dead (0% to 5%)				
SW 27TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		White Fly	Trunk Damage - Moderate	Dead Wood
SW 27TH AVE	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		

SW 32nd Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 32ND AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 32ND AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 32ND AVE	Black Olive	21-30"	No	45'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Dead Wood	Sprouting
SW 32ND AVE	Black Olive	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 32ND AVE	Bottlebrush	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Bottlebrush	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 32ND AVE	Bottlebrush	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 32ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 32ND AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Suppressed Canopy	Nutrient Deficiency	Trunk Damage - Minor
SW 32ND AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor	Nutrient Deficiency	

(Continued on Next Page)

Street Tree Inventory

SW 32nd Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 32ND AVE	Crepe Myrtle	1-5"	No	5'	Dead (0% to 5%)	Utility Lines Above			
SW 32ND AVE	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Crepe Myrtle	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Moderate		
SW 32ND AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 32ND AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 32ND AVE	Crepe Myrtle	6-10"	Yes	10'	Dead (0% to 5%)	Utility Lines Above			
SW 32ND AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Crepe Myrtle	1-5"	No	5'	Dead (0% to 5%)	Utility Lines Above			
SW 32ND AVE	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Green Buttonwood	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Topped	Sprouting
SW 32ND AVE	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Topped	Sprouting
SW 32ND AVE	Green Buttonwood	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Topped	Sprouting	
SW 32ND AVE	Japanese Privet	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Strap Constricting Tree	
SW 32ND AVE	Japanese Privet	6-10"	No	10'	Good (61% to 80%)				
SW 32ND AVE	Japanese Privet	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Japanese Privet	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 32ND AVE	Japanese Privet	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Major	
SW 32ND AVE	Japanese Privet	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Major	
SW 32ND AVE	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 32ND AVE	Japanese Privet	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Major	
SW 32ND AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Improperly Mulched	
SW 32ND AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 32ND AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Sprouting	
SW 32ND AVE	Live Oak	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 32ND AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 32ND AVE	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	
SW 32ND AVE	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	
SW 32ND AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 32ND AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Dead Wood	Sprouting	
SW 32ND AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 32ND AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Dead Wood	Sprouting	
SW 32ND AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 32ND AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 32ND AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Dead Wood	Sprouting
SW 32ND AVE	Live Oak	11-15"	No	35'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 32ND AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 32ND AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 32ND AVE	Live Oak	41-50"	No	60'	Good (61% to 80%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 32ND AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major	Stubs with Sprouts
SW 32ND AVE	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 32ND AVE	Mahogany	41-50"	No	60'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 32ND AVE	Mahogany	41-50"	No	70'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 32ND AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Minor



CITRUS GROVE

Streets | Terraces



Looking West - SW 19th Avenue




Looking West - SW 23rd Avenue



Looking West - SW 22nd Avenue



Looking West - SW 23rd Avenue



Looking East - SW 27th Avenue



Looking East - SW 21st Court



Looking East - SW 23rd Avenue



Looking East - SW 24th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 2nd Street	1	Citrus Grove	3	50	2300	No	No	Yes	2	City	Few	Few	5	Yes	Yes	Mostly on South Side	Broken into three segments. No Street trees between 19th Avenue and 21st Court. Construction near 22nd Avenue intersection with dirt swales.
SW 2nd Terrace	1	Citrus Grove	3	50	1200	No	No	No	2	City	Some	Few	8	Some	Yes	Mostly on South Side	New tree plantings (Orange Geiger) along north side. Some swales used for parking.

SW 2nd Street
TYPOLOGY A & D

SW 2nd Terrace
TYPOLOGY A

Street Tree Inventory

SW 2nd Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 2ND ST	Black Olive	16-20"	No	25'	Poor (21% to 40%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 2ND ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Major
SW 2ND ST	Black Olive	11-15"	Yes	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 2ND ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 2ND ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 2ND ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 2ND ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 2ND ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 2ND ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 2ND ST	Foxtail Palm	1-5"	No	10'	Good (61% to 80%)				
SW 2ND ST	Glaucous Cassia	1-5"	No	15'	Fair (41% to 60%)		Leaning - Minor	Codominant Leaders/Included Bark	
SW 2ND ST	Gumbo Limbo	11-15"	No	10'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 2ND ST	Gumbo Limbo	6-10"	No	10'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 2ND ST	Hong Kong Orchid	11-15"	No		Dead (0% to 5%)	Utility Lines Above			
SW 2ND ST	Hong Kong Orchid	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 2ND ST	Hong Kong Orchid	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Sprouting
SW 2ND ST	Hong Kong Orchid	11-15"	No	15'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 2ND ST	Java Bishopwood	21-30"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 2ND ST	Java Bishopwood	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Dead Wood
SW 2ND ST	Java Bishopwood	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Apical Dieback	Dead Wood
SW 2ND ST	Java Bishopwood	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	
SW 2ND ST	Java Bishopwood	16-20"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Crown Density - Very Low	Dead Wood	
SW 2ND ST	Java Bishopwood	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Girdling Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 2ND ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 2ND ST	Live Oak	6-10"	No	20'	Poor (21% to 40%)		Plunged	Crown Density - Excessive (Due to Epicormic Growth)	Stubs with Sprouts
SW 2ND ST	Live Oak	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 2ND ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 2ND ST	Orange Geiger	1-5"	No	10'	Good (61% to 80%)				
SW 2ND ST	Orange Geiger	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 2ND ST	Papaya	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Papaya	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Trunk Damage - Moderate	Decay Observed
SW 2ND ST	Pink Tabebuia	21-30"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	
SW 2ND ST	Royal Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 2ND ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 2ND ST	Royal Poinciana	11-15"	No	25'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 2ND ST	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Sprouting
SW 2ND ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 2ND ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 2ND ST	Starburst Clerodendron	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 2ND ST	Tamarind	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 2ND ST	Tamarind	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 2ND ST	Umbrella Tree	6-10"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Codominant Leaders/Included Bark
SW 2ND ST	Umbrella Tree	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 2ND ST	Umbrella Tree	11-15"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Restricted Canopy
SW 2ND ST	Umbrella Tree	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed

Street Tree Inventory

SW 2nd Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 2ND TER	Areca Palm	21-30"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Nutrient Deficiency	
SW 2ND TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 2ND TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 2ND TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 2ND TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 2ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 2ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 2ND TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 2ND TER	Dracaena sp.	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 2ND TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 2ND TER	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 2ND TER	Horseflesh Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 2ND TER	Horseflesh Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 2ND TER	Horseflesh Mahogany	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs
SW 2ND TER	Horseflesh Mahogany	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs
SW 2ND TER	Java Bishopwood	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Leader - Bent
SW 2ND TER	Java Bishopwood	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 2ND TER	Java Bishopwood	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Apical Dieback	Codominant Leaders/No Included Bark
SW 2ND TER	Java Bishopwood	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Apical Dieback	Codominant Leaders/No Included Bark
SW 2ND TER	Melaleuca	16-20"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	Ficus Growing on Tree
SW 2ND TER	Oleander	6-10"	Yes	10'	Good (61% to 80%)				
SW 2ND TER	Orange Geiger	1-5"	No	15'	Fair (41% to 60%)		Leaning - Minor	Strap Constricting Tree	
SW 2ND TER	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)		Leaning - Minor		
SW 2ND TER	Orange Geiger	1-5"	No	10'	Poor (21% to 40%)		Leaning - Minor	Leader - Broken	Strap Constricting Tree
SW 2ND TER	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)		Leaning - Minor	Trunk Damage - Moderate	Strap Constricting Tree
SW 2ND TER	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 2ND TER	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 2ND TER	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 2ND TER	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 2ND TER	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		

Streets



Looking West - SW 19th Avenue




Looking West - SW 17th Court



Looking West - SW 19th Avenue



Looking West - SW 24th Avenue



Looking East - SW 23rd Avenue



Looking East - SW 27th Avenue



Looking East - Beacom Boulevard



Looking East - SW 22nd Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale	Curbs	Sidewalks	Overhead Utilities	Notes
SW 3rd Street	1	Citrus Grove	3	50	3400	No	No	Yes	2	City	Few	Few	7 (W. of 22nd Ave)	Yes	Yes	Mostly on South Side	Segmented by 22nd Avenue. No curbs between 25 and 24th avenue. Swales highly segmented by driveways. No swales between 17th and 22nd Avenue. New tree plantings under utility lines near 25th Avenue.
SW 4th Street	1	Citrus Grove	3	50	3400	No	No	Yes	2	City	Few	Yes	5 (W. of 22nd Ave)	W. of 22nd Ave	Some, sparse E of 22nd	Mostly on South Side	One Way - West between 17th and 22nd Avenue. Segmented by 22nd Avenue. Road Narrows significantly between 17th and 22nd Ave.

SW 3rd Street

TYPOLOGY A & D

SW 4th Street

TYPOLOGY B & C

Street Tree Inventory

SW 3rd Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 3RD ST	Canary Island Date Palm	11-15"	No	10'	Good (61% to 80%)				
SW 3RD ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy	Reduced Canopy - Minor	
SW 3RD ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 3RD ST	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 3RD ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 3RD ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 3RD ST	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)				
SW 3RD ST	Green Buttonwood	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)	
SW 3RD ST	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Trunk Damage - Minor	
SW 3RD ST	Horseflesh Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 3RD ST	Horseflesh Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 3RD ST	Horseflesh Mahogany	31-40"	No	20'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Crown Density - Very Low	Dead Wood	
SW 3RD ST	Horseflesh Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 3RD ST	Horseflesh Mahogany	16-20"	No	25'	Dead (0% to 5%)				
SW 3RD ST	Horseflesh Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 3RD ST	Horseflesh Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 3RD ST	Horseflesh Mahogany	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Apical Dieback	Dead Wood
SW 3RD ST	Java Bishopwood	21-30"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	
SW 3RD ST	Java Bishopwood	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 3RD ST	Java Bishopwood	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 3RD ST	Java Bishopwood	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 3RD ST	Java Bishopwood	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Dead Wood
SW 3RD ST	Java Bishopwood	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 3RD ST	Java Bishopwood	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 3RD ST	Java Bishopwood	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 3RD ST	Java Bishopwood	21-30"	No	20'	Poor (21% to 40%)		Apical Dieback	Basal Co-Dominant	Dead Wood
SW 3RD ST	Java Bishopwood	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 3RD ST	Java Bishopwood	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 3RD ST	Live Oak	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 3RD ST	Mahogany	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 3RD ST	Orange Geiger	1-5"	No	15'	Good (61% to 80%)		Sprouting	Strap Constricting Tree	
SW 3RD ST	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 3RD ST	Pink Tabebuia	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 3RD ST	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 3RD ST	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Codominant Leaders/Included Bark	Strap Constricting Tree	Sprouting
SW 3RD ST	Pink Tabebuia	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Decay Observed	Reduced Canopy - Moderate
SW 3RD ST	Pygmy Date Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 3RD ST	Pygmy Date Palm	11-15"	Yes	5'	Good (61% to 80%)				
SW 3RD ST	Pygmy Date Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 3RD ST	Tamarind	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	
SW 3RD ST	Tamarind	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Stubs with Sprouts
SW 3RD ST	Tamarind	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)
SW 3RD ST	Tamarind	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Crown Density - Excessive (Due to Epicormic Growth)	Trunk Damage - Moderate
SW 3RD ST	Weeping Fig	31-40"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Moderate	Decay Observed
SW 3RD ST	Weeping Fig	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Codominant Leaders/Included Bark	Dead Wood
SW 3RD ST	Weeping Fig	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 3RD ST	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)				
SW 3RD ST	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)				

SW 4th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 4TH ST	Avocado	6-10"	No	25'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 4TH ST	Bald Cypress	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Moderate		
SW 4TH ST	Bald Cypress	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Black Olive	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 4TH ST	Black Olive	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 4TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Reduced Canopy - Moderate
SW 4TH ST	Blackbead	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 4TH ST	Blackbead	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant	Constricted Roots	

(Continued on Next Page)

Street Tree Inventory

SW 4th Street (Continued)

SW 4TH ST	Blackbead	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Trunk Damage - Major	Sprouting
SW 4TH ST	Bottle Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 4TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 4TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Suppressed Canopy	Restricted Canopy
SW 4TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 4TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 4TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH ST	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)				
SW 4TH ST	Golden Shower Tree	11-15"	No	30'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Restricted Canopy	Dead Wood
SW 4TH ST	Golden Shower Tree	6-10"	No	30'	Good (61% to 80%)		Dead Wood		
SW 4TH ST	Green Buttonwood	6-10"	No	25'	Fair (41% to 60%)		Sprouting		
SW 4TH ST	Gumbo Limbo	11-15"	No	20'	Poor (21% to 40%)		Girdling Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 4TH ST	Hong Kong Orchid	21-30"	No	25'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Topped	Sprouting
SW 4TH ST	Mahogany	1-5"	No	15'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 4TH ST	Mahogany	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 4TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 4TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots		

(Continued on Next Page)

Street Tree Inventory

SW 4th Street (Continued)

SW 4TH ST	Mahogany	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 4TH ST	Mahogany	6-10"	No	20'	Poor (21% to 40%)		Reduced Canopy - Moderate	Leader - Broken	Decay Observed
SW 4TH ST	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Restricted Canopy	Codominant Leaders/No Included Bark
SW 4TH ST	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Trunk Damage - Minor
SW 4TH ST	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 4TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 4TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 4TH ST	Mahogany	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 4TH ST	Mahogany	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 4TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major
SW 4TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 4TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 4TH ST	Mahogany	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 4TH ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 4TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 4TH ST	Mango	1-5"	No	10'	Dead (0% to 5%)				
SW 4TH ST	Orange Geiger	1-5"	No	15'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 4TH ST	Orange Geiger	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Paradise Tree	1-5"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 4TH ST	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 4TH ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Pink Tabebuia	1-5"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	
SW 4TH ST	Sacred Fig	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 4TH ST	Sacred Fig	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 4TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 4TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Southern Red Cedar	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 4TH ST	Strangler Fig	11-15"	No	15'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low	Dead Wood	Decay Observed
SW 4TH ST	Tamarind	6-10"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood
SW 4TH ST	Tropical Almond	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 4TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 4TH ST	Vera Wood	1-5"	No	15'	Poor (21% to 40%)		Leaning - Major		
SW 4TH ST	Vera Wood	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate	Strap Constricting Tree
SW 4TH ST	Vera Wood	6-10"	No	15'	Fair (41% to 60%)		Crown Density - Excessive (Due to Epicormic Growth)	Strap Constricting Tree	
SW 4TH ST	Weeping Fig	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 4TH ST	Weeping Fig	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Dead Wood	Reduced Canopy - Moderate
SW 4TH ST	Weeping Fig	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Stubs
SW 4TH ST	Weeping Fig	6-10"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Broken Branches
SW 4TH ST	White Geiger	6-10"	Yes	5'	Good (61% to 80%)				
SW 4TH ST	Yellow Tabebuia	6-10"	No	15'	Good (61% to 80%)				

Streets



Looking West - SW 17th Avenue




Looking West - SW 19th Avenue




Looking West - SW 17th Avenue



Looking West - SW 19th Avenue



Looking East - SW 23rd Avenue



Looking East - SW 27th Avenue



Looking East - SW 22nd Avenue



Looking East - SW 27th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 5th Street	1	Citrus Grove	3	50	3400	No	No	Yes	2	City	Few	Few	5 (W. of 22nd Ave)	W. of 22nd Ave	Yes	South Side, btw 27 and 24th Ave	One Way - East between 17th and 22nd Avenue. Paved/Dirt swales between 17th and 22nd Ave. Large paved driveways for multi-family homes.
SW 6th Street	1	Citrus Grove	3	50	3400	No	No	Yes	2	City	Some	Few	6	Intermittent	Yes	South Side, btw 27 and 23rd Ave,	One Way - West. Share the lane bike markings on North side. Some segments with dirt/paved swales near 22nd Avenue intersection.

SW 5th Street

TYPOLOGY B & C

SW 6th Street

TYPOLOGY D & B

Street Tree Inventory

SW 5th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 5TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 5TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 5TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Australian Pine	21-30"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 5TH ST	Black Olive	21-30"	No	30'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 5TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Bottlebrush	11-15"	No	10'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Sprouting
SW 5TH ST	Bridalveil Tree	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Trunk Damage - Minor	Strap Constricting Tree
SW 5TH ST	BV UNID 4	1-5"	No	10'	Poor (21% to 40%)		Constricted Roots	Leader - Bent	Trunk Damage - Minor
SW 5TH ST	Cabbage Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Suppressed Canopy	
SW 5TH ST	Cabbage Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 5TH ST	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)		Suppressed Canopy		
SW 5TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 5TH ST	Christmas Palm	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Tapered Trunk
SW 5TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Moderate	
SW 5TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Moderate	
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Tapered Trunk	
SW 5TH ST	Coconut Palm	6-10"	No	30'	Good (61% to 80%)				
SW 5TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 5TH ST	Coconut Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 5TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	White Fly	
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 5TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 5TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 5TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	1-5"	No	10'	Fair (41% to 60%)		Restricted Canopy	White Fly	
SW 5TH ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Restricted Canopy	Nutrient Deficiency	White Fly
SW 5TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		

(Continued on Next Page)

Street Tree Inventory

SW 5th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH ST	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)				
SW 5TH ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Dead Wood
SW 5TH ST	Gumbo Limbo	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 5TH ST	Hong Kong Orchid	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 5TH ST	Hong Kong Orchid	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Trunk Damage - Major	Epicormic Growth
SW 5TH ST	Jacaranda	6-10"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Lopsided/Moderately Reduced Canopy	Strap Constricting Tree
SW 5TH ST	Japanese Privet	6-10"	Yes	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Trunk Damage - Major	Decay Observed	
SW 5TH ST	Java Bishopwood	21-30"	No	35'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders/Included Bark
SW 5TH ST	Java Bishopwood	16-20"	No	20'	Very Poor/Critical (6% to 20%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 5TH ST	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 5TH ST	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Lopsided/Moderately Reduced Canopy	Trunk Damage - Major	Leaning - Minor
SW 5TH ST	Mahogany	6-10"	Yes	15'	Fair (41% to 60%)		Topped	Sprouting	
SW 5TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Root Damage/Decay	Codominant Leaders/Included Bark	
SW 5TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 5TH ST	Mahogany	16-20"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Dead Wood
SW 5TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Trunk Damage - Minor	
SW 5TH ST	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 5TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	
SW 5TH ST	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/No Included Bark	
SW 5TH ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 5TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 5TH ST	Mahogany	21-30"	No	45'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 5TH ST	Mango	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 5TH ST	Mango	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Topped	Sprouting	Basal Co-Dominant with Adjacent Tree(s)
SW 5TH ST	Oriental Arborvitae	16-20"	No	20'	Good (61% to 80%)				
SW 5TH ST	Pink Tabebuia	21-30"	No	25'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Lopsided/Moderately Reduced Canopy
SW 5TH ST	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 5TH ST	Pink Tabebuia	6-10"	No		Dead (0% to 5%)	Utility Line Conflict			
SW 5TH ST	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Topped	Sprouting	Trunk Damage - Moderate
SW 5TH ST	Pongam	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)
SW 5TH ST	Pongam	11-15"	No	25'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Crown Density - Excessive (Due to Epicormic Growth)
SW 5TH ST	Pygmy Date Palm	6-10"	No	15'	Fair (41% to 60%)		Frizzled Fronds	Trunk Damage - Moderate	
SW 5TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Pygmy Date Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Pygmy Date Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Queen Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Queen Palm	6-10"	No	25'	Good (61% to 80%)				
SW 5TH ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Tapered Trunk	
SW 5TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 5TH ST	Royal Poinciana	6-10"	No	30'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Leader - Bent	
SW 5TH ST	Royal Poinciana	6-10"	No	20'	Poor (21% to 40%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Limb Damage - Moderate
SW 5TH ST	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 5TH ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Trunk Damage - Moderate
SW 5TH ST	Royal Poinciana	6-10"	No	30'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Restricted Canopy	
SW 5TH ST	Royal Poinciana	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 5TH ST	Sea Grape	1-5"	Yes	5'	Good (61% to 80%)				
SW 5TH ST	Silver Buttonwood	16-20"	No	15'	Fair (41% to 60%)		Basal Co-Dominant	Suppressed Canopy	Dead Wood
SW 5TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 5TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 5TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 5TH ST	Washington Palm	11-15"	No	15'	Poor (21% to 40%)		Trunk Damage - Moderate	Reduced Canopy - Minor	Nutrient Deficiency
SW 5TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 5TH ST	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 5TH ST	Weeping Fig	16-20"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 5th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH ST	Yellow Poinciana	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 5TH ST	Yellow Poinciana	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	Decay Observed
SW 5TH ST	Yellow Poinciana	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 5TH ST	Yellow Poinciana	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 5TH ST	Yellow Poinciana	31-40"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed

SW 6th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 6TH ST	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 6TH ST	Black Olive	31-40"	No	40'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 6TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 6TH ST	Black Olive	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 6TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 6TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 6TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 6TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Christmas Palm	1-5"	No	10'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Cracks in Trunk	
SW 6TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 6TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Tapered Trunk	
SW 6TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 6TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 6TH ST	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)		Restricted Canopy	Trunk Damage - Moderate	
SW 6TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 6TH ST	Christmas Palm	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Cracks in Trunk	Trunk Damage - Major	
SW 6TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 6TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 6TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 6TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 6TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 6TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 6TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Moderate	
SW 6TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 6TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Moderate	White Fly
SW 6TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Leaning - Moderate	
SW 6TH ST	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Crepe Myrtle	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH ST	Frangipani	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 6TH ST	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Leader - Broken	Dead Wood
SW 6TH ST	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark
SW 6TH ST	Java Bishopwood	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 6TH ST	Java Bishopwood	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 6TH ST	Java Bishopwood	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 6TH ST	Live Oak	11-15"	No	40'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 6TH ST	Live Oak	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Trunk Damage - Minor	
SW 6TH ST	Live Oak	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 6TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 6TH ST	Live Oak	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 6th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 6TH ST	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 6TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 6TH ST	Live Oak	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Girdling Roots	Reduced Canopy - Moderate	Sprouting
SW 6TH ST	Live Oak	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 6TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 6TH ST	Mahogany	41-50"	No	70'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 6TH ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 6TH ST	Mahogany	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 6TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 6TH ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark
SW 6TH ST	Mahogany	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 6TH ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 6TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 6TH ST	Mahogany	21-30"	No	25'	Very Poor/Critical (6% to 20%)		Root Damage/Decay	Trunk Damage - Major	Reduced Canopy - Major
SW 6TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 6TH ST	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 6TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 6TH ST	Oriental Arborvitae	11-15"	No	20'	Good (61% to 80%)				
SW 6TH ST	Oriental Arborvitae	11-15"	No	20'	Good (61% to 80%)				
SW 6TH ST	Pink Tabebuia	1-5"	No		Dead (0% to 5%)				
SW 6TH ST	Pink Tabebuia	1-5"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 6TH ST	Pink Tabebuia	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 6TH ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 6TH ST	Pongam	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 6TH ST	Pongam	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 6TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 6TH ST	Royal Poinciana	16-20"	No	45'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Restricted Canopy
SW 6TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 6TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 6TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 6TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 6TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 6TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 6TH ST	Umbrella Tree	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low	Dead Wood	
SW 6TH ST	Umbrella Tree	11-15"	No	15'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 6TH ST	Unidentified Dead Tree (Defoliated)	11-15"	No	10'	Dead (0% to 5%)				
SW 6TH ST	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 6TH ST	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 6TH ST	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 6TH ST	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 6TH ST	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		

Streets



Looking West - SW 17th Avenue



Looking West - SW 22nd Avenue



Looking East - SW 22nd Avenue



Looking East - SW 27th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 7th Street	1	Citrus Grove	3	50	3400	No	No	No	3	State	No	No	0	Yes	Yes	Mostly on North Side	One Way - West. No Street Trees. Not pedestrian friendly.

SW 7th Street

TYPOLOGY E

Street Tree Inventory

SW 7th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 7TH ST	Washingtonia Palm	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 7TH ST	Washingtonia Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 7TH ST	Washingtonia Palm	11-15"	No	15'	Good (61% to 80%)				
SW 7TH ST	Wild/Cuban Tamarind	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	Stubs with Sprouts



Looking North - SW 3rd Street



Looking North - SW 3rd Street



Looking North - SW 5th Street



Looking South - SW 1st Street



Looking South - SW 5th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 17th Court	1	Citrus Grove	3	50	900	No	No	Yes	2	City	Few	No	2	Yes	Yes	Mostly on West Side	Royal Poinciana and Strangler Fig with some decay on south side of Court.
SW 18th Avenue	1	Citrus Grove	3	50/25 btw 4 and 5 street	2100	No	No	Yes	2	City	No	Few	0	Yes	Yes	Mostly on West Side	Segmented by 3rd and 4th Street, sidewalk/alley connects both segments. Southern segment One Way - North. Dirt swales used for parking on South segment. No Street Trees on North segment.

SW 17th Court

TYPOLOGY D & B

SW 18th Avenue

TYPOLOGY C & D

Street Tree Inventory

SW 17th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 17TH CT	Black Olive	16-20"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 17TH CT	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Cavities
SW 17TH CT	Black Olive	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 17TH CT	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH CT	Mahogany	31-40"	Yes	45'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 17TH CT	Royal Poinciana	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 17TH CT	Sea Grape	11-15"	Yes	25'	Fair (41% to 60%)		Constricted Roots	Discolored Foliage	Reduced Canopy - Moderate
SW 17TH CT	Sea Grape	6-10"	Yes	20'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	
SW 17TH CT	Strangler Fig	31-40"	No	35'	Very Poor/Critical (6% to 20%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed

SW 18th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 18TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Decay Observed
SW 18TH AVE	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 18TH AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Decay Observed
SW 18TH AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 18TH AVE	Christmas Palm	1-5"	Yes	15'	Good (61% to 80%)				
SW 18TH AVE	Crepe Myrtle	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Codominant Leaders/No Included Bark	
SW 18TH AVE	Mahogany	6-10"	Yes	20'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Stubs with Sprouts	Codominant Leaders/Included Bark	
SW 18TH AVE	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 18TH AVE	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Moderate	
SW 18TH AVE	Starburst Clerodendron	6-10"	Yes	10'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Crown Density - Very Low	Dead Wood	Codominant Leaders/Included Bark
SW 18TH AVE	Weeping Fig	6-10"	No	20'	Poor (21% to 40%)		Lifting	Reduced Canopy - Major	Trunk Damage - Moderate
SW 18TH AVE	Weeping Fig	6-10"	No	20'	Poor (21% to 40%)		Lifting	Stubs with Sprouts	Trunk Damage - Moderate

Streets



Looking North - SW 3rd Street



Looking North - SW 8th Street



Looking North - SW 4th Street



Looking South - SW 1st Street



Looking South - SW 5th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 18th Court	1	Citrus Grove	3	50 - 40	700	No	No	Yes	2	City	Few	No	5	Yes	Mostly on East	Mostly on West Side	Sidewalk not consistent throughout block. Only one large Mahogany and small Gumbo Limbo. Large paved driveways for multi-family housing.
SW 19th Avenue	1	Citrus Grove	3	50 / 45 N of 4th street	2200	No	No	Yes	2	City	Few	Few	5	No	Yes	Mostly West, East side south of 4th	Sidewalks not consistent North of 4th Street. Lacking street trees.

SW 18th Court

TYPOLOGY D & B

SW 19th Avenue

TYPOLOGY C & D/X

Street Tree Inventory

SW 18th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 18TH CT	Gumbo Limbo	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Lifting	Reduced Canopy - Major
SW 18TH CT	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Lifting	Reduced Canopy - Moderate

SW 19th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH AVE	Areca Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH AVE	Areca Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 19TH AVE	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 19TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH AVE	Black Olive	16-20"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 19TH AVE	Cabbage Palm	21-30"	No	15'	Good (61% to 80%)	Utility Lines Above	Ficus Growing on Tree		
SW 19TH AVE	Royal Palm	11-15"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 19TH AVE	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	


Avenues



Looking North - SW 3rd Street



Looking North - SW 2nd Street



Looking North - SW 7th Street



Looking North - SW 3rd Street



Looking South - SW 2nd Street



Looking South - SW 1st Street



Looking South- SW 4th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 20th Avenue	1	Citrus Grove	3	45	700	No	No	Yes	2	City	No	No	0	Yes	Yes	Mostly on West Side	No street trees except for two small Weeping Fig on East side of northern block. Mostly paved driveways for multi-family homes.
SW 21st Avenue	1	Citrus Grove	3	50	2000	No	No	Yes	2	City	Few	Few	5 (S. of 4th Street)	N of 5th street	Yes	West Side, N of 3rd Street	Segmented by 3rd and 4th Street. No street trees on northern segment. Nice canopy of mahoganies on south portion of southern segment. Swales used for parking on south segment.

SW 20th Avenue

TYPOLOGY D

SW 21st Avenue

TYPOLOGY C & D

Street Tree Inventory

SW 20th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 20TH AVE	Weeping Fig	11-15"	Yes	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 20TH AVE	Weeping Fig	6-10"	Yes	15'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 20TH AVE	Weeping Fig	6-10"	Yes	10'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	

SW 21st Avenue


STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 21ST AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST AVE	Black Olive	16-20"	No	35'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders/Included Bark
SW 21ST AVE	Black Olive	16-20"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 21ST AVE	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Suppressed Canopy
SW 21ST AVE	Black Olive	6-10"	No	15'	Poor (21% to 40%)		Constricted Roots	Topped	Suppressed Canopy
SW 21ST AVE	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 21ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 21ST AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 21ST AVE	Mahogany	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	Restricted Canopy
SW 21ST AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 21ST AVE	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders/Included Bark
SW 21ST AVE	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders/Included Bark
SW 21ST AVE	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 21ST AVE	Mahogany	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 21ST AVE	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 21ST AVE	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 21ST AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 21ST AVE	Royal Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 21ST AVE	Umbrella Tree	6-10"	Yes	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Suppressed Canopy
SW 21ST AVE	Weeping Fig	41-50"	Yes	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 21ST AVE	Weeping Fig	16-20"	Yes	25'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		



Looking North - SW 3rd Street




Looking North - SW 8th Street



Looking North - SW 4th Street



Looking South - SW 1st Street



Looking South- SW 5th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 21st Court	1	Citrus Grove	3	50	700	No	No	Yes	2	City	Few	Some	0	Yes	Yes	Both Sides	West side completely covered by Publix façade and utility lines.
SW 22nd Avenue	1	Citrus Grove	3	75	2600	Yes, 20ft	No	No	4	County	Some	Few	0	Yes	Yes	Mostly on West Side	Medians mostly planted with yellow tabebuia and live oak. No vegetation on median between 7th and 8th Street.

SW 21st Court

TYPOLOGY D

SW 22nd Avenue

TYPOLOGY I & E

Street Tree Inventory

SW 21st Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 21ST CT	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				

SW 22nd Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Ashoka Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND AVE	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Major	Lopsided/Moderately Reduced Canopy	
SW 22ND AVE	Live Oak	6-10"	No	35'	Fair (41% to 60%)		Trunk Damage - Moderate	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 22ND AVE	Live Oak	6-10"	No	15'	Poor (21% to 40%)		Suppressed Canopy		
SW 22ND AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Apical Dieback	Codominant Leaders/Included Bark	Restricted Canopy
SW 22ND AVE	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 22ND AVE	Live Oak	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Apical Dieback	Sprouting
SW 22ND AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	Sprouting
SW 22ND AVE	Live Oak	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Trunk Damage - Minor	
SW 22ND AVE	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 22ND AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Constricted Roots		
SW 22ND AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Constricted Roots		
SW 22ND AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Constricted Roots		
SW 22ND AVE	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 22ND AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots		
SW 22ND AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Constricted Roots		
SW 22ND AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND AVE	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 22ND AVE	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 22ND AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 22ND AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND AVE	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 22ND AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 22ND AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	
SW 22ND AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	
SW 22ND AVE	Pink Tabebuia	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Very Low	Desiccated Foliage	
SW 22ND AVE	Pink Tabebuia	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Very Low	Desiccated Foliage	Loose Trunk
SW 22ND AVE	Pink Tabebuia	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Very Low	Desiccated Foliage	Leaning - Minor
SW 22ND AVE	Pink Tabebuia	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Very Low	Desiccated Foliage	Leaning - Minor
SW 22ND AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 22ND AVE	Weeping Fig	6-10"	Yes	15'	Fair (41% to 60%)		Lifting	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 22ND AVE	Yellow Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Suppressed Canopy
SW 22ND AVE	Yellow Tabebuia	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 22ND AVE	Yellow Tabebuia	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 22ND AVE	Yellow Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots		
SW 22ND AVE	Yellow Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Leaning - Moderate		
SW 22ND AVE	Yellow Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND AVE	Yellow Tabebuia	11-15"	No	15'	Poor (21% to 40%)		Constricted Roots	Leader - Broken	Reduced Canopy - Moderate
SW 22ND AVE	Yellow Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Cracks in Trunk	Sprouting
SW 22ND AVE	Yellow Tabebuia	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 22ND AVE	Yellow Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	


Avenues



Looking North - SW 7th Street



Looking North - SW 4th Street



Looking North - SW 7th Street



Looking North - SW 3rd Street



Looking South - SW 5th Street



Looking South - SW 1st Street



Looking South- SW 5th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 23rd Avenue	1	Citrus Grove	3	50	2600	No	No	Yes	2	City	Yes	Few	5-10	b/w 6th and 3rd street	Yes	East Side, N of 3rd street	North and south ends use swale for parking, not much tree canopy there.
SW 24th Avenue	1	Citrus Grove	3	50	1800	No	No	Yes	2	City	Some	Few	5	No	Yes	Mostly on West Side	Segmented by 3rd and 4th Street. Northern segment used by Miami Senior High for parking, some juvenile trees planted on setback. Some Swales on southern segment used for parking. Royal poinciana severely damaged between 5th and 6th street.

SW 23rd Avenue

TYPOLOGY B & C

SW 24th Avenue

TYPOLOGY B & D

Street Tree Inventory

SW 23rd Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD AVE	Black Olive	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark
SW 23RD AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 23RD AVE	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Horseflesh Mahogany	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 23RD AVE	Horseflesh Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Codominant Leaders/Included Bark	Decay Observed
SW 23RD AVE	Horseflesh Mahogany	21-30"	Yes	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 23RD AVE	Horseflesh Mahogany	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 23RD AVE	Horseflesh Mahogany	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 23RD AVE	Horseflesh Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 23RD AVE	Mahogany	41-50"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 23RD AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 23RD AVE	Oriental Arborvitae	6-10"	No	5'	Good (61% to 80%)				
SW 23RD AVE	Papaya	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots		
SW 23RD AVE	Papaya	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 23RD AVE	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 23RD AVE	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 23RD AVE	Royal Poinciana	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Leaning - Major	Sprouting
SW 23RD AVE	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 23RD AVE	Royal Poinciana	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD AVE	Royal Poinciana	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 23RD AVE	Royal Poinciana	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 23RD AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Yellow Poinciana	31-40"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 23RD AVE	Yellow Poinciana	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 23RD AVE	Yellow Poinciana	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 23RD AVE	Yellow Poinciana	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 23RD AVE	Yellow Poinciana	31-40"	No	55'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 23RD AVE	Yellow Poinciana	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD AVE	Yellow Poinciana	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD AVE	Yellow Poinciana	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD AVE	Yellow Poinciana	31-40"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Limb Damage - Major	Sprouting

SW 24th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH AVE	Black Olive	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 24TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 24TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 24TH AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 24TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 24TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 24th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH AVE	Gumbo Limbo	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 24TH AVE	Horseflesh Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH AVE	Horseflesh Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH AVE	Jacaranda	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Dead Wood
SW 24TH AVE	Java Bishopwood	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Dead Wood
SW 24TH AVE	Java Bishopwood	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 24TH AVE	Java Bishopwood	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 24TH AVE	Java Bishopwood	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 24TH AVE	Java Bishopwood	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 24TH AVE	Java Bishopwood	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 24TH AVE	Java Bishopwood	16-20"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 24TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH AVE	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH AVE	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Broken Branches
SW 24TH AVE	Royal Poinciana	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major
SW 24TH AVE	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 24TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Strangler Fig	6-10"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 24TH AVE	Tamarind	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 24TH AVE	Tamarind	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 24TH AVE	Tamarind	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Trunk Damage - Moderate
SW 24TH AVE	Tamarind	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark
SW 24TH AVE	Tamarind	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 24TH AVE	Tamarind	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Moderate	Crown Density - Excessive (Due to Epicormic Growth)	Trunk Damage - Major
SW 24TH AVE	Washington Palm	6-10"	No	15'	Good (61% to 80%)				
SW 24TH AVE	Weeping Fig	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Dead Wood	Decay Observed
SW 24TH AVE	Yellow Poinciana	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH AVE	Yellow Poinciana	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH AVE	Yellow Poinciana	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH AVE	Yellow Poinciana	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Sprouting


Avenues | Boulevards



Looking North - SW 8th Street



Looking North - SW 4th Street



Looking Northeast - SW 8th Street



Looking Northeast - SW 4th Street



Looking South - SW 5th Street



Looking South - SW 1st Street



Looking Southwest - SW 4th Street



Looking Southwest - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 25th Avenue	1	Citrus Grove	3	50	2600	No	No	Yes	2	City	Some	Some	5-7 (S. of 3rd Street)	Intermittent	Yes	Mostly on West Side	No swales north of 3rd street. Some parking on swales between 3rd and 4th street. Busy intersections between 6th and 7th street
Beacom Boulevard	1	Citrus Grove	3	70	3000	No	No	Yes	4	City	No	No	0	Yes	Yes	No	Very Wide ROW for amount of traffic moving through, possible opportunity for median or swales. Not pedestrian friendly.

SW 25th Avenue

TYPOLOGY A & D

Beacom Boulevard

TYPOLOGY D

Street Tree Inventory


SW 25th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH AVE	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 25TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Nutrient Deficiency	
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 25TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 25TH AVE	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH AVE	Crepe Myrtle	6-10"	Yes	5'	Good (61% to 80%)				
SW 25TH AVE	Horseflesh Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Apical Dieback	Dead Wood
SW 25TH AVE	Horseflesh Mahogany	21-30"	No	30'	Dead (0% to 5%)	Utility Line Conflict			
SW 25TH AVE	Horseflesh Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Stubs with Sprouts	Decay Observed
SW 25TH AVE	Java Bishopwood	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Dead Wood
SW 25TH AVE	Java Bishopwood	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 25TH AVE	Java Bishopwood	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Apical Dieback	Dead Wood
SW 25TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 25TH AVE	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Girdling Roots	Strap Constricting Tree
SW 25TH AVE	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 25TH AVE	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 25TH AVE	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 25TH AVE	Pitch Apple	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 25TH AVE	Pongam	6-10"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots		
SW 25TH AVE	Pongam	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Codominant Leaders/No Included Bark	
SW 25TH AVE	Pongam	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 25TH AVE	Pongam	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots		
SW 25TH AVE	Pongam	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Leaning - Minor	Dead Wood
SW 25TH AVE	Pongam	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Leaning - Moderate	Uprooted - Partially	Trunk Damage - Major
SW 25TH AVE	Pongam	6-10"	No	35'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	
SW 25TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Queen Palm	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major		
SW 25TH AVE	Queen Palm	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major		
SW 25TH AVE	Queen Palm	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Major		
SW 25TH AVE	Queen Palm	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Major		
SW 25TH AVE	Queen Palm	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major		
SW 25TH AVE	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs
SW 25TH AVE	Royal Poinciana	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 25TH AVE	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 25TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH AVE	Spindle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 25TH AVE	Strangler Fig	41-50"	No	35'	Poor (21% to 40%)		Constricted Roots	Insect Damage Leaves	
SW 25TH AVE	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Wild/Cuban Tamarind	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	Stubs with Sprouts
SW 25TH AVE	Wild/Cuban Tamarind	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Dead Wood	Decay Observed
SW 25TH AVE	Yellow Poinciana	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Sprouting
SW 25TH AVE	Yellow Poinciana	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 25TH AVE	Yellow Tabebuia	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		

Bordering Streets



Looking West - SW 17th Avenue




Looking West - SW 22nd Avenue




Looking West - SW 17th Avenue



Looking West - SW 22nd Avenue




Looking East - SW 22nd Avenue



Looking East - SW 27th Avenue



Looking East - SW 22nd Avenue



Looking East - SW 27th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 1st Street	1	Citrus Grove	3	50	5400	No	No	Yes	3	State	Yes	Some	9	Yes	Yes	No	One Way - East. New Tree Plantings along both sides West of 22nd Ave. Bike lane along South side.
SW 8th Street	1	Citrus Grove	3	70	3400	No	No	Yes	3	State	Few	Yes	0	Yes	Yes	No	One Way - East. Crosswalks just East of 25th, 23rd, 20th, and 19th Avenue. All crosswalks have vegetated curb extensions. Sidewalk cutouts for trees along both sides.

SW 1st Street

TYPOLOGY A & D

SW 8th Street

TYPOLOGY D

Street Tree Inventory

SW 1st Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 1ST ST	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 1ST ST	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 1ST ST	Cabbage Palm	16-20"	No	10'	Fair (41% to 60%)		Restricted Canopy	Ficus Growing on Tree	
SW 1ST ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 1ST ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 1ST ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 1ST ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 1ST ST	Christmas Palm	6-10"	Yes	20'	Fair (41% to 60%)		Reduced Canopy - Major	Restricted Canopy	
SW 1ST ST	Christmas Palm	11-15"	Yes	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 1ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 1ST ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 1ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Reduced Canopy - Moderate	
SW 1ST ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	Nutrient Deficiency
SW 1ST ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	Nutrient Deficiency
SW 1ST ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	Nutrient Deficiency
SW 1ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	
SW 1ST ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	
SW 1ST ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	
SW 1ST ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	
SW 1ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Nutrient Deficiency	
SW 1ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 1ST ST	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Trunk Damage - Minor	
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Reduced Canopy - Moderate	
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Stubs with Sprouts	
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Stubs with Sprouts	Reduced Canopy - Moderate
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Stubs with Sprouts	Reduced Canopy - Moderate
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)				
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Trunk Damage - Minor	
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Trunk Damage - Minor
SW 1ST ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Live Oak	21-30"	No	35'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Dead Wood
SW 1ST ST	Live Oak	21-30"	No	45'	Fair (41% to 60%)		Dead Wood	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Crown Density - Moderate	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	20'	Poor (21% to 40%)		Crown Density - Very Low	Strap Constricting Tree	Root Damage/Decay
SW 1ST ST	Live Oak	6-10"	No	20'	Poor (21% to 40%)		Crown Density - Very Low	Strap Constricting Tree	Root Damage/Decay
SW 1ST ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Moderate	Strap Constricting Tree	
SW 1ST ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Moderate	Strap Constricting Tree	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Crown Density - Moderate	Strap Constricting Tree	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Crown Density - Moderate	Strap Constricting Tree	Codominant Leaders/Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 1st Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 1ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Crown Density - Moderate	Strap Constricting Tree	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Crown Density - Moderate	Strap Constricting Tree	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Crown Density - Moderate	Strap Constricting Tree	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Crown Density - Moderate	
SW 1ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Crown Density - Moderate	Root Damage/Decay
SW 1ST ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Strap Constricting Tree	Crown Density - Low	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Strap Constricting Tree	Crown Density - Moderate	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Crown Density - Low	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Crown Density - Moderate	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	Root Damage/Decay
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	Crown Density - Moderate
SW 1ST ST	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Crown Density - Moderate	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Crown Density - Low	Codominant Leaders/Included Bark
SW 1ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Crown Density - Moderate
SW 1ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Crown Density - Moderate
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Crown Density - Low
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Crown Density - Low
SW 1ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Crown Density - Moderate
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Crown Density - Low
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Crown Density - Low
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Crown Density - Low
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Crown Density - Low
SW 1ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Crown Density - Low
SW 1ST ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Broken Branches	
SW 1ST ST	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 1ST ST	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 1ST ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 1ST ST	Sea Grape	21-30"	No	35'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	
SW 1ST ST	Sea Grape	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 1ST ST	Sea Grape	11-15"	No	20'	Very Poor/Critical (6% to 20%)		Uprooted - Partially	Cracks in Trunk	Decay Observed
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 1ST ST	Yellow Poinciana	11-15"	No	15'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 1ST ST	Yellow Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Sprouting	Dead Wood

Street Tree Inventory

SW 8th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 8TH ST	Black Olive	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 8TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Trunk Damage - Minor
SW 8TH ST	Black Olive	6-10"	No	15'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 8TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Limb Damage - Moderate
SW 8TH ST	Black Olive	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 8TH ST	Black Olive	6-10"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Minor
SW 8TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 8TH ST	Black Olive	6-10"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark
SW 8TH ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 8TH ST	Black Olive	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Trunk Damage - Minor
SW 8TH ST	Black Olive	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Dead Wood	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 8TH ST	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sprouting
SW 8TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 8TH ST	Black Olive	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Stubs with Sprouts
SW 8TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Trunk Damage - Moderate
SW 8TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Limb Damage - Moderate
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Limb Damage - Moderate
SW 8TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 8TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	15'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	
SW 8TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Girdling Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Trunk Damage - Major
SW 8TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Girdling Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Trunk Damage - Major
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Girdling Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 8TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	
SW 8TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 8TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 8TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	11-15"	No	25'	Very Poor/Critical (6% to 20%)		Topped	Suppressed Canopy	Lopsided/Significantly Reduced Canopy
SW 8TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Girdling Roots	Trunk Damage - Moderate	Restricted Canopy
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Major
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	25'	Very Poor/Critical (6% to 20%)		Constricted Roots	Decay Observed	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Cavities
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	6-10"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Lopsided/Moderately Reduced Canopy
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 8th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Girdling Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Cavities
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Lifting	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Lifting	Decay Observed
SW 8TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 8TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 8TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 8TH ST	Live Oak	1-5"	No	10'	Poor (21% to 40%)		Crown Density - Low	Dead Wood	
SW 8TH ST	Live Oak	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low	Dead Wood	Trunk Damage - Moderate
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 8TH ST	Montgomery Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Reduced Canopy - Moderate	
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Minor	Cracks in Trunk	
SW 8TH ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Minor	Nutrient Deficiency
SW 8TH ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)		Trunk Damage - Minor	Reduced Canopy - Minor	Nutrient Deficiency
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Frizzled Fronds	
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		

(Continued on Next Page)

Street Tree Inventory

SW 8th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 8TH ST	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Constricted Roots	
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Constricted Roots		
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	6-10"	No	10'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Minor	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Restricted Canopy	Nutrient Deficiency	
SW 8TH ST	Yellow Tabebuia	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Trunk Damage - Moderate

Bordering Avenues



Looking North - SW 7th Street



Looking North - SW 4th Street



Looking North - SW 8th Street



Looking North - SW 4th Street



Looking South - SW 5th Street



Looking South - SW 1st Street



Looking South- SW 5th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft..)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 17th Avenue	1	Citrus Grove	3	70	2400	Yes	No	No	4	County	Median	No	0	Yes	Yes	Mostly on West Side	Brick Sidewalks along both sides. Crosswalk at 3rd Street with median along both sides. New tree plantings in Median. Share the lane bike markings along both sides.
SW 27th Avenue	1	Citrus Grove	3	100	2600	Yes	No	No	6	State	No	No	0	Yes	Yes	No	Major thoroughfare. No street trees. Not pedestrian friendly.

SW 17th Avenue

TYPOLOGY I & E

SW 27th Avenue

TYPOLOGY E

Street Tree Inventory

SW 17th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 17TH AVE	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Fungus on Leaves		
SW 17TH AVE	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH AVE	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Uprooted - Mostly	Trunk Damage - Moderate	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Uprooted - Mostly	Leaning - Major	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Uprooted - Mostly	Leaning - Major	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Uprooted - Partially	Leaning - Moderate	Strap Constricting Tree
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Leaning - Moderate	Strap Constricting Tree	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate	Trunk Damage - Moderate	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Partially	Crown Density - Low	Strap Constricting Tree
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Partially	Leaning - Moderate	Strap Constricting Tree
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	Leaning - Minor
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		



SHENANDOAH NORTH

Streets



Looking East - SW 27th Avenue



Looking East - SW 17th Avenue



Looking East - SW 25th Avenue



Looking East - SW 22nd Avenue



Looking West - SW 19th Avenue



Looking West - SW 24th Court



Looking West - SW 12th Avenue



Looking West - SW 16th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 9th Street	2	Shenandoah North	4	50	6300	No	No	Yes	2	City	Yes	Yes	7	some	yes	north side, periodically crossing	Grass and paved swales. Grass swales mostly correspond with curbed areas all east of SW 10th Street Road.
SW 10th Street	2	Shenandoah North	4	50-70	7400	Yes, 10ft	No	Yes	2	City	Yes	Yes	7	some	yes	north/southside b/t 27th and 25th Ave, southside b/t 25 ave and 24th ct	ROW 70' btw 19th and 22nd Ave. Median between 19th and 22nd Avenue. Roundabout at SW 24th Ave.

SW 9th Street

TYPOLOGY B & D

SW 10th Street

TYPOLOGY B & F

Street Tree Inventory

SW 9th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 9TH ST	Pongam	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 9TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Moderate
SW 9TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Suppressed Canopy	
SW 9TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Major
SW 9TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Major
SW 9TH ST	Pongam	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Reduced Canopy - Moderate
SW 9TH ST	Sacred Fig	21-30"	No	40'	Poor (21% to 40%)		Cavities	Stubs with Sprouts	Codominant Leaders - Multi
SW 9TH ST	Purple Tabebuia	1-5"	No	5'	Good (61% to 80%)		Leaning - Moderate		
SW 9TH ST	Purple Tabebuia	1-5"	No	5'	Good (61% to 80%)		Leaning - Moderate		
SW 9TH ST	Purple Tabebuia	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate	Discolored Foliage	
SW 9TH ST	Purple Tabebuia	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate	Discolored Foliage	
SW 9TH ST	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)				
SW 9TH ST	Green Buttonwood	11-15"	No	25'	Good (61% to 80%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 9TH ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 9TH ST	Green Buttonwood	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Lifting	Stubs with Sprouts
SW 9TH ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Lifting	Stubs with Sprouts
SW 9TH ST	Green Buttonwood	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lifting	Stubs with Sprouts
SW 9TH ST	Green Buttonwood	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Topped
SW 9TH ST	Green Buttonwood	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 9TH ST	Green Buttonwood	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark
SW 9TH ST	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Lifting	Sprouting
SW 9TH ST	Sapodilla	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 9TH ST	Crepe Myrtle	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 9TH ST	Crepe Myrtle	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 9TH ST	Live Oak	21-30"	No	55'	Very Poor/Critical (6% to 20%)		Constricted Roots	Crown Density - Very Low	Dead Wood
SW 9TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Moderate	
SW 9TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	
SW 9TH ST	Christmas Palm	6-10"	No	10'	Very Poor/Critical (6% to 20%)		Suppressed Canopy	Leaning - Moderate	Cracks in Trunk
SW 9TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 9TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	
SW 9TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Moderate		
SW 9TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Moderate		
SW 9TH ST	Red Bay	21-30"	No	30'	Poor (21% to 40%)		Topped	Decay Observed	Stubs with Sprouts
SW 9TH ST	Royal Palm	6-10"	No	15'	Fair (41% to 60%)		Discolored Foliage	Nutrient Deficiency	
SW 9TH ST	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Limb Damage - Major	Stubs with Sprouts
SW 9TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 9TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 9TH ST	Yellow Tabebuia	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 9TH ST	Yellow Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Leaning - Moderate	
SW 9TH ST	Weeping Fig	6-10"	Yes	15'	Poor (21% to 40%)		Decay Observed	Lifting	Dead Wood
SW 9TH ST	Weeping Fig	6-10"	Yes	10'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Decay Observed	Over Pruned
SW 9TH ST	Weeping Fig	6-10"	Yes	5'	Poor (21% to 40%)		Topped	Decay Observed	Stubs with Sprouts
SW 9TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 9TH ST	Brazilian Beauty Leaf	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 9TH ST	Brazilian Beauty Leaf	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 9TH ST	Washington Palm	16-20"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 9TH ST	Washington Palm	16-20"	No	15'	Fair (41% to 60%)		Sloughing Bark		
SW 9TH ST	Washington Palm	16-20"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate		

(Continued on Next Page)

Street Tree Inventory

SW 9th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 9TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 9TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 9TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 9TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 9TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Improperly Mulched	
SW 9TH ST	Cabbage Palm	11-15"	No	5'	Good (61% to 80%)		Reduced Canopy - Major		
SW 9TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 9TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 9TH ST	Weeping Fig	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Decay Observed	
SW 9TH ST	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Reduced Canopy - Major	Decay Observed	Crown Density - Low
SW 9TH ST	Golden Shower Tree	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 9TH ST	Chinese Golden Rain Tree	11-15"	No	30'	Fair (41% to 60%)		Trunk Damage - Moderate	Crown Density - Moderate	Dead Wood
SW 9TH ST	Cabbage Palm	11-15"	No	5'	Good (61% to 80%)		Reduced Canopy - Major		
SW 9TH ST	Cabbage Palm	11-15"	No	5'	Good (61% to 80%)		Reduced Canopy - Major		
SW 9TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 9TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Nutrient Deficiency	
SW 9TH ST	Cabada Palm	11-15"	No	5'	Good (61% to 80%)		Reduced Canopy - Major		
SW 9TH ST	Weeping Fig	21-30"	Yes	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Crown Density - Moderate
SW 9TH ST	Weeping Fig	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Codominant Leaders - Multi	
SW 9TH ST	Oriental Arborvitae	21-30"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Dead Wood
SW 9TH ST	Weeping Fig	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 9TH ST	Marlberry	1-5"	No	5'	Good (61% to 80%)				
SW 9TH ST	Red Bay	1-5"	No	5'	Fair (41% to 60%)		Lifting	Fungus on Leaves	
SW 9TH ST	Weeping Fig	21-30"	No	50'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Codominant Leaders - Multi	Decay Observed
SW 9TH ST	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 9TH ST	Silk Floss Tree	16-20"	No	20'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	
SW 9TH ST	Yellow Tabebuia	16-20"	No	20'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 9TH ST	Yellow Tabebuia	11-15"	No	25'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	
SW 9TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate	
SW 9TH ST	Royal Poinciana	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 9TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 9TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy	Leaning - Moderate	
SW 9TH ST	Queen Crepe Myrtle	1-5"	No	15'	Fair (41% to 60%)		Trunk Damage - Minor	Leaning - Moderate	Over Extended Limb(s)
SW 9TH ST	Queen Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Leaning - Moderate		
SW 9TH ST	Queen Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Leaning - Moderate		
SW 9TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 9TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 9TH ST	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Broken Branches		
SW 9TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 9TH ST	Hong Kong Orchid	1-5"	Yes	5'	Good (61% to 80%)		Fungus on Leaves		
SW 9TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 9TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Improperly Mulched		
SW 9TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Improperly Mulched		
SW 9TH ST	Royal Poinciana	1-5"	No	10'	Good (61% to 80%)		Improperly Mulched		
SW 9TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Improperly Mulched		
SW 9TH ST	Mahogany	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Over Extended Limb(s)
SW 9TH ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Over Extended Limb(s)
SW 9TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Major		
SW 9TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 9TH ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Cavities	

(Continued on Next Page)

Street Tree Inventory

SW 9th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 9TH ST	Gumbo Limbo	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Reduced Canopy - Moderate
SW 9TH ST	Green Buttonwood	11-15"	No	35'	Good (61% to 80%)		Crown Density - Excessive (Due to Epicormic Growth)		
SW 9TH ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	
SW 9TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Limb Damage - Moderate
SW 9TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 9TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 9TH ST	Green Buttonwood	16-20"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 9TH ST	Green Buttonwood	16-20"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 9TH ST	Green Buttonwood	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 9TH ST	Green Buttonwood	11-15"	No	20'	Very Poor/Critical (6% to 20%)		Uprooted - Mostly	Leaning - Major	Supported By Other Tree
SW 9TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 9TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	Nutrient Deficiency
SW 9TH ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 9TH ST	Black Olive	21-30"	No	30'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low	Cavities	Dead Wood
SW 9TH ST	Gumbo Limbo	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 9TH ST	Orange Geiger	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Stubs with Sprouts
SW 9TH ST	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)		Reduced Canopy - Major	Strap Constricting Tree	
SW 9TH ST	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)		Reduced Canopy - Major	Strap Constricting Tree	
SW 9TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 9TH ST	Weeping Fig	16-20"	Yes	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 9TH ST	Weeping Fig	11-15"	Yes	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 9TH ST	Royal Poinciana	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Major	Over Pruned	
SW 9TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Limb Damage - Moderate	Reduced Canopy - Moderate	
SW 9TH ST	Areca Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 9TH ST	Pink Tabebuia	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Stubs with Sprouts
SW 9TH ST	Washington Palm	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 9TH ST	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)		Reduced Canopy - Major	Strap Constricting Tree	
SW 9TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Reduced Canopy - Minor	
SW 9TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 9TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 9TH ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)		Restricted Canopy		
SW 9TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 9TH ST	Dracaena sp.	6-10"	Yes	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Stubs with Sprouts	Restricted Canopy
SW 9TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 9TH ST	Peacock Flower	1-5"	No	10'	Poor (21% to 40%)		Topped	Stubs with Sprouts	Decay Observed
SW 9TH ST	Peacock Flower	6-10"	Yes	10'	Poor (21% to 40%)		Topped	Stubs with Sprouts	Decay Observed
SW 9TH ST	Indian Laurel Fig	31-40"	No	60'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Minor	Stubs with Sprouts
SW 9TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 9TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Reduced Canopy - Minor	Sprouting
SW 9TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Reduced Canopy - Minor	Sprouting
SW 9TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Reduced Canopy - Minor	Sprouting
SW 9TH ST	Dracaena sp.	11-15"	Yes	15'	Good (61% to 80%)		Restricted Canopy	Trunk Damage - Minor	
SW 9TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Leaning - Moderate	Restricted Canopy	
SW 9TH ST	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)		Reduced Canopy - Major	Strap Constricting Tree	
SW 9TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 9TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 9TH ST	Umbrella Tree	1-5"	No	5'	Good (61% to 80%)				
SW 9TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 9TH ST	Peacock Flower	1-5"	Yes	15'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs	
SW 9TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 9th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 9TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	
SW 9TH ST	Golden Shower Tree	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Broken Branches
SW 9TH ST	Golden Shower Tree	21-30"	No	30'	Fair (41% to 60%)		Seasonal Defoliation/Discolored Foliage	Lopsided/Reduced Canopy - Moderate	Reduced Canopy - Moderate
SW 9TH ST	Golden Shower Tree	16-20"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 9TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				

SW 10th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 10TH ST	Pongam	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Codominant Leaders - Multi
SW 10TH ST	Brazilian Beauty Leaf	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Lopsided/Reduced Canopy - Moderate	Dead Wood
SW 10TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Leaning - Moderate
SW 10TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 10TH ST	Japanese Privet	16-20"	No	45'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 10TH ST	Dracaena sp.	6-10"	Yes	15'	Good (61% to 80%)				
SW 10TH ST	Dracaena sp.	6-10"	Yes	15'	Good (61% to 80%)				
SW 10TH ST	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Leaning - Moderate	Codominant Leaders - Multi
SW 10TH ST	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 10TH ST	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 10TH ST	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Lifting
SW 10TH ST	Brazilian Beauty Leaf	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Stubs	
SW 10TH ST	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 10TH ST	Brazilian Beauty Leaf	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 10TH ST	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 10TH ST	Brazilian Beauty Leaf	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 10TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders - Multi
SW 10TH ST	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Cavities	Crown Density - Low
SW 10TH ST	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Decay Observed	Crown Density - Low
SW 10TH ST	Weeping Fig	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Lifting	Decay Observed
SW 10TH ST	Brazilian Beauty Leaf	16-20"	No	35'	Good (61% to 80%)		Constricted Roots	Sprouting	
SW 10TH ST	Rubber Tree	16-20"	No	25'	Poor (21% to 40%)		Decay Observed	Leaning - Moderate	Reduced Canopy - Major
SW 10TH ST	Rubber Tree	21-30"	No	40'	Fair (41% to 60%)		Cavities	Stubs with Sprouts	Reduced Canopy - Moderate
SW 10TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 10TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 10TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders - Multi
SW 10TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 10TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 10TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 10TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Montgomery Palm	1-5"	Yes	15'	Good (61% to 80%)				
SW 10TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 10TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 10TH ST	Brazilian Beauty Leaf	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Cavities	Lopsided/Reduced Canopy - Moderate
SW 10TH ST	Brazilian Beauty Leaf	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 10TH ST	Tropical Almond	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Strap Constricting Tree	Trunk Damage - Moderate
SW 10TH ST	Brazilian Beauty Leaf	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 10TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Moderate		
SW 10TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Broken Branches	
SW 10TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 10TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 10TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		

(Continued on Next Page)

Street Tree Inventory

SW 10th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 10TH ST	African Tulip Tree	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 10TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	16-20"	No	30'	Good (61% to 80%)		Constricted Roots	Codominant Leaders - Multi	Sprouting
SW 10TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 10TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Lifting
SW 10TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 10TH ST	Frangipani	1-5"	No	10'	Fair (41% to 60%)		Root Flair - None	Codominant Leaders/Included Bark	Trunk Damage - Moderate
SW 10TH ST	Mimosa/Silk Tree	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 10TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Leaning - Minor	Trunk Damage - Moderate	
SW 10TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Leaning - Minor		
SW 10TH ST	Rubber Tree	21-30"	No	35'	Fair (41% to 60%)		Cavities	Limb Damage - Moderate	Over Extended Limb(s)
SW 10TH ST	Brazilian Beauty Leaf	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Cavities	Codominant Leaders - Multi
SW 10TH ST	Brazilian Beauty Leaf	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Cavities	Codominant Leaders - Multi
SW 10TH ST	Weeping Fig	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 10TH ST	Brazilian Beauty Leaf	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Over Extended Limb(s)	Codominant Leaders/No Included Bark
SW 10TH ST	Brazilian Beauty Leaf	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Lifting
SW 10TH ST	Brazilian Beauty Leaf	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Leaning - Moderate
SW 10TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Java Bishopwood	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 10TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Live Oak	1-5"	No	15'	Good (61% to 80%)				
SW 10TH ST	Live Oak	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 10TH ST	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Broken Branches	Codominant Leaders - Multi
SW 10TH ST	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Montgomery Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Live Oak	11-15"	No	35'	Good (61% to 80%)		Reduced Canopy - Moderate	Dead Wood	
SW 10TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 10TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 10TH ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Cavities
SW 10TH ST	Horseradish Tree	6-10"	Yes	15'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 10TH ST	Pongam	21-30"	No	15'	Very Poor/Critical (6% to 20%)		Constricted Roots	Decay Observed	Dead Wood
SW 10TH ST	Pongam	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Codominant Leaders/Included Bark
SW 10TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 10TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 10TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Fungus on Leaves		
SW 10TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Fungus on Leaves		
SW 10TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Cabbage Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Plunged		
SW 10TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched	Plunged	
SW 10TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched	Plunged	
SW 10TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched	Plunged	
SW 10TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched	Plunged	

(Continued on Next Page)

Street Tree Inventory

SW 10th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 10TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 10TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 10TH ST	Green Buttonwood	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Topped	Stubs with Sprouts
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy	Topped	Stubs with Sprouts
SW 10TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 10TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Stubs
SW 10TH ST	Christmas Palm	11-15"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 10TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 10TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 10TH ST	Green Buttonwood	6-10"	No	10'	Good (61% to 80%)				
SW 10TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Girdling Roots	Topped	Stubs with Sprouts
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 10TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 10TH ST	Gumbo Limbo	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Stubs with Sprouts	Decay Observed
SW 10TH ST	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 10TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Limb Damage - Moderate
SW 10TH ST	Gumbo Limbo	16-20"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 10TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 10TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 10TH ST	Tropical Almond	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 10TH ST	Pink Tabebuia	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 10TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 10TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 10TH ST	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 10TH ST	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Major		
SW 10TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Seaside Mahoe	1-5"	No	15'	Good (61% to 80%)				
SW 10TH ST	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 10TH ST	Royal Poinciana	1-5"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 10TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 10TH ST	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 10TH ST	Gumbo Limbo	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Lifting
SW 10TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 10TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 10TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 10TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 10TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Fungus on Leaves	
SW 10TH ST	Spindle Palm	16-20"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Fungus on Leaves	
SW 10TH ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Fungus on Leaves	
SW 10TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 10th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 10TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 10TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Mahogany	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	
SW 10TH ST	Spanish Lime	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts
SW 10TH ST	Green Buttonwood	6-10"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Over Extended Limb(s)	
SW 10TH ST	Green Buttonwood	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Minor	Broken Branches	
SW 10TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 10TH ST	Gumbo Limbo	11-15"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 10TH ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	Stubs with Sprouts
SW 10TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 10TH ST	Green Buttonwood	6-10"	No	25'	Good (61% to 80%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 10TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 10TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 10TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 10TH ST	Live Oak	41-50"	No	70'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders - Multi	Dead Wood
SW 10TH ST	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 10TH ST	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST	Sacred Fig	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 10TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 10TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 10TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 10TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Bottle Palm	11-15"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 10TH ST	Bottle Palm	11-15"	No	Negligible	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Discolored Foliage	
SW 10TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 10TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 10TH ST	Glaucous Cassia	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Major	Stubs with Sprouts	
SW 10TH ST	Green Buttonwood	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 10TH ST	Green Buttonwood	21-30"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders - Multi
SW 10TH ST	Frangipani	11-15"	Yes	20'	Good (61% to 80%)		Stubs with Sprouts	Decay Observed	
SW 10TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Lifting
SW 10TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Restricted Canopy
SW 10TH ST	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Lifting
SW 10TH ST	Bottle Palm	1-5"	No	Negligible	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 10TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 10th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 10TH ST	Royal Poinciana	11-15"	No	25'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate	Over Extended Limb(s)
SW 10TH ST	Weeping Fig	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Stubs with Sprouts	Decay Observed
SW 10TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 10TH ST	Frangipani	1-5"	Yes	5'	Good (61% to 80%)		Insect Damage Leaves		
SW 10TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	
SW 10TH ST	Areca Palm	1-5"	Yes	10'	Fair (41% to 60%)				
SW 10TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 10TH ST	Weeping Fig	16-20"	No	35'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Restricted Canopy	Decay Observed
SW 10TH ST	Mahogany	16-20"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 10TH ST	Umbrella Tree	21-30"	No	25'	Very Poor/Critical (6% to 20%)		Basal Co-Dominant	Cavities	Leaning - Major
SW 10TH ST	Cabbage Palm	11-15"	No	15'	Fair (41% to 60%)		Girdling Roots	Restricted Canopy	Trunk Damage - Moderate
SW 10TH ST	Weeping Fig	16-20"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Lifting	Codominant Leaders - Multi
SW 10TH ST	Weeping Fig	16-20"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Lifting	Codominant Leaders - Multi
SW 10TH ST	Yellow Poinciana	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders - Multi
SW 10TH ST	Weeping Fig	6-10"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Lifting
SW 10TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Cavities	Codominant Leaders - Multi
SW 10TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST	Yellow Poinciana	11-15"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Trunk Damage - Minor
SW 10TH ST	Weeping Fig	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Over Extended Limb(s)
SW 10TH ST	Weeping Fig	6-10"	No	10'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Restricted Canopy	Lifting
SW 10TH ST	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Lifting
SW 10TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 10TH ST	Royal Poinciana	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Moderate	Decay Observed
SW 10TH ST	Royal Poinciana	11-15"	No	10'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Cavities	Crown Density - Low
SW 10TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 10TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 10TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 10TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor	Leaning - Moderate	Restricted Canopy
SW 10TH ST	Mahogany	11-15"	No	35'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 10TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 10TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Leaning - Moderate	Restricted Canopy	
SW 10TH ST	Christmas Palm	1-5"		5'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"		5'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"		5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 10TH ST	Christmas Palm	1-5"		5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 10TH ST	Mahogany	21-30"		40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 10TH ST	Royal Poinciana	16-20"		45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 10TH ST	Mango	21-30"		50'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Restricted Canopy
SW 10TH ST	Mango	21-30"		45'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Restricted Canopy
SW 10TH ST	Royal Poinciana	16-20"		40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Restricted Canopy
SW 10TH ST	Carrotwood	1-5"		20'	Good (61% to 80%)				
SW 10TH ST	Live Oak	31-40"		95'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Over Extended Limb(s)
SW 10TH ST	Christmas Palm	6-10"		10'	Good (61% to 80%)		Leaning - Moderate		
SW 10TH ST	Christmas Palm	1-5"		10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"		10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 10TH ST	Christmas Palm	1-5"		10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 10TH ST	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 10TH ST	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 10TH ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 10TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi

(Continued on Next Page)

Street Tree Inventory

SW 10th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 10TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 10TH ST	Strangler Fig	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage
SW 10TH ST	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Moderate
SW 10TH ST	Frangipani	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy	Seasonal Defoliation/Discolored Foliage	Reduced Canopy - Minor
SW 10TH ST	Frangipani	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage	
SW 10TH ST	Frangipani	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage	Trunk Damage - Moderate
SW 10TH ST	Frangipani	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage	
SW 10TH ST	Unidentified Dead Tree (Defoliated)	6-10"	No	Negligible	Dead (0% to 5%)				
SW 10TH ST	Mango	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Codominant Leaders/Included Bark	
SW 10TH ST	Mango	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 10TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Fungus on Leaves	
SW 10TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Trunk Damage - Minor	
SW 10TH ST	Norfolk Pine	1-5"	Yes	5'	Good (61% to 80%)				
SW 10TH ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 10TH ST	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Reduced Canopy - Minor	
SW 10TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 10TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 10TH ST	Yellow Tabebuia	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Minor
SW 10TH ST	Pink Tabebuia	6-10"	No	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Decay Observed	Discolored Foliage
SW 10TH ST	African Tulip Tree	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate
SW 10TH ST	Weeping Fig	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 10TH ST	Weeping Fig	21-30"	No	55'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed

Streets



Looking NW - SW 9th Street




Looking East - SW 14th Avenue



Looking West - SW 12th Avenue



Looking SW - SW 22nd Avenue



Looking West - SW 15th Avenue



Looking West - SW 25th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 10th Street Road	2	Shenandoah North	4	75	850	Yes, 10ft	No	Yes	2	City	Yes	Yes	4	yes	yes	no	Median between 8th and 10th Street
SW 11th Street	2	Shenandoah North	4	50-60	7,100	No	No	Yes, East of 19th Ave	2	City	Yes	Yes	7	some	yes	north side b/t 27th and 24th Ave	ROW 60' btw 14th and 19th Ave. Grass, gravel, and paved swales

SW 10th Street Road

TYPOLOGY F

SW 11th Street

TYPOLOGY C & D

Street Tree Inventory

SW 10th Street Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 10TH ST RD	Crepe Myrtle	6-10"	Yes	15'	Good (61% to 80%)		Insect Damage Leaves		
SW 10TH ST RD	Purple Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Crown Density - Low	Strap Constricting Tree
SW 10TH ST RD	Purple Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Crown Density - Low	Strap Constricting Tree
SW 10TH ST RD	Carrotwood	6-10"	No	25'	Good (61% to 80%)		Leader - Broken		
SW 10TH ST RD	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST RD	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST RD	Java Plum	11-15"	No	5'	Poor (21% to 40%)		Topped	Stubs with Sprouts	Reduced Canopy - Major
SW 10TH ST RD	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST RD	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 10TH ST RD	Royal Poinciana	6-10"	No	20'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Decay Observed
SW 10TH ST RD	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 10TH ST RD	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST RD	Royal Poinciana	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders - Multi
SW 10TH ST RD	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 10TH ST RD	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST RD	Yellow Poinciana	11-15"	No	35'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 10TH ST RD	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 10TH ST RD	Gumbo Limbo	6-10"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Suppressed Canopy	Over Extended Limb(s)
SW 10TH ST RD	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 10TH ST RD	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 10TH ST RD	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Reduced Canopy - Major	Restricted Canopy	
SW 10TH ST RD	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Reduced Canopy - Major	Restricted Canopy	
SW 10TH ST RD	Satin Leaf	6-10"	No	20'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Lopsided/Reduced Canopy - Major	Crown Density - Very Low	
SW 10TH ST RD	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 10TH ST RD	Gumbo Limbo	1-5"	No	10'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Lopsided/Reduced Canopy - Major	Suppressed Canopy	Crown Density - Low
SW 10TH ST RD	Gumbo Limbo	1-5"	No	15'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Lopsided/Reduced Canopy - Major	Suppressed Canopy	Crown Density - Low
SW 10TH ST RD	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Restricted Canopy
SW 10TH ST RD	Mahogany	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	Restricted Canopy
SW 10TH ST RD	Gumbo Limbo	1-5"	No	20'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST RD	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST RD	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Utility Pruned	
SW 10TH ST RD	Spindle Palm	11-15"	No	5'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Discolored Foliage	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 10TH ST RD	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST RD	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST RD	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	Utility Pruned
SW 10TH ST RD	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST RD	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST RD	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST RD	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 10TH ST RD	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Constricted Roots
SW 10TH ST RD	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Suppressed Canopy	Stubs with Sprouts
SW 10TH ST RD	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 10TH ST RD	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST RD	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST RD	Live Oak	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		

Street Tree Inventory

SW 11th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH ST	Black Olive	31-40"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Cavities	Lopsided/Reduced Canopy - Major
SW 11TH ST	Black Olive	16-20"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 11TH ST	Java Bishopwood	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 11TH ST	Java Bishopwood	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 11TH ST	Green Buttonwood	11-15"	Yes	10'	Poor (21% to 40%)	Utility Line Conflict	Topped	Sprouting	
SW 11TH ST	Green Buttonwood	11-15"	Yes	10'	Poor (21% to 40%)	Utility Line Conflict	Topped	Sprouting	Decay Observed
SW 11TH ST	Green Buttonwood	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Leaning - Moderate	Lopsided/Reduced Canopy - Major
SW 11TH ST	Frangipani	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Sprouting	Decay Observed
SW 11TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 11TH ST	Green Buttonwood	11-15"	No	25'	Good (61% to 80%)		Limb Damage - Moderate	Sprouting	
SW 11TH ST	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Improperly Mulched	Root Flair - None	Reduced Canopy - Minor
SW 11TH ST	Strangler Fig	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 11TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Trunk Damage - Minor	Decay Observed	Codominant Leaders/Included Bark
SW 11TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 11TH ST	Green Buttonwood	11-15"	No	20'	Good (61% to 80%)		Sprouting		
SW 11TH ST	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 11TH ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)		Codominant Leaders - Multi	Topped	Sprouting
SW 11TH ST	Green Buttonwood	16-20"	No	35'	Good (61% to 80%)		Codominant Leaders - Multi	Reduced Canopy - Moderate	
SW 11TH ST	Strangler Fig	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 11TH ST	Strangler Fig	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 11TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Broken Branches	Dead Wood
SW 11TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Sprouting	Improperly Mulched	
SW 11TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Improperly Mulched	
SW 11TH ST	Strangler Fig	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Cavities	Decay Observed
SW 11TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Lifting	Strap Constricting Tree	
SW 11TH ST	Strangler Fig	31-40"	No	60'	Fair (41% to 60%)		Decay Observed	Codominant Leaders/Included Bark	Improperly Mulched
SW 11TH ST	Strangler Fig	31-40"	No	60'	Fair (41% to 60%)		Cavities	Decay Observed	
SW 11TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH ST	Glaucous Cassia	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH ST	Glaucous Cassia	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH ST	Sacred Fig	41-50"	No	60'	Poor (21% to 40%)		Constricted Roots	Cavities	Codominant Leaders - Multi
SW 11TH ST	Weeping Fig	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Broken Branches	
SW 11TH ST	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH ST	Mahogany	6-10"	No	25'	Good (61% to 80%)		Stubs	Desiccated Foliage	
SW 11TH ST	Strangler Fig	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Cavities	Reduced Canopy - Moderate
SW 11TH ST	Strangler Fig	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Cavities	Reduced Canopy - Major
SW 11TH ST	Strangler Fig	51-60"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 11TH ST	Pigeon Plum	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Sprouting	
SW 11TH ST	Green Buttonwood	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH ST	Date Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 11TH ST	Sapodilla	11-15"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Trunk Damage - Moderate	
SW 11TH ST	Green Buttonwood	11-15"	No	25'	Good (61% to 80%)		Strap Constricting Tree	Broken Branches	Basal Co-Dominant
SW 11TH ST	Mahogany	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Reduced Canopy - Minor	
SW 11TH ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Girdling Roots	Topped	Reduced Canopy - Moderate
SW 11TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Suppressed Canopy	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 11TH ST	Royal Poinciana	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 11TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy		
SW 11TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 11th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH ST	Frangipani	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Basal Co-Dominant	Crown Density - Very Low	Insect Damage Leaves
SW 11TH ST	Tropical Almond	6-10"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Codominant Leaders - Multi
SW 11TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 11TH ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Lifting
SW 11TH ST	Yellow Tabebuia	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 11TH ST	Yellow Tabebuia	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 11TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Reduced Canopy - Moderate
SW 11TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Reduced Canopy - Moderate
SW 11TH ST	Coconut Palm	11-15"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Gumbo Limbo	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	Reduced Canopy - Moderate
SW 11TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Suppressed Canopy	
SW 11TH ST	Mahogany	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Lifting
SW 11TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 11TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Mango	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Topped	Stubs with Sprouts
SW 11TH ST	Mango	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Leaning - Moderate	Stubs with Sprouts
SW 11TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 11TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 11TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 11TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 11TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 11TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 11TH ST	Strangler Fig	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Restricted Canopy	Constricted Roots
SW 11TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 11TH ST	Royal Poinciana	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 11TH ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 11TH ST	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 11TH ST	Starburst Clerodendron	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 11TH ST	Starburst Clerodendron	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Restricted Canopy
SW 11TH ST	Starburst Clerodendron	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Stubs with Sprouts	
SW 11TH ST	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy	Stubs with Sprouts	
SW 11TH ST	Starburst Clerodendron	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Stubs with Sprouts	
SW 11TH ST	Black Olive	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Utility Pruned
SW 11TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Trunk Damage - Minor	
SW 11TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 11TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 11TH ST	Royal Poinciana	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 11TH ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 11TH ST	Areca Palm	16-20"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 11TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 11th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH ST	Royal Poinciana	1-5"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Over Extended Limb(s)	
SW 11TH ST	Royal Poinciana	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Queen Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Discolored Foliage	
SW 11TH ST	Mahogany	51-60"	No	60'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 11TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 11TH ST	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Cavities	Ficus Growing on Tree	
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 11TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	11-15"	Yes	20'	Good (61% to 80%)				
SW 11TH ST	Coconut Palm	16-20"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	
SW 11TH ST	Royal Poinciana	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Cavities	Stubs with Sprouts
SW 11TH ST	Weeping Fig	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Crown Density - Low	Lifting
SW 11TH ST	Weeping Fig	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Crown Density - Low	Lifting
SW 11TH ST	Gumbo Limbo	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 11TH ST	Gumbo Limbo	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 11TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 11TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Suppressed Canopy	
SW 11TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 11TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Gumbo Limbo	6-10"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Restricted Canopy
SW 11TH ST	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 11TH ST	Areca Palm	16-20"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 11TH ST	Yellow Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Codominant Leaders/Included Bark
SW 11TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 11TH ST	Carrotwood	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 11TH ST	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Suppressed Canopy	
SW 11TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Suppressed Canopy	
SW 11TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH ST	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Gumbo Limbo	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 11TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 11TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 11TH ST	Gumbo Limbo	11-15"	No	25'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Limb Damage - Major	
SW 11TH ST	Christmas Palm	11-15"	No	15'	Good (61% to 80%)				
SW 11TH ST	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 11TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 11TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 11TH ST	Royal Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Live Oak	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Limb Damage - Major	Stubs with Sprouts
SW 11TH ST	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs	
SW 11TH ST	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Date Palm	16-20"	No	20'	Good (61% to 80%)				
SW 11TH ST	Date Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 11TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Live Oak	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		

(Continued on Next Page)

Street Tree Inventory

SW 11th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH ST	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 11TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 11TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 11TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Tapered Trunk	Improperly Mulched	
SW 11TH ST	Gumbo Limbo	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	
SW 11TH ST	Gumbo Limbo	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	
SW 11TH ST	Gumbo Limbo	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 11TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 11TH ST	Live Oak	16-20"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 11TH ST	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 11TH ST	Live Oak	6-10"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 11TH ST	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders - Multi
SW 11TH ST	Gumbo Limbo	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 11TH ST	Hong Kong Orchid	16-20"	No	25'	Poor (21% to 40%)		Basal Co-Dominant	Lopsided/Reduced Canopy - Major	Restricted Canopy
SW 11TH ST	Gumbo Limbo	11-15"	No	25'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Restricted Canopy	Stubs with Sprouts
SW 11TH ST	Orange Geiger	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Restricted Canopy	Codominant Leaders/Included Bark
SW 11TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH ST	Windmill Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Royal Poinciana	21-30"	No	60'	Poor (21% to 40%)		Root Damage/Decay	Reduced Canopy - Moderate	Stubs with Sprouts
SW 11TH ST	Royal Poinciana	31-40"	No	50'	Poor (21% to 40%)		Reduced Canopy - Major	Limb Damage - Moderate	Codominant Leaders - Multi
SW 11TH ST	Christmas Palm	21-30"	Yes	20'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	31-40"	Yes	25'	Fair (41% to 60%)		Restricted Canopy		
SW 11TH ST	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 11TH ST	Areca Palm	11-15"	No	25'	Poor (21% to 40%)		Reduced Canopy - Major	Topped	Stubs with Sprouts
SW 11TH ST	Live Oak	11-15"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Live Oak	11-15"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Areca Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 11TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)				
SW 11TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 11TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Minor	Nutrient Deficiency	Leaning - Minor
SW 11TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Trunk Damage - Minor	Nutrient Deficiency	
SW 11TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Reduced Canopy - Moderate	Nutrient Deficiency
SW 11TH ST	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)				
SW 11TH ST	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Strap Constricting Tree	Reduced Canopy - Moderate
SW 11TH ST	Mahogany	11-15"	No	35'	Good (61% to 80%)		Trunk Damage - Minor	Reduced Canopy - Minor	
SW 11TH ST	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH ST	Pongam	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Stubs with Sprouts	
SW 11TH ST	Florida Thatch Palm	6-10"	No	5'	Good (61% to 80%)				
SW 11TH ST	Orange Geiger	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Minor	Restricted Canopy	
SW 11TH ST	Mahogany	11-15"	No	35'	Good (61% to 80%)				
SW 11TH ST	Weeping Fig	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 11TH ST	Weeping Fig	6-10"	No	25'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	

(Continued on Next Page)

Street Tree Inventory

SW 11th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH ST	Live Oak	21-30"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Crown Density - Moderate
SW 11TH ST	Live Oak	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 11TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 11TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 11TH ST	Oriental Arborvitae	6-10"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	
SW 11TH ST	Oriental Arborvitae	6-10"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	
SW 11TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 11TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 11TH ST	Oriental Arborvitae	16-20"	No	20'	Fair (41% to 60%)		Lifting	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 11TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	
SW 11TH ST	Crepe Myrtle	6-10"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	Reduced Canopy - Moderate
SW 11TH ST	Weeping Fig	21-30"	No	25'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Decay Observed
SW 11TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)		Damaged Fronds		
SW 11TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 11TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	
SW 11TH ST	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	
SW 11TH ST	Mahogany	6-10"	No	30'	Good (61% to 80%)				
SW 11TH ST	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 11TH ST	Mahogany	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Decay Observed
SW 11TH ST	Mahogany	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Limb Damage - Moderate
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 11TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Limb Damage - Major	Reduced Canopy - Moderate	
SW 11TH ST	Weeping Fig	11-15"	No	40'	Poor (21% to 40%)		Reduced Canopy - Moderate	Decay Observed	Stubs with Sprouts
SW 11TH ST	Weeping Fig	6-10"	No	25'	Poor (21% to 40%)		Reduced Canopy - Moderate	Decay Observed	Suppressed Canopy
SW 11TH ST	Weeping Fig	11-15"	No	25'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Decay Observed	Suppressed Canopy
SW 11TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 11TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 11TH ST	Unidentified Dead Tree (Defoliated)	1-5"	No	Negligible	Dead (0% to 5%)				
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 11TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate	Limb Damage - Minor	
SW 11TH ST	Red Bay	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 11TH ST	Norfolk Pine	6-10"	Yes	10'	Fair (41% to 60%)		Pruned Into Shrub	Desiccated Foliage	
SW 11TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 11TH ST	Gumbo Limbo	11-15"	No	35'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 11TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 11TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH ST	Oriental Arborvitae	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Lifting	Stubs with Sprouts
SW 11TH ST	Norfolk Pine	21-30"	No	25'	Fair (41% to 60%)		Basal Co-Dominant		
SW 11TH ST	Tamarind	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Restricted Canopy
SW 11TH ST	Norfolk Pine	31-40"	No	25'	Fair (41% to 60%)		Basal Co-Dominant	Restricted Canopy	
SW 11TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH ST	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 11TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)		Root Damage/Decay	Reduced Canopy - Moderate	Stubs with Sprouts
SW 11TH ST	Powderpuff Tree	6-10"	No	25'	Fair (41% to 60%)		Suppressed Canopy	Suppressed Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 11th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Codominant Leaders/Included Bark
SW 11TH ST	Brazilian Beauty Leaf	6-10"	No	20'	Poor (21% to 40%)		Suppressed Canopy	Topped	Stubs with Sprouts
SW 11TH ST	Pygmy Date Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 11TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 11TH ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	
SW 11TH ST	Royal Poinciana	11-15"	No	40'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 11TH ST	Starburst Clerodendron	6-10"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Stubs with Sprouts
SW 11TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Leaning - Moderate	Nutrient Deficiency	
SW 11TH ST	Starburst Clerodendron	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	Broken Branches
SW 11TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Tapered Trunk	Leaning - Minor	Nutrient Deficiency
SW 11TH ST	Coconut Palm	11-15"	No	20'	Poor (21% to 40%)		Tapered Trunk	Damaged Fronds	Reduced Canopy - Moderate
SW 11TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 11TH ST	Coconut Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 11TH ST	Washington Palm	16-20"	No	20'	Good (61% to 80%)				

Streets | Terraces



Looking West - SW 23rd Avenue



Looking East - SW 19th Avenue



Looking West - SW 25th Avenue




Looking West - SW 20th Avenue



Looking West - SW 16th Avenue



Looking West - SW 14th Avenue



Looking West - SW 12th Avenue



Looking East - SW 14th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 11th Terrace	2	Shenandoah North	4	50-70	4,500	No	No	Yes, East of 19th Ave	2	City	Yes	Yes	7 (20 W of 22nd Ave)	East of 19th Ave	yes	north side b/t 22nd and 17th Ave	ROW 70' btw 22nd and 24th Avenue (large swales). No sidewalk on southside b/t 22nd Ave and 21st Ave
SW 12th Street	2	Shenandoah North	4	50	7,600	No	No	Mostly	2	City	Yes	Yes	6 (11 W of 22nd Ave)	some	yes	southside b/t 21st and 19th Ave and 14th and 12th Ave	No Street Parking between 19th and 22nd Avenue.

SW 11th Terrace

TYPOLOGY B & A & D

SW 12th Street

TYPOLOGY B & A & D

Street Tree Inventory

SW 11th Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH TER	Strangler Fig	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	
SW 11TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 11TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH TER	Golden Shower Tree	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH TER	Weeping Fig	1-5"	No	10'	Good (61% to 80%)				
SW 11TH TER	Gumbo Limbo	21-30"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Dead Wood
SW 11TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH TER	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major		
SW 11TH TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Insect Damage Leaves	Discolored Foliage	Broken Branches
SW 11TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	White Fly	
SW 11TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting		
SW 11TH TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched		
SW 11TH TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched		
SW 11TH TER	Mahogany	6-10"	No	20'	Good (61% to 80%)				
SW 11TH TER	Mahogany	6-10"	No	20'	Good (61% to 80%)				
SW 11TH TER	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 11TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 11TH TER	Areca Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 11TH TER	Royal Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH TER	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Cavities	Reduced Canopy - Moderate
SW 11TH TER	Norfolk Pine	21-30"	No	30'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Reduced Canopy - Moderate	Reduced Canopy - Moderate
SW 11TH TER	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Reduced Canopy - Moderate	Cavities
SW 11TH TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Topped	Lopsided/Reduced Canopy - Major	Suppressed Canopy
SW 11TH TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Stubs with Sprouts	Insect Damage Leaves
SW 11TH TER	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Dead Wood	
SW 11TH TER	Lancewood	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Lifting	Codominant Leaders - Multi
SW 11TH TER	Live Oak	6-10"	No	30'	Good (61% to 80%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 11TH TER	Strangler Fig	11-15"	No	40'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 11TH TER	Silk Floss Tree	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	Crown Density - Low
SW 11TH TER	Royal Poinciana	21-30"	No	35'	Fair (41% to 60%)		Reduced Canopy - Major	Codominant Leaders - Multi	Decay Observed
SW 11TH TER	Pongam	21-30"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Decay Observed
SW 11TH TER	Mahogany	11-15"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 11TH TER	Mango	21-30"	No	20'	Poor (21% to 40%)		Topped	Sprouting	Decay Observed
SW 11TH TER	Melaleuca	21-30"	No	20'	Poor (21% to 40%)		Topped	Sprouting	Crown Density - Low
SW 11TH TER	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 11TH TER	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 11TH TER	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Insect Damage Leaves	
SW 11TH TER	Glaucous Cassia	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched		
SW 11TH TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Broken Branches		
SW 11TH TER	Weeping Fig	11-15"	No	15'	Fair (41% to 60%)		Decay Observed	Reduced Canopy - Moderate	Lifting
SW 11TH TER	Japanese Fern Tree	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Major	Stubs with Sprouts	Reduced Canopy - Moderate
SW 11TH TER	Weeping Fig	11-15"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 11TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 11TH TER	Mahogany	11-15"	No	40'	Good (61% to 80%)		Reduced Canopy - Minor	Trunk Damage - Minor	
SW 11TH TER	Bottlebrush	6-10"	No	10'	Poor (21% to 40%)		Trunk Damage - Major	Root Damage/Decay	Suppressed Canopy
SW 11TH TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 11TH TER	Mahogany	11-15"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate	Trunk Damage - Minor	

(Continued on Next Page)

Street Tree Inventory

SW 11th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH TER	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Trunk Damage - Minor
SW 11TH TER	Mahogany	11-15"	No	35'	Good (61% to 80%)		Reduced Canopy - Moderate	Trunk Damage - Minor	
SW 11TH TER	Mahogany	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Lifting	
SW 11TH TER	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Lifting	Stubs with Sprouts
SW 11TH TER	Hong Kong Orchid	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Suppressed Canopy	Leaning - Moderate
SW 11TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 11TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 11TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 11TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 11TH TER	Royal Palm	16-20"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Tapered Trunk	
SW 11TH TER	Mango	16-20"	No	30'	Poor (21% to 40%)		Cavities	Stubs with Sprouts	Reduced Canopy - Moderate
SW 11TH TER	Mango	16-20"	No	30'	Fair (41% to 60%)		Stubs with Sprouts	Decay Observed	
SW 11TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 11TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 11TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 11TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH TER	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 11TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 11TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH TER	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Minor		
SW 11TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH TER	Solitaire Palm	6-10"	Yes	15'	Fair (41% to 60%)		Discolored Foliage		
SW 11TH TER	Spindle Palm	11-15"	No	Negligible	Dead (0% to 5%)				
SW 11TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH TER	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 11TH TER	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 11TH TER	Norfolk Pine	21-30"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 11TH TER	Norfolk Pine	21-30"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Crown Density - Moderate
SW 11TH TER	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 11TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 11TH TER	Japanese Privet	6-10"	Yes	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Crown Density - Very Low	Decay Observed
SW 11TH TER	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Trunk Damage - Moderate	Codominant Leaders - Multi
SW 11TH TER	Sea Grape	21-30"	Yes	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Decay Observed	Stubs with Sprouts
SW 11TH TER	Gumbo Limbo	11-15"	Yes	5'	Fair (41% to 60%)		Pruned Into Shrub	Stubs with Sprouts	
SW 11TH TER	Gumbo Limbo	11-15"	Yes	5'	Fair (41% to 60%)		Pruned Into Shrub	Stubs with Sprouts	
SW 11TH TER	Gumbo Limbo	6-10"	Yes	5'	Fair (41% to 60%)		Pruned Into Shrub	Stubs with Sprouts	
SW 11TH TER	Areca Palm	6-10"	Yes	15'	Fair (41% to 60%)		Desiccated Foliage		
SW 11TH TER	Desert Cassia	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH TER	Mahogany	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH TER	Golden Shower Tree	6-10"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 11TH TER	Desert Cassia	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 11TH TER	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Lifting	
SW 11TH TER	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Restricted Canopy
SW 11TH TER	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Restricted Canopy

(Continued on Next Page)

Street Tree Inventory

SW 11th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH TER	Mahogany	11-15"	No	30'	Good (61% to 80%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 11TH TER	Royal Poinciana	1-5"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Limb Damage - Major	
SW 11TH TER	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 11TH TER	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 11TH TER	Japanese Fern Tree	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 11TH TER	Mahogany	16-20"	No	25'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	
SW 11TH TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 11TH TER	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 11TH TER	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 11TH TER	Brazilian Beuty Leaf	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Suppressed Canopy	Reduced Canopy - Moderate
SW 11TH TER	Powderpuff Tree	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 11TH TER	Mahogany	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 11TH TER	Oriental Arborvitae	11-15"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 11TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 11TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 11TH TER	Weeping Fig	16-20"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH TER	Coconut Palm	11-15"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Leaning - Moderate	Nutrient Deficiency
SW 11TH TER	Weeping Fig	11-15"	No	30'	Poor (21% to 40%)		Reduced Canopy - Moderate	Decay Observed	Stubs with Sprouts
SW 11TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH TER	Pink Cassia	1-5"	No	20'	Fair (41% to 60%)		Leader - Bent	Reduced Canopy - Moderate	Broken Branches
SW 11TH TER	Frangipani	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage	Broken Branches
SW 11TH TER	Frangipani	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage	
SW 11TH TER	Frangipani	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage	Decay Observed
SW 11TH TER	Orange Geiger	6-10"	No	30'	Fair (41% to 60%)		Trunk Damage - Major	Reduced Canopy - Moderate	
SW 11TH TER	Bottlebrush	1-5"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 11TH TER	Bottlebrush	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Moderate	Leaning - Moderate	Crown Density - Moderate
SW 11TH TER	Orange Geiger	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 11TH TER	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 11TH TER	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 11TH TER	Royal Poinciana	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Leaning - Moderate
SW 11TH TER	Mahogany	31-40"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Over Extended Limb(s)
SW 11TH TER	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 11TH TER	Mahogany	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Lopsided/Reduced Canopy - Moderate
SW 11TH TER	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 11TH TER	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor	Restricted Canopy	
SW 11TH TER	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor	Restricted Canopy	
SW 11TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 11TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH TER	Hong Kong Orchid	6-10"	No	20'	Fair (41% to 60%)		Strap Constricting Tree	Sooty Mold Present	Reduced Canopy - Moderate
SW 11TH TER	Hong Kong Orchid	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 11TH TER	Hong Kong Orchid	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Sooty Mold Present
SW 11TH TER	Hong Kong Orchid	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs	Sooty Mold Present
SW 11TH TER	Mahogany	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 11TH TER	Mahogany	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 11TH TER	Coconut Palm	11-15"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	Nutrient Deficiency
SW 11TH TER	Coconut Palm	11-15"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	Nutrient Deficiency
SW 11TH TER	Queen Crepe Myrtle	1-5"	No	15'	Fair (41% to 60%)		Leader - Broken	Stubs with Sprouts	Suppressed Canopy
SW 11TH TER	Gumbo Limbo	16-20"	No	40'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 11TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 11TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 11th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Desiccated Foliage	
SW 11TH TER	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Desiccated Foliage	
SW 11TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Desiccated Foliage	
SW 11TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH TER	Weeping Fig	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Cavities	Stubs with Sprouts
SW 11TH TER	Yellow Elder	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 11TH TER	Yellow Elder	1-5"	No	10'	Poor (21% to 40%)		Cracks in Trunk	Strap Constricting Tree	Reduced Canopy - Moderate
SW 11TH TER	Brazilian Beauty Leaf	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 11TH TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 11TH TER	Umbrella Tree	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 11TH TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 11TH TER	Black Olive	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 11TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 11TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 11TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Discolored Foliage		
SW 11TH TER	Satin Leaf	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 11TH TER	Pink Cassia	1-5"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Suppressed Canopy
SW 11TH TER	Coconut Palm	6-10"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 11TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 11TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Trunk Damage - Minor	
SW 11TH TER	Mango	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Restricted Canopy
SW 11TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 11TH TER	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Tapered Trunk	Restricted Canopy	
SW 11TH TER	Mango	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Leader - Broken	
SW 11TH TER	Pink Cassia	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Leaning - Moderate	Seasonal Defoliation/Discolored Foliage
SW 11TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH TER	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Desiccated Foliage		
SW 11TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)				
SW 11TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 11TH TER	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 11TH TER	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 11TH TER	Weeping Fig	11-15"	No	15'	Poor (21% to 40%)		Pruned Into Shrub	Trunk Damage - Major	
SW 11TH TER	Weeping Fig	11-15"	No	15'	Fair (41% to 60%)		Pruned Into Shrub	Trunk Damage - Moderate	
SW 11TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH TER	Lead Tree	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 11TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Minor	
SW 11TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Minor	
SW 11TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Tapered Trunk		
SW 11TH TER	Christmas Palm	6-10"	Yes	10'	Poor (21% to 40%)		Cracks in Trunk		

Street Tree Inventory

SW 12th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH ST	Brazilian Beauty Leaf	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 12TH ST	Brazilian Beauty Leaf	21-30"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 12TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 12TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 12TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 12TH ST	Coconut Palm	6-10"	No	5'	Good (61% to 80%)				
SW 12TH ST	Dracaena sp.	16-20"	No	15'	Good (61% to 80%)		Basal Co-Dominant		
SW 12TH ST	Rubber Tree	6-10"	Yes	10'	Fair (41% to 60%)		Basal Co-Dominant	Topped	
SW 12TH ST	Christmas Palm		No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH ST	Black Olive	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Topped	Sprouting
SW 12TH ST	Black Olive	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Topped	Sprouting
SW 12TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 12TH ST	Pygmy Date Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Moderate	Nutrient Deficiency
SW 12TH ST	Washington Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Black Olive	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Trunk Damage - Moderate
SW 12TH ST	Black Olive	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 12TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Black Olive	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Codominant Leaders - Multi
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Black Olive	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Moderate
SW 12TH ST	Black Olive	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Cavities
SW 12TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Crown Density - Low
SW 12TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 12TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders - Multi
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Black Olive	16-20"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Lifting
SW 12TH ST	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 12TH ST	Papaya	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Black Olive	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Lifting
SW 12TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 12TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 12TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Sprouting
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy		
SW 12TH ST	Royal Poinciana	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Restricted Canopy
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy		
SW 12TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 12th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH ST	Black Olive	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Dead Wood
SW 12TH ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Lifting
SW 12TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 12TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders - Multi
SW 12TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 12TH ST	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)		Suppressed Canopy		
SW 12TH ST	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Weeping Fig	6-10"	No	15'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate	Decay Observed
SW 12TH ST	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 12TH ST	Black Olive	21-30"	No	10'	Very Poor/Critical (6% to 20%)		Topped	Sprouting	Decay Observed
SW 12TH ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 12TH ST	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Trunk Damage - Moderate	
SW 12TH ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 12TH ST	Weeping Fig	16-20"	No	25'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate	
SW 12TH ST	Melaleuca	16-20"	No	10'	Very Poor/Critical (6% to 20%)		Topped	Sprouting	Decay Observed
SW 12TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Reduced Canopy - Major	Limb Damage - Moderate
SW 12TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 12TH ST	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Damaged Fronds	Leaning - Moderate
SW 12TH ST	Black Olive	16-20"	No	55'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Dead Wood
SW 12TH ST	Areca Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Areca Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Crown Density - Low	Broken Branches
SW 12TH ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Lopsided/Reduced Canopy - Moderate	Leaning - Moderate
SW 12TH ST	Live Oak	6-10"	No	25'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	Crown Density - Low
SW 12TH ST	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 12TH ST	Mahogany	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 12TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Limb Damage - Minor		
SW 12TH ST	Mahogany	6-10"	No	25'	Good (61% to 80%)		Trunk Damage - Minor	Codominant Leaders - Multi	
SW 12TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 12TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 12TH ST	Silver Buttonwood	6-10"	No	10'	Fair (41% to 60%)		Topped	Sprouting	
SW 12TH ST	Mahogany	11-15"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	Limb Damage - Minor
SW 12TH ST	Mahogany	11-15"	No	20'	Good (61% to 80%)		Limb Damage - Minor	Codominant Leaders/Included Bark	
SW 12TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Tapered Trunk	Reduced Canopy - Major	
SW 12TH ST	Coconut Palm	16-20"	No	15'	Fair (41% to 60%)			Damaged Fronds	Reduced Canopy - Minor
SW 12TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Discolored Foliage	
SW 12TH ST	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Damaged Fronds	Discolored Foliage
SW 12TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 12th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Restricted Canopy
SW 12TH ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Leaning - Moderate
SW 12TH ST	Hong Kong Orchid	21-30"	No	30'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	Decay Observed
SW 12TH ST	Live Oak	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 12TH ST	Christmas Palm	11-15"	Yes	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 12TH ST	Sapodilla	11-15"	No	20'	Fair (41% to 60%)		Suppressed Canopy	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 12TH ST	Royal Poinciana	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Royal Poinciana	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Reduced Canopy - Moderate	
SW 12TH ST	Spindle Palm	11-15"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Desiccated Foliage	Disease
SW 12TH ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 12TH ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 12TH ST	Queen Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Carrotwood	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 12TH ST	Green Buttonwood	6-10"	No	20'	Good (61% to 80%)		Sprouting		
SW 12TH ST	Gumbo Limbo	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Date Palm	21-30"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 12TH ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Sacred Fig	31-40"	No	50'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Stubs with Sprouts	Decay Observed
SW 12TH ST	Sacred Fig	31-40"	No	50'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Moderate	Stubs with Sprouts	Cavities
SW 12TH ST	Weeping Fig	41-50"	No	65'	Poor (21% to 40%)		Reduced Canopy - Major	Crown Density - Low	Over Extended Limb(s)
SW 12TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 12TH ST	Sapodilla	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Lifting	
SW 12TH ST	Coconut Palm	16-20"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Nutrient Deficiency	
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH ST	Umbrella Tree	21-30"	No	25'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Basal Co-Dominant
SW 12TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH ST	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Satin Leaf	1-5"	No	5'	Poor (21% to 40%)		Suppressed Canopy	Reduced Canopy - Major	Dead Wood
SW 12TH ST	Satin Leaf	1-5"	No	5'	Poor (21% to 40%)		Suppressed Canopy	Reduced Canopy - Major	Stubs with Sprouts
SW 12TH ST	Florida Thatch Palm	1-5"	No	15'	Good (61% to 80%)		Suppressed Canopy	Fungus on Leaves	
SW 12TH ST	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Basal Co-Dominant	
SW 12TH ST	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Suppressed Canopy	
SW 12TH ST	Eucalyptus	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 12TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Restricted Canopy
SW 12TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Restricted Canopy
SW 12TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Restricted Canopy
SW 12TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 12TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 12th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Lead Tree	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Carrotwood	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Lifting	Restricted Canopy
SW 12TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Golden Shower Tree	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH ST	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH ST	Yellow Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Yellow Poinciana	16-20"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 12TH ST	Chinese Golden Rain Tree	6-10"	No	25'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Chinese Golden Rain Tree	11-15"	No	30'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 12TH ST	Sea Grape	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Suppressed Canopy
SW 12TH ST	Sea Grape	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Suppressed Canopy
SW 12TH ST	Sea Grape	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Suppressed Canopy
SW 12TH ST	Sea Grape	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Suppressed Canopy
SW 12TH ST	Sea Grape	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Suppressed Canopy
SW 12TH ST	Sea Grape	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Suppressed Canopy
SW 12TH ST	Live Oak	11-15"	No	30'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Restricted Canopy
SW 12TH ST	Live Oak	11-15"	No	15'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Restricted Canopy
SW 12TH ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Mahogany	16-20"	No	35'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Trunk Damage - Minor
SW 12TH ST	Norfolk Pine	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 12TH ST	Umbrella Tree	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Oriental Arborvitae	16-20"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders - Multi	Restricted Canopy
SW 12TH ST	Oriental Arborvitae	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders - Multi	Restricted Canopy
SW 12TH ST	Mahogany	16-20"	No	15'	Very Poor/Critical (6% to 20%)		Lopsided/Reduced Canopy - Major	Trunk Damage - Major	Stubs with Sprouts
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Strangler Fig	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy	Codominant Leaders/Included Bark	
SW 12TH ST	Mahogany	16-20"	No	30'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Limb Damage - Major	Stubs with Sprouts
SW 12TH ST	Mahogany	16-20"	No	45'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Reduced Canopy - Moderate	Strap Constricting Tree
SW 12TH ST	Yellow Tabebuia	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 12TH ST	Coconut Palm	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 12TH ST	Lancepod	1-5"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	
SW 12TH ST	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Lopsided/Reduced Canopy - Moderate	
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 12TH ST	Carrotwood	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Royal Poinciana	1-5"	No	20'	Good (61% to 80%)		Limb Damage - Moderate		
SW 12TH ST	Mahogany	16-20"	No	40'	Poor (21% to 40%)		Reduced Canopy - Major	Lion's Tailing	Over Pruned
SW 12TH ST	Florida Thatch Palm	6-10"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Mango	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Reduced Canopy - Moderate	
SW 12TH ST	Starburst Clerodendron	6-10"	Yes	10'	Fair (41% to 60%)		Stubs with Sprouts	Decay Observed	
SW 12TH ST	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Codominant Leaders - Multi	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Pongam	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH ST	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)		Constricted Roots	Planted in Plastic Container	

(Continued on Next Page)

Street Tree Inventory

SW 12th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH ST	Gumbo Limbo	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 12TH ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH ST	Royal Palm	11-15"	No	20'	Fair (41% to 60%)		Tapered Trunk		
SW 12TH ST	Royal Palm	16-20"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Desiccated Foliage	
SW 12TH ST	Royal Poinciana	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 12TH ST	Mimosa/Silk Tree	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched		
SW 12TH ST	Mahogany	31-40"	No	65'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Trunk Damage - Major
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk		
SW 12TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk	Trunk Damage - Minor	
SW 12TH ST	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk	Trunk Damage - Moderate	
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 12TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Sapodilla	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Major
SW 12TH ST	Oriental Arborvitae	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 12TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 12TH ST	Rubber Tree	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Girdling Roots		
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Norfolk Pine	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 12TH ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 12TH ST	Chinese Golden Rain Tree	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 12TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate		
SW 12TH ST	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)		Stubs with Sprouts		
SW 12TH ST	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)		Stubs with Sprouts		
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 12TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 12TH ST	Oriental Arborvitae	11-15"	Yes	15'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate		
SW 12TH ST	Mahogany	31-40"	No	60'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Lifting
SW 12TH ST	Oriental Arborvitae	11-15"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 12TH ST	Oriental Arborvitae	11-15"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 12TH ST	Oriental Arborvitae	11-15"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 12TH ST	Mahogany	31-40"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Over Extended Limb(s)

(Continued on Next Page)

Street Tree Inventory

SW 12th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Fungus on Leaves		
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Tapered Trunk	Fungus on Leaves	
SW 12TH ST	Unidentified Dead Tree (Defoliated)	6-10"	Yes	Negligible	Dead (0% to 5%)				
SW 12TH ST	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)		Leaning - Moderate		
SW 12TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Discolored Foliage		
SW 12TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Discolored Foliage	Trunk Damage - Moderate	
SW 12TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Mango	21-30"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 12TH ST	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH ST	Montgomery Palm	6-10"	No	15'	Poor (21% to 40%)		Desiccated Foliage	Reduced Canopy - Moderate	
SW 12TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 12TH ST	Pink Tabebuia	11-15"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Leader - Bent	Trunk Damage - Moderate
SW 12TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 12TH ST	Horseflesh Mahogany	1-5"	No	5'	Fair (41% to 60%)		Leader - Broken	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 12TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Trunk Damage - Moderate	Discolored Foliage	
SW 12TH ST	Lychee Tree	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Dead Wood	Leaning - Moderate
SW 12TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Damaged Fronds		
SW 12TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 12TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 12TH ST	ML UNID 6	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Decay Observed
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH ST	Mango	21-30"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 12TH ST	Sapodilla	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 12TH ST	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Restricted Canopy
SW 12TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 12TH ST	Live Oak	1-5"	No	20'	Good (61% to 80%)				
SW 12TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 12TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Limb Damage - Major	Reduced Canopy - Moderate	
SW 12TH ST	Black Olive	11-15"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 12TH ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 12TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 12TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 12TH ST	Black Olive	11-15"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 12TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 12TH ST	Black Olive	21-30"	No	55'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Over Extended Limb(s)
SW 12TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH ST	Live Oak	1-5"	No	25'	Poor (21% to 40%)		Suppressed Canopy	Reduced Canopy - Major	Crown Density - Low
SW 12TH ST	Live Oak	6-10"	No	25'	Poor (21% to 40%)		Suppressed Canopy	Reduced Canopy - Major	Crown Density - Low
SW 12TH ST	Black Olive	6-10"	No	25'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Minor	
SW 12TH ST	Black Olive	11-15"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Limb Damage - Moderate
SW 12TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 12TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 12TH ST	Date Palm	6-10"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 12TH ST	Royal Palm	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 12th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 12TH ST	Frangipani	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 12TH ST	Oriental Arborvitae	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 12TH ST	Oriental Arborvitae	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 12TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Discolored Foliage		
SW 12TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				

Streets



Looking East - SW 27th Street



Looking East - SW 22nd Avenue



Looking East - SW 25th Avenue



Looking West - SW 23rd Avenue



Looking West - SW 12th Court



Looking West - SW 13th Court



Looking East - SW 17th Avenue



Looking East - SW 19th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 13th Street	2	Shenandoah North	4	50-70	7,600	No	No	Mostly	2	City	Yes	Yes	6-9	mostly	yes	north side b/t 13th ct and 12th ave	ROW 70' btw 12th and 14th Ave, 60' btw 19th and 22nd avenue. No Street Parking between 19th and 22nd Avenue. Roundabout at 18th Ave
SW 14th Street	2	Shenandoah North	4	40-60	6,500	No	No	Yes, East of 19th Ave	2	City	Yes	Yes	6 (15 W of 24th Ave)	east of 22nd Ave	yes	north side b/t 25th ave and 22nd ave, southside b/t 13th and 12th Ave	Roundabout at 24th Ave. Grass, paved, and gravel swales west of 22nd Ave and curbed grass swales east of 22nd Ave

SW 13th Street

TYPOLOGY B & D

SW 14th Street

TYPOLOGY B & A & C

Street Tree Inventory

SW 13th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Moderate
SW 13TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Crown Density - Low
SW 13TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 13TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Dead Wood
SW 13TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 13TH ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Crown Density - Low
SW 13TH ST	Mahogany	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Sloughing Bark
SW 13TH ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Topped
SW 13TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Topped
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 13TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 13TH ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 13TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 13TH ST	Starburst Clerodendron	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Codominant Leaders - Multi	Trunk Damage - Moderate
SW 13TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 13TH ST	Bottle Palm	6-10"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 13TH ST	Bottle Palm	16-20"	No	10'	Good (61% to 80%)				
SW 13TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 13TH ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 13TH ST	Mahogany	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Dead Wood
SW 13TH ST	Mahogany	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Major		
SW 13TH ST	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 13TH ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	
SW 13TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 13TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 13TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 13TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Major
SW 13TH ST	Mahogany	16-20"	No	25'	Fair (41% to 60%)		Reduced Canopy - Major	Codominant Leaders/Included Bark	Lifting
SW 13TH ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 13TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 13TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Mahogany	1-5"	No	10'	Good (61% to 80%)		Discolored Foliage		
SW 13TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 13TH ST	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders - Multi	Topped	Stubs with Sprouts
SW 13TH ST	Mahogany	6-10"	No	10'	Fair (41% to 60%)		Codominant Leaders - Multi	Topped	Stubs with Sprouts
SW 13TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 13TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Decay Observed
SW 13TH ST	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders - Multi	
SW 13TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Codominant Leaders - Multi	Topped	Stubs with Sprouts
SW 13TH ST	Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 13TH ST	Mahogany	31-40"	No	60'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Areca Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Tapered Trunk		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Moderate	Leaning - Minor	
SW 13TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)		Tapered Trunk	Reduced Canopy - Moderate	
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 13TH ST	Christmas Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 13TH ST	Christmas Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 13TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Leaning - Minor		
SW 13TH ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Broken Branches	Limb Damage - Moderate
SW 13TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 13TH ST	Live Oak	11-15"	No	25'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 13TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Suppressed Canopy	
SW 13TH ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Reduced Canopy - Minor	Suppressed Canopy
SW 13TH ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Lopsided/Reduced Canopy - Moderate	Suppressed Canopy
SW 13TH ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Lifting	Suppressed Canopy
SW 13TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)				
SW 13TH ST	Live Oak	11-15"	No	25'	Good (61% to 80%)		Broken Branches		
SW 13TH ST	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Very Low	Discolored Foliage	
SW 13TH ST	Sacred Fig	31-40"	No	50'	Poor (21% to 40%)		Cavities	Reduced Canopy - Major	Sprouting
SW 13TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Minor	Stubs with Sprouts	
SW 13TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Limb Damage - Moderate	
SW 13TH ST	Loquat	6-10"	No	15'	Poor (21% to 40%)		Cavities	Trunk Damage - Major	Codominant Leaders/Included Bark
SW 13TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 13TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 13TH ST	Tropical Almond	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 13TH ST	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Cavities
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor	Nutrient Deficiency	
SW 13TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Moderate	
SW 13TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Minor	
SW 13TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Live Oak	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Minor
SW 13TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 13TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 13TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Girdling Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 13TH ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Crown Density - Low
SW 13TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Codominant Leaders - Multi
SW 13TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Topped
SW 13TH ST	Mahogany	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Topped
SW 13TH ST	Mahogany	41-50"	No	55'	Poor (21% to 40%)		Constricted Roots	Over Extended Limb(s)	Codominant Leaders - Multi
SW 13TH ST	Mahogany	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Codominant Leaders - Multi
SW 13TH ST	Mahogany	41-50"	No	60'	Poor (21% to 40%)		Constricted Roots	Topped	Over Extended Limb(s)
SW 13TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Sprouting
SW 13TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 13TH ST	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Crown Density - Low	Codominant Leaders/No Included Bark
SW 13TH ST	Mahogany	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Lion's Tailing
SW 13TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Over Pruned	Lopsided/Reduced Canopy - Major	Sprouting
SW 13TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 13TH ST	Mahogany	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Cavities	Lopsided/Reduced Canopy - Moderate
SW 13TH ST	Mahogany	6-10"	No	15'	Good (61% to 80%)		Limb Damage - Moderate		
SW 13TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Reduced Canopy - Moderate	Decay Observed	
SW 13TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Crown Density - Low	
SW 13TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)		Lopsided/Reduced Canopy - Moderate		
SW 13TH ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Minor	Dead Wood
SW 13TH ST	Mahogany	41-50"	No	60'	Poor (21% to 40%)		Constricted Roots	Codominant Leaders - Multi	Sprouting
SW 13TH ST	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Basal Co-Dominant with Adjacent Tree(s)	Sprouting
SW 13TH ST	Mahogany	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Limb Damage - Major
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor	Suppressed Canopy	
SW 13TH ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Lifting
SW 13TH ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 13TH ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 13TH ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Over Extended Limb(s)
SW 13TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Crown Density - Low
SW 13TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 13TH ST	Mahogany	41-50"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Lifting
SW 13TH ST	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Dead Wood
SW 13TH ST	Mahogany	16-20"	No	30'	Poor (21% to 40%)		Cavities	Suppressed Canopy	Lopsided/Reduced Canopy - Major
SW 13TH ST	Mahogany	31-40"	No	55'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Over Extended Limb(s)
SW 13TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 13TH ST	Mahogany	41-50"	No	60'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Lopsided/Reduced Canopy - Major	Over Extended Limb(s)
SW 13TH ST	Mahogany	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Suppressed Canopy	Codominant Leaders/Included Bark
SW 13TH ST	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Root Damage/Decay	Reduced Canopy - Major	Stubs with Sprouts
SW 13TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	Stubs with Sprouts
SW 13TH ST	Crepe Myrtle	6-10"	Yes	15'	Fair (41% to 60%)		Strap Constricting Tree	Crown Density - Moderate	
SW 13TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Berry Tree	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 13TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Sea Grape	1-5"	Yes	5'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy	Leaning - Moderate	

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	Nutrient Deficiency
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders - Multi
SW 13TH ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Limb Damage - Moderate
SW 13TH ST	Green Buttonwood	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Lifting	Stubs with Sprouts
SW 13TH ST	Green Buttonwood	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 13TH ST	Mahogany	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH ST	Mahogany	6-10"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Talipot Palm	6-10"	No	10'	Good (61% to 80%)				
SW 13TH ST	Royal Poinciana	1-5"	No	25'	Poor (21% to 40%)		Crown Density - Low	Reduced Canopy - Major	
SW 13TH ST	Royal Poinciana	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Talipot Palm	6-10"	No	5'	Good (61% to 80%)				
SW 13TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 13TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)				
SW 13TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH ST	Mahogany	11-15"	No	35'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Discolored Foliage	
SW 13TH ST	Mahogany	1-5"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Mahogany	11-15"	No	40'	Good (61% to 80%)		Lopsided/Reduced Canopy - Moderate		
SW 13TH ST	Mahogany	1-5"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Mahogany	11-15"	No	40'	Good (61% to 80%)		Lopsided/Reduced Canopy - Moderate		
SW 13TH ST	Mahogany	16-20"	No	40'	Poor (21% to 40%)		Girdling Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH ST	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)				
SW 13TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Pink Cassia	6-10"	No	35'	Good (61% to 80%)		Over Extended Limb(s)		
SW 13TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Reduced Canopy - Moderate
SW 13TH ST	Australian Fan Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Damaged Fronds
SW 13TH ST	Fan Palm/Pritchardia	6-10"	No	10'	Good (61% to 80%)				
SW 13TH ST	Pink Cassia	16-20"	No	35'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 13TH ST	Frangipani	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Fungus on Leaves
SW 13TH ST	Copernicia sp.	11-15"	No	5'	Good (61% to 80%)				
SW 13TH ST	Frangipani	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 13TH ST	Pritchardia sp.	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Frangipani	1-5"	No	15'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Suppressed Canopy	Limb Damage - Minor
SW 13TH ST	Cuban Petticoat Palm	6-10"	No	10'	Good (61% to 80%)		Damaged Fronds		
SW 13TH ST	Fan Palm/Pritchardia	16-20"	No	45'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Vine Cover - Heavy	Stubs with Sprouts
SW 13TH ST	Fan Palm/Pritchardia	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Mango	11-15"	No	30'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	Leaning - Moderate
SW 13TH ST	Mirguama Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Fungus on Leaves	
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)		Suppressed Canopy	Fungus on Leaves	
SW 13TH ST	Mirguama Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Mango	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH ST	Talipot Palm	6-10"	No	5'	Good (61% to 80%)				
SW 13TH ST	Oriental Arborvitae	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 13TH ST	Oriental Arborvitae	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Oriental Arborvitae	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 13TH ST	Royal Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Tamarind	16-20"	No	40'	Fair (41% to 60%)		Root Damage/Decay	Reduced Canopy - Moderate	Dead Wood
SW 13TH ST	Lancepod	1-5"	No	10'	Poor (21% to 40%)		Trunk Damage - Moderate	Suppressed Canopy	Crown Density - Low
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 13TH ST	ML UNID 1	1-5"	No	15'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Trunk Damage - Moderate
SW 13TH ST	Yellow Elder	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Lignum Vitae	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Frangipani	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Minor
SW 13TH ST	Starburst Clerodendron	6-10"	No	10'	Good (61% to 80%)		Basal Co-Dominant		
SW 13TH ST	Hong Kong Orchid	16-20"	Yes	10'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Stubs with Sprouts
SW 13TH ST	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 13TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 13TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Desiccated Foliage	
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)				
SW 13TH ST	Florida Thatch Palm	6-10"	No	5'	Good (61% to 80%)				
SW 13TH ST	Yellow Tabebuia	6-10"	No	10'	Fair (41% to 60%)		Girdling Roots		
SW 13TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Florida Thatch Palm	6-10"	No	5'	Good (61% to 80%)				
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)		Fungus on Leaves		
SW 13TH ST	Talipot Palm	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 13TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Stubs with Sprouts	Lifting	Reduced Canopy - Moderate
SW 13TH ST	Mahogany	6-10"	No	20'	Poor (21% to 40%)		Restricted Canopy	Lifting	Reduced Canopy - Major
SW 13TH ST	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Lifting	Stubs with Sprouts
SW 13TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Christmas Palm	11-15"	Yes	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Poor (21% to 40%)		Trunk Damage - Major		
SW 13TH ST	Christmas Palm	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 13TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Buccaneer Palm	6-10"	No	5'	Good (61% to 80%)				
SW 13TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 13TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Crown Density - Excessive (Due to Epicormic Grov	Strap Constricting Tree	
SW 13TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Mahogany	31-40"	No	60'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Lion's Tailing
SW 13TH ST	Christmas Berry Tree	1-5"	Yes	10'	Poor (21% to 40%)		Suppressed Canopy	Broken Branches	
SW 13TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Crown Density - Low
SW 13TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 13TH ST	Mahogany	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 13TH ST	Vera Wood	1-5"	No	20'	Good (61% to 80%)		Strap Constricting Tree		

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Vera Wood	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Nutrient Deficiency	
SW 13TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Tapered Trunk		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Tapered Trunk		
SW 13TH ST	Weeping Fig	6-10"	No	5'	Poor (21% to 40%)		Topped	Stubs with Sprouts	Decay Observed
SW 13TH ST	Talipot Palm	1-5"	No	5'	Good (61% to 80%)		Fungus on Leaves		
SW 13TH ST	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Fan Palm/Pritchardia	6-10"	No	5'	Good (61% to 80%)		Damaged Fronds		
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)		Damaged Fronds	Fungus on Leaves	
SW 13TH ST	Bridalveil Tree	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH ST	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	Suppressed Canopy
SW 13TH ST	Royal Poinciana	1-5"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Minor	
SW 13TH ST	Yellow Tabebuia	6-10"	No	15'	Good (61% to 80%)				
SW 13TH ST	Tamarind	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	
SW 13TH ST	Coconut Palm	16-20"	No	20'	Fair (41% to 60%)		Leaning - Moderate		
SW 13TH ST	Norfolk Pine	21-30"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 13TH ST	Coconut Palm	16-20"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Spiny Black Olive	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Lifting	Stubs with Sprouts
SW 13TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders - Multi
SW 13TH ST	Royal Poinciana	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Cavities	Reduced Canopy - Moderate
SW 13TH ST	Norfolk Pine	21-30"	No	25'	Fair (41% to 60%)		Codominant Leaders/Included Bark		
SW 13TH ST	Yellow Tabebuia	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 13TH ST	Yellow Tabebuia	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Talipot Palm	6-10"	No	5'	Good (61% to 80%)				
SW 13TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Royal Poinciana	6-10"	No	20'	Good (61% to 80%)				
SW 13TH ST	Talipot Palm	11-15"	No	10'	Fair (41% to 60%)		Damaged Fronds	Nutrient Deficiency	
SW 13TH ST	Mirguama Palm	11-15"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)				
SW 13TH ST	Frangipani	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Fungus on Leaves
SW 13TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Fungus on Leaves		
SW 13TH ST	Golden Shower Tree	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 13TH ST	Mirguama Palm	1-5"	No	10'	Good (61% to 80%)		Fungus on Leaves		
SW 13TH ST	Coccothrinax sp.	1-5"	No	5'	Good (61% to 80%)		Fungus on Leaves		
SW 13TH ST	Fan Palm/Pritchardia	11-15"	No	15'	Good (61% to 80%)		Fungus on Leaves		
SW 13TH ST	Purple Tabebuia	1-5"	No	20'	Fair (41% to 60%)		Restricted Canopy	Fungus on Leaves	
SW 13TH ST	Fan Palm/Pritchardia	6-10"	No	20'	Fair (41% to 60%)		Fungus on Leaves		
SW 13TH ST	Orange Geiger	1-5"	No	5'	Fair (41% to 60%)		Leader - Broken	Reduced Canopy - Moderate	
SW 13TH ST	Talipot Palm	6-10"	No	5'	Good (61% to 80%)				
SW 13TH ST	Bismark Palm	16-20"	No	15'	Good (61% to 80%)		Restricted Canopy	Damaged Fronds	
SW 13TH ST	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders - Multi

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Bismark Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Damaged Fronds	
SW 13TH ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Bismark Palm	11-15"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH ST	Yellow Elder	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Yellow Elder	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Pink Cassia	1-5"	No	25'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 13TH ST	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Leaning - Moderate	Nutrient Deficiency	
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)				
SW 13TH ST	Umbrella Tree	16-20"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Decay Observed
SW 13TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Sprouting	Strap Constricting Tree	
SW 13TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 13TH ST	Mahogany	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 13TH ST	Talipot Palm	16-20"	No	10'	Good (61% to 80%)				
SW 13TH ST	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 13TH ST	Talipot Palm	6-10"	No	5'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH ST	Royal Poinciana	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Broken Branches	
SW 13TH ST	Royal Poinciana	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Topped
SW 13TH ST	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH ST	Sapodilla	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH ST	Weeping Fig	21-30"	No	30'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Decay Observed
SW 13TH ST	Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Low		
SW 13TH ST	Crepe Myrtle	6-10"	No	10'	Fair (41% to 60%)		Crown Density - Low		
SW 13TH ST	Queen Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 13TH ST	Bottle Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Discolored Foliage	
SW 13TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Triangle Palm	16-20"	No	15'	Good (61% to 80%)		Fungus on Leaves		
SW 13TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 13TH ST	European Fan Palm	21-30"	Yes	15'	Good (61% to 80%)				
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Green Buttonwood	6-10"	No	20'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Trunk Damage - Moderate
SW 13TH ST	Golden Shower Tree	6-10"	No	25'	Fair (41% to 60%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 13TH ST	Golden Shower Tree	6-10"	No	25'	Good (61% to 80%)		Strap Constricting Tree		
SW 13TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 13TH ST	Umbrella Tree	21-30"	No	35'	Poor (21% to 40%)		Root Damage/Decay	Sloughing Bark	Stubs with Sprouts
SW 13TH ST	Bottle Palm	6-10"	No	10'	Fair (41% to 60%)		Damaged Fronds	Desiccated Foliage	Reduced Canopy - Moderate
SW 13TH ST	Bottle Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 13TH ST	Spanish Lime	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts
SW 13TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 13TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Black Calabash	16-20"	Yes	40'	Fair (41% to 60%)		Leaning - Major	Stubs with Sprouts	
SW 13TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 13TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 13TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 13TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 13TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH ST	Oriental Arborvitae	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Desiccated Foliage	
SW 13TH ST	Oriental Arborvitae	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Desiccated Foliage	
SW 13TH ST	Black Calabash	11-15"	Yes	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 13TH ST	Oriental Arborvitae	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 13TH ST	Mango	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Mango	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Discolored Foliage	
SW 13TH ST	Brazilian Beauty Leaf	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH ST	Sacred Fig	51-60"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Cavities
SW 13TH ST	Montgomery Palm	21-30"	Yes	25'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH ST	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	
SW 13TH ST	Sacred Fig	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Cavities
SW 13TH ST	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH ST	Christmas Palm	6-10"	Yes	20'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Moderate	
SW 13TH ST	Yellow Elder	6-10"	Yes	20'	Fair (41% to 60%)		Restricted Canopy	Leaning - Moderate	Stubs with Sprouts
SW 13TH ST	Yellow Elder	6-10"	Yes	10'	Fair (41% to 60%)		Restricted Canopy	Stubs with Sprouts	Reduced Canopy - Moderate
SW 13TH ST	Sacred Fig	21-30"	No	50'	Poor (21% to 40%)		Cavities	Reduced Canopy - Major	Stubs with Sprouts
SW 13TH ST	Weeping Fig	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH ST	Sacred Fig	21-30"	No	60'	Poor (21% to 40%)		Constricted Roots	Stubs with Sprouts	Decay Observed
SW 13TH ST	Sacred Fig	21-30"	No	40'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 13TH ST	Sacred Fig	21-30"	No	40'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 13TH ST	Sacred Fig	21-30"	No	50'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 13TH ST	Sacred Fig	21-30"	No	60'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 13TH ST	Weeping Fig	11-15"	No	15'	Good (61% to 80%)		Pruned Into Shrub		
SW 13TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 13TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 13TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 13TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 13TH ST	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 13TH ST	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 13TH ST	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 13TH ST	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 13TH ST	Black Olive	21-30"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Cracks in Trunk	
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Tapered Trunk		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 13TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 13TH ST	Black Olive	11-15"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 13TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Moderate	
SW 13TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Christmas Palm	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 13TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	Decay Observed
SW 13TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Girdling Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 13TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 13TH ST	Weeping Fig	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	Decay Observed
SW 13TH ST	Christmas Berry Tree	16-20"	Yes	20'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 13TH ST	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 13TH ST	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 13TH ST	Black Olive	21-30"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Cracks in Trunk	
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Tapered Trunk		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 13TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 13TH ST	Black Olive	11-15"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 13TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Moderate	
SW 13TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Christmas Palm	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 13TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	Decay Observed
SW 13TH ST	Christmas Palm	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 13TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	Decay Observed
SW 13TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Girdling Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 13TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 13TH ST	Weeping Fig	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	Decay Observed
SW 13TH ST	Christmas Berry Tree	16-20"	Yes	20'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy		
SW 13TH ST	Strangler Fig	51-60"	Yes	60'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Cavities
SW 13TH ST	Christmas Palm	1-5"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Restricted Canopy	
SW 13TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Tapered Trunk	
SW 13TH ST	Yellow Poinciana	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Restricted Canopy
SW 13TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 13TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 13TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Minor		
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Discolored Foliage		
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Discolored Foliage	Damaged Fronds	
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Discolored Foliage	Damaged Fronds	
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 13TH ST	Frangipani	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage	
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 13TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Discolored Foliage	
SW 13TH ST	Mango	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Stubs with Sprouts	
SW 13TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Restricted Canopy	Discolored Foliage
SW 13TH ST	Papaya	1-5"	No	40'	Fair (41% to 60%)		Leaning - Moderate	Restricted Canopy	Lopsided/Reduced Canopy - Moderate
SW 13TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH ST	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Codominant Leaders/Included Bark
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage	Trunk Damage - Minor	
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 13TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Restricted Canopy	
SW 13TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Restricted Canopy	Leaning - Moderate
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Leaning - Moderate	
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Leaning - Minor	
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Cracks in Trunk		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Sacred Fig	16-20"	No	50'	Poor (21% to 40%)		Stubs with Sprouts	Limb Damage - Major	Decay Observed
SW 13TH ST	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Sacred Fig	1-5"	Yes	5'	Fair (41% to 60%)		Leader - Broken	Stubs with Sprouts	
SW 13TH ST	Sacred Fig	1-5"	Yes	5'	Fair (41% to 60%)		Leader - Broken	Stubs with Sprouts	
SW 13TH ST	Sacred Fig	6-10"	Yes	10'	Fair (41% to 60%)		Leader - Broken	Stubs with Sprouts	
SW 13TH ST	Sacred Fig	21-30"	No	50'	Poor (21% to 40%)		Vine Cover - Heavy	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 13TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Leaning - Moderate	Lopsided/Reduced Canopy - Moderate
SW 13TH ST	Sacred Fig	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 13TH ST	Sacred Fig	21-30"	No	60'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Cavities
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Restricted Canopy	Tapered Trunk	
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Mango	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 13TH ST	Japanese Privet	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree		
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 13TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 13TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Moderate	Leaning - Moderate
SW 13TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 13TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH ST	Mahogany	51-60"	No	80'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Reduced Canopy - Moderate
SW 13TH ST	Spanish Lime	16-20"	No	30'	Fair (41% to 60%)		Leaning - Moderate	Lifting	Stubs with Sprouts
SW 13TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 13TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 13TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Bottle Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH ST	Indian Laurel Fig	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 13TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 13TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH ST	Bottle Palm	21-30"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 13TH ST	Pygmy Date Palm	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Partially		

Street Tree Inventory

SW 14th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH ST	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Cavities	Reduced Canopy - Major	Stubs with Sprouts
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 14TH ST	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 14TH ST	Rubber Tree	16-20"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Topped	Decay Observed	Sprouting
SW 14TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 14TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Suppressed Canopy	
SW 14TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Dead Wood
SW 14TH ST	Weeping Fig	6-10"	No	5'	Poor (21% to 40%)	Utility Lines Above	Lopsided/Reduced Canopy - Major	Decay Observed	Vine Cover - Heavy
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 14TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Leaning - Moderate		
SW 14TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Leaning - Moderate		
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Leaning - Moderate		
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Leaning - Moderate		
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Leaning - Moderate		
SW 14TH ST	Frangipani	1-5"	No	5'	Fair (41% to 60%)		Fungus on Leaves	Reduced Canopy - Moderate	
SW 14TH ST	Strangler Fig	6-10"	No	10'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	
SW 14TH ST	Royal Poinciana	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Over Pruned
SW 14TH ST	Montgomery Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Decay Observed		
SW 14TH ST	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 14TH ST	Christmas Palm	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 14TH ST	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Decay Observed	Discolored Foliage	
SW 14TH ST	Mahogany	31-40"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 14TH ST	Gumbo Limbo	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 14TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Tapered Trunk		
SW 14TH ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Topped	Sprouting	Codominant Leaders/Included Bark
SW 14TH ST	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Trunk Damage - Minor	Lifting
SW 14TH ST	Japanese Blueberry	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	
SW 14TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 14TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 14TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH ST	Coconut Palm	11-15"	Yes	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH ST	Coconut Palm	11-15"	Yes	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH ST	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 14TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)		Tapered Trunk		
SW 14TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)		Tapered Trunk		
SW 14TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)		Tapered Trunk		
SW 14TH ST	Tropical Almond	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 14TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 14TH ST	Queen Palm	11-15"	No	10'	Fair (41% to 60%)		Trunk Damage - Major		
SW 14TH ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Desiccated Foliage	
SW 14TH ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH ST	Yellow Tabebuia	6-10"	No	10'	Poor (21% to 40%)		Topped	Sprouting	Codominant Leaders - Multi
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 14th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH ST	Mahogany	16-20"	No	20'	Fair (41% to 60%)		Topped	Pruned Into Shrub	
SW 14TH ST	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Moderate	Codominant Leaders - Multi
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Tapered Trunk		
SW 14TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Tamarind	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Minor
SW 14TH ST	Umbrella Tree	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Major	Lateral Branching - None	
SW 14TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Moderate	
SW 14TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Broken Branches	
SW 14TH ST	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Dead Wood
SW 14TH ST	Weeping Fig	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Crown Density - Very Low
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 14TH ST	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 14TH ST	Triangle Palm	11-15"	No	15'	Good (61% to 80%)		Fungus on Leaves		
SW 14TH ST	Triangle Palm	11-15"	No	15'	Good (61% to 80%)		Fungus on Leaves		
SW 14TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH ST	Carrotwood	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 14TH ST	Date Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH ST	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 14TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Strap Constricting Tree	
SW 14TH ST	Bottle Palm	11-15"	No	5'	Good (61% to 80%)				
SW 14TH ST	Queen Palm	11-15"	No	20'	Fair (41% to 60%)		Tapered Trunk		
SW 14TH ST	Queen Palm	11-15"	No	20'	Fair (41% to 60%)		Tapered Trunk	Strap Constricting Tree	Trunk Damage - Minor
SW 14TH ST	Queen Palm	11-15"	No	20'	Fair (41% to 60%)		Tapered Trunk	Strap Constricting Tree	Trunk Damage - Minor
SW 14TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 14TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 14TH ST	Queen Palm	11-15"	No	20'	Good (61% to 80%)				
SW 14TH ST	Queen Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 14TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders - Multi
SW 14TH ST	Christmas Palm	1-5"	Yes	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	One Dead Trunk
SW 14TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 14TH ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Trunk Damage - Minor
SW 14TH ST	Mahogany	11-15"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 14TH ST	Christmas Palm	11-15"	No	10'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	16-20"	No	15'	Good (61% to 80%)				
SW 14TH ST	Green Buttonwood	21-30"	No	45'	Fair (41% to 60%)		Stubs with Sprouts		
SW 14TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 14TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Strap Constricting Tree	
SW 14TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 14th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH ST	Cabbage Palm	11-15"	No	5'	Good (61% to 80%)				
SW 14TH ST	Bottle Palm	11-15"	No	5'	Fair (41% to 60%)		Tapered Trunk	Reduced Canopy - Moderate	
SW 14TH ST	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Major	Crown Density - Low	Dead Wood
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Fungus on Leaves		
SW 14TH ST	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 14TH ST	Areca Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 14TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 14TH ST	Sandbox Tree	6-10"	Yes	5'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 14TH ST	Royal Poinciana	21-30"	Yes	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Moderate	Stubs with Sprouts
SW 14TH ST	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	
SW 14TH ST	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Moderate	Leaning - Moderate
SW 14TH ST	Tamarind	11-15"	No	30'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 14TH ST	Mango	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Cavities
SW 14TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH ST	Bottle Palm	6-10"	No	10'	Poor (21% to 40%)		Disease	Desiccated Foliage	Reduced Canopy - Moderate
SW 14TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Discolored Foliage		
SW 14TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)				
SW 14TH ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Sapodilla	21-30"	No	40'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 14TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH ST	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Tamarind	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH ST	Java Plum	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Leaning - Moderate
SW 14TH ST	Yellow Elder	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Limb Damage - Moderate	Stubs with Sprouts
SW 14TH ST	Yellow Elder	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Limb Damage - Moderate	Stubs with Sprouts
SW 14TH ST	Strangler Fig	31-40"	No	60'	Poor (21% to 40%)		Constricted Roots	Ficus Growing on Tree	Stubs with Sprouts
SW 14TH ST	Strangler Fig	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH ST	Strangler Fig	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 14TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Discolored Foliage		
SW 14TH ST	Peacock Flower	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 14TH ST	Common Fig	11-15"	No	20'	Fair (41% to 60%)		Discolored Foliage		
SW 14TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 14TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 14TH ST	Bottlebrush	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Bottlebrush	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Arjun Tree	11-15"	No	25'	Poor (21% to 40%)		Trunk Damage - Major	Restricted Canopy	Lopsided/Reduced Canopy - Moderate
SW 14TH ST	Weeping Fig	11-15"	No	30'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Decay Observed
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 14TH ST	Coconut Palm	6-10"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Discolored Foliage	
SW 14TH ST	Arjun Tree	41-50"	No	80'	Poor (21% to 40%)		Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts
SW 14TH ST	Pink Cassia	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 14TH ST	Date Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Damaged Fronds	

(Continued on Next Page)

Street Tree Inventory

SW 14th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH ST	Date Palm	6-10"	No	15'	Good (61% to 80%)				
SW 14TH ST	Date Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Damaged Fronds	
SW 14TH ST	Royal Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 14TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 14TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH ST	Queen Palm	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Leader - Bent	Reduced Canopy - Major	Trunk Damage - Moderate
SW 14TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 14TH ST	Queen Palm	6-10"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Discolored Foliage	
SW 14TH ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Major		
SW 14TH ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 14TH ST	Mahogany	1-5"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	
SW 14TH ST	Mahogany	1-5"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 14TH ST	Melaleuca	21-30"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 14TH ST	Crepe Myrtle	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH ST	Spindle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 14TH ST	Spindle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 14TH ST	Spindle Palm	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 14TH ST	Spindle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 14TH ST	Mahogany	21-30"	No	30'	Good (61% to 80%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 14TH ST	Spindle Palm	11-15"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 14TH ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 14TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 14TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 14TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Limb Damage - Moderate	
SW 14TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 14TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Limb Damage - Moderate	
SW 14TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH ST	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)		Pruned Into Shrub		
SW 14TH ST	Sapodilla	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 14TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 14TH ST	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 14TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 14TH ST	Hong Kong Orchid	21-30"	No	30'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Cavities
SW 14TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 14TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		

(Continued on Next Page)

Street Tree Inventory

SW 14th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH ST	Black Olive	16-20"	No	40'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Lopsided/Reduced Canopy - Major	Decay Observed
SW 14TH ST	Black Olive	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Trunk Damage - Moderate
SW 14TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 14TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 14TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Discolored Foliage	
SW 14TH ST	Hong Kong Orchid	11-15"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Cavities
SW 14TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Leaning - Moderate		
SW 14TH ST	Java Plum	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 14TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 14TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor	Restricted Canopy	
SW 14TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 14TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 14TH ST	Umbrella Tree	1-5"	No	5'	Poor (21% to 40%)		Leaning - Major	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH ST	Royal Poinciana	31-40"	No	65'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts

Streets | Terraces



Looking East - SW 22nd Avenue



Looking West - SW 19th Avenue



Looking East - SW 27th Avenue



Looking East - SW 23rd Avenue



Looking West - SW 16th Avenue



Looking West - SW 14th Avenue



Looking West - SW 12th Avenue



Looking West - SW 17th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 14th Terrace	2	Shenandoah North	4	50	4,000	No	No	Yes	2	City	Yes	Yes	5-6	yes	yes	north side b/t 19th and 17th avenue	Roundabout at 19th Ave. Grass curbed swales
SW 15th Street	2	Shenandoah North	4	40-60	7,000	No	No	Yes, East of 19th Ave.	2	City	Yes	Yes	5-6	east of 19th ave	yes	north side b/t 25th amd 22nd Ave	ROW 60' btw 25th and 27th Ave, 40' btw 22nd and 25th Ave. Grass, gravel and paved swales where curbless.

SW 14th Terrace

TYPOLOGY B

SW 15th Street

TYPOLOGY B & C & D

Street Tree Inventory

SW 14th Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH TER	Yellow Poinciana	21-30"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Limb Damage - Moderate
SW 14TH TER	Yellow Poinciana	16-20"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Limb Damage - Moderate
SW 14TH TER	Yellow Poinciana	16-20"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 14TH TER	Yellow Poinciana	16-20"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 14TH TER	Yellow Poinciana	16-20"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 14TH TER	Yellow Poinciana	11-15"	No	25'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Trunk Damage - Major
SW 14TH TER	Yellow Poinciana	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 14TH TER	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH TER	Gumbo Limbo	16-20"	No	30'	Poor (21% to 40%)		Cracks in Trunk	Disease	Crown Density - Low
SW 14TH TER	Yellow Poinciana	16-20"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 14TH TER	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 14TH TER	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 14TH TER	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 14TH TER	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 14TH TER	Areca Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 14TH TER	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 14TH TER	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 14TH TER	Yellow Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	
SW 14TH TER	Yellow Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Reduced Canopy - Moderate
SW 14TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 14TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 14TH TER	Weeping Fig	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Decay Observed	
SW 14TH TER	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Limb Damage - Moderate
SW 14TH TER	ML UNID 2	21-30"	Yes	10'	Good (61% to 80%)				
SW 14TH TER	Vera Wood	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 14TH TER	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)				
SW 14TH TER	Frangipani	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low	Dead Wood	Disease
SW 14TH TER	Bismark Palm	16-20"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH TER	Pink Cassia	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 14TH TER	Frangipani	1-5"	No	Negligible	Dead (0% to 5%)				
SW 14TH TER	Vera Wood	1-5"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 14TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 14TH TER	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 14TH TER	Java Bishopwood	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Stubs with Sprouts
SW 14TH TER	Java Bishopwood	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Stubs with Sprouts
SW 14TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Damaged Fronds		
SW 14TH TER	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Damaged Fronds		
SW 14TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Damaged Fronds		
SW 14TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Damaged Fronds		
SW 14TH TER	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Damaged Fronds	Nutrient Deficiency	
SW 14TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Damaged Fronds		
SW 14TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Damaged Fronds		
SW 14TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Damaged Fronds		
SW 14TH TER	Crepe Myrtle	6-10"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Crown Density - Low	Dead Wood	
SW 14TH TER	Crepe Myrtle	6-10"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Crown Density - Low	Dead Wood	
SW 14TH TER	Starburst Clerodendron	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Stubs with Sprouts	
SW 14TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH TER	Tropical Almond	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 14th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Fungus on Leaves		
SW 14TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Fungus on Leaves		
SW 14TH TER	Crepe Myrtle	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Crown Density - Low	Dead Wood	Strap Constricting Tree
SW 14TH TER	Crepe Myrtle	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Crown Density - Low	Dead Wood	Strap Constricting Tree
SW 14TH TER	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 14TH TER	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 14TH TER	Mango	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 14TH TER	Japanese Privet	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Fungus on Leaves	Reduced Canopy - Moderate	
SW 14TH TER	Weeping Fig	21-30"	Yes	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	Limb Damage - Moderate
SW 14TH TER	Mahogany	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 14TH TER	Avocado	1-5"	No	10'	Good (61% to 80%)		Fungus on Leaves		
SW 14TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 14TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 14TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH TER	Crepe Myrtle	1-5"	Yes	10'	Fair (41% to 60%)		Restricted Canopy	Strap Constricting Tree	
SW 14TH TER	Crepe Myrtle	1-5"	Yes	10'	Fair (41% to 60%)		Restricted Canopy		
SW 14TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH TER	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Nutrient Deficiency	Restricted Canopy
SW 14TH TER	Avocado	16-20"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Suppressed Canopy	Stubs with Sprouts
SW 14TH TER	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Nutrient Deficiency	Restricted Canopy
SW 14TH TER	Coconut Palm	11-15"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	Restricted Canopy
SW 14TH TER	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Nutrient Deficiency	Leaning - Minor
SW 14TH TER	Avocado	1-5"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Suppressed Canopy	Leaning - Moderate
SW 14TH TER	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Nutrient Deficiency	
SW 14TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Nutrient Deficiency	
SW 14TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Nutrient Deficiency	Leaning - Major
SW 14TH TER	Coconut Palm	11-15"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 14TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 14TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 14TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH TER	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Leader - Broken	Lopsided/Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 14TH TER	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH TER	Coconut Palm	11-15"	No	15'	Good (61% to 80%)				
SW 14TH TER	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Lifting	
SW 14TH TER	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Lifting	Stubs with Sprouts
SW 14TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Fungus on Leaves
SW 14TH TER	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 14TH TER	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Damaged Fronds	
SW 14TH TER	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Lifting	Codominant Leaders/Included Bark
SW 14TH TER	Queen Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Discolored Foliage	
SW 14TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Discolored Foliage		
SW 14TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 14TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH TER	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Tapered Trunk	Reduced Canopy - Moderate	Nutrient Deficiency
SW 14TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH TER	Weeping Fig	6-10"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Decay Observed	
SW 14TH TER	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 14TH TER	Weeping Fig	11-15"	No	35'	Fair (41% to 60%)		Leaning - Moderate	Lopsided/Reduced Canopy - Moderate	
SW 14TH TER	Starburst Clerodendron	1-5"	No	10'	Fair (41% to 60%)		Stubs with Sprouts		

(Continued on Next Page)

Street Tree Inventory

SW 14th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH TER	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Leaning - Moderate	Restricted Canopy	
SW 14TH TER	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Leaning - Moderate	Suppressed Canopy	
SW 14TH TER	Rubber Tree	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Leaning - Moderate	Stubs with Sprouts
SW 14TH TER	Queen Crepe Myrtle	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Moderate	
SW 14TH TER	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Fungus on Leaves		
SW 14TH TER	Crepe Myrtle	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	
SW 14TH TER	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)				
SW 14TH TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH TER	Royal Poinciana	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 14TH TER	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Damaged Fronds		
SW 14TH TER	Frangipani	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Dead Wood	Trunk Damage - Moderate
SW 14TH TER	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Insect Damage Leaves	
SW 14TH TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH TER	Royal Poinciana	16-20"	No	45'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 14TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	
SW 14TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 14TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 14TH TER	Coconut Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH TER	Coconut Palm	6-10"	Yes	15'	Good (61% to 80%)		Fungus on Leaves	Suppressed Canopy	
SW 14TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Suppressed Canopy	
SW 14TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 14TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Moderate	
SW 14TH TER	Sapodilla	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 14TH TER	Live Oak	31-40"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	
SW 14TH TER	Banyan	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Lopsided/Reduced Canopy - Moderate	
SW 14TH TER	Sacred Fig	1-5"	No	5'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	
SW 14TH TER	Coconut Palm	1-5"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH TER	Mahogany	11-15"	No	50'	Good (61% to 80%)		Reduced Canopy - Minor	Limb Damage - Minor	
SW 14TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH TER	Hong Kong Orchid	6-10"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Nutrient Deficiency	
SW 14TH TER	Yellow Poinciana	16-20"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 14TH TER	Yellow Poinciana	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 14TH TER	Yellow Poinciana	16-20"	No	35'	Poor (21% to 40%)		Reduced Canopy - Moderate	Limb Damage - Major	Stubs with Sprouts
SW 14TH TER	Gumbo Limbo	11-15"	No	40'	Poor (21% to 40%)		Reduced Canopy - Moderate	Lifting	Codominant Leaders - Multi
SW 14TH TER	Yellow Poinciana	21-30"	No	50'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Limb Damage - Major	Stubs with Sprouts
SW 14TH TER	Yellow Poinciana	16-20"	No	30'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Limb Damage - Major	Stubs with Sprouts
SW 14TH TER	Yellow Poinciana	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Dead Wood	Stubs with Sprouts
SW 14TH TER	Yellow Poinciana	16-20"	No	35'	Poor (21% to 40%)		Reduced Canopy - Major	Leaning - Moderate	Stubs with Sprouts
SW 14TH TER	Yellow Poinciana	11-15"	No	30'	Poor (21% to 40%)		Reduced Canopy - Major	Lifting	Limb Damage - Moderate
SW 14TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH TER	Sapodilla	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH TER	Sapodilla	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 14TH TER	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH TER	Royal Poinciana	6-10"	No	10'	Good (61% to 80%)				
SW 14TH TER	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)				
SW 14TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH TER	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 14TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 14TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 14th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 14TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 14TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Restricted Canopy	Discolored Foliage	
SW 14TH TER	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 14TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Restricted Canopy	Discolored Foliage	
SW 14TH TER	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 14TH TER	Royal Poinciana	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate
SW 14TH TER	Yellow Poinciana	6-10"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Limb Damage - Minor
SW 14TH TER	Royal Palm	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Moderate	Discolored Foliage	
SW 14TH TER	Frangipani	1-5"	No	15'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Limb Damage - Moderate	Seasonal Defoliation/Discolored Foliage
SW 14TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Broken Branches	Reduced Canopy - Minor
SW 14TH TER	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 14TH TER	Crepe Myrtle	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Decay Observed	
SW 14TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH TER	Peacock Flower	1-5"	Yes	10'	Fair (41% to 60%)		Decay Observed		
SW 14TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 14TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 14TH TER	Avocado	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Stubs with Sprouts	
SW 14TH TER	Sapodilla	6-10"	No	25'	Good (61% to 80%)		Restricted Canopy		
SW 14TH TER	Royal Poinciana	16-20"	No	55'	Poor (21% to 40%)		Cavities	Limb Damage - Moderate	Stubs with Sprouts
SW 14TH TER	Royal Poinciana	11-15"	No	40'	Poor (21% to 40%)		Restricted Canopy	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 14TH TER	Mango	21-30"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Dead Wood	Codominant Leaders - Multi
SW 14TH TER	Mango	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH TER	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 14TH TER	Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 14TH TER	Royal Poinciana	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH TER	Yellow Poinciana	6-10"	No	35'	Poor (21% to 40%)		Topped	Stubs with Sprouts	Restricted Canopy
SW 14TH TER	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Stubs with Sprouts	Lopsided/Reduced Canopy - Major	Decay Observed
SW 14TH TER	Mango	6-10"	No	25'	Fair (41% to 60%)		Stubs with Sprouts		
SW 14TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 14TH TER	Sapodilla	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH TER	Sapodilla	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH TER	Royal Poinciana	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH TER	Silk Floss Tree	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 14TH TER	Southern Magnolia	1-5"	No	5'	Good (61% to 80%)				
SW 14TH TER	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Girdling Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 14TH TER	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Broken Branches	
SW 14TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH TER	Sapodilla	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 14TH TER	Sapodilla	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH TER	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 14TH TER	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 14TH TER	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 14TH TER	Royal Poinciana	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Constricted Roots	Cavities	Crown Density - Moderate
SW 14TH TER	Royal Poinciana	21-30"	No	60'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 14TH TER	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Cavities
SW 14TH TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 14TH TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 14th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 14TH TER	Queen Palm	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 14TH TER	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 14TH TER	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 14TH TER	Umbrella Tree	16-20"	No	25'	Fair (41% to 60%)		Decay Observed	Lopsided/Reduced Canopy - Moderate	Limb Damage - Moderate
SW 14TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 14TH TER	Pink Tabebuia	6-10"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Reduced Canopy - Moderate	Seasonal Defoliation/Discolored Foliage
SW 14TH TER	Weeping Fig	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders - Multi
SW 14TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Trunk Damage - Minor	
SW 14TH TER	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 14TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 14TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 14TH TER	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 14TH TER	Royal Poinciana	6-10"	No	25'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Suppressed Canopy

SW 15th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 15TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 15TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 15TH ST	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 15TH ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 15TH ST	Oriental Arborvitae	11-15"	Yes	15'	Fair (41% to 60%)	Utility Lines Above	Decay Observed	Limb Damage - Moderate	
SW 15TH ST	Oriental Arborvitae	16-20"	Yes	20'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Lifting	Dead Wood
SW 15TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Cabbage Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Major	Discolored Foliage	
SW 15TH ST	Cabbage Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Major	Discolored Foliage	
SW 15TH ST	Areca Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 15TH ST	Weeping Fig	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Vine Cover - Heavy	Stubs with Sprouts	Decay Observed
SW 15TH ST	Silver Buttonwood	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 15TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub	Basal Co-Dominant	
SW 15TH ST	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 15TH ST	Silver Buttonwood	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 15TH ST	Strangler Fig	31-40"	Yes	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 15TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 15TH ST	Oriental Arborvitae	21-30"	Yes	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Lifting	
SW 15TH ST	Mahogany	21-30"	No	30'	Very Poor/Critical (6% to 20%)		Cavities	Codominant Leaders - Multi	Sprouting
SW 15TH ST	Queen Palm	11-15"	No	15'	Good (61% to 80%)				
SW 15TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 15TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 15TH ST	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)				
SW 15TH ST	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 15TH ST	Stragnler Fig	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 15TH ST	Stragnler Fig	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Codominant Leaders - Multi
SW 15TH ST	Avocado	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 15TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Minor	Strap Constricting Tree	

(Continued on Next Page)

Street Tree Inventory

SW 15th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 15TH ST	Royal Poinciana	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 15TH ST	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Nutrient Deficiency	
SW 15TH ST	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Nutrient Deficiency	
SW 15TH ST	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Nutrient Deficiency	
SW 15TH ST	Royal Poinciana	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 15TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 15TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 15TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 15TH ST	Southern Magnolia	1-5"	No	5'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 15TH ST	Live Oak	16-20"	No	35'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 15TH ST	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Major	Nutrient Deficiency	Leaning - Moderate
SW 15TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Nutrient Deficiency	Leaning - Moderate
SW 15TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Nutrient Deficiency	Leaning - Moderate
SW 15TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Nutrient Deficiency	Leaning - Moderate
SW 15TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Nutrient Deficiency	Leaning - Moderate
SW 15TH ST	Yellow Poinciana	16-20"	No	50'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 15TH ST	Areca Palm	6-10"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 15TH ST	Yellow Poinciana	11-15"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders - Multi
SW 15TH ST	Yellow Poinciana	16-20"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 15TH ST	Yellow Poinciana	16-20"	No	15'	Very Poor/Critical (6% to 20%)		Tapered Trunk	Crown Density - Excessive (Due to Epicormic Gro	Trunk Damage - Major
SW 15TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 15TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 15TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 15TH ST	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Cavities
SW 15TH ST	Black Olive	21-30"	No	50'	Poor (21% to 40%)		Trunk Damage - Major	Codominant Leaders - Multi	Stubs with Sprouts
SW 15TH ST	Yellow Poinciana	16-20"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 15TH ST	Yellow Poinciana	21-30"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Trunk Damage - Moderate
SW 15TH ST	Tamarind	21-30"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Trunk Damage - Moderate
SW 15TH ST	Yellow Poinciana	21-30"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Limb Damage - Minor
SW 15TH ST	Yellow Poinciana	21-30"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 15TH ST	Black Olive	21-30"	No	60'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Limb Damage - Moderate
SW 15TH ST	Yellow Poinciana	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Limb Damage - Moderate
SW 15TH ST	Yellow Poinciana	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Limb Damage - Moderate
SW 15TH ST	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 15TH ST	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 15TH ST	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 15TH ST	Mahogany	11-15"	No	40'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 15TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 15TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 15TH ST	Coconut Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 15TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 15TH ST	Bottlebrush	1-5"	No	5'	Good (61% to 80%)				
SW 15TH ST	Bottlebrush	1-5"	No	5'	Good (61% to 80%)				
SW 15TH ST	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 15TH ST	Chickasaw Plum	1-5"	No	10'	Poor (21% to 40%)		Crown Density - Very Low	Discolored Foliage	Dead Wood
SW 15TH ST	Barbados Cherry	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 15TH ST	Red Maple	1-5"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Crown Density - Low	Discolored Foliage
SW 15TH ST	Avocado	1-5"	No	15'	Good (61% to 80%)		Fungus on Leaves	Reduced Canopy - Moderate	

(Continued on Next Page)

Street Tree Inventory

SW 15th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 15TH ST	Christmas Palm	16-20"	Yes	20'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 15TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 15TH ST	Bottle Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 15TH ST	Bottle Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 15TH ST	Bottle Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 15TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 15TH ST	Coconut Palm	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Yellow Tabebuia	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Leaning - Moderate	Restricted Canopy
SW 15TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Damaged Fronds	
SW 15TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 15TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Moderate	
SW 15TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 15TH ST	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Suppressed Canopy	Lopsided/Reduced Canopy - Moderate	Over Extended Limb(s)
SW 15TH ST	Coconut Palm	11-15"	No	20'	Poor (21% to 40%)		Trunk Damage - Moderate	Leaning - Moderate	Nutrient Deficiency
SW 15TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 15TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 15TH ST	Bougainvillea sp.	6-10"	No	10'	Fair (41% to 60%)		Leaning - Moderate		
SW 15TH ST	Montgomery Palm	11-15"	Yes	20'	Good (61% to 80%)				
SW 15TH ST	Montgomery Palm	11-15"	Yes	20'	Good (61% to 80%)				
SW 15TH ST	Solitaire Palm	1-5"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Leaning - Moderate	
SW 15TH ST	Royal Poinciana	16-20"	No	50'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Reduced Canopy - Moderate
SW 15TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Fungus on Leaves		
SW 15TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 15TH ST	Mahogany	16-20"	No	30'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 15TH ST	Sapodilla	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Sapodilla	11-15"	No	25'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Sapodilla	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 15TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 15TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 15TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 15TH ST	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 15TH ST	Satin Leaf	6-10"	No	25'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Moderate	Lifting
SW 15TH ST	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 15TH ST	Mahogany	31-40"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Over Pruned	
SW 15TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Over Pruned	
SW 15TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Over Pruned	
SW 15TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Over Pruned	
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	Restricted Canopy
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	Restricted Canopy
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	Restricted Canopy
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	Restricted Canopy
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	Restricted Canopy
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Moderate	Restricted Canopy

(Continued on Next Page)

Street Tree Inventory

SW 15th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Moderate	Restricted Canopy
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	Restricted Canopy
SW 15TH ST	Coconut Palm	11-15"	No	25'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	Restricted Canopy
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	Restricted Canopy
SW 15TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Leaning - Moderate	
SW 15TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 15TH ST	Christmas Palm	6-10"	Yes	20'	Good (61% to 80%)				
SW 15TH ST	Solitaire Palm	1-5"	Yes	10'	Fair (41% to 60%)		Cracks in Trunk		
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 15TH ST	Brazilian Beauty Leaf	11-15"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 15TH ST	Brazilian Beauty Leaf	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Cavities
SW 15TH ST	Brazilian Beauty Leaf	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 15TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Minor		
SW 15TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Leaning - Minor		
SW 15TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 15TH ST	Mango	11-15"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Broken Branches	
SW 15TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 15TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 15TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Discolored Foliage		
SW 15TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Discolored Foliage		
SW 15TH ST	Live Oak	6-10"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Concave Trunk	
SW 15TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 15TH ST	Golden Shower Tree	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate	Broken Branches	
SW 15TH ST	Yellow Poinciana	16-20"	No	40'	Fair (41% to 60%)		Root Damage/Decay	Leaning - Moderate	Lopsided/Reduced Canopy - Moderate
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Leaning - Moderate	Desiccated Foliage	Trunk Damage - Minor
SW 15TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Pencil Top	Strap Constricting Tree	
SW 15TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Peacock Flower	1-5"	No	15'	Fair (41% to 60%)		Restricted Canopy		
SW 15TH ST	ML UNID 4	1-5"	No	15'	Fair (41% to 60%)		Restricted Canopy		
SW 15TH ST	Spanish Lime	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 15TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 15TH ST	ML UNID 4	1-5"	No	15'	Fair (41% to 60%)		Restricted Canopy		
SW 15TH ST	Spanish Lime	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Leaning - Minor	
SW 15TH ST	ML UNID 4	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy		
SW 15TH ST	ML UNID 4	1-5"	No	10'	Fair (41% to 60%)		Restricted Canopy		
SW 15TH ST	Brazilian Pepper	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 15TH ST	Hong Kong Orchid	1-5"	No	15'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	
SW 15TH ST	Fishtail Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 15TH ST	Black Olive	16-20"	No	20'	Very Poor/Critical (6% to 20%)		Lopsided/Reduced Canopy - Major	Decay Observed	Stubs with Sprouts
SW 15TH ST	Brazilian Pepper	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 15TH ST	Hong Kong Orchid	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy		
SW 15TH ST	Fishtail Palm	21-30"	Yes	20'	Fair (41% to 60%)		Suppressed Canopy	Discolored Foliage	
SW 15TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 15TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Cavities	Stubs with Sprouts
SW 15TH ST	Hong Kong Orchid	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy		
SW 15TH ST	Hong Kong Orchid	6-10"	No	35'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 15th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 15TH ST	Fishtail Palm	31-40"	Yes	25'	Fair (41% to 60%)		Restricted Canopy		
SW 15TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 15TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy		
SW 15TH ST	Royal Poinciana	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	Seasonal Defoliation/Discolored Foliage
SW 15TH ST	Japanese Privet	1-5"	No	5'	Fair (41% to 60%)		Strap Constricting Tree		
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 15TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 15TH ST	Coconut Palm	1-5"	No	10'	Good (61% to 80%)				
SW 15TH ST	Jamaican Dogwood	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 15TH ST	Jamaican Dogwood	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 15TH ST	Jamaican Dogwood	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 15TH ST	Oriental Arborvitae	16-20"	Yes	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 15TH ST	Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 15TH ST	Oriental Arborvitae	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 15TH ST	Pygmy Date Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 15TH ST	Solitaire Palm	11-15"	Yes	20'	Good (61% to 80%)	Utility Line Conflict			
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Minor	Leaning - Moderate	
SW 15TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 15TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 15TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Limb Damage - Moderate
SW 15TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 15TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 15TH ST	Black Olive	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	Utility Pruned
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 15TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Spindle Palm	16-20"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 15TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 15TH ST	Crepe Myrtle	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 15TH ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH ST	Yellow Poinciana	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Limb Damage - Major	Stubs with Sprouts	Reduced Canopy - Moderate
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Improperly Mulched	Strap Constricting Tree	
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Moderate		
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 15TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	16-20"	No	40'	Poor (21% to 40%)		Reduced Canopy - Major	Broken Branches	Stubs with Sprouts
SW 15TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Discolored Foliage		
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 15TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 15TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 15TH ST	Montgomery Palm	11-15"	Yes	20'	Good (61% to 80%)				
SW 15TH ST	Montgomery Palm	6-10"	Yes	10'	Good (61% to 80%)		Damaged Fronds		
SW 15TH ST	Montgomery Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 15TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 15TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 15TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Leaning - Moderate	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 15th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 15TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 15TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Damaged Fronds		
SW 15TH ST	Starburst Clerodendron	6-10"	No	10'	Fair (41% to 60%)		Topped	Stubs with Sprouts	
SW 15TH ST	Starburst Clerodendron	6-10"	No	10'	Fair (41% to 60%)		Topped	Stubs with Sprouts	
SW 15TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 15TH ST	Grapefruit	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Major	Crown Density - Low	Decay Observed
SW 15TH ST	Mahogany	31-40"	No	50'	Very Poor/Critical (6% to 20%)		Constricted Roots	Decay Observed	Sloughing Bark
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 15TH ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Over Pruned	Reduced Canopy - Moderate	
SW 15TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 15TH ST	Queen Crepe Myrtle	1-5"	No	25'	Good (61% to 80%)		Over Extended Limb(s)	Dead Wood	
SW 15TH ST	Washington Palm	11-15"	No	10'	Fair (41% to 60%)		Over Pruned	Reduced Canopy - Moderate	
SW 15TH ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Leaning - Moderate	Restricted Canopy	
SW 15TH ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Leaning - Moderate	Restricted Canopy	
SW 15TH ST	Chinese Fan Palm	11-15"	No	10'	Fair (41% to 60%)				
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 15TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 15TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 15TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 15TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 15TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 15TH ST	Mango	11-15"	No	10'	Very Poor/Critical (6% to 20%)		Topped	Stubs with Sprouts	Fungus on Leaves
SW 15TH ST	Bottlebrush	16-20"	No	20'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Decay Observed	Dead Wood
SW 15TH ST	Bottlebrush	16-20"	No	25'	Poor (21% to 40%)		Reduced Canopy - Moderate	Decay Observed	Crown Density - Low
SW 15TH ST	Vera Wood	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 15TH ST	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 15TH ST	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	
SW 15TH ST	Coconut Palm	11-15"	No	20'	Poor (21% to 40%)		Suppressed Canopy	Leaning - Moderate	
SW 15TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 15TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 15TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)				
SW 15TH ST	Gumbo Limbo	1-5"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 15TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Moderate
SW 15TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Leaning - Moderate		

Terraces



Looking West - SW 12th Avenue



Looking West - Center of Terrace



Looking East - Center of Terrace



Looking East - SW 13th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 15th Terrace	2	Shenandoah North	4	50	600	No	No	Yes	2	City	Yes	Yes	6	yes	yes	southside	Grass swales. Storm drains on both sides at center of street.

SW 15th Terrace

TYPOLOGY B

Street Tree Inventory

SW 15th Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 15TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			

Courts | Avenues



Looking South - SW 8th Street



Looking North - SW 13th Street



Looking North - SW 12th Street



Looking South - SW 11th Street



Looking North - SW 11th Street



Looking North - SW 10th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 12th Court	2	Shenandoah North	4	50	1,800	No	No	Yes	2	City	Few	No	0	yes	yes	west side	Completely paved swales with corner bulb-outs
SW 13th Avenue	2	Shenandoah North	4	100	2,900	Yes, 30ft	No	Yes, North of 13th street	2	City	Yes	Yes	6	yes	yes	within median	Planted median and linear park. Planted swales

SW 12th Court

TYPOLOGY D

SW 13th Avenue

TYPOLOGY F & G

Street Tree Inventory

SW 12th Court

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH CT	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 12TH CT	Weeping Fig	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 12TH CT	Yellow Tabebuia	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 12TH CT	Royal Poinciana	16-20"	No	20'	Good (61% to 80%)		Discolored Foliage	Trunk Damage - Minor	

SW 13th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Black Olive	16-20"	No	30'	Good (61% to 80%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	25'	Fair (41% to 60%)		Leaning - Moderate	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 13TH AVE	Live Oak	11-15"	No	25'	Poor (21% to 40%)		Leaning - Moderate	Trunk Damage - Major	Stubs with Sprouts
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)		Restricted Canopy	Leaning - Minor	
SW 13TH AVE	Black Olive	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Lifting
SW 13TH AVE	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Lifting
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	15'	Good (61% to 80%)				
SW 13TH AVE	African Tulip Tree	21-30"	No	40'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Decay Observed	Stubs with Sprouts
SW 13TH AVE	African Tulip Tree	41-50"	No	65'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Over Extended Limb(s)
SW 13TH AVE	African Tulip Tree	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Reduced Canopy - Moderate
SW 13TH AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Restricted Canopy
SW 13TH AVE	Live Oak	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Restricted Canopy
SW 13TH AVE	Weeping Fig	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 13TH AVE	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)				
SW 13TH AVE	Washington Palm	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major		
SW 13TH AVE	African Tulip Tree	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Reduced Canopy - Moderate
SW 13TH AVE	African Tulip Tree	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 13TH AVE	African Tulip Tree	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Pink Tabebuia	1-5"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Trunk Damage - Major	Restricted Canopy
SW 13TH AVE	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 13TH AVE	African Tulip Tree	31-40"	No	65'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 13TH AVE	Umbrella Tree	6-10"	Yes	20'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Moderate	
SW 13TH AVE	African Tulip Tree	41-50"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH AVE	African Tulip Tree	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 13TH AVE	African Tulip Tree	31-40"	No	65'	Poor (21% to 40%)		Constricted Roots	Leaning - Moderate	Dead Wood
SW 13TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Major	Discolored Foliage	
SW 13TH AVE	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH AVE	African Tulip Tree	21-30"	No	60'	Good (61% to 80%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 13TH AVE	African Tulip Tree	21-30"	No	65'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Reduced Canopy - Moderate
SW 13TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 13TH AVE	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Insect Damage Leaves		
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	25'	Good (61% to 80%)		Leaning - Major	Trunk Damage - Moderate	Codominant Leaders - Multi
SW 13TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 13TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 13TH AVE	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 13TH AVE	Live Oak	1-5"	No	25'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 13TH AVE	Orange Tree	1-5"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Codominant Leaders - Multi	
SW 13TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 13TH AVE	Live Oak	6-10"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate		
SW 13TH AVE	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Broken Branches	

(Continued on Next Page)

Street Tree Inventory

SW 13th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH AVE	Japanese Privet	1-5"	No	10'	Poor (21% to 40%)		Dead Wood	Desiccated Foliage	Stubs with Sprouts
SW 13TH AVE	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH AVE	Pygmy Date Palm	6-10"	Yes	15'	Good (61% to 80%)		Reduced Canopy - Moderate	Over Pruned	
SW 13TH AVE	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Discolored Foliage		
SW 13TH AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)		Leaning - Minor		
SW 13TH AVE	Royal Poinciana	6-10"	Yes	20'	Fair (41% to 60%)		Leaning - Moderate	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Royal Poinciana	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Royal Poinciana	6-10"	Yes	20'	Fair (41% to 60%)		Leaning - Moderate	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Sprouting
SW 13TH AVE	Golden Shower Tree	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 13TH AVE	African Tulip Tree	41-50"	No	45'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Major	Lopsided/Reduced Canopy - Moderate
SW 13TH AVE	Black Olive	31-40"	No	55'	Fair (41% to 60%)		Vine Cover - Heavy	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 13TH AVE	Chinese Fan Palm	16-20"	No	20'	Fair (41% to 60%)		Suppressed Canopy	Fungus on Leaves	
SW 13TH AVE	Black Olive	21-30"	No	55'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Moderate	Decay Observed
SW 13TH AVE	Black Olive	21-30"	No	45'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Dead Wood	Trunk Damage - Moderate
SW 13TH AVE	Live Oak	16-20"	No	50'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 13TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Discolored Foliage	Leaning - Minor	
SW 13TH AVE	Solitaire Palm	1-5"	Yes	10'	Fair (41% to 60%)		Trunk Damage - Minor	Suppressed Canopy	
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	35'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Flush Cuts	Lopsided/Reduced Canopy - Moderate
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Improperly Mulched	Strap Constricting Tree	
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Improperly Mulched	Strap Constricting Tree	
SW 13TH AVE	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 13TH AVE	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Insect Damage Leaves	Trunk Damage - Moderate	
SW 13TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Insect Damage Leaves		
SW 13TH AVE	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 13TH AVE	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Limb Damage - Major	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 13TH AVE	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Leaning - Moderate	Lopsided/Reduced Canopy - Major	
SW 13TH AVE	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Leaning - Moderate	Reduced Canopy - Major	
SW 13TH AVE	Japanese Golden Rain Tree	1-5"	No	10'	Good (61% to 80%)		Stubs with Sprouts	Reduced Canopy - Moderate	
SW 13TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 13TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Broken Branches	Codominant Leaders/Included Bark
SW 13TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Limb Damage - Minor		
SW 13TH AVE	Black Olive	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH AVE	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Restricted Canopy	
SW 13TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 13TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH AVE	Sapodilla	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 13th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Broken Branches	Reduced Canopy - Minor	
SW 13TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Discolored Foliage		
SW 13TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 13TH AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 13TH AVE	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Reduced Canopy - Moderate	
SW 13TH AVE	Sapodilla	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Gumbo Limbo	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 13TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Washington Palm	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Fungus on Leaves	
SW 13TH AVE	African Tulip Tree	21-30"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Reduced Canopy - Moderate
SW 13TH AVE	African Tulip Tree	31-40"	No	70'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 13TH AVE	Live Oak	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Limb Damage - Minor	Codominant Leaders/Included Bark
SW 13TH AVE	Mahogany	6-10"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	
SW 13TH AVE	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Minor	
SW 13TH AVE	Live Oak	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 13TH AVE	Washington Palm	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH AVE	African Tulip Tree	21-30"	No	80'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 13TH AVE	Black Olive	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Leaning - Moderate	Restricted Canopy
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	40'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 13TH AVE	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Reduced Canopy - Moderate	Dead Wood	Cavities
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 13TH AVE	Black Olive	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Crown Density - Low	Dead Wood
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 13TH AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Stubs with Sprouts	Restricted Canopy	
SW 13TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Limb Damage - Moderate	Codominant Leaders - Multi	Stubs with Sprouts
SW 13TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major		
SW 13TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate	Limb Damage - Moderate	
SW 13TH AVE	Crepe Myrtle	1-5"	No	25'	Good (61% to 80%)		Reduced Canopy - Minor	Restricted Canopy	
SW 13TH AVE	Crepe Myrtle	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Crepe Myrtle	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Crepe Myrtle	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Royal Poinciana	16-20"	No	65'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Mostly	Leaning - Moderate	
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Mostly	Leaning - Major	
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Mostly	Leaning - Major	
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Partially	Leaning - Major	
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Mostly	Leaning - Major	
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Fair (41% to 60%)		Uprooted - Partially		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Fair (41% to 60%)		Uprooted - Partially	Leaning - Moderate	
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 13th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Golden Shower Tree	11-15"	No	30'	Poor (21% to 40%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Dead Wood
SW 13TH AVE	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Reduced Canopy - Major	Cavities	Stubs with Sprouts
SW 13TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Crepe Myrtle	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 13TH AVE	Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 13TH AVE	Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	Stubs
SW 13TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Crepe Myrtle	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 13TH AVE	Crepe Myrtle	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor	Restricted Canopy	
SW 13TH AVE	Hong Kong Orchid	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Restricted Canopy	Leaning - Minor
SW 13TH AVE	Kapok	60+"	No	90'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 13TH AVE	Hong Kong Orchid	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 13TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Bottle Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 13TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Christmas Palm	11-15"	No	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Bottle Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Minor	Suppressed Canopy	
SW 13TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Suppressed Canopy	
SW 13TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Suppressed Canopy	
SW 13TH AVE	Vera Wood	1-5"	No	25'	Fair (41% to 60%)		Leaning - Moderate	Reduced Canopy - Moderate	
SW 13TH AVE	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Reduced Canopy - Moderate	
SW 13TH AVE	Mahogany	1-5"	No	Negligible	Dead (0% to 5%)				
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	
SW 13TH AVE	Black Olive	21-30"	No	60'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 13TH AVE	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Restricted Canopy	
SW 13TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 13th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 13TH AVE	Mahogany	11-15"	No	60'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Restricted Canopy
SW 13TH AVE	Banyan	60+"	No	90'	Fair (41% to 60%)		Reduced Canopy - Moderate	Cavities	Restricted Canopy
SW 13TH AVE	Live Oak	16-20"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Live Oak	6-10"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Royal Poinciana	11-15"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Stubs with Sprouts	
SW 13TH AVE	Royal Poinciana	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	
SW 13TH AVE	Royal Poinciana	11-15"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Restricted Canopy
SW 13TH AVE	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Restricted Canopy
SW 13TH AVE	Strangler Fig	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Restricted Canopy
SW 13TH AVE	Yellow Poinciana	1-5"	No	20'	Fair (41% to 60%)		Strap Constricting Tree	Stubs with Sprouts	Reduced Canopy - Minor
SW 13TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Mahogany	6-10"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Crown Density - Low	Stubs with Sprouts
SW 13TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Mahogany	11-15"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Moderate	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Washington Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 13TH AVE	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Live Oak	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Royal Palm	11-15"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Restricted Canopy	Discolored Foliage
SW 13TH AVE	Java Plum	31-40"	No	70'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Rubber Tree	31-40"	No	45'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Leaning - Major	Restricted Canopy
SW 13TH AVE	Java Plum	31-40"	No	60'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Live Oak	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Date Palm	16-20"	No	25'	Fair (41% to 60%)		Ficus Growing on Tree	Restricted Canopy	Discolored Foliage
SW 13TH AVE	Weeping Fig	31-40"	Yes	40'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	
SW 13TH AVE	Gumbo Limbo	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	Trunk Damage - Moderate

(Continued on Next Page)

Street Tree Inventory

SW 13th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Gumbo Limbo	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 13TH AVE	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	
SW 13TH AVE	Weeping Fig	6-10"	Yes	10'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Major	
SW 13TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 13TH AVE	Mahogany	11-15"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Live Oak	6-10"	No	40'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 13TH AVE	Live Oak	6-10"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 13TH AVE	Live Oak	11-15"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 13TH AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Live Oak	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Live Oak	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Live Oak	11-15"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Live Oak	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 13TH AVE	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Date Palm	16-20"	No	25'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Restricted Canopy	Discolored Foliage	Ficus Growing on Tree
SW 13TH AVE	Mahogany	6-10"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate
SW 13TH AVE	Yellow Poinciana	1-5"	No	20'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 13TH AVE	Weeping Fig	21-30"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Moderate	Lion's Tailing	Crown Density - Moderate
SW 13TH AVE	Weeping Fig	31-40"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Over Extended Limb(s)	Decay Observed	Crown Density - Moderate
SW 13TH AVE	Weeping Fig	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Live Oak	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Stubs with Sprouts	
SW 13TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Stubs with Sprouts	
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Fair (41% to 60%)		Concave Trunk	Sloughing Bark	
SW 13TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Stubs with Sprouts	
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Fair (41% to 60%)		Concave Trunk	Sloughing Bark	
SW 13TH AVE	Weeping Fig	21-30"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Utility Pruned	Dead Wood	Over Extended Limb(s)
SW 13TH AVE	Mahogany	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 13TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Reduced Canopy - Moderate	Restricted Canopy
SW 13TH AVE	Mahogany	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Trunk Damage - Moderate
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 13TH AVE	Black Olive	16-20"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Limb Damage - Moderate
SW 13TH AVE	Yellow Poinciana	1-5"	No	20'	Fair (41% to 60%)		Trunk Damage - Major	Reduced Canopy - Moderate	
SW 13TH AVE	Mahogany	16-20"	No	55'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 13TH AVE	Weeping Fig	31-40"	No	60'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Over Extended Limb(s)
SW 13TH AVE	Weeping Fig	21-30"	No	60'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Over Extended Limb(s)
SW 13TH AVE	Weeping Fig	21-30"	No	60'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Over Extended Limb(s)

Courts | Avenues



Looking South - SW 8th Street



Looking South - SW 11th Street



Looking North - SW 11th Street



Looking West - SW 13th Street



Looking South - SW 12th Street



Looking South - SW 13th Street



Looking North - SW 15th Street



Looking North - SW 16th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 13th Court	2	Shenandoah North	4	50	1,800	No	No	Yes	2	City	Few	No	0	yes	yes	west side	completely paved swales with corner bulb-outs
SW 14th Avenue	2	Shenandoah North	4	40-50	2,800	No	No	No	2	City	Yes	Yes	4-6	mostly	yes	westide	Compltely paved swale b/t 8th and 10th street.. Grass swales where curbed south of 10th st.

SW 13th Court

TYPOLOGY D

SW 14th Avenue

TYPOLOGY B & D

Street Tree Inventory

SW 13th Court

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH CT	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 13TH CT	Yellow Tabebuia	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	
SW 13TH CT	Yellow Tabebuia	6-10"	No	30'	Good (61% to 80%)		Leaning - Moderate	Reduced Canopy - Moderate	Limb Damage - Minor
SW 13TH CT	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 13TH CT	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 13TH CT	Black Olive	16-20"	No	50'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Cavities

SW 14th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Discolored Foliage		
SW 14TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 14TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 14TH AVE	Italian Cypress	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Mahogany	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 14TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	
SW 14TH AVE	Royal Poinciana	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 14TH AVE	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	Reduced Canopy - Moderate
SW 14TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots		
SW 14TH AVE	Yellow Poinciana	16-20"	No	45'	Fair (41% to 60%)		Limb Damage - Major	Reduced Canopy - Moderate	
SW 14TH AVE	Peacock Flower	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Moderate	
SW 14TH AVE	Yellow Poinciana	16-20"	No	45'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Codominant Leaders/Included Bark
SW 14TH AVE	Brazilian Pepper	1-5"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 14TH AVE	Mahogany	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 14TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots		
SW 14TH AVE	Yellow Poinciana	1-5"	No	15'	Good (61% to 80%)				
SW 14TH AVE	Mahogany	6-10"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 14TH AVE	Mahogany	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 14TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 14TH AVE	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Reduced Canopy - Major	Trunk Damage - Moderate	Restricted Canopy
SW 14TH AVE	Royal Poinciana	16-20"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Cavities	Restricted Canopy
SW 14TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)		Topped		
SW 14TH AVE	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate
SW 14TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Leaning - Moderate	Suppressed Canopy	
SW 14TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 14TH AVE	Sapodilla	21-30"	No	30'	Poor (21% to 40%)		Decay Observed	Reduced Canopy - Major	Stubs with Sprouts
SW 14TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Tamarind	16-20"	No	55'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 14TH AVE	Areca Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 14TH AVE	Bismark Palm	16-20"	No	20'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Mango	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 14TH AVE	Christmas Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy	Leaning - Moderate	

(Continued on Next Page)

Street Tree Inventory

SW 14th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Christmas Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Discolored Foliage	
SW 14TH AVE	Buccaneer Palm	1-5"	No	10'	Poor (21% to 40%)		Discolored Foliage	Restricted Canopy	
SW 14TH AVE	Buccaneer Palm	1-5"	No	10'	Poor (21% to 40%)		Discolored Foliage	Restricted Canopy	
SW 14TH AVE	Bismark Palm	16-20"	No	20'	Fair (41% to 60%)				
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage	Trunk Damage - Minor	
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 14TH AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Discolored Foliage		
SW 14TH AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Discolored Foliage		
SW 14TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH AVE	Royal Poinciana	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate
SW 14TH AVE	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Lopsided/Reduced Canopy - Moderate
SW 14TH AVE	Oriental Arborvitae	1-5"	No	5'	Good (61% to 80%)				
SW 14TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH AVE	Mango	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Major		
SW 14TH AVE	Mango	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Major		
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Leaning - Moderate	Discolored Foliage	
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Trunk Damage - Minor	
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Major	Crown Density - Low	
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Limb Damage - Moderate	Reduced Canopy - Moderate
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Limb Damage - Moderate	Reduced Canopy - Moderate
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 14TH AVE	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Fungus on Leaves	
SW 14TH AVE	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Fungus on Leaves	
SW 14TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 14TH AVE	Silver Buttonwood	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate	Sprouting	Reduced Canopy - Moderate
SW 14TH AVE	Silver Buttonwood	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate	Sprouting	Reduced Canopy - Moderate
SW 14TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 14TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor		
SW 14TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 14TH AVE	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Cavities	Reduced Canopy - Moderate	Decay Observed
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 14TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)	Utility Lines Above	Tapered Trunk		
SW 14TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Tapered Trunk		
SW 14TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Christmas Palm	1-5"		10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Jacaranda	11-15"		10'	Poor (21% to 40%)	Utility Line Conflict	Leaning - Moderate	Restricted Canopy	Reduced Canopy - Major
SW 14TH AVE	Royal Poinciana	1-5"		10'	Dead (0% to 5%)	Utility Lines Above			
SW 14TH AVE	Tamarind	16-20"		35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts


(Continued on Next Page)

Street Tree Inventory

SW 14th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH AVE	Longan	16-20"		40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH AVE	Banyan	6-10"		30'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Lopsided/Reduced Canopy - Moderate	
SW 14TH AVE	Gumbo Limbo	21-30"		55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Codominant Leaders - Multi
SW 14TH AVE	Japanese Privet	1-5"		10'	Dead (0% to 5%)				
SW 14TH AVE	Mahogany	11-15"		35'	Fair (41% to 60%)		Codominant Leaders - Multi	Reduced Canopy - Moderate	
SW 14TH AVE	Mahogany	6-10"		25'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 14TH AVE	Mahogany	11-15"		25'	Poor (21% to 40%)		Limb Damage - Major	Lopsided/Reduced Canopy - Major	
SW 14TH AVE	Royal Poinciana	21-30"		60'	Fair (41% to 60%)		Reduced Canopy - Moderate	Cavities	
SW 14TH AVE	Royal Poinciana	6-10"		20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Dead Wood	
SW 14TH AVE	Mahogany	11-15"		40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 14TH AVE	Mahogany	21-30"		50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 14TH AVE	Mahogany	6-10"	No	30'	Good (61% to 80%)		Limb Damage - Moderate		
SW 14TH AVE	Mahogany	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	
SW 14TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 14TH AVE	Weeping Fig	16-20"	Yes	30'	Fair (41% to 60%)		Reduced Canopy - Major	Decay Observed	
SW 14TH AVE	Weeping Fig	1-5"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Major	
SW 14TH AVE	Weeping Fig	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Major	Decay Observed
SW 14TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 14TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 14TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 14TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 14TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 14TH AVE	Oriental Arborvitae	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 14TH AVE	Oriental Arborvitae	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		

Avenues



Looking North - SW 11th Street




Looking North - SW 9th Street



Looking North - SW 11th Terrace




Looking North - SW 15th Street



Looking North - SW 9th Street



Looking North - SW 12th Street



Looking North - SW 16th Street



Looking South - SW 10th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 15th Avenue	2	Shenandoah North	4	50	1,400	No	No	Yes	2	City	Yes	Yes	6	Mostly	Yes	East side	Portion between 8th and 9th street blocked off for pedestrian plaza. No curbs on east side between 9th and 10th Street, dirt/gravel swales used for parking
SW 16th Avenue	2	Shenandoah North	4	60	2,800	No	No	Yes	2	City	Yes	Yes	7	Yes	Yes	East side	Roundabout at 11th street. Predominantly grass swales.

SW 15th Avenue

TYPOLOGY B

SW 16th Avenue

TYPOLOGY B

Street Tree Inventory

SW 15th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 15TH AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 15TH AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 15TH AVE	Longan	11-15"	No	25'	Fair (41% to 60%)		Leaning - Moderate	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH AVE		6-10"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH AVE	Weeping Fig	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 15TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 15TH AVE	Hong Kong Orchid	1-5"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Topped
SW 15TH AVE	Hong Kong Orchid	1-5"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Topped
SW 15TH AVE	Hong Kong Orchid	1-5"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Topped
SW 15TH AVE	Hong Kong Orchid	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Major	Stubs with Sprouts	Lifting
SW 15TH AVE	Frangipani	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Moderate	
SW 15TH AVE	Sea Grape	6-10"	Yes	10'	Fair (41% to 60%)		Fungus on Leaves		
SW 15TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 15TH AVE	Simpson's Stopper	1-5"	No	5'	Poor (21% to 40%)		Dead Meristem	Dead Wood	Disease
SW 15TH AVE	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts
SW 15TH AVE	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Leaning - Moderate	Trunk Damage - Moderate	
SW 15TH AVE	Black Olive	21-30"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 15TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Stubs with Sprouts
SW 15TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Stubs with Sprouts
SW 15TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Utility Pruned	Stubs with Sprouts
SW 15TH AVE	Umbrella Tree	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy	Stubs with Sprouts	
SW 15TH AVE	Weeping Fig	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Decay Observed	Utility Pruned
SW 15TH AVE	Weeping Fig	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Stubs	Utility Pruned
SW 15TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 15TH AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 15TH AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Leaning - Minor	
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH AVE	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 15TH AVE	Vera Wood	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 15TH AVE	Live Oak	11-15"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate		
SW 15TH AVE	Live Oak	6-10"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 15TH AVE	Solitaire Palm	6-10"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 15TH AVE	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 15TH AVE	Solitaire Palm	6-10"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 15TH AVE	Solitaire Palm	6-10"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 15TH AVE	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 15TH AVE	Solitaire Palm	6-10"		15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 15TH AVE	Tamarind	6-10"		25'	Fair (41% to 60%)		Suppressed Canopy	Stubs with Sprouts	
SW 15TH AVE	Royal Poinciana	16-20"		45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 15TH AVE	Royal Poinciana	16-20"		40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 15th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 15TH AVE	Royal Palm	11-15"		20'	Good (61% to 80%)		Discolored Foliage		
SW 15TH AVE	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 15TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 15TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 15TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 15TH AVE	Tropical Almond	1-5"	Yes	10'	Good (61% to 80%)				
SW 15TH AVE	Black Olive	11-15"	Yes	35'	Fair (41% to 60%)		Reduced Canopy - Major	Codominant Leaders - Multi	Stubs with Sprouts

SW 16th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Leaning - Moderate	Restricted Canopy	Trunk Damage - Minor
SW 16TH AVE	Strangler Fig	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 16TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH AVE	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 16TH AVE	Rubber Tree	6-10"	No	10'	Very Poor/Critical (6% to 20%)		Leader - Broken	Stubs with Sprouts	Decay Observed
SW 16TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate		
SW 16TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate		
SW 16TH AVE	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Minor	Leaning - Moderate	
SW 16TH AVE	Avocado	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 16TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 16TH AVE	Japanese Privet	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Fungus on Leaves	Desiccated Foliage	
SW 16TH AVE	Japanese Privet	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Fungus on Leaves	Desiccated Foliage	
SW 16TH AVE	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk	Trunk Damage - Moderate	
SW 16TH AVE	Black Olive	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH AVE	Black Olive	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH AVE	Jacaranda	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Leaning - Major	Trunk Damage - Major	Reduced Canopy - Moderate
SW 16TH AVE	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Reduced Canopy - Moderate
SW 16TH AVE	Royal Poinciana	21-30"	No	65'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Reduced Canopy - Moderate
SW 16TH AVE	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy		
SW 16TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 16TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 16TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 16TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 16TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 16TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 16TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 16TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 16TH AVE	Rubber Tree	31-40"	Yes	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 16TH AVE	Rubber Tree	21-30"	Yes	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 16TH AVE	Gumbo Limbo	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	
SW 16TH AVE	Tropical Almond	16-20"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Leaning - Moderate	
SW 16TH AVE	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Decay Observed
SW 16TH AVE	Longan	11-15"	No	40'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 16TH AVE	Starfruit	6-10"	No	10'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Stubs with Sprouts	Crown Density - Low
SW 16TH AVE	Starfruit	11-15"	No	Negligible	Dead (0% to 5%)	Utility Line Conflict			
SW 16TH AVE	Mango	16-20"	No	40'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 16TH AVE	Triangle Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Discolored Foliage		

(Continued on Next Page)

Street Tree Inventory

SW 16th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH AVE	Sapodilla	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Reduced Canopy - Moderate
SW 16TH AVE	Mulberry	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Major	Reduced Canopy - Moderate
SW 16TH AVE	Longan	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Leaning - Moderate	
SW 16TH AVE	Weeping Fig	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Decay Observed	Dead Wood
SW 16TH AVE	Weeping Fig	31-40"	No	15'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Decay Observed	Dead Wood
SW 16TH AVE	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH AVE	Weeping Fig	21-30"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Decay Observed	Dead Wood
SW 16TH AVE	Weeping Fig	6-10"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Decay Observed	Stubs with Sprouts
SW 16TH AVE	Weeping Fig	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	Constricted Roots
SW 16TH AVE	Tamarind	6-10"	No	30'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 16TH AVE	Gumbo Limbo	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Decay Observed	Stubs with Sprouts
SW 16TH AVE	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 16TH AVE	Gumbo Limbo	11-15"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Cavities	Trunk Damage - Major	Reduced Canopy - Moderate
SW 16TH AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 16TH AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 16TH AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 16TH AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Lopsided/Reduced Canopy - Moderate	
SW 16TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Trunk Damage - Moderate	
SW 16TH AVE	Solitaire Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 16TH AVE	Loquat	11-15"	Yes	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Limb Damage - Moderate	
SW 16TH AVE	Strangler Fig	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH AVE	Royal Poinciana	11-15"	No	45'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 16TH AVE	Royal Poinciana	11-15"	No	45'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 16TH AVE	Royal Poinciana	11-15"	No	45'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 16TH AVE	Black Olive	31-40"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Dead Wood	Reduced Canopy - Major
SW 16TH AVE	Black Olive	31-40"	No	70'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Cavities	Reduced Canopy - Moderate
SW 16TH AVE	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 16TH AVE	Black Olive	21-30"	No	45'	Poor (21% to 40%)		Crown Density - Low	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 16TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 16TH AVE	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 16TH AVE	Black Olive	21-30"	No	45'	Poor (21% to 40%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 16TH AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Limb Damage - Major
SW 16TH AVE	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 16TH AVE	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 16TH AVE	Coconut Palm	16-20"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	
SW 16TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Discolored Foliage	Trunk Damage - Minor	
SW 16TH AVE	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Damaged Fronds	Reduced Canopy - Moderate	
SW 16TH AVE	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Damaged Fronds	Reduced Canopy - Moderate	Leaning - Moderate
SW 16TH AVE	Mango	21-30"	No	65'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 16TH AVE	Jamaican Dogwood	6-10"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 16TH AVE	Java Bishopwood	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 16TH AVE	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 16TH AVE	Strangler Fig	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 16TH AVE	Mahogany	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 16TH AVE	Mahogany	11-15"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 16TH AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	Leaning - Moderate
SW 16TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 16TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 16TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 16TH AVE	Live Oak	31-40"	No	70'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	
SW 16TH AVE	Mango	1-5"	No	15'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 16TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Discolored Foliage		

(Continued on Next Page)

Street Tree Inventory

SW 16th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH AVE	Mango	1-5"	No	10'	Good (61% to 80%)		Discolored Foliage		
SW 16TH AVE		1-5"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Moderate	
SW 16TH AVE	Pink Tabebuia	16-20"	No	25'	Fair (41% to 60%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH AVE	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 16TH AVE	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders - Multi
SW 16TH AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Reduced Canopy - Moderate
SW 16TH AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Reduced Canopy - Moderate
SW 16TH AVE	Guiana Chestnut	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH AVE	Umbrella Tree	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Reduced Canopy - Moderate
SW 16TH AVE	Longan	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Cavities
SW 16TH AVE	Oriental Arborvitae	16-20"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Limb Damage - Moderate
SW 16TH AVE	Oriental Arborvitae	16-20"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 16TH AVE	Norfolk Pine	21-30"	No	35'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Reduced Canopy - Moderate	
SW 16TH AVE	Sapodilla	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	
SW 16TH AVE	Chinese Golden Rain Tree	11-15"	No	25'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Dead Wood	Cavities
SW 16TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH AVE	Black Olive	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 16TH AVE	Coconut Palm	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Leaning - Moderate	Damaged Fronds	Reduced Canopy - Major
SW 16TH AVE	Coconut Palm	16-20"	Yes	30'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 16TH AVE	Coconut Palm	11-15"	No	25'	Fair (41% to 60%)		Discolored Foliage		
SW 16TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Discolored Foliage		
SW 16TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Discolored Foliage		
SW 16TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Discolored Foliage		
SW 16TH AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Discolored Foliage		
SW 16TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Discolored Foliage		
SW 16TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 16TH AVE	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 16TH AVE	Royal Poinciana	1-5"	No	20'	Good (61% to 80%)				
SW 16TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH AVE	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Reduced Canopy - Moderate	Root Damage/Decay	Stubs with Sprouts
SW 16TH AVE	Yellow Tabebuia	11-15"	No	30'	Good (61% to 80%)		Suppressed Canopy	Reduced Canopy - Moderate	
SW 16TH AVE	Jacaranda	11-15"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 16TH AVE	Jacaranda	6-10"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 16TH AVE	Gauva (Common)	6-10"	Yes	20'	Good (61% to 80%)				
SW 16TH AVE	Queen Palm	11-15"	No	20'	Good (61% to 80%)				
SW 16TH AVE	Sapodilla	1-5"	No	10'	Good (61% to 80%)				
SW 16TH AVE	Sapodilla	1-5"	No	10'	Good (61% to 80%)				
SW 16TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH AVE	Royal Palm	16-20"	No	25'	Good (61% to 80%)		Discolored Foliage		
SW 16TH AVE	Royal Palm	16-20"	No	25'	Good (61% to 80%)		Discolored Foliage		
SW 16TH AVE	Royal Palm	16-20"	No	25'	Fair (41% to 60%)		Discolored Foliage	Reduced Canopy - Moderate	

Avenues



Looking North - SW 15th Street



Looking North - SW 16th Terrace



Looking North - SW 10th Street



Looking North - SW 13th Street



Looking South - SW 10th Street



Looking South - SW 15th Street



Looking North - SW 14th Street



Looking North - SW 16th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 17th Avenue	2	Shenandoah North	4	70	2,700	Some, 6ft	No	No	2	County	Few	No	0	Yes	Yes	West side	Main thoroughfare. Shared use bike lane going both directions. Pedestrian crosswalk at 14th, 12th, and 10th streets. Some vegetated medians with new tree plantings
SW 18th Avenue	2	Shenandoah North	4	60	2,700	No	No	Yes	2	City	Yes	Yes	7	Some	Yes	No	Predominantly grass swales, dirt swales between 8th and 9th street. Roundabouts at 13th and 16th street.

SW 17th Avenue

TYPOLOGY E

SW 18th Avenue

TYPOLOGY B

Street Tree Inventory

SW 17th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH AVE	Hong Kong Orchid	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Hong Kong Orchid	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Strap Constricting Tree	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		Reduced Canopy - Moderate
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		Reduced Canopy - Moderate
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		

SW 18th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH AVE	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Trunk Damage - Major	Tapered Trunk	
SW 18TH AVE	Gumbo Limbo	16-20"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	
SW 18TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)				
SW 18TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Codominant Leaders - Multi
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Nutrient Deficiency	
SW 18TH AVE	Yellow Tabebuia	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 18TH AVE	Yellow Tabebuia	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate	Stubs with Sprouts
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Nutrient Deficiency	
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	Leaning - Moderate
SW 18TH AVE	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Nutrient Deficiency	
SW 18TH AVE	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 18TH AVE	Bottle Palm	21-30"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Over Pruned	
SW 18TH AVE	Bottle Palm	16-20"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Over Pruned	Trunk Damage - Minor
SW 18TH AVE	Bottle Palm	21-30"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Over Pruned	
SW 18TH AVE	Bottle Palm	16-20"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Over Pruned	
SW 18TH AVE	Bottle Palm	16-20"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Over Pruned	
SW 18TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 18TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Tapered Trunk	Broken Branches	
SW 18TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Broken Branches		
SW 18TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 18TH AVE	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Stubs with Sprouts	
SW 18TH AVE	Tamarind	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Trunk Damage - Moderate
SW 18TH AVE	Tamarind	16-20"	No	45'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 18TH AVE	Royal Poinciana	31-40"	No	60'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Root Damage/Decay	Cavities	Reduced Canopy - Moderate
SW 18TH AVE	Gumbo Limbo	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	
SW 18TH AVE	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor	Codominant Leaders/No Included Bark	
SW 18TH AVE	Gumbo Limbo	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 18TH AVE	Gumbo Limbo	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 18TH AVE	Hong Kong Orchid	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Nutrient Deficiency
SW 18TH AVE	Queen Palm	11-15"	No	20'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 18TH AVE	Queen Palm	11-15"	No	20'	Good (61% to 80%)				
SW 18TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 18th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Lifting	
SW 18TH AVE	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate		
SW 18TH AVE	Royal Poinciana	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 18TH AVE	Royal Poinciana	6-10"	No	40'	Good (61% to 80%)		Reduced Canopy - Minor	Limb Damage - Minor	
SW 18TH AVE	Royal Poinciana	11-15"	No	40'	Good (61% to 80%)		Reduced Canopy - Minor	Limb Damage - Minor	
SW 18TH AVE	Pink Tabebuia	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 18TH AVE	Pink Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 18TH AVE	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 18TH AVE	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Limb Damage - Major	Restricted Canopy	
SW 18TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 18TH AVE	Live Oak	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 18TH AVE	Live Oak	1-5"	No	15'	Poor (21% to 40%)		Suppressed Canopy	Stubs with Sprouts	
SW 18TH AVE	Live Oak	21-30"	No	55'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 18TH AVE	Live Oak	6-10"	No	20'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Restricted Canopy	
SW 18TH AVE	Live Oak	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 18TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 18TH AVE	Yellow Tabebuia	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Leaning - Moderate	Lopsided/Reduced Canopy - Moderate
SW 18TH AVE	Spanish Lime	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate
SW 18TH AVE	Spanish Lime	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 18TH AVE	Brazilian Beauty Leaf	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Lifting	Stubs with Sprouts
SW 18TH AVE	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Moderate	
SW 18TH AVE	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Moderate	
SW 18TH AVE	Mahogany	21-30"	No	55'	Very Poor/Critical (6% to 20%)		Lopsided/Reduced Canopy - Major	Cavities	Leaning - Major
SW 18TH AVE	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Moderate
SW 18TH AVE	Frangipani	6-10"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Dead Wood	Discolored Foliage
SW 18TH AVE	Mango	11-15"	No	20'	Fair (41% to 60%)		Stubs with Sprouts		
SW 18TH AVE	Barbados Cherry	1-5"	No	10'	Good (61% to 80%)		Stubs with Sprouts	Restricted Canopy	
SW 18TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Damaged Fronds	Nutrient Deficiency	
SW 18TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 18TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Leaning - Moderate	
SW 18TH AVE	Coconut Palm	11-15"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Mango	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 18TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Pink Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 18TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 18TH AVE	Queen Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Queen Palm	6-10"	No	10'	Poor (21% to 40%)		Tapered Trunk	Reduced Canopy - Moderate	Discolored Foliage
SW 18TH AVE	Pink Cassia	1-5"	No	5'	Fair (41% to 60%)				
SW 18TH AVE	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 18TH AVE	Weeping Fig	11-15"	Yes	10'	Poor (21% to 40%)		Reduced Canopy - Moderate	Decay Observed	
SW 18TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 18TH AVE	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 18TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 18TH AVE	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 18TH AVE	Pink Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Minor	
SW 18TH AVE	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Minor	
SW 18TH AVE	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Pruned Into Shrub		
SW 18TH AVE	Talipot Palm	6-10"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 18th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH AVE	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 18TH AVE	Yellow Tabebuia	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 18TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 18TH AVE	Pink Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 18TH AVE	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Desiccated Foliage		
SW 18TH AVE	Pink Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 18TH AVE	Pink Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 18TH AVE	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 18TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Golden Shower Tree	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 18TH AVE	Sea Grape	21-30"	Yes	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor	Nutrient Deficiency	
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Leaning - Moderate	Nutrient Deficiency	
SW 18TH AVE	Gumbo Limbo	6-10"	No	20'	Poor (21% to 40%)		Leaning - Major	Lopsided/Reduced Canopy - Major	
SW 18TH AVE	Gumbo Limbo	6-10"	No	35'	Fair (41% to 60%)		Leaning - Moderate	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 18TH AVE	Gumbo Limbo	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 18TH AVE	Gumbo Limbo	1-5"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 18TH AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 18TH AVE	Live Oak	11-15"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 18TH AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Gumbo Limbo	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 18TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 18TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 18TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 18TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 18TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 18TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 18TH AVE	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Spindle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 18TH AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 18TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH AVE	Gumbo Limbo	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 18TH AVE	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	

Avenues



Looking North - SW 9th Street



Looking North - SW 11th Street



Looking South - SW 9th Street




Looking South - SW 10th Street



Looking North - SW 14th Street



Looking North - SW 16th Street



Looking North - SW 10th Street



Looking North - SW 16th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 19th Avenue	2	Shenandoah North	4	50	2,700	No	No	Yes	2	City	Yes	Yes	5	Mostly	Yes	No	Paved swales south of 14th Terrace. Roundabout at 14th Terrace. Some segments with no curbs north of 11th street.
SW 20th Avenue	2	Shenandoah North	4	40-50	1,100	No	No	Mostly	2	City	Yes	Some	5	Yes	Yes	East side	Divided into three segments. No Street parking and ROW 40' between 14th Terr.. and 16th Street. Paved swales between 8th and 9th street, with vegetated bulb outs along East side.

SW 19th Avenue

TYPOLOGY B & D

SW 20th Avenue

TYPOLOGY B & D

Street Tree Inventory

SW 19th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH AVE	Peacock Flower	1-5"	Yes	10'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH AVE	Dracaena sp.	11-15"	Yes	10'	Fair (41% to 60%)		Stubs with Sprouts		
SW 19TH AVE	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 19TH AVE	Dracaena sp.	11-15"	Yes	10'	Fair (41% to 60%)		Stubs with Sprouts		
SW 19TH AVE	Dracaena sp.	11-15"	Yes	10'	Fair (41% to 60%)		Stubs with Sprouts		
SW 19TH AVE	Dracaena sp.	11-15"	Yes	10'	Fair (41% to 60%)		Stubs with Sprouts		
SW 19TH AVE	Dracaena sp.	11-15"	Yes	10'	Fair (41% to 60%)		Stubs with Sprouts		
SW 19TH AVE	Dracaena sp.	11-15"	Yes	10'	Fair (41% to 60%)		Stubs with Sprouts		
SW 19TH AVE	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 19TH AVE	Sea Grape	6-10"	No	10'	Fair (41% to 60%)		Pruned Into Shrub	Cavities	
SW 19TH AVE	Sea Grape	6-10"	No	10'	Fair (41% to 60%)		Pruned Into Shrub	Cavities	
SW 19TH AVE	Dracaena sp.	21-30"	Yes	20'	Fair (41% to 60%)	Utility Line Conflict	Stubs with Sprouts		
SW 19TH AVE	Dracaena sp.	11-15"	Yes	15'	Fair (41% to 60%)	Utility Line Conflict	Stubs with Sprouts		
SW 19TH AVE	Sea Grape	1-5"	Yes	5'	Fair (41% to 60%)	Utility Line Conflict	Pruned Into Shrub		
SW 19TH AVE	Indian Laurel Fig	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Restricted Canopy
SW 19TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 19TH AVE	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Codominant Leaders - Multi
SW 19TH AVE	Java Plum	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 19TH AVE	Marlberry	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Moderate	Discolored Foliage	Crown Density - Low
SW 19TH AVE	Marlberry	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Moderate	Leader - Broken	Crown Density - Low
SW 19TH AVE	Marlberry	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 19TH AVE	Frangipani	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Nutrient Deficiency	
SW 19TH AVE	Royal Poinciana	6-10"	No	35'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 19TH AVE	Bridalveil Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Tapered Trunk	
SW 19TH AVE	Bridalveil Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 19TH AVE	Pink Cassia	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 19TH AVE	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Royal Poinciana	21-30"	No	50'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Cavities	Reduced Canopy - Moderate
SW 19TH AVE	Mimosa/Silk Tree	1-5"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Queen Crepe Myrtle	1-5"	No	20'	Good (61% to 80%)				
SW 19TH AVE	Papaya	1-5"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Royal Poinciana	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Over Extended Limb(s)
SW 19TH AVE	Royal Poinciana	11-15"	No	35'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Suppressed Canopy	Crown Density - Very Low
SW 19TH AVE	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Suppressed Canopy	Crown Density - Low
SW 19TH AVE	Vera Wood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 19TH AVE	Crepe Myrtle	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Crown Density - Low	Dead Wood
SW 19TH AVE	Vera Wood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Restricted Canopy	
SW 19TH AVE	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	
SW 19TH AVE	Talipot Palm	16-20"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 19TH AVE	Talipot Palm	16-20"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 19TH AVE	Purple Tabebuia	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 19TH AVE	Purple Tabebuia	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 19TH AVE	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 19TH AVE	Talipot Palm	21-30"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 19TH AVE	Talipot Palm	11-15"	No	10'	Poor (21% to 40%)		Reduced Canopy - Moderate	Suppressed Canopy	Nutrient Deficiency
SW 19TH AVE	Florida Thatch Palm	11-15"	No	10'	Good (61% to 80%)		Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 19th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH AVE	Talipot Palm	21-30"	No	10'	Good (61% to 80%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 19TH AVE	Talipot Palm	21-30"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Damaged Fronds	
SW 19TH AVE	Talipot Palm	6-10"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Cavities	Stubs with Sprouts
SW 19TH AVE	Sapodilla	11-15"	No	25'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Crown Density - Low
SW 19TH AVE	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/No Included Bark
SW 19TH AVE	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 19TH AVE	Talipot Palm	21-30"	No	10'	Good (61% to 80%)				
SW 19TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH AVE	Talipot Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Peacock Flower	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH AVE	Allspice	1-5"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Peacock Flower	1-5"	No	10'	Good (61% to 80%)				
SW 19TH AVE	Royal Poinciana	11-15"	No	25'	Good (61% to 80%)		Limb Damage - Minor		
SW 19TH AVE	Japanese Privet	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Trunk Damage - Moderate
SW 19TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 19TH AVE	ML UNID 3	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Lifting	
SW 19TH AVE	Black Olive	16-20"	No	50'	Poor (21% to 40%)		Reduced Canopy - Moderate	Trunk Damage - Major	Cavities
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH AVE	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH AVE	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Leaning - Minor		
SW 19TH AVE	Coconut Palm	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 19TH AVE	Vera Wood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Limb Damage - Moderate	
SW 19TH AVE	Satin Leaf	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low	Dead Wood	Desiccated Foliage
SW 19TH AVE	Talipot Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Royal Poinciana	1-5"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Broken Branches	
SW 19TH AVE	Allspice	1-5"	No	10'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 19TH AVE	Allspice	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 19TH AVE	Talipot Palm	21-30"	No	15'	Fair (41% to 60%)		Discolored Foliage		
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Restricted Canopy	Vine Cover - Heavy	
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH AVE	Mango	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate
SW 19TH AVE	Golden Shower Tree	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Trunk Damage - Moderate
SW 19TH AVE	Talipot Palm	16-20"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Damaged Fronds
SW 19TH AVE	Talipot Palm	16-20"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH AVE	Mango	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 19TH AVE	Mango	6-10"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 19TH AVE	Spanish Lime	16-20"	No	25'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Codominant Leaders - Multi
SW 19TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 19th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Nutrient Deficiency	
SW 19TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Nutrient Deficiency	
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Nutrient Deficiency	
SW 19TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Nutrient Deficiency	
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Nutrient Deficiency	
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Nutrient Deficiency	
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Nutrient Deficiency	
SW 19TH AVE	Sapodilla	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 19TH AVE	Lead Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 19TH AVE	Bridalveil Tree	6-10"	No	30'	Fair (41% to 60%)	Utility Lines Above	Girdling Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 19TH AVE	Bridalveil Tree	1-5"	No	30'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 19TH AVE	Bridalveil Tree	1-5"	No	25'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 19TH AVE	Vera Wood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Royal Poinciana	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Reduced Canopy - Moderate	
SW 19TH AVE	Desert Cassia	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Codominant Leaders - Multi	Reduced Canopy - Moderate	
SW 19TH AVE	Desert Cassia	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders - Multi		
SW 19TH AVE	Royal Poinciana	21-30"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Crown Density - Very Low
SW 19TH AVE	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Girdling Roots	Reduced Canopy - Moderate	
SW 19TH AVE	Bridalveil Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 19TH AVE	Pink Cassia	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 19TH AVE	Pink Cassia	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 19TH AVE	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy	Reduced Canopy - Moderate	
SW 19TH AVE	Crepe Myrtle	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Crown Density - Low	
SW 19TH AVE	Silk Floss Tree	6-10"	No	25'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor		
SW 19TH AVE	Bridalveil Tree	1-5"	No	25'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor		
SW 19TH AVE	Bridalveil Tree	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Leaning - Minor	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 19TH AVE	Bridalveil Tree	1-5"	No	20'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate	Strap Constricting Tree	
SW 19TH AVE	Bridalveil Tree	6-10"	No	30'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 19TH AVE	Bridalveil Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate	Trunk Damage - Minor	
SW 19TH AVE	Royal Poinciana	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH AVE	Bridalveil Tree	1-5"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Reduced Canopy - Minor	
SW 19TH AVE	Bridalveil Tree	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH AVE	Bridalveil Tree	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Reduced Canopy - Minor	
SW 19TH AVE	Royal Poinciana	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Reduced Canopy - Minor	
SW 19TH AVE	Royal Poinciana	6-10"	No	25'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Limb Damage - Moderate	Reduced Canopy - Moderate
SW 19TH AVE	Dracaena sp.	16-20"	No	15'	Good (61% to 80%)		Stubs with Sprouts		
SW 19TH AVE	Vera Wood	1-5"	No	10'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Discolored Foliage	Reduced Canopy - Moderate
SW 19TH AVE	Pink Tabebuia	6-10"	No	30'	Fair (41% to 60%)		Leaning - Moderate	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 19TH AVE	Green Buttonwood	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 19TH AVE	Green Buttonwood	6-10"	No	20'	Poor (21% to 40%)		Leaning - Moderate	Reduced Canopy - Major	Stubs with Sprouts
SW 19TH AVE	Avocado	1-5"	No	10'	Poor (21% to 40%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 19TH AVE	Green Buttonwood	6-10"	No	20'	Poor (21% to 40%)		Leaning - Moderate	Reduced Canopy - Major	Stubs with Sprouts
SW 19TH AVE	Green Buttonwood	11-15"	No	20'	Poor (21% to 40%)		Leaning - Moderate	Reduced Canopy - Major	Stubs with Sprouts
SW 19TH AVE	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 19TH AVE	Green Buttonwood	6-10"	No	25'	Poor (21% to 40%)		Leaning - Moderate	Reduced Canopy - Moderate	Stubs with Sprouts
SW 19TH AVE	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 19TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		

(Continued on Next Page)

Street Tree Inventory

SW 19th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	1-5"	No	5'	Poor (21% to 40%)		Desiccated Foliage	Fungus on Leaves	Trunk Damage - Minor
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Cracks in Trunk	Trunk Damage - Moderate	
SW 19TH AVE	Christmas Palm	1-5"	Yes	10'	Fair (41% to 60%)		Cracks in Trunk	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 19TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 19TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 19TH AVE	Crepe Myrtle	1-5"	No	10'	Poor (21% to 40%)		Trunk Damage - Major	Strap Constricting Tree	Crown Density - Low
SW 19TH AVE	Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Strap Constricting Tree	Crown Density - Low
SW 19TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 19TH AVE	Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 19TH AVE	Royal Palm	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Cavities		

SW 20th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Lopsided/Reduced Canopy - Moderate	Suppressed Canopy
SW 20TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 20TH AVE	Crepe Myrtle	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 20TH AVE	Crepe Myrtle	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 20TH AVE	Crepe Myrtle	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 20TH AVE	Crepe Myrtle	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 20TH AVE	Crepe Myrtle	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Restricted Canopy	
SW 20TH AVE	Gumbo Limbo	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Limb Damage - Major	Stubs with Sprouts
SW 20TH AVE	Kapok	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 20TH AVE	Sapodilla	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 20TH AVE	Bismark Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Leaning - Moderate	Reduced Canopy - Moderate	Restricted Canopy
SW 20TH AVE	Gumbo Limbo	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 20TH AVE	Gumbo Limbo	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 20TH AVE	Spanish Lime	6-10"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 20TH AVE	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 20TH AVE	Tropical Almond	6-10"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 20TH AVE	Java Plum	1-5"	No	5'	Good (61% to 80%)				
SW 20TH AVE	Pink Cassia	1-5"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 20TH AVE	Pink Cassia	1-5"	No	10'	Poor (21% to 40%)		Crown Density - Low	Discolored Foliage	Reduced Canopy - Moderate
SW 20TH AVE	Pink Cassia	1-5"	No	10'	Good (61% to 80%)				
SW 20TH AVE	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 20TH AVE	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 20TH AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 20TH AVE	Pink Cassia	1-5"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 20TH AVE	Pink Cassia	1-5"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 20TH AVE	Pink Cassia	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	
SW 20TH AVE	Pink Cassia	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	
SW 20TH AVE	Pygmy Date Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH AVE	Pygmy Date Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Damaged Fronds		
SW 20TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Damaged Fronds		

(Continued on Next Page)

Street Tree Inventory

SW 20th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH AVE	Solitaire Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 20TH AVE	Florida Thatch Palm	6-10"	No	5'	Good (61% to 80%)				
SW 20TH AVE	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 20TH AVE	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 20TH AVE	Sacred Fig	21-30"	No	35'	Very Poor/Critical (6% to 20%)		Leaning - Major	Cavities	Stubs with Sprouts
SW 20TH AVE	Sacred Fig	21-30"	No	35'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Cavities	Stubs with Sprouts
SW 20TH AVE	Sacred Fig	16-20"	No	40'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Cavities	Stubs with Sprouts
SW 20TH AVE	Sacred Fig	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Cavities	Stubs with Sprouts
SW 20TH AVE	Gumbo Limbo	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 20TH AVE	Gumbo Limbo	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Lopsided/Reduced Canopy - Major
SW 20TH AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	
SW 20TH AVE	Strangler Fig	60+"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 20TH AVE	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 20TH AVE	Royal Palm	11-15"	No	Negligible	Dead (0% to 5%)	Utility Line Conflict			



Looking North - SW 16th Street




Looking North - SW 12th Street



Looking North - SW 13th Street



Looking South - Dead End



Looking North - SW 14th Terrace



Looking North - SW 16th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 20th Court	2	Shenandoah North	4	40	300	No	No	Yes	2	City	No	No	0	Yes	Yes	No	Dead end street.
SW 21st Avenue	2	Shenandoah North	4	50	2,000	No	No	Yes	2	City	Some	Yes	5	Yes	Yes	West side	No swales on East side between 10th and 12th street. Roundabout at 16th Street.

SW 20th Court

TYPOLOGY D

SW 21st Avenue

TYPOLOGY B & D

Street Tree Inventory

*Note SW 20th Court has no trees

SW 21st Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Weeping Fig	6-10"	No	15'	Good (61% to 80%)				
SW 21ST AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 21ST AVE	Coconut Palm	11-15"	No	25'	Fair (41% to 60%)		Leaning - Moderate	Nutrient Deficiency	
SW 21ST AVE	Coconut Palm	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	Suppressed Canopy
SW 21ST AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 21ST AVE	Weeping Fig	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 21ST AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 21ST AVE	Pink Cassia	6-10"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Over Extended Limb(s)
SW 21ST AVE	Red Latan Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Moderate
SW 21ST AVE	Hong Kong Orchid	21-30"	No	40'	Poor (21% to 40%)		Cavities	Stubs with Sprouts	Constricted Roots
SW 21ST AVE	Black Olive	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 21ST AVE	Black Olive	16-20"	No	30'	Very Poor/Critical (6% to 20%)		Constricted Roots	Crown Density - Very Low	Dead Wood
SW 21ST AVE	Black Olive	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Constricted Roots	Crown Density - Low	Discolored Foliage
SW 21ST AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Coconut Palm	6-10"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Constricted Roots
SW 21ST AVE	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Constricted Roots
SW 21ST AVE	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Constricted Roots
SW 21ST AVE	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Constricted Roots
SW 21ST AVE	Sea Grape	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Brazilian Beauty Leaf	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Leader - Broken	Reduced Canopy - Minor
SW 21ST AVE	Japanese Privet	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Java Plum	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Topped	Stubs with Sprouts	Reduced Canopy - Major
SW 21ST AVE	Java Plum	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Topped	Stubs with Sprouts	Reduced Canopy - Major
SW 21ST AVE	Sea Grape	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 21ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy	Leaning - Moderate	
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 21ST AVE	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory


SW 21st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy	Trunk Damage - Minor	
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy	Trunk Damage - Minor	
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 21ST AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 21ST AVE	Bridalveil Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 21ST AVE	Mimosa/Silk Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Codominant Leaders - Multi	
SW 21ST AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Reduced Canopy - Moderate	
SW 21ST AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate	Crown Density - Moderate	
SW 21ST AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 21ST AVE	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 21ST AVE	Talipot Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Tapered Trunk	
SW 21ST AVE	Bridalveil Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 21ST AVE	Bridalveil Tree	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Trunk Damage - Moderate	
SW 21ST AVE	Bridalveil Tree	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 21ST AVE	Christmas Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate		
SW 21ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 21ST AVE	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 21ST AVE	Mahogany	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Cavities	Reduced Canopy - Moderate
SW 21ST AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 21ST AVE	Bottlebrush	21-30"	No	30'	Poor (21% to 40%)		Reduced Canopy - Major	Lifting	Codominant Leaders - Multi
SW 21ST AVE	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 21ST AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Washington Palm	11-15"	No	20'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 21ST AVE	ML UNID 5	1-5"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs	

Courts | Avenues



Looking North - SW 11th Street




Looking North - SW 14th Street



Looking North - SW 13th Street



Looking South - SW 13th Street



Looking South - SW 10th Street



Looking South - SW 12th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 22nd Avenue	2	Shenandoah North	4	75	2,700	Some, 11ft	No	No	4	County	Few	Few	0	Yes	Yes	West side	Main thoroughfare. Some vegetated islands along median of road.
SW 22nd Court	2	Shenandoah North	4	50	300	No	Yes	No	2	City	Few	Few	6	West side	Yes	No	On-street parking for Bryan Park on West side. Vegetated bulb outs at intersections. Swales only on West side.

SW 22nd Avenue

TYPOLOGY E

SW 22nd Court

TYPOLOGY B & E

Street Tree Inventory

SW 22nd Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND AVE	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Tapered Trunk		
SW 22ND AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 22ND AVE	Green Buttonwood	1-5"	No	20'	Good (61% to 80%)	Utility Line Conflict	Leaning - Minor	Lifting	Sprouting
SW 22ND AVE	Green Buttonwood	6-10"	No	25'	Good (61% to 80%)		Limb Damage - Moderate	Broken Branches	
SW 22ND AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 22ND AVE	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Limb Damage - Moderate	Stubs with Sprouts
SW 22ND AVE	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Broken Branches	Stubs with Sprouts
SW 22ND AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Leaning - Moderate	Crown Density - Low	Dead Wood
SW 22ND AVE	Yellow Tabebuia	11-15"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Leaning - Major	
SW 22ND AVE	Yellow Poinciana	16-20"	No	45'	Good (61% to 80%)		Limb Damage - Moderate	Codominant Leaders/Included Bark	
SW 22ND AVE	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Broken Branches	Crown Density - Low
SW 22ND AVE	Royal Poinciana	16-20"	No	25'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Reduced Canopy - Moderate	Stubs with Sprouts
SW 22ND AVE	Carrotwood	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots		
SW 22ND AVE	Yellow Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 22ND AVE	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 22ND AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 22ND AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 22ND AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Trunk Damage - Minor		

SW 22nd Court

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND CT	Live Oak	11-15"	No	40'	Good (61% to 80%)		Trunk Damage - Moderate		

Courts | Avenues



Looking North - SW 10th Street



Looking North - SW 12th Street



Looking North - SW 13th Street



Looking North - SW 14th Street



Looking North - SW 16th Street



Looking South - SW 12th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 23rd Avenue	2	Shenandoah North	4	30-75	2,350	No	No	Yes, North of 10th Street	2	City	Yes	Few	9 (20 btw 11th and 12th St)	North of 10th street.	North of 13th street.	West side south of 13th street	ROW 30' btw 13th and 16th street, 75' btw 13th and 10th street, and 50' btw 10th and 8th street. Segmented by Bryan Park at 12th and 13th street. Dirt swales on 30' segment, large curbless swales on 70' segment, and valley gutters along 50' segment.
SW 23rd Court	2	Shenandoah North	4	50	300	No	Yes	No	2	City	No	No	4	East side	Yes	No	On-street parking for Bryan Park on East side. Vegetated bulb outs at intersections. Swale only on east side

SW 23rd Avenue

TYPOLOGY B & A & D

SW 23rd Court

TYPOLOGY B & E

Street Tree Inventory

*Note SW 23rd Court has no trees

SW 23rd Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD AVE	Sacred Fig	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Major	Decay Observed	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	21-30"	Yes	30'	Fair (41% to 60%)		Sprouting	Decay Observed	
SW 23RD AVE	Sacred Fig	11-15"	No	30'	Good (61% to 80%)		Over Extended Limb(s)	Codominant Leaders/Included Bark	
SW 23RD AVE	Sacred Fig	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Major	Stubs with Sprouts	Cavities
SW 23RD AVE	Sacred Fig	16-20"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Decay Observed	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	31-40"	No	45'	Fair (41% to 60%)		Reduced Canopy - Major	Decay Observed	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	16-20"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Cavities	Over Extended Limb(s)
SW 23RD AVE	Sacred Fig	11-15"	No	40'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Topped	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	16-20"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Topped	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	21-30"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Cavities	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	21-30"	No	50'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate	Cavities
SW 23RD AVE	Sacred Fig	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Major	Topped	Sprouting
SW 23RD AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 23RD AVE	Royal Poinciana	11-15"	Yes	45'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Restricted Canopy
SW 23RD AVE	Royal Poinciana	16-20"	No	55'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Restricted Canopy
SW 23RD AVE	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 23RD AVE	Sacred Fig	16-20"	No	40'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders - Multi	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	21-30"	No	45'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Cavities	Codominant Leaders/Included Bark
SW 23RD AVE	Sacred Fig	16-20"	No	45'	Fair (41% to 60%)		Stubs with Sprouts	Codominant Leaders - Multi	
SW 23RD AVE	Satin Leaf	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD AVE	Sacred Fig	16-20"	No	50'	Fair (41% to 60%)		Stubs with Sprouts	Limb Damage - Moderate	Over Extended Limb(s)
SW 23RD AVE	Sacred Fig	16-20"	No	35'	Fair (41% to 60%)		Stubs with Sprouts	Limb Damage - Major	Decay Observed
SW 23RD AVE	Sacred Fig	11-15"	No	25'	Very Poor/Critical (6% to 20%)		Topped	Stubs with Sprouts	Cavities
SW 23RD AVE	Sacred Fig	16-20"	No	30'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Cavities
SW 23RD AVE	Sacred Fig	16-20"	No	40'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Cavities
SW 23RD AVE	Sacred Fig	16-20"	No	45'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Over Extended Limb(s)
SW 23RD AVE	Sacred Fig	11-15"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Over Extended Limb(s)
SW 23RD AVE	Brazilian Beauty Leaf	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Leaning - Moderate	Cavities
SW 23RD AVE	Brazilian Beauty Leaf	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 23RD AVE	Sacred Fig	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Cavities	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	21-30"	No	45'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Cavities	Stubs with Sprouts
SW 23RD AVE	Brazilian Beauty Leaf	16-20"	No	45'	Fair (41% to 60%)		Girdling Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 23RD AVE	Brazilian Beauty Leaf	11-15"	No	15'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Cracks in Trunk	Topped
SW 23RD AVE	Brazilian Beauty Leaf	6-10"	No	20'	Fair (41% to 60%)		Cavities	Reduced Canopy - Moderate	
SW 23RD AVE	Sacred Fig	60+"	Yes	60'	Poor (21% to 40%)	Utility Line Conflict	Stubs with Sprouts	Lopsided/Reduced Canopy - Major	Over Extended Limb(s)
SW 23RD AVE	Brazilian Beauty Leaf	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 23RD AVE	Brazilian Beauty Leaf	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 23RD AVE	Sacred Fig	21-30"	No	40'	Poor (21% to 40%)		Cavities	Stubs with Sprouts	Limb Damage - Major
SW 23RD AVE	Brazilian Beauty Leaf	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders - Multi
SW 23RD AVE	Glaucous Cassia	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD AVE	Royal Poinciana	11-15"	No	Negligible	Dead (0% to 5%)				
SW 23RD AVE	Brazilian Beauty Leaf	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	
SW 23RD AVE	Bougainvillea sp.	1-5"	Yes	5'	Fair (41% to 60%)		Suppressed Canopy		
SW 23RD AVE	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Nutrient Deficiency	
SW 23RD AVE	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Leaning - Moderate	Fungus on Leaves	
SW 23RD AVE	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Fungus on Leaves	
SW 23RD AVE	Sacred Fig	31-40"	No	50'	Poor (21% to 40%)		Cavities	Stubs with Sprouts	Codominant Leaders - Multi

(Continued on Next Page)

Street Tree Inventory


SW 23rd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD AVE	Coconut Palm	31-40"	Yes	40'	Good (61% to 80%)		Leaning - Moderate		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Damaged Fronds	
SW 23RD AVE	Sacred Fig	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 23RD AVE	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Strap Constricting Tree	
SW 23RD AVE	Coconut Palm	16-20"	No	20'	Fair (41% to 60%)		Leaning - Minor	Trunk Damage - Moderate	
SW 23RD AVE	Sacred Fig	31-40"	No	45'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Basal Co-Dominant
SW 23RD AVE	Sacred Fig	21-30"	No	35'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Cavities
SW 23RD AVE	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Codominant Leaders - Multi	Reduced Canopy - Moderate	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	11-15"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Cavities	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	21-30"	No	45'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Basal Co-Dominant	Stubs with Sprouts
SW 23RD AVE	Green Buttonwood	21-30"	No	50'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Lifting	Sprouting
SW 23RD AVE	Sacred Fig	31-40"	No	50'	Fair (41% to 60%)		Cavities	Stubs with Sprouts	Basal Co-Dominant
SW 23RD AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 23RD AVE	Gumbo Limbo	21-30"	No	50'	Fair (41% to 60%)		Restricted Canopy	Basal Co-Dominant	Lopsided/Reduced Canopy - Moderate
SW 23RD AVE	Sacred Fig	21-30"	No	40'	Fair (41% to 60%)		Restricted Canopy	Basal Co-Dominant	Lopsided/Reduced Canopy - Moderate
SW 23RD AVE	Sacred Fig	31-40"	No	40'	Very Poor/Critical (6% to 20%)		Topped	Stubs with Sprouts	Decay Observed
SW 23RD AVE	Sacred Fig	16-20"	No	40'	Fair (41% to 60%)		Cavities	Stubs with Sprouts	
SW 23RD AVE	Sacred Fig	16-20"	No	30'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Cavities
SW 23RD AVE	Sacred Fig	16-20"	No	40'	Fair (41% to 60%)		Lifting	Stubs with Sprouts	Reduced Canopy - Moderate
SW 23RD AVE	Sacred Fig	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Major	Lifting	Stubs with Sprouts
SW 23RD AVE	Pink Tabebuia	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 23RD AVE	Sacred Fig	21-30"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Cavities
SW 23RD AVE	Sacred Fig	16-20"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 23RD AVE	Vera Wood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD AVE	Sacred Fig	16-20"	No	25'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Lifting	Stubs with Sprouts
SW 23RD AVE	Sacred Fig	16-20"	No	30'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Lifting	Stubs with Sprouts

Courts | Avenues




Looking North - SW 10th Street




Looking North - SW 12th Street




Looking North - SW 10th Street



Looking North - SW 14th Street



Looking North - SW 16th Street



Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 24th Avenue	2	Shenandoah North	4	50-55	2,700	No	No	Yes, North of 10th Street	2	City	Some	Some	7-14	No	Yes	East side South of 10th street	ROW 55' South of 10th Street. Roundabouts at 10th and 14th street. Some dirt swales used for parking in curbless portion.
SW 24th Court	2	Shenandoah North	4	50	600	No	Yes	No	2	City	Some	No	0	Yes	Yes	West side	One-Way South. Intermittent vegetated bulb outs with tree plantings. Road narrows to one lane approaching 8th street.

SW 24th Avenue

TYPOLOGY C & D

SW 24th Court

TYPOLOGY D

Street Tree Inventory

SW 24th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH AVE	Live Oak	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Dead Wood
SW 24TH AVE	Brazilian Beauty Leaf	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH AVE	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)		Limb Damage - Minor		
SW 24TH AVE	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 24TH AVE	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	Broken Branches
SW 24TH AVE	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 24TH AVE	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Green Buttonwood	11-15"	No	45'	Good (61% to 80%)		Sprouting		
SW 24TH AVE	Mahogany	1-5"	No	Negligible	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy	Trunk Damage - Minor	
SW 24TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 24TH AVE	Mahogany	41-50"	No	60'	Poor (21% to 40%)		Topped	Sprouting	Over Extended Limb(s)
SW 24TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 24TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	
SW 24TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 24TH AVE	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Suppressed Canopy	Tapered Trunk	
SW 24TH AVE	Black Olive	21-30"	No	55'	Poor (21% to 40%)		Constricted Roots	Topped	Over Extended Limb(s)
SW 24TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Reduced Canopy - Moderate	Dead Wood
SW 24TH AVE	Mahogany	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 24TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 24TH AVE	Mahogany	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 24TH AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Codominant Leaders/Included Bark	Sprouting
SW 24TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Black Olive	11-15"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 24TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 24TH AVE	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)		Basal Co-Dominant	Suppressed Canopy	Sprouting
SW 24TH AVE	Green Buttonwood	6-10"	Yes	15'	Fair (41% to 60%)		Topped	Sprouting	
SW 24TH AVE	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 24TH AVE	Sapodilla	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Decay Observed	Leaning - Moderate
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency	Desiccated Foliage	
SW 24TH AVE	Mahogany	41-50"	No	60'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Root Damage/Decay	Utility Pruned
SW 24TH AVE	Sacred Fig	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Adjacent Light Pole	Topped	Sprouting
SW 24TH AVE	Sacred Fig	11-15"	Yes	5'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Adjacent Utility Marker	Topped	Sprouting
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Moderate	
SW 24TH AVE	Mahogany	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Lopsided/Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 24TH AVE	Mahogany	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 24TH AVE	Mahogany	6-10"	No	30'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Codominant Leaders - Multi	
SW 24TH AVE	Silver Buttonwood	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Codominant Leaders/Included Bark
SW 24TH AVE	Silver Buttonwood	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Codominant Leaders/Included Bark
SW 24TH AVE	Pink Tabebuia	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 24TH AVE	Green Buttonwood	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Codominant Leaders/No Included Bark
SW 24TH AVE	Weeping Fig	1-5"	Yes	Negligible	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 24th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH AVE	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		

SW 24th Court

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH CT	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH CT	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders - Multi
SW 24TH CT	Live Oak	1-5"	No	Negligible	Very Poor/Critical (6% to 20%)		Epicormic Growth	Reduced Canopy - Major	Dead Wood
SW 24TH CT	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Suppressed Canopy	Dead Wood
SW 24TH CT	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Suppressed Canopy	Dead Wood
SW 24TH CT	Brazilian Beauty Leaf	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 24TH CT	Brazilian Beauty Leaf	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	

Avenues



Looking North - SW 10th Street



Looking North - SW 14th Street



Looking South - SW 11th Street



Looking South - SW 13th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 25th Avenue	2	Shenandoah North	4	45-50	2500	No	No	Yes, North of 10th Street	2	City	Some	Some	5	North of 13th Street	Yes	West side north of 11th street	ROW 45' South of 11th Street. Parking on swale where curbless.

SW 25th Avenue

TYPOLOGY B & D

Street Tree Inventory

SW 25th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Lopsided/Reduced Canopy - Major	Ficus Growing on Tree
SW 25TH AVE	Mahogany	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 25TH AVE	Brazilian Beauty Leaf	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH AVE	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 25TH AVE	Glaucous Cassia	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor	Nutrient Deficiency	
SW 25TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Moderate		
SW 25TH AVE	Brazilian Beauty Leaf	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	
SW 25TH AVE	Mahogany	31-40"	No	60'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 25TH AVE	Brazilian Beauty Leaf	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Leaning - Moderate
SW 25TH AVE	Mahogany	41-50"	No	60'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 25TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 25TH AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Mahogany	31-40"	No	60'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Lifting
SW 25TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Leaning - Moderate		
SW 25TH AVE	Golden Shower Tree	21-30"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders - Multi	Stubs with Sprouts
SW 25TH AVE	Southern Magnolia	1-5"	No	Negligible	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Dead Wood	Trunk Damage - Major
SW 25TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Fungus on Leaves	
SW 25TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Fungus on Leaves	
SW 25TH AVE	Mahogany	41-50"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 25TH AVE	Mahogany	21-30"	No	Negligible	Dead (0% to 5%)				
SW 25TH AVE	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Utility Pruned	Ficus Growing on Tree
SW 25TH AVE	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 25TH AVE	Mahogany	51-60"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 25TH AVE	Mahogany	41-50"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 25TH AVE	Mahogany	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 25TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Cavities
SW 25TH AVE	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 25TH AVE	Mahogany	16-20"	No	35'	Poor (21% to 40%)		Trunk Damage - Major	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 25TH AVE	Mahogany	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Dead Wood
SW 25TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH AVE	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Decay Observed	Codominant Leaders - Multi
SW 25TH AVE	Mahogany	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Cavities
SW 25TH AVE	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 25TH AVE	Cabbage Palm	16-20"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH AVE	Mahogany	41-50"	No	65'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Over Extended Limb(s)
SW 25TH AVE	Mahogany	41-50"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Over Extended Limb(s)
SW 25TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 25TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Improperly Mulched	Codominant Leaders/Included Bark	
SW 25TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Improperly Mulched	Codominant Leaders/Included Bark	
SW 25TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Improperly Mulched		
SW 25TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 25TH AVE	Cabbage Palm	16-20"	No	15'	Fair (41% to 60%)		Desiccated Foliage	Desiccated Foliage	

Bordering Streets



Looking East - SW 19th Avenue



Looking East - SW 15th Avenue



Looking West - SW 25th Avenue



Looking West - SW 23rd Avenue



Looking East - SW 14th Avenue



Looking East - SW 12th Avenue



Looking East - SW 14th Avenue



Looking East - SW 18th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 8th Street	2	Shenandoah North	4	65-75	8000	No	No	Yes	3	State	Yes	Yes	0	yes	yes	no	Main street. Periodically planted swales between on street parking.
SW 16th Street	2	Shenandoah North	4	50-60	8,000	No	btw. 17th and 19th Ave.	Yes	2	City	Yes	Yes	5-6	yes	yes	both sides, west of 22nd Avenue	West of 22nd Avenue, share the road lanes with on street parking. Intermittent trees and palms. East of 22nd Avenue grass swales, some designated on-street parking. Roundabout at 14th Ave, 21st Ave, and 18th Ave.

SW 8th Street

TYPOLOGY D

SW 16th Street

TYPOLOGY B & D

Street Tree Inventory

SW 8th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Black Olive	1-5"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Major	Lopsided/Moderately Reduced Canopy
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Tapered Trunk		
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Crown Density - Low
SW 8TH ST	Black Olive	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 8TH ST	Royal Palm	11-15"	No	15'	Poor (21% to 40%)		Desiccated Foliage	Discolored Foliage	Reduced Canopy - Major
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Root Damage/Decay
SW 8TH ST	Black Olive	11-15"	No	25'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Cavities
SW 8TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Tapered Trunk	Nutrient Deficiency	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Tapered Trunk	Nutrient Deficiency	Reduced Canopy - Moderate
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Root Damage/Decay	Dead Wood
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 8TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Tapered Trunk	Nutrient Deficiency	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Decay Observed
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Discolored Foliage	Trunk Damage - Moderate	
SW 8TH ST	Montgomery Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 8TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Discolored Foliage	Trunk Damage - Moderate
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Insect Damage Leaves		
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Limb Damage - Moderate
SW 8TH ST	Black Olive	1-5"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Suppressed Canopy	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	35'	Poor (21% to 40%)		Trunk Damage - Major	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 8th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 8TH ST	Royal Palm	21-30"	No	15'	Good (61% to 80%)				
SW 8TH ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Girdling Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Girdling Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	16-20"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 8TH ST	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 8TH ST	Black Olive	16-20"	No	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Crown Density - Low
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Trunk Damage - Moderate
SW 8TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 8TH ST	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Major	Nutrient Deficiency
SW 8TH ST	Royal Palm	21-30"	No	15'	Fair (41% to 60%)		Tapered Trunk	Reduced Canopy - Moderate	
SW 8TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Moderate		
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 8TH ST	Royal Palm	21-30"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 8TH ST	Black Olive	11-15"	No	25'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 8TH ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 8TH ST	Royal Palm	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Tapered Trunk	Reduced Canopy - Moderate	
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 8TH ST	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Discolored Foliage	Trunk Damage - Moderate	
SW 8TH ST	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Discolored Foliage	Trunk Damage - Moderate	
SW 8TH ST	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 8TH ST	Royal Palm	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 8TH ST	Royal Palm	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Discolored Foliage	
SW 8TH ST	Royal Palm	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Discolored Foliage	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Discolored Foliage	
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Brazilian Beauty Leaf	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Broken Branches	

(Continued on Next Page)

Street Tree Inventory

SW 8th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 8TH ST	Black Olive	11-15"	No	40'	Poor (21% to 40%)		Reduced Canopy - Moderate	Decay Observed	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Trunk Damage - Minor
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Constricted Roots
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 8TH ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 8TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Minor
SW 8TH ST	Black Olive	6-10"	No	25'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Suppressed Canopy	Stubs with Sprouts
SW 8TH ST	Black Olive	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Suppressed Canopy
SW 8TH ST	Live Oak	1-5"	No	10'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs	Suppressed Canopy
SW 8TH ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 8TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Leader - Bent	Strap Constricting Tree	
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 8TH ST	Royal Palm	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 8TH ST	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Desiccated Foliage	Nutrient Deficiency	
SW 8TH ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Lopsided/Reduced Canopy - Moderate
SW 8TH ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Minor	Strap Constricting Tree	
SW 8TH ST	Black Olive	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 8TH ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Minor	Strap Constricting Tree	
SW 8TH ST	Black Olive	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 8TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				

SW 16th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH ST	Golden Shower Tree	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Cavities
SW 16TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 16TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 16TH ST	Golden Shower Tree	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH ST	Golden Shower Tree	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH ST	Golden Shower Tree	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH ST	Golden Shower Tree	21-30"	No	45'	Poor (21% to 40%)		Reduced Canopy - Moderate	Basal Co-Dominant	Cavities
SW 16TH ST	Golden Shower Tree	16-20"	No	35'	Poor (21% to 40%)		Reduced Canopy - Moderate	Crown Density - Low	Stubs with Sprouts
SW 16TH ST	Golden Shower Tree	16-20"	No	40'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 16TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 16TH ST	Golden Shower Tree	21-30"	No	35'	Poor (21% to 40%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 16TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 16TH ST	Golden Shower Tree	16-20"	No	20'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 16TH ST	Golden Shower Tree	16-20"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 16TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)		Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 16th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 16TH ST	Date Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Date Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Date Palm	16-20"	No	15'	Good (61% to 80%)				
SW 16TH ST	Golden Shower Tree	21-30"	No	50'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH ST	Golden Shower Tree	21-30"	No	35'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH ST	Golden Shower Tree	16-20"	No	40'	Fair (41% to 60%)		Stubs with Sprouts		
SW 16TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 16TH ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 16TH ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)				
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)		Fungus on Leaves		
SW 16TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)		Fungus on Leaves		
SW 16TH ST	Golden Shower Tree	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH ST	Golden Shower Tree	21-30"	No	35'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH ST	Bottlebrush	21-30"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate	Stubs with Sprouts
SW 16TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Trunk Damage - Moderate	Stubs with Sprouts
SW 16TH ST	Weeping Fig	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Crown Density - Low	Dead Wood
SW 16TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Reduced Canopy - Major	Lifting	Stubs with Sprouts
SW 16TH ST	Mahogany	31-40"	No	45'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Cavities	Codominant Leaders/Included Bark
SW 16TH ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	
SW 16TH ST	Mahogany	16-20"	No	45'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 16TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 16TH ST	Live Oak	1-5"	No	20'	Good (61% to 80%)		Lopsided/Reduced Canopy - Moderate		
SW 16TH ST	Mahogany	16-20"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Stubs with Sprouts
SW 16TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH ST	Mahogany	16-20"	No	50'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 16TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Limb Damage - Minor	
SW 16TH ST	Queen Palm	6-10"	No	10'	Poor (21% to 40%)		Restricted Canopy		
SW 16TH ST	Mahogany	16-20"	No	45'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Codominant Leaders - Multi	Stubs with Sprouts
SW 16TH ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)		Adjacent Light Pole		
SW 16TH ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 16TH ST	White Geiger	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH ST	Bougainvillea sp.	6-10"	Yes	15'	Good (61% to 80%)				
SW 16TH ST	Yellow Tabebuia	11-15"	No	35'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 16TH ST	Golden Shower Tree	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 16TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 16TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Strap Constricting Tree	
SW 16TH ST	Christmas Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Discolored Foliage	
SW 16TH ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Discolored Foliage	
SW 16TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Fungus on Leaves		
SW 16TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders - Multi	Strap Constricting Tree	
SW 16TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 16TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 16TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 16TH ST	Mahogany	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Reduced Canopy - Moderate

(Continued on Next Page)

Street Tree Inventory

SW 16th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH ST	Pygmy Date Palm	1-5"	No	10'	Fair (41% to 60%)		Leaning - Moderate	Discolored Foliage	
SW 16TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 16TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 16TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Minor	Codominant Leaders - Multi	
SW 16TH ST	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 16TH ST	Royal Palm	1-5"	No	10'	Fair (41% to 60%)		Discolored Foliage	Damaged Fronds	
SW 16TH ST	Christmas Palm	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major		
SW 16TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Leaning - Moderate	
SW 16TH ST	Pitch Apple	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Stubs with Sprouts
SW 16TH ST	Gumbo Limbo	1-5"	No	10'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Stubs with Sprouts
SW 16TH ST	Umbrella Tree	11-15"	No	20'	Poor (21% to 40%)		Leaning - Moderate	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)				
SW 16TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Discolored Foliage		
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 16TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Restricted Canopy	Trunk Damage - Moderate	
SW 16TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 16TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 16TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 16TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 16TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 16TH ST	Mahogany	41-50"	No	60'	Poor (21% to 40%)		Constricted Roots	Dead Wood	Stubs with Sprouts
SW 16TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 16TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Discolored Foliage	Leaning - Moderate	
SW 16TH ST	Black Olive	31-40"	No	65'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders - Multi
SW 16TH ST	Royal Poinciana	1-5"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 16TH ST	Royal Poinciana	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 16TH ST	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 16TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 16TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 16TH ST	Umbrella Tree	6-10"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Leaning - Moderate		
SW 16TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 16TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Discolored Foliage	
SW 16TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Discolored Foliage	
SW 16TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 16TH ST	Coconut Palm	1-5"	No	20'	Fair (41% to 60%)		Tapered Trunk	Reduced Canopy - Moderate	
SW 16TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Desiccated Foliage		
SW 16TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Desiccated Foliage	Leaning - Moderate	
SW 16TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Tapered Trunk		
SW 16TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Tapered Trunk		


(Continued on Next Page)

Street Tree Inventory

SW 16th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Fungus on Leaves		
SW 16TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Fungus on Leaves		
SW 16TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Moderate		
SW 16TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 16TH ST	Live Oak	6-10"	No	25'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Topped	Stubs with Sprouts	Restricted Canopy
SW 16TH ST	Coconut Palm	6-10"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Moderate	Reduced Canopy - Moderate	Discolored Foliage
SW 16TH ST	Starburst Clerodendron	6-10"	Yes	10'	Poor (21% to 40%)	Utility Lines Above	Stubs with Sprouts	Dead Wood	Crown Density - Low
SW 16TH ST	Japanese Privet	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Fungus on Leaves	Strap Constricting Tree	
SW 16TH ST	Japanese Privet	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Fungus on Leaves	Strap Constricting Tree	
SW 16TH ST	Umbrella Tree	16-20"	No	20'	Poor (21% to 40%)	Utility Lines Above	Girdling Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 16TH ST	Royal Poinciana	21-30"	No	30'	Very Poor/Critical (6% to 20%)	Utility Lines Adjacent (laterally)	Lopsided/Reduced Canopy - Major	Root Damage/Decay	Leaning - Moderate
SW 16TH ST	Tamarind	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		

Bordering Avenues



Looking North - SW 16th Street



Looking North - SW 13th Street



Looking North - SW 16th Street




Looking North - SW 13th Street



Looking South - SW 13th Street



Looking South - SW 8th Street



Looking South - SW 13th Street



Looking South - SW 8th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft.)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 12th Avenue	2	Shenandoah North	4	70	2,900	Some,	No	Yes	4	State	Yes	Yes	10	yes	yes	west side	
SW 27th Avenue	2	Shenandoah North	4	100	2700	Some, 11ft	No	Yes	4	State	Few	Some	3	Yes	Yes	No	vegetated bulb outs placed close to intersections, some places with opportunities to increase. Some portions of median vegetated.

SW 12th Avenue

TYPOLOGY D

SW 27th Avenue

TYPOLOGY F & B

Street Tree Inventory

SW 12th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Moderate		
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor		
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor	Trunk Damage - Minor	
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor		
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor		
SW 12TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Mahogany	31-40"	No	50'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Cavities	Utility Pruned
SW 12TH AVE	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 12TH AVE	Orange Geiger	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Bottle Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Suppressed Canopy	
SW 12TH AVE	Yellow Poinciana	21-30"	No	40'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders - Multi
SW 12TH AVE	Bottle Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Suppressed Canopy	
SW 12TH AVE	Live Oak	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 12TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Moderate	Stubs with Sprouts
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Minor		
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Moderate		
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Moderate	Trunk Damage - Moderate	Leaning - Moderate
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Flush Cuts	
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Flush Cuts	
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Flush Cuts	Trunk Damage - Moderate
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Flush Cuts	
SW 12TH AVE	Black Olive	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Cavities	Reduced Canopy - Major
SW 12TH AVE	Dahoon Holly	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Moderate		
SW 12TH AVE	Dahoon Holly	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Low	Dead Wood	
SW 12TH AVE	Dahoon Holly	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Moderate		
SW 12TH AVE	Dahoon Holly	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 27th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUN	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Poor (21% to 40%)		Trunk Damage - Major	Discolored Foliage	
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Fair (41% to 60%)		Tapered Trunk		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Brazilian Beauty Leaf	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Lifting
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				



SHENANDOAH SOUTH

Streets | Terraces | Lanes



Looking East - SW 27th Avenue



Looking East - SW 22nd Avenue



Looking West - SW 27th Avenue



Looking East - SW 24th Avenue



Looking East - SW 21st Avenue



Looking East - SW 17th Avenue



Looking East - SW 18th Avenue



Looking West - SW 17th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 16th Terrace	2	Shenandoah South	4	50	5380	No	No	Yes	3	City	Some	Yes	5	Yes	Yes	Northside west of 24th Ave	Paved and grass swales with on street parking.
SW 17th Street	2	Shenandoah South	4	50	7920	No	No	Yes	2	City	Yes	Yes	6	Yes	Yes	West of SW 24th Ave Periodically crossing over	Grass paved and gravel swales west of 24th Ave Roundabout at SW 18th Ave.

SW 16th Terrace

TYPOLOGY B & D

SW 17th Street

TYPOLOGY B & C

Street Tree Inventory

SW 16th Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH TER	Royal Poinciana	41-50"	No	60'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Trunk Damage - Moderate
SW 16TH TER	Royal Poinciana	21-30"	No	55'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Cavities
SW 16TH TER	Royal Poinciana	31-40"	No	65'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Lopsided/Reduced Canopy - Moderate
SW 16TH TER	Tamarind	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Lopsided/Reduced Canopy - Moderate
SW 16TH TER	Tamarind	21-30"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Restricted Canopy	Stubs with Sprouts
SW 16TH TER	Mango	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH TER	Frangipani	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 16TH TER	Avocado	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 16TH TER	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Discolored Foliage		
SW 16TH TER	Royal Palm	16-20"	No	25'	Fair (41% to 60%)		Discolored Foliage		
SW 16TH TER	Mahogany	11-15"	No	40'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 16TH TER	Australian Pine	21-30"	No	70'	Fair (41% to 60%)		Leaning - Moderate	Codominant Leaders/No Included Bark	
SW 16TH TER	Christmas Palm	1-5"	No	5'	Poor (21% to 40%)		Tapered Trunk	Cracks in Trunk	Trunk Damage - Major
SW 16TH TER	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders - Multi
SW 16TH TER	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 16TH TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 16TH TER	Japanese Golden Rain Tree	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Major	
SW 16TH TER	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 16TH TER	Mango	1-5"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Limb Damage - Moderate	
SW 16TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 16TH TER	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 16TH TER	Starfruit	1-5"	Yes	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 16TH TER	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders - Multi	Reduced Canopy - Minor	
SW 16TH TER	Mahogany	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders - Multi	Reduced Canopy - Minor	
SW 16TH TER	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders - Multi	Reduced Canopy - Minor	
SW 16TH TER	Mahogany	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders - Multi	Reduced Canopy - Minor	
SW 16TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Discolored Foliage		
SW 16TH TER	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH TER	Areca Palm	6-10"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 16TH TER	Mahogany	6-10"	Yes	15'	Good (61% to 80%)		Pruned Into Shrub		
SW 16TH TER	Mahogany	6-10"	Yes	15'	Good (61% to 80%)		Pruned Into Shrub		
SW 16TH TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 16TH TER	Vera Wood	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 16TH TER	Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Royal Poinciana	16-20"	Yes	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 16TH TER	Strangler Fig	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 16TH TER	Strangler Fig	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH TER	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Trunk Damage - Moderate	

(Continued on Next Page)

Street Tree Inventory

SW 16th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH TER	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 16TH TER	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Major	Leaning - Moderate	
SW 16TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	
SW 16TH TER	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 16TH TER	Slash Pine	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Dead Wood	
SW 16TH TER	Slash Pine	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Dead Wood	
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH TER	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 16TH TER	Guiana Chestnut	1-5"	Yes	10'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 16TH TER	Mango	11-15"	Yes	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Lopsided/Reduced Canopy - Moderate	
SW 16TH TER	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH TER	Bottlebrush	11-15"	No	25'	Poor (21% to 40%)		Leaning - Moderate	Reduced Canopy - Major	Stubs with Sprouts
SW 16TH TER	Spanish Lime	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark
SW 16TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 16TH TER	Laurel Oak	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Decay Observed	Reduced Canopy - Moderate
SW 16TH TER	Spanish Lime	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 16TH TER	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH TER	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Leaning - Moderate	Discolored Foliage	
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 16TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH TER	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Trunk Damage - Moderate	
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH TER	Papaya	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Major	
SW 16TH TER	Papaya	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 16TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 16TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Restricted Canopy	Trunk Damage - Minor	
SW 16TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy	Trunk Damage - Minor	
SW 16TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Restricted Canopy	Trunk Damage - Minor	
SW 16TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 16TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage	Trunk Damage - Minor	
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Leaning - Moderate		
SW 16TH TER	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)		Leaning - Major	Trunk Damage - Minor	
SW 16TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Discolored Foliage		
SW 16TH TER	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 16TH TER	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	
SW 16TH TER	Loquat	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 16TH TER	Royal Poinciana	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Leaning - Moderate
SW 16TH TER	Royal Poinciana	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH TER	Live Oak	16-20"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs with Sprouts	

(Continued on Next Page)

Street Tree Inventory

SW 16th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH TER	Mahogany	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 16TH TER	Longan	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	Girdling Roots
SW 16TH TER	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Stubs with Sprouts
SW 16TH TER	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 16TH TER	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Reduced Canopy - Moderate	Decay Observed	
SW 16TH TER	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 16TH TER	Royal Palm	16-20"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Desiccated Foliage	Discolored Foliage
SW 16TH TER	Royal Palm	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 16TH TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 16TH TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 16TH TER	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 16TH TER	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 16TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy		
SW 16TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 16TH TER	Christmas Palm	6-10"	Yes	10'	Poor (21% to 40%)		Trunk Damage - Major		
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	6-10"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 16TH TER	Royal Poinciana	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 16TH TER	Royal Poinciana	11-15"	No	35'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Leaning - Major	Stubs with Sprouts
SW 16TH TER	Strangler Fig	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH TER	Royal Poinciana	1-5"	No	25'	Poor (21% to 40%)		Constricted Roots	Suppressed Canopy	Leaning - Major
SW 16TH TER	Royal Poinciana	1-5"	No	15'	Poor (21% to 40%)		Constricted Roots	Suppressed Canopy	Leaning - Major
SW 16TH TER	Royal Poinciana	11-15"	No	5'	Very Poor/Critical (6% to		Topped	Stubs with Sprouts	Suppressed Canopy
SW 16TH TER	Royal Poinciana	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Leaning - Moderate
SW 16TH TER	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH TER	Live Oak	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 16TH TER	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 16TH TER	Loquat	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 16TH TER	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Reduced Canopy - Minor
SW 16TH TER	Live Oak	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 16TH TER	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 16TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 16TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 16TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 16TH TER	Spindle Palm	11-15"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major		
SW 16TH TER	Spindle Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 16TH TER	Spindle Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 16TH TER	Foxtail Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH TER	Foxtail Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH TER	Spindle Palm	11-15"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Nutrient Deficiency	
SW 16TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 16th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH TER	Queen Palm	6-10"	No	5'	Fair (41% to 60%)		Over Pruned	Restricted Canopy	
SW 16TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH TER	Foxtail Palm	1-5"	No	10'	Poor (21% to 40%)		Nutrient Deficiency	Reduced Canopy - Moderate	Frizzled Fronds
SW 16TH TER	Pongam	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Decay Observed
SW 16TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 16TH TER	Christmas Palm	6-10"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 16TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 16TH TER	Queen Palm	11-15"	Yes	20'	Good (61% to 80%)				
SW 16TH TER	Hong Kong Orchid	11-15"	No	20'	Poor (21% to 40%)		Basal Co-Dominant	Sprouting	
SW 16TH TER	Queen Palm	16-20"	Yes	20'	Good (61% to 80%)	Utility Lines Above	Over Pruned		
SW 16TH TER	Sapodilla	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 16TH TER	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 16TH TER	Live Oak	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 16TH TER	Live Oak	1-5"	Yes	5'	Very Poor/Critical (6% to		Reduced Canopy - Major	Sprouting	
SW 16TH TER	Florida Thatch Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 16TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 16TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 16TH TER	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Over Pruned	Restricted Canopy	
SW 16TH TER	Moringa	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 16TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned	Restricted Canopy	
SW 16TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned	Restricted Canopy	
SW 16TH TER	Guiana Chestnut	6-10"	Yes	5'	Poor (21% to 40%)		Basal Co-Dominant	Suppressed Canopy	
SW 16TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned	Restricted Canopy	
SW 16TH TER	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 16TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Over Pruned	White Fly	
SW 16TH TER	Canary Island Date Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH TER	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 16TH TER	Hong Kong Orchid	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 16TH TER	Orange Geiger	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Dead Wood
SW 16TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 16th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 16TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH TER	Solitaire Palm	1-5"	No	5'	Poor (21% to 40%)		Nutrient Deficiency		
SW 16TH TER	Oriental Arborvitae	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 16TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 16TH TER	Oriental Arborvitae	1-5"	No	5'	Good (61% to 80%)				
SW 16TH TER	Hong Kong Orchid	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH TER	Hong Kong Orchid	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH TER	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 16TH TER	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	
SW 16TH TER	Montgomery Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 16TH TER	Montgomery Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 16TH TER	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH TER	Montgomery Palm	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Leader - Bent	

SW 17th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH ST	Queen Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency	Frizzled Fronds	
SW 17TH ST	Slash Pine	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy		
SW 17TH ST	Slash Pine	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy	Dead Wood	
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Starburst Clerodendron	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 17TH ST	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Sprouting	
SW 17TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Trunk Damage - Minor	
SW 17TH ST	Queen Crepe Myrtle	6-10"	No	5'	Very Poor/Critical (6% to	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Royal Poinciana	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Umbrella Tree	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Sprouting
SW 17TH ST	Umbrella Tree	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Restricted Canopy
SW 17TH ST	Weeping Fig	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Major	Decay Observed
SW 17TH ST	Sapodilla	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH ST	Sapodilla	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	11-15"	Yes	20'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		

(Continued on Next Page)

Street Tree Inventory

SW 17th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	White Fly	
SW 17TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	White Fly	
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Dead Wood
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 17TH ST	Tropical Almond	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Sprouting	
SW 17TH ST	Lead Tree	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Suppressed Canopy	
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 17TH ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 17TH ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Dead Wood
SW 17TH ST	Weeping Fig	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 17TH ST	Strangler Fig	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Dead Wood
SW 17TH ST	Strangler Fig	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Live Oak	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Trunk Damage - Minor	
SW 17TH ST	Mahogany	6-10"	No	25'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	
SW 17TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Mahogany	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Limb Damage - Minor	Sprouting
SW 17TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 17TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 17TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 17TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Tamarind	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Crown Density - Excessive (Due to Epicormic Gr	Decay Observed
SW 17TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 17TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Jacaranda	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 17TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 17TH ST	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Over Pruned	
SW 17TH ST	Mahogany	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Leader - Bent
SW 17TH ST	Live Oak	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 17TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 17TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Restricted Canopy

(Continued on Next Page)

Street Tree Inventory

SW 17th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 17TH ST	Live Oak	6-10"	No	20'	Poor (21% to 40%)		Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 17TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 17TH ST	Umbrella Tree	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Restricted Canopy	
SW 17TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/No Included Bark	Reduced Canopy - Moderate	Sprouting
SW 17TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 17TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	1-5"	Yes	5'	Poor (21% to 40%)		Discolored Foliage	Trunk Damage - Moderate	
SW 17TH ST	Umbrella Tree	6-10"	No	10'	Very Poor/Critical (6% to		Trunk Damage - Major	Reduced Canopy - Major	Lifting
SW 17TH ST	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Insect Damage Leaves	Trunk Damage - Moderate	
SW 17TH ST	Coconut Palm	11-15"	No	20'	Poor (21% to 40%)		Trunk Damage - Moderate	Discolored Foliage	Leaning - Moderate
SW 17TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	
SW 17TH ST	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Restricted Canopy	Lopsided/Reduced Canopy - Moderate
SW 17TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 17TH ST	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 17TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 17TH ST	Royal Poinciana	21-30"	No	55'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Major	Leaning - Moderate
SW 17TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Southern Magnolia	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Dead Wood	
SW 17TH ST	Fishtail Palm	1-5"	No	5'	Fair (41% to 60%)		Discolored Foliage		
SW 17TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 17TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Tapered Trunk	
SW 17TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Gumbo Limbo	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 17TH ST	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)				
SW 17TH ST	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)				
SW 17TH ST	Live Oak	11-15"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 17TH ST	Live Oak	6-10"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 17TH ST	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Codominant Leaders/Included Bark
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 17th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH ST	Coconut Palm	11-15"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Fungus on Leaves	
SW 17TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Vera Wood	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH ST	Black Olive	31-40"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 17TH ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 17TH ST	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 17TH ST	Solitaire Palm	1-5"	Yes	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 17TH ST	Frangipani	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 17TH ST	Yellow Tabebuia	6-10"	No	5'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	
SW 17TH ST	Japanese Fern Tree	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Japanese Fern Tree	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Discolored Foliage	Fungus on Leaves
SW 17TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 17TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor	Reduced Canopy - Moderate	
SW 17TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 17TH ST	Mahogany	1-5"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	
SW 17TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 17TH ST	Bottle Palm	6-10"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 17TH ST	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	Sprouting
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 17TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH ST	Buccaneer Palm	1-5"	No	5'	Good (61% to 80%)		Discolored Foliage		
SW 17TH ST	Buccaneer Palm	1-5"	No	5'	Good (61% to 80%)		Discolored Foliage		
SW 17TH ST	Buccaneer Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Bottle Palm	11-15"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH ST	Bottle Palm	11-15"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Tapered Trunk		
SW 17TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Fungus on Leaves	Strap Constricting Tree	
SW 17TH ST	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 17TH ST	Buccaneer Palm	6-10"	No	10'	Fair (41% to 60%)		Discolored Foliage		
SW 17TH ST	Buccaneer Palm	6-10"	No	15'	Fair (41% to 60%)		Discolored Foliage		
SW 17TH ST	Buccaneer Palm	6-10"	No	15'	Fair (41% to 60%)		Discolored Foliage		
SW 17TH ST	Gumbo Limbo	1-5"	No	20'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH ST	Gumbo Limbo	1-5"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	
SW 17TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 17TH ST	Papaya	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Papaya	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 17TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 17th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 17TH ST	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 17TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 17TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Leaning - Moderate		
SW 17TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 17TH ST	Areca Palm	11-15"	No	10'	Good (61% to 80%)		Fungus on Leaves		
SW 17TH ST	Areca Palm	6-10"	No	10'	Good (61% to 80%)		Fungus on Leaves		
SW 17TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH ST	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 17TH ST	Japanese Fern Tree	6-10"	Yes	20'	Good (61% to 80%)		Restricted Canopy		
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 17TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)				
SW 17TH ST	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 17TH ST	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 17TH ST	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 17TH ST	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Limb Damage - Moderate
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH ST	Longan	11-15"	No	25'	Fair (41% to 60%)		Limb Damage - Moderate	Reduced Canopy - Moderate	Stubs with Sprouts
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 17TH ST	Areca Palm	11-15"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 17TH ST	Areca Palm	11-15"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH ST	Bottlebrush	11-15"	No	30'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Major	Sprouting	
SW 17TH ST	Podocarpus	11-15"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 17TH ST	Podocarpus	11-15"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 17TH ST	Spanish Lime	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 17TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Fungus on Leaves		
SW 17TH ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 17TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Moderate	
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 17TH ST	Weeping Fig	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 17TH ST	Royal Poinciana	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 17TH ST	Silver Buttonwood	16-20"	No	25'	Good (61% to 80%)	Utility Line Conflict	Basal Co-Dominant	Multi-Trunk Form - Not Downgraded for Struct	Dead Wood
SW 17TH ST	Silver Buttonwood	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Basal Co-Dominant	Multi-Trunk Form - Not Downgraded for Struct	Dead Wood
SW 17TH ST	Silver Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Basal Co-Dominant	Multi-Trunk Form - Not Downgraded for Struct	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 17th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH ST	Silver Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Basal Co-Dominant	Multi-Trunk Form - Not Downgraded for Struct	Dead Wood
SW 17TH ST	Silver Buttonwood	16-20"	No	25'	Good (61% to 80%)	Utility Line Conflict	Basal Co-Dominant	Multi-Trunk Form - Not Downgraded for Struct	Dead Wood
SW 17TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	
SW 17TH ST	Weeping Fig	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 17TH ST	Royal Poinciana	41-50"	No	70'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 17TH ST	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 17TH ST	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Frangipani	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Limb Damage - Minor	Dead Wood
SW 17TH ST	Umbrella Tree	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Sprouting		
SW 17TH ST	Umbrella Tree	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Girdling Roots	Codominant Leaders/Included Bark	Sprouting
SW 17TH ST	Umbrella Tree	11-15"	No	10'	Poor (21% to 40%)	Utility Lines Above	Girdling Roots	Reduced Canopy - Major	Sprouting
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Hong Kong Orchid	1-5"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Vera Wood	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 17TH ST	Queen Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 17TH ST	Pink Cassia	6-10"	No	40'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 17TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 17TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 17TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 17TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 17TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Oleander	6-10"	Yes	10'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 17TH ST	Royal Poinciana	21-30"	No	65'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 17TH ST	Mahogany	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Moderate
SW 17TH ST	Mahogany	41-50"	No	65'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 17TH ST	Christmas Palm	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Trunk Damage - Major		
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Leader - Bent		
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 17TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ST	Solitaire Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH ST	Live Oak	11-15"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 17TH ST	Live Oak	6-10"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 17TH ST	Live Oak	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Dead Wood	Sprouting
SW 17TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 17th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Sprouting	Dead Wood	Leader - Broken
SW 17TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)	Utility Lines Above	Sprouting	Dead Wood	
SW 17TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Sprouting	Dead Wood	
SW 17TH ST	Live Oak	6-10"	No	30'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH ST	Live Oak	6-10"	No	30'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH ST	Live Oak	6-10"	No	30'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Sprouting	Dead Wood	Constricted Roots
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Orange Geiger	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 17TH ST	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Codominant Leaders/Included Bark
SW 17TH ST	Pygmy Date Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)				
SW 17TH ST	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Vine Cover - Heavy
SW 17TH ST	Strangler Fig	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Reduced Canopy - Minor
SW 17TH ST	Norfolk Pine	16-20"	No	15'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	
SW 17TH ST	Weeping Fig	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 17TH ST	Guiana Chestnut	6-10"	No	10'	Good (61% to 80%)		Basal Co-Dominant		
SW 17TH ST	Weeping Fig	41-50"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH ST	Dracaena sp.	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 17TH ST	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 17TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/No Included Bark
SW 17TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/No Included Bark
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 17TH ST	Royal Poinciana	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 17TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 17TH ST	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Leader - Broken	Sprouting	
SW 17TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Southern Magnolia	6-10"	No	10'	Good (61% to 80%)		Basal Co-Dominant	Dead Wood	
SW 17TH ST	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 17TH ST	Mahogany	1-5"	No	5'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 17TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Over Pruned	
SW 17TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Over Pruned	
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 17th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 17TH ST	Royal Poinciana	21-30"	No	15'	Very Poor/Critical (6% to		Topped	Reduced Canopy - Major	Sprouting
SW 17TH ST	Silk Floss Tree	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 17TH ST	Umbrella Tree	11-15"	No	10'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 17TH ST	Umbrella Tree	16-20"	Yes	10'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 17TH ST	Dracaena sp.	6-10"	Yes	5'	Good (61% to 80%)				
SW 17TH ST	White Frangipani	6-10"	No	10'	Good (61% to 80%)		Basal Co-Dominant		
SW 17TH ST	Mango	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH ST	Pink Tabebuia	16-20"	No	20'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Sprouting
SW 17TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 17TH ST	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH ST	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Recumbent	Sprouting
SW 17TH ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 17TH ST	Soursop	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	
SW 17TH ST	Peregrina	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 17TH ST	Moringa	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	Codominant Leaders/Included Bark
SW 17TH ST	Black Olive	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Codominant Leaders/Included Bark
SW 17TH ST	Peregrina	6-10"	No	15'	Good (61% to 80%)		Basal Co-Dominant	Dead Wood	
SW 17TH ST	Umbrella Tree	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 17TH ST	Starburst Clerodendron	6-10"	No	10'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 17TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 17TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 17TH ST	Royal Poinciana	6-10"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH ST	Royal Poinciana	6-10"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 17TH ST	Royal Poinciana	6-10"	No	Negligible	Dead (0% to 5%)				
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Tapered Trunk		
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 17th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 17TH ST	Montgomery Palm	1-5"	No	15'	Good (61% to 80%)				
SW 17TH ST	Montgomery Palm	11-15"	Yes	20'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 17TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 17TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Canary Island Date Palm	16-20"	Yes	10'	Fair (41% to 60%)		Over Pruned		
SW 17TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 17TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Coconut Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Damaged Fronds	
SW 17TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	31-40"	Yes	20'	Good (61% to 80%)				
SW 17TH ST	Christmas Palm	21-30"	Yes	20'	Good (61% to 80%)	Utility Lines Adjacent (lateral			

(Continued on Next Page)

Streets | Terraces | Lanes



Looking East - SW 24th Avenue



Looking East - SW 23rd Avenue



Looking East - SW 27th Avenue



Looking East - SW 25th Avenue



Looking East - SW 23rd Avenue



Looking East - SW 22nd Avenue



Looking East - SW 21st Avenue



Looking West - SW 17th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 17th Lane (Ally)	2	Shenandoah South	4	25	1950	No	No	Yes	1	City	Some, mostly east of 22nd Ave	No	7	No	No	Periodically crossing over	One lane alley way between backyard of homes. Grass, gravel and planted swales. Parking half in swale half in alley west of 22nd Ave. Parking lot to Shenandoah park on south side east of 22nd Ave.
SW 17th Terrace	2	Shenandoah South	4	50	5085	No	No	Yes	2	City	Yes	Yes	6 (execept btw 23rd Ave and 22nd Ave)	Mostly, except south side east of 17th Ave, or east of 14th Avenue	Yes	Northside west of 22nd Ave	Grass and some paved swales between SW 23rd and 22nd Avenue with on street parking.

SW 17th Lane (Ally)

TYPOLOGY C

SW 17th Terrace

TYPOLOGY B & D

Street Tree Inventory

SW 17th Ally

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH ALY	Christmas Palm	31-40"	Yes	20'	Good (61% to 80%)				
SW 17TH ALY	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 17TH ALY	Christmas Palm	31-40"	Yes	15'	Good (61% to 80%)				
SW 17TH ALY	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ALY	Christmas Palm	11-15"	No	15'	Good (61% to 80%)				
SW 17TH ALY	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH ALY	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 17TH ALY	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 17TH ALY	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Vine Cover - Heavy	
SW 17TH ALY	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ALY	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 17TH ALY	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH ALY	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)				
SW 17TH ALY	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 17TH ALY	Mahogany	41-50"	No	30'	Very Poor/Critical (6% to		Trunk Damage - Major	Decay Observed	Constricted Roots
SW 17TH ALY	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Over Pruned		
SW 17TH ALY	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 17TH ALY	Coconut Palm	16-20"	No	25'	Good (61% to 80%)	Utility Line Conflict	Over Pruned		
SW 17TH ALY	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ALY	Lime Tree	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy		
SW 17TH ALY	Lime Tree	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy	Crown Density - Moderate	
SW 17TH ALY	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ALY	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ALY	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH ALY	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy		
SW 17TH ALY	White Frangipani	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy		
SW 17TH ALY	Hong Kong Orchid	16-20"	No	30'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting

SW 17th Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH TER	Coconut Palm	16-20"	Yes	30'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH TER	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 17TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH TER	Oriental Arborvitae	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 17TH TER	Oriental Arborvitae	1-5"	No	5'	Good (61% to 80%)				
SW 17TH TER	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 17TH TER	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 17TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 17TH TER	Bottlebrush	11-15"	No	20'	Poor (21% to 40%)		Cracks in Trunk	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 17TH TER	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Restricted Canopy
SW 17TH TER	Gumbo Limbo	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 17TH TER	Royal Poinciana	6-10"	No	30'	Poor (21% to 40%)		Restricted Canopy	Lopsided/Reduced Canopy - Major	Leaning - Moderate
SW 17TH TER	Black Olive	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 17th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH TER	Royal Poinciana	11-15"	No	30'	Poor (21% to 40%)		Restricted Canopy	Lopsided/Reduced Canopy - Major	Leaning - Moderate
SW 17TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 17TH TER	Mahogany	31-40"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Crown Density - Low
SW 17TH TER	Sacred Fig	11-15"	No	5'	Very Poor/Critical (6% to		Topped	Stubs with Sprouts	Basal Co-Dominant
SW 17TH TER	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Codominant Leaders - Multi	Stubs with Sprouts	Reduced Canopy - Major
SW 17TH TER	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Major	Stubs with Sprouts	
SW 17TH TER	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH TER	Vera Wood	11-15"	No	35'	Fair (41% to 60%)		Limb Damage - Moderate	Reduced Canopy - Moderate	Restricted Canopy
SW 17TH TER	Vera Wood	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Leaning - Moderate
SW 17TH TER	Vera Wood	6-10"	No	15'	Very Poor/Critical (6% to		Topped	Stubs with Sprouts	Root Damage/Decay
SW 17TH TER	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Tapered Trunk	Suppressed Canopy	
SW 17TH TER	Gumbo Limbo	6-10"	Yes	20'	Poor (21% to 40%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	Leaning - Moderate
SW 17TH TER	Papaya	6-10"	Yes	5'	Poor (21% to 40%)		Topped	Stubs with Sprouts	
SW 17TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH TER	Yellow Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 17TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Damaged Fronds		
SW 17TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 17TH TER	Frangipani	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 17TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 17TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 17TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Leaning - Moderate		
SW 17TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Discolored Foliage		
SW 17TH TER	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Discolored Foliage		
SW 17TH TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Discolored Foliage		
SW 17TH TER	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Discolored Foliage		
SW 17TH TER	Pink Tabebuia	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 17TH TER	Yellow Poinciana	16-20"	No	55'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Broken Branches
SW 17TH TER	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 17TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 17TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Minor		
SW 17TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Discolored Foliage	
SW 17TH TER	Simpson's Stopper	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 17TH TER	Areca Palm	21-30"	Yes	20'	Good (61% to 80%)				
SW 17TH TER	Live Oak	11-15"	No	45'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 17TH TER	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 17TH TER	Crepe Myrtle	1-5"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 17TH TER	Live Oak	1-5"	No	15'	Good (61% to 80%)				
SW 17TH TER	Bottle Palm	11-15"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Over Pruned	
SW 17TH TER	Bottle Palm	11-15"	No	10'	Fair (41% to 60%)		Discolored Foliage	Trunk Damage - Moderate	
SW 17TH TER	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 17TH TER	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 17TH TER	Jacaranda	6-10"	No	25'	Fair (41% to 60%)		Girdling Roots	Lopsided/Reduced Canopy - Moderate	Broken Branches
SW 17TH TER	Jacaranda	11-15"	No	30'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	Broken Branches
SW 17TH TER	Lignum Vitae	6-10"	No	25'	Poor (21% to 40%)		Restricted Canopy	Leaning - Moderate	Stubs with Sprouts
SW 17TH TER	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	Stubs with Sprouts
SW 17TH TER	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Major	Leaning - Moderate
SW 17TH TER	Royal Poinciana	16-20"	No	60'	Fair (41% to 60%)		Restricted Canopy	Reduced Canopy - Moderate	
SW 17TH TER	Mahogany	21-30"	No	55'	Poor (21% to 40%)		Constricted Roots	Stubs with Sprouts	Reduced Canopy - Moderate
SW 17TH TER	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Moderate	

(Continued on Next Page)

Street Tree Inventory

SW 17th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH TER	Black Olive	21-30"	No	35'	Very Poor/Critical (6% to		Topped	Stubs with Sprouts	Cavities
SW 17TH TER	Queen Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Queen Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Starburst Clerodendron	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH TER	Starburst Clerodendron	1-5"	No	Negligible	Dead (0% to 5%)				
SW 17TH TER	Starburst Clerodendron	6-10"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Dead Wood	Decay Observed
SW 17TH TER	Starburst Clerodendron	1-5"	No	10'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Bottlebrush	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Strap Constricting Tree	
SW 17TH TER	Bottlebrush	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Loose Trunk	Girdling Roots	Strap Constricting Tree
SW 17TH TER	Bottlebrush	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Strap Constricting Tree	
SW 17TH TER	Bottlebrush	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 17TH TER	Strangler Fig	51-60"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Decay Observed
SW 17TH TER	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Broken Branches
SW 17TH TER	Gumbo Limbo	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Grafted Branches
SW 17TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Lime Tree	1-5"	No	5'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 17TH TER	Java Plum	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 17TH TER	Java Plum	31-40"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH TER	Java Plum	41-50"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH TER	Java Plum	41-50"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH TER	Hong Kong Orchid	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 17TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 17TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 17TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 17TH TER	Sapodilla	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 17TH TER	Yellow Tabebuia	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 17TH TER	Dracaena sp.	6-10"	Yes	10'	Good (61% to 80%)				
SW 17TH TER	Sea Grape	6-10"	No	15'	Good (61% to 80%)		Basal Co-Dominant	Reduced Canopy - Moderate	Sprouting
SW 17TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH TER	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 17TH TER	Live Oak	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 17TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 17TH TER	Bottlebrush	16-20"	No	25'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	Codominant Leaders/Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 17th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Norfolk Pine	21-30"	No	20'	Good (61% to 80%)		Basal Co-Dominant		
SW 17TH TER	White Frangipani	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Mango	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Coconut Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH TER	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)				
SW 17TH TER	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 17TH TER	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 17TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Sprouting	Codominant Leaders/Included Bark	
SW 17TH TER	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 17TH TER	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Pigeon Plum	11-15"	No	20'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 17TH TER	Jamaican Dogwood	16-20"	No	25'	Poor (21% to 40%)		Topped	Basal Co-Dominant	Sprouting
SW 17TH TER	Areca Palm	6-10"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 17TH TER	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 17TH TER	Black Olive	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 17TH TER	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 17TH TER	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 17TH TER	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 17TH TER	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 17TH TER	Live Oak	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	Sprouting
SW 17TH TER	Live Oak	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	Sprouting
SW 17TH TER	Live Oak	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	Sprouting
SW 17TH TER	Seaside Mahoe	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Dead Wood
SW 17TH TER	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 17TH TER	Weeping Fig	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 17TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH TER	Bougainvillea sp.	6-10"	No	15'	Good (61% to 80%)		Basal Co-Dominant	Dead Wood	
SW 17TH TER	Bougainvillea sp.	11-15"	No	15'	Good (61% to 80%)		Basal Co-Dominant	Dead Wood	
SW 17TH TER	Mango	16-20"	No	25'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	Sprouting
SW 17TH TER	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	Dead Wood
SW 17TH TER	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Very Low	Pruned Into Shrub	Dead Wood
SW 17TH TER	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	Dead Wood
SW 17TH TER	Weeping Fig	1-5"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Pruned Into Shrub	Dead Wood
SW 17TH TER	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 17TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Sprouting		
SW 17TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Sprouting		
SW 17TH TER	Mahogany	31-40"	No	20'	Very Poor/Critical (6% to		Constricted Roots	Trunk Damage - Major	Topped
SW 17TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 17TH TER	Bamboo Palm	16-20"	Yes	10'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 17th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)				
SW 17TH TER	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 17TH TER	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)				
SW 17TH TER	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)				
SW 17TH TER	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 17TH TER	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 17TH TER	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)				
SW 17TH TER	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Horseflesh Mahogany	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Crown Density - Low	
SW 17TH TER	Royal Poinciana	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 17TH TER	Royal Poinciana	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 17TH TER	African Tulip Tree	21-30"	No	40'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH TER	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 17TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 17TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Orange Jasmine	16-20"	Yes	20'	Good (61% to 80%)		Dead Wood	Galls	
SW 17TH TER	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 17TH TER	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 17TH TER	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 17TH TER	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)				
SW 17TH TER	African Tulip Tree	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Dead Wood
SW 17TH TER	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Royal Palm	11-15"	No	25'	Good (61% to 80%)				
SW 17TH TER	Royal Palm	11-15"	No	25'	Good (61% to 80%)				
SW 17TH TER	Royal Palm	11-15"	No	25'	Good (61% to 80%)				
SW 17TH TER	Florida Thatch Palm	1-5"	No	15'	Good (61% to 80%)				
SW 17TH TER	Florida Thatch Palm	1-5"	No	15'	Good (61% to 80%)				
SW 17TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 17TH TER	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Cabbage Palm	6-10"	No	5'	Good (61% to 80%)				
SW 17TH TER	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 17TH TER	Bottle Palm	16-20"	No	10'	Very Poor/Critical (6% to		Trunk Damage - Major	Cavities	Nutrient Deficiency
SW 17TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 17TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 17TH TER	Fishtail Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Norfolk Pine	11-15"	No	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 17th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH TER	Norfolk Pine	11-15"	No	15'	Good (61% to 80%)				
SW 17TH TER	Norfolk Pine	11-15"	No	15'	Good (61% to 80%)				
SW 17TH TER	Mahogany	11-15"	No	25'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH TER	Mahogany	11-15"	No	25'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH TER	Live Oak	6-10"	No	25'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH TER	Mahogany	16-20"	No	45'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 17TH TER	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 17TH TER	Strangler Fig	6-10"	No	15'	Fair (41% to 60%)		Basal Co-Dominant		
SW 17TH TER	Coconut Palm	21-30"	Yes	40'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Avocado	16-20"	No	25'	Poor (21% to 40%)		Trunk Damage - Major	Cavities	Constricted Roots
SW 17TH TER	Sapodilla	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 17TH TER	Mahogany	21-30"	No	15'	Very Poor/Critical (6% to	Utility Lines Above	Constricted Roots	Topped	Sprouting
SW 17TH TER	Mahogany	21-30"	No	15'	Very Poor/Critical (6% to	Utility Lines Above	Constricted Roots	Topped	Sprouting
SW 17TH TER	Mahogany	21-30"	No	15'	Very Poor/Critical (6% to	Utility Lines Above	Constricted Roots	Topped	Sprouting
SW 17TH TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Bamboo Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH TER	Date Palm	6-10"	No	15'	Good (61% to 80%)				
SW 17TH TER	Date Palm	6-10"	No	15'	Good (61% to 80%)				
SW 17TH TER	Mahogany	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 17TH TER	Mahogany	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 17TH TER	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Sprouting	Codominant Leaders/Included Bark
SW 17TH TER	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Sprouting	Codominant Leaders/Included Bark
SW 17TH TER	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Sprouting	Codominant Leaders/Included Bark
SW 17TH TER	Yellow Tabebuia	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH TER	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark	Dead Wood	
SW 17TH TER	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark	Dead Wood	
SW 17TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 17TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 17TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 17TH TER	Royal Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH TER	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 17TH TER	Green Buttonwood	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	
SW 17TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	
SW 17TH TER	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH TER	Mahogany	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 17TH TER	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 17TH TER	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 17TH TER	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 17TH TER	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Sprouting	Codominant Leaders/Included Bark
SW 17TH TER	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Sprouting	Codominant Leaders/Included Bark
SW 17TH TER	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Lychee	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Dead Wood	
SW 17TH TER	Starburst Clerodendron	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	Dead Wood
SW 17TH TER	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 17TH TER	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Streets | Terraces | Lanes



Looking East - SW 27th Avenue



Looking East - SW 19th Avenue



Looking East - SW 27th Avenue



Looking West - SW 21st Avenue



Looking East - SW 16th Avenue



Looking East - SW 12th Avenue



Looking West - SW 17th Court



Looking West - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 18th Street	2	Shenandoah South	4	50	7325	No	No	Yes	2	City	Yes (east of 24th Ave)	Yes (east of 24th Ave)	7	Yes, east of 22nd Ave until 14th Avenue then east of 13th Avenue	No	Northside west of 22nd Ave, East of 13th Avenue and periodically crossing over	Grass paved and gravel swales with on street parking. Roundabout at SW 24th Ave. Speed bump just east SW 17th Avenue
SW 19th Street	2	Shenandoah South	4	50	7920	No	No	Yes	2	City	Some	Yes	8	Periodically on either	Yes	Northside west of 22nd Ave	Grass, paved and gravel swales with on street parking. Roundabout at SW 19th and 16th Ave.

SW 18th Street
TYPOLOGY A & C

SW 19th Street
TYPOLOGY C & B & D

Street Tree Inventory

SW 18th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 18TH ST	Brazilian Beauty Leaf	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 18TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 18TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Reduced Canopy - Minor
SW 18TH ST	Washington Palm	6-10"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency	Damaged Fronds	
SW 18TH ST	Washington Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Damaged Fronds	
SW 18TH ST	Washington Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Damaged Fronds	
SW 18TH ST	Foxtail Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Suppressed Canopy	Over Pruned
SW 18TH ST	Gumbo Limbo	16-20"	No	35'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 18TH ST	Umbrella Tree	21-30"	No	25'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	Sprouting
SW 18TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Coconut Palm	21-30"	Yes	20'	Good (61% to 80%)				
SW 18TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 18TH ST	Queen Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 18TH ST	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Leaning - Moderate	Codominant Leaders/Included Bark
SW 18TH ST	Black Olive	6-10"	No	20'	Poor (21% to 40%)		Crown Density - Very Low	Dead Wood	Codominant Leaders/Included Bark
SW 18TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 18TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 18TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 18TH ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH ST	Queen Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 18TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 18th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 18TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 18TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 18TH ST	Banyan	60+"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 18TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 18TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 18TH ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 18TH ST	Banyan	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 18TH ST	Royal Poinciana	16-20"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 18TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 18TH ST	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 18TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 18TH ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 18TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 18TH ST	Weeping Fig	6-10"	Yes	10'	Good (61% to 80%)		Dead Wood		
SW 18TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 18TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Lopsided/Significantly Reduced Canopy
SW 18TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Dead Wood	Sprouting	Codominant Leaders/Included Bark
SW 18TH ST	Jackfruit	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 18TH ST	Jackfruit	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 18TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Ackee Tree	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 18TH ST	Mango	1-5"	No	5'	Good (61% to 80%)				
SW 18TH ST	Mango	1-5"	No	5'	Fair (41% to 60%)		Basal Co-Dominant		
SW 18TH ST	Ackee Tree	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 18TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Royal Poinciana	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 18TH ST	Royal Poinciana	21-30"	No	60'	Good (61% to 80%)		Dead Wood	Sprouting	Codominant Leaders/Included Bark
SW 18TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Restricted Canopy		
SW 18TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 18TH ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 18th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	11-15"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Pygmy Date Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Pygmy Date Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 18TH ST	Royal Palm	11-15"	No	25'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	11-15"	No	25'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	11-15"	No	25'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	11-15"	No	25'	Good (61% to 80%)				
SW 18TH ST	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	Dead Wood
SW 18TH ST	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	Dead Wood
SW 18TH ST	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	Dead Wood
SW 18TH ST	Peregrina	16-20"	Yes	15'	Good (61% to 80%)		Basal Co-Dominant	Dead Wood	
SW 18TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 18TH ST	Bottle Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	16-20"	No	10'	Poor (21% to 40%)		Nutrient Deficiency		
SW 18TH ST	Royal Palm	11-15"	No	25'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				
SW 18TH ST	Foxtail Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Brazilian Beauty Leaf	1-5"	No	15'	Good (61% to 80%)				
SW 18TH ST	Brazilian Beauty Leaf	1-5"	No	15'	Good (61% to 80%)				
SW 18TH ST	Brazilian Beauty Leaf	1-5"	No	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 18th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Florida Thatch Palm	6-10"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 18TH ST	Queen Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Tropical Almond	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Dead Wood	Codominant Leaders/Included Bark
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy		
SW 18TH ST	Tropical Almond	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 18TH ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Over Pruned		
SW 18TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 18TH ST	Sapodilla	6-10"	No	20'	Poor (21% to 40%)	Utility Lines Above	Basal Co-Dominant		
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 18TH ST	Spindle Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Limb Damage - Moderate	Sprouting
SW 18TH ST	Silver Buttonwood	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	
SW 18TH ST	Japanese Fern Tree	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Sprouting	Decay Observed
SW 18TH ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark		
SW 18TH ST	Java Bishopwood	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Sprouting	
SW 18TH ST	Java Bishopwood	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark		
SW 18TH ST	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Basal Co-Dominant		
SW 18TH ST	Montgomery Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 18TH ST	Silver Buttonwood	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy		
SW 18TH ST	Silver Buttonwood	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	
SW 18TH ST	Vera Wood	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Uprooted - Partially	Reduced Canopy - Major	Sprouting
SW 18TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Winged Sumac	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 18TH ST	Strangler Fig	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Seasonal Defoliation/Discolored Foliage	Scale Insect
SW 18TH ST	Christmas Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 18TH ST	Seven Year Apple	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 18TH ST	Seven Year Apple	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 18TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Silver Buttonwood	11-15"	Yes	10'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Leaning - Major
SW 18TH ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH ST	Silver Buttonwood	6-10"	No	5'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Sprouting
SW 18TH ST	Live Oak	1-5"	No	5'	Very Poor/Critical (6% to		Reduced Canopy - Major	Loose Trunk	
SW 18TH ST	Live Oak	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 18TH ST	Chinese Fan Palm	11-15"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 18TH ST	Royal Poinciana	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	
SW 18TH ST	Chinese Fan Palm	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Over Pruned		
SW 18TH ST	Lychee	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 18TH ST	Areca Palm	11-15"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Coconut Palm	6-10"	No	5'	Poor (21% to 40%)	Utility Line Conflict	Over Pruned		
SW 18TH ST	Coconut Palm	6-10"	No	5'	Poor (21% to 40%)	Utility Line Conflict	Over Pruned		
SW 18TH ST	Coconut Palm	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Over Pruned		

(Continued on Next Page)

Street Tree Inventory

SW 18th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Date Palm	16-20"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 18TH ST	Date Palm	16-20"	No	15'	Good (61% to 80%)		Over Pruned		
SW 18TH ST	Date Palm	16-20"	No	20'	Good (61% to 80%)		Basal Sprouts		
SW 18TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 18TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Limb Damage - Moderate
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Weeping Fig	6-10"	No	10'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	
SW 18TH ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 18TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 18TH ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Limb Damage - Moderate	
SW 18TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)				
SW 18TH ST	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 18TH ST	Orange Geiger	1-5"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Leader - Broken	
SW 18TH ST	Sapodilla	6-10"	No	10'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Sprouting
SW 18TH ST	Sapodilla	6-10"	No	15'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Dead Wood	
SW 18TH ST	Umbrella Tree	16-20"	No	20'	Poor (21% to 40%)		Crown Density - Low	Trunk Damage - Major	
SW 18TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Areca Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Areca Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Starburst Clerodendron	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 18TH ST	Spanish Lime	1-5"	No	10'	Poor (21% to 40%)	Utility Lines Above	Basal Co-Dominant		
SW 18TH ST	Umbrella Tree	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Major	Dead Wood
SW 18TH ST	Gumbo Limbo	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	
SW 18TH ST	Gumbo Limbo	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	
SW 18TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 18TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Discolored Foliage	Fungus on Leaves	
SW 18TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Orange Geiger	6-10"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 18TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 18TH ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 18TH ST	Areca Palm	11-15"	Yes	15'	Fair (41% to 60%)		Suppressed Canopy		
SW 18TH ST	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Leaning - Moderate	
SW 18TH ST	Jacaranda	6-10"	No	20'	Very Poor/Critical (6% to		Lopsided/Reduced Canopy - Major	Limb Damage - Major	Trunk Damage - Moderate
SW 18TH ST	Live Oak	6-10"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 18TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Reduced Canopy - Moderate	
SW 18TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Reduced Canopy - Moderate	
SW 18TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Reduced Canopy - Moderate	
SW 18TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Lifting
SW 18TH ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Lifting
SW 18TH ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Lifting
SW 18TH ST	Cabbage Palm	6-10"	No	15'	Fair (41% to 60%)		Ficus Growing on Tree		
SW 18TH ST	Live Oak	11-15"	No	35'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 18th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH ST	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Black Olive	31-40"	No	55'	Very Poor/Critical (6% to		Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 18TH ST	Black Olive	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Sprouting	Reduced Canopy - Moderate
SW 18TH ST	Sapodilla	16-20"	No	35'	Poor (21% to 40%)		Trunk Damage - Major	Lopsided/Reduced Canopy - Major	Sprouting
SW 18TH ST	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Reduced Canopy - Moderate	Limb Damage - Moderate	
SW 18TH ST	Queen Palm	1-5"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 18TH ST	Queen Palm	1-5"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 18TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 18TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Reduced Canopy - Major	Decay Observed	Stubs with Sprouts
SW 18TH ST	Mahogany	31-40"	No	60'	Poor (21% to 40%)		Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 18TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Stubs with Sprouts	Reduced Canopy - Major
SW 18TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 18TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Restricted Canopy	Cavities	Reduced Canopy - Moderate
SW 18TH ST	Areca Palm	1-5"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 18TH ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 18TH ST	Mango	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Cavities	Stubs with Sprouts	Reduced Canopy - Major
SW 18TH ST	Washington Palm	11-15"	No	20'	Good (61% to 80%)				
SW 18TH ST	Washington Palm	11-15"	No	20'	Good (61% to 80%)				
SW 18TH ST	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Leaning - Moderate	Lopsided/Reduced Canopy - Moderate	Limb Damage - Moderate
SW 18TH ST	Mahogany	21-30"	No	65'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Leaning - Moderate
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 18TH ST	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy		
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Trunk Damage - Moderate	
SW 18TH ST	Royal Poinciana	21-30"	No	40'	Very Poor/Critical (6% to	Utility Line Conflict	Root Damage/Decay	Reduced Canopy - Moderate	Constricted Roots
SW 18TH ST	Mahogany	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Restricted Canopy
SW 18TH ST	Mahogany	31-40"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Dead Wood
SW 18TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 18TH ST	Mahogany	21-30"	No	20'	Very Poor/Critical (6% to	Utility Line Conflict	Trunk Damage - Major	Lopsided/Reduced Canopy - Major	Constricted Roots
SW 18TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 18TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 18TH ST	Mahogany	1-5"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Strap Constricting Tree	
SW 18TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 18TH ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Stubs with Sprouts
SW 18TH ST	Mahogany	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	Utility Pruned
SW 18TH ST	Mahogany	31-40"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Reduced Canopy - Major
SW 18TH ST	Mahogany	31-40"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Codominant Leaders - Multi
SW 18TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH ST	Desert Cassia	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 18TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Tapered Trunk		
SW 18TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH ST	Queen Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 18th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 18TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 18TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 18TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 18TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)		Tapered Trunk	Trunk Damage - Moderate	
SW 18TH ST	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 18TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 18TH ST	African Tulip Tree	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 18TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH ST	Live Oak	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 18TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Reduced Canopy - Moderate
SW 18TH ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Codominant Leaders/Included Bark
SW 18TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	Sprouting
SW 18TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate	Dead Wood	Sprouting
SW 18TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	Sprouting
SW 18TH ST	Mahogany	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Lopsided/Significantly Reduced Canopy	Trunk Damage - Moderate	Dead Wood
SW 18TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	Dead Wood
SW 18TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Codominant Leaders/Included Bark	Dead Wood	
SW 18TH ST	Mahogany	1-5"	No	15'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	
SW 18TH ST	Mahogany	1-5"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 18TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 18TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH ST	Christmas Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 18TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 18th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH ST	Live Oak	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 18TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 18TH ST	Mahogany	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Minor	Reduced Canopy - Minor
SW 18TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 18TH ST	Mahogany	31-40"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 18TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting

SW 19th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Christmas Palm	11-15"		15'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Royal Poinciana	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 19TH ST	Royal Poinciana	16-20"	No	40'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor	Sprouting	Dead Wood
SW 19TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 19TH ST	Paradise Tree	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 19TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Black Olive	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Coconut Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Desiccated Foliage	Dead Wood
SW 19TH ST	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)				
SW 19TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Desiccated Foliage	Dead Wood
SW 19TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Insect Damage Leaves		
SW 19TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 19TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 19TH ST	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH ST	Foxtail Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH ST	Foxtail Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 19TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 19TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 19TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 19TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 19TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 19TH ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH ST	Black Olive	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 19TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 19th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 19TH ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 19TH ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 19TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 19TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 19TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 19TH ST	Longan	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 19TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 19TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Sapodilla	16-20"	No	15'	Very Poor/Critical (6% to	Utility Line Conflict	Constricted Roots	Topped	Sprouting
SW 19TH ST	Sapodilla	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH ST	Sapodilla	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 19TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Desiccated Foliage	Dead Wood
SW 19TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 19TH ST	Gumbo Limbo	1-5"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Codominant Leaders/Included Bark	Dead Wood	
SW 19TH ST	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Dracaena sp.	16-20"	No	15'	Good (61% to 80%)		Basal Co-Dominant		
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Areca Palm	31-40"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Weeping Fig	6-10"	No	5'	Very Poor/Critical (6% to		Constricted Roots	Topped	Dead Wood
SW 19TH ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Umbrella Tree	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 19th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH ST	Mahogany	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Trunk Damage - Minor		
SW 19TH ST	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)		Decay Observed	Reduced Canopy - Moderate	Dead Wood
SW 19TH ST	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)		Decay Observed	Reduced Canopy - Moderate	Dead Wood
SW 19TH ST	Lead Tree	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Royal Poinciana	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 19TH ST	Live Oak	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 19TH ST	Royal Poinciana	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Tropical Almond	11-15"	No	15'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 19TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 19TH ST	Weeping Fig	31-40"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 19TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Restricted Canopy	Nutrient Deficiency
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 19TH ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 19TH ST	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Foxtail Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Foxtail Palm	1-5"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Foxtail Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Mahogany	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 19TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	African Tulip Tree	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Bottlebrush	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 19TH ST	Bottlebrush	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 19TH ST	Bottlebrush	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 19TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Oriental Arborvitae	16-20"	No	15'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 19TH ST	Oriental Arborvitae	16-20"	No	15'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 19TH ST	White Frangipani	11-15"	Yes	5'	Good (61% to 80%)				
SW 19TH ST	White Frangipani	11-15"	Yes	5'	Good (61% to 80%)				
SW 19TH ST	White Frangipani	11-15"	Yes	5'	Good (61% to 80%)				
SW 19TH ST	White Frangipani	11-15"	Yes	5'	Good (61% to 80%)				
SW 19TH ST	Tamarind	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Above	Topped	Reduced Canopy - Major	Sprouting
SW 19TH ST	Norfolk Pine	6-10"	No	5'	Good (61% to 80%)		Basal Co-Dominant		

(Continued on Next Page)

Street Tree Inventory

SW 19th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH ST	Japanese Privet	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Low	Desiccated Foliage	Dead Wood
SW 19TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 19TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Codominant Leaders/Included Bark	Dead Wood	
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH ST	Arjun Tree	21-30"	No	65'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Limb Damage - Major	Lopsided/Reduced Canopy - Major
SW 19TH ST	Arjun Tree	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Stubs with Sprouts
SW 19TH ST	Arjun Tree	21-30"	No	70'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 19TH ST	Arjun Tree	16-20"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Utility Pruned	Reduced Canopy - Major	Stubs with Sprouts
SW 19TH ST	Arjun Tree	21-30"	No	70'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 19TH ST	Arjun Tree	21-30"	No	70'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 19TH ST	Arjun Tree	21-30"	No	65'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Restricted Canopy
SW 19TH ST	Arjun Tree	16-20"	No	65'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Lopsided/Reduced Canopy - Major
SW 19TH ST	Arjun Tree	21-30"	No	70'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 19TH ST	Arjun Tree	21-30"	No	70'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 19TH ST	Arjun Tree	21-30"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 19TH ST	Arjun Tree	21-30"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 19TH ST	Arjun Tree	21-30"	No	70'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Over Extended Limb(s)
SW 19TH ST	Arjun Tree	21-30"	No	70'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Limb Damage - Moderate
SW 19TH ST	Arjun Tree	31-40"	No	70'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Moderate
SW 19TH ST	Arjun Tree	16-20"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Major	Limb Damage - Moderate
SW 19TH ST	Arjun Tree	21-30"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Over Extended Limb(s)
SW 19TH ST	Arjun Tree	16-20"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Utility Pruned	Restricted Canopy
SW 19TH ST	Arjun Tree	21-30"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	
SW 19TH ST	Arjun Tree	31-40"	No	70'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Restricted Canopy
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 19TH ST	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Limb Damage - Major	Reduced Canopy - Major	Stubs with Sprouts
SW 19TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 19TH ST	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Fungus on Leaves	Decay Observed
SW 19TH ST	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Fungus on Leaves	Decay Observed
SW 19TH ST	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Fungus on Leaves	Decay Observed
SW 19TH ST	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)		Pruned Into Shrub	Fungus on Leaves	Crown Density - Very Low
SW 19TH ST	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Fungus on Leaves	Decay Observed
SW 19TH ST	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Fungus on Leaves	Decay Observed
SW 19TH ST	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Fungus on Leaves	Decay Observed
SW 19TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Bottlebrush	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Bottlebrush	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Sea Grape	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Leaning - Moderate	Cavities
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Weeping Fig	1-5"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 19TH ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 19TH ST	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)		Pruned Into Shrub	Crown Density - Low	Trunk Damage - Major
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 19TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Codominant Leaders - Multi
SW 19TH ST	Carrotwood	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Stubs with Sprouts	
SW 19TH ST	Live Oak	11-15"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate		

(Continued on Next Page)

Street Tree Inventory

SW 19th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH ST	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Low	Decay Observed	Suppressed Canopy
SW 19TH ST	Weeping Fig	1-5"	No	Negligible	Dead (0% to 5%)				
SW 19TH ST	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Low	Decay Observed	Suppressed Canopy
SW 19TH ST	Weeping Fig	1-5"	No	5'	Dead (0% to 5%)				
SW 19TH ST	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Low	Suppressed Canopy	
SW 19TH ST	Weeping Fig	1-5"	Yes	5'	Poor (21% to 40%)		Crown Density - Low	Suppressed Canopy	Decay Observed
SW 19TH ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 19TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Lopsided/Reduced Canopy - Moderate	Restricted Canopy	
SW 19TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Reduced Canopy - Moderate	
SW 19TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 19TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 19TH ST	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 19TH ST	Mahogany	31-40"	No	70'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Moderate
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Starburst Clerodendron	1-5"	No	10'	Good (61% to 80%)		Pruned Into Shrub	Suppressed Canopy	
SW 19TH ST	Sapodilla	16-20"	No	25'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 19TH ST	Queen Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Avocado	6-10"	No	15'	Fair (41% to 60%)		Crown Density - Moderate	Dead Wood	Codominant Leaders/No Included Bark
SW 19TH ST	Avocado	6-10"	No	15'	Fair (41% to 60%)		Stubs with Sprouts	Codominant Leaders/Included Bark	
SW 19TH ST	Live Oak	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 19TH ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Trunk Damage - Minor	
SW 19TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark		
SW 19TH ST	Royal Poinciana	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 19TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 19TH ST	Umbrella Tree	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 19TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH ST	Pygmy Date Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)				
SW 19TH ST	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 19TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 19TH ST	Umbrella Tree	16-20"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Sprouting
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH ST	Sapodilla	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Strap Constricting Tree	
SW 19TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 19TH ST	Mahogany	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Broken Branches	
SW 19TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 19TH ST	Mahogany	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 19TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 19th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH ST	Mahogany	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 19TH ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 19TH ST	Montgomery Palm	6-10"	No	20'	Good (61% to 80%)				
SW 19TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 19TH ST	Wild/Cuban Tamarind	6-10"	No	15'	Poor (21% to 40%)		Basal Co-Dominant		
SW 19TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 19TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH ST	Paper Mulberry	6-10"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	White Frangipani	6-10"	No	5'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Paper Mulberry	1-5"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Crepe Myrtle	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 19TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Mahogany	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH ST	Oriental Arborvitae	21-30"	Yes	20'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Oriental Arborvitae	16-20"	No	20'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Moderate	Dead Wood	
SW 19TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 19TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 19TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 19TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 19TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 19TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 19TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 19TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 19TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	16-20"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Areca Palm	31-40"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 19TH ST	Pitch Apple	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 19TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 19TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 19th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH ST	Umbrella Tree	11-15"	No	10'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Dead Wood
SW 19TH ST	Weeping Fig	1-5"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 19TH ST	Weeping Fig	1-5"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 19TH ST	Weeping Fig	1-5"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 19TH ST	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 19TH ST	Mahogany	11-15"	No	25'	Good (61% to 80%)		Limb Damage - Minor	Codominant Leaders/Included Bark	
SW 19TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Starburst Clerodendron	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Crown Density - Low		
SW 19TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Reduced Canopy - Minor	
SW 19TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH ST	Java Bishopwood	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Apical Dieback	Sprouting
SW 19TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 19TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH ST	Royal Poinciana	11-15"	No	20'	Fair (41% to 60%)		Limb Damage - Moderate	Sprouting	Codominant Leaders/Included Bark
SW 19TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 19TH ST	Strangler Fig	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 19TH ST	Sapodilla	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood

Streets | Terraces | Lanes




Looking East - SW 27th Avenue



Looking East - SW 23rd Avenue



Looking East- SW 27th Avenue



Looking East - SW 19th Avenue



Looking East - SW 19th Avenue



Looking East - SW 12th Avenue



Looking East- SW 16th Avenue



Looking East - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 19th Terrace	2	Shenandoah South	4	50	2505	No	No	Yes	2	City	Yes	Yes	10 (execept E of 17th Ave)	Yes, except b/t 27th Ave and 25th Ave, 19th Ave and 14th Ave	Yes	Northside b/t 27th Ave and 25th Ave, 22nd and 21st Ave, 18th Ct and 18th Ave, 17th Ave and 14th Ave, and 13th and 12th Ave	Grass and gravel swales in areas without curbs, mostly grass but some paved swales in curbed areas. Entirely paved swale between 22nd and 21st Ave.
SW 20th Street	2	Shenandoah South	4	50-25	7470	No	No	Yes	2	City	Yes	Yes	6-10	Yes, except b/t 27th Ave and 25th Ave, 19th Ave and 14th Ave	Yes	North and south sides b/t 27th Ave and 25th Ave, north side b/t 17th and 14th Ave, southside b/t 14th-13th Ave	Grass paved and gravel swales with on street parking. Roundabout at SW 23rd and 20th Ave. Speed bump just east SW 27th Avenue. Roadway narrows to one lane between 19th Ave and 17th Ct.

SW 19th Terrace

TYPOLOGY B & C

SW 20th Street

TYPOLOGY B & C

Street Tree Inventory

SW 19th Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH TER	Rubber Tree	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Decay Observed	Stubs with Sprouts	Limb Damage - Moderate
SW 19TH TER	Weeping Fig	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 19TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 19TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 19TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 19TH TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Discolored Foliage		
SW 19TH TER	Sacred Fig	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 19TH TER	Spindle Palm	6-10"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Tapered Trunk	Reduced Canopy - Moderate
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH TER	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 19TH TER	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 19TH TER	Mahogany	21-30"	No	40'	Very Poor/Critical (6% to		Constricted Roots	Crown Density - Very Low	Trunk Damage - Major
SW 19TH TER	Mahogany	21-30"	No	40'	Very Poor/Critical (6% to		Constricted Roots	Crown Density - Very Low	Lopsided/Reduced Canopy - Major
SW 19TH TER	Brazilian Pepper	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Above	Basal Co-Dominant		
SW 19TH TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 19TH TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 19TH TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 19TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree

Street Tree Inventory

SW 19th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 19TH TER	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Minor	Codominant Leaders/Included Bark
SW 19TH TER	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Codominant Leaders/Included Bark
SW 19TH TER	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Topped	Sprouting
SW 19TH TER	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Topped
SW 19TH TER	Mahogany	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH TER	Bottlebrush	21-30"	No	15'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Topped
SW 19TH TER	Tamarind	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Dead Wood	Restricted Canopy
SW 19TH TER	Ackee Tree	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Sprouting	Suppressed Canopy
SW 19TH TER	Live Oak	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH TER	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 19TH TER	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 19TH TER	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	Sprouting
SW 19TH TER	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Topped
SW 19TH TER	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 19TH TER	Mahogany	6-10"	No	25'	Good (61% to 80%)				
SW 19TH TER	Live Oak	16-20"	No	40'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 19TH TER	Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH TER	Mahogany	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Topped
SW 19TH TER	Mahogany	6-10"	No	25'	Good (61% to 80%)				
SW 19TH TER	Queen Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH TER	Vera Wood	1-5"	No	15'	Fair (41% to 60%)		Topped	Sprouting	
SW 19TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Tamarind	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH TER	Mimosa/Silk Tree	6-10"	No	25'	Good (61% to 80%)				
SW 19TH TER	Japanese Fern Tree	6-10"	No	35'	Fair (41% to 60%)		Crown Density - Low	Trunk Damage - Minor	
SW 19TH TER	Mahogany	6-10"	No	25'	Good (61% to 80%)				
SW 19TH TER	Mahogany	6-10"	No	20'	Good (61% to 80%)				
SW 19TH TER	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots		
SW 19TH TER	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 19TH TER	Black Olive	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 19TH TER	Spindle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Spindle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Royal Poinciana	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Tapered Trunk	

(Continued on Next Page)

Street Tree Inventory

SW 19th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH TER	Live Oak	31-40"	No	55'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Lion's Tailing
SW 19TH TER	Mahogany	6-10"	No	40'	Fair (41% to 60%)		Constricted Roots		
SW 19TH TER	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 19TH TER	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 19TH TER	Black Olive	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH TER	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 19TH TER	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Suppressed Canopy	Dead Wood
SW 19TH TER	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 19TH TER	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 19TH TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	
SW 19TH TER	Strangler Fig	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 19TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 19TH TER	Spindle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 19TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Strangler Fig	51-60"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 19TH TER	Cabbage Palm	11-15"	No	10'	Poor (21% to 40%)		Ficus Growing on Tree		
SW 19TH TER	Cabbage Palm	11-15"	No	10'	Poor (21% to 40%)		Ficus Growing on Tree		
SW 19TH TER	Oriental Arborvitae	6-10"	No	5'	Good (61% to 80%)				
SW 19TH TER	Oriental Arborvitae	6-10"	No	5'	Good (61% to 80%)				
SW 19TH TER	Oriental Arborvitae	6-10"	No	5'	Good (61% to 80%)				
SW 19TH TER	Sacred Fig	1-5"	Yes	10'	Good (61% to 80%)		Basal Co-Dominant with Adjacent Tree(s)		
SW 19TH TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Basal Co-Dominant with Adjacent Tree(s)		
SW 19TH TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Basal Co-Dominant with Adjacent Tree(s)		
SW 19TH TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Basal Co-Dominant with Adjacent Tree(s)		
SW 19TH TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Basal Co-Dominant with Adjacent Tree(s)		
SW 19TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Bougainvillea sp.	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH TER	Bougainvillea sp.	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH TER	Banyan	31-40"	No	25'	Good (61% to 80%)				
SW 19TH TER	Bougainvillea sp.	6-10"	Yes	5'	Good (61% to 80%)				
SW 19TH TER	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Weeping Fig	6-10"	No	15'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Insect Damage Leaves
SW 19TH TER	Weeping Fig	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Crown Density - Moderate	Dead Wood
SW 19TH TER	Weeping Fig	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Crown Density - Low	Insect Damage Leaves
SW 19TH TER	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Basal Co-Dominant	Reduced Canopy - Major
SW 19TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Bottle Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Bottle Palm	6-10"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency	Insect Damage Leaves	
SW 19TH TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 19th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Peregrina	1-5"	Yes	5'	Good (61% to 80%)		Dead Wood		
SW 19TH TER	Peregrina	1-5"	No	10'	Good (61% to 80%)		Basal Co-Dominant	Dead Wood	
SW 19TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Dracaena sp.	16-20"	No	15'	Good (61% to 80%)		Basal Co-Dominant	Decay Observed	
SW 19TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 19TH TER	Weeping Fig	11-15"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Trunk Damage - Major	Pruned Into Shrub	Dead Wood
SW 19TH TER	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Trunk Damage - Major	Nutrient Deficiency	
SW 19TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 19TH TER	Christmas Palm	41-50"	Yes	20'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH TER	Royal Poinciana	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Reduced Canopy - Major
SW 19TH TER	Weeping Fig	16-20"	No	30'	Very Poor/Critical (6% to	Utility Lines Adjacent (lateral	Constricted Roots	Trunk Damage - Major	Topped
SW 19TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Hibiscus sp.	21-30"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH TER	Foxtail Palm	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Nutrient Deficiency	Frizzled Fronds	
SW 19TH TER	Mahogany	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Dead Wood	Sprouting
SW 19TH TER	Royal Poinciana	1-5"	No	Negligible	Dead (0% to 5%)				
SW 19TH TER	Chinese Fan Palm	6-10"	No	15'	Good (61% to 80%)				
SW 19TH TER	Peregrina	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 19TH TER	Peregrina	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 19TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Dead Wood		
SW 19TH TER	Mahogany	41-50"	No	65'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 19TH TER	Umbrella Tree	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH TER	Crepe Myrtle	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Dead Wood	Basal Co-Dominant	
SW 19TH TER	Crepe Myrtle	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Basal Co-Dominant	
SW 19TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 19TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Triangle Palm	11-15"	No	20'	Good (61% to 80%)				
SW 19TH TER	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 19TH TER	Guiana Chestnut	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Pigeon Plum	1-5"	No	15'	Good (61% to 80%)	Utility Line Conflict	Dead Wood	Codominant Leaders/Included Bark	
SW 19TH TER	Indian Laurel Fig	41-50"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 19TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Pink Tabebuia	16-20"	No	40'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 19TH TER	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)		Restricted Canopy	Dead Wood	Codominant Leaders/Included Bark
SW 19TH TER	Pink Tabebuia	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 19TH TER	Crepe Myrtle	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Dead Wood		
SW 19TH TER	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 19th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH TER	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Basal Co-Dominant	Dead Wood	
SW 19TH TER	Italian Cypress	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Italian Cypress	1-5"	No	5'	Good (61% to 80%)				
SW 19TH TER	Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH TER	Simpson's Stopper	41-50"	Yes	20'	Good (61% to 80%)		Dead Wood		

SW 20th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH ST	Starburst Clerodendron	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Nutrient Deficiency	
SW 20TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood		
SW 20TH ST	Royal Poinciana	6-10"	No	20'	Fair (41% to 60%)		Basal Co-Dominant		
SW 20TH ST	Royal Poinciana	6-10"	No	35'	Good (61% to 80%)				
SW 20TH ST	Black Olive	21-30"	No	10'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 20TH ST	Black Olive	16-20"	No	Negligible	Dead (0% to 5%)		Topped		
SW 20TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Mahogany	16-20"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 20TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 20TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 20TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 20TH ST	Mango	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	Dead Wood
SW 20TH ST	Coconut Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 20TH ST	Mahogany	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 20TH ST	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub	Codominant Leaders/Included Bark	
SW 20TH ST	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub	Codominant Leaders/Included Bark	
SW 20TH ST	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub	Codominant Leaders/Included Bark	
SW 20TH ST	Mahogany	41-50"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Mahogany	41-50"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Gumbo Limbo	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Pink Tabebuia	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 20th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 20TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 20TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 20TH ST	Sapodilla	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 20TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 20TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 20TH ST	Chinese Fan Palm	16-20"	Yes	10'	Good (61% to 80%)				
SW 20TH ST	Chinese Fan Palm	16-20"	Yes	10'	Good (61% to 80%)				
SW 20TH ST	Chinese Fan Palm	16-20"	Yes	10'	Good (61% to 80%)				
SW 20TH ST	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)				
SW 20TH ST	Arjun Tree	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 20TH ST	Arjun Tree	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Arjun Tree	41-50"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Arjun Tree	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Arjun Tree	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Arjun Tree	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Dwarf Schefflera	6-10"	Yes	10'	Good (61% to 80%)		Basal Co-Dominant with Adjacent Tree(s)		
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Live Oak	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate	Sprouting	
SW 20TH ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Live Oak	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Constricted Roots	Dead Wood
SW 20TH ST	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Minor	Dead Wood
SW 20TH ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 20TH ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 20TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 20TH ST	Mahogany	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 20TH ST	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 20TH ST	Black Olive	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 20TH ST	Avocado	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 20TH ST	Queen Crepe Myrtle	1-5"	No	10'	Very Poor/Critical (6% to		Trunk Damage - Major	Topped	Reduced Canopy - Major
SW 20TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Tamarind	1-5"	No	5'	Good (61% to 80%)				
SW 20TH ST	Queen Crepe Myrtle	1-5"	No	5'	Fair (41% to 60%)		White Fly		
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor		
SW 20TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 20TH ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 20th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH ST	Queen Palm	1-5"	No	10'	Good (61% to 80%)				
SW 20TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 20TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 20TH ST	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 20TH ST	Live Oak	6-10"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 20TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots		
SW 20TH ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 20TH ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 20TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 20TH ST	Live Oak	11-15"	No	30'	Good (61% to 80%)		Sprouting		
SW 20TH ST	Live Oak	11-15"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Dead Wood	
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Crown Density - Low	
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Montgomery Palm	16-20"	Yes	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Washington Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Washington Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Washington Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Washington Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Bird of Paradise	21-30"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Black Olive	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Black Olive	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Black Olive	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Black Olive	21-30"	No	15'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 20TH ST	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 20TH ST	Strangler Fig	51-60"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 20TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Black Olive	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 20TH ST	Black Olive	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 20TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 20TH ST	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Mahogany	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Fishtail Palm	16-20"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Washington Palm	11-15"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Moderate	
SW 20TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 20TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 20th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 20TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Montgomery Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Montgomery Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Montgomery Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Montgomery Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Montgomery Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 20TH ST	Royal Poinciana	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Restricted Canopy
SW 20TH ST	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)				
SW 20TH ST	Bamboo Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 20TH ST	Royal Poinciana	1-5"	No	10'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	
SW 20TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 20TH ST	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Restricted Canopy	Suppressed Canopy
SW 20TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	
SW 20TH ST	Fiddle Leaf Fig	6-10"	Yes	5'	Good (61% to 80%)				
SW 20TH ST	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 20TH ST	Peregrina	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Insect Damage Leaves	
SW 20TH ST	Mahogany	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 20TH ST	Starburst Clerodendron	1-5"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 20TH ST	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 20TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Live Oak	11-15"	No	40'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	
SW 20TH ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Silk Floss Tree	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 20TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 20TH ST	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)		Dead Wood	Multi-Trunk Form - Not Downgraded for Struct	
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 20TH ST	Gumbo Limbo	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 20TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 20TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 20TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 20TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 20TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 20TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 20TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 20TH ST	Rubber Tree	11-15"	Yes	15'	Good (61% to 80%)				
SW 20TH ST	Brazilian Pepper	6-10"	No	10'	Poor (21% to 40%)		Topped	Sprouting	
SW 20TH ST	Queen Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 20TH ST	Queen Palm	1-5"	No	5'	Good (61% to 80%)				
SW 20TH ST	Queen Crepe Myrtle	1-5"	Yes	5'	Poor (21% to 40%)		Topped	Sprouting	
SW 20TH ST	Pencil Tree	1-5"	No	5'	Good (61% to 80%)		Dead Wood		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 20TH ST	Dracaena sp.	6-10"	Yes	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 20th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH ST	Dracaena sp.	6-10"	Yes	5'	Good (61% to 80%)				
SW 20TH ST	Silver Buttonwood	1-5"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	
SW 20TH ST	Red Cassia	1-5"	No	15'	Good (61% to 80%)				
SW 20TH ST	Wild/Cuban Tamarind	6-10"	No	20'	Good (61% to 80%)				
SW 20TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 20TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 20TH ST	Paradise Tree	11-15"	No	30'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Moderate	Leader - Broken
SW 20TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 20TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 20TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Umbrella Tree	16-20"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Suppressed Canopy	
SW 20TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 20TH ST	Sapodilla	21-30"	No	30'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 20TH ST	Umbrella Tree	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	
SW 20TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 20TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 20TH ST	Green Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 20TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 20TH ST	Narrow Leaf Ficus	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Narrow Leaf Ficus	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Royal Palm	16-20"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 20TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 20TH ST	Live Oak	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Limb Damage - Major	Sprouting
SW 20TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 20TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 20TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 20TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 20TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 20TH ST	Desert Cassia	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Low	Strap Constricting Tree	
SW 20TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 20TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 20TH ST	Weeping Fig	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Crown Density - Low	Sprouting
SW 20TH ST	Weeping Fig	41-50"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)	Utility Line Conflict	Suppressed Canopy	Restricted Canopy	
SW 20TH ST	Mahogany	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy	Restricted Canopy	
SW 20TH ST	Mahogany	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy	Restricted Canopy	
SW 20TH ST	Mahogany	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Cabbage Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 20TH ST	Ackee Tree	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Ackee Tree	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Strap Constricting Tree	Sprouting
SW 20TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 20TH ST	Yellow Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Dead Wood	Limb Damage - Minor
SW 20TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Over Pruned	
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 20th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 20TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 20TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	
SW 20TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Black Olive	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 20TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 20TH ST	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Dahoon Holly	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Dead Wood	
SW 20TH ST	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 20TH ST	Montgomery Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Dahoon Holly	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Sprouting	
SW 20TH ST	Dahoon Holly	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Dead Wood	
SW 20TH ST	Bottlebrush	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Dead Wood	Codominant Leaders/Included Bark	Sprouting
SW 20TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Mahogany	41-50"	No	50'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 20TH ST	Dracaena sp.	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 20TH ST	Bottle Palm	6-10"	No	10'	Poor (21% to 40%)		Nutrient Deficiency	Dead Meristem	Frizzled Fronds
SW 20TH ST	Triangle Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Suppressed Canopy	
SW 20TH ST	Royal Poinciana	16-20"	No	55'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 20TH ST	Japanese Privet	1-5"	No	Negligible	Dead (0% to 5%)				
SW 20TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Dead Wood	Insect Damage Leaves	Codominant Leaders/Included Bark
SW 20TH ST	Bottlebrush	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Dead Wood
SW 20TH ST	Sea Grape	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 20TH ST	Sea Grape	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 20TH ST	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)	Utility Line Conflict			
SW 20TH ST	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Adjacent (lateral			
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Coconut Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 20TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 20TH ST	Coconut Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Brunfelsia sp.	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Brunfelsia sp.	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 20TH ST	Desert Cassia	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 20TH ST	Vera Wood	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Topped	Reduced Canopy - Major	Sprouting
SW 20TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 20TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			

(Continued on Next Page)

Street Tree Inventory

SW 20th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH ST	Christmas Palm	21-30"	Yes	20'	Good (61% to 80%)				
SW 20TH ST	Frangipani	1-5"	No	10'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 20TH ST	Slash Pine	1-5"	No	15'	Good (61% to 80%)				
SW 20TH ST	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 20TH ST	Sea Grape	11-15"	No	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Reduced Canopy - Major	Dead Wood
SW 20TH ST	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Sprouting		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Restricted Canopy	
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Restricted Canopy	
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Restricted Canopy	
SW 20TH ST	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Restricted Canopy	
SW 20TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Restricted Canopy	
SW 20TH ST	Solitaire Palm	1-5"	Yes	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Restricted Canopy	

Streets | Terraces | Lanes



Looking East - SW 27th Avenue



Looking East - SW 22nd Avenue



Looking East - SW 27th Avenue



Looking West - SW 21st Avenue



Looking East - SW 19th Avenue



Looking West - SW 13th Avenue



Looking West- SW 19th Avenue



Looking West - SW 13th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 21st Street	2	Shenandoah South	4	50	2505	No	No	Yes	2	City	Yes	Yes	4-7	Yes except b/t 17th and 13th Ave	Yes	South side b/t 27th and 25th Ave	Grass and some paved swales with on street parking. Roundabout at SW 18th Ave.
SW 21st Terrace	2	Shenandoah South	4	50	7140	No	No	Yes	2	City	Yes	Yes	4-7	Yes except b/t 13 and 14th Avenue	Yes	South side east of 17th Ave	Grass and some paved swales with on street parking. One-way only between SW 13th-14th Ave

SW 21st Street

TYPOLOGY B & D

SW 21st Terrace

TYPOLOGY B & C

Street Tree Inventory

SW 21st Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST ST	Black Olive	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 21ST ST	Live Oak	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Restricted Canopy	
SW 21ST ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Queen Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Moderate	
SW 21ST ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Restricted Canopy	
SW 21ST ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST ST	Bottle Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST ST	Bottle Palm	11-15"	No	5'	Poor (21% to 40%)	Utility Lines Above	Nutrient Deficiency	Frizzled Fronds	Damaged Fronds
SW 21ST ST	Bottle Palm	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Nutrient Deficiency	Frizzled Fronds	Damaged Fronds
SW 21ST ST	Bottle Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy		
SW 21ST ST	Mahogany	51-60"	No	65'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 21ST ST	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 21ST ST	Weeping Fig	6-10"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Gumbo Limbo	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 21ST ST	Lancepod	11-15"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 21ST ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Coconut Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Coconut Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Purple Castor Bean	1-5"	No	10'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Major	Dead Wood
SW 21ST ST	Indian Rosewood	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 21ST ST	Sea Grape	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Basal Co-Dominant		
SW 21ST ST	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST ST	Weeping Fig	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant	Dead Wood	Sprouting
SW 21ST ST	Slash Pine	21-30"	No	40'	Good (61% to 80%)	Utility Line Conflict	Dead Wood		
SW 21ST ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Suppressed Canopy	Dead Wood	Codominant Leaders/Included Bark
SW 21ST ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Restricted Canopy	Dead Wood	Codominant Leaders/Included Bark
SW 21ST ST	Mahogany	11-15"	No	35'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 21ST ST	Bottlebrush	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Codominant Leaders/Included Bark	Sprouting	
SW 21ST ST	Bottlebrush	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 21ST ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 21ST ST	Mahogany	41-50"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 21st Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST ST	Manila Tamarind	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 21ST ST	Yellow Tabebuia	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 21ST ST	Yellow Tabebuia	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Topped	Sprouting	Trunk Damage - Moderate
SW 21ST ST	Sapodilla	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 21ST ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 21ST ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 21ST ST	Mahogany	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Dead Wood
SW 21ST ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 21ST ST	Green Buttonwood	1-5"	No	15'	Good (61% to 80%)		Sprouting		
SW 21ST ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 21ST ST	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				
SW 21ST ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Tropical Almond	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Topped	Sprouting
SW 21ST ST	White Frangipani	6-10"	No	5'	Good (61% to 80%)		Basal Co-Dominant		
SW 21ST ST	White Frangipani	11-15"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	White Frangipani	6-10"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	White Frangipani	11-15"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Live Oak	6-10"	Yes	20'	Good (61% to 80%)		Sprouting	Dead Wood	
SW 21ST ST	Java Bishopwood	16-20"	No	35'	Good (61% to 80%)		Constricted Roots	Topped	Sprouting
SW 21ST ST	Royal Poinciana	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 21ST ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Desiccated Foliage	Trunk Damage - Minor
SW 21ST ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Desiccated Foliage	Trunk Damage - Minor
SW 21ST ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Desiccated Foliage	Trunk Damage - Minor
SW 21ST ST	White Frangipani	1-5"	No	5'	Fair (41% to 60%)		Topped	Sprouting	
SW 21ST ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Starburst Clerodendron	16-20"	Yes	10'	Fair (41% to 60%)		Topped	Sprouting	
SW 21ST ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Leader - Broken	
SW 21ST ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate	Dead Wood	
SW 21ST ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 21ST ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Trunk Damage - Minor	Nutrient Deficiency	
SW 21ST ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Nutrient Deficiency	
SW 21ST ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots		
SW 21ST ST	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 21ST ST	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 21ST ST	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots		
SW 21ST ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	

(Continued on Next Page)

Street Tree Inventory

SW 21st Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST ST	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	
SW 21ST ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Minor	Dead Wood
SW 21ST ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST ST	Royal Poinciana	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Japanese Fern Tree	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Japanese Fern Tree	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Japanese Fern Tree	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Simpson's Stopper	1-5"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Simpson's Stopper	1-5"	No	5'	Good (61% to 80%)				
SW 21ST ST	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Restricted Canopy	
SW 21ST ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 21ST ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 21ST ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 21ST ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 21ST ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 21ST ST	Solitaire Palm	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Oriental Arborvitae	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Yellow Elder	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST ST	Narrow Leaf Ficus	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Nutrient Deficiency	
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST ST	Tropical Almond	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots		
SW 21ST ST	Pink Tabebuia	11-15"	No	10'	Very Poor/Critical (6% to		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 21ST ST	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST ST	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 21ST ST	Washington Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 21ST ST	Java Plum	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Topped
SW 21ST ST	Java Plum	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Topped
SW 21ST ST	Weeping Fig	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Tropical Almond	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Topped
SW 21ST ST	Sapodilla	21-30"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST ST	Starburst Clerodendron	6-10"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Topped	
SW 21ST ST	Black Olive	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 21ST ST	Live Oak	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	Codominant Leaders/Included Bark
SW 21ST ST	Black Olive	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 21ST ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Restricted Canopy
SW 21ST ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Pygmy Date Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Pop Ash	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST ST	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 21ST ST	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 21st Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Dead Wood	Restricted Canopy
SW 21ST ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Sprouting
SW 21ST ST	Live Oak	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 21ST ST	Live Oak	6-10"	No	10'	Very Poor/Critical (6% to		Reduced Canopy - Major	Topped	Dead Wood
SW 21ST ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Major	Dead Wood	
SW 21ST ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 21ST ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Codominant Leaders/Included Bark
SW 21ST ST	Mahogany	31-40"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 21ST ST	Mahogany	41-50"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Topped
SW 21ST ST	Gumbo Limbo	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 21ST ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Pygmy Date Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Pygmy Date Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	
SW 21ST ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 21ST ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 21ST ST	Pigeon Plum	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Insect Damage Leaves	Reduced Canopy - Moderate
SW 21ST ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 21ST ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Leader - Broken	Codominant Leaders/Included Bark	Sprouting
SW 21ST ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders/Included Bark
SW 21ST ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders/Included Bark
SW 21ST ST	Oriental Arborvitae	1-5"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Oriental Arborvitae	6-10"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Oriental Arborvitae	6-10"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Oriental Arborvitae	6-10"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Oriental Arborvitae	6-10"	Yes	5'	Good (61% to 80%)				
SW 21ST ST	Pitch Apple	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Pitch Apple	6-10"	Yes	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 21st Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST ST	Pitch Apple	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Pitch Apple	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Pitch Apple	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 21ST ST	Mahogany	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 21ST ST	Mahogany	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 21ST ST	Spindle Palm	11-15"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Tapered Trunk	Nutrient Deficiency
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor	Nutrient Deficiency	
SW 21ST ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 21ST ST	Horseflesh Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 21ST ST	Paradise Tree	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 21ST ST	Paradise Tree	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots		
SW 21ST ST	Paradise Tree	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Sprouting	Trunk Damage - Minor
SW 21ST ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Sprouting	
SW 21ST ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 21ST ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST ST	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Mahogany	41-50"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Areca Palm	16-20"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 21ST ST	Areca Palm	16-20"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Mahogany	41-50"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Mahogany	51-60"	No	55'	Poor (21% to 40%)		Constricted Roots	Decay Observed	Reduced Canopy - Moderate
SW 21ST ST	Mahogany	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 21ST ST	Tamarind	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/No Included Bark
SW 21ST ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 21ST ST	Jacaranda	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders/Included Bark
SW 21ST ST	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Reduced Canopy - Minor
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Restricted Canopy	Nutrient Deficiency
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Yellow Poinciana	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	Codominant Leaders/Included Bark
SW 21ST ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Royal Poinciana	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Sprouting	Dead Wood
SW 21ST ST	Vera Wood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST ST	Orange Geiger	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Topped	Reduced Canopy - Major	Sprouting
SW 21ST ST	Hibiscus sp.	1-5"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Peregrina	6-10"	Yes	15'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	
SW 21ST ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	Strap Constricting Tree
SW 21ST ST	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Over Pruned	
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Christmas Palm	11-15"	No	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 21st Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST ST	Pitch Apple	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Pitch Apple	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Pitch Apple	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 21ST ST	Mahogany	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 21ST ST	Mahogany	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 21ST ST	Spindle Palm	11-15"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Tapered Trunk	Nutrient Deficiency
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor	Nutrient Deficiency	
SW 21ST ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 21ST ST	Horseflesh Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 21ST ST	Paradise Tree	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 21ST ST	Paradise Tree	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots		
SW 21ST ST	Paradise Tree	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Sprouting	Trunk Damage - Minor
SW 21ST ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor	Sprouting	
SW 21ST ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 21ST ST	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST ST	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Mahogany	41-50"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Areca Palm	16-20"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 21ST ST	Areca Palm	16-20"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Mahogany	41-50"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Mahogany	51-60"	No	55'	Poor (21% to 40%)		Constricted Roots	Decay Observed	Reduced Canopy - Moderate
SW 21ST ST	Mahogany	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 21ST ST	Tamarind	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/No Included Bark
SW 21ST ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 21ST ST	Jacaranda	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders/Included Bark
SW 21ST ST	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Reduced Canopy - Minor
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Restricted Canopy	Nutrient Deficiency
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Yellow Poinciana	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	Codominant Leaders/Included Bark
SW 21ST ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Royal Poinciana	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Sprouting	Dead Wood
SW 21ST ST	Vera Wood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST ST	Orange Geiger	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Topped	Reduced Canopy - Major	Sprouting
SW 21ST ST	Hibiscus sp.	1-5"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Peregrina	6-10"	Yes	15'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	
SW 21ST ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	Strap Constricting Tree
SW 21ST ST	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Over Pruned	
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST ST	Christmas Palm	11-15"	No	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 21st Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	11-15"	No	15'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	11-15"	No	15'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	11-15"	No	15'	Good (61% to 80%)				
SW 21ST ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 21ST ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 21ST ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 21ST ST	Tamarind	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Tamarind	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST ST	Tamarind	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST ST	Tamarind	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Suppressed Canopy		
SW 21ST ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Suppressed Canopy		

SW 21st Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST TER	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)		Basal Co-Dominant		
SW 21ST TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST TER	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Desiccated Foliage	Crown Density - Moderate	Dead Wood
SW 21ST TER	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Dead Wood
SW 21ST TER	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 21ST TER	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST TER	Yucca sp.	11-15"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Yucca sp.	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 21ST TER	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST TER	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST TER	Royal Poinciana	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Royal Poinciana	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Codominant Leaders/Included Bark
SW 21ST TER	Umbrella Tree	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Reduced Canopy - Moderate

(Continued on Next Page)

Street Tree Inventory

SW 21st Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST TER	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 21ST TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Low	Insect Damage Leaves	Dead Wood
SW 21ST TER	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Crown Density - Moderate	Insect Damage Leaves	Dead Wood
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 21ST TER	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Sprouting	Codominant Leaders/Included Bark
SW 21ST TER	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lifting	Dead Wood
SW 21ST TER	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 21ST TER	Wild Lime	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST TER	Avocado	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Sprouting	Codominant Leaders/Included Bark
SW 21ST TER	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Mahogany	41-50"	No	70'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 21ST TER	Sea Grape	16-20"	No	10'	Poor (21% to 40%)		Basal Co-Dominant	Topped	Sprouting
SW 21ST TER	Sea Grape	16-20"	No	10'	Poor (21% to 40%)		Basal Co-Dominant	Topped	Sprouting
SW 21ST TER	Sea Grape	16-20"	No	10'	Poor (21% to 40%)		Basal Co-Dominant	Topped	Sprouting
SW 21ST TER	Sea Grape	11-15"	No	10'	Poor (21% to 40%)		Basal Co-Dominant	Topped	Sprouting
SW 21ST TER	Weeping Fig	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST TER	Mahogany	51-60"	No	70'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 21ST TER	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Lifting	Dead Wood
SW 21ST TER	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Banyan	1-5"	No	15'	Good (61% to 80%)				
SW 21ST TER	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)				
SW 21ST TER	Banyan	1-5"	No	15'	Good (61% to 80%)				
SW 21ST TER	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)				
SW 21ST TER	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST TER	Mahogany	51-60"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 21ST TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 21ST TER	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 21ST TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 21ST TER	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST TER	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Limb Damage - Minor	
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 21ST TER	Black Olive	16-20"	No	20'	Very Poor/Critical (6% to		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 21ST TER	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 21ST TER	Royal Poinciana	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Reduced Canopy - Major
SW 21ST TER	Banyan	1-5"	No	15'	Good (61% to 80%)		Basal Co-Dominant		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Live Oak	31-40"	No	55'	Good (61% to 80%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST TER	Mahogany	21-30"	No	20'	Very Poor/Critical (6% to		Topped	Reduced Canopy - Major	Sprouting
SW 21ST TER	Mahogany	41-50"	No	40'	Poor (21% to 40%)		Constricted Roots	Girdling Roots	Reduced Canopy - Major
SW 21ST TER	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 21st Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST TER	Black Olive	41-50"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Ficus Growing on Tree	Sprouting
SW 21ST TER	Bamboo Palm	16-20"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Mahogany	21-30"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST TER	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 21ST TER	Mahogany	60+"	No	50'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Constricted Roots	Basal Co-Dominant	Reduced Canopy - Major
SW 21ST TER	Mahogany	41-50"	No	35'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Restricted Canopy		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 21ST TER	Norfolk Pine	1-5"	Yes	5'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Sacred Fig	16-20"	No	20'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 21ST TER	Peregrina	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above	Basal Co-Dominant	Dead Wood	
SW 21ST TER	White Frangipani	1-5"	No	5'	Good (61% to 80%)		Basal Co-Dominant		
SW 21ST TER	White Frangipani	6-10"	No	5'	Good (61% to 80%)		Basal Co-Dominant		
SW 21ST TER	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Black Olive	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 21ST TER	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 21ST TER	Live Oak	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Cabbage Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Black Olive	31-40"	No	45'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 21ST TER	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST TER	Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST TER	Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 21ST TER	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Royal Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 21ST TER	Japanese Privet	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Low	Codominant Leaders/Included Bark	Dead Wood
SW 21ST TER	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 21ST TER	Jamaican Dogwood	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST TER	White Frangipani	1-5"	No	5'	Good (61% to 80%)		Basal Co-Dominant		
SW 21ST TER	White Frangipani	11-15"	No	5'	Good (61% to 80%)		Basal Co-Dominant		
SW 21ST TER	Solitaire Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Damaged Fronds	
SW 21ST TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Damaged Fronds	
SW 21ST TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Damaged Fronds	Trunk Damage - Minor
SW 21ST TER	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST TER	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	Damaged Fronds
SW 21ST TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Damaged Fronds	
SW 21ST TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Damaged Fronds	
SW 21ST TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 21st Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST TER	Desert Cassia	6-10"	No	15'	Fair (41% to 60%)		Basal Co-Dominant	Insect Damage Leaves	Dead Wood
SW 21ST TER	Weeping Fig	6-10"	No	15'	Good (61% to 80%)		Pruned Into Shrub	Crown Density - Moderate	Dead Wood
SW 21ST TER	Royal Palm	21-30"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Pencil Top	Nutrient Deficiency
SW 21ST TER	Paradise Tree	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Dead Wood
SW 21ST TER	Paradise Tree	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Minor	Dead Wood
SW 21ST TER	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structur	Pruned Into Shrub	
SW 21ST TER	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structur	Pruned Into Shrub	
SW 21ST TER	Norfolk Pine	11-15"	No	15'	Good (61% to 80%)		Basal Co-Dominant		
SW 21ST TER	Mango	1-5"	No	5'	Good (61% to 80%)				
SW 21ST TER	Mango	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 21ST TER	Starburst Clerodendron	11-15"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	
SW 21ST TER	Gumbo Limbo	1-5"	No	15'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	
SW 21ST TER	Peregrina	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 21ST TER	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Major		
SW 21ST TER	Frangipani	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Norfolk Pine	16-20"	No	15'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Norfolk Pine	16-20"	No	15'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	
SW 21ST TER	Green Buttonwood	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 21ST TER	Solitaire Palm	1-5"	Yes	5'	Poor (21% to 40%)		Dead Meristem	Nutrient Deficiency	
SW 21ST TER	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST TER	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 21ST TER	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST TER	Umbrella Tree	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots		
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Moderate	
SW 21ST TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 21ST TER	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Limb Damage - Minor
SW 21ST TER	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST TER	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 21ST TER	Royal Poinciana	6-10"	No	30'	Good (61% to 80%)		Dead Wood	Restricted Canopy	
SW 21ST TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Solitaire Palm	1-5"	No	Negligible	Very Poor/Critical (6% to		Crown Density - Very Low	Nutrient Deficiency	
SW 21ST TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 21st Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Royal Poinciana	16-20"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Solitaire Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub	Dead Wood	
SW 21ST TER	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Dead Wood	
SW 21ST TER	Queen Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	Sprouting
SW 21ST TER	Horseflesh Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST TER	Lead Tree	11-15"	No	15'	Very Poor/Critical (6% to		Topped	Reduced Canopy - Major	Disease
SW 21ST TER	Cabbage Palm	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Ficus Growing on Tree		
SW 21ST TER	Strangler Fig	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Weeping Fig	1-5"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Leaning - Major	Dead Wood	
SW 21ST TER	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Dead Wood	Multi-Trunk Form - Not Downgraded for Struct	
SW 21ST TER	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Dead Wood	Multi-Trunk Form - Not Downgraded for Struct	
SW 21ST TER	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Dead Wood	Multi-Trunk Form - Not Downgraded for Struct	
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST TER	Vera Wood	1-5"	No	15'	Good (61% to 80%)				
SW 21ST TER	Peregrina	6-10"	Yes	10'	Good (61% to 80%)		Dead Wood		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 21ST TER	Hong Kong Orchid	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Dead Wood	Sprouting
SW 21ST TER	Mahogany	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 21ST TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 21ST TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 21ST TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Queen Palm	6-10"	No	5'	Very Poor/Critical (6% to		Dead Meristem	Nutrient Deficiency	Frizzled Fronds
SW 21ST TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 21ST TER	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 21ST TER	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 21ST TER	Japanese Golden Rain Tree	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	

(Continued on Next Page)

Street Tree Inventory

SW 21st Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Live Oak	1-5"	No	15'	Good (61% to 80%)		Dead Wood		
SW 21ST TER	Longan	6-10"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST TER	Bottlebrush	1-5"	No	15'	Good (61% to 80%)		Dead Wood		
SW 21ST TER	Bottlebrush	1-5"	No	5'	Good (61% to 80%)		Reduced Canopy - Moderate	Dead Wood	
SW 21ST TER	Weeping Fig	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 21ST TER	Royal Poinciana	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 21ST TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	Leader - Bent
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	Leader - Bent
SW 21ST TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	Leader - Bent
SW 21ST TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST TER	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST TER	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 21ST TER	Live Oak	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting

Bordering Streets



Looking East - SW 27th Avenue



Looking East - SW 19th Avenue



Looking East- SW 27th Avenue



Looking West - SW 25th Avenue



Looking East - SW 16th Avenue



Looking West - SW 12th Avenue



Looking West - SW 18th Avenue



Looking West - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 16th Street	2	Shenandoah South	4	50	7920	No	No	Yes	3	City	some, mostly east of 17th Avenue	Yes	6 (East of 22nd Ave)	Yes	Yes	Both sides, west of 22nd Avenue	West of 22nd Avenue, share the road lanes with on street parking. Intermittent trees and palms. East of 22nd Avenue grass swales, some designated on- street parking. Roundabout at 14th Ave, 21st Ave, and 18th Ave.
SW 22nd Street (Coral Way)	2	Shenandoah South	4	100	7660	Yes	No	Yes	4	State	Yes	Few	0	Yes	Yes	No	Main street, share the road lanes. Tree lines planted median.

SW 16th Street

TYPOLOGY B & D

SW 22nd Street (Coral Way)

TYPOLOGY F

Street Tree Inventory

SW 16th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH ST	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)				
SW 16TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Royal Poinciana	1-5"	No	5'	Very Poor/Critical (6% to		Girdling Roots	Leader - Broken	Sprouting
SW 16TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Jacaranda	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 16TH ST	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Lychee	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Lychee	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Lychee	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Black Olive	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 16TH ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 16TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 16TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Ficus Growing on Tree
SW 16TH ST	Rubber Tree	6-10"	Yes	10'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate	Dead Wood
SW 16TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Mahogany	41-50"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 16TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 16TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 16TH ST	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Weeping Fig	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 16TH ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Vine Cover - Heavy		
SW 16TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Vine Cover - Heavy		
SW 16TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 16TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Citrus sp.	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 16TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 16TH ST	Bamboo Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Earleaf Acacia	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 16TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Weeping Fig	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 16TH ST	Weeping Fig	31-40"	No	25'	Poor (21% to 40%)		Reduced Canopy - Major	Sprouting	White Fly
SW 16TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 16th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Pitch Apple	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Trunk Damage - Minor	
SW 16TH ST	Pitch Apple	1-5"	No	10'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 16TH ST	Japanese Privet	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Moderate	Desiccated Foliage	Dead Wood
SW 16TH ST	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 16TH ST	Sapodilla	16-20"	No	25'	Poor (21% to 40%)		Girdling Roots	Reduced Canopy - Major	Sprouting
SW 16TH ST	Sapodilla	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 16TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 16TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Nutrient Deficiency		
SW 16TH ST	Vera Wood	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Leader - Broken	Codominant Leaders/Included Bark	Crown Density - Moderate
SW 16TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 16TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Crown Density - Moderate	
SW 16TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH ST	Vera Wood	6-10"	No	Negligible	Dead (0% to 5%)		Basal Co-Dominant		
SW 16TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 16TH ST	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 16TH ST	Sapodilla	6-10"	No	20'	Good (61% to 80%)				
SW 16TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 16TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	Dead Wood
SW 16TH ST	Rainbow Eucalyptus	1-5"	No	10'	Fair (41% to 60%)		Leader - Broken	Codominant Leaders/Included Bark	Dead Wood
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Cracks in Trunk	Dead Wood
SW 16TH ST	Orange Geiger	1-5"	No	5'	Fair (41% to 60%)		Leader - Bent	Insect Damage Leaves	
SW 16TH ST	Orange Geiger	1-5"	No	5'	Fair (41% to 60%)		Leader - Bent	Insect Damage Leaves	
SW 16TH ST	Orange Geiger	1-5"	No	5'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Insect Damage Leaves	
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Cracks in Trunk	Sprouting
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 16TH ST	Golden Shower Tree	11-15"	No	30'	Very Poor/Critical (6% to	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 16TH ST	Golden Shower Tree	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 16TH ST	Golden Shower Tree	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Dead Wood
SW 16TH ST	Montgomery Palm	11-15"	Yes	15'	Good (61% to 80%)		Reduced Canopy - Minor	Strap Constricting Tree	
SW 16TH ST	Golden Shower Tree	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Dead Wood
SW 16TH ST	Golden Shower Tree	11-15"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Decay Observed
SW 16TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Reduced Canopy - Moderate
SW 16TH ST	Chinese Fan Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 16TH ST	Gumbo Limbo	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate
SW 16TH ST	Gumbo Limbo	16-20"	No	45'	Poor (21% to 40%)		Girdling Roots	Restricted Canopy	Reduced Canopy - Moderate
SW 16TH ST	Gumbo Limbo	16-20"	No	30'	Very Poor/Critical (6% to		Reduced Canopy - Major	Trunk Damage - Major	Cavities
SW 16TH ST	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts
SW 16TH ST	Frangipani	11-15"	No	25'	Poor (21% to 40%)		Suppressed Canopy	Limb Damage - Major	Cavities
SW 16TH ST	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Reduced Canopy - Moderate

(Continued on Next Page)

Street Tree Inventory

SW 16th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH ST	Black Olive	31-40"	No	65'	Poor (21% to 40%)		Constricted Roots	Vine Cover - Heavy	Codominant Leaders - Multi
SW 16TH ST	Black Olive	31-40"	No	55'	Poor (21% to 40%)		Constricted Roots	Vine Cover - Heavy	Stubs with Sprouts
SW 16TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 16TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 16TH ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Fungus on Leaves		
SW 16TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH ST	Mahogany	31-40"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 16TH ST	Lead Tree	1-5"	No	5'	Poor (21% to 40%)		Suppressed Canopy	Reduced Canopy - Major	Dead Wood
SW 16TH ST	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Reduced Canopy - Major	Decay Observed	Stubs with Sprouts
SW 16TH ST	Mahogany	31-40"	No	45'	Very Poor/Critical (6% to		Lopsided/Reduced Canopy - Major	Dead Wood	Codominant Leaders - Multi
SW 16TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 16TH ST	Horseflesh Mahogany	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched		
SW 16TH ST	Sapodilla	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 16TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)		Fungus on Leaves		
SW 16TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 16TH ST	Coconut Palm	1-5"	No	10'	Fair (41% to 60%)		Over Pruned		
SW 16TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Over Pruned		
SW 16TH ST	Coconut Palm	1-5"	No	10'	Fair (41% to 60%)		Over Pruned		
SW 16TH ST	Canary Island Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH ST	Canary Island Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 16TH ST	Golden Shower Tree	11-15"	No	40'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Dead Wood
SW 16TH ST	Golden Shower Tree	16-20"	No	35'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Dead Wood
SW 16TH ST	Golden Shower Tree	16-20"	No	45'	Poor (21% to 40%)		Stubs with Sprouts	Codominant Leaders/Included Bark	Dead Wood
SW 16TH ST	Golden Shower Tree	11-15"	No	35'	Poor (21% to 40%)		Stubs with Sprouts	Codominant Leaders/No Included Bark	Dead Wood
SW 16TH ST	Golden Shower Tree	11-15"	No	35'	Poor (21% to 40%)		Stubs with Sprouts	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 16TH ST	Golden Shower Tree	11-15"	No	40'	Poor (21% to 40%)		Stubs with Sprouts	Codominant Leaders/Included Bark	Limb Damage - Moderate
SW 16TH ST	Lead Tree	6-10"	No	35'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Reduced Canopy - Major	
SW 16TH ST	Golden Shower Tree	1-5"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Lopsided/Reduced Canopy - Major	
SW 16TH ST	Golden Shower Tree	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 16TH ST	Golden Shower Tree	16-20"	No	45'	Fair (41% to 60%)		Stubs with Sprouts	Codominant Leaders - Multi	Limb Damage - Moderate
SW 16TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH ST	Coconut Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			

SW 22nd Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND ST	Black Olive	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 22ND ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Minor
SW 22ND ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Girdling Roots	Restricted Canopy	Reduced Canopy - Minor
SW 22ND ST	Black Olive	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Black Olive	11-15"	No	35'	Good (61% to 80%)		Reduced Canopy - Moderate	Dead Wood	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 22nd Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 22ND ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 22ND ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND ST	Black Olive	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	Sprouting
SW 22ND ST	Black Olive	31-40"	No	65'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 22ND ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Black Olive	6-10"	No	25'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Dead Wood	Sprouting
SW 22ND ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Black Olive	16-20"	No	45'	Good (61% to 80%)		Lopsided/Moderately Reduced Canopy	Sprouting	
SW 22ND ST	Black Olive	6-10"	No	20'	Fair (41% to 60%)		Suppressed Canopy	Restricted Canopy	Reduced Canopy - Moderate
SW 22ND ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Tapered Trunk	Nutrient Deficiency	
SW 22ND ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 22ND ST	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 22ND ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 22ND ST	Black Olive	16-20"	No	40'	Good (61% to 80%)		Reduced Canopy - Moderate	Dead Wood	Sprouting
SW 22ND ST	Black Olive	11-15"	No	25'	Very Poor/Critical (6% to		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 22ND ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)				
SW 22ND ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)				
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 22ND ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 22ND ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)				


Avenues | Courts




Looking South - SW 17th Street



Looking North - SW 18th Street



Looking North - SW 21th Street



Looking North - Between SW 21st Street and 20th Street



Looking North - SW 20th Street



Looking North - SW 21st Terrace



Looking North - Between SW 21st Street and 20th Street



Looking South - SW 20th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 13th Avenue	2	Shenandoah South	4	100	2700	No	No	Yes	2	City	Yes	Yes	15	Yes	Yes	East side	Heavily planted median with winding walkway.
SW 13th Court	2	Shenandoah South	4	60	360	No	No	Yes	2	City	Extremely few	Yes	9	No	Yes	West side	Curbless grass and gravel swales.

SW 13th Avenue

TYPOLOGY I

SW 13th Court

TYPOLOGY A

Street Tree Inventory

SW 13th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Good (61% to 80%)		Dead Wood	Improperly Mulched	
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Minor	Dead Wood
SW 13TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH AVE	Montgomery Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Frizzled Fronds	Over Pruned
SW 13TH AVE	Pygmy Date Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 13TH AVE	Bougainvillea sp.	6-10"	Yes	15'	Good (61% to 80%)		Basal Co-Dominant	Dead Wood	
SW 13TH AVE	Avocado	11-15"	No	25'	Fair (41% to 60%)		Leader - Broken	Reduced Canopy - Minor	Dead Wood
SW 13TH AVE	Mahogany	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Royal Poinciana	21-30"	No	60'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	Sprouting
SW 13TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 13TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 13TH AVE	Mahogany	11-15"	No	45'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	Sprouting
SW 13TH AVE	Mahogany	6-10"	No	Negligible	Dead (0% to 5%)				
SW 13TH AVE	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Girdling Roots	Trunk Damage - Major	Limb Damage - Minor
SW 13TH AVE	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Crown Density - Low	Insect Damage Leaves	Dead Wood
SW 13TH AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 13TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Lifting	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Lifting	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	15'	Good (61% to 80%)		Improperly Mulched	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Brazilian Beauty Leaf	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	20'	Good (61% to 80%)		Lopsided/Moderately Reduced Canopy	Dead Wood	Sprouting
SW 13TH AVE	Dracaena sp.	1-5"	No	5'	Good (61% to 80%)		Basal Co-Dominant		
SW 13TH AVE	Lead Tree	21-30"	No	60'	Good (61% to 80%)		Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 13TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 13TH AVE	Yellow Poinciana	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Major	Sprouting	Dead Wood
SW 13TH AVE	Weeping Fig	51-60"	No	60'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 13TH AVE	Weeping Fig	31-40"	No	55'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 13TH AVE	Weeping Fig	21-30"	No	45'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 13TH AVE	Strangler Fig	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Insect Damage Leaves	Dead Wood
SW 13TH AVE	Yellow Poinciana	6-10"	No	25'	Good (61% to 80%)		Limb Damage - Minor	Sprouting	Dead Wood
SW 13TH AVE	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 13TH AVE	Mango	1-5"	No	5'	Fair (41% to 60%)		Basal Co-Dominant	Dead Wood	Sprouting
SW 13TH AVE	Areca Palm	31-40"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH AVE	Live Oak	11-15"	Yes	35'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 13TH AVE	Coconut Palm	16-20"	Yes	30'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 13TH AVE	Mahogany	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 13TH AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 13TH AVE	Areca Palm	41-50"	Yes	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 13TH AVE	Norfolk Pine	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 13TH AVE	Norfolk Pine	21-30"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 13TH AVE	Norfolk Pine	31-40"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 13TH AVE	Norfolk Pine	31-40"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 13TH AVE	Yellow Poinciana	60+"	No	70'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 13TH AVE	Weeping Fig	41-50"	No	60'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Sprouting	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 13th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Weeping Fig	31-40"	No	45'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	Dead Wood
SW 13TH AVE	Weeping Fig	31-40"	No	55'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 13TH AVE	Yellow Poinciana	6-10"	No	25'	Good (61% to 80%)		Strap Constricting Tree	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Sprouting
SW 13TH AVE	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Crown Density - Moderate	Reduced Canopy - Minor	Dead Wood
SW 13TH AVE	Live Oak	11-15"	No	40'	Fair (41% to 60%)	Utility Lines Above	Girdling Roots	Dead Wood	Sprouting
SW 13TH AVE	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 13TH AVE	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 13TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 13TH AVE	Pink Tabebuia	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 13TH AVE	Brazilian Beauty Leaf	1-5"	No	10'	Fair (41% to 60%)		Improperly Mulched	Crown Density - Low	Dead Wood
SW 13TH AVE	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Sprouting	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Yellow Poinciana	1-5"	No	20'	Good (61% to 80%)		Limb Damage - Minor	Sprouting	Dead Wood
SW 13TH AVE	Yellow Poinciana	1-5"	No	20'	Good (61% to 80%)		Limb Damage - Minor	Sprouting	Dead Wood
SW 13TH AVE	Weeping Fig	41-50"	No	55'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	Dead Wood
SW 13TH AVE	Weeping Fig	31-40"	No	50'	Good (61% to 80%)		Lopsided/Moderately Reduced Canopy	Sprouting	Dead Wood
SW 13TH AVE	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Suppressed Canopy	Limb Damage - Minor
SW 13TH AVE	Royal Poinciana	16-20"	No	45'	Good (61% to 80%)		Trunk Damage - Minor	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	40'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	Dead Wood
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	35'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	Dead Wood
SW 13TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Damaged Fronds	Restricted Canopy	
SW 13TH AVE	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 13TH AVE	Tropical Almond	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 13TH AVE	Tropical Almond	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 13TH AVE	Yellow Poinciana	6-10"	No	25'	Fair (41% to 60%)		Leader - Broken	Sprouting	Dead Wood
SW 13TH AVE	Weeping Fig	31-40"	No	45'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 13TH AVE	Weeping Fig	31-40"	No	50'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 13TH AVE	Weeping Fig	31-40"	No	50'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 13TH AVE	Mahogany	11-15"	No	25'	Good (61% to 80%)		Restricted Canopy	Sprouting	Dead Wood
SW 13TH AVE	Jamaican Dogwood	11-15"	No	35'	Good (61% to 80%)		Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 13TH AVE	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Limb Damage - Minor	Sprouting	Dead Wood
SW 13TH AVE	Loquat	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Pink Tabebuia	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Dead Wood	Sprouting
SW 13TH AVE	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 13TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 13th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Live Oak	21-30"	No	50'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Dead Wood	Sprouting
SW 13TH AVE	Strangler Fig	6-10"	No	15'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	Sprouting
SW 13TH AVE	Weeping Fig	21-30"	No	45'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	Sprouting
SW 13TH AVE	Weeping Fig	31-40"	No	55'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	Sprouting
SW 13TH AVE	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Leader - Broken	Reduced Canopy - Major	Sprouting
SW 13TH AVE	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 13TH AVE	Live Oak	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Live Oak	6-10"	No	Negligible	Dead (0% to 5%)				
SW 13TH AVE	Live Oak	6-10"	No	25'	Poor (21% to 40%)		Trunk Damage - Moderate	Lopsided/Significantly Reduced Canopy	Sprouting
SW 13TH AVE	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Trunk Damage - Major	Reduced Canopy - Moderate	Sprouting
SW 13TH AVE	Mahogany	11-15"	No	30'	Good (61% to 80%)		Limb Damage - Minor	Sprouting	Dead Wood
SW 13TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 13TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 13TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 13TH AVE	Silver Buttonwood	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Basal Co-Dominant	Dead Wood	Sprouting
SW 13TH AVE	Silver Buttonwood	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Basal Co-Dominant	Dead Wood	Sprouting
SW 13TH AVE	Silver Buttonwood	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Basal Co-Dominant	Dead Wood	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 13TH AVE	Black Olive	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Black Olive	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Black Olive	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Black Olive	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Crown Density - Moderate	Dead Wood	Sprouting
SW 13TH AVE	Date Palm	16-20"	No	20'	Fair (41% to 60%)		Over Pruned	Nutrient Deficiency	
SW 13TH AVE	Date Palm	16-20"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH AVE	Bougainvillea sp.	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 13TH AVE	Desert Cassia	1-5"	No	15'	Good (61% to 80%)		Limb Damage - Minor	Sprouting	Dead Wood
SW 13TH AVE	Desert Cassia	1-5"	No	10'	Poor (21% to 40%)		Crown Density - Very Low	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Desert Cassia	1-5"	No	15'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Desert Cassia	1-5"	No	10'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 13TH AVE	Desert Cassia	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Crown Density - Moderate	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Desert Cassia	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Crown Density - Moderate	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Desert Cassia	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Crown Density - Moderate	Dead Wood	Codominant Leaders/Included Bark
SW 13TH AVE	Desert Cassia	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 13TH AVE	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Tapered Trunk	Frizzled Fronds	Nutrient Deficiency
SW 13TH AVE	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Tapered Trunk	Frizzled Fronds	Nutrient Deficiency
SW 13TH AVE	Sacred Fig	60+"	No	85'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Live Oak	31-40"	No	45'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 13TH AVE	Mahogany	6-10"	No	15'	Good (61% to 80%)		Sprouting	Dead Wood	
SW 13TH AVE	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Sprouting	Dead Wood
SW 13TH AVE	Weeping Fig	41-50"	No	60'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Sprouting	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 13th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Weeping Fig	41-50"	No	60'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Sprouting	Dead Wood
SW 13TH AVE	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 13TH AVE	Mahogany	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 13TH AVE	Brazilian Beauty Leaf	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 13TH AVE	Loquat	11-15"	No	30'	Very Poor/Critical (6% to	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Crown Density - Very Low
SW 13TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 13TH AVE	Solitaire Palm	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Nutrient Deficiency	Frizzled Fronds	
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 13TH AVE	Brazilian Beauty Leaf	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting

SW 13th Court

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH CT	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH CT	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH CT	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH CT	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 13TH CT	Queen Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 13TH CT	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 13TH CT	Bottle Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 13TH CT	Bottle Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 13TH CT	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 13TH CT	Royal Poinciana	6-10"	No	35'	Good (61% to 80%)		Trunk Damage - Minor	Dead Wood	Codominant Leaders/Included Bark

Avenues | Courts



Looking South - SW 16th Street



Looking South - SW 18th Street



Looking South - SW 16th Street



Looking North - SW 18th Street



Looking South - SW 21st Street



Looking North - SW 22nd Street (Coral Way)



Looking North - SW 18th Street



Looking North - SW 22nd Street (Coral Way)

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 14th Avenue	2	Shenandoah South	4	35-50	2700	No	No	Yes	2	City	Yes	Yes	10 (except on the eastside b/t SW 20th St and 21st Ter)	No	Yes except on west side b/t SW 20th St and 21st Ter.	East side south of 19th Street	Grass, gravel, paved and periodically grass block swales. Narrowing of street and swales to nearly one way.
SW 16th Avenue	2	Shenandoah South	4	60	2500	No	No	Yes	5	County	Yes	Yes	7-10	Yes except between SW 17th Ter and 18th St	Yes	East side	Grass, gravel, paved and periodically grass block swales. Widening of swale between SW 17th Ter and 18th Street, and Coral Way. Roundabout at SW 20th and 19th Street.

SW 14th Avenue

TYPOLOGY A

SW 16th Avenue

TYPOLOGY B & A

Street Tree Inventory

SW 14th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 14TH AVE	Bougainvillea sp.	11-15"	No	10'	Fair (41% to 60%)		Topped	Sprouting	Dead Wood
SW 14TH AVE	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	Dead Wood
SW 14TH AVE	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	Dead Wood
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH AVE	Live Oak	1-5"	No	Negligible	Dead (0% to 5%)				
SW 14TH AVE	Sapodilla	6-10"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Sprouting	
SW 14TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 14TH AVE	Mahogany	11-15"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 14TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 14TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 14TH AVE	Pink Tabebuia	1-5"	No	15'	Good (61% to 80%)		Sprouting	Codominant Leaders/Included Bark	
SW 14TH AVE	Paradise Tree	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sprouting
SW 14TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 14TH AVE	Live Oak	6-10"	No	15'	Good (61% to 80%)		Dead Wood	Sprouting	Codominant Leaders/Included Bark
SW 14TH AVE	Yellow Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 14TH AVE	Tamarind	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	
SW 14TH AVE	Paradise Tree	1-5"	No	15'	Good (61% to 80%)		Dead Wood		
SW 14TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 14TH AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 14TH AVE	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 14TH AVE	Umbrella Tree	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Girdling Roots	Basal Co-Dominant	Trunk Damage - Moderate
SW 14TH AVE	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 14TH AVE	Mahogany	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Dead Wood
SW 14TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 14TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Dead Wood	Sprouting
SW 14TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 14TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Dead Wood
SW 14TH AVE	Live Oak	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 14TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 14TH AVE	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Reduced Canopy - Minor
SW 14TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	Dead Wood
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 14TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 14TH AVE	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 14TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH AVE	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 14TH AVE	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)				
SW 14TH AVE	Southern Magnolia	1-5"	Yes	5'	Fair (41% to 60%)		Basal Co-Dominant	Insect Damage Leaves	
SW 14TH AVE	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)		Dead Wood		
SW 14TH AVE	Southern Magnolia	1-5"	Yes	5'	Poor (21% to 40%)		Basal Co-Dominant	Dead Wood	Insect Damage Leaves
SW 14TH AVE	Southern Magnolia	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 14TH AVE	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH AVE	Pygmy Date Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 14th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 14TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH AVE	Mahogany	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 14TH AVE	Sapodilla	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 14TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH AVE	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 14TH AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 14TH AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 14TH AVE	Gumbo Limbo	6-10"	No	30'	Good (61% to 80%)		Restricted Canopy	Suppressed Canopy	Codominant Leaders/No Included Bark
SW 14TH AVE	Sapodilla	1-5"	No	15'	Good (61% to 80%)		Suppressed Canopy	Restricted Canopy	
SW 14TH AVE	Sapodilla	16-20"	No	15'	Very Poor/Critical (6% to		Constricted Roots	Trunk Damage - Major	Topped
SW 14TH AVE	Weeping Fig	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 14TH AVE	Sapodilla	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 14TH AVE	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)		Basal Co-Dominant	Dead Wood	Sprouting
SW 14TH AVE	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)		Basal Co-Dominant	Crown Density - Moderate	Dead Wood
SW 14TH AVE	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)		Basal Co-Dominant	Crown Density - Moderate	Dead Wood
SW 14TH AVE	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 14TH AVE	Foxtail Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 14TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 14TH AVE	Black Olive	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 14TH AVE	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	Dead Wood

SW 16th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 16TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Trunk Damage - Minor	
SW 16TH AVE	Bottle Palm	6-10"	No	5'	Poor (21% to 40%)	Utility Lines Above	Nutrient Deficiency	Tapered Trunk	Frizzled Fronds
SW 16TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH AVE	Royal Poinciana	1-5"	No	20'	Good (61% to 80%)		Limb Damage - Moderate		
SW 16TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 16TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 16TH AVE	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 16TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 16TH AVE	Bougainvillea sp.	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 16TH AVE	Bougainvillea sp.	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 16TH AVE	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	Sprouting
SW 16TH AVE	Vera Wood	1-5"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 16TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 16TH AVE	Coconut Palm	6-10"	No	5'	Very Poor/Critical (6% to	Utility Lines Adjacent (lateral	Nutrient Deficiency	Damaged Fronds	Frizzled Fronds
SW 16TH AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Sprouting	Dead Wood
SW 16TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Sprouting	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 16th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken	Sprouting	Dead Wood
SW 16TH AVE	Mahogany	41-50"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH AVE	Mahogany	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 16TH AVE	Black Olive	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Dead Wood
SW 16TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Sprouting
SW 16TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH AVE	Royal Poinciana	41-50"	No	50'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 16TH AVE	Live Oak	41-50"	No	45'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 16TH AVE	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH AVE	Mahogany	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 16TH AVE	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 16TH AVE	Gumbo Limbo	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 16TH AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 16TH AVE	Mahogany	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Lopsided/Significantly Reduced Canopy
SW 16TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 16TH AVE	Coconut Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH AVE	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 16TH AVE	Umbrella Tree	31-40"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 16TH AVE	Pink Tabebuia	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 16TH AVE	Live Oak	1-5"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Restricted Canopy	Suppressed Canopy
SW 16TH AVE	Areca Palm	21-30"	Yes	15'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH AVE	Areca Palm	31-40"	Yes	15'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH AVE	Areca Palm	31-40"	Yes	15'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH AVE	Areca Palm	31-40"	Yes	15'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 16TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 16TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 16TH AVE	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 16TH AVE	Areca Palm	31-40"	Yes	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 16TH AVE	Norfolk Pine	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 16TH AVE	Mango	1-5"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Codominant Leaders/Included Bark		
SW 16TH AVE	Royal Poinciana	6-10"	No	Negligible	Dead (0% to 5%)				
SW 16TH AVE	Hibiscus sp.	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 16TH AVE	Hibiscus sp.	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 16TH AVE	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Dead Wood	Codominant Leaders/Included Bark	
SW 16TH AVE	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 16TH AVE	Japanese Privet	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Crown Density - Moderate	Dead Wood	Codominant Leaders/Included Bark
SW 16TH AVE	Weeping Fig	51-60"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 16TH AVE	Bottle Palm	1-5"	No	5'	Very Poor/Critical (6% to	Utility Lines Above	Trunk Damage - Major	Nutrient Deficiency	Damaged Fronds
SW 16TH AVE	Bottle Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency	Frizzled Fronds	
SW 16TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor	Tapered Trunk	
SW 16TH AVE	Areca Palm	31-40"	Yes	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH AVE	Areca Palm	31-40"	Yes	20'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 16TH AVE	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 16TH AVE	Live Oak	41-50"	No	75'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 16TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 16TH AVE	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Over Pruned	Damaged Fronds
SW 16TH AVE	Royal Poinciana	16-20"	No	45'	Good (61% to 80%)		Reduced Canopy - Moderate	Sprouting	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 16th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH AVE	Mahogany	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Lopsided/Moderately Reduced Canopy
SW 16TH AVE	Mahogany	21-30"	No	25'	Poor (21% to 40%)		Trunk Damage - Major	Decay Observed	Dead Wood
SW 16TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 16TH AVE	Avocado	6-10"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Dead Wood	
SW 16TH AVE	Mahogany	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 16TH AVE	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)		Leader - Broken	Sprouting	Dead Wood
SW 16TH AVE	Orange Geiger	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Moderate	Strap Constricting Tree	Dead Wood
SW 16TH AVE	Bottle Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency	Frizzled Fronds	

Avenues | Courts



Looking South - SW 16th Street



Looking South - SW 17th Terrace




Looking North - SW 19th Street



Looking North - Between SW 19th and 20th Street



Looking South - SW 19th Terrace



Looking North - SW 22nd Street (Coral Way)



Looking South - SW 20th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 17th Avenue	2	Shenandoah South	4	70	2700	Yes	No	Yes	5	County	Some	Some	0	Yes	Yes	West side and periodically crossing	Main street. No swales. Periodically planted medians.
SW 17th Court	2	Shenandoah South	4	50	960	No	No	Yes	2	City	Extremely few	Yes	7	No	Yes	West side	Curbless grass and paved swales with linear stormwater channels.

SW 17th Avenue

TYPOLOGY E

SW 17th Court

TYPOLOGY C

Street Tree Inventory

SW 17th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Hong Kong Orchid	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Hong Kong Orchid	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Hong Kong Orchid	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				

SW 17th Court

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH CT	Date Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH CT	Date Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH CT	Gumbo Limbo	16-20"	No	30'	Good (61% to 80%)		Reduced Canopy - Minor	Dead Wood	Codominant Leaders/Included Bark
SW 17TH CT	Gumbo Limbo	16-20"	No	30'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	Codominant Leaders/Included Bark
SW 17TH CT	Mahogany	31-40"	No	70'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 17TH CT	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	
SW 17TH CT	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH CT	Yellow Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	Codominant Leaders/Included Bark
SW 17TH CT	Yellow Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Topped	Sprouting	Codominant Leaders/Included Bark
SW 17TH CT	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Major
SW 17TH CT	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 17TH CT	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 17TH CT	Queen Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 17TH CT	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 17TH CT	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 17TH CT	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 17TH CT	Tropical Almond	16-20"	No	15'	Very Poor/Critical (6% to		Constricted Roots	Topped	Sprouting
SW 17TH CT	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 17TH CT	Areca Palm	41-50"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 17TH CT	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 17TH CT	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 17TH CT	Black Olive	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting


Avenues | Courts



Looking South - SW 16th Street



Looking North - SW 17th Street



Looking South - SW 19th Street



Looking North - SW 19th Terrace



Looking North - SW 20th Street



Looking North -SW 22nd Street (Coral Way)



Looking North - SW 20th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 18th Avenue	2	Shenandoah South	4	50	2700	No	No	Yes	2	City	Some	Yes	7	Some only north of 17th Street	Yes	Periodically crossing	Grass and periodically paved swales. Roundabout at SW 16th Street.
SW 18th Court	2	Shenandoah South	4	50	660	No	No	Yes	2	City	Few	Yes	12	No	Yes	West side	Curbless grass and gravel swales.

SW 18th Avenue

TYPOLOGY B & A

SW 18th Court

TYPOLOGY A

Street Tree Inventory

SW 18th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH AVE	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)		Pruned Into Shrub	Insect Damage Leaves	Dead Wood
SW 18TH AVE	Weeping Fig	1-5"	Yes	5'	Fair (41% to 60%)		Pruned Into Shrub	Insect Damage Leaves	Dead Wood
SW 18TH AVE	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Insect Damage Leaves	Dead Wood
SW 18TH AVE	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Pruned Into Shrub	Insect Damage Leaves	Dead Wood
SW 18TH AVE	Podocarpus	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 18TH AVE	Oriental Arborvitae	16-20"	No	15'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structur		
SW 18TH AVE	Weeping Fig	21-30"	No	25'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 18TH AVE	Weeping Fig	31-40"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 18TH AVE	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Crown Density - Moderate	Dead Wood	Codominant Leaders/Included Bark
SW 18TH AVE	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 18TH AVE	Pink Tabebuia	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 18TH AVE	Buccaneer Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 18TH AVE	Areca Palm	51-60"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 18TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Reduced Canopy - Minor	Dead Wood
SW 18TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Reduced Canopy - Minor	Dead Wood
SW 18TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH AVE	Bamboo Palm	21-30"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 18TH AVE	Red Maple	1-5"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)		Pruned Into Shrub	Insect Damage Leaves	Dead Wood
SW 18TH AVE	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)		Pruned Into Shrub	Insect Damage Leaves	Dead Wood
SW 18TH AVE	Areca Palm	41-50"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Day Blooming Jasmine	11-15"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Moderate	Insect Damage Leaves	Dead Wood
SW 18TH AVE	Weeping Fig	41-50"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Mahogany	1-5"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 18TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 18TH AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)		Crown Density - Moderate		
SW 18TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 18TH AVE	Date Palm	51-60"	Yes	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 18TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 18TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 18TH AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 18TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	1-5"	No	10'	Poor (21% to 40%)		Crown Density - Very Low	Insect Damage Leaves	
SW 18TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	11-15"	No	40'	Good (61% to 80%)	Utility Line Conflict	Dead Wood		

(Continued on Next Page)

Street Tree Inventory

SW 18th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH AVE	Live Oak	6-10"	No	30'	Good (61% to 80%)		Insect Damage Leaves	Dead Wood	
SW 18TH AVE	Live Oak	6-10"	No	30'	Good (61% to 80%)		Insect Damage Leaves	Dead Wood	Trunk Damage - Minor
SW 18TH AVE	Yellow Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 18TH AVE	Yellow Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH AVE	Yellow Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	6-10"	No	30'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	6-10"	No	30'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	Dead Wood
SW 18TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 18TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 18TH AVE	Japanese Privet	1-5"	No	10'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 18TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 18TH AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Green Buttonwood	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Tamarind	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH AVE	Bottlebrush	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 18TH AVE	Bottlebrush	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 18TH AVE	Pygmy Date Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH AVE	Pygmy Date Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH AVE	Pygmy Date Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 18TH AVE	Japanese Privet	1-5"	No	10'	Poor (21% to 40%)		Crown Density - Low	Insect Damage Leaves	Dead Wood
SW 18TH AVE	Live Oak	6-10"	No	30'	Good (61% to 80%)		Dead Wood		
SW 18TH AVE	Frangipani	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 18TH AVE	Royal Poinciana	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 18TH AVE	Bird of Paradise	31-40"	Yes	25'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 18TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Jacaranda	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 18TH AVE	Royal Poinciana	16-20"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 18TH AVE	Peacock Flower	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 18TH AVE	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 18TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 18TH AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Mahogany	41-50"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH AVE	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH AVE	Mahogany	41-50"	No	65'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Minor
SW 18TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 18TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 18TH AVE	Black Olive	31-40"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Suppressed Canopy		
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Suppressed Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 18th Avenue (Countinued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Nutrient Deficiency	
SW 18TH AVE	Royal Poinciana	21-30"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Reduced Canopy - Minor	Dead Wood
SW 18TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 18TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 18TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Nutrient Deficiency	
SW 18TH AVE	Tamarind	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 18TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 18TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 18TH AVE	Mahogany	41-50"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				

SW 18th Court

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH CT	Paradise Tree	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH CT	Weeping Fig	6-10"	No	5'	Fair (41% to 60%)		Basal Co-Dominant	Pruned Into Shrub	
SW 18TH CT	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH CT	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 18TH CT	Vera Wood	1-5"	No	15'	Good (61% to 80%)				
SW 18TH CT	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 18TH CT	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 18TH CT	Royal Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH CT	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH CT	Christmas Palm	16-20"	Yes	20'	Good (61% to 80%)				
SW 18TH CT	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 18TH CT	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 18TH CT	Royal Poinciana	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 18TH CT	Dracaena sp.	21-30"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 18TH CT	Dracaena sp.	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 18TH CT	Royal Poinciana	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		


Avenues | Courts



Looking South - SW 16th Street



Looking South - SW 19th Terrace



Looking South - SW 17th Terrace



Looking South - SW 18th Street



Looking South - SW 21st Terrace



Looking North - SW 22nd Street



Looking South - SW 19th Street



Looking North - SW 19th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 19th Avenue	2	Shenandoah South	4	50	2700	No	No	Yes	2	City	Yes	Yes	10 (intermittent)	Some mostly only on the west side	Yes	East side	Grass and periodically paved swales. Roundabout at SW 17th, 19th, and 21st Street.
SW 20th Avenue	2	Shenandoah South	4	40	220	No	No	Yes	2	City	Few	Yes	6 (west side)	Yes	West side	Periodically crossing	Street becomes one-way going north between SW 18th and 19th Street.

SW 19th Avenue

TYPOLOGY B & D

SW 20th Avenue

TYPOLOGY B & E

Street Tree Inventory

SW 19th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH AVE	Mango	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH AVE	White Frangipani	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Crown Density - Very Low	White Fly	Codominant Leaders - Multi
SW 19TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Suppressed Canopy		
SW 19TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Suppressed Canopy		
SW 19TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH AVE	Black Olive	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 19TH AVE	Black Olive	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 19TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Damaged Fronds	Nutrient Deficiency	
SW 19TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 19TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 19TH AVE	Silver Buttonwood	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major	Strap Constricting Tree	
SW 19TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)		Sprouting		
SW 19TH AVE	Silver Buttonwood	6-10"	No	15'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 19TH AVE	Wild/Cuban Tamarind	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 19TH AVE	Wild/Cuban Tamarind	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 19TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)				
SW 19TH AVE	Green Buttonwood	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 19TH AVE	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 19TH AVE	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Decay Observed	
SW 19TH AVE	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Black Olive	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Banyan	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Codominant Leaders/No Included Bark
SW 19TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 19TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 19TH AVE	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Oriental Arborvitae	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Decay Observed	
SW 19TH AVE	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH AVE	Gumbo Limbo	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Dead Wood	Codominant Leaders/No Included Bark
SW 19TH AVE	Spindle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 19TH AVE	Spindle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 19TH AVE	Queen Palm	1-5"	No	5'	Poor (21% to 40%)		Nutrient Deficiency		
SW 19TH AVE	Queen Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Paradise Tree	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Girdling Roots	Trunk Damage - Minor	Codominant Leaders/Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 19th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH AVE	Paradise Tree	6-10"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Limb Damage - Minor		
SW 19TH AVE	Paradise Tree	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Crown Density - Moderate	Insect Damage Leaves	
SW 19TH AVE	Paradise Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 19TH AVE	Royal Poinciana	41-50"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH AVE	Dahoon Holly	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant	Suppressed Canopy	Sprouting
SW 19TH AVE	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	Codominant Leaders/Included Bark
SW 19TH AVE	Frangipani	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leader - Bent	Restricted Canopy	Codominant Leaders/Included Bark
SW 19TH AVE	Spindle Palm	11-15"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 19TH AVE	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 19TH AVE	Black Olive	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 19TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 19TH AVE	Weeping Fig	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sprouting
SW 19TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 19TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Leaning - Moderate	Discolored Foliage	
SW 19TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Nutrient Deficiency		
SW 19TH AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)		Discolored Foliage		

* Note SW 20th Avenue has no trees

Avenues | Courts



Looking South - SW 16th Street



Looking South - SW 18th Street



Looking South - SW 22nd Street



Looking South - SW 17th Terrace



Looking South - SW 20th Street



Looking North - SW 22nd Street



Looking South - SW 19th Street



Looking North -SW 22nd Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 21st Avenue	2	Shenandoah South	4	50	2700	No	No	Yes	2	City	Yes	Yes	4-7	Yes except b/t SW 16th Street and 16th Terrace	Yes	West side b/t SW 16th Street and SW 17th Lane	Grass and periodically paved swales. Roundabout at SW 16th Street.
SW 22nd Avenue	2	Shenandoah South	4	70	2700	Yes	No	Yes	5	County	Some	Some	0	Yes	Yes	West side and periodically crossing	Semi-main street. No swales. Periodically planted medians.

SW 21st Avenue

TYPOLOGY B & D

SW 22nd Avenue

TYPOLOGY E

Street Tree Inventory

SW 21st Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)		Discolored Foliage		
SW 21ST AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)		Discolored Foliage		
SW 21ST AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 21ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 21ST AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Damaged Fronds		
SW 21ST AVE	Coconut Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 21ST AVE	Gumbo Limbo	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 21ST AVE	Gumbo Limbo	11-15"	No	Negligible	Very Poor/Critical (6% to		Constricted Roots	Topped	Codominant Leaders/No Included Bark
SW 21ST AVE	Coconut Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Coconut Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST AVE	Live Oak	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 21ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy	Tapered Trunk	
SW 21ST AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 21ST AVE	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Minor
SW 21ST AVE	Tamarind	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST AVE	Tamarind	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 21ST AVE	Tamarind	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Minor
SW 21ST AVE	Tamarind	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST AVE	Tamarind	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST AVE	Tamarind	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 21ST AVE	Tamarind	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST AVE	Tamarind	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 21ST AVE	Tamarind	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 21ST AVE	Tamarind	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Suppressed Canopy	Dead Wood
SW 21ST AVE	Tamarind	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Suppressed Canopy	Dead Wood
SW 21ST AVE	Tamarind	11-15"	No	35'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 21ST AVE	Tamarind	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 21ST AVE	Tamarind	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 21ST AVE	Tamarind	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 21ST AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Damaged Fronds		
SW 21ST AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Minor
SW 21ST AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Oriental Arborvitae	11-15"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 21ST AVE	Oriental Arborvitae	11-15"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 21ST AVE	Oriental Arborvitae	11-15"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 21ST AVE	Oriental Arborvitae	11-15"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Arjun Tree	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Reduced Canopy - Minor
SW 21ST AVE	Arjun Tree	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Dead Wood
SW 21ST AVE	Arjun Tree	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Reduced Canopy - Minor
SW 21ST AVE	Arjun Tree	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Reduced Canopy - Minor

(Continued on Next Page)

Street Tree Inventory

SW 21st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST AVE	Arjun Tree	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Dead Wood
SW 21ST AVE	Mahogany	41-50"	No	60'	Poor (21% to 40%)		Constricted Roots	Decay Observed	Codominant Leaders - Multi
SW 21ST AVE	Mahogany	41-50"	No	45'	Poor (21% to 40%)	Utility Lines Adjacent (lateral	Girdling Roots	Decay Observed	Trunk Damage - Major
SW 21ST AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Weeping Fig	41-50"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Restricted Canopy
SW 21ST AVE	Strangler Fig	51-60"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Sprouting
SW 21ST AVE	Live Oak	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Low		
SW 21ST AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 21ST AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				

SW 22nd Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND AVE	Cabbage Palm	11-15"	No	5'	Good (61% to 80%)		Fronds Removed for Installation		
SW 22ND AVE	Cabbage Palm	11-15"	No	5'	Good (61% to 80%)		Fronds Removed for Installation		
SW 22ND AVE	Cabbage Palm	6-10"	No	20'	Good (61% to 80%)				
SW 22ND AVE	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 22ND AVE	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 22ND AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 22ND AVE	Arjun Tree	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 22ND AVE	Arjun Tree	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND AVE	Arjun Tree	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND AVE	Arjun Tree	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND AVE	Arjun Tree	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND AVE	Arjun Tree	41-50"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND AVE	Arjun Tree	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 22ND AVE	Arjun Tree	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND AVE	Arjun Tree	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			

Avenues | Courts



Looking South - SW 16th Street



Looking South - SW 17th Terrace



Looking South - SW 16th Street



Looking North - SW 17th Street



Looking South - SW 19th Ter



Looking North - SW 22nd Street



Looking North - SW 20th Street



Looking North - SW 22nd Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 23rd Avenue	2	Shenandoah South	4	50	2700	No	No	Yes	2	City	Yes	Yes	6	Yes	Yes	West side North of SW 19th Street, east side south of 21st Street	Grass paved and gravel swales. Roundabout at SW 20th Street.
SW 24th Avenue	2	Shenandoah South	4	60	2700	No	No	Yes	2	City	Yes	Yes	4	Yes except b/t 16th Ter and 19th Street on west side	Yes	East side	Grass paved and gravel swales. Roundabout at SW 16th and 18th Street.

SW 23rd Avenue

TYPOLOGY B & A

SW 24th Avenue

TYPOLOGY B & A

Street Tree Inventory

SW 23rd Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD AVE	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Starburst Clerodendron	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Starburst Clerodendron	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Pink Tabebuia	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Insect Damage Leaves
SW 23RD AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Suppressed Canopy	
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Suppressed Canopy	
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD AVE	Royal Poinciana	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Cavities	Dead Wood
SW 23RD AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 23RD AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Hong Kong Orchid	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 23RD AVE	Royal Poinciana	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Limb Damage - Major
SW 23RD AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Bottle Palm	16-20"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 23rd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD AVE	Weeping Fig	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD AVE	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 23RD AVE	Weeping Fig	11-15"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 23RD AVE	Weeping Fig	6-10"	No	Negligible	Dead (0% to 5%)				
SW 23RD AVE	Weeping Fig	16-20"	No	20'	Very Poor/Critical (6% to		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 23RD AVE	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 23RD AVE	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	25'	Fair (41% to 60%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Black Olive	21-30"	No	60'	Fair (41% to 60%)	Utility Lines Adjacent (lateral	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 23RD AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 23RD AVE	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Leader - Bent		
SW 23RD AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD AVE	Weeping Fig	41-50"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD AVE	Sea Grape	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Suppressed Canopy	
SW 23RD AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 23RD AVE	Sapodilla	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Sapodilla	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood		
SW 23RD AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD AVE	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD AVE	Royal Poinciana	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD AVE	Silver Buttonwood	6-10"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 23rd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD AVE	Red Latan Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Chinese Fan Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				
SW 23RD AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 23RD AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 23RD AVE	Black Olive	6-10"	No	15'	Poor (21% to 40%)		Suppressed Canopy	Reduced Canopy - Major	Sprouting
SW 23RD AVE	Black Olive	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting

SW 24th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH AVE	Royal Poinciana	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Crown Density - Very Low	Trunk Damage - Major
SW 24TH AVE	Mahogany	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 24TH AVE	Yellow Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 24TH AVE	Mahogany	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 24TH AVE	Bottlebrush	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 24TH AVE	Bottlebrush	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 24TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 24TH AVE	Christmas Palm	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Minor	Disease	
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 24TH AVE	Queen Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH AVE	Queen Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 24TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH AVE	Queen Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 24TH AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 24TH AVE	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 24TH AVE	Avocado	1-5"	No	10'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH AVE	Avocado	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 24TH AVE	White Frangipani	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Major	Lifting	Dead Wood
SW 24TH AVE	Live Oak	21-30"	No	60'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Sprouting	
SW 24TH AVE	Avocado	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Limb Damage - Major	Restricted Canopy
SW 24TH AVE	Live Oak	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 24TH AVE	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 24TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Mahogany	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots		
SW 24TH AVE	Umbrella Tree	21-30"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	
SW 24TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 24TH AVE	Sapodilla	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Sprouting
SW 24TH AVE	Gumbo Limbo	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 24TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leader - Bent	Dead Wood	
SW 24TH AVE	Mahogany	6-10"	No	20'	Good (61% to 80%)				
SW 24TH AVE	Live Oak	16-20"	No	40'	Good (61% to 80%)		Lopsided/Moderately Reduced Canopy	Sprouting	Dead Wood
SW 24TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Suppressed Canopy	Sprouting	Dead Wood
SW 24TH AVE	Live Oak	6-10"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Topped	Suppressed Canopy	Sprouting
SW 24TH AVE	Live Oak	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Restricted Canopy

(Continued on Next Page)

Street Tree Inventory

SW 24th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH AVE	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Restricted Canopy
SW 24TH AVE	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Suppressed Canopy	Dead Wood
SW 24TH AVE	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Limb Damage - Moderate	Sprouting
SW 24TH AVE	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH AVE	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Restricted Canopy
SW 24TH AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 24TH AVE	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Dead Wood	
SW 24TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)				
SW 24TH AVE	Mahogany	6-10"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Sprouting	
SW 24TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 24TH AVE	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Mahogany	6-10"	No	30'	Good (61% to 80%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy		
SW 24TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots		
SW 24TH AVE	Narrow Leaf Ficus	6-10"	No	10'	Fair (41% to 60%)		Constricted Roots		
SW 24TH AVE	Bougainvillea sp.	6-10"	No	10'	Good (61% to 80%)		Basal Co-Dominant		
SW 24TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 24TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 24TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 24TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 24TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 24TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 24TH AVE	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 24TH AVE	Strangler Fig	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH AVE	Weeping Fig	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 24TH AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Damaged Fronds	
SW 24TH AVE	Weeping Fig	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Weeping Fig	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above	Basal Co-Dominant		
SW 24TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Mahogany	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor	Leader - Bent	
SW 24TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor	Leader - Bent	
SW 24TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			

Avenues | Courts



Looking South - SW 16th Street



Looking South - SW 17th Steet



Looking South - SW 19th Terrace



Looking North - SW 22nd Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 25th Avenue	2	Shenandoah South	4	50	2700	No	No	Yes	2	City	Yes	Yes	5	Yes, not between SW 21st Ter and ally just north of Coral Way	Yes	Periodically crossing over, largely on the west side when running parallel	Grass and some paved swales with on street parking. Roundabout at SW 18th Ave.

SW 25th Avenue

TYPOLOGY B & D

Street Tree Inventory

SW 25th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH AVE	Sapodilla	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 25TH AVE	Spindle Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency	Tapered Trunk	
SW 25TH AVE	Spindle Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH AVE	Spindle Palm	11-15"	No	5'	Dead (0% to 5%)	Utility Lines Above			
SW 25TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 25TH AVE	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Crown Density - Low	Dead Wood	
SW 25TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Starburst Clerodendron	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Weeping Fig	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Unidentified Dead Tree (De	1-5"	No	5'	Dead (0% to 5%)	Utility Lines Above			
SW 25TH AVE	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Areca Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 25TH AVE	Silver Buttonwood	1-5"	No	5'	Poor (21% to 40%)		Lopsided/Moderately Reduced Canopy	Restricted Canopy	
SW 25TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH AVE	Starburst Clerodendron	6-10"	No	10'	Poor (21% to 40%)		Crown Density - Low	Dead Wood	
SW 25TH AVE	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 25TH AVE	Solitaire Palm	16-20"	No	15'	Fair (41% to 60%)		Codominant Leaders/Included Bark		
SW 25TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH AVE	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 25TH AVE	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 25TH AVE	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 25TH AVE	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 25TH AVE	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 25TH AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 25TH AVE	Cabbage Palm	16-20"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Ficus Growing on Tree	
SW 25TH AVE	Strangler Fig	16-20"	No	25'	Fair (41% to 60%)		Basal Co-Dominant with Adjacent Tree(s)	Lopsided/Moderately Reduced Canopy	Constricted Roots
SW 25TH AVE	Sea Grape	31-40"	Yes	40'	Fair (41% to 60%)		Restricted Canopy	Constricted Roots	Multi-Trunk Form - Not Downgraded for Stru
SW 25TH AVE	Mahogany	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 25TH AVE	Mahogany	21-30"	No	45'	Very Poor/Critical (6% to		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 25TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH AVE	Black Olive	16-20"	No	30'	Very Poor/Critical (6% to		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 25TH AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Major	Decay Observed
SW 25TH AVE	Black Olive	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Moderate	Decay Observed
SW 25TH AVE	Solitaire Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH AVE	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH AVE	Solitaire Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH AVE	Bottlebrush	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Leader - Bent	Trunk Damage - Minor	
SW 25TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Leader - Bent	Trunk Damage - Minor	
SW 25TH AVE	Sapodilla	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Trunk Damage - Moderate	
SW 25TH AVE	Sapodilla	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Restricted Canopy
SW 25TH AVE	Sapodilla	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Trunk Damage - Major

(Continued on Next Page)

Street Tree Inventory

SW 25th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH AVE	Queen Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH AVE	Queen Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH AVE	Japanese Golden Rain Tree	21-30"	No	20'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Topped	Sprouting
SW 25TH AVE	Sacred Fig	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 25TH AVE	Sacred Fig	1-5"	No	5'	Good (61% to 80%)				
SW 25TH AVE	Loquat	6-10"	No	15'	Very Poor/Critical (6% to	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 25TH AVE	Loquat	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 25TH AVE	Oriental Arborvitae	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Restricted Canopy
SW 25TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 25TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Christmas Palm	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			

Bordering Streets



Looking South - SW 16th Street



Looking South - SW 17th Terrace



Looking South - SW 16th Street



Looking South - SW 17th Street



Looking South - SW 19th Terrace



Looking North - SW 22nd Street



Looking South - SW 19th Street



Looking North -SW 22nd Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 12th Avenue	2	Shenandoah South	4	80	2700	No	No	Yes	5	State	Some	Some	10	Yes	Yes	west side and periodically crossing	Main street. No swales. Periodically planted medians.
SW 27th Avenue	2	Shenandoah South	4	100	2700	Yes	No	Yes	5	State	Some	Some	4	Yes	Yes	No	Main street. Periodically planted medians and ROW. Parking, planting and reserved space along east and west side of ROW. Grassed swales on both sides.

SW 12th Avenue

TYPOLOGY B

SW 27th Avenue

TYPOLOGY F

Street Tree Inventory

SW 12th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH AVE	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 12TH AVE	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 12TH AVE	Crepe Myrtle	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 12TH AVE	Crepe Myrtle	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 12TH AVE	Crepe Myrtle	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 12TH AVE	Strawberry Guava	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 12TH AVE	Strawberry Guava	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 12TH AVE	Strawberry Guava	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 12TH AVE	Strawberry Guava	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 12TH AVE	Southern Magnolia	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Codominant Leaders/Included Bark	Dead Wood	
SW 12TH AVE	Southern Magnolia	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Crown Density - Moderate	Dead Wood	Codominant Leaders/Included Bark
SW 12TH AVE	Weeping Fig	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Crown Density - Low	Dead Wood	Codominant Leaders/Included Bark
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Codominant Leaders/Included Bark		
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral	Codominant Leaders/Included Bark		
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 12TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Damaged Fronds	
SW 12TH AVE	Mahogany	41-50"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 12TH AVE	Mahogany	41-50"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 25th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 12TH AVE	Weeping Fig	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant	Dead Wood	Sprouting
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 12TH AVE	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 12TH AVE	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 12TH AVE	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 12TH AVE	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Italian Cypress	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (lateral			
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Sprouting	
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Sprouting	
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Leaning - Moderate	Trunk Damage - Minor	Dead Wood
SW 12TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Hong Kong Orchid	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Major	Reduced Canopy - Major	Sprouting
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Codominant Leaders/Included Bark	
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				

SW 27th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 27th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITIES	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH AVE	Cabbage Palm	11-15"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Cabbage Palm	11-15"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Cabbage Palm	6-10"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Cabbage Palm	11-15"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Cabbage Palm	11-15"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Slash Pine	1-5"	No	Negligible	Dead (0% to 5%)				
SW 27TH AVE	Slash Pine	1-5"	No	Negligible	Dead (0% to 5%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	6-10"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Girdling Roots	Codominant Leaders/No Included Bark	Leaning - Minor
SW 27TH AVE	Florida Thatch Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Strap Constricting Tree
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Live Oak	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Leaning - Minor	
SW 27TH AVE	Live Oak	11-15"	No	20'	Poor (21% to 40%)		Basal Co-Dominant	Girdling Roots	
SW 27TH AVE	Desert Cassia	1-5"	No	5'	Good (61% to 80%)		Dead Wood		
SW 27TH AVE	Desert Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 27TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 27TH AVE	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Restricted Canopy
SW 27TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 27TH AVE	Black Olive	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Major
SW 27TH AVE	Black Olive	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sprouting
SW 27TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	



SILVER BLUFF

Streets | Terraces | Lanes



Looking East - SW 27th Avenue



Looking East - SW 22nd Avenue




Looking East - SW 27th Avenue



Looking West - SW 23rd Avenue



Looking East - Between SW 19th and 18th Avenue



Looking West - SW 17th Avenue



Looking East - SW 21st Avenue



Looking West - SW 17th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 22nd Terrace	2	Silver Bluff	4	50	5300	No	No	Yes	2	City	Yes	Yes	7	Yes	Yes	No	Grass swales with curb and paved on-street parking. Speed bump between SW 23rd and 22nd Ave, and SW 22nd and 21st Ave. Roundabout at SW 18th Ave
SW 23rd Street	2	Silver Bluff	4	50	5300	No	No	Yes	3	City	Yes	Yes	7	Yes	Yes	No	Grass swales with curb and paved on-street parking. Speed bump between SW 17th and 18th Ave, and SW 22nd and 21st Ave. Roundabout at SW 25th and 19th Ave

SW 22nd Terrace

TYPOLOGY B

SW 23rd Street

TYPOLOGY B

Street Tree Inventory

SW 22nd Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Gumbo Limbo	11-15"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 22ND TER	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	Basal Co-Dominant
SW 22ND TER	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 22ND TER	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 22ND TER	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 22ND TER	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Suppressed Canopy	
SW 22ND TER	Brazilian Pepper	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	
SW 22ND TER	Weeping Fig	11-15"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	Multi-Trunk Form - Not Downgraded for Structure
SW 22ND TER	Weeping Fig	11-15"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	Multi-Trunk Form - Not Downgraded for Structure
SW 22ND TER	Weeping Fig	11-15"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	Multi-Trunk Form - Not Downgraded for Structure
SW 22ND TER	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	Multi-Trunk Form - Not Downgraded for Structure
SW 22ND TER	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	Multi-Trunk Form - Not Downgraded for Structure
SW 22ND TER	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	Multi-Trunk Form - Not Downgraded for Structure
SW 22ND TER	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	Multi-Trunk Form - Not Downgraded for Structure
SW 22ND TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 22ND TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Areca Palm	16-20"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Areca Palm	16-20"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Pink Tabebuia	11-15"	No	20'	Good (61% to 80%)		Dead Wood	Insect Damage Leaves	
SW 22ND TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Major	Insect Damage Leaves	Dead Wood
SW 22ND TER	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Lifting	Reduced Canopy - Major	Insect Damage Leaves
SW 22ND TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Dead Wood	Trunk Damage - Minor
SW 22ND TER	Pink Tabebuia	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Insect Damage Leaves
SW 22ND TER	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Insect Damage Leaves
SW 22ND TER	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Insect Damage Leaves
SW 22ND TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Insect Damage Leaves
SW 22ND TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Insect Damage Leaves
SW 22ND TER	Pink Tabebuia	1-5"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Lopsided/Moderately Reduced Canopy	Insect Damage Leaves
SW 22ND TER	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 22ND TER	Pink Tabebuia	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Sprouting	Insect Damage Leaves
SW 22ND TER	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Insect Damage Leaves
SW 22ND TER	Pink Tabebuia	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Major	Suppressed Canopy	Insect Damage Leaves
SW 22ND TER	Strangler Fig	51-60"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 22ND TER	Hong Kong Orchid	16-20"	No	25'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Restricted Canopy	Suppressed Canopy

(Continued on Next Page)

Street Tree Inventory

SW 22nd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND TER	Hong Kong Orchid	16-20"	No	25'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Restricted Canopy	Suppressed Canopy
SW 22ND TER	Tropical Almond	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 22ND TER	Tropical Almond	21-30"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Basal Co-Dominant
SW 22ND TER	Tropical Almond	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Leaning - Moderate	Dead Wood
SW 22ND TER	Dracaena sp.	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate	Sprouting	Insect Damage Leaves
SW 22ND TER	Pink Tabebuia	16-20"	No	20'	Fair (41% to 60%)		Trunk Damage - Major	Reduced Canopy - Moderate	Sprouting
SW 22ND TER	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND TER	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Moderate	Insect Damage Leaves	Dead Wood
SW 22ND TER	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 22ND TER	Silver Buttonwood	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Dead Wood	Sprouting
SW 22ND TER	Earleaf Acacia	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Lifting	Reduced Canopy - Major
SW 22ND TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Dracaena sp.	6-10"	Yes	5'	Good (61% to 80%)				
SW 22ND TER	Dracaena sp.	6-10"	Yes	5'	Good (61% to 80%)				
SW 22ND TER	Prickly Pear Cactus	6-10"	Yes	5'	Good (61% to 80%)				
SW 22ND TER	Dracaena sp.	1-5"	Yes	5'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	16-20"	Yes	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 22ND TER	White Frangipani	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 22ND TER	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Restricted Canopy	Sprouting
SW 22ND TER	Dracaena sp.	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Indian Laurel Fig	41-50"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND TER	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Restricted Canopy
SW 22ND TER	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 22ND TER	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 22ND TER	Pink Tabebuia	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	Sprouting
SW 22ND TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Dead Wood	Insect Damage Leaves
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Over Pruned	
SW 22ND TER	Queen Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Frizzled Fronds	
SW 22ND TER	Pink Tabebuia	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Constricted Roots	Crown Density - Very Low	Dead Wood
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 22nd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND TER	Washington Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Washington Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Strangler Fig	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	
SW 22ND TER	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 22ND TER	Sacred Fig	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 22ND TER	Jacaranda	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Suppressed Canopy	
SW 22ND TER	Jacaranda	6-10"	No	10'	Fair (41% to 60%)		Restricted Canopy	Suppressed Canopy	
SW 22ND TER	Croton	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 22ND TER	Sacred Fig	11-15"	No	30'	Good (61% to 80%)				
SW 22ND TER	Sacred Fig	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots		
SW 22ND TER	Yellow Poinciana	1-5"	No	15'	Fair (41% to 60%)		Restricted Canopy	Suppressed Canopy	
SW 22ND TER	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy	Insect Damage Leaves	
SW 22ND TER	Washington Palm	1-5"	No	5'	Good (61% to 80%)		Basal Co-Dominant with Adjacent Tree(s)		
SW 22ND TER	Jacaranda	6-10"	Yes	20'	Fair (41% to 60%)		Reduced Canopy - Major		
SW 22ND TER	Croton	1-5"	Yes	5'	Good (61% to 80%)		Restricted Canopy		
SW 22ND TER	Dracaena sp.	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 22ND TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Sandbox Tree	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Strangler Fig	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Crown Density - Moderate	Dead Wood	Insect Damage Leaves
SW 22ND TER	Peregrina	6-10"	Yes	10'	Good (61% to 80%)		Dead Wood		
SW 22ND TER	Mahogany	1-5"	Yes	10'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 22ND TER	Weeping Fig	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 22ND TER	Weeping Fig	1-5"	No	10'	Good (61% to 80%)		Crown Density - Moderate	Dead Wood	
SW 22ND TER	Spindle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Bottlebrush	11-15"	No	10'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 22ND TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 22ND TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 22ND TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Umbrella Tree	21-30"	No	15'	Poor (21% to 40%)		Constricted Roots	Topped	Trunk Damage - Major
SW 22ND TER	Umbrella Tree	21-30"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 22ND TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 22ND TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	6-10"	Yes	Negligible	Dead (0% to 5%)				
SW 22ND TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 22nd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 22ND TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 22ND TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 22ND TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	Restricted Canopy
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 22ND TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 22ND TER	Royal Poinciana	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND TER	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND TER	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND TER	Yellow Poinciana	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND TER	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Bamboo Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 22ND TER	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Areca Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND TER	Weeping Fig	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 22ND TER	Weeping Fig	6-10"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 22ND TER	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Pink Tabebuia	21-30"	No	20'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 22ND TER	Starburst Clerodendron	16-20"	Yes	15'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure	Dead Wood	
SW 22ND TER	Rubber Tree	60+"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 22ND TER	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 22ND TER	Royal Poinciana	11-15"	No	40'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 22ND TER	Weeping Fig	31-40"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 22ND TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Sprouting	Codominant Leaders/Included Bark
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 22nd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 22ND TER	Orange Geiger	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Suppressed Canopy	Dead Wood
SW 22ND TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Spanish Lime	6-10"	No	25'	Fair (41% to 60%)		Basal Co-Dominant	Dead Wood	Insect Damage Leaves
SW 22ND TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 22ND TER	Horseradish Tree	1-5"	No	20'	Good (61% to 80%)				
SW 22ND TER	Horseradish Tree	1-5"	No	15'	Good (61% to 80%)				
SW 22ND TER	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 22ND TER	Royal Poinciana	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Major	Cavities
SW 22ND TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 22ND TER	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 22ND TER	Sabal sp.	16-20"	No	20'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 22ND TER	Spindle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Royal Poinciana	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 22ND TER	Royal Poinciana	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 22ND TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Royal Poinciana	1-5"	No	5'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 22ND TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 22ND TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 22ND TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 22ND TER	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Stubs with Sprouts		
SW 22ND TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Cavities
SW 22ND TER	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Gumbo Limbo	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 22ND TER	Royal Poinciana	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots		
SW 22ND TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Starburst Clerodendron	11-15"	Yes	10'	Good (61% to 80%)				
SW 22ND TER	Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Starburst Clerodendron	6-10"	Yes	10'	Good (61% to 80%)				
SW 22ND TER	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Minor
SW 22ND TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 22ND TER	Live Oak	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 22nd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND TER	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 22ND TER	Weeping Fig	11-15"	No	20'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Chinese Fan Palm	6-10"	No	20'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Moderate	White Fly
SW 22ND TER	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 22ND TER	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 22ND TER	Vera Wood	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 22ND TER	Golden Shower Tree	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 22ND TER	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Lopsided/Moderately Reduced Canopy
SW 22ND TER	Banyan	51-60"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 22ND TER	Hong Kong Orchid	21-30"	No	35'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	Sprouting
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Black Olive	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 22ND TER	Live Oak	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 22ND TER	Royal Poinciana	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Black Olive	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND TER	Black Olive	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 22ND TER	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 22ND TER	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 22ND TER	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 22ND TER	Black Olive	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Suppressed Canopy	Reduced Canopy - Moderate	Stubs with Sprouts
SW 22ND TER	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 22ND TER	Black Olive	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 22ND TER	Live Oak	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Significantly Reduced Canopy	Girdling Roots	Sprouting
SW 22ND TER	Crepe Myrtle	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 22ND TER	Brazilian Beauty Leaf	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	
SW 22ND TER	Weeping Fig	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lifting	Dead Wood
SW 22ND TER	Weeping Fig	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 22ND TER	Yellow Tabebuia	11-15"	No	25'	Good (61% to 80%)				
SW 22ND TER	Yellow Tabebuia	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 22ND TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	
SW 22ND TER	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 22nd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND TER	Areca Palm	31-40"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 22ND TER	Areca Palm	21-30"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 22ND TER	Areca Palm	21-30"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 22ND TER	Brazilian Pepper	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 22ND TER	Brazilian Pepper	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 22ND TER	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Stubs with Sprouts
SW 22ND TER	Royal Poinciana	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 22ND TER	Jacaranda	16-20"	No	25'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	Decay Observed
SW 22ND TER	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Live Oak	16-20"	No	40'	Poor (21% to 40%)		Basal Co-Dominant	Constricted Roots	
SW 22ND TER	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 22ND TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 22ND TER	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 22ND TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 22ND TER	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 22ND TER	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 22ND TER	Desert Cassia	6-10"	Yes	15'	Good (61% to 80%)				
SW 22ND TER	Desert Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 22ND TER	Foxtail Palm	11-15"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 22ND TER	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 22ND TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		

Street Tree Inventory

SW 23rd Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD ST	Silver Buttonwood	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 23RD ST	Silver Buttonwood	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 23RD ST	Pink Tabebuia	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Insect Damage Leaves	
SW 23RD ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)		Basal Co-Dominant	Dead Wood	
SW 23RD ST	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Reduced Canopy - Minor
SW 23RD ST	Java Bishopwood	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant	Trunk Damage - Moderate
SW 23RD ST	Java Bishopwood	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 23RD ST	Java Bishopwood	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 23RD ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 23RD ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 23RD ST	Brazilian Beauty Leaf	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	
SW 23RD ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Canary Island Date Palm	21-30"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Lopsided/Moderately Reduced Canopy
SW 23RD ST	Gumbo Limbo	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD ST	Gumbo Limbo	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Gumbo Limbo	31-40"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 23RD ST	Pink Tabebuia	11-15"	No	25'	Good (61% to 80%)		Dead Wood	Insect Damage Leaves	
SW 23RD ST	Mahogany	6-10"	No	25'	Good (61% to 80%)		Dead Wood		
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	Trunk Damage - Minor
SW 23RD ST	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Trunk Damage - Moderate
SW 23RD ST	Mahogany	41-50"	No	35'	Poor (21% to 40%)		Constricted Roots	Topped	Trunk Damage - Major
SW 23RD ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots		
SW 23RD ST	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 23RD ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Minor	Dead Wood
SW 23RD ST	Pink Tabebuia	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 23RD ST	Desert Cassia	1-5"	No	10'	Fair (41% to 60%)		Crown Density - Low	Dead Wood	Insect Damage Leaves
SW 23RD ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 23RD ST	Live Oak	41-50"	No	60'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 23RD ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Vera Wood	11-15"	No	30'	Good (61% to 80%)		Dead Wood		
SW 23RD ST	Vera Wood	11-15"	No	30'	Good (61% to 80%)		Dead Wood		
SW 23RD ST	Weeping Fig	11-15"	No	20'	Good (61% to 80%)		Restricted Canopy	Dead Wood	Multi-Trunk Form - Not Downgraded for Structure
SW 23RD ST	Weeping Fig	16-20"	No	30'	Good (61% to 80%)		Dead Wood	Multi-Trunk Form - Not Downgraded for Structure	
SW 23RD ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Dead Wood	Insect Damage Leaves	
SW 23RD ST	Weeping Fig	41-50"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 23RD ST	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)				
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		

Street Tree Inventory

SW 23rd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Weeping Fig	11-15"	Yes	10'	Poor (21% to 40%)		Constricted Roots	Topped	
SW 23RD ST	Weeping Fig	21-30"	No	10'	Poor (21% to 40%)		Constricted Roots	Topped	Trunk Damage - Major
SW 23RD ST	Weeping Fig	21-30"	No	10'	Poor (21% to 40%)		Constricted Roots	Topped	Trunk Damage - Major
SW 23RD ST	Cycad	6-10"	No	5'	Good (61% to 80%)				
SW 23RD ST	Green Buttonwood	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD ST	Montgomery Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Montgomery Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Montgomery Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Montgomery Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Montgomery Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Dead Wood	Sprouting
SW 23RD ST	Live Oak	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Mahogany	51-60"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Mahogany	41-50"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD ST	Black Olive	16-20"	No	25'	Poor (21% to 40%)		Girdling Roots	Trunk Damage - Major	Restricted Canopy
SW 23RD ST	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 23RD ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Lifting	Dead Wood
SW 23RD ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Mahogany	41-50"	No	55'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood		
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 23RD ST	Live Oak	1-5"	No	15'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 23RD ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 23RD ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 23RD ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Lifting	Reduced Canopy - Major
SW 23RD ST	Mahogany	41-50"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Fishtail Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 23RD ST	Peregrina	6-10"	No	10'	Fair (41% to 60%)		Girdling Roots	Dead Wood	Multi-Trunk Form - Not Downgraded for Structure
SW 23RD ST	Cassia sp.	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 23RD ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Restricted Canopy	
SW 23RD ST	Neem Tree	1-5"	Yes	5'	Good (61% to 80%)				
SW 23RD ST	Neem Tree	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Brazilian Pepper	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 23rd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD ST	Brazilian Pepper	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Brazilian Pepper	1-5"	Yes	5'	Good (61% to 80%)				
SW 23RD ST	Brazilian Pepper	1-5"	Yes	5'	Good (61% to 80%)				
SW 23RD ST	Glaucous Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Glaucous Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Sapodilla	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 23RD ST	Sapodilla	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 23RD ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Royal Poinciana	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD ST	Japanese Privet	16-20"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub	Dead Wood	
SW 23RD ST	Green Buttonwood	41-50"	No	45'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 23RD ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark
SW 23RD ST	Royal Poinciana	21-30"	No	50'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 23RD ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 23RD ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 23RD ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy		
SW 23RD ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 23RD ST	Green Buttonwood	6-10"	No	20'	Fair (41% to 60%)		Leader - Broken	Sprouting	
SW 23RD ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 23RD ST	Green Buttonwood	6-10"	No	20'	Fair (41% to 60%)		Leader - Broken	Sprouting	
SW 23RD ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Grafted Branches
SW 23RD ST	Wild/Cuban Tamarind	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Leader - Broken
SW 23RD ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	
SW 23RD ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD ST	Bottle Palm	6-10"	No	5'	Fair (41% to 60%)		Over Pruned		
SW 23RD ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 23RD ST	Pink Tabebuia	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 23RD ST	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	
SW 23RD ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Yellow Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Topped	Sprouting	
SW 23RD ST	Yellow Tabebuia	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD ST	Yellow Tabebuia	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD ST	Yellow Tabebuia	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 23RD ST	Yellow Tabebuia	11-15"	No	20'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 23rd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD ST	Yellow Tabebuia	11-15"	No	25'	Fair (41% to 60%)		Topped	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Yellow Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Sprouting	
SW 23RD ST	Gumbo Limbo	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 23RD ST	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Frangipani	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Canary Island Date Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Canary Island Date Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Canary Island Date Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Prickly Pear Cactus	6-10"	Yes	5'	Good (61% to 80%)				
SW 23RD ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	
SW 23RD ST	Gumbo Limbo	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots		
SW 23RD ST	Sapodilla	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Neem Tree	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Suppressed Canopy
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Tamarind	11-15"	No	25'	Good (61% to 80%)				
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 23RD ST	Queen Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 23RD ST	Royal Poinciana	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Cracks in Trunk
SW 23RD ST	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Trunk Damage - Moderate	Decay Observed	Constricted Roots
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 23RD ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Royal Poinciana	11-15"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Sprouting	Dead Wood
SW 23RD ST	Guiana Chestnut	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Nutrient Deficiency	
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Nutrient Deficiency	
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy	Nutrient Deficiency	
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 23rd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Frangipani	1-5"	Yes	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Discolored Foliage	
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 23RD ST	Fiddle Leaf Fig	11-15"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Dracaena sp.	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Mahogany	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 23RD ST	Mahogany	1-5"	No	15'	Fair (41% to 60%)		Topped	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Queen Palm	11-15"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major		
SW 23RD ST	Mahogany	1-5"	No	10'	Fair (41% to 60%)		Topped	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Topped	Reduced Canopy - Moderate	Sprouting
SW 23RD ST	Mahogany	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 23RD ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 23RD ST	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 23RD ST	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 23RD ST	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 23RD ST	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 23RD ST	Royal Poinciana	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 23RD ST	Mahogany	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 23RD ST	Gumbo Limbo	1-5"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 23RD ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 23RD ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 23RD ST	Royal Poinciana	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 23RD ST	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Yellow Poinciana	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 23RD ST	Weeping Fig	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 23RD ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	White Fly	
SW 23RD ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 23RD ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Pygmy Date Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Pygmy Date Palm	6-10"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Over Pruned		
SW 23RD ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD ST	Mahogany	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	
SW 23RD ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 23rd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD ST	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 23RD ST	Cabbage Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD ST	Cabbage Palm	16-20"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 23RD ST	Mahogany	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 23RD ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 23RD ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Ficus Growing on Tree
SW 23RD ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 23RD ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 23RD ST	Oriental Arborvitae	16-20"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD ST	Frangipani	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Fungus on Leaves		
SW 23RD ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Leaning - Moderate	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Tapered Trunk		
SW 23RD ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 23RD ST	Live Oak	6-10"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark		
SW 23RD ST	Yellow Poinciana	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots		
SW 23RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 23RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 23RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Loquat	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Dead Wood
SW 23RD ST	Japanese Fern Tree	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Queen Crepe Myrtle	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Codominant Leaders/Included Bark	
SW 23RD ST	Royal Poinciana	1-5"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 23RD ST	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)				
SW 23RD ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 23RD ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 23RD ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 23RD ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 23rd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD ST	Mahogany	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 23RD ST	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 23RD ST	Royal Poinciana	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 23RD ST	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 23RD ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)				
SW 23RD ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 23RD ST	Green Buttonwood	31-40"	No	45'	Poor (21% to 40%)		Basal Co-Dominant	Constricted Roots	Trunk Damage - Major
SW 23RD ST	Bottlebrush	21-30"	No	20'	Very Poor/Critical (6% to 20%)		Basal Co-Dominant	Trunk Damage - Major	Decay Observed
SW 23RD ST	Bottlebrush	6-10"	No	10'	Poor (21% to 40%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 23RD ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 23RD ST	Frangipani	1-5"	No	10'	Good (61% to 80%)				
SW 23RD ST	Tamarind	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting

Streets | Terraces | Lanes



Looking West - SW 25th Avenue



Looking East - SW 24th Avenue



Looking East - SW 27th Avenue



Looking West - SW 24th Avenue



Looking East - SW 22nd Avenue



Looking West - SW 17th Avenue



Looking East - SW 19th Avenue



Looking West - SW 17th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 23rd Terrace	2	Silver Bluff	4	50	4800	No	No	Yes	2	City	Yes	Yes	7	Yes	Yes	South side	Grass swales with curb and paved on-street parking. No Curb west of SW 25th Ave. Speed bump between SW 23rd and 22nd Ave.
SW 24th Street	2	Silver Bluff	4	60-50	5300	No	No	Yes	3	City	Yes	Yes	7	Yes	Yes	Crossing SW 25th Ave and SW 22nd Ave, south side east of SW 22nd Ave.	Grass swales with curb and paved on-street parking. Speed bump between SW 22nd and 21st Ave. Round-about at SW 19th Ave. ROW width reduces east of SW 22nd Ave

SW 23rd Terrace
TYPOLOGY B

SW 24th Street
TYPOLOGY B

Street Tree Inventory

SW 23rd Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Chinese Fan Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Chinese Fan Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Pitch Apple	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Pitch Apple	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Pitch Apple	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Pitch Apple	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Pitch Apple	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Pencil Top	
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy	Restricted Canopy	
SW 23RD TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 23RD TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 23rd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Bougainvillea	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Peregrina	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 23RD TER	Yellow Tabebuia	6-10"	No	15'	Good (61% to 80%)		Dead Wood		
SW 23RD TER	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Strangler Fig	60+"	No	45'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Trunk Damage - Moderate
SW 23RD TER	Washington Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Strangler Fig	6-10"	Yes	5'	Good (61% to 80%)				
SW 23RD TER	Green Buttonwood	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 23RD TER	Silk Floss Tree	6-10"	No	10'	Good (61% to 80%)		Dead Wood	Basal Co-Dominant	Crown Density - Moderate
SW 23RD TER	Weeping Fig	6-10"	No	25'	Good (61% to 80%)		Dead Wood		
SW 23RD TER	Queen Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Mahogany	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 23RD TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Radermachera yunnanensis	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Radermachera yunnanensis	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Radermachera yunnanensis	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Radermachera yunnanensis	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Radermachera yunnanensis	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Radermachera yunnanensis	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Radermachera yunnanensis	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Radermachera yunnanensis	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Radermachera yunnanensis	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Radermachera yunnanensis	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Bottle Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Insect Damage Leaves	
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Mahogany	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 23RD TER	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 23RD TER	Weeping Fig	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD TER	Mahogany	41-50"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD TER	Sapodilla	21-30"	No	25'	Poor (21% to 40%)		Girdling Roots	Basal Co-Dominant	Sprouting
SW 23RD TER	Umbrella Tree	16-20"	No	15'	Fair (41% to 60%)		Constricted Roots	Multi-Trunk Form - Not Downgraded for Structure	Sprouting
SW 23RD TER	Black Olive	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 23rd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD TER	Black Olive	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 23RD TER	Live Oak	21-30"	No	40'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 23RD TER	Weeping Fig	51-60"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD TER	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Washington Palm	11-15"	Yes	5'	Good (61% to 80%)				
SW 23RD TER	Washington Palm	11-15"	Yes	5'	Good (61% to 80%)				
SW 23RD TER	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)				
SW 23RD TER	Dracaena sp.	11-15"	Yes	10'	Good (61% to 80%)				
SW 23RD TER	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Bottle Palm	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Insect Damage Leaves	Nutrient Deficiency
SW 23RD TER	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Major	Nutrient Deficiency	
SW 23RD TER	Carribean Silk Tree	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Sprouting
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Chinese Fan Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 23RD TER	Green Buttonwood	41-50"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 23RD TER	Red Cassia	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD TER	Coconut Palm	11-15"	Yes	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 23RD TER	Coconut Palm	11-15"	Yes	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Neem Tree	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD TER	Golden Shower Tree	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 23RD TER	Carribean Silk Tree	41-50"	No	65'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD TER	Carribean Silk Tree	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD TER	Simpson's Stopper	11-15"	No	15'	Fair (41% to 60%)		Crown Density - Moderate	Dead Wood	Multi-Trunk Form - Not Downgraded for Structure

(Continued on Next Page)

Street Tree Inventory

SW 23rd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Spindle Palm	6-10"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Tapered Trunk	
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	White Fly	
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 23RD TER	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Live Oak	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 23RD TER	Live Oak	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Cabbage Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Decay Observed
SW 23RD TER	Paradise Tree	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Codominant Leaders/Included Bark
SW 23RD TER	Rubber Tree	21-30"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 23RD TER	Green Buttonwood	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 23RD TER	Black Olive	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 23RD TER	Weeping Fig	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 23RD TER	Royal Poinciana	31-40"	No	55'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Reduced Canopy - Major
SW 23RD TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD TER	BV UNID 1	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 23RD TER	Pencil Tree	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Live Oak	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 23RD TER	Starburst Clerodendron	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Japanese Privet	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Sapodilla	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Ficus Growing on Tree
SW 23RD TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	False Mastic	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Bougainvillea sp.	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots		
SW 23RD TER	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Restricted Canopy	Codominant Leaders/No Included Bark	

(Continued on Next Page)

Street Tree Inventory

SW 23rd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 23RD TER	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	
SW 23RD TER	Golden Shower Tree	11-15"	No	40'	Fair (41% to 60%)		Lateral Branching - None	Limb Damage - Moderate	Sprouting
SW 23RD TER	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 23RD TER	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Black Olive	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Nutrient Deficiency	
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Areca Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Green Buttonwood	41-50"	No	40'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Dead Wood
SW 23RD TER	Royal Poinciana	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Washington Palm	6-10"	No	15'	Good (61% to 80%)				
SW 23RD TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 23RD TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 23RD TER	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 23RD TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Weeping Fig	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Significantly Reduced Canopy	Dead Wood	
SW 23RD TER	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Sprouting	
SW 23RD TER	Royal Poinciana	41-50"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	
SW 23RD TER	Coconut Palm	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD TER	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Chinese Fan Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Chinese Fan Palm	16-20"	Yes	20'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Chinese Fan Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Chinese Fan Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Chinese Fan Palm	6-10"	No	5'	Fair (41% to 60%)	Utility Lines Above	Over Pruned		
SW 23RD TER	Pink Tabebuia	11-15"	No	15'	Poor (21% to 40%)		Basal Co-Dominant with Adjacent Tree(s)	Lopsided/Moderately Reduced Canopy	
SW 23RD TER	Live Oak	6-10"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant with Adjacent Tree(s)	Lopsided/Moderately Reduced Canopy	
SW 23RD TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 23rd Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Suppressed Canopy	
SW 23RD TER	Live Oak	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Over Pruned		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 23RD TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 23RD TER	Bottlebrush	6-10"	No	10'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Recumbent	Trunk Damage - Major	
SW 23RD TER	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 23RD TER	Mahogany	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Basal Co-Dominant with Adjacent Tree(s)
SW 23RD TER	Strangler Fig	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 23RD TER	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Minor
SW 23RD TER	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 23RD TER	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	
SW 23RD TER	Mahogany	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 23RD TER	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Stubs with Sprouts
SW 23RD TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 23RD TER	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Suppressed Canopy	Codominant Leaders/No Included Bark
SW 23RD TER	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	
SW 23RD TER	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 23RD TER	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Coconut Palm	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD TER	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Crepe Myrtle	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Apical Dieback		
SW 23RD TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Weeping Fig	21-30"	No	15'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Crown Density - Very Low	Decay Observed
SW 23RD TER	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 23RD TER	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood

Street Tree Inventory

SW 24th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Live Oak	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 24TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)				
SW 24TH ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	
SW 24TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting	Dead Wood	
SW 24TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH ST	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Trunk Damage - Minor	Dead Wood	
SW 24TH ST	Sugarberry	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Reduced Canopy - Major	Sprouting
SW 24TH ST	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Dead Wood	Sprouting	
SW 24TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Gumbo Limbo	16-20"	No	35'	Good (61% to 80%)		Dead Wood		
SW 24TH ST	Japanese Privet	1-5"	Yes	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH ST	Oriental Arborvitae	21-30"	No	20'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure	Dead Wood	
SW 24TH ST	Oriental Arborvitae	21-30"	No	20'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure	Dead Wood	
SW 24TH ST	Gumbo Limbo	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH ST	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Topped		
SW 24TH ST	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Topped		
SW 24TH ST	Golden Rain Tree	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH ST	Christmas Palm	16-20"	No	15'	Good (61% to 80%)				
SW 24TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Longan	6-10"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 24TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Longan	6-10"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 24TH ST	Starfruit	6-10"	No	10'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 24TH ST	Golden Rain Tree	11-15"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Dead Wood	Sprouting
SW 24TH ST	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Dead Wood		
SW 24TH ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Insect Damage Leaves	
SW 24TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 24TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 24TH ST	Black Olive	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 24TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 24TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 24TH ST	Canary Island Date Palm	31-40"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Canary Island Date Palm	31-40"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Queen Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Areca Palm	21-30"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Bird of Paradise	21-30"	Yes	10'	Good (61% to 80%)				
SW 24TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 24TH ST	Japanese Blueberry	6-10"	No	15'	Good (61% to 80%)		Sprouting		
SW 24TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Sprouting		

(Continued on Next Page)

Street Tree Inventory

SW 24th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Girdling Roots	Sprouting	
SW 24TH ST	Live Oak	11-15"	No	30'	Good (61% to 80%)		Lopsided/Moderately Reduced Canopy	Dead Wood	
SW 24TH ST	Vera Wood	1-5"	No	10'	Poor (21% to 40%)		Crown Density - Low	Dead Wood	
SW 24TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 24TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 24TH ST	Starburst Clerodendron	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Sprouting	
SW 24TH ST	Yellow Poinciana	6-10"	No	25'	Good (61% to 80%)		Dead Wood		
SW 24TH ST	Yellow Poinciana	1-5"	No	20'	Good (61% to 80%)		Dead Wood		
SW 24TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 24TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Tapered Trunk		
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Solitaire Palm	6-10"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency	Restricted Canopy	Suppressed Canopy
SW 24TH ST	Bottle Palm	16-20"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Bottle Palm	16-20"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Christmas Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 24TH ST	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH ST	Norfolk Pine	16-20"	No	15'	Fair (41% to 60%)		Constricted Roots		
SW 24TH ST	Bottlebrush	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 24TH ST	Bottlebrush	21-30"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH ST	Croton	6-10"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 24TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 24th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH ST	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH ST	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH ST	Ackee Tree	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH ST	Ackee Tree	11-15"	No	20'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 24TH ST	Bottlebrush	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 24TH ST	Bottlebrush	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Major	Dead Wood	Sprouting
SW 24TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Live Oak	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH ST	Orange Geiger	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Norfolk Pine	31-40"	No	20'	Fair (41% to 60%)		Constricted Roots	Multi-Trunk Form - Not Downgraded for Structure	
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Sugar Apple	1-5"	No	15'	Good (61% to 80%)		Limb Damage - Minor	Dead Wood	
SW 24TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 24TH ST	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)		Reduced Canopy - Moderate	Dead Wood	Sprouting
SW 24TH ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 24TH ST	Live Oak	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Bismark Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Bismark Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Foxtail Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Foxtail Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Foxtail Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	1-5"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Queen Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 24TH ST	Queen Palm	6-10"	No	15'	Poor (21% to 40%)		Nutrient Deficiency	Frizzled Fronds	
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 24th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Black Olive	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH ST	Weeping Fig	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Major	Sprouting	Dead Wood
SW 24TH ST	Weeping Fig	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 24TH ST	Gumbo Limbo	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 24TH ST	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Girdling Roots	Restricted Canopy	Dead Wood
SW 24TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH ST	Jacaranda	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 24TH ST	Bougainvillea sp.	11-15"	No	20'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH ST	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Suppressed Canopy	
SW 24TH ST	Starburst Clerodendron	1-5"	No	15'	Good (61% to 80%)		Sprouting	Dead Wood	
SW 24TH ST	Royal Poinciana	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 24TH ST	Bottlebrush	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Sprouting
SW 24TH ST	Black Ironwood	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Trunk Damage - Major	Sprouting	
SW 24TH ST	Gumbo Limbo	1-5"	No	15'	Fair (41% to 60%)		Crown Density - Low		
SW 24TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Paradise Tree	1-5"	No	10'	Good (61% to 80%)				
SW 24TH ST	Paradise Tree	1-5"	No	10'	Good (61% to 80%)				
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Paradise Tree	1-5"	No	10'	Good (61% to 80%)				
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Norfolk Pine	11-15"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Over Extended Limb(s)	Trunk Damage - Moderate
SW 24TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 24TH ST	Japanese Blueberry	1-5"	No	5'	Fair (41% to 60%)		Basal Co-Dominant		
SW 24TH ST	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Suppressed Canopy		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH ST	Areca Palm	31-40"	Yes	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 24TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Christmas Palm	1-5"	No	5'	Poor (21% to 40%)		Tapered Trunk	Nutrient Deficiency	
SW 24TH ST	Canary Island Date Palm	21-30"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Ficus Growing on Tree	
SW 24TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Paradise Tree	1-5"	No	10'	Good (61% to 80%)				
SW 24TH ST	Solitaire Palm	1-5"	No		Very Poor/Critical (6% to 20%)		Reduced Canopy - Major		
SW 24TH ST	Powderpuff Tree	1-5"	No	15'	Good (61% to 80%)				
SW 24TH ST	Sapodilla	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	
SW 24TH ST	Queen Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Suppressed Canopy	
SW 24TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH ST	Canary Island Date Palm	21-30"	No	10'	Good (61% to 80%)				
SW 24TH ST	Peregrina	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 24th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Bottle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Royal Poinciana	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	
SW 24TH ST	Paradise Tree	1-5"	No	10'	Good (61% to 80%)				
SW 24TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 24TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Apical Dieback
SW 24TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 24TH ST	Pink Tabebuia	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 24TH ST	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH ST	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH ST	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH ST	Pink Tabebuia	6-10"	No	5'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 24TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 24TH ST	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Gumbo Limbo	6-10"	No	25'	Fair (41% to 60%)		Crown Density - Moderate	Codominant Leaders/Included Bark	
SW 24TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Gumbo Limbo	6-10"	No	25'	Fair (41% to 60%)		Crown Density - Moderate	Codominant Leaders/Included Bark	
SW 24TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 24TH ST	Oleander	6-10"	Yes	15'	Good (61% to 80%)				
SW 24TH ST	Montgomery Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 24TH ST	Montgomery Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 24TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 24TH ST	Montgomery Palm	6-10"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 24TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH ST	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 24TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 24TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH ST	Black Olive	21-30"	No	20'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 24TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)				
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 24th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 24TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 24TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH ST	Crepe Myrtle	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy		
SW 24TH ST	Pitch Apple	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	
SW 24TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH ST	Mahogany	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 24TH ST	Live Oak	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Crown Density - Very Low		
SW 24TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Live Oak	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Moderate	Codominant Leaders/Included Bark	
SW 24TH ST	Live Oak	16-20"	No	40'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Codominant Leaders/Included Bark	Leaning - Moderate
SW 24TH ST	Christmas Palm	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	16-20"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Mahogany	31-40"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 24TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Neem Tree	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 24TH ST	Bottlebrush	1-5"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Crown Density - Very Low	
SW 24TH ST	Ponytail Palm	11-15"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Paradise Tree	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lifting	Codominant Leaders/No Included Bark
SW 24TH ST	Weeping Fig	6-10"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Decay Observed
SW 24TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Black Olive	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH ST	Black Olive	31-40"	No	45'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 24TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH ST	Weeping Fig	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH ST	Weeping Fig	6-10"	No	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Topped	Reduced Canopy - Major	Dead Wood
SW 24TH ST	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH ST	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk	Codominant Leaders/No Included Bark	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 24th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH ST	Japanese Privet	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Japanese Privet	1-5"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Moderate		
SW 24TH ST	Japanese Privet	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Sprouting
SW 24TH ST	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH ST	Brazilian Beauty Leaf	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH ST	Japanese Privet	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Japanese Privet	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Japanese Privet	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Peregrina	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH ST	Umbrella Tree	31-40"	Yes	10'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 24TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	

Streets | Terraces | Lanes



Looking East - SW 27th Avenue



Looking East - SW 25th Avenue



Looking East - SW 27th Avenue



Looking East - SW 23rd Avenue



Looking East - SW 21st Avenue



Looking West - SW 17th Avenue



Looking West - SW 21st Avenue



Looking East - SW 19th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 24th Terrace	2	Silver Bluff	4	60-50	5300	No	No	Yes	2	City	Yes	Yes	7	Yes	Yes	Crossing between SW 27th and 26th Ave, at SW 22nd Ave, North/south side between 22nd and 21st Ave, south side east of 21st Ave	Grass swales with curb and paved on-street parking. Speed bump between SW 25th and 24th Ave, and SW 24th and 23rd Ave and 21st and 19th Ave. Roundabout at SW 25th, 23rd, 21st and 18th Ave. ROW width reduces east of SW 22nd Ave
SW 25th Street	2	Silver Bluff	4	60-50	5300	No	No	Yes	2	City	Yes	Yes	7	Yes	Yes	Crossing SW 25th Ave and SW 22nd Ave, south side east of SW 22nd Ave.	Grass swales with curb and paved on-street parking. Speed bump between SW 22nd and 21st Ave. Roundabout at SW 19th Ave. ROW width reduces east of SW 22nd Ave

SW 24th Terrace

TYPOLOGY B/A

SW 25th Street

TYPOLOGY B/A

Street Tree Inventory

SW 24th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH TER	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 24TH TER	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 24TH TER	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 24TH TER	Weeping Fig	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH TER	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Weeping Fig	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 24TH TER	Weeping Fig	41-50"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH TER	Hong Kong Orchid	6-10"	No	20'	Poor (21% to 40%)		Ficus Growing on Tree	Reduced Canopy - Major	Sprouting
SW 24TH TER	Rainbow Eucalyptus	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH TER	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH TER	Orange Geiger	1-5"	No	15'	Fair (41% to 60%)		Girdling Roots	Crown Density - Moderate	Insect Damage Leaves
SW 24TH TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Dead Wood		
SW 24TH TER	Gumbo Limbo	11-15"	No	30'	Good (61% to 80%)		Dead Wood		
SW 24TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH TER	Areca Palm	6-10"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH TER	Areca Palm	16-20"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH TER	Gumbo Limbo	6-10"	No	25'	Good (61% to 80%)		Dead Wood		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Mango	1-5"	No	10'	Good (61% to 80%)				
SW 24TH TER	Peregrina	11-15"	Yes	15'	Good (61% to 80%)		Dead Wood		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	White Frangipani	6-10"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Oriental Arborvitae	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH TER	Oriental Arborvitae	16-20"	No	15'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH TER	Oriental Arborvitae	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH TER	Mahogany	41-50"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 24TH TER	Mahogany	41-50"	No	45'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 24TH TER	Mahogany	31-40"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 24TH TER	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH TER	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH TER	Coconut Palm	16-20"	Yes	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Royal Poinciana	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH TER	Royal Poinciana	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 24TH TER	Weeping Fig	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub	Dead Wood	
SW 24TH TER	Hibiscus	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low	Dead Wood	
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 24TH TER	Gumbo Limbo	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH TER	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

Street Tree Inventory

SW 24th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 24TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 24TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 24TH TER	Cassia sp.	1-5"	No	10'	Good (61% to 80%)		Limb Damage - Minor		
SW 24TH TER	Cassia sp.	1-5"	No	10'	Good (61% to 80%)		Limb Damage - Minor		
SW 24TH TER	Date Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Date Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 24TH TER	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 24TH TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 24TH TER	Satin Leaf	1-5"	No	15'	Good (61% to 80%)		Dead Wood		
SW 24TH TER	Satin Leaf	1-5"	No	15'	Good (61% to 80%)		Dead Wood		
SW 24TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 24TH TER	Umbrella Tree	21-30"	No	10'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 24TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 24TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 24TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 24TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 24TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 24TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	Trunk Damage - Minor
SW 24TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 24TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 24TH TER	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 24TH TER	Royal Poinciana	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Croton	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Bottlebrush	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 24TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 24th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 24TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 24TH TER	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Hong Kong Orchid	21-30"	No	30'	Poor (21% to 40%)		Trunk Damage - Major	Topped	Sprouting
SW 24TH TER	Slash Pine	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Sapodilla	6-10"	No	20'	Good (61% to 80%)				
SW 24TH TER	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH TER	Mahogany	1-5"	No	10'	Good (61% to 80%)				
SW 24TH TER	Pigeon Plum	11-15"	No	20'	Good (61% to 80%)		Limb Damage - Minor	Codominant Leaders/No Included Bark	
SW 24TH TER	Black Olive	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH TER	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 24TH TER	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 24TH TER	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH TER	Montgomery Palm	1-5"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	11-15"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Leader - Bent	
SW 24TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Queen Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Live Oak	1-5"	No	5'	Good (61% to 80%)		Dead Wood		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 24th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Tapered Trunk	
SW 24TH TER	Neem Tree	1-5"	No	20'	Good (61% to 80%)		Limb Damage - Moderate		
SW 24TH TER	Neem Tree	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH TER	Neem Tree	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH TER	Neem Tree	1-5"	Yes	10'	Good (61% to 80%)				
SW 24TH TER	Neem Tree	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH TER	Royal Poinciana	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 24TH TER	Black Olive	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 24TH TER	Frangipani	6-10"	No	5'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH TER	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)				
SW 24TH TER	Silk Floss Tree	1-5"	No	15'	Good (61% to 80%)				
SW 24TH TER	Crepe Myrtle	11-15"	Yes	10'	Good (61% to 80%)				
SW 24TH TER	Bougainvillea sp.	16-20"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 24TH TER	Gumbo Limbo	11-15"	No	30'	Good (61% to 80%)		Dead Wood		
SW 24TH TER	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Weeping Fig	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Major	Dead Wood
SW 24TH TER	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 24TH TER	Bottle Palm	11-15"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 24TH TER	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 24TH TER	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 24TH TER	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 24TH TER	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 24TH TER	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 24TH TER	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 24TH TER	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs	Dead Wood
SW 24TH TER	Tropical Almond	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	
SW 24TH TER	Tropical Almond	6-10"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH TER	Tropical Almond	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH TER	Glaucous Cassia	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Trunk Damage - Major	Dead Wood
SW 24TH TER	Glaucous Cassia	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Basal Co-Dominant	Trunk Damage - Major	Dead Wood
SW 24TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH TER	Sapodilla	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Lifting	Codominant Leaders/No Included Bark	Reduced Canopy - Moderate
SW 24TH TER	Sapodilla	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Limb Damage - Major	Sprouting
SW 24TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH TER	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Over Pruned		
SW 24TH TER	Jacaranda	1-5"	No	10'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Stubs with Sprouts	Leaning - Moderate

(Continued on Next Page)

Street Tree Inventory

SW 24th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH TER	Jacaranda	1-5"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Stubs with Sprouts	
SW 24TH TER	Black Olive	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 24TH TER	Black Olive	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH TER	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Black Olive	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Leader - Bent	Reduced Canopy - Minor	
SW 24TH TER	Crepe Myrtle	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Royal Poinciana	21-30"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 24TH TER	Queen Crepe Myrtle	6-10"	No	10'	Fair (41% to 60%)		Strap Constricting Tree		
SW 24TH TER	Queen Crepe Myrtle	1-5"	No	10'	Poor (21% to 40%)		Apical Dieback	Dead Wood	Discolored Foliage
SW 24TH TER	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Cavities
SW 24TH TER	Areca Palm	31-40"	Yes	20'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH TER	Queen Crepe Myrtle	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Topped	Reduced Canopy - Moderate	Sprouting
SW 24TH TER	Queen Crepe Myrtle	1-5"	No	15'	Poor (21% to 40%)	Utility Lines Above	Topped	Reduced Canopy - Moderate	Sprouting
SW 24TH TER	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 24TH TER	Rubber Tree	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 24TH TER	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 24TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH TER	Japanese Privet	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH TER	Coconut Palm	11-15"	No	25'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Cabbage Palm	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major		
SW 24TH TER	Royal Poinciana	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 24TH TER	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH TER	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH TER	Live Oak	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 24TH TER	Weeping Fig	6-10"	No	10'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 24TH TER	Bismark Palm	16-20"	No	20'	Good (61% to 80%)				
SW 24TH TER	Bismark Palm	16-20"	No	20'	Good (61% to 80%)				
SW 24TH TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH TER	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH TER	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)				
SW 24TH TER	Norfolk Pine	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Ponytail Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 24TH TER	Areca Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH TER	Frangipani	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH TER	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 24TH TER	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 24th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH TER	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 24TH TER	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Pygmy Date Palm	6-10"	No	5'	Good (61% to 80%)				
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH TER	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 24TH TER	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 24TH TER	Pink Tabebuia	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 24TH TER	Paradise Tree	1-5"	No	10'	Good (61% to 80%)				
SW 24TH TER	Pink Tabebuia	1-5"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	
SW 24TH TER	Pink Tabebuia	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH TER	Jacaranda	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 24TH TER	Jacaranda	6-10"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Codominant Leaders/Included Bark	
SW 24TH TER	Paradise Tree	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 24TH TER	Japanese Blueberry	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Japanese Blueberry	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Japanese Blueberry	1-5"	No	5'	Good (61% to 80%)				
SW 24TH TER	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 24TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Foxtail Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH TER	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Foxtail Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 24TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 24TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 24TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH TER	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 24TH TER	Royal Poinciana	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 24TH TER	Christmas Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 24TH TER	Hong Kong Orchid	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 24TH TER	Tropical Almond	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 24TH TER	Royal Poinciana	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 24TH TER	Royal Poinciana	31-40"	No	75'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 24TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Hibiscus	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 24TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 24TH TER	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 24TH TER	Mahogany	21-30"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Trunk Damage - Moderate	Reduced Canopy - Major	Dead Wood
SW 24TH TER	Mahogany	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 24th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH TER	Betelnut Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH TER	Orange Geiger	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 24TH TER	Orange Geiger	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Leader - Broken		
SW 24TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		

Street Tree Inventory

SW 25th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs
SW 25TH ST	Spanish Lime	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Apical Dieback
SW 25TH ST	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 25TH ST	Loquat	6-10"	No	15'	Fair (41% to 60%)		Basal Co-Dominant		
SW 25TH ST	Live Oak	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Cavities
SW 25TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Yellow Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Strap Constricting Tree	Codominant Leaders/Included Bark	Dead Wood
SW 25TH ST	Royal Poinciana	16-20"	No	55'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 25TH ST	Starburst Clerodendron	6-10"	Yes	10'	Poor (21% to 40%)		Topped	Sprouting	Suppressed Canopy
SW 25TH ST	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Minor	
SW 25TH ST	Coconut Palm	16-20"	No	20'	Fair (41% to 60%)		Over Pruned		
SW 25TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH ST	Mahogany	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH ST	Mahogany	41-50"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 25TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	30'	Good (61% to 80%)				
SW 25TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH ST	Starburst Clerodendron	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH ST	Weeping Fig	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Dead Wood	Stubs
SW 25TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 25TH ST	Coconut Palm	6-10"	No	30'	Good (61% to 80%)				
SW 25TH ST	Weeping Fig	6-10"	No	10'	Very Poor/Critical (6% to 20%)		Topped	Sprouting	Decay Observed
SW 25TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 25TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH ST	Mango	1-5"	No		Good (61% to 80%)				
SW 25TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 25th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Guiana Chestnut	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Stubs
SW 25TH ST	Guiana Chestnut	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	
SW 25TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH ST	Guiana Chestnut	6-10"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 25TH ST	Sea Grape	6-10"	No	15'	Very Poor/Critical (6% to 20%)		Crown Density - Very Low	Dead Wood	
SW 25TH ST	Coconut Palm	6-10"	No	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Hong Kong Orchid	11-15"	Yes	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH ST	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)		Dead Wood	Sprouting	
SW 25TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH ST	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 25TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Moderate	Sprouting
SW 25TH ST	Weeping Fig	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	
SW 25TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Royal Poinciana	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 25TH ST	Spindle Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Royal Poinciana	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 25TH ST	Bridalveil Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 25TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)				
SW 25TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Citrus sp.	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Citrus sp.	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Mango	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 25TH ST	Mango	1-5"	Yes	5'	Good (61% to 80%)		Restricted Canopy		
SW 25TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 25TH ST	Royal Poinciana	31-40"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Dead Wood	Insect Damage Leaves	
SW 25TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Dead Wood	Insect Damage Leaves	
SW 25TH ST	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 25th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH ST	Weeping Fig	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 25TH ST	Melaleuca	21-30"	No	Negligible	Dead (0% to 5%)				
SW 25TH ST	Weeping Fig	21-30"	No	15'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 25TH ST	Mahogany	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 25TH ST	Solitaire Palm	1-5"	Yes	10'	Fair (41% to 60%)		Suppressed Canopy	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 25TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Suppressed Canopy	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 25TH ST	Queen Palm	1-5"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Restricted Canopy	
SW 25TH ST	Queen Palm	1-5"	No	5'	Poor (21% to 40%)		Nutrient Deficiency		
SW 25TH ST	Bamboo Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH ST	Date Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH ST	Date Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 25TH ST	Royal Poinciana	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 25TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Strangler Fig	51-60"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 25TH ST	Queen Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Queen Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Queen Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Queen Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Queen Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Queen Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Queen Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Mahogany	41-50"	No	60'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 25TH ST	Mahogany	31-40"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 25TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Basal Co-Dominant with Adjacent Tree(s)	
SW 25TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Sprouting	
SW 25TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Mahogany	31-40"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 25TH ST	Mahogany	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 25TH ST	Hong Kong Orchid	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 25TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor		
SW 25TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Weeping Fig	1-5"	No	10'	Good (61% to 80%)		White Fly		
SW 25TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Yellow Tabebuia	16-20"	Yes	30'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 25TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 25th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH ST	Royal Palm	1-5"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Suppressed Canopy	
SW 25TH ST	Royal Palm	16-20"	No	25'	Good (61% to 80%)				
SW 25TH ST	Royal Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 25TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 25TH ST	Royal Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 25TH ST	Pink Poui Tabebuia	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Topped
SW 25TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Restricted Canopy		
SW 25TH ST	Cycad	11-15"	No	10'	Good (61% to 80%)				
SW 25TH ST	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 25TH ST	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 25TH ST	Malabar Plum	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 25TH ST	Glaucous Cassia	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 25TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Suppressed Canopy	
SW 25TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 25TH ST	Paradise Tree	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 25TH ST	Paradise Tree	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 25TH ST	Paradise Tree	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 25TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	No	25'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH ST	Coconut Palm	6-10"	No	30'	Good (61% to 80%)				
SW 25TH ST	Cabbage Palm	11-15"	No	20'	Good (61% to 80%)				
SW 25TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 25TH ST	Coconut Palm	6-10"	No	30'	Good (61% to 80%)				
SW 25TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH ST	Montgomery Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH ST	Montgomery Palm	1-5"	No	20'	Good (61% to 80%)				
SW 25TH ST	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 25TH ST	Mahogany	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 25TH ST	Royal Poinciana	6-10"	No	30'	Good (61% to 80%)		Girdling Roots	Codominant Leaders/No Included Bark	
SW 25TH ST	Gumbo Limbo	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Restricted Canopy
SW 25TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 25TH ST	Queen Palm	11-15"	No	25'	Good (61% to 80%)				
SW 25TH ST	Queen Palm	11-15"	No	25'	Good (61% to 80%)				
SW 25TH ST	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 25TH ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH ST	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 25TH ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs
SW 25TH ST	Earleaf Acacia	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 25TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 25th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 25TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Solitaire Palm	1-5"	Yes	15'	Good (61% to 80%)				
SW 25TH ST	Sapodilla	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 25TH ST	Sapodilla	16-20"	No	20'	Fair (41% to 60%)		Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 25TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH ST	Desert Cassia	1-5"	No	10'	Good (61% to 80%)				
SW 25TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		

Streets | Terraces | Lanes



Looking East - SW 27th Avenue



Looking East - SW 24th Avenue



Looking East- SW 27th Avenue



Looking East - SW 25th Avenue



Looking East - SW 22nd Avenue



Looking East - SW 21st Avenue



Looking West- SW 23rd Avenue



Looking East - SW 21st Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 25th Terrace	2	Silver Bluff	4	50	4100	No	No	Yes	2	City	Yes	Yes	7 (10 W of 24th Ave/ E of 22nd Ave)	Yes	Yes	North side Between SW 27th and SW 24th Ave, Crossing 25th Ave	Grass, gravel, and paved swales. Speed bump between SW 27th and 25th Ave and SW 23rd and 22nd Ave and 21st and 19th Ave. Roundabout at SW 23rd Ave.
SW 26th Street	2	Silver Bluff	4	60-50	3500	No	No	Yes	2	City	Yes	Yes	7	Between 27th Ave and 22nd Ave	Yes	South side between 23rd Ave and 22nd Ave, north side between 24th Ave and 25th ave. Crossing 25th Ave and just east of 27th Ave.	Grass, gravel, and paved swales. Designated on-street parking on south side between SW 25th and 24th Ave. Angular oblong roundabout at SW 24th Ave and triangular round about at intersection with SW 26th Lane and SW 22nd Ave. Speed bump between SW 23rd and 22nd Ave. ROW width increases between SW 25th Ave and SW 22nd Ave.

SW 25th Terrace

TYPOLOGY B & A

SW 26th Street

TYPOLOGY B & A

Street Tree Inventory

SW 25th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH TER	Bottle Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Weeping Fig	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 25TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Over Pruned		
SW 25TH TER	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	6-10"	No	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 25TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH TER	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	
SW 25TH TER	Royal Poinciana	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 25TH TER	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Dead Wood
SW 25TH TER	Areca Palm	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Mostly	Nutrient Deficiency	
SW 25TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Over Pruned		
SW 25TH TER	Coconut Palm	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 25TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Loquat	11-15"	No	20'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Trunk Damage - Major	Decay Observed	Reduced Canopy - Major
SW 25TH TER	Japanese Privet	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH TER	Lychee	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant	Dead Wood	
SW 25TH TER	Bottle Palm	11-15"	No	5'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH TER	Coconut Palm	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	11-15"	No	25'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Moderate	
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Mahogany	41-50"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 25TH TER	Starfruit	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Reduced Canopy - Moderate	
SW 25TH TER	Crepe Myrtle	11-15"	Yes	10'	Good (61% to 80%)				
SW 25TH TER	Frangipani	1-5"	No	15'	Good (61% to 80%)				
SW 25TH TER	Spindle Palm	11-15"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Moderate	
SW 25TH TER	Crepe Myrtle	11-15"	Yes	10'	Good (61% to 80%)				
SW 25TH TER	Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 25TH TER	Triangle Palm	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 25th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH TER	Black Olive	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 25TH TER	Black Olive	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Restricted Canopy	
SW 25TH TER	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 25TH TER	Gumbo Limbo	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 25TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	11-15"	No	35'	Good (61% to 80%)				
SW 25TH TER	Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 25TH TER	Royal Poinciana	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Dead Wood	Stubs with Sprouts
SW 25TH TER	Mahogany	51-60"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Major
SW 25TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	16-20"	Yes	15'	Fair (41% to 60%)		Cracks in Trunk	One Dead Trunk	
SW 25TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 25TH TER	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 25TH TER	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 25TH TER	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 25TH TER	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH TER	Royal Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Brazilian Beauty Leaf	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 25TH TER	Brazilian Beauty Leaf	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 25TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	White Stopper	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Satin Leaf	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Very Low	Strap Constricting Tree	
SW 25TH TER	Jamaica Caper	1-5"	No	5'	Good (61% to 80%)				
SW 25TH TER	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 25TH TER	Mahogany	51-60"	No	50'	Poor (21% to 40%)		Constricted Roots	Lifting	Stubs with Sprouts
SW 25TH TER	Royal Poinciana	16-20"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Grafted Branches	Trunk Damage - Moderate
SW 25TH TER	Mahogany	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 25TH TER	Pink Poui Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Insect Damage Leaves	
SW 25TH TER	Bismark Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH TER	Bottlebrush	11-15"	Yes	10'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure		
SW 25TH TER	Pygmy Date Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Pygmy Date Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Pink Poui Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Stubs with Sprouts	Dead Wood
SW 25TH TER	Pink Poui Tabebuia	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Stubs with Sprouts	Dead Wood
SW 25TH TER	Royal Poinciana	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Cavities	Decay Observed
SW 25TH TER	Royal Poinciana	6-10"	No	30'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Dead Wood	
SW 25TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 25TH TER	Frangipani	1-5"	No	10'	Fair (41% to 60%)		Fungus on Leaves		
SW 25TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Trunk Damage - Minor
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 25th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH TER	Royal Poinciana	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Royal Poinciana	16-20"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 25TH TER	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Spindle Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH TER	Chinese Fan Palm	21-30"	Yes	15'	Fair (41% to 60%)		Suppressed Canopy	Disease	
SW 25TH TER	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Cavities
SW 25TH TER	Chinese Fan Palm	6-10"	No	20'	Fair (41% to 60%)		Suppressed Canopy	Disease	
SW 25TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 25TH TER	Chinese Fan Palm	21-30"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH TER	Bottlebrush	21-30"	Yes	10'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 25TH TER	Strawberry Guava	6-10"	Yes	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 25TH TER	Strawberry Guava	6-10"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 25TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Royal Poinciana	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Dead Wood
SW 25TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Montgomery Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 25TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH TER	Pigeon Plum	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Major	Reduced Canopy - Moderate	Sprouting
SW 25TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 25TH TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH TER	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Senegal Date Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH TER	Pongam	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Discolored Foliage
SW 25TH TER	Pongam	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 25TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Weeping Fig	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	
SW 25TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 25th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Chinese Fan Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH TER	Chinese Fan Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Norfolk Pine	16-20"	No	20'	Fair (41% to 60%)		Basal Co-Dominant		
SW 25TH TER	Royal Poinciana	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 25TH TER	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH TER	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 25TH TER	Desert Cassia	1-5"	No	5'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 25TH TER	Sapodilla	6-10"	No	20'	Good (61% to 80%)		Suppressed Canopy		
SW 25TH TER	Royal Poinciana	16-20"	No	35'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	Dead Wood
SW 25TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 25TH TER	Royal Poinciana	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Pigeon Plum	11-15"	No	15'	Poor (21% to 40%)		Topped	Reduced Canopy - Major	Sprouting
SW 25TH TER	Glaucous Cassia	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Glaucous Cassia	1-5"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 25TH TER	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Trunk Damage - Minor
SW 25TH TER	Black Olive	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 25TH TER	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 25TH TER	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 25TH TER	Spindle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	16-20"	Yes	25'	Good (61% to 80%)		Over Pruned	Nutrient Deficiency	
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Weeping Fig	6-10"	No	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 25TH TER	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Over Pruned	Nutrient Deficiency	
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Live Oak	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark	Improperly Mulched	
SW 25TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Over Pruned		
SW 25TH TER	Montgomery Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Over Pruned	
SW 25TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 25TH TER	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 25th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH TER	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Stubs with Sprouts	Fungus on Leaves
SW 25TH TER	Pygmy Date Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Pygmy Date Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 25TH TER	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Over Pruned		
SW 25TH TER	Coconut Palm	16-20"	Yes	30'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH TER	Coconut Palm	16-20"	Yes	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH TER	Japanese Fern Tree	6-10"	No	25'	Good (61% to 80%)		Improperly Mulched		
SW 25TH TER	Japanese Fern Tree	6-10"	No	25'	Good (61% to 80%)		Improperly Mulched		
SW 25TH TER	Key Lime Tree	1-5"	No	10'	Good (61% to 80%)				
SW 25TH TER	Norfolk Pine	16-20"	No	15'	Good (61% to 80%)				
SW 25TH TER	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 25TH TER	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 25TH TER	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH TER	Silk Floss Tree	1-5"	No	15'	Good (61% to 80%)		Desiccated Foliage		

Street Tree Inventory

SW 26th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH ST	Weeping Fig	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Christmas Palm	21-30"	Yes	20'	Good (61% to 80%)				
SW 26TH ST	Pygmy Date Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH ST	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 26TH ST	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	White Fly	
SW 26TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Umbrella Tree	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 26TH ST	Coconut Palm	6-10"	No	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Gumbo Limbo	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	
SW 26TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots		
SW 26TH ST	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 26TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Girdling Roots		
SW 26TH ST	Norfolk Pine	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Minor	Leaning - Minor	
SW 26TH ST	Live Oak	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 26TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	Stubs with Sprouts
SW 26TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Crown Density - Moderate	Codominant Leaders/No Included Bark	Dead Wood
SW 26TH ST	Live Oak	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Lopsided/Moderately Reduced Canopy	
SW 26TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Restricted Canopy	
SW 26TH ST	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 26TH ST	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 26TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Topped	Sprouting	Suppressed Canopy
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Basal Co-Dominant	Restricted Canopy	
SW 26TH ST	Pink Tabebuia	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 26TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Brazilian Pepper	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant with Adjacent Tree(s)		
SW 26TH ST	Papaya	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant with Adjacent Tree(s)	Reduced Canopy - Moderate	
SW 26TH ST	Weeping Fig	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Weeping Fig	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Papaya	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 26TH ST	Mango	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 26TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 26th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Paurotis Palm	1-5"	No	Negligible	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major		
SW 26TH ST	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Suppressed Canopy	
SW 26TH ST	Mahogany	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 26TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 26TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Suppressed Canopy	
SW 26TH ST	Key Lime Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 26TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 26TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 26TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Mahogany	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Suppressed Canopy	
SW 26TH ST	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy	Lopsided/Moderately Reduced Canopy	
SW 26TH ST	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Sprouting	Suppressed Canopy
SW 26TH ST	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 26TH ST	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Suppressed Canopy	
SW 26TH ST	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy		
SW 26TH ST	Solitaire Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Restricted Canopy	
SW 26TH ST	Weeping Fig	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark		
SW 26TH ST	Weeping Fig	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Dead Wood
SW 26TH ST	Weeping Fig	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Basal Co-Dominant with Adjacent Tree(s)	
SW 26TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Suppressed Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 26TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Weeping Fig	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Dead Wood
SW 26TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Dead Wood
SW 26TH ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 26TH ST	Weeping Fig	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Basal Co-Dominant		
SW 26TH ST	Weeping Fig	11-15"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Royal Poinciana	16-20"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 26TH ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 26TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 26TH ST	Queen Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor		
SW 26TH ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 26TH ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 26TH ST	Queen Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 26TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Bottlebrush	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 26TH ST	Golden Rain Tree	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Topped	Trunk Damage - Major
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 26TH ST	Green Buttonwood	21-30"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 26TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Royal Poinciana	11-15"	No	40'	Good (61% to 80%)		Dead Wood		
SW 26TH ST	Weeping Fig	21-30"	No	25'	Poor (21% to 40%)		Reduced Canopy - Moderate	Dead Wood	Decay Observed
SW 26TH ST	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 26TH ST	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 26TH ST	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Black Olive	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 26TH ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	
SW 26TH ST	Mahogany	11-15"	No	15'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Stubs with Sprouts	

(Continued on Next Page)

Street Tree Inventory

SW 26th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH ST	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Girdling Roots	Leaning - Minor	Reduced Canopy - Moderate
SW 26TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 26TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH ST	Japanese Fern Tree	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 26TH ST	Oriental Arborvitae	11-15"	No	15'	Good (61% to 80%)				
SW 26TH ST	Sea Grape	6-10"	No	20'	Good (61% to 80%)				
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned	Nutrient Deficiency	
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned	Nutrient Deficiency	
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned	Nutrient Deficiency	
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned	Nutrient Deficiency	
SW 26TH ST	MacArthur Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH ST	Mahogany	11-15"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	
SW 26TH ST	Mahogany	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Limb Damage - Minor	
SW 26TH ST	Japanese Privet	11-15"	Yes	10'	Poor (21% to 40%)		Reduced Canopy - Moderate	Epicormic Growth	Dead Wood
SW 26TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Over Pruned		
SW 26TH ST	Umbrella Tree	16-20"	Yes	25'	Fair (41% to 60%)		Basal Co-Dominant	Restricted Canopy	
SW 26TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Coconut Palm	6-10"	No	10'	Fair (41% to 60%)		Suppressed Canopy	Over Pruned	
SW 26TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Umbrella Tree	11-15"	Yes	15'	Fair (41% to 60%)		Basal Co-Dominant	Restricted Canopy	
SW 26TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 26TH ST	Umbrella Tree	6-10"	No	10'	Poor (21% to 40%)		Topped	Sprouting	Suppressed Canopy
SW 26TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Woman's Tongue	11-15"	No	25'	Good (61% to 80%)		Restricted Canopy	Dead Wood	
SW 26TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 26TH ST	Strangler Fig	6-10"	No	30'	Good (61% to 80%)				
SW 26TH ST	Java Bishopwood	6-10"	No	25'	Good (61% to 80%)		Restricted Canopy		
SW 26TH ST	Green Buttonwood	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Root Damage/Decay	Dead Wood
SW 26TH ST	Norfolk Pine	11-15"	No	15'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH ST	Umbrella Tree	21-30"	No	20'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Sprouting
SW 26TH ST	Umbrella Tree	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 26TH ST	Umbrella Tree	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 26TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 26TH ST	Green Buttonwood	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 26TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 26TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 26TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 26th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate	Limb Damage - Moderate
SW 26TH ST	Orange Geiger	1-5"	Yes	5'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Moderate	Stubs
SW 26TH ST	Solitaire Palm	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Suppressed Canopy	
SW 26TH ST	Mahogany	21-30"	Yes	20'	Poor (21% to 40%)		Basal Co-Dominant	Limb Damage - Moderate	Sprouting
SW 26TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark	Restricted Canopy	
SW 26TH ST	Pigeon Plum	16-20"	No	20'	Poor (21% to 40%)		Reduced Canopy - Moderate	Trunk Damage - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 26TH ST	Pigeon Plum	6-10"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Vine Cover - Heavy	
SW 26TH ST	Pigeon Plum	11-15"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Vine Cover - Heavy	
SW 26TH ST	Bougainvillea sp.	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy		
SW 26TH ST	Weeping Fig	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Moderate	Dead Wood	
SW 26TH ST	Dracaena sp.	21-30"	Yes	15'	Good (61% to 80%)				
SW 26TH ST	Royal Poinciana	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH ST	Norfolk Pine	1-5"	No	5'	Good (61% to 80%)				
SW 26TH ST	Golden Shower Tree	1-5"	No	15'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Areca Palm	1-5"	Yes	5'	Poor (21% to 40%)		Reduced Canopy - Major	Suppressed Canopy	
SW 26TH ST	Areca Palm	1-5"	Yes	5'	Poor (21% to 40%)		Reduced Canopy - Major	Suppressed Canopy	
SW 26TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Strangler Fig	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 26TH ST	Norfolk Pine	21-30"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Suppressed Canopy	
SW 26TH ST	Norfolk Pine	16-20"	No	20'	Fair (41% to 60%)		Basal Co-Dominant		
SW 26TH ST	Glaucous Cassia	6-10"	Yes	20'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Sprouting

Streets | Terraces | Lanes



Looking East - SW 25th Avenue



Looking East - SW 24th Avenue



Looking East - SW 27th Avenue



Looking East - SW 24th Avenue



Looking East - SW 23rd Avenue



Looking West - SW 26th Lane



Looking West- SW 24th Avenue



Looking East - SW 26th Terrace

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 26th Terrace	2	Silver Bluff	4	60	1050	No	No	Yes	2	City	Yes	Yes	7	Yes	Yes	South side between 25th Ave and 23rd Ave	Mostly grass, one gravel swales. Both sides of street have on street parking next to travel lane
SW 26th Lane	2	Silver Bluff	4	60	2700	No	No	Yes	2	City	Yes	Yes	7	Yes	Yes	No	Grass swale, room for on-street parking next to travel lane. Roundabout at 25th Ave

SW 26th Terrace

TYPOLOGY B

SW 26th Lane

TYPOLOGY B

Street Tree Inventory

SW 26th Terrace

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH TER	Mahogany	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH TER	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Codominant Leaders/Included Bark		
SW 26TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH TER	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH TER	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Over Pruned		
SW 26TH TER	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Over Pruned		
SW 26TH TER	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)				
SW 26TH TER	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Stubs	Dead Wood
SW 26TH TER	Frangipani	1-5"	No	15'	Good (61% to 80%)				
SW 26TH TER	Coconut Palm	6-10"	No	30'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH TER	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH TER	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 26TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 26TH TER	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 26TH TER	Queen Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH TER	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH TER	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH TER	Montgomery Palm	11-15"	No	15'	Good (61% to 80%)				
SW 26TH TER	Montgomery Palm	11-15"	No	15'	Good (61% to 80%)				
SW 26TH TER	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH TER	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH TER	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH TER	Frangipani	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 26TH TER	Queen Crepe Myrtle	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 26TH TER	Avocado	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 26TH TER	Strangler Fig	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Basal Co-Dominant with Adjacent Tree(s)	
SW 26TH TER	Cabbage Palm	11-15"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Ficus Growing on Tree	
SW 26TH TER	Umbrella Tree	1-5"	No	10'	Good (61% to 80%)				
SW 26TH TER	Earleaf Acacia	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Topped
SW 26TH TER	Silver Buttonwood	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Topped	Sprouting	
SW 26TH TER	Strawberry Guava	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 26TH TER	Umbrella Tree	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Basal Co-Dominant		
SW 26TH TER	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	
SW 26TH TER	Silk Floss Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 26TH TER	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Trunk Damage - Minor	Stubs with Sprouts
SW 26TH TER	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor		
SW 26TH TER	Coconut Palm	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Nutrient Deficiency	
SW 26TH TER	Coconut Palm	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	White Fly	
SW 26TH TER	Live Oak	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Sprouting	
SW 26TH TER	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 26TH TER	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)		Girdling Roots		

Street Tree Inventory

SW 26th Terrace (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH TER	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Girdling Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 26TH TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 26TH TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 26TH TER	Gumbo Limbo	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 26TH TER	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 26TH TER	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 26TH TER	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 26TH TER	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 26TH TER	Mahogany	11-15"	No	40'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH TER	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 26TH TER	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH TER	Yellow Poinciana	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Grafted Branches	
SW 26TH TER	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 26TH TER	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 26TH TER	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH TER	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 26TH TER	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		

Street Tree Inventory

SW 26th Lane

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH LN	Areca Palm	6-10"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH LN	Spindle Palm	11-15"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH LN	Spindle Palm	6-10"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH LN	Green Buttonwood	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 26TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned	Tapered Trunk	
SW 26TH LN	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 26TH LN	Gumbo Limbo	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Leader - Bent
SW 26TH LN	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy		
SW 26TH LN	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 26TH LN	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 26TH LN	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH LN	Dracaena sp.	11-15"	Yes	10'	Good (61% to 80%)				
SW 26TH LN	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH LN	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH LN	Coconut Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH LN	Mahogany	11-15"	No	30'	Good (61% to 80%)		Dead Wood	Codominant Leaders/Included Bark	
SW 26TH LN	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Major	Stubs with Sprouts
SW 26TH LN	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 26TH LN	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Restricted Canopy
SW 26TH LN	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 26TH LN	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Root Damage/Decay	Codominant Leaders/Included Bark	
SW 26TH LN	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots		
SW 26TH LN	Black Olive	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 26TH LN	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Topped	Sprouting	
SW 26TH LN	Norfolk Pine	11-15"	No	25'	Good (61% to 80%)				
SW 26TH LN	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 26TH LN	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 26TH LN	Mahogany	11-15"	No	35'	Good (61% to 80%)				
SW 26TH LN	Mahogany	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH LN	Mahogany	11-15"	No	25'	Good (61% to 80%)				
SW 26TH LN	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Girdling Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 26TH LN	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Root Damage/Decay	Restricted Canopy	Codominant Leaders/Included Bark
SW 26TH LN	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH LN	Bottle Palm	6-10"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major	Nutrient Deficiency	
SW 26TH LN	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH LN	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH LN	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Codominant Leaders/Included Bark	
SW 26TH LN	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 26TH LN	Mahogany	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Minor	Codominant Leaders/Included Bark	
SW 26TH LN	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH LN	Coconut Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH LN	Mango	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 26TH LN	Coconut Palm	1-5"	No	Negligible	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 26TH LN	Coconut Palm	1-5"	No	Negligible	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 26TH LN	Tropical Almond	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 26th Lane (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH LN	Coconut Palm	1-5"	No	Negligible	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 26TH LN	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 26TH LN	Coconut Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 26TH LN	Coconut Palm	1-5"	No	Negligible	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 26TH LN	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 26TH LN	Mahogany	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 26TH LN	Bottle Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH LN	Bottle Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH LN	Bottle Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 26TH LN	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Frizzled Fronds		
SW 26TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 26TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH LN	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				
SW 26TH LN	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Dead Wood		
SW 26TH LN	Coconut Palm	6-10"	No	25'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH LN	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH LN	Cabbage Palm	16-20"	No	15'	Fair (41% to 60%)		Restricted Canopy	Ficus Growing on Tree	
SW 26TH LN	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH LN	Gumbo Limbo	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major		
SW 26TH LN	Starfruit	6-10"	No	15'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Suppressed Canopy	
SW 26TH LN	Brazilian Pepper	21-30"	No	20'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Dead Wood
SW 26TH LN	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 26TH LN	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	16-20"	Yes	20'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Live Oak	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 26TH LN	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH LN	Live Oak	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH LN	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 26TH LN	Coconut Palm	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 26TH LN	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH LN	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)				
SW 26TH LN	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	21-30"	Yes	20'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 26th Lane (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH LN	Mahogany	41-50"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 26TH LN	Mahogany	41-50"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 26TH LN	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	11-15"	Yes	20'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Areca Palm	16-20"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH LN	Areca Palm	11-15"	Yes	15'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH LN	Golden Rain Tree	31-40"	Yes	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sprouting
SW 26TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 26TH LN	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Restricted Canopy	Codominant Leaders/Included Bark
SW 26TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 26TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 26TH LN	Coconut Palm	11-15"	No	25'	Fair (41% to 60%)		Over Pruned	Nutrient Deficiency	
SW 26TH LN	Montgomery Palm	16-20"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 26TH LN	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Stubs	Decay Observed
SW 26TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH LN	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH LN	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 26TH LN	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 26TH LN	Frangipani	1-5"	No	15'	Good (61% to 80%)				
SW 26TH LN	Coconut Palm	11-15"	No	25'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH LN	Royal Poinciana	41-50"	No	45'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 26TH LN	Royal Poinciana	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 26TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)	
SW 26TH LN	Manilla Tamarind	51-60"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Ficus Growing on Tree
SW 26TH LN	Strangler Fig	21-30"	No	20'	Poor (21% to 40%)		Constricted Roots	Supporting Manilla Tamarind Tree	
SW 26TH LN	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH LN	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 26TH LN	Lead Tree	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Leaning - Moderate	Sprouting
SW 26TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH LN	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH LN	Royal Poinciana	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Stubs	Decay Observed
SW 26TH LN	Frangipani	1-5"	No	15'	Fair (41% to 60%)		Rebar in Trunk		
SW 26TH LN	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 26TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 26TH LN	Bottle Palm	6-10"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Nutrient Deficiency	
SW 26TH LN	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 26TH LN	Bottle Palm	6-10"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH LN	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 26TH LN	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 26TH LN	Royal Poinciana	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 26th Lane (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 26TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate	Limb Damage - Moderate
SW 26TH ST	Orange Geiger	1-5"	Yes	5'	Poor (21% to 40%)		Basal Co-Dominant	Reduced Canopy - Moderate	Stubs
SW 26TH ST	Solitaire Palm	1-5"	No	5'	Poor (21% to 40%)		Trunk Damage - Major	Suppressed Canopy	
SW 26TH ST	Mahogany	21-30"	Yes	20'	Poor (21% to 40%)		Basal Co-Dominant	Limb Damage - Moderate	Sprouting
SW 26TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark	Restricted Canopy	
SW 26TH ST	Pigeon Plum	16-20"	No	20'	Poor (21% to 40%)		Reduced Canopy - Moderate	Trunk Damage - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 26TH ST	Pigeon Plum	6-10"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Vine Cover - Heavy	
SW 26TH ST	Pigeon Plum	11-15"	No	15'	Poor (21% to 40%)		Basal Co-Dominant	Vine Cover - Heavy	
SW 26TH ST	Bougainvillea sp.	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy		
SW 26TH ST	Weeping Fig	11-15"	No	20'	Poor (21% to 40%)		Reduced Canopy - Moderate	Dead Wood	
SW 26TH ST	Dracaena sp.	21-30"	Yes	15'	Good (61% to 80%)				
SW 26TH ST	Royal Poinciana	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Royal Poinciana	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 26TH ST	Norfolk Pine	1-5"	No	5'	Good (61% to 80%)				
SW 26TH ST	Golden Shower Tree	1-5"	No	15'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 26TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 26TH ST	Areca Palm	1-5"	Yes	5'	Poor (21% to 40%)		Reduced Canopy - Major	Suppressed Canopy	
SW 26TH ST	Areca Palm	1-5"	Yes	5'	Poor (21% to 40%)		Reduced Canopy - Major	Suppressed Canopy	
SW 26TH ST	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH ST	Strangler Fig	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 26TH ST	Norfolk Pine	21-30"	No	20'	Fair (41% to 60%)		Basal Co-Dominant	Suppressed Canopy	
SW 26TH ST	Norfolk Pine	16-20"	No	20'	Fair (41% to 60%)		Basal Co-Dominant		
SW 26TH ST	Glaucous Cassia	6-10"	Yes	20'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Sprouting

Streets | Terraces | Lanes




Looking East - SW 27th Avenue



Looking West - SW 28th Lane



Looking West - SW 27th Avenue



Looking West - SW 27th Avenue



Looking West - SW 23rd Avenue



Looking West - SW 22nd Avenue



Looking West - SW 27th Avenue



Looking East - SW 27th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 27th Street	2	Silver Bluff	4	60	1400	No	No	Yes	2	City	Yes	Yes	8	Yes	Yes	No	Grass swale, room for on-street parking next to travel lane. Roundabout at 24th Ave
SW 28th Lane	2	Silver Bluff	4	60	1000	No	No	Yes	2	City	Yes	Yes	5	Yes	Yes	North side Between SW 27th and intersection with 27th Street	Grass, or paved swales. Both sides of street have on street parking next to travel lane

SW 27th Street

TYPOLOGY B

SW 28th Lane

TYPOLOGY B

Street Tree Inventory

SW 27th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 27TH ST	Oleander	21-30"	Yes	20'	Good (61% to 80%)				
SW 27TH ST	Papaya	11-15"	Yes	15'	Good (61% to 80%)				
SW 27TH ST	Areca Palm	31-40"	Yes	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 27TH ST	Mahogany	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 27TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 27TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Reduced Canopy - Minor	Stubs with Sprouts
SW 27TH ST	Mahogany	6-10"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 27TH ST	Mahogany	11-15"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Stubs with Sprouts	
SW 27TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 27TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 27TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 27TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 27TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 27TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 27TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 27TH ST	Mahogany	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 27TH ST	Mahogany	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 27TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 27TH ST	Royal Poinciana	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 27TH ST	Mahogany	1-5"	No	5'	Poor (21% to 40%)		Crown Density - Low	Improperly Mulched	
SW 27TH ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Restricted Canopy
SW 27TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Restricted Canopy	Codominant Leaders/Included Bark
SW 27TH ST	Golden Rain Tree	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 27TH ST	Royal Poinciana	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 27TH ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Restricted Canopy
SW 27TH ST	Black Olive	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Restricted Canopy
SW 27TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 27TH ST	Black Olive	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 27TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 27TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 27TH ST	Pigeon Plum	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 27TH ST	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Topped	Sprouting	Dead Wood
SW 27TH ST	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Topped	Sprouting	Dead Wood
SW 27TH ST	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Topped	Sprouting	Dead Wood
SW 27TH ST	MacArthur Palm	11-15"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 27TH ST	Umbrella Tree	1-5"	No	5'	Good (61% to 80%)				
SW 27TH ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency	White Fly	
SW 27TH ST	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 27TH ST	Gumbo Limbo	1-5"	No	5'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 27TH ST	Tropical Almond	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 27TH ST	Avocado	6-10"	No	15'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 27TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots		
SW 27TH ST	Ackee Tree	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Sprouting	Growing on Fence
SW 27TH ST	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Growing on Fence	

(Continued on Next Page)

Street Tree Inventory

SW 27th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 27TH ST	Gumbo Limbo	11-15"	No	25'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/No Included Bark		
SW 27TH ST	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 27TH ST	Gumbo Limbo	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Girdling Roots	Trunk Damage - Major	Decay Observed
SW 27TH ST	Gumbo Limbo	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 27TH ST	Japanese Privet	6-10"	No	10'	Good (61% to 80%)				
SW 27TH ST	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH ST	Japanese Privet	6-10"	Yes	10'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH ST	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 27TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Ficus Growing on Tree		
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)		Ficus Growing on Tree		
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)		Trunk Damage - Major	Stubs with Sprouts	Dead Wood
SW 27TH ST	Mahogany	16-20"	No	35'	Poor (21% to 40%)		Trunk Damage - Moderate	Girdling Roots	Decay Observed
SW 27TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 27TH ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Girdling Roots	Reduced Canopy - Moderate	Dead Wood
SW 27TH ST	Mahogany	16-20"	No	30'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Girdling Roots	Trunk Damage - Major	Decay Observed
SW 27TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Girdling Roots	Stubs with Sprouts	Dead Wood
SW 27TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Girdling Roots	Stubs with Sprouts	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 27TH ST	Mahogany	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 27th Street (Continued)


STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 27TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	31-40"	No	60'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	Dead Wood
SW 27TH ST	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Girdling Roots	Dead Wood	Stubs with Sprouts
SW 27TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Girdling Roots	Dead Wood	Stubs with Sprouts
SW 27TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)		Girdling Roots	Dead Wood	Stubs with Sprouts
SW 27TH ST	Mahogany	21-30"	No	40'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Cavities
SW 27TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 27TH ST	Black Olive	21-30"	No	30'	Poor (21% to 40%)		Girdling Roots	Reduced Canopy - Major	Sprouting
SW 27TH ST	Black Olive	21-30"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Sprouting	
SW 27TH ST	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 27TH ST	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)				
SW 27TH ST	Pink Tabebuia	1-5"	No	5'	Fair (41% to 60%)		Basal Co-Dominant		
SW 27TH ST	Solitaire Palm	11-15"	Yes	10'	Fair (41% to 60%)		Fungus on Leaves	One Dead Trunk	
SW 27TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 27TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 27TH ST	Coconut Palm	1-5"	No	Negligible	Fair (41% to 60%)		Nutrient Deficiency		
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH ST	Royal Palm	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Minor	Cracks in Trunk	
SW 27TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)				
SW 27TH ST	Royal Palm	11-15"	No	Negligible	Dead (0% to 5%)				
SW 27TH ST	Royal Palm	11-15"	No	25'	Good (61% to 80%)				
SW 27TH ST	BV UNID 2	41-50"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 27TH ST	Mahogany	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 27TH ST	BV UNID 2	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Limb Damage - Major	Stubs with Sprouts

Street Tree Inventory

SW 28th Lane

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 28TH LN	Weeping Fig	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts	
SW 28TH LN	Weeping Fig	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Above	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts	
SW 28TH LN	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 28TH LN	Umbrella Tree	1-5"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Topped	Sprouting	
SW 28TH LN	Weeping Fig	21-30"	No	30'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 28TH LN	Weeping Fig	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Broken Branches	Dead Wood
SW 28TH LN	Coconut Palm	16-20"	Yes	30'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Over Pruned	
SW 28TH LN	Coconut Palm	16-20"	Yes	35'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Over Pruned	
SW 28TH LN	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH LN	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH LN	Coconut Palm	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Nutrient Deficiency	Root Damage/Decay	
SW 28TH LN	Queen Palm	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency		
SW 28TH LN	Silver Buttonwood	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy		
SW 28TH LN	Silver Buttonwood	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy		
SW 28TH LN	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 28TH LN	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 28TH LN	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 28TH LN	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 28TH LN	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		

Bordering Streets



Looking West- SW 17th Avenue



Looking West - SW 18th Avenue



Looking East - SW 22nd Avenue



Looking East - SW 27th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 22nd Street	2	Silver Bluff	4	100	5300	Yes	No	Yes	4	State	Yes	No	0	Yes	Yes	No	Main street, no bike lanes. Street trees and planting mainly within center median. On- street parking on both side

SW 22nd Street (Coral Way)

TYPOLOGY D

Street Tree Inventory

SW 22nd Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 22ND ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 22ND ST	Banyan	60+"	No	85'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	41-50"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Basal Co-Dominant
SW 22ND ST	Banyan	60+"	No	90'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	21-30"	No	40'	Fair (41% to 60%)		Girdling Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	85'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 22ND ST	Banyan	60+"	No	75'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	75'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Live Oak	11-15"	No	25'	Good (61% to 80%)		Insect Damage Leaves	Dead Wood	
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 22ND ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 22ND ST	Banyan	60+"	No	85'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 22ND ST	Banyan	51-60"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Banyan	41-50"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Banyan	51-60"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Basal Co-Dominant
SW 22ND ST	Banyan	60+"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 22ND ST	Banyan	60+"	No	50'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 22ND ST	Banyan	51-60"	No	40'	Fair (41% to 60%)		Constricted Roots	Sprouting	Trunk Damage - Moderate
SW 22ND ST	Banyan	60+"	No	50'	Fair (41% to 60%)		Constricted Roots	Cavities	Sprouting
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Cavities	Sprouting
SW 22ND ST	Banyan	60+"	No	60'	Fair (41% to 60%)		Constricted Roots	Cavities	Sprouting
SW 22ND ST	Banyan	60+"	No	75'	Fair (41% to 60%)		Constricted Roots	Cavities	Sprouting
SW 22ND ST	Banyan	60+"	No	75'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 22ND ST	Banyan	60+"	No	60'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Cavities	Sprouting
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Cavities	Sprouting
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Cavities	Sprouting
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	70'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 22nd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND ST	Banyan	60+"	No	70'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	95'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	65'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	75'	Fair (41% to 60%)		Constricted Roots	Stubs	Sprouting
SW 22ND ST	Banyan	41-50"	No	40'	Good (61% to 80%)		Sprouting	Decay Observed	
SW 22ND ST	Banyan	60+"	No	85'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	85'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	75'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	90'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	90'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	95'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	80'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Banyan	60+"	No	90'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Sprouting
SW 22ND ST	Black Olive	16-20"	No	45'	Poor (21% to 40%)		Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Stubs with Sprouts
SW 22ND ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 22ND ST	Black Olive	21-30"	No	60'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 22ND ST	Black Olive	21-30"	No	60'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 22ND ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 22ND ST	Black Olive	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 22ND ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Cavities	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 22ND ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 22ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 22ND ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 22ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 22ND ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 22ND ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 22ND ST	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 22ND ST	Weeping Fig	1-5"	No	10'	Good (61% to 80%)		Pruned Into Shrub		

Avenues | Courts



Looking South - SW 22nd Street



Looking South - SW 23rd Street



Looking South - SW 22nd Street



Looking South - SW 22nd Terrace



Looking South - SW 24th Street



Looking North - SW 24th Terrace



Looking South - SW 23rd Terrace



Looking North - SW 25th Terrace

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 18th Avenue	2	Silver Bluff	4	50	1700	No	No	Yes	2	City	Yes	Yes	6	Yes	Yes	West side	Grass swales. Room for on street parking. Roundabout at 22nd Terr. and 24th Terr.
SW 19th Avenue	2	Silver Bluff	4	50	2200	No	No	No	2	City	Yes	Yes	8	Yes	Yes except south of 24th Terr..	West side	Grass swales. Room for on street parking. Roundabout at 23rd St., 24th St..

SW 18th Avenue

TYPOLOGY A

SW 19th Avenue

TYPOLOGY A

Street Tree Inventory

SW 18th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 18TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Tamarind	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	Dead Wood
SW 18TH AVE	Tamarind	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	
SW 18TH AVE	Tamarind	6-10"	No	10'	Poor (21% to 40%)		Leaning - Minor	Uprooted - Partially	Lopsided/Moderately Reduced Canopy
SW 18TH AVE	Tamarind	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	
SW 18TH AVE	Guiana Chestnut	1-5"	No	10'	Poor (21% to 40%)		Leader - Broken	Nutrient Deficiency	Lopsided/Moderately Reduced Canopy
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Over Pruned		
SW 18TH AVE	Mahogany	16-20"	No	20'	Fair (41% to 60%)		Girdling Roots	Lifting	Reduced Canopy - Moderate
SW 18TH AVE	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 18TH AVE	Mahogany	21-30"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Lifting
SW 18TH AVE	Live Oak	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 18TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/No Included Bark	
SW 18TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 18TH AVE	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH AVE	Crepe Myrtle	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH AVE	Black Olive	21-30"	No	40'	Good (61% to 80%)		Constricted Roots	Lifting	Trunk Damage - Moderate
SW 18TH AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Decay Observed	Lifting	Topped
SW 18TH AVE	Yellow Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/Included Bark	
SW 18TH AVE	Coconut Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Trunk Damage - Minor	Nutrient Deficiency	
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 18TH AVE	Weeping Fig	1-5"	No	10'	Good (61% to 80%)			Pruned Into Shrub	
SW 18TH AVE	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 18TH AVE	Pygmy Date Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 18TH AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 18TH AVE	Japanese Privet	1-5"		10'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 18TH AVE	Queen Palm	6-10"	No	10'	Poor (21% to 40%)		Leaning - Major	Crown Density - Low	
SW 18TH AVE	Queen Palm	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Tapered Trunk	
SW 18TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Queen Palm	6-10"	No	15'	Poor (21% to 40%)		Tapered Trunk	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 18TH AVE	Royal Palm	11-15"	No		Dead (0% to 5%)				
SW 18TH AVE	Royal Palm	6-10"	No		Dead (0% to 5%)				
SW 18TH AVE	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 18TH AVE	Mahogany	21-30"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 18TH AVE	Areca Palm	16-20"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 18th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 18TH AVE	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 18TH AVE	Royal Palm	21-30"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 18TH AVE	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 18TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 18TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)				
SW 18TH AVE	Mahogany	41-50"	No	40'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 18TH AVE	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 18TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 18TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 18TH AVE	Solitaire Palm	1-5"	No		Dead (0% to 5%)				
SW 18TH AVE	Dahoon Holly	1-5"	No	5'	Fair (41% to 60%)		Leaning - Minor	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 18TH AVE	Christmas Palm	6-10"	Yes	5'	Good (61% to 80%)				
SW 18TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)				
SW 18TH AVE	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				

Street Tree Inventory

SW 19th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Coconut Palm	11-15"	No	25'	Good (61% to 80%)				
SW 19TH AVE	Crepe Myrtle	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned		
SW 19TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy		
SW 19TH AVE	Weeping Fig	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Royal Poinciana	6-10"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 19TH AVE	Royal Poinciana	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 19TH AVE	Royal Poinciana	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major
SW 19TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 19TH AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 19TH AVE	Royal Poinciana	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 19TH AVE	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Silver Buttonwood	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 19TH AVE	Mahogany	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Mahogany	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Suppressed Canopy		
SW 19TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 19TH AVE	Mahogany	6-10"	No	30'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 19TH AVE	Slash Pine	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH AVE	Solitaire Palm	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 19TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Weeping Fig	21-30"	Yes	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs	Dead Wood
SW 19TH AVE	Weeping Fig	21-30"	Yes	15'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Stubs	Dead Wood
SW 19TH AVE	Gumbo Limbo	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 19TH AVE	Gumbo Limbo	6-10"	No	20'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Moderate	Decay Observed
SW 19TH AVE	Japanese Privet	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Frangipani	11-15"	No	20'	Poor (21% to 40%)	Utility Lines Above	Discolored Foliage	Topped	Decay Observed
SW 19TH AVE	Green Buttonwood	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 19TH AVE	Royal Poinciana	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Basal Co-Dominant	Dead Wood	Grafted Branches
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 19TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Tapered Trunk		
SW 19TH AVE	Japanese Blueberry	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 19TH AVE	Japanese Blueberry	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 19TH AVE	Japanese Blueberry	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		

(Continued on Next Page)

Street Tree Inventory

SW 19th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH AVE	Japanese Blueberry	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 19TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 19TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 19TH AVE	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 19TH AVE	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Decay Observed	Reduced Canopy - Moderate
SW 19TH AVE	Weeping Fig	31-40"	No	20'	Very Poor/Critical (6% to 20%)		Constricted Roots	Decay Observed	Reduced Canopy - Moderate
SW 19TH AVE	Gumbo Limbo	6-10"	No	20'	Poor (21% to 40%)		Basal Co-Dominant with Adjacent Tree(s)	Suppressed Canopy	Constricted Roots
SW 19TH AVE	Weeping Fig	31-40"	No	35'	Very Poor/Critical (6% to 20%)		Constricted Roots	Decay Observed	Reduced Canopy - Major
SW 19TH AVE	Live Oak	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	
SW 19TH AVE	Queen Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 19TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Girdling Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 19TH AVE	Royal Poinciana	16-20"	No	40'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Limb Damage - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 19TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Girdling Roots	Restricted Canopy	Decay Observed
SW 19TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 19TH AVE	Gumbo Limbo	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH AVE	Strangler Fig	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Sprouting	Lopsided/Significantly Reduced Canopy
SW 19TH AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 19TH AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 19TH AVE	Mahogany	31-40"	No	45'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 19TH AVE	Mahogany	31-40"	No	45'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 19TH AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 19TH AVE	Mahogany	41-50"	No	45'	Poor (21% to 40%)		Constricted Roots	Limb Damage - Major	Sprouting
SW 19TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 19TH AVE	Gumbo Limbo	1-5"	No	10'	Fair (41% to 60%)		Basal Co-Dominant	Sprouting	Sprouting
SW 19TH AVE	Frangipani	6-10"	Yes	10'	Good (61% to 80%)		Fungus on Leaves	Sprouting	
SW 19TH AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 19TH AVE	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 19TH AVE	Norfolk Pine	1-5"	Yes	5'	Good (61% to 80%)				
SW 19TH AVE	Black Olive	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Decay Observed	Codominant Leaders/Included Bark
SW 19TH AVE	Gumbo Limbo	6-10"	No	30'	Fair (41% to 60%)		Limb Damage - Major	Decay Observed	Restricted Canopy
SW 19TH AVE	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 19TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Sprouting
SW 19TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 19TH AVE	Jacaranda	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Codominant Leaders/Included Bark	Dead Wood	Sprouting
SW 19TH AVE	Royal Poinciana	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Grafted Branches	Codominant Leaders/No Included Bark
SW 19TH AVE	Mahogany	31-40"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 19TH AVE	Umbrella Tree	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Trunk Damage - Minor
SW 19TH AVE	Mahogany	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 19TH AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 19TH AVE	Solitaire Palm	1-5"	No		Dead (0% to 5%)				
SW 19TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Minor
SW 19TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 19TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 19th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 19TH AVE	Fan Palm/Pritchardia	1-5"	No	10'	Good (61% to 80%)				
SW 19TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 19TH AVE	Cabbage Palm	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Restricted Canopy	
SW 19TH AVE	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)		Restricted Canopy	Leader - Bent	Ficus Growing on Tree
SW 19TH AVE	Mahogany	11-15"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 19TH AVE	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)				
SW 19TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				


Avenues | Courts



Looking South - SW 22nd Street



Looking South - SW 23rd Terrace



Looking South - SW 22nd Street



Looking South - SW 23rd Terrace



Looking South - SW 25th Street



Looking North - SW 25th Terrace



Looking South - SW 25th Street



Looking North - US 1

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 21st Avenue	2	Silver Bluff	4	50	2500	No	No	Yes	5	County	Yes	Yes	5 (btw 24th St. and 24th Ter)	Yes except between 24th St. and 24th Terr.	Yes except between 24th St. and 24th Terr.	East side between 25th and 26 St.	Grass swales. Pave on street parking with no swale between 24th St. and 24th Terr. . Room for on street parking. Roundabout at 24th Terr.. Driveway narrows to one-way between 24th Terr. and 25th Terr. with loss of curbs and sidewalk. Houses closer to edge of lot and some swales with gravel and paving.
SW 22nd Avenue	2	Silver Bluff	4	75	2700	No	No	Yes	2	City	Yes	Yes	0	Yes	Yes	West side	Main street, no bike lanes. Intermittent trees and palms

SW 21st Avenue

TYPOLOGY A & E

SW 22nd Avenue

TYPOLOGY I

Street Tree Inventory

SW 21st Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 21ST AVE	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 21ST AVE	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 21ST AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 21ST AVE	Areca Palm	11-15"	Yes	10'	Good (61% to 80%)		Suppressed Canopy		
SW 21ST AVE	Yellow Poinciana	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	
SW 21ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 21ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Umbrella Tree	31-40"	No	25'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Umbrella Tree	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Dracaena sp.	6-10"	Yes	10'	Good (61% to 80%)		Dead Wood		
SW 21ST AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Dead Wood		
SW 21ST AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)		Dead Wood		
SW 21ST AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)		Dead Wood		
SW 21ST AVE	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)		Dead Wood		
SW 21ST AVE	Tropical Almond	11-15"	No	25'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Sprouting
SW 21ST AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 21ST AVE	Live Oak	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 21ST AVE	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/No Included Bark	Dead Wood
SW 21ST AVE	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Grafted Branches
SW 21ST AVE	Royal Poinciana	16-20"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 21ST AVE	Royal Poinciana	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 21ST AVE	Lead Tree	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant	Decay Observed
SW 21ST AVE	Starfruit	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/Included Bark	Leaning - Minor	
SW 21ST AVE	Vera Wood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Bottlebrush	16-20"	No	20'	Fair (41% to 60%)		Trunk Damage - Major	Codominant Leaders/Included Bark	Sprouting
SW 21ST AVE	Royal Poinciana	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 21ST AVE	Royal Poinciana	31-40"	No	45'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 21ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 21ST AVE	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 21ST AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 21ST AVE	Silver Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Silver Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Silver Palm	6-10"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Hurricane/Princess Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Saw Palmetto	16-20"	Yes	15'	Good (61% to 80%)				
SW 21ST AVE	BV UNID 3	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Buccaneer Palm	6-10"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Mulberry	1-5"	No	15'	Fair (41% to 60%)		Codominant Leaders/No Included Bark		
SW 21ST AVE	Saw Palmetto	11-15"	Yes	5'	Good (61% to 80%)				
SW 21ST AVE	Lignum Vitae	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 21st Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 21ST AVE	Solitaire Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 21ST AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 21ST AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 21ST AVE	Mahogany	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST AVE	Mahogany	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict			
SW 21ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Royal Poinciana	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 21ST AVE	Royal Poinciana	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 21ST AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Royal Poinciana	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 21ST AVE	Royal Poinciana	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 21ST AVE	Royal Poinciana	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 21ST AVE	Royal Poinciana	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Broken Branches
SW 21ST AVE	Green Buttonwood	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 21ST AVE	Live Oak	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 21ST AVE	Live Oak	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 21ST AVE	Royal Poinciana	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Broken Branches
SW 21ST AVE	Avocado	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Limb Damage - Major	Sprouting
SW 21ST AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 21ST AVE	Live Oak	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Broken Branches
SW 21ST AVE	Live Oak	21-30"	No	20'	Poor (21% to 40%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 21ST AVE	Live Oak	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	Stubs
SW 21ST AVE	Hibiscus	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Pygmy Date Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Pygmy Date Palm	6-10"	Yes	5'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Frizzled Fronds	
SW 21ST AVE	Pygmy Date Palm	6-10"	Yes	5'	Poor (21% to 40%)	Utility Lines Above	Nutrient Deficiency		
SW 21ST AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 21ST AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 21ST AVE	Live Oak	41-50"	No	65'	Good (61% to 80%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 21ST AVE	Cabbage Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate		
SW 21ST AVE	Pink Tabebuia	1-5"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 21ST AVE	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Suppressed Canopy		
SW 21ST AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 21ST AVE	Washington Palm	11-15"	No	10'	Good (61% to 80%)				
SW 21ST AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 21ST AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 21ST AVE	Coconut Palm	16-20"	No	20'	Good (61% to 80%)				
SW 21ST AVE	Carrotwood	16-20"	No	30'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Moderate	Cracks in Trunk
SW 21ST AVE	Black Olive	11-15"	No	45'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 21ST AVE	Royal Poinciana	6-10"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark
SW 21ST AVE	Areca Palm	21-30"	Yes	15'	Poor (21% to 40%)		Nutrient Deficiency		

Street Tree Inventory

SW 22nd Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 22ND AVE	Strangler Fig	51-60"	No	25'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Topped	Reduced Canopy - Major
SW 22ND AVE	Strangler Fig	51-60"	No	25'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Topped	Reduced Canopy - Major
SW 22ND AVE	Live Oak	6-10"	No	10'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Constricted Roots
SW 22ND AVE	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	Dead Wood
SW 22ND AVE	Live Oak	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 22ND AVE	Live Oak	11-15"	No	25'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Dead Wood	
SW 22ND AVE	Live Oak	16-20"	No	25'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Crown Density - Very Low	Decay Observed	
SW 22ND AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood

Avenues | Courts




Looking South - SW 22nd Street



Looking South - SW 23rd Street



Looking South - SW 25th Street



Looking South - SW 24th Court



Looking South - SW 25th Street



Looking North - SW 27th Street



Looking North - SW 24th Court

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 23rd Avenue	2	Silver Bluff	4	50	2900	No	No	Yes	2	City	Yes	Yes	5	Yes	Yes	Between 24th Terr. and 25th St.., and 26th Ln. and 27th St..	Grass swales. Room for on street parking. Roundabout at 24th Terr., and 25th Terr..
SW 24th Court	2	Silver Bluff	4	60	230	No	No	Yes	2	City	Yes	Yes	10	Intermittently	Yes	Yes	Grass swales. Room for on street parking

SW 23rd Avenue

TYPOLOGY A

SW 24th Court

TYPOLOGY A

Street Tree Inventory

SW 23rd Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 23RD AVE	Royal Poinciana	16-20"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 23RD AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	11-15"	No	30'	Good (61% to 80%)				
SW 23RD AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Yellow Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders/No Included Bark
SW 23RD AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Restricted Canopy		
SW 23RD AVE	Manilla Tamarind	31-40"	No	60'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Ficus Growing on Tree
SW 23RD AVE	Brazilian Pepper	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Basal Co-Dominant with Adjacent Tree(s)	Lopsided/Significantly Reduced Canopy
SW 23RD AVE	Manilla Tamarind	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Suppressed Canopy	
SW 23RD AVE	Brazilian Pepper	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD AVE	Java Bishopwood	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD AVE	Tropical Almond	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Adjacent Fence
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Washington Palm	16-20"	No	15'	Good (61% to 80%)				
SW 23RD AVE	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Tapered Trunk	
SW 23RD AVE	Solitaire Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	Negligible	Dead (0% to 5%)				
SW 23RD AVE	Coconut Palm	6-10"	No	25'	Good (61% to 80%)				
SW 23RD AVE	Rainbow Eucalyptus	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 23RD AVE	Live Oak	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark	Dead Wood	
SW 23RD AVE	Sandbox Tree	11-15"	No	15'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Decay Observed	Crown Density - Very Low
SW 23RD AVE	Tamarind	11-15"	No	20'	Poor (21% to 40%)		Lopsided/Significantly Reduced Canopy	Sprouting	Trunk Damage - Minor
SW 23RD AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	
SW 23RD AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 23RD AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots		
SW 23RD AVE	Sapodilla	11-15"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Sloughing Bark	Suppressed Canopy
SW 23RD AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 23RD AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 23RD AVE	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Codominant Leaders/Included Bark	Lopsided/Moderately Reduced Canopy
SW 23RD AVE	Solitaire Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Black Olive	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD AVE	Black Olive	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Dead Wood	Sprouting
SW 23RD AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 23RD AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 23RD AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Sprouting
SW 23RD AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 23RD AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Frizzled Fronds	

(Continued on Next Page)

Street Tree Inventory

SW 23rd Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	Trunk Damage - Minor
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Bottlebrush	31-40"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD AVE	Bottlebrush	11-15"	No	10'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Leader - Broken	Reduced Canopy - Major
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Over Pruned	
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Solitaire Palm	21-30"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Live Oak	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 23RD AVE	Green Buttonwood	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 23RD AVE	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Girdling Roots	Dead Wood	Restricted Canopy
SW 23RD AVE	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Restricted Canopy
SW 23RD AVE	Live Oak	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	
SW 23RD AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD AVE	Paradise Tree	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 23RD AVE	Rubber Tree	11-15"	No	30'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 23RD AVE	Bottle Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Trunk Damage - Minor	
SW 23RD AVE	Pygmy Date Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Multi-Trunk Form - Not Downgraded for Structure	
SW 23RD AVE	Pygmy Date Palm	16-20"	No	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Multi-Trunk Form - Not Downgraded for Structure	
SW 23RD AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 23RD AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency	Over Pruned	
SW 23RD AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 23RD AVE	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 23RD AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 23RD AVE	Weeping Fig	41-50"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 23RD AVE	Lead Tree	1-5"	No	15'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Suppressed Canopy	
SW 23RD AVE	Unid 10	60+"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Unid 10	41-50"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 23RD AVE	Mahogany	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 23RD AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Stubs with Sprouts
SW 23RD AVE	Black Olive	31-40"	No	55'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 23rd Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 23RD AVE	Norfolk Pine	6-10"	No	15'	Good (61% to 80%)		Dead Wood		
SW 23RD AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 23RD AVE	Black Olive	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 23RD AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 23RD AVE	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Girdling Roots	Insect Damage Leaves	
SW 23RD AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	

SW 24th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH CT	Bottle Palm	11-15"	No	5'	Good (61% to 80%)				
SW 24TH CT	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 24TH CT	Glaucous Cassia	1-5"	No	5'	Poor (21% to 40%)	Utility Lines Above	Topped	Reduced Canopy - Major	Sprouting
SW 24TH CT	Peregrina	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 24TH CT	Glaucous Cassia	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 24TH CT	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH CT	Yellow Tabebuia	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Lopsided/Moderately Reduced Canopy	
SW 24TH CT	Areca Palm	21-30"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH CT	Areca Palm	21-30"	Yes	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH CT	Mahogany	16-20"	No	40'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 24TH CT	Lychee	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH CT	Lychee	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Codominant Leaders/No Included Bark	Seasonal Defoliation/Discolored Foliage	Stubs with Sprouts
SW 24TH CT	Live Oak	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 24TH CT	Seven Year Apple	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark		

Avenues | Courts



Looking South - SW 22nd Street



Looking South - SW 23rd Street



Looking South - SW 22nd Street



Looking South - SW 24th Street



Looking South - SW 25th Terrace



Looking North - SW 27th Street



Looking South - SW 25th Terrace



Looking North - SW 27th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 24th Avenue	2	Silver Bluff	4	60	3200	No	No	Yes	2	City	Yes	Yes	8	Yes except southern half between 25th Terr. and 26th Terr. on west side	Yes	West side	Grass swales. Room for on street parking. Roundabout at 22nd Terr., 25th St., 26th St., and 27th St.
SW 25th Avenue	2	Silver Bluff	4	50	3200	No	No	Yes	2	City	Yes	Yes	6	Yes except southern half between 25th St. and 25th Terr.	Yes	Crossing 25th Terr.., 26th Terr.., and between 26th Ln. and 27th St..	Grass swales. Room for on street parking. Road narrows between southern half between 25th St. and 26th St. with loss of curb and gravel swales. Roundabout at 23rd Street, 25th Terr., and 26th Lane

SW 24th Avenue

TYPOLOGY B

SW 25th Avenue

TYPOLOGY A

Street Tree Inventory

SW 24th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Mahogany	41-50"	No	50'	Fair (41% to 60%)		Constricted Roots	Sprouting	Decay Observed
SW 24TH AVE	Mahogany	41-50"	No	50'	Poor (21% to 40%)		Constricted Roots	Lifting	Dead Wood
SW 24TH AVE	Mahogany	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 24TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 24TH AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 24TH AVE	Royal Poinciana	21-30"	No	55'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 24TH AVE	Black Olive	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH AVE	Black Olive	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Sprouting
SW 24TH AVE	Black Olive	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Sprouting
SW 24TH AVE	Queen Crepe Myrtle	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH AVE	Queen Crepe Myrtle	16-20"	No	20'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 24TH AVE	Queen Crepe Myrtle	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 24TH AVE	Mahogany	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH AVE	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 24TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH AVE	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 24TH AVE	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 24TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Mahogany	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 24TH AVE	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	Multi-Trunk Form - Not Downgraded for Structure
SW 24TH AVE	Day Blooming Jasmine	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Suppressed Canopy	Dead Wood
SW 24TH AVE	Green Buttonwood	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 24TH AVE	Green Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 24TH AVE	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy		
SW 24TH AVE	Brazilian Pepper	11-15"	Yes	15'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)	
SW 24TH AVE	Green Buttonwood	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy	Basal Co-Dominant with Adjacent Tree(s)	
SW 24TH AVE	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 24TH AVE	Green Buttonwood	6-10"	No	10'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 24TH AVE	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	
SW 24TH AVE	Green Buttonwood	16-20"	No	15'	Poor (21% to 40%)		Restricted Canopy	Lopsided/Moderately Reduced Canopy	Basal Co-Dominant
SW 24TH AVE	Green Buttonwood	6-10"	Yes	10'	Poor (21% to 40%)	Utility Lines Above	Restricted Canopy	Lopsided/Moderately Reduced Canopy	Basal Co-Dominant
SW 24TH AVE	Green Buttonwood	16-20"	Yes	15'	Poor (21% to 40%)	Utility Line Conflict	Restricted Canopy	Lopsided/Moderately Reduced Canopy	Basal Co-Dominant
SW 24TH AVE	Weeping Fig	51-60"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH AVE	Coconut Palm	6-10"	No	25'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH AVE	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark		
SW 24TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Stubs	
SW 24TH AVE	Sapodilla	21-30"	No	35'	Fair (41% to 60%)		Basal Co-Dominant		

(Continued on Next Page)

Street Tree Inventory

SW 24th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH AVE	Sapodilla	21-30"	No	35'	Fair (41% to 60%)		Basal Co-Dominant		
SW 24TH AVE	Bottle Palm	1-5"	No	5'	Poor (21% to 40%)		Reduced Canopy - Major		
SW 24TH AVE	Bottle Palm	6-10"	No	5'	Poor (21% to 40%)		Reduced Canopy - Moderate	Frizzled Fronds	
SW 24TH AVE	Mahogany	31-40"	No	40'	Fair (41% to 60%)		Constricted Roots	Epicormic Growth	Stubs with Sprouts
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Over Pruned	
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Over Pruned	
SW 24TH AVE	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Over Pruned		
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 24TH AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Over Pruned	Nutrient Deficiency	
SW 24TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Rubber Tree	6-10"	Yes	15'	Poor (21% to 40%)		Reduced Canopy - Major	Trunk Damage - Major	Dead Wood
SW 24TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 24TH AVE	Orange Geiger	1-5"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 24TH AVE	Orange Geiger	1-5"	No	10'	Very Poor/Critical (6% to 20%)		Trunk Damage - Moderate	Leaning - Major	
SW 24TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Over Pruned		
SW 24TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 24TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 24TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Over Pruned		
SW 24TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH AVE	Oleander	1-5"	Yes	5'	Good (61% to 80%)				
SW 24TH AVE	Oleander	1-5"	Yes	10'	Good (61% to 80%)				
SW 24TH AVE	Oleander	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH AVE	Oleander	11-15"	Yes	15'	Good (61% to 80%)				
SW 24TH AVE	Tropical Almond	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 24TH AVE	Tropical Almond	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 24TH AVE	Tropical Almond	41-50"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 24TH AVE	Tropical Almond	31-40"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 24TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 24TH AVE	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Cabbage Palm	11-15"	No	15'	Good (61% to 80%)				
SW 24TH AVE	Silver Buttonwood	11-15"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Codominant Leaders/Included Bark	Dead Wood
SW 24TH AVE	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Strangler Fig	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	

(Continued on Next Page)

Street Tree Inventory

SW 24th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH AVE	Strangler Fig	11-15"	No	10'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Crown Density - Very Low	Dead Wood
SW 24TH AVE	Gumbo Limbo	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH AVE	Mahogany	31-40"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 24TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 24TH AVE	Tropical Almond	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Trunk Damage - Moderate	Dead Wood
SW 24TH AVE	Cat Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Cat Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Cat Palm	11-15"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Hibiscus	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 24TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Crepe Myrtle	16-20"	Yes	10'	Good (61% to 80%)		Dead Wood		
SW 24TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Pygmy Date Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Pygmy Date Palm	1-5"	Yes	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Live Oak	16-20"	No	45'	Good (61% to 80%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH AVE	Dracaena sp.	6-10"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Crown Density - Moderate	Dead Wood	
SW 24TH AVE	Starburst Clerodendron	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Weeping Fig	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Yellow Tabebuia	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 24TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 24TH AVE	Live Oak	1-5"	No	20'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 24TH AVE	Gumbo Limbo	6-10"	No	25'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH AVE	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	
SW 24TH AVE	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Major	Sprouting	
SW 24TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Live Oak	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 24TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Bottle Palm	11-15"	No	Negligible	Dead (0% to 5%)				
SW 24TH AVE	Bottle Palm	11-15"	No	Negligible	Dead (0% to 5%)				
SW 24TH AVE	Bottle Palm	16-20"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Unid 1	1-5"	Yes	5'	Fair (41% to 60%)		Dead Wood		
SW 24TH AVE	Unid 1	1-5"	Yes	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 24th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 24TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 24TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 24TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 24TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 24TH AVE	Weeping Fig	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Dead Wood		
SW 24TH AVE	Weeping Fig	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 24TH AVE	Royal Poinciana	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 24TH AVE	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Silver Buttonwood	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Multi-Trunk Form - Not Downgraded for Structure		
SW 24TH AVE	Gumbo Limbo	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 24TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 24TH AVE	Christmas Palm	6-10"	Yes	10'	Fair (41% to 60%)		Nutrient Deficiency	Frizzled Fronds	
SW 24TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 24TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		

SW 25th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 25TH AVE	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH AVE	Solitaire Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 25TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 25TH AVE	Royal Poinciana	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts

Street Tree Inventory

SW 25th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH AVE	Foxtail Palm	1-5"	No	5'	Good (61% to 80%)				
SW 25TH AVE	Foxtail Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Moderate	
SW 25TH AVE	Foxtail Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Coconut Palm	6-10"	No	25'	Fair (41% to 60%)		Nutrient Deficiency	Tapered Trunk	
SW 25TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH AVE	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH AVE	Queen Palm	6-10"	No	15'	Good (61% to 80%)				
SW 25TH AVE	Queen Palm	6-10"	No	20'	Good (61% to 80%)				
SW 25TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Minor	
SW 25TH AVE	Christmas Palm	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Nutrient Deficiency	Frizzled Fronds	
SW 25TH AVE	Royal Palm	11-15"	No	5'	Poor (21% to 40%)		Nutrient Deficiency	Reduced Canopy - Major	Frizzled Fronds
SW 25TH AVE	Tropical Almond	16-20"	No	20'	Poor (21% to 40%)		Girdling Roots	Topped	Reduced Canopy - Major
SW 25TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 25TH AVE	Tropical Almond	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Reduced Canopy - Major
SW 25TH AVE	Royal Palm	16-20"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH AVE	Bottle Palm	1-5"	No	5'	Poor (21% to 40%)		Loose Trunk	Tapered Trunk	Cracks in Trunk
SW 25TH AVE	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 25TH AVE	Weeping Fig	6-10"	No	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 25TH AVE	Bottle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 25TH AVE	Bottle Palm	6-10"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 25TH AVE	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency		
SW 25TH AVE	Mahogany	11-15"	No	25'	Good (61% to 80%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 25TH AVE	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Trunk Damage - Major	Reduced Canopy - Major	Sprouting
SW 25TH AVE	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Major	Suppressed Canopy	Sprouting
SW 25TH AVE	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 25TH AVE	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 25TH AVE	Live Oak	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 25TH AVE	Black Olive	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sprouting
SW 25TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 25TH AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 25TH AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 25TH AVE	Mahogany	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 25TH AVE	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Sprouting
SW 25TH AVE	Black Olive	21-30"	No	65'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Dead Wood	Sprouting
SW 25TH AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Restricted Canopy	Suppressed Canopy	Sprouting
SW 25TH AVE	Golden Shower Tree	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 25TH AVE	Royal Poinciana	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Dead Wood	
SW 25TH AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Restricted Canopy
SW 25TH AVE	Live Oak	16-20"	No	50'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 25TH AVE	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 25TH AVE	Vera Wood	1-5"	No	10'	Good (61% to 80%)				
SW 25TH AVE	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				

(Continued on Next Page)

Street Tree Inventory

SW 25th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 25TH AVE	Pink Tabebuia	1-5"	No	5'	Good (61% to 80%)				
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Melaleuca	31-40"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 25TH AVE	Bottlebrush	21-30"	No	15'	Poor (21% to 40%)		Girdling Roots	Basal Co-Dominant	Reduced Canopy - Major
SW 25TH AVE	Bottlebrush	16-20"	No	15'	Fair (41% to 60%)		Basal Co-Dominant	Reduced Canopy - Moderate	Sprouting
SW 25TH AVE	Umbrella Tree	16-20"	No	15'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sprouting
SW 25TH AVE	Mahogany	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Major	Crown Density - Moderate	Dead Wood
SW 25TH AVE	Pink Tabebuia	31-40"	No	35'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 25TH AVE	Pink Tabebuia	31-40"	No	35'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 25TH AVE	Mahogany	31-40"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 25TH AVE	Longan	16-20"	No	30'	Good (61% to 80%)		Codominant Leaders/Included Bark	Sprouting	
SW 25TH AVE	Vera Wood	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Crown Density - Moderate	Dead Wood
SW 25TH AVE	Neem Tree	6-10"	No	25'	Good (61% to 80%)				
SW 25TH AVE	Washington Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Solitaire Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Silk Floss Tree	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Sea Grape	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Structure	Trunk Damage - Minor	Leaning - Moderate
SW 25TH AVE	Silver Buttonwood	1-5"	No	20'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 25TH AVE	Silver Buttonwood	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Leaning - Moderate	Dead Wood	
SW 25TH AVE	Silk Floss Tree	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 25TH AVE	Areca Palm	16-20"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH AVE	Japanese Blueberry	6-10"	No	15'	Good (61% to 80%)				
SW 25TH AVE	Bottle Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Frangipani	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Golden Trumpet	11-15"	No	20'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Structure	Sprouting	Dead Wood
SW 25TH AVE	Simpson's Stopper	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 25TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 25TH AVE	Podocarpus	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above	Pruned Into Shrub		
SW 25TH AVE	Live Oak	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 25TH AVE	Orange Geiger	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Dead Wood		
SW 25TH AVE	Live Oak	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 25TH AVE	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Suppressed Canopy	Dead Wood
SW 25TH AVE	Orange Tree	6-10"	No	15'	Good (61% to 80%)		Dead Wood		
SW 25TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Trunk Damage - Minor	
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 25TH AVE	Date Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		


Bordering Streets



Looking South - SW 25th Street



Looking South - SW 26th Avenue



Looking North - SW 26th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 26th Avenue	2	Silver Bluff	4	50	230	No	No	Yes	2	City	Yes	Yes	6	Yes	Yes	Yes	Grass swales. Room for on street parking

SW 26th Avenue

TYPOLOGY A

Street Tree Inventory

SW 26th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 26TH AVE	Sapodilla	6-10"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Sprouting
SW 26TH AVE	Coconut Palm	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 26TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Over Pruned	
SW 26TH AVE	Silver Buttonwood	1-5"	Yes	10'	Good (61% to 80%)		Pruned Into Shrub		
SW 26TH AVE	Silver Buttonwood	1-5"	Yes	5'	Good (61% to 80%)		Pruned Into Shrub		
SW 26TH AVE	Areca Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 26TH AVE	Areca Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency	Suppressed Canopy	
SW 26TH AVE	Areca Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Suppressed Canopy	
SW 26TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 26TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 26TH AVE	Narrow Leaf Ficus	1-5"	Yes	5'	Good (61% to 80%)				
SW 26TH AVE	Pink Poui Tabebuia	1-5"	No	20'	Poor (21% to 40%)		Root Damage/Decay	Codominant Leaders/No Included Bark	Trunk Damage - Moderate
SW 26TH AVE	Pink Poui Tabebuia	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts

Bordering Streets



Looking South - SW 22nd Street



Looking South - SW 22nd Terrace



Looking South - SW 22nd Street



Looking South - SW 23rd Terrace



Looking South - SW 24th Street



Looking North - US 1



Looking South - SW 26th Lane



Looking North - SW 28th Lane

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 17th Avenue	2	Silver Bluff	4	75	1800	No	No	Yes	5	County	Yes	Yes	0	Yes	Yes	West side and just north of 22nd Terr., 23rd St., 24th Terr.	Main street, share the road lanes. Intermittent trees and palms
SW 27th Avenue	2	Silver Bluff	4	100	3700	No	No	Yes	5	State	Yes	Yes	3	Yes	Yes	Crossing between 22nd street and 22nd Terr.., between SW 23rd Terr.. and 24th Street and at SW 25th Terr..	Main street, no bike lanes. Intermittent trees and palms

SW 17th Avenue

TYPOLOGY I

SW 27th Avenue

TYPOLOGY F

Street Tree Inventory

SW 17th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Queen Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Apical Dieback		
SW 17TH AVE	Queen Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Apical Dieback		

SW 27th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Reduced Canopy - Moderate	
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 27TH AVE	Florida Thatch Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Strap Constricting Tree	
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Minor		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Reduced Canopy - Minor	Nutrient Deficiency	Strap Constricting Tree
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 27TH AVE	Montgomery Palm	1-5"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 27TH AVE	Slash Pine	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Slash Pine	1-5"	No	5'	Poor (21% to 40%)		Strap Constricting Tree	Desiccated Foliage	
SW 27TH AVE	Live Oak	1-5"	No	15'	Fair (41% to 60%)		Girdling Roots	Codominant Leaders/No Included Bark	
SW 27TH AVE	Live Oak	6-10"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Florida Thatch Palm	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 27TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 27th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Live Oak	6-10"	No	20'	Fair (41% to 60%)		Girdling Roots	Dead Wood	
SW 27TH AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)		Dead Wood		
SW 27TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)		Girdling Roots	Dead Wood	
SW 27TH AVE	Live Oak	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Dead Wood		
SW 27TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)	Utility Lines Above	Dead Wood	Reduced Canopy - Minor	Sprouting
SW 27TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 27TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Dead Wood	Sprouting	
SW 27TH AVE	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 27TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)		Dead Wood		
SW 27TH AVE	Live Oak	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 27TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Dead Wood		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 27TH AVE	Tropical Almond	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Leaning - Moderate	



LATIN QUARTER

Streets



Looking West - SW 12th Avenue



Looking West - SW 15th Avenue



Looking West - SW 12th Avenue



Looking West - SW 15th Avenue




Looking East - SW 14th Avenue



Looking East - SW 17th Avenue



Looking East - SW 14th Avenue



Looking East - SW 17th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 2nd Street	1	Latin Quarter	3	50	2700	No	No	Yes	2	City	Yes	No	5	Yes	Yes	Mostly on South Side	One-Way West. Wide road at 12th street entrance. Dense canopy between 13th and 15th Avenue
SW 3rd Street	1	Latin Quarter	3	50	2700	No	No	Yes	2	City	Yes	Yes	5	Yes	Yes	Mostly on South Side	One-Way East. Significant amount of Green Button-woods between 14th and 17th Avenue.

SW 2nd Street

TYPOLOGY B

SW 3rd Street

TYPOLOGY B

Street Tree Inventory

SW 2nd Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 2ND ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency	Suppressed Canopy	
SW 2ND ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Moderate
SW 2ND ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 2ND ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Moderate	Cavities
SW 2ND ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 2ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Decay Observed
SW 2ND ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Black Olive	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 2ND ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 2ND ST	Black Olive	16-20"	No	25'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 2ND ST	Black Olive	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Cavities
SW 2ND ST	Black Olive	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 2ND ST	Black Olive	16-20"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Epicormic Growth
SW 2ND ST	Black Olive	16-20"	No	30'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Constricted Roots	Crown Density - Very Low	Decay Observed
SW 2ND ST	Black Olive	11-15"	No	35'	Dead (0% to 5%)	Utility Line Conflict			
SW 2ND ST	Black Olive	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Black Olive	21-30"	No	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Decay Observed	Trunk Damage - Major
SW 2ND ST	Black Olive	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 2ND ST	Cabbage Palm	16-20"	No	15'	Good (61% to 80%)	Utility Line Conflict	Ficus Growing on Tree		
SW 2ND ST	Cabbage Palm	16-20"	No	10'	Good (61% to 80%)	Utility Lines Above	Ficus Growing on Tree	Reduced Canopy - Moderate	
SW 2ND ST	Cabbage Palm	11-15"	No	5'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy	Constricted Roots	
SW 2ND ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy		
SW 2ND ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Restricted Canopy	Suppressed Canopy	
SW 2ND ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 2ND ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 2ND ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 2ND ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 2ND ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency	Tapered Trunk	
SW 2ND ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 2ND ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 2ND ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk		
SW 2ND ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 2ND ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate		
SW 2ND ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Suppressed Canopy	Trunk Damage - Moderate	
SW 2ND ST	Christmas Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 2ND ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 2ND ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 2ND ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Nutrient Deficiency	
SW 2ND ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 2ND ST	Frangipani	6-10"	Yes	10'	Poor (21% to 40%)		Constricted Roots	Decay Observed	Epicormic Growth
SW 2ND ST	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Green Buttonwood	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Epicormic Growth	Codominant Leaders - Multi
SW 2ND ST	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 2ND ST	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 2ND ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 2ND ST	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 2nd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 2ND ST	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Epicormic Growth
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Epicormic Growth
SW 2ND ST	Green Buttonwood	11-15"	Yes	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 2ND ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	6-10"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Girdling Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Leaning - Major
SW 2ND ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 2ND ST	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 2ND ST	Green Buttonwood	11-15"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Green Buttonwood	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 2ND ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Over Extended Limb(s)		
SW 2ND ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)		Over Extended Limb(s)		
SW 2ND ST	Gumbo Limbo	6-10"	No	15'	Good (61% to 80%)		Over Extended Limb(s)	Codominant Leaders - Multi	
SW 2ND ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)	Utility Line Conflict	Over Extended Limb(s)	Codominant Leaders - Multi	
SW 2ND ST	Live Oak	6-10"	No	20'	Dead (0% to 5%)		Reduced Canopy - Major	Codominant Leaders - Multi	
SW 2ND ST	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Codominant Leaders/Included Bark	
SW 2ND ST	Mahogany	6-10"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 2ND ST	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 2ND ST	Mahogany	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 2ND ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Mahogany	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 2ND ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Mahogany	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Mahogany	6-10"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Reduced Canopy - Major	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 2ND ST	Mahogany	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 2ND ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders - Multi	Reduced Canopy - Moderate
SW 2ND ST	Sapodilla	6-10"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	
SW 2ND ST	Sapodilla	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Umbrella Tree	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 2ND ST	Weeping Fig	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Lifting

Street Tree Inventory

SW 3rd Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 3RD ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 3RD ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders/Included Bark
SW 3RD ST	Black Olive	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Crown Density - Very Low	Decay Observed
SW 3RD ST	Black Olive	21-30"	No	35'	Very Poor/Critical (6% to 20%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 3RD ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 3RD ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Ficus Growing on Tree		
SW 3RD ST	Cabbage Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Ficus Growing on Tree	Trunk Damage - Moderate	
SW 3RD ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 3RD ST	Cabbage Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 3RD ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 3RD ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)		Restricted Canopy		
SW 3RD ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 3RD ST	Coconut Palm	11-15"	No	10'	Good (61% to 80%)				
SW 3RD ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)				
SW 3RD ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency	White Fly	
SW 3RD ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 3RD ST	Coconut Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Nutrient Deficiency	
SW 3RD ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Nutrient Deficiency	
SW 3RD ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Leaning - Moderate	
SW 3RD ST	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 3RD ST	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 3RD ST	Green Buttonwood	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Epicormic Growth	
SW 3RD ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Broken Branches
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 3RD ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Lifting
SW 3RD ST	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 3RD ST	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 3RD ST	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Decay Observed		
SW 3RD ST	Green Buttonwood	11-15"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Cracks in Trunk	Reduced Canopy - Major	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 3rd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Green Buttonwood	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Lopsided/Moderately Reduced Canopy
SW 3RD ST	Indian Laurel Fig	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 3RD ST	Indian Laurel Fig	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 3RD ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Cavities
SW 3RD ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 3RD ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 3RD ST	Mahogany	31-40"	No	35'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 3RD ST	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	
SW 3RD ST	Mahogany	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 3RD ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 3RD ST	Mahogany	11-15"	No	35'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 3RD ST	Mahogany	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 3RD ST	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Minor		
SW 3RD ST	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Limb Damage - Major	Codominant Leaders/Included Bark
SW 3RD ST	Oriental Arborvitae	11-15"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Trunk Damage - Moderate	
SW 3RD ST	Pigeon Plum	11-15"	Yes	15'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 3RD ST	Queen Crepe Myrtle	1-5"	No	5'	Poor (21% to 40%)		Strap Constricting Tree	Nutrient Deficiency	Apical Dieback
SW 3RD ST	Queen Crepe Myrtle	1-5"	No	Negligible	Dead (0% to 5%)				
SW 3RD ST	Queen Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Apical Dieback	Nutrient Deficiency	Dead Wood
SW 3RD ST	Queen Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Apical Dieback	Nutrient Deficiency	Dead Wood
SW 3RD ST	Royal Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 3RD ST	Royal Palm	6-10"	No	5'	Good (61% to 80%)				
SW 3RD ST	Sea Grape	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Lifting
SW 3RD ST	Strangler Fig	51-60"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 3RD ST	Strangler Fig	16-20"	Yes	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 3RD ST	Weeping Fig	6-10"	Yes	20'	Good (61% to 80%)	Utility Line Conflict	Codominant Leaders/Included Bark	Lifting	
SW 3RD ST	Weeping Fig	1-5"	Yes	5'	Fair (41% to 60%)	Utility Lines Above	Decay Observed		
SW 3RD ST	Weeping Fig	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 3RD ST	Weeping Fig	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Reduced Canopy - Moderate	Decay Observed

Streets



Looking West - SW 12th Avenue



Looking West - SW 15th Avenue



Looking West - SW 12th Avenue



Looking West - SW 15th Avenue



Looking East - SW 14th Avenue



Looking East - SW 17th Avenue



Looking East - SW 14th Avenue



Looking East - SW 17th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 4th Street	1	Latin Quarter	3	50	2700	No	No	Yes	2	City	Yes	Yes	5 (Except south side btw 12th and 14th Ave)	Yes	Yes	Mostly on South Side	One-Way West. Newly planted pigeon plums in poor condition (leaning) near 16th Ave intersection. Dense Canopy between 15th and 16th Avenue.
SW 5th Street	1	Latin Quarter	3	50	2700	No	No	Yes	2	City	Yes	No	5	Yes	Yes	Mostly on South Side	One-Way East. Canopy trees mostly at intersections. Mostly vegetated swales. Brick sidewlaks at 16th Avenue intersection.

SW 4th Street
TYPOLOGY B

SW 5th Street
TYPOLOGY B

Street Tree Inventory

SW 4th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 4TH ST	Areca Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 4TH ST	Cabbage Palm	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	Ficus Growing on Tree
SW 4TH ST	Cabbage Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 4TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH ST	Cabbage Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 4TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH ST	Cabbage Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 4TH ST	Cabbage Palm	6-10"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 4TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)	Utility Line Conflict	Ficus Growing on Tree		
SW 4TH ST	Carrotwood	1-5"	No	10'	Fair (41% to 60%)		Apical Dieback	Broken Branches	Dead Wood
SW 4TH ST	Carrotwood	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Restricted Canopy	Reduced Canopy - Moderate	
SW 4TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Moderate		
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 4TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Tapered Trunk	Nutrient Deficiency	
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)			Trunk Damage - Moderate	
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 4TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 4TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk		
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 4TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk		
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 4TH ST	Christmas Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk		
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 4TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 4TH ST	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Nutrient Deficiency	Tapered Trunk
SW 4TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Tapered Trunk		
SW 4TH ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Moderate	
SW 4TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 4TH ST	Dahoon Holly	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 4TH ST	Dahoon Holly	1-5"	No	10'	Fair (41% to 60%)		Leaning - Moderate	Codominant Leaders/Included Bark	
SW 4TH ST	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 4TH ST	Green Buttonwood	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 4TH ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Epicormic Growth
SW 4TH ST	Green Buttonwood	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Epicormic Growth	
SW 4TH ST	Green Buttonwood	6-10"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Strap Constricting Tree	Leaning - Moderate
SW 4TH ST	Green Buttonwood	6-10"	No	5'	Very Poor/Critical (6% to 20%)		Topped	Reduced Canopy - Major	Epicormic Growth
SW 4TH ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Strap Constricting Tree	Codominant Leaders/Included Bark
SW 4TH ST	Green Buttonwood	6-10"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Codominant Leaders/Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 4th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 4TH ST	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)		Reduced Canopy - Major	Trunk Damage - Moderate	Epicormic Growth
SW 4TH ST	Green Buttonwood	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Moderate	Epicormic Growth
SW 4TH ST	Green Buttonwood	6-10"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Topped	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 4TH ST	Green Buttonwood	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Reduced Canopy - Major	Stubs with Sprouts	Strap Constricting Tree
SW 4TH ST	Green Buttonwood	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Strap Constricting Tree	Codominant Leaders - Multi
SW 4TH ST	Green Buttonwood	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Epicormic Growth
SW 4TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 4TH ST	Mahogany	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 4TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 4TH ST	Mahogany	6-10"	No	15'	Fair (41% to 60%)		Suppressed Canopy	Lopsided/Moderately Reduced Canopy	
SW 4TH ST	Montgomery Palm	1-5"	No	5'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 4TH ST	Papaya Tree	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Restricted Canopy	Constricted Roots
SW 4TH ST	Pigeon Plum	1-5"	No	15'	Poor (21% to 40%)	Utility Lines Above	Leaning - Major	Strap Constricting Tree	Codominant Leaders - Multi
SW 4TH ST	Pigeon Plum	1-5"	No	15'	Poor (21% to 40%)	Utility Lines Above	Leaning - Major	Strap Constricting Tree	Codominant Leaders - Multi
SW 4TH ST	Pigeon Plum	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Strap Constricting Tree	Codominant Leaders/Included Bark
SW 4TH ST	Pigeon Plum	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 4TH ST	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Trunk Damage - Moderate	Strap Constricting Tree
SW 4TH ST	Pigeon Plum	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 4TH ST	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor		
SW 4TH ST	Queen Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 4TH ST	Royal Poinciana	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 4TH ST	Royal Poinciana	6-10"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Broken Branches
SW 4TH ST	Royal Poinciana	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Broken Branches	Stubs with Sprouts
SW 4TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 4TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders - Multi	Trunk Damage - Moderate	
SW 4TH ST	Silver Buttonwood	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders - Multi	Trunk Damage - Moderate	
SW 4TH ST	Silver Buttonwood	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Trunk Damage - Moderate	Strap Constricting Tree
SW 4TH ST	Silver Buttonwood	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders - Multi		
SW 4TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH ST	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 4TH ST	Solitaire Palm	1-5"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 4TH ST	Starburst Clerodendron	6-10"	No	5'	Good (61% to 80%)		Stubs with Sprouts		
SW 4TH ST	Unidentified Dead Tree (De	1-5"	No	Negligible	Dead (0% to 5%)				
SW 4TH ST	Unidentified Dead Tree (De	1-5"	No	Negligible	Dead (0% to 5%)				
SW 4TH ST	Unidentified Dead Tree (De	1-5"	No	Negligible	Dead (0% to 5%)				
SW 4TH ST	Washington Palm	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 4TH ST	Washington Palm	11-15"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate		
SW 4TH ST	Weeping Fig	1-5"	Yes	5'	Fair (41% to 60%)		Crown Density - Low	Codominant Leaders/Included Bark	
SW 4TH ST	Weeping Fig	1-5"	No	Negligible	Dead (0% to 5%)				
SW 4TH ST	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Pruned Into Shrub	
SW 4TH ST	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Pruned Into Shrub	

Street Tree Inventory

SW 5th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH ST	Ackee Tree	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark		
SW 5TH ST	Black Olive	21-30"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Decay Observed	Dead Wood
SW 5TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 5TH ST	Black Olive	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 5TH ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Codominant Leaders/Included Bark
SW 5TH ST	Black Olive	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 5TH ST	Black Olive	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Codominant Leaders - Multi
SW 5TH ST	Black Olive	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 5TH ST	Black Olive	31-40"	No	60'	Poor (21% to 40%)		Constricted Roots	Codominant Leaders/Included Bark	Decay Observed
SW 5TH ST	Black Olive	31-40"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 5TH ST	Black Olive	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 5TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	Yes	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)		Restricted Canopy		
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	6-10"	No	5'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 5TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 5TH ST	Christmas Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 5TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Tapered Trunk		
SW 5TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Christmas Palm	6-10"	No	5'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 5TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 5TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy		
SW 5TH ST	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 5TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 5TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Line Conflict			
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Nutrient Deficiency	
SW 5TH ST	Coconut Palm	11-15"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 5TH ST	Coconut Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 5TH ST	Coconut Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 5TH ST	Coconut Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 5TH ST	Coconut Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 5TH ST	Coconut Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 5TH ST	Coconut Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 5TH ST	Coconut Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 5TH ST	Coconut Palm	1-5"	Yes	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 5TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 5th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy	Nutrient Deficiency	
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy	Nutrient Deficiency	
SW 5TH ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy	Nutrient Deficiency	
SW 5TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk	Broken Branches	Reduced Canopy - Moderate
SW 5TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Broken Branches	
SW 5TH ST	Hong Kong Orchid	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 5TH ST	Live Oak	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Trunk Damage - Major	Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 5TH ST	Live Oak	6-10"	No	15'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 5TH ST	Live Oak	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Lifting
SW 5TH ST	Live Oak	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 5TH ST	Live Oak	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 5TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Lopsided/Significantly Reduced Canopy
SW 5TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 5TH ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 5TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)				
SW 5TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Montgomery Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 5TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Montgomery Palm	6-10"	Yes	15'	Good (61% to 80%)				
SW 5TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 5TH ST	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 5TH ST	Pongam	21-30"	Yes	35'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 5TH ST	Pongam	16-20"	No	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Cavities	Dead Wood	Root Damage/Decay
SW 5TH ST	Pongam	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 5TH ST	Pongam	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Lopsided/Significantly Reduced Canopy
SW 5TH ST	Queen Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 5TH ST	Queen Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Nutrient Deficiency	
SW 5TH ST	Royal Poinciana	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 5TH ST	Sandbox Tree	21-30"	No	40'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Decay Observed	Reduced Canopy - Major
SW 5TH ST	Sandbox Tree	31-40"	Yes	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 5TH ST	Sea Grape	31-40"	Yes	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 5TH ST	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Codominant Leaders/Included Bark	Leaning - Moderate
SW 5TH ST	Silver Buttonwood	1-5"	No	10'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Codominant Leaders/Included Bark	
SW 5TH ST	Solitaire Palm	1-5"	Yes	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Spanish Lime	1-5"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 5TH ST	Strangler Fig	21-30"	Yes	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots		
SW 5TH ST	Umbrella Tree	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Leaning - Moderate	
SW 5TH ST	Umbrella Tree	11-15"	Yes	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Decay Observed	Trunk Damage - Major
SW 5TH ST	Umbrella Tree	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Restricted Canopy	Constricted Roots	Stubs with Sprouts
SW 5TH ST	Washington Palm	11-15"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 5TH ST	Weeping Fig	11-15"	Yes	20'	Fair (41% to 60%)	Utility Line Conflict	Decay Observed	Stubs with Sprouts	Crown Density - Moderate

Streets



Looking West - SW 12th Avenue



Looking West - SW 15th Avenue



Looking West - SW 12th Avenue



Looking West - SW 15th Avenue



Looking East - SW 14th Avenue



Looking East - SW 17th Avenue



Looking East - SW 14th Avenue



Looking East - SW 17th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 6th Street	1	Latin Quarter	3	50	2700	No	No	Yes	2	City	No	No	0	Yes	Yes	Both Sides	One-Way West. Brick Sidewalks on both sides. Share the lane bike markings on Northern side.
SW 7th Street	1	Latin Quarter	3	50	2700	No	No	No	3	State	No	No	0	Yes	Yes	Both Sides, Mostly North	One-Way West. Brick Sidewalks on both sides. Except for 17th and 12th Avenue, lacking pedestrian crosswalks going North-South.

SW 6th Street

TYPOLOGY D

SW 7th Street

TYPOLOGY E

Street Tree Inventory

SW 6th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 6TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 6TH ST	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Cavities
SW 6TH ST	Pongam	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 6TH ST	Sapodilla	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Apical Dieback	Codominant Leaders/Included Bark

SW 7th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 7TH ST	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)		Pruned Into Shrub	Strap Constricting Tree	
SW 7TH ST	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)		Pruned Into Shrub	Strap Constricting Tree	

Streets



Looking North - SW 8th Street



Looking North - SW 4th Street



Looking North - SW 8th Street



Looking North - SW 4th Street



Looking South - SW 5th Street



Looking South - SW 1st Street



Looking South - SW 5th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale	Curbs	Sidewalks	Overhead Utilities	Notes
SW 13th Avenue	1	Latin Quarter	3	50	2400	No	No	Yes	2	City	No	Yes	2 (N of 5th St)	Yes	Yes	Mostly on West Side	One-Way North. Brick Sidewalks from 5th to 8th St. Swales too narrow for Street Trees.
SW 14th Avenue	1	Latin Quarter	3	50	2400	No	No	Yes	2	City	Yes	Few	5 (N of 5th St)	Yes	Yes	Both Side	One-Way South. Brick Sidewalks from 5th to 8th St. Trees planted in curb cutouts south of 5th street, lifting up brick paving.

SW 13th Avenue

TYPOLOGY B & D

SW 14th Avenue

TYPOLOGY B & D

Street Tree Inventory

SW 13th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 13TH AVE	Black Olive	21-30"	No	55'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts
SW 13TH AVE	Black Olive	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts
SW 13TH AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Codominant Leaders - Multi
SW 13TH AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 13TH AVE	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Dead Wood
SW 13TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Decay Observed	Codominant Leaders/Included Bark
SW 13TH AVE	Black Olive	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Decay Observed	Codominant Leaders/Included Bark
SW 13TH AVE	Brazilian Beauty Leaf	16-20"	No	40'	Fair (41% to 60%)		Girdling Roots	Leaning - Moderate	Codominant Leaders - Multi
SW 13TH AVE	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)		Suppressed Canopy		
SW 13TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Christmas Palm	6-10"	Yes	15'	Fair (41% to 60%)		Restricted Canopy	Trunk Damage - Moderate	
SW 13TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)		Damaged Fronds	Trunk Damage - Moderate	
SW 13TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 13TH AVE	Christmas Palm	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Leaning - Moderate	Codominant Leaders/Included Bark
SW 13TH AVE	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Restricted Canopy	Trunk Damage - Moderate	
SW 13TH AVE	Green Buttonwood	6-10"	No	15'	Good (61% to 80%)				
SW 13TH AVE	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)				
SW 13TH AVE	Live Oak	1-5"	No	15'	Good (61% to 80%)				
SW 13TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 13TH AVE	Mahogany	1-5"	No	15'	Good (61% to 80%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 13TH AVE	Pongam	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Stubs with Sprouts
SW 13TH AVE	Pongam	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Decay Observed	Codominant Leaders - Multi
SW 13TH AVE	Pongam	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Decay Observed	Codominant Leaders/Included Bark
SW 13TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Leaning - Moderate	
SW 13TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders/No Included Bark	Leaning - Moderate	
SW 13TH AVE	Silver Buttonwood	1-5"	No	15'	Good (61% to 80%)		Codominant Leaders - Multi		
SW 13TH AVE	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		

SW 14th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 14TH AVE	Black Olive	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 14TH AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 14TH AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 14TH AVE	Black Olive	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 14TH AVE	Black Olive	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Codominant Leaders - Multi
SW 14TH AVE	Black Olive	11-15"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Cavities
SW 14TH AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Over Pruned	Epicormic Growth
SW 14TH AVE	Black Olive	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Over Pruned	Epicormic Growth
SW 14TH AVE	Calabash Tree	11-15"	Yes	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts
SW 14TH AVE	Carrotwood	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lifting	Codominant Leaders/Included Bark
SW 14TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory


SW 14th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 14TH AVE	Christmas Palm	6-10"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Moderate		
SW 14TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 14TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 14TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 14TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Leaning - Moderate	Tapered Trunk	Nutrient Deficiency
SW 14TH AVE	Coconut Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 14TH AVE	Coconut Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Lines Above	Damaged Fronds	Nutrient Deficiency	Leaning - Moderate
SW 14TH AVE	Crepe Myrtle	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 14TH AVE	Florida Privet	11-15"	Yes	15'	Fair (41% to 60%)		Topped	Stubs with Sprouts	Dead Wood
SW 14TH AVE	Glaucous Cassia	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Trunk Damage - Moderate	Reduced Canopy - Moderate	Stubs with Sprouts
SW 14TH AVE	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Epicormic Growth
SW 14TH AVE	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 14TH AVE	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lifting	Codominant Leaders - Multi
SW 14TH AVE	Green Buttonwood	16-20"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 14TH AVE	Green Buttonwood	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lifting	Codominant Leaders - Multi
SW 14TH AVE	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lifting	Codominant Leaders - Multi
SW 14TH AVE	Green Buttonwood	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 14TH AVE	Gumbo Limbo	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 14TH AVE	Live Oak	21-30"	Yes	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Sloughing Bark	Reduced Canopy - Moderate
SW 14TH AVE	Live Oak	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders/Included Bark
SW 14TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 14TH AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Leaning - Moderate	Decay Observed
SW 14TH AVE	Mahogany	11-15"	No	20'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Trunk Damage - Major	Crown Density - Moderate
SW 14TH AVE	Peregrina	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 14TH AVE	Peregrina	6-10"	Yes	10'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Moderate		
SW 14TH AVE	Pigeon Plum	16-20"	Yes	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Topped	Codominant Leaders - Multi
SW 14TH AVE	Pink Tabebuia	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 14TH AVE	Pongam	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 14TH AVE	Pongam	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 14TH AVE	Pongam	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Cavities	Stubs with Sprouts

Streets



Looking North - SW 8th Street



Looking North - SW 4th Street




Looking North - SW 8th Street



Looking North - SW 4th Street



Looking South - SW 5th Street



Looking South - SW 1st Street



Looking South - SW 5th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 15th Avenue	1	Latin Quarter	3	50	2400	No	No	Yes	2	City	Some	Few	5 (N of 5th St)	Yes	Yes	Mostly on West Side	One-Way North. Brick Sidewalks from 5th to 8th St. Trees planted in curb cutouts south of 5th street, lifting up brick paving. Closed to car traffic between 7th and 9th street for pedestrain plaza
SW 16th Avenue	1	Latin Quarter	3	50	2400	No	No	Yes	2	City	Few	No	0	Yes	Yes	Mostly on West Side	One-Way South. Brick Sidewalks from 5th to 8th St. Wide Road brings lots of car traffic avoiding 17th Avenue.

SW 15th Avenue

TYPOLOGY B & D

SW 16th Avenue

TYPOLOGY D

Street Tree Inventory

SW 15th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 15TH AVE	Areca Palm	6-10"	Yes	5'	Very Poor/Critical (6% to 20%)		Discolored Foliage	Apical Dieback	Reduced Canopy - Major
SW 15TH AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Cavities	
SW 15TH AVE	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Lifting	Codominant Leaders - Multi
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 15TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 15TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 15TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Leaning - Moderate		
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Leaning - Moderate		
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Line Conflict	Leaning - Moderate	Trunk Damage - Moderate	
SW 15TH AVE	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk	Trunk Damage - Moderate	
SW 15TH AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Tapered Trunk	Leaning - Moderate	Nutrient Deficiency
SW 15TH AVE	Date Palm	16-20"	No	20'	Good (61% to 80%)				
SW 15TH AVE	Date Palm	16-20"	No	20'	Good (61% to 80%)				
SW 15TH AVE	Frangipani	1-5"	No	5'	Good (61% to 80%)		Leaning - Moderate	Strap Constricting Tree	
SW 15TH AVE	Green Buttonwood	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 15TH AVE	Green Buttonwood	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Minor	Codominant Leaders/Included Bark
SW 15TH AVE	Gumbo Limbo	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 15TH AVE	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Topped	Stubs with Sprouts
SW 15TH AVE	Live Oak	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders - Multi
SW 15TH AVE	Live Oak	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Lion's Tailing
SW 15TH AVE	Live Oak	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 15TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 15TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Lifting
SW 15TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lifting	Codominant Leaders/Included Bark
SW 15TH AVE	Mahogany	51-60"	No	60'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Codominant Leaders - Multi
SW 15TH AVE	Mahogany	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Discolored Foliage
SW 15TH AVE	Mahogany	31-40"	No	45'	Very Poor/Critical (6% to 20%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 15TH AVE	Mahogany	16-20"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 15TH AVE	Mahogany	31-40"	No	50'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 15TH AVE	Mahogany	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 15TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Codominant Leaders - Multi
SW 15TH AVE	Mahogany	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH AVE	Mango	11-15"	No	55'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 15TH AVE	Norfolk Pine	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Suppressed Canopy	Lifting
SW 15TH AVE	Orange Geiger	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Leaning - Moderate		
SW 15TH AVE	Papaya Tree	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Above	Decay Observed	Dead Wood	Codominant Leaders/Included Bark
SW 15TH AVE	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Lifting	Stubs with Sprouts
SW 15TH AVE	Pongam	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders - Multi	Stubs with Sprouts
SW 15TH AVE	Tropical Almond	6-10"	No	25'	Fair (41% to 60%)		Leader - Broken	Codominant Leaders/No Included Bark	Over Extended Limb(s)
SW 15TH AVE	Umbrella Tree	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	
SW 15TH AVE	Unidentified Dead Tree (De	1-5"	No	Negligible	Dead (0% to 5%)				
SW 15TH AVE	Weeping Fig	6-10"	Yes	15'	Fair (41% to 60%)		Topped	Stubs with Sprouts	Reduced Canopy - Moderate
SW 15TH AVE	Weeping Fig	6-10"	Yes	15'	Fair (41% to 60%)		Topped	Stubs with Sprouts	Reduced Canopy - Moderate

(Continued on Next Page)

Street Tree Inventory

SW 16th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 16TH AVE	Black Olive	21-30"	No	50'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 16TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Reduced Canopy - Moderate
SW 16TH AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 16TH AVE	Black Olive	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders - Multi
SW 16TH AVE	Mahogany	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major
SW 16TH AVE	Mahogany	16-20"	No	35'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Moderate
SW 16TH AVE	Papaya	1-5"	Yes	5'	Good (61% to 80%)		Suppressed Canopy		
SW 16TH AVE	Pongam	11-15"	No	10'	Very Poor/Critical (6% to 20%)		Topped	Decay Observed	Epicormic Growth
SW 16TH AVE	Pongam	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Cavities	Reduced Canopy - Moderate
SW 16TH AVE	Pongam	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Cavities	Reduced Canopy - Moderate

Streets



Looking West - SW 12th Avenue




Looking West - SW 15th Avenue



Looking West - SW 12th Avenue




Looking West - SW 15th Avenue



Looking East - SW 14th Avenue



Looking East - SW 17th Avenue



Looking East - SW 14th Avenue



Looking East - SW 17th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 1st Street	1	Latin Quarter	3	60	2700	No	No	Yes	3	State	Some	Some	0	Yes	Yes	Mostly on South Side	One-Way East. Share the lane bike markings along southern lane. Crosswalks immediately West of 15th and 14th Avenue intersections.
SW 8th Street	1	Latin Quarter	3	70	2700	No	No	Yes	3	State	Some	Few	0	Yes	Yes	No	One-Way East. Brick sidewalks on both sides. Cross-walks immediately West of 16th, 15th, and 13th Avenues.

SW 1st Street
TYPOLOGY D

SW 8th Street
TYPOLOGY D

Street Tree Inventory

SW 1st Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 1ST ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 1ST ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 1ST ST	Royal Palm	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency	Tapered Trunk	
SW 1ST ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 1ST ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 1ST ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	Royal Palm	6-10"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 1ST ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 1ST ST	Royal Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			

SW 8th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 8TH ST	Black Olive	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 8TH ST	Live Oak	6-10"	No	15'	Good (61% to 80%)		Stubs		
SW 8TH ST	Live Oak	1-5"	No	5'	Good (61% to 80%)		Improperly Mulched	Strap Constricting Tree	
SW 8TH ST	Live Oak	6-10"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Epicormic Growth	
SW 8TH ST	Live Oak	6-10"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate	Leaning - Minor	Codominant Leaders/Included Bark
SW 8TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)		Leader - Bent	Codominant Leaders/Included Bark	
SW 8TH ST	Mahogany	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Lopsided/Significantly Reduced Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 8TH ST	Montgomery Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Discolored Foliage	Reduced Canopy - Moderate	Improperly Mulched
SW 8TH ST	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Discolored Foliage	Reduced Canopy - Moderate	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Discolored Foliage	Reduced Canopy - Moderate	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Discolored Foliage	Reduced Canopy - Moderate	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Discolored Foliage	Reduced Canopy - Moderate	
SW 8TH ST	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Discolored Foliage	Reduced Canopy - Moderate	
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Discolored Foliage	Reduced Canopy - Moderate	
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Discolored Foliage	Tapered Trunk	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Discolored Foliage	Tapered Trunk	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Discolored Foliage	Trunk Damage - Moderate	
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Discolored Foliage	Reduced Canopy - Moderate	Discolored Foliage
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 8th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 8TH ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)		Reduced Canopy - Moderate	Discolored Foliage	Tapered Trunk
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Tapered Trunk	Discolored Foliage	Reduced Canopy - Moderate
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Damaged Fronds	
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Tapered Trunk	Strap Constricting Tree	
SW 8TH ST	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Tapered Trunk	Strap Constricting Tree	Discolored Foliage
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		

Streets



Looking North - SW 8th Street



Looking North - SW 4th Street



Looking North - SW 8th Street



Looking North - SW 4th Street



Looking South - SW 5th Street



Looking South - SW 1st Street



Looking South- SW 5th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 12th Avenue	1	Latin Quarter	3	80	2400	No	No	Yes	4	State	Some	Yes	0	Yes	Yes	No	Pedestrian crosswalk between 2nd and 3rd Street. Possible opportunities for vegetated curb extensions where parking is prohibited.
SW 17th Avenue	1	Latin Quarter	3	70	2400	Yes	No	No	4	County	Median	No	0	Yes	Yes	Mostly on West Side	Brick Sidewalks along both sides. Crosswalk at 3rd Street with median along both sides. New tree plantings in Median. Share the lane bike markings along both sides.

SW 12th Avenue

TYPOLOGY D

SW 17th Avenue

TYPOLOGY I & E

Street Tree Inventory

SW 12th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 12TH AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 12TH AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 12TH AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 12TH AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Restricted Canopy
SW 12TH AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Restricted Canopy
SW 12TH AVE	Black Olive	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Major	Stubs with Sprouts	Dead Wood
SW 12TH AVE	Cabbage Palm	6-10"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Desiccated Foliage	Ficus Growing on Tree
SW 12TH AVE	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH AVE	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH AVE	Cabbage Palm	6-10"	No	15'	Fair (41% to 60%)		Desiccated Foliage	Reduced Canopy - Moderate	
SW 12TH AVE	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency	White Fly	
SW 12TH AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 12TH AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 12TH AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 12TH AVE	Date Palm	6-10"	No	15'	Good (61% to 80%)				
SW 12TH AVE	Date Palm	11-15"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Gumbo Limbo	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Broken Branches	Reduced Canopy - Moderate
SW 12TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Spanish Lime	11-15"	No	20'	Fair (41% to 60%)		Lopsided/Significantly Reduced Canopy	Restricted Canopy	Codominant Leaders/Included Bark
SW 12TH AVE	Woman's Tongue	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Woman's Tongue	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Woman's Tongue	1-5"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Woman's Tongue	1-5"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate	Apical Dieback	Damaged Fronds
SW 12TH AVE	Woman's Tongue	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Woman's Tongue	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Woman's Tongue	1-5"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Woman's Tongue	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Woman's Tongue	1-5"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Woman's Tongue	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Woman's Tongue	1-5"	No	10'	Good (61% to 80%)		Basal Co-Dominant	Leader - Broken	
SW 12TH AVE	Woman's Tongue	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		

SW 17th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 17TH AVE	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Fungus on Leaves		
SW 17TH AVE	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH AVE	Gumbo Limbo	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Leaning - Moderate	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Uprooted - Mostly	Trunk Damage - Moderate	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Uprooted - Mostly	Leaning - Major	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree	Trunk Damage - Moderate	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Very Poor/Critical (6% to 20%)		Uprooted - Mostly	Leaning - Major	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Uprooted - Partially	Leaning - Moderate	Strap Constricting Tree
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Leaning - Moderate	Strap Constricting Tree	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate	Trunk Damage - Moderate	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Partially	Crown Density - Low	Strap Constricting Tree
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate		

(Continued on Next Page)

Street Tree Inventory

SW 17th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Poor (21% to 40%)		Uprooted - Partially	Leaning - Moderate	Strap Constricting Tree
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Strap Constricting Tree	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Fair (41% to 60%)		Strap Constricting Tree	Codominant Leaders/Included Bark	
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Fair (41% to 60%)		Leaning - Moderate		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Codominant Leaders/Included Bark	Strap Constricting Tree	Leaning - Minor
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		



EAST LITTLE HAVANA

Streets



Looking West - SW 4th Avenue



Looking West - SW 8th Avenue



Looking West - SW 4th Avenue



Looking West - SW 8th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 2nd Street	1	East Little Havana	3	50 / 70 btw 6 and 8 ave	4500	No	No	Yes	2	City	Some	No	0	Yes	Yes	Mostly on South Side	Dense canopy of Mahogany between 9th and 10th avenue, no valley gutters on this block. Vegetated curb extensions at intersections and some center of blocks.
SW 3rd Street	1	East Little Havana	3	50	4500	No	No	Yes	2	City	Few	No	0	Yes	Yes	Mostly on South Side	Street slopes down significanlty at 11th avenue intersection. Valley gutters on both sides.

SW 2nd Street
TYPOLOGY D

SW 3rd Street
TYPOLOGY D

Street Tree Inventory

SW 2nd Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 2ND ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 2ND ST	Areca Palm	11-15"	Yes	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 2ND ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Trunk Damage - Minor
SW 2ND ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 2ND ST	Cabbage Palm	1-5"	No	5'	Good (61% to 80%)		Suppressed Canopy		
SW 2ND ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Restricted Canopy		
SW 2ND ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency	Restricted Canopy	
SW 2ND ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Damaged Fronds	Restricted Canopy	
SW 2ND ST	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Damaged Fronds	Restricted Canopy	
SW 2ND ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)				
SW 2ND ST	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Damaged Fronds		
SW 2ND ST	Dahoon Holly	1-5"	No	5'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Crown Density - Low	Dead Wood	Trunk Damage - Minor
SW 2ND ST	Eucalyptus	41-50"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Limb Damage - Minor
SW 2ND ST	Mahogany	31-40"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 2ND ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Mahogany	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 2ND ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders - Multi
SW 2ND ST	Mahogany	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 2ND ST	Mahogany	21-30"	No	55'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Dead Wood
SW 2ND ST	Mahogany	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 2ND ST	Mahogany	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Reduced Canopy - Moderate
SW 2ND ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)		Constricted Roots	Crown Density - Low	Dead Wood
SW 2ND ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Crown Density - Low	Dead Wood
SW 2ND ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Mahogany	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major
SW 2ND ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 2ND ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 2ND ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 2ND ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Crown Density - Low	Dead Wood
SW 2ND ST	Mahogany	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major
SW 2ND ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 2ND ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Discolored Foliage
SW 2ND ST	Mahogany	21-30"	No	55'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Major	Codominant Leaders/Included Bark
SW 2ND ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Leaning - Moderate	Decay Observed
SW 2ND ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Lion's Tailing
SW 2ND ST	Mahogany	16-20"	No	30'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 2ND ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 2ND ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 2ND ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders - Multi
SW 2ND ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 2ND ST	Mahogany	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 2ND ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 2ND ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Decay Observed
SW 2ND ST	Mahogany	16-20"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Leaning - Moderate	Codominant Leaders - Multi
SW 2ND ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Codominant Leaders - Multi	Decay Observed
SW 2ND ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 2ND ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 2ND ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 2ND ST	Mahogany	31-40"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 2ND ST	Mahogany	51-60"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 2ND ST	Mahogany	1-5"	No	15'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor	Dead Wood	
SW 2ND ST	Pongam	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 2nd Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 2ND ST	Pongam	16-20"	No	35'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 2ND ST	Pongam	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Codominant Leaders/No Included Bark
SW 2ND ST	Royal Poinciana	11-15"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots		
SW 2ND ST	Sapodilla	41-50"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 2ND ST	Sapodilla	41-50"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 2ND ST	Triangle Palm	11-15"	No	10'	Fair (41% to 60%)		Damaged Fronds	Nutrient Deficiency	
SW 2ND ST	Unidentified Dead Tree (	1-5"	No	Negligible	Dead (0% to 5%)				
SW 2ND ST	Washington Palm	11-15"	No	15'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Trunk Damage - Moderate		
SW 2ND ST	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 2ND ST	Weeping Fig	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Multi-Trunk Form - Not Downgraded for Str	Restricted Canopy	
SW 2ND ST	Weeping Fig	1-5"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Restricted Canopy		

SW 3rd Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 3RD ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 3RD ST	Black Olive	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 3RD ST	Black Olive	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 3RD ST	Christmas Palm	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 3RD ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Trunk Damage - Minor	Nutrient Deficiency	
SW 3RD ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 3RD ST	Gumbo Limbo	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lifting	Reduced Canopy - Moderate
SW 3RD ST	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	
SW 3RD ST	Hong Kong Orchid	16-20"	No	20'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 3RD ST	Live Oak	21-30"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Broken Branches
SW 3RD ST	Live Oak	6-10"	No	30'	Good (61% to 80%)	Utility Lines Above	Limb Damage - Minor	Dead Wood	
SW 3RD ST	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Minor	Sprouting	
SW 3RD ST	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 3RD ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 3RD ST	Mahogany	51-60"	No	65'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 3RD ST	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 3RD ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 3RD ST	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 3RD ST	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Reduced Canopy - Moderate	Decay Observed	Lifting
SW 3RD ST	Pink Tabebuia	11-15"	No	20'	Fair (41% to 60%)		Restricted Canopy	Decay Observed	Lifting
SW 3RD ST	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Decay Observed	Lifting
SW 3RD ST	Pink Tabebuia	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Lifting	Decay Observed
SW 3RD ST	Pongam	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 3RD ST	Pongam	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Leaning - Major	Dead Wood
SW 3RD ST	Pongam	6-10"	No	20'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Reduced Canopy - Major	Sprouting
SW 3RD ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Damaged Fronds		
SW 3RD ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 3RD ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict			

Streets



Looking West - SW 4th Avenue



Looking West - SW 8th Avenue



Looking West - SW 4th Avenue



Looking West - SW 8th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 4th Street	1	East Little Havana	3	50	4500	No	No	Yes	2	City	Some	Few	0	Yes	Yes	Mostly on South Side	One Way - West. Street slopes down significantly going east at 7th Avenue. Valley gutters on both sides. Vegetated curb extensions at intersections and some center of blocks
SW 5th Street	1	East Little Havana	3	50	4500	No	No	Yes	2	City	Few	No	0	Yes	Yes	Mostly on South Side	One Way - East. Vegetated Curb extentions at Intersections and some center of blocks. Valley gutters along both sides.

SW 4th Street
TYPOLOGY D

SW 5th Street
TYPOLOGY D

Street Tree Inventory

SW 4th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 4TH ST	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 4TH ST	Black Olive	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 4TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 4TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Tapered Trunk	
SW 4TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 4TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 4TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 4TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 4TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)	Utility Lines Above	Reduced Canopy - Major	Lifting	Constricted Roots
SW 4TH ST	Live Oak	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Sprouting	Dead Wood
SW 4TH ST	Live Oak	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 4TH ST	Live Oak	6-10"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Suppressed Canopy	Restricted Canopy	Sprouting
SW 4TH ST	Live Oak	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 4TH ST	Mahogany	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 4TH ST	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 4TH ST	Mahogany	21-30"	No	55'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 4TH ST	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Restricted Canopy	Lifting	Codominant Leaders/Included Bark
SW 4TH ST	Mahogany	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders - Multi	Reduced Canopy - Moderate
SW 4TH ST	Mahogany	21-30"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Lion's Tailing
SW 4TH ST	Mahogany	16-20"	No	55'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 4TH ST	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Lion's Tailing
SW 4TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 4TH ST	Mahogany	16-20"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Cavities
SW 4TH ST	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 4TH ST	Mahogany	16-20"	No	45'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 4TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 4TH ST	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Moderate
SW 4TH ST	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 4TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict	Nutrient Deficiency		
SW 4TH ST	Pigeon Plum	6-10"	No	20'	Fair (41% to 60%)		Leader - Broken	Codominant Leaders/Included Bark	
SW 4TH ST	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Insect Damage Leaves	Reduced Canopy - Minor	Sprouting
SW 4TH ST	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Leader - Broken	Dead Wood
SW 4TH ST	Pongam	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 4TH ST	Pongam	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Sprouting
SW 4TH ST	Spanish Lime	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Insect Damage Leaves	Dead Wood	Multi-Trunk Form - Not Downgraded for Structure
SW 4TH ST	Washington Palm	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 4TH ST	Washington Palm	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 4TH ST	Weeping Fig	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting

SW 5th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 5TH ST	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 5TH ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 5TH ST	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 5TH ST	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 5TH ST	Black Olive	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 5TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 5TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Trunk Damage - Moderate	Reduced Canopy - Major	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 5th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH ST	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 5TH ST	Live Oak	31-40"	No	55'	Very Poor/Critical (6% to 20%)		Constricted Roots	Dead Wood	Decay Observed
SW 5TH ST	Live Oak	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Reduced Canopy - Minor	Sprouting	Dead Wood
SW 5TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Minor	Sprouting	Dead Wood
SW 5TH ST	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 5TH ST	Mahogany	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 5TH ST	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 5TH ST	Mahogany	31-40"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 5TH ST	Orange Geiger	1-5"	No	10'	Fair (41% to 60%)		Topped	Epicormic Growth	
SW 5TH ST	Orange Geiger	1-5"	No	10'	Good (61% to 80%)				
SW 5TH ST	Pink Tabebuia	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Lifting
SW 5TH ST	Pink Tabebuia	16-20"	No	10'	Poor (21% to 40%)		Topped	Stubs with Sprouts	
SW 5TH ST	Pink Tabebuia	11-15"	No	15'	Poor (21% to 40%)		Trunk Damage - Major	Lifting	Dead Wood
SW 5TH ST	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Lifting	Dead Wood
SW 5TH ST	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate	Apical Dieback	
SW 5TH ST	Pink Tabebuia	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Lifting
SW 5TH ST	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Dead Wood	Lifting
SW 5TH ST	Pongam	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 5TH ST	Pongam	11-15"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate	Reduced Canopy - Minor	Sprouting
SW 5TH ST	Strangler Fig	60+"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major

Streets



Looking West - SW 4th Avenue



Looking West - SW 8th Avenue



Looking West - SW 4th Avenue



Looking West - SW 8th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 6th Street	1	East Little Havana	3	50	4500	No	No	Yes	2	City	No	No	0	Yes	Yes	Mostly on South Side	One Way - West. No street trees. Share the lane bike markings.
SW 7th Street	1	East Little Havana	3	50	4500	No	No	No	3	State	Few	Few	0	Yes	Yes	Mostly on North Side	One Way - West. No Street Trees. Not pedestrian friendly.

SW 6th Street

TYPOLOGY D

SW 7th Street

TYPOLOGY E

Street Tree Inventory

*Note there are no trees on SW 6th Street or SW 7th Street

Streets



Looking West - SW 4th Avenue



Looking West - SW 8th Avenue



Looking West - SW 4th Avenue



Looking West - SW 8th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 8th Street	1	East Little Havana	3	70	4500	No	No	Yes	3	State	Yes	Some	0	Yes	Yes	None	One Way - East. Crosswalks after 10th ave, 6th Ave and before 9th Ct, 7th Ave. Sidewalk cutouts for trees along both sides.
SW 9th Street	1	East Little Havana	3	50	4500	No	No	Yes	2	City	Some	Few	0	Few	Yes	Mostly on North Side	Street slopes down significantly going east at 11th Avenue intersection. Vegetated curb extensions at intersections and some centers of blocks. Valley gutters along both sides.

SW 8th Street

TYPOLOGY D

SW 9th Street

TYPOLOGY D

Street Tree Inventory

SW 8th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders - Multi
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Crown Density - Moderate
SW 8TH ST	Black Olive	16-20"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Major
SW 8TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Crown Density - Moderate
SW 8TH ST	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders - Multi
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lifting	Trunk Damage - Moderate
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Crown Density - Moderate
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders - Multi
SW 8TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 8TH ST	Black Olive	11-15"	No	45'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Codominant Leaders - Multi
SW 8TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Crown Density - Low
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Lopsided/Moderately Reduced Canopy
SW 8TH ST	Black Olive	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Major	Lifting
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders - Multi
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders - Multi
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Cavities	Crown Density - Low
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders - Multi	Dead Wood
SW 8TH ST	Black Olive	16-20"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Lifting
SW 8TH ST	Black Olive	16-20"	No	45'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders/Included Bark
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Lifting
SW 8TH ST	Black Olive	16-20"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 8TH ST	Black Olive	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 8TH ST	Black Olive	16-20"	No	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 8TH ST	Black Olive	16-20"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 8TH ST	Black Olive	6-10"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 8TH ST	Black Olive	6-10"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 8TH ST	Black Olive	11-15"	No	30'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 8TH ST	Black Olive	6-10"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 8TH ST	Black Olive	11-15"	No	25'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 8TH ST	Black Olive	6-10"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Reduced Canopy - Moderate
SW 8TH ST	Black Olive	6-10"	No	25'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Minor
SW 8TH ST	Black Olive	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 8TH ST	Black Olive	11-15"	No	40'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Minor	Reduced Canopy - Minor
SW 8TH ST	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Minor
SW 8TH ST	Black Olive	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Limb Damage - Moderate	Reduced Canopy - Moderate
SW 8TH ST	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Lifting	Reduced Canopy - Major
SW 8TH ST	Black Olive	16-20"	No	30'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 8TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 8TH ST	Black Olive	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 8TH ST	Cabbage Palm	6-10"	No	5'	Fair (41% to 60%)		Girdling Roots	Suppressed Canopy	Restricted Canopy
SW 8TH ST	Desert Cassia	1-5"	No	10'	Good (61% to 80%)		Constricted Roots	Strap Constricting Tree	

(Continued on Next Page)

Street Tree Inventory

SW 8th Street (Continued)

SW 8TH ST	Desert Cassia	1-5"	No	10'	Good (61% to 80%)		Constricted Roots	Strap Constricting Tree	
SW 8TH ST	Desert Cassia	1-5"	No	15'	Good (61% to 80%)		Constricted Roots	Strap Constricting Tree	Codominant Leaders/Included Bark
SW 8TH ST	Desert Cassia	1-5"	No	10'	Good (61% to 80%)		Constricted Roots	Strap Constricting Tree	Codominant Leaders/Included Bark
SW 8TH ST	Foxtail Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Insect Damage Leaves		
SW 8TH ST	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	21-30"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Discolored Foliage		
SW 8TH ST	Royal Palm	16-20"	No	15'	Poor (21% to 40%)		Tapered Trunk	Reduced Canopy - Major	Desiccated Foliage
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	6-10"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Tapered Trunk	Nutrient Deficiency	
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	16-20"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	16-20"	No	15'	Fair (41% to 60%)		Nutrient Deficiency	Pencil Top	
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Trunk Damage - Moderate	
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency	Tapered Trunk	
SW 8TH ST	Royal Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Over Pruned	
SW 8TH ST	Royal Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Over Pruned	Trunk Damage - Minor
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency	Over Pruned	
SW 8TH ST	Royal Palm	16-20"	No	20'	Good (61% to 80%)		Nutrient Deficiency		

SW 9th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 9TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 9TH ST	Black Olive	16-20"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 9TH ST	Bottle Palm	11-15"	No	5'	Good (61% to 80%)				
SW 9TH ST	Bottlebrush	21-30"	No	20'	Very Poor/Critical (6% to 20%)	Utility Lines Above	Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 9TH ST	Bottlebrush	16-20"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Decay Observed
SW 9TH ST	Bottlebrush	16-20"	No	15'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Desiccated Foliage
SW 9TH ST	Christmas Palm	6-10"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 9TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)				
SW 9TH ST	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 9TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 9TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Reduced Canopy - Moderate		
SW 9TH ST	Coconut Palm	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major		
SW 9TH ST	Coconut Palm	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major		

(Continued on Next Page)

Street Tree Inventory

SW 9th Street (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 9TH ST	Foxtail Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 9TH ST	Foxtail Palm	6-10"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 9TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Codominant Leaders/Included Bark	
SW 9TH ST	Gumbo Limbo	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 9TH ST	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Limb Damage - Moderate	Sprouting
SW 9TH ST	Jamaican Dogwood	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 9TH ST	Jamaican Dogwood	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 9TH ST	Jamaican Dogwood	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 9TH ST	Jamaican Dogwood	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 9TH ST	Java Bishopwood	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 9TH ST	Java Bishopwood	16-20"	No	15'	Very Poor/Critical (6% to 20%)	Utility Line Conflict	Reduced Canopy - Major	Crown Density - Very Low	Dead Wood
SW 9TH ST	Java Bishopwood	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 9TH ST	Mango	1-5"	No	5'	Fair (41% to 60%)		Basal Co-Dominant		
SW 9TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 9TH ST	Solitaire Palm	1-5"	Yes	5'	Good (61% to 80%)				
SW 9TH ST	Strangler Fig	60+"	No	60'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 9TH ST	Weeping Fig	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 9TH ST	Weeping Fig	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/No Included Bark		
SW 9TH ST	Yellow Poinciana	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 9TH ST	Yellow Poinciana	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting


Streets



Looking West - SW 4th Avenue



Looking West - SW 9th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 10th Street	1	East Little Havana	3	50	3800	No	No	Yes	2	City	Few	Few	0	Few	Yes	Mostly on North Side	Street slopes down significantly going east at 11th Avenue intersection. Segmented at 8th and 9th Avenue. Vegetated curb extensions at intersections and some centers of blocks. Valley gutters along both sides.

SW 10th Street

TYPOLOGY D

Street Tree Inventory

SW 10th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 10TH ST	African Tulip Tree	21-30"	Yes	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 10TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)				
SW 10TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 10TH ST	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 10TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	11-15"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	5'	Fair (41% to 60%)		Nutrient Deficiency		
SW 10TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 10TH ST	Christmas Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Coconut Palm	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict	Restricted Canopy		
SW 10TH ST	Coconut Palm	16-20"	Yes	30'	Good (61% to 80%)	Utility Line Conflict			
SW 10TH ST	Coconut Palm	6-10"	No	10'	Good (61% to 80%)				
SW 10TH ST	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 10TH ST	Golden Rain Tree	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 10TH ST	Golden Rain Tree	16-20"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 10TH ST	Golden Rain Tree	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 10TH ST	Golden Rain Tree	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 10TH ST	Golden Shower Tree	16-20"	Yes	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 10TH ST	Golden Shower Tree	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 10TH ST	Golden Shower Tree	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Topped	Sprouting	Lopsided/Moderately Reduced Canopy
SW 10TH ST	Golden Shower Tree	16-20"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Topped	Sprouting	Lopsided/Moderately Reduced Canopy
SW 10TH ST	Gumbo Limbo	11-15"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Dead Wood	
SW 10TH ST	Gumbo Limbo	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Sprouting	
SW 10TH ST	Gumbo Limbo	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 10TH ST	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 10TH ST	Gumbo Limbo	6-10"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 10TH ST	Java Bishopwood	16-20"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 10TH ST	Java Bishopwood	11-15"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 10TH ST	Java Bishopwood	11-15"	No	5'	Very Poor/Critical (6% to 20%)		Reduced Canopy - Major	Trunk Damage - Major	Sprouting
SW 10TH ST	Live Oak	1-5"	No	5'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	
SW 10TH ST	Live Oak	6-10"	No	25'	Good (61% to 80%)				
SW 10TH ST	Live Oak	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Codominant Leaders/No Included Bark	
SW 10TH ST	Pongam	11-15"	No	35'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Codominant Leaders/Included Bark	Crown Density - Excessive (Due to Epicormic Growth)
SW 10TH ST	Royal Poinciana	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 10TH ST	Royal Poinciana	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 10TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Solitaire Palm	1-5"	No	10'	Good (61% to 80%)				
SW 10TH ST	Weeping Fig	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts

Avenues



Looking North- SW 11th Street




Looking North - SW 6th Street



Looking North - SW 11th Street



Looking North - SW 6th Street



Looking South - SW 6th Street



Looking South - SW 1st Street



Looking South - SW 6th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 5th Avenue	1	East Little Havana	3	50	3500	No	No	Yes	2	City	Few	No	0	Yes	Yes	Mostly on West Side	Valley gutters on both sides except blocks between 8th and 6th street. Vegetated curb extensions at intersections. Trees only at intersections.
SW 6th Avenue	1	East Little Havana	3	50	3500	No	No	Yes	2	City	Few	No	5	Yes	Yes	Mostly on West Side	One Way - South between 1st and 6th Street. Valley gutters along both sides. Vegetated curb extensions at intersections.

SW 5th Avenue
TYPOLOGY D

SW 6th Avenue
TYPOLOGY D

Street Tree Inventory

SW 5th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 5TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Minor	Sprouting
SW 5TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 5TH AVE	Black Olive	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 5TH AVE	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 5TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 5TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Dead Wood
SW 5TH AVE	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 5TH AVE	Black Olive	11-15"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 5TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 5TH AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 5TH AVE	Black Olive	11-15"	No	30'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 5TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 5TH AVE	Black Olive	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 5TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Minor	Sprouting
SW 5TH AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Crown Density - Moderate
SW 5TH AVE	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 5TH AVE	Black Olive	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 5TH AVE	Black Olive	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 5TH AVE	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 5TH AVE	Christmas Palm	11-15"	Yes	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 5TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 5TH AVE	Gumbo Limbo	16-20"	No	20'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 5TH AVE	Live Oak	16-20"	No	35'	Poor (21% to 40%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 5TH AVE	Montgomery Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 5TH AVE	Washington Palm	6-10"	No	10'	Good (61% to 80%)				
SW 5TH AVE	Washington Palm	11-15"	No	10'	Good (61% to 80%)				

SW 6th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 6TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 6TH AVE	Black Olive	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 6TH AVE	Black Olive	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 6TH AVE	Black Olive	16-20"	No	40'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 6TH AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Cavities
SW 6TH AVE	Black Olive	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Codominant Leaders/Included Bark	
SW 6TH AVE	Black Olive	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 6TH AVE	Black Olive	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 6TH AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 6TH AVE	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 6TH AVE	Christmas Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency	Suppressed Canopy	
SW 6TH AVE	Christmas Palm	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH AVE	Dahoon Holly	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 6TH AVE	Lead Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Restricted Canopy	Suppressed Canopy	
SW 6TH AVE	Live Oak	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 6TH AVE	Live Oak	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 6TH AVE	Live Oak	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 6TH AVE	Mahogany	41-50"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 6TH AVE	Mahogany	31-40"	No	60'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 6TH AVE	Mahogany	31-40"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Ficus Growing on Tree

(Continued on Next Page)

Street Tree Inventory

SW 6th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 6TH AVE	Papaya	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Multi-Trunk Form - Not Downgraded for Structure
SW 6TH AVE	Pongam	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 6TH AVE	Pongam	21-30"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 6TH AVE	Pongam	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Limb Damage - Moderate	Sprouting
SW 6TH AVE	Pongam	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Suppressed Canopy	Dead Wood
SW 6TH AVE	Pongam	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 6TH AVE	Pygmy Date Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 6TH AVE	Weeping Fig	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Pruned Into Shrub	Dead Wood
SW 6TH AVE	Weeping Fig	1-5"	No	5'	Fair (41% to 60%)		Trunk Damage - Moderate	Lopsided/Moderately Reduced Canopy	



Looking North - SW 6th Street



Looking North - SW 11th Street



Looking North - SW 6th Street



Looking South - SW 5th Street



Looking South - SW 6th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 6th Court	1	East Little Havana	3	50	350	No	No	Yes	2	City	No	No	0	Yes	Yes	Mostly on West Side	Valley gutters along both sides. Curb extensions at street corners.
SW 7th Avenue	1	East Little Havana	3	50	3500	No	No	Yes	2	City	Few	Few	5	Yes	Yes	Mostly on West Side	One Way - North between 1st and 6th Street . Swales between 7th and 8th Street. Valley gutters on both sides except between 6th and 9th Street.

SW 6th Court

TYPOLOGY D

SW 7th Avenue

TYPOLOGY D

Street Tree Inventory

SW 6th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 6TH CT	Coconut Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		

SW 7th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 7TH AVE	African Tulip Tree	31-40"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark
SW 7TH AVE	African Tulip Tree	21-30"	No	30'	Poor (21% to 40%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 7TH AVE	African Tulip Tree	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 7TH AVE	African Tulip Tree	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	Dead Wood
SW 7TH AVE	African Tulip Tree	31-40"	No	50'	Fair (41% to 60%)		Constricted Roots	Stubs with Sprouts	Dead Wood
SW 7TH AVE	Banana Tree	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 7TH AVE	Banana Tree	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 7TH AVE	Banana Tree	6-10"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 7TH AVE	Banana Tree	11-15"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 7TH AVE	Black Olive	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 7TH AVE	Black Olive	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Major
SW 7TH AVE	Black Olive	16-20"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Sprouting
SW 7TH AVE	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 7TH AVE	Christmas Palm	6-10"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 7TH AVE	Coconut Palm	1-5"	No	5'	Good (61% to 80%)				
SW 7TH AVE	Dracaena sp.	16-20"	Yes	10'	Good (61% to 80%)				
SW 7TH AVE	Earleaf Acacia	21-30"	No	30'	Fair (41% to 60%)		Lateral Branching - None	Limb Damage - Moderate	Sprouting
SW 7TH AVE	Gumbo Limbo	1-5"	No	15'	Fair (41% to 60%)		Restricted Canopy	Suppressed Canopy	
SW 7TH AVE	Live Oak	60+"	No	70'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Moderate
SW 7TH AVE	Live Oak	16-20"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 7TH AVE	Loquat	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 7TH AVE	Loquat	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 7TH AVE	Loquat	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 7TH AVE	Loquat	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 7TH AVE	Loquat	1-5"	No	5'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 7TH AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 7TH AVE	Mahogany	21-30"	No	30'	Poor (21% to 40%)	Utility Lines Above	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Major
SW 7TH AVE	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 7TH AVE	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 7TH AVE	Mahogany	31-40"	No	60'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Minor	Dead Wood
SW 7TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 7TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Moderate	Dead Wood
SW 7TH AVE	Mahogany	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Dead Wood	Sprouting
SW 7TH AVE	Mahogany	31-40"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Ficus Growing on Tree
SW 7TH AVE	Oleander	16-20"	Yes	15'	Good (61% to 80%)		Insect Damage Leaves	Crown Density - Moderate	
SW 7TH AVE	Pongam	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Dead Wood
SW 7TH AVE	Pongam	21-30"	No	40'	Fair (41% to 60%)		Constricted Roots	Sprouting	Codominant Leaders/Included Bark
SW 7TH AVE	Pongam	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 7TH AVE	Pongam	16-20"	No	30'	Fair (41% to 60%)	Utility Lines Above	Constricted Roots	Reduced Canopy - Minor	Sprouting
SW 7TH AVE	Rubber Tree	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Multi-Trunk Form - Not Downgraded for Structure	Restricted Canopy
SW 7TH AVE	Rubber Tree	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Multi-Trunk Form - Not Downgraded for Structure	Restricted Canopy
SW 7TH AVE	Rubber Tree	21-30"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Multi-Trunk Form - Not Downgraded for Structure	Restricted Canopy
SW 7TH AVE	Sea Grape	16-20"	No	25'	Fair (41% to 60%)		Constricted Roots	Multi-Trunk Form - Not Downgraded for Structure	
SW 7TH AVE	Solitaire Palm	1-5"	No	10'	Fair (41% to 60%)		Nutrient Deficiency	Suppressed Canopy	Restricted Canopy
SW 7TH AVE	Unidentified Dead Tree (	11-15"	No	Negligible	Dead (0% to 5%)	Utility Lines Above			
SW 7TH AVE	Weeping Fig	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Dead Wood	Multi-Trunk Form - Not Downgraded for Structure
SW 7TH AVE	Weeping Fig	1-5"	Yes	10'	Good (61% to 80%)	Utility Lines Above	Dead Wood		

Courts | Avenues



Looking North - SW 7th Street



Looking North - SW 6th Street



Looking North - SW 11 Street



Looking North - SW 6th Street




Looking South - SW 6th Street



Looking South - SW 5th Street



Looking South - SW 6th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 7th Court	1	East Little Havana	3	50	1000	No	No	Yes	2	City	Few	No	0	Yes	Yes	Mostly on West Side	New tree plantings on west side of southern block. Vegetated curb extnesions at intersections. Valley gutters along both sides.
SW 8th Avenue	1	East Little Havana	3	50 / 60 N of 7th street	3500	No	Btw 8th and 10th Street	Mostly	2	State	Some	Some	0	Yes	Yes	Mostly on West Side	Avenue becomes main thouroughfare North of 8th Street. Opporutnities for extended curb extnesions where parking is currently not allowed. Share the lane bike markings on both sides.

SW 7th Court

TYPOLOGY D

SW 8th Avenue

TYPOLOGY D

Street Tree Inventory

SW 7th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 7TH CT	Jacaranda	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Sprouting
SW 7TH CT	Mahogany	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Crown Density - Low	Dead Wood
SW 7TH CT	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 7TH CT	Pongam	16-20"	No	30'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Sprouting	Dead Wood

SW 8th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 8TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)				
SW 8TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)				
SW 8TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 8TH AVE	Frangipani	6-10"	Yes	10'	Good (61% to 80%)				
SW 8TH AVE	Live Oak	16-20"	No	30'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 8TH AVE	Live Oak	16-20"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Dead Wood
SW 8TH AVE	Live Oak	16-20"	No	30'	Very Poor/Critical (6% to 20%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 8TH AVE	Orange Geiger	1-5"	No	5'	Poor (21% to 40%)		Leader - Broken	Cracks in Trunk	Sprouting
SW 8TH AVE	Orange Geiger	1-5"	No	5'	Fair (41% to 60%)		Leaning - Major	Strap Constricting Tree	Constricted Roots
SW 8TH AVE	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Constricted Roots	Strap Constricting Tree	Insect Damage Leaves
SW 8TH AVE	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Constricted Roots	Strap Constricting Tree	Insect Damage Leaves
SW 8TH AVE	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Constricted Roots	Strap Constricting Tree	Insect Damage Leaves
SW 8TH AVE	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Constricted Roots	Strap Constricting Tree	Insect Damage Leaves
SW 8TH AVE	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Constricted Roots	Strap Constricting Tree	Insect Damage Leaves
SW 8TH AVE	Orange Geiger	1-5"	No	5'	Poor (21% to 40%)		Constricted Roots	Strap Constricting Tree	Leaning - Major
SW 8TH AVE	Orange Geiger	1-5"	No	5'	Good (61% to 80%)		Constricted Roots	Strap Constricting Tree	Insect Damage Leaves
SW 8TH AVE	Oriental Arborvitae	6-10"	No	10'	Fair (41% to 60%)		Apical Dieback		
SW 8TH AVE	Oriental Arborvitae	6-10"	No	10'	Good (61% to 80%)				
SW 8TH AVE	Pink Tabebuia	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Topped	Sprouting
SW 8TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 8TH AVE	Pink Tabebuia	6-10"	No	10'	Poor (21% to 40%)		Reduced Canopy - Major	Sprouting	Codominant Leaders/No Included Bark
SW 8TH AVE	Pink Tabebuia	6-10"	No	10'	Poor (21% to 40%)		Topped	Stubs	
SW 8TH AVE	Pongam	11-15"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Sprouting
SW 8TH AVE	Weeping Fig	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Stubs	Sprouting

Courts | Avenues



Looking North - SW 9th Street



Looking North - SW 5th Street



Looking North - SW 11th Street



Looking North- SW 6th Street




Looking South - SW 5th Street



Looking South - SW 8th Street



Looking South - SW 6th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 8th Court	1	East Little Havana	3	50 / 20 bw 5 and 6 street	1400	No	No	Yes	2	City	Few	No	0	N of 5th Street	N of 5th Street	Mostly on West Side	No Street Parking between 5th and 6th Street, narrows like an alleyway. Segemented by 6th and 8th Street. Dead end on South side. Valley gutters on both sides. Vegetated curb extensions at intersections.
SW 9th Avenue	1	East Little Havana	3	50	3500	No	No	Yes	2	City	Few	Few	0	Yes	Yes	Mostly on West Side	One Way - South. Sidewalk cutouts for trees on west side between 1st and 2nd street. Segmented at 8th Street. Road narrows south of 8th street. Valley gutters along both sides.

SW 8th Court

TYPOLOGY D & x

SW 9th Avenue

TYPOLOGY D

Street Tree Inventory

SW 8th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 8TH CT	Bottle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 8TH CT	Golden Shower Tree	11-15"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Sprouting

SW 9th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 9TH AVE	Areca Palm	21-30"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 9TH AVE	Areca Palm	21-30"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency		
SW 9TH AVE	Black Olive	11-15"	No	35'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 9TH AVE	Black Olive	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 9TH AVE	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 9TH AVE	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)				
SW 9TH AVE	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 9TH AVE	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 9TH AVE	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict	Ficus Growing on Tree		
SW 9TH AVE	Cabbage Palm	11-15"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 9TH AVE	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)	Utility Lines Adjacent (laterally)			
SW 9TH AVE	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 9TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 9TH AVE	Christmas Palm	21-30"	Yes	15'	Good (61% to 80%)	Utility Line Conflict			
SW 9TH AVE	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 9TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate	Nutrient Deficiency	
SW 9TH AVE	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)		Discolored Foliage	Nutrient Deficiency	
SW 9TH AVE	Coconut Palm	6-10"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency	Tapered Trunk	
SW 9TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 9TH AVE	Coconut Palm	6-10"	Yes	15'	Fair (41% to 60%)		Nutrient Deficiency	Tapered Trunk	
SW 9TH AVE	Coconut Palm	6-10"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 9TH AVE	Coconut Palm	11-15"	No	20'	Fair (41% to 60%)		Nutrient Deficiency		
SW 9TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 9TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Sprouting	
SW 9TH AVE	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)				
SW 9TH AVE	Jamaican Dogwood	16-20"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 9TH AVE	Jamaican Dogwood	21-30"	No	50'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 9TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Crown Density - Low	Reduced Canopy - Moderate	Epicormic Growth
SW 9TH AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 9TH AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Lion's Tailing
SW 9TH AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Lifting
SW 9TH AVE	Mahogany	21-30"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 9TH AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major
SW 9TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 9TH AVE	Mahogany	21-30"	No	35'	Poor (21% to 40%)	Utility Line Conflict	Girdling Roots	Lopsided/Significantly Reduced Canopy	Trunk Damage - Major
SW 9TH AVE	Mahogany	31-40"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders - Multi
SW 9TH AVE	Pink Tabebuia	16-20"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Lifting	
SW 9TH AVE	Pink Tabebuia	11-15"	No	30'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Lifting	Codominant Leaders/Included Bark
SW 9TH AVE	Pink Tabebuia	11-15"	No	30'	Good (61% to 80%)		Reduced Canopy - Moderate	Lifting	Dead Wood
SW 9TH AVE	Pink Tabebuia	16-20"	No	25'	Good (61% to 80%)	Utility Line Conflict	Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 9TH AVE	Pink Tabebuia	11-15"	No	20'	Good (61% to 80%)		Lopsided/Moderately Reduced Canopy	Dead Wood	Discolored Foliage
SW 9TH AVE	Pink Tabebuia	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Significantly Reduced Canopy	Lifting
SW 9TH AVE	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Topped	Stubs with Sprouts	Trunk Damage - Moderate
SW 9TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 9TH AVE	Royal Palm	16-20"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Damaged Fronds	
SW 9TH AVE	Spindle Palm	6-10"	No	5'	Good (61% to 80%)		Nutrient Deficiency		
SW 9TH AVE	Spindle Palm	6-10"	No	5'	Good (61% to 80%)				
SW 9TH AVE	Weeping Fig	16-20"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Broken Branches	Dead Wood
SW 9TH AVE	Weeping Fig	16-20"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood

Courts | Avenues



Looking North - SW 11th Street



Looking North - SW 9th Street



Looking North - SW 11th Street



Looking North - SW 6th Street



Looking South - SW 9th Street



Looking South - SW 10th Street



Looking South - SW 6th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 9th Court	1	East Little Havana	3	50	1000	No	No	Yes	2	City	Some	No	5 - 7	Yes	Intermittent	Mostly on West Side	Swale on east side of south end lined with Gumbo Limbo. No sidewalks between 10th and 9th street. Private properties abutting the road
SW 10th Avenue	1	East Little Havana	3	50	3500	No	No	Yes	2	City	Few	Few	0	Yes	Yes	Mostly on West Side	One Way - North between 7th and 8th Street. Valley gutters along both sides. Share the lane bike markings along both sides. Vegetated curb extensions at street intersections.

SW 9th Court

TYPOLOGY D

SW 10th Avenue

TYPOLOGY D

Street Tree Inventory


SW 9th Court

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 9TH CT	Bottlebrush	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Above	Trunk Damage - Major	Decay Observed	
SW 9TH CT	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 9TH CT	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 9TH CT	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 9TH CT	Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 9TH CT	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	
SW 9TH CT	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 9TH CT	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 9TH CT	Gumbo Limbo	6-10"	No	15'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 9TH CT	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 9TH CT	Gumbo Limbo	11-15"	No	15'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Major	Decay Observed
SW 9TH CT	Gumbo Limbo	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 9TH CT	Live Oak	16-20"	No	20'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Sprouting
SW 9TH CT	Mahogany	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Codominant Leaders/Included Bark
SW 9TH CT	Moringa Tree	6-10"	No	15'	Fair (41% to 60%)		Trunk Damage - Moderate	Codominant Leaders/No Included Bark	Restricted Canopy
SW 9TH CT	Moringa Tree	6-10"	No	15'	Fair (41% to 60%)		Codominant Leaders/Included Bark	Restricted Canopy	Dead Wood
SW 9TH CT	Starburst Clerodendron	6-10"	No	10'	Fair (41% to 60%)	Utility Lines Above	Crown Density - Moderate		

SW 10th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 10TH AVE	Black Olive	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark		
SW 10TH AVE	Coconut Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 10TH AVE	Crepe Myrtle	1-5"	No	5'	Good (61% to 80%)		Strap Constricting Tree		
SW 10TH AVE	Green Buttonwood	11-15"	No	10'	Very Poor/Critical (6% to 20%)		Topped	Epicormic Growth	
SW 10TH AVE	Mahogany	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Lifting
SW 10TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)		Constricted Roots	Lopsided/Moderately Reduced Canopy	Trunk Damage - Moderate
SW 10TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Limb Damage - Moderate
SW 10TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 10TH AVE	Mahogany	21-30"	No	40'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 10TH AVE	Pink Tabebuia	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 10TH AVE	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)		Reduced Canopy - Moderate	Broken Branches	
SW 10TH AVE	Pink Tabebuia	16-20"	No	30'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Trunk Damage - Moderate	Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 10TH AVE	Pink Tabebuia	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict	Trunk Damage - Moderate	Reduced Canopy - Moderate	
SW 10TH AVE	Pongam	11-15"	No	35'	Good (61% to 80%)		Codominant Leaders/Included Bark	Trunk Damage - Moderate	
SW 10TH AVE	Powderpuff Tree	6-10"	No	10'	Poor (21% to 40%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	Crown Density - Excessive (Due to Epicormic Growth)
SW 10TH AVE	Queen Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Discolored Foliage	Sprouting	Nutrient Deficiency
SW 10TH AVE	Queen Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Discolored Foliage	Strap Constricting Tree	Nutrient Deficiency
SW 10TH AVE	Queen Crepe Myrtle	1-5"	No	10'	Good (61% to 80%)		Discolored Foliage	Sprouting	Codominant Leaders/Included Bark
SW 10TH AVE	Royal Palm	16-20"	No	20'	Good (61% to 80%)				
SW 10TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 10TH AVE	Spanish Lime	1-5"	No	5'	Good (61% to 80%)		Insect Damage Leaves		
SW 10TH AVE	Starburst Clerodendron	6-10"	No	10'	Good (61% to 80%)	Utility Lines Above			
SW 10TH AVE	Umbrella Tree	6-10"	No	10'	Poor (21% to 40%)	Utility Line Conflict	Topped	Reduced Canopy - Major	Sprouting
SW 10TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)		Trunk Damage - Moderate		
SW 10TH AVE	Yellow Poinciana	16-20"	No	15'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Major	Sprouting

Avenues



Looking North - SW 11th Street



Looking North - SW 6th Street



Looking South - SW 6th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 11th Avenue	1	East Little Havana	3	50	3500	No	No	Yes	2	City	Few	Few	0	Yes	Yes	Mostly on West Side	One Way - South. Valley gutters along both sides. Curb extensions at intersections, mostly vegetated.

SW 11th Avenue


TYPOLOGY D

Street Tree Inventory

SW 11th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 11TH AVE	Banyan	1-5"	No	5'	Good (61% to 80%)				
SW 11TH AVE	Black Olive	16-20"	No	40'	Fair (41% to 60%)		Constricted Roots	Cavities	Codominant Leaders - Multi
SW 11TH AVE	Christmas Palm	6-10"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 11TH AVE	Christmas Palm	16-20"	Yes	15'	Good (61% to 80%)	Utility Lines Above			
SW 11TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH AVE	Christmas Palm	1-5"	No	10'	Good (61% to 80%)				
SW 11TH AVE	Coconut Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Adjacent (laterally)	Nutrient Deficiency		
SW 11TH AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Cavities
SW 11TH AVE	Mahogany	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders - Multi
SW 11TH AVE	Mahogany	16-20"	No	30'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 11TH AVE	Pink Tabebuia	21-30"	No	30'	Fair (41% to 60%)	Codominant Leaders/Included Bark	Constricted Roots	Reduced Canopy - Moderate	Topped
SW 11TH AVE	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Trunk Damage - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 11TH AVE	Pink Tabebuia	6-10"	No	20'	Fair (41% to 60%)		Codominant Leaders - Multi	Reduced Canopy - Moderate	Dead Wood
SW 11TH AVE	Pink Tabebuia	11-15"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Codominant Leaders - Multi	Codominant Leaders - Multi
SW 11TH AVE	Pink Tabebuia	11-15"	No	25'	Fair (41% to 60%)	Utility Line Conflict	Reduced Canopy - Moderate	Lifting	Stubs with Sprouts
SW 11TH AVE	Pink Tabebuia	11-15"	No	15'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Reduced Canopy - Major	Trunk Damage - Major	Lifting
SW 11TH AVE	Pink Tabebuia	6-10"	No	15'	Poor (21% to 40%)		Reduced Canopy - Major	Crown Density - Very Low	Lifting
SW 11TH AVE	Pongam	21-30"	No	35'	Poor (21% to 40%)		Constricted Roots	Trunk Damage - Major	Dead Wood
SW 11TH AVE	Queen Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate		
SW 11TH AVE	Sapodilla	21-30"	No	50'	Fair (41% to 60%)		Constricted Roots	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 11TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH AVE	Solitaire Palm	1-5"	No	5'	Good (61% to 80%)				
SW 11TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 11TH AVE	Washington Palm	11-15"	No	15'	Good (61% to 80%)				
SW 11TH AVE	Yellow Poinciana	31-40"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 11TH AVE	Yellow Poinciana	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Sprouting

Bordering Streets




Looking West - SW 6th Avenue



Looking West - SW 8th Avenue



Looking West - SW 4th Avenue




Looking West - SW 8th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th Avenue



Looking East - SW 8th Avenue



Looking East - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 1st Street	1	East Little Havana	3	60	4400	No	No	Yes	3	State	Some	Some	0	Yes	Yes	Mostly on South Side	One Way-West. Share the lane bike markings. Cross-walk between 9th and 10th avenue, and after 11th Avenue.
SW 11th Street	1	East Little Havana	3	50 / 60 E of 8th Ave	4500	No	No	Yes	2	City	Some	Few	10 (intermittent)	Few	Yes	Mostly on North Side	Street slopes down significantly going east at 11th Avenue intersection. North side mainly consists of on-street parking for apartments, no swales. Valley gutters along north side after 10th Avenue.

SW 1st Street

TYPOLOGY D

SW 11th Street

TYPOLOGY B & D

Street Tree Inventory

SW 1st Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 1ST ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Tapered Trunk	Strap Constricting Tree	
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Reduced Canopy - Moderate	
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Tapered Trunk	
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Reduced Canopy - Moderate	Nutrient Deficiency
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Reduced Canopy - Moderate	Nutrient Deficiency
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Reduced Canopy - Moderate	Nutrient Deficiency
SW 1ST ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Reduced Canopy - Moderate	Nutrient Deficiency
SW 1ST ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Reduced Canopy - Moderate	Nutrient Deficiency
SW 1ST ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Reduced Canopy - Moderate	Nutrient Deficiency
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency	Strap Constricting Tree	
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Nutrient Deficiency	
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Nutrient Deficiency	
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Nutrient Deficiency	
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Nutrient Deficiency	
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree	Nutrient Deficiency	
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above	Strap Constricting Tree		
SW 1ST ST	Royal Palm	11-15"	No	10'	Fair (41% to 60%)	Utility Lines Above	Strap Constricting Tree	Reduced Canopy - Moderate	Nutrient Deficiency
SW 1ST ST	Silver Buttonwood	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Broken Branches	
SW 1ST ST	Silver Buttonwood	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Leaning - Moderate	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 1ST ST	Triangle Palm	11-15"	No	10'	Good (61% to 80%)	Utility Lines Above			

(Continued on Next Page)

Street Tree Inventory

SW 1st Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 1ST ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 1ST ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)				
SW 1ST ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			
SW 1ST ST	White Frangipani	1-5"	No	5'	Good (61% to 80%)	Utility Lines Above			


SW 11th Street

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 11TH ST	Areca Palm	1-5"	Yes	5'	Fair (41% to 60%)		Nutrient Deficiency	Nutrient Deficiency	
SW 11TH ST	Black Olive	16-20"	No	35'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	
SW 11TH ST	Black Olive	11-15"	No	20'	Very Poor/Critical (6% to 20%)	Utility Lines Adjacent (laterally)	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 11TH ST	Black Olive	11-15"	No	20'	Poor (21% to 40%)	Utility Lines Adjacent (laterally)	Constricted Roots	Reduced Canopy - Major	Sprouting
SW 11TH ST	Cabbage Palm	11-15"	No	10'	Fair (41% to 60%)		Trunk Damage - Moderate		
SW 11TH ST	Cabbage Palm	6-10"	No	10'	Good (61% to 80%)				
SW 11TH ST	Cabbage Palm	6-10"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 11TH ST	Coconut Palm	6-10"	No	15'	Fair (41% to 60%)	Utility Lines Above	Nutrient Deficiency		
SW 11TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)	Utility Lines Above	Nutrient Deficiency		
SW 11TH ST	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Pruned Into Shrub		
SW 11TH ST	Gumbo Limbo	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	
SW 11TH ST	Gumbo Limbo	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 11TH ST	Gumbo Limbo	1-5"	No	15'	Good (61% to 80%)				
SW 11TH ST	Live Oak	6-10"	No	20'	Fair (41% to 60%)	Utility Lines Above	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Crown Density - Excessive (Due to Epicormic Growth)
SW 11TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Live Oak	1-5"	No	10'	Good (61% to 80%)				
SW 11TH ST	Pink Tabebuia	1-5"	No	10'	Fair (41% to 60%)		Lopsided/Moderately Reduced Canopy	Dead Wood	
SW 11TH ST	Pink Tabebuia	6-10"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	Sprouting
SW 11TH ST	Pink Tabebuia	11-15"	No	15'	Fair (41% to 60%)		Restricted Canopy	Codominant Leaders/Included Bark	Sprouting
SW 11TH ST	Royal Poinciana	21-30"	No	45'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Major	Dead Wood
SW 11TH ST	Sapodilla	31-40"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 11TH ST	Spindle Palm	11-15"	No	10'	Good (61% to 80%)				
SW 11TH ST	Spindle Palm	6-10"	No	5'	Fair (41% to 60%)		Reduced Canopy - Moderate	Trunk Damage - Minor	
SW 11TH ST	Yellow Poinciana	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 11TH ST	Yellow Poinciana	21-30"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 11TH ST	Yellow Tabebuia	11-15"	No	25'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Codominant Leaders/No Included Bark	
SW 11TH ST	Yellow Tabebuia	11-15"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Trunk Damage - Moderate	Reduced Canopy - Moderate	Dead Wood
SW 11TH ST	Yellow Tabebuia	6-10"	No	20'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	
SW 11TH ST	Yellow Tabebuia	11-15"	No	25'	Good (61% to 80%)	Utility Lines Above	Codominant Leaders/Included Bark	Dead Wood	

Bordering Avenues



Looking Northeast - SW 3rd Avenue



Looking Northeast - SW 21st Road



Looking North - SW 11th Street



Looking North - SW 6th Street




Looking Northeast - SW 28th Road



Looking Southwest - SW 19th Road



Looking South - SW 6th Street



Looking South - SW 1st Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 4th Avenue	1	East Little Havana	3	50 / 70 btw 9th St and 7th St	3500	No	No	Yes	2	City	Few	No	0	Yes	Yes	Mostly on West Side	One Way - South between 7th and 8th Street, 4 lanes. Street slopes down significantly going north at 6th street intersection. Valley gutters only between 1st and 6th Street
SW 12th Avenue	1	East Little Havana	3	80	3500	No	No	Yes	4	State	Few	Few	0	Yes	Yes	None	Share the lanes bike markings going both directions south of 6th Street. Opportunities for vegetated curb extensions or islands where parking is currently not allowed.

SW 4th Avenue

TYPOLOGY D

SW 12th Avenue

TYPOLOGY D

Street Tree Inventory

SW 4th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 4TH AVE	Coconut Palm	6-10"	No	20'	Fair (41% to 60%)	Utility Line Conflict	Nutrient Deficiency	Over Pruned	
SW 4TH AVE	Coconut Palm	11-15"	No	20'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH AVE	Florida Thatch Palm	1-5"	No	10'	Good (61% to 80%)		Nutrient Deficiency		
SW 4TH AVE	Jamaica Caper	6-10"	No	10'	Good (61% to 80%)		Multi-Trunk Form - Not Downgraded for Str	Trunk Damage - Moderate	
SW 4TH AVE	Live Oak	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Minor	Dead Wood
SW 4TH AVE	Live Oak	6-10"	No	25'	Poor (21% to 40%)	Utility Line Conflict	Constricted Roots	Lifting	Dead Wood
SW 4TH AVE	Mahogany	21-30"	No	45'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 4TH AVE	Mahogany	31-40"	No	50'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 4TH AVE	Mahogany	21-30"	No	40'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots	Trunk Damage - Moderate	Reduced Canopy - Minor
SW 4TH AVE	Mahogany	21-30"	No	45'	Fair (41% to 60%)	Utility Lines Adjacent (laterally)	Constricted Roots	Dead Wood	Sprouting
SW 4TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)	Utility Line Conflict	Constricted Roots		
SW 4TH AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	
SW 4TH AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Restricted Canopy	
SW 4TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots		
SW 4TH AVE	Mahogany	11-15"	No	20'	Poor (21% to 40%)		Constricted Roots	Reduced Canopy - Major	Sprouting
SW 4TH AVE	Mahogany	11-15"	No	25'	Fair (41% to 60%)		Constricted Roots	Sprouting	
SW 4TH AVE	Mahogany	11-15"	No	30'	Fair (41% to 60%)		Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 4TH AVE	Pink Tabebuia	6-10"	No	15'	Good (61% to 80%)		Reduced Canopy - Moderate	Dead Wood	Sprouting
SW 4TH AVE	Pink Tabebuia	6-10"	No	20'	Good (61% to 80%)		Dead Wood	Sprouting	

SW 12th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 12TH AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 12TH AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 12TH AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 12TH AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 12TH AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)		Nutrient Deficiency		
SW 12TH AVE	Date Palm	11-15"	No	15'	Good (61% to 80%)				
SW 12TH AVE	Date Palm	11-15"	No	20'	Good (61% to 80%)				
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Crown Density - Moderate	Trunk Damage - Minor
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)		Improperly Mulched		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	15'	Good (61% to 80%)		Improperly Mulched		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Improperly Mulched		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Improperly Mulched	Strap Constricting Tree	
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Improperly Mulched	Reduced Canopy - Moderate
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Improperly Mulched	Reduced Canopy - Moderate
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Reduced Canopy - Moderate	Broken Branches
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Reduced Canopy - Moderate	
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Horseflesh Mahogany	1-5"	No	10'	Good (61% to 80%)		Strap Constricting Tree	Stubs with Sprouts	

(Continued on Next Page)

Street Tree Inventory

SW 12th Avenue (Continued)

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 12TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Codominant Leaders/Included Bark	Lifting	
SW 12TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Codominant Leaders/Included Bark	Lifting	Reduced Canopy - Moderate
SW 12TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Lifting	
SW 12TH AVE	Live Oak	6-10"	No	25'	Good (61% to 80%)		Reduced Canopy - Minor		
SW 12TH AVE	Live Oak	6-10"	No	20'	Good (61% to 80%)		Reduced Canopy - Moderate	Lifting	Trunk Damage - Minor
SW 12TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Strap Constricting Tree		
SW 12TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate		
SW 12TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)		Reduced Canopy - Moderate	Nutrient Deficiency	
SW 12TH AVE	Montgomery Palm	6-10"	No	10'	Fair (41% to 60%)		Tapered Trunk	Nutrient Deficiency	
SW 12TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)				
SW 12TH AVE	Montgomery Palm	6-10"	No	10'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	Discolored Foliage
SW 12TH AVE	Royal Palm	6-10"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	Tapered Trunk
SW 12TH AVE	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	Tapered Trunk
SW 12TH AVE	Royal Palm	11-15"	No	15'	Fair (41% to 60%)		Strap Constricting Tree	Reduced Canopy - Moderate	Tapered Trunk
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'	Good (61% to 80%)	Utility Lines Above			
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Sylvester Date Palm	11-15"	No	20'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Sylvester Date Palm	6-10"	No	15'	Good (61% to 80%)	Utility Line Conflict			
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'	Good (61% to 80%)				



THE ROADS

Avenues



Looking Northeast - SW 3rd Avenue



Looking Northeast - SW 21st Road



Looking Northeast - SW 21st Road



Looking Northeast - SW 31st Road



Looking Northeast - SW 28th Road



Looking Southwest - SW 19th Road



Looking Southwest - SW 19th Road



Looking Southwest - SW 28th Road

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 1st Avenue	1	Roads	3	50	7200	No	Some	No	2	City	Yes	Some	5	Southwest of 23rd Road	Yes	Mostly on NW	Avenue segmented at Viscaya MetroRail station on SW 32nd Road. Avenue comes to dead end and becomes one-way NE between 32 and 31st Road.
SW 2nd Avenue	1	Roads	3	70	5000	Some, btw 23rd and 27th Road	No	Yes	2	City	Yes	Yes	12	Southwest of 23rd Road	Yes	Mostly on SE	Large segments of swales between 19th and 23rd Road with no tree canopy. Avenue merges with 22nd Street on SW end.

SW 1st Avenue

TYPOLOGY A and B

SW 2nd Avenue

TYPOLOGY A and F

Street Tree Inventory

SW 1st Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/Included Bark	Epicormic Growth
SW 1ST AVE	Pink Tabebuia	1-5"	No	10'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Sprouting
SW 1ST AVE	Pink Tabebuia	21-30"	No	35'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Sprouting
SW 1ST AVE	Live Oak	6-10"	No	35'		Poor (21% to 40%)	Trunk Damage - Moderate	Limb Damage - Moderate	Crown Density - Excessive (Due to Epicormic Growth)
SW 1ST AVE	Pigeon Plum	1-5"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 1ST AVE	Pigeon Plum	1-5"	No	5'		Poor (21% to 40%)	Topped	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Pigeon Plum	6-10"	No	10'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Dead Wood
SW 1ST AVE	Fishtail Palm	21-30"	Yes	20'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Paurotis Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Paurotis Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Cabbage Palm	6-10"	No	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Ficus Growing on Tree
SW 1ST AVE	Mahogany	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Epicormic Growth
SW 1ST AVE	Pigeon Plum	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Suppressed Canopy
SW 1ST AVE	Montgomery Palm	11-15"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	Suppressed Canopy
SW 1ST AVE	Jamaica Caper	1-5"	Yes	5'		Good (61% to 80%)	Sprouting	Grafted Branches	
SW 1ST AVE	Live Oak	1-5"	Yes	5'		Good (61% to 80%)	Sprouting	Grafted Branches	
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Sprouting	
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Suppressed Canopy	
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark		
SW 1ST AVE	Pigeon Plum	16-20"	Yes	20'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Insect Damage Leaves	Epicormic Growth
SW 1ST AVE	Pigeon Plum	21-30"	Yes	20'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Insect Damage Leaves	Epicormic Growth
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark		
SW 1ST AVE	Live Oak	1-5"	Yes	5'		Good (61% to 80%)	Grafted Branches		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Adjacent Light Pole	
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Adjacent Light Pole	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Live Oak	31-40"	No	70'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Restricted Canopy	
SW 1ST AVE	Live Oak	1-5"	Yes	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Restricted Canopy	Epicormic Growth
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Pigeon Plum	11-15"	No	25'		Poor (21% to 40%)	Basal Co-Dominant	Insect Damage Leaves	Dead Wood
SW 1ST AVE	Jamaica Caper	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Live Oak	6-10"	No	30'	Utility Lines Above	Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Adjacent Light Pole
SW 1ST AVE	Live Oak	1-5"	No	5'		Poor (21% to 40%)	Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Grafted Branches
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Pink Tabebuia	6-10"	No	30'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Dead Wood
SW 1ST AVE	Pink Tabebuia	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Discolored Foliage	Insect Damage Leaves	Stubs with Sprouts
SW 1ST AVE	Pink Tabebuia	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/Included Bark	Grafted Branches	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Pink Tabebuia	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	21-30"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Limb Damage - Minor
SW 1ST AVE	Royal Poinciana	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 1ST AVE	Royal Poinciana	16-20"	No	45'		Poor (21% to 40%)	Basal Co-Dominant	Crown Density - Low	Broken Branches
SW 1ST AVE	Royal Poinciana	16-20"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Cavities
SW 1ST AVE	Weeping Fig	16-20"	No	15'	Utility Lines Above	Poor (21% to 40%)	Topped	Crown Density - Low	Epicormic Growth
SW 1ST AVE	Jacaranda	6-10"	No	20'	Utility Lines Above	Poor (21% to 40%)	Leader - Broken	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Broken Branches	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Grafted Branches	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	Codominant Leaders/No Included Bark
SW 1ST AVE	Christmas Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Surinam Cherry	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)	Codominant Leaders/Included Bark
SW 1ST AVE	Weeping Fig	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Restricted Canopy	Sprouting
SW 1ST AVE	Weeping Fig	21-30"	Yes	30'	Utility Lines Above	Fair (41% to 60%)	Discolored Foliage	Restricted Canopy	Dead Wood
SW 1ST AVE	Mahogany	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Grafted with Adjacent Tree	Restricted Canopy	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Mahogany	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Jacaranda	1-5"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Codominant Leaders/Included Bark
SW 1ST AVE	Jacaranda	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Leader - Broken	Epicormic Growth	
SW 1ST AVE	Dracaena sp.	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Grafted with Adjacent Tree	
SW 1ST AVE	Weeping Fig	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Topped	Restricted Canopy	Sprouting
SW 1ST AVE	Dracaena sp.	16-20"	Yes	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Pruned Into Shrub	Sprouting
SW 1ST AVE	Mahogany	1-5"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lifting	Restricted Canopy	Suppressed Canopy
SW 1ST AVE	Mahogany	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Grafted with Adjacent Tree
SW 1ST AVE	Mahogany	6-10"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Vine Cover - Heavy	Restricted Canopy	Grafted with Adjacent Tree
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Stubs with Sprouts	Restricted Canopy	Grafted with Adjacent Tree
SW 1ST AVE	Mahogany	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Stubs with Sprouts	Restricted Canopy	Limb Damage - Moderate
SW 1ST AVE	Mahogany	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Epicormic Growth	Restricted Canopy	Grafted with Adjacent Tree
SW 1ST AVE	Weeping Fig	31-40"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Crown Density - Low	Restricted Canopy	Epicormic Growth
SW 1ST AVE	Gumbo Limbo	1-5"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lifting	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 1ST AVE	Jacaranda	11-15"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Leader - Broken	Sprouting	Restricted Canopy
SW 1ST AVE	Weeping Fig	6-10"	No	Negligible	Utility Lines Above	Dead (0% to 5%)	Leader - Broken	Dead Wood	Sloughing Bark
SW 1ST AVE	Dracaena sp.	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Mango	1-5"	No	15'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Restricted Canopy
SW 1ST AVE	Gumbo Limbo	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Gumbo Limbo	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Crown Density - Low
SW 1ST AVE	Gumbo Limbo	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Adjacent Concrete Damage	Trunk Damage - Major	Ficus Growing on Tree
SW 1ST AVE	Coconut Palm	11-15"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	16-20"	Yes	20'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Christmas Palm	16-20"	Yes	20'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Damaged Fronds		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Damaged Fronds		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Damaged Fronds		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Montgomery Palm	6-10"	Yes	15'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Insect Damage Leaves	
SW 1ST AVE	Montgomery Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Jacaranda	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Codominant Leaders/No Included Bark	Epicormic Growth	Crown Density - Low
SW 1ST AVE	Sapodilla	16-20"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Glaucous Cassia	6-10"	No	15'	Utility Lines Above	Poor (21% to 40%)	Uprooted - Mostly	Sloughing Bark	Topped
SW 1ST AVE	Weeping Fig	11-15"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Pruned Into Shrub
SW 1ST AVE	Weeping Fig	6-10"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Pruned Into Shrub
SW 1ST AVE	Coconut Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Over Pruned	Lopsided/Significantly Reduced Canopy	Nutrient Deficiency
SW 1ST AVE	Solitaire Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Solitaire Palm	6-10"	Yes	15'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Damaged Fronds	
SW 1ST AVE	Solitaire Palm	11-15"	Yes	20'	Utility Lines Above	Good (61% to 80%)	Damaged Fronds		
SW 1ST AVE	Solitaire Palm	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Damaged Fronds	Nutrient Deficiency	Restricted Canopy
SW 1ST AVE	Solitaire Palm	11-15"	Yes	15'	Utility Line Conflict	Fair (41% to 60%)	Damaged Fronds	Restricted Canopy	One Dead Trunk
SW 1ST AVE	Florida Thatch Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Florida Thatch Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Florida Thatch Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Florida Thatch Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Japanese Blueberry	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Topped	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Japanese Blueberry	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Green Buttonwood	6-10"	Yes	10'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 1ST AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Queen Crepe Myrtle	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Seasonal Defoliation/Discolored Foliage	Leader - Broken	Stubs with Sprouts
SW 1ST AVE	Cabbage Palm	31-40"	Yes	20'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	Ficus Growing on Tree
SW 1ST AVE	Cabbage Palm	16-20"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	
SW 1ST AVE	Cabbage Palm	16-20"	Yes	10'	Utility Line Conflict	Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	Damaged Fronds
SW 1ST AVE	Jacaranda	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Leader - Bent	Epicormic Growth
SW 1ST AVE	Jacaranda	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Leader - Bent	Vine Cover - Heavy
SW 1ST AVE	Mahogany	21-30"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Reduced Canopy - Major	Decay Observed	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Reduced Canopy - Moderate	Decay Observed	Topped
SW 1ST AVE	Black Olive	21-30"	No	30'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Trunk Damage - Major	Sloughing Bark	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Mahogany	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Limb Damage - Major	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Gumbo Limbo	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Utility Pruned	Stubs with Sprouts	Lopsided/Moderately Reduced Canopy
SW 1ST AVE	Horseflesh Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Horseflesh Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Broken Branches
SW 1ST AVE	Horseflesh Mahogany	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Girdling Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 1ST AVE	Yellow Tabebuia	11-15"	No	30'		Poor (21% to 40%)	Topped	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Horseflesh Mahogany	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Mahogany	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 1ST AVE	Mahogany	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 1ST AVE	Mahogany	21-30"	No	50'		Fair (41% to 60%)	Girdling Roots	Dead Wood	Codominant Leaders/Included Bark
SW 1ST AVE	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 1ST AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Trunk Damage - Minor
SW 1ST AVE	Crepe Myrtle	6-10"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Grafted Branches
SW 1ST AVE	Crepe Myrtle	6-10"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Grafted Branches
SW 1ST AVE	Crepe Myrtle	6-10"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 1ST AVE	Yellow Tabebuia	11-15"	No	20'		Poor (21% to 40%)	Plunged	Crown Density - Low	Stubs with Sprouts
SW 1ST AVE	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Girdling Roots	Adjacent Asphalt Damage	Stubs with Sprouts
SW 1ST AVE	Mahogany	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 1ST AVE	Green Buttonwood	6-10"	No	20'		Good (61% to 80%)	Adjacent Asphalt Damage	Leader - Bent	Stubs with Sprouts
SW 1ST AVE	Green Buttonwood	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Yellow Tabebuia	6-10"	No	10'		Poor (21% to 40%)	Trunk Damage - Moderate	Topped	Galls
SW 1ST AVE	Green Buttonwood	6-10"	No	15'		Fair (41% to 60%)	Galls	Epicormic Growth	Broken Branches
SW 1ST AVE	Green Buttonwood	6-10"	No	10'		Poor (21% to 40%)	Girdling Roots	Galls	Apical Dieback
SW 1ST AVE	Green Buttonwood	6-10"	No	10'		Good (61% to 80%)	Trunk Damage - Minor	Epicormic Growth	Broken Branches
SW 1ST AVE	Brazilian Beauty Leaf	16-20"	No	35'		Poor (21% to 40%)	Limb Damage - Major	Apical Dieback	Decay Observed
SW 1ST AVE	Brazilian Beauty Leaf	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Broken Branches
SW 1ST AVE	Neem Tree	51-60"	No	50'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Decay Observed
SW 1ST AVE	Silk Floss Tree	1-5"	No	15'		Fair (41% to 60%)	Discolored Foliage	Epicormic Growth	Codominant Leaders/Included Bark
SW 1ST AVE	Pink Tabebuia	6-10"	No	15'		Poor (21% to 40%)	Sloughing Bark	Apical Dieback	Stubs with Sprouts
SW 1ST AVE	Pink Tabebuia	11-15"	No	20'		Poor (21% to 40%)	Trunk Damage - Moderate	Apical Dieback	Stubs with Sprouts
SW 1ST AVE	Mahogany	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 1ST AVE	Mahogany	11-15"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 1ST AVE	Mahogany	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Discolored Foliage	Apical Dieback
SW 1ST AVE	Mahogany	6-10"	No	25'		Poor (21% to 40%)	Girdling Roots	Discolored Foliage	Apical Dieback
SW 1ST AVE	Mahogany	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Yellow Tabebuia	6-10"	No	15'		Poor (21% to 40%)	Discolored Foliage	Trunk Damage - Major	Limb Damage - Major
SW 1ST AVE	Mahogany	6-10"	No	10'		Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	Apical Dieback
SW 1ST AVE	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Girdling Roots	Dead Wood	Apical Dieback
SW 1ST AVE	Mahogany	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Epicormic Growth
SW 1ST AVE	Mahogany	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Galls	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Dead Wood
SW 1ST AVE	Brazilian Beauty Leaf	11-15"	No	25'		Poor (21% to 40%)	Sloughing Bark	Apical Dieback	Epicormic Growth
SW 1ST AVE	Brazilian Beauty Leaf	11-15"	No	30'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Decay Observed
SW 1ST AVE	Live Oak	6-10"	No	30'		Poor (21% to 40%)	Apical Dieback	Crown Density - Low	Epicormic Growth
SW 1ST AVE	Live Oak	16-20"	No	45'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 1ST AVE	Live Oak	11-15"	No	45'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Live Oak	11-15"	No	40'		Poor (21% to 40%)	Plunged	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 1ST AVE	Royal Poinciana	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Broken Branches

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Royal Poinciana	11-15"	No	40'		Fair (41% to 60%)	Apical Dieback	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Live Oak	11-15"	No	35'		Poor (21% to 40%)	Lopsided/Moderately Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 1ST AVE	Live Oak	16-20"	No	50'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Live Oak	11-15"	No	40'		Poor (21% to 40%)	Lopsided/Moderately Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 1ST AVE	Royal Poinciana	21-30"	No	60'		Good (61% to 80%)	Adjacent Asphalt Damage	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	Live Oak	11-15"	No	40'		Poor (21% to 40%)	Root Damage/Decay	Apical Dieback	Epicormic Growth
SW 1ST AVE	Live Oak	11-15"	No	35'		Poor (21% to 40%)	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback	Codominant Leaders/No Included Bark
SW 1ST AVE	Horseflesh Mahogany	31-40"	No	55'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Trunk Damage - Major
SW 1ST AVE	Horseflesh Mahogany	21-30"	No	50'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Mahogany	31-40"	No	60'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Broken Branches
SW 1ST AVE	Mahogany	21-30"	No	55'		Good (61% to 80%)	Trunk Damage - Minor	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Mahogany	31-40"	No	55'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Mahogany	21-30"	No	45'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)			
SW 1ST AVE	Mahogany	21-30"	No	45'		Good (61% to 80%)	Adjacent Asphalt Damage	Epicormic Growth	Codominant Leaders/No Included Bark
SW 1ST AVE	Mahogany	16-20"	No	45'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Broken Branches
SW 1ST AVE	Mahogany	21-30"	No	45'		Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Mahogany	21-30"	No	55'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Stubs with Sprouts	Limb Damage - Moderate
SW 1ST AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	45'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Dead Wood
SW 1ST AVE	Mahogany	21-30"	No	45'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Dead Wood
SW 1ST AVE	Yellow Poinciana	11-15"	No	35'		Fair (41% to 60%)	Limb Damage - Moderate	Stubs with Sprouts	Trunk Damage - Minor
SW 1ST AVE	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Trunk Damage - Moderate	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Gumbo Limbo	16-20"	No	40'		Good (61% to 80%)	Trunk Damage - Minor	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Mahogany	31-40"	No	55'		Fair (41% to 60%)	Trunk Damage - Moderate	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Mahogany	1-5"	No	10'		Poor (21% to 40%)	Girdling Roots	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Mahogany	21-30"	No	45'		Fair (41% to 60%)	Girdling Roots	Dead Wood	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	6-10"	No	10'	Utility Lines Above	Poor (21% to 40%)	Suppressed Canopy	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 1ST AVE	Gumbo Limbo	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Decay Observed	Dead Wood	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	1-5"	No	15'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	1-5"	No	20'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Lion's Tailing	Codominant Leaders/No Included Bark
SW 1ST AVE	Royal Poinciana	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Stubs
SW 1ST AVE	Royal Poinciana	1-5"	No	20'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Leader - Bent
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Areca Palm	21-30"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Pigeon Plum	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Epicormic Growth
SW 1ST AVE	Christmas Palm	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Mahogany	21-30"	No	40'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Decay Observed	Utility Pruned
SW 1ST AVE	Mahogany	21-30"	No	45'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Decay Observed	Utility Pruned
SW 1ST AVE	Java Bishopwood	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Mahogany	31-40"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Washington Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 1ST AVE	Mahogany	21-30"	No	15'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	25'	Utility Lines Above	Very Poor/Critical (6% to 20%)	Constricted Roots	Decay Observed	Lopsided/Reduced Canopy - Major
SW 1ST AVE	Royal Poinciana	21-30"	No	65'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 1ST AVE	Christmas Palm	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency	Suppressed Canopy	Restricted Canopy
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)	Damaged Fronds	Suppressed Canopy	Restricted Canopy
SW 1ST AVE	Areca Palm	16-20"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Suppressed Canopy	
SW 1ST AVE	Umbrella Tree	6-10"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Live Oak	31-40"	No	55'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Dead Wood	Utility Pruned
SW 1ST AVE	Australian Pine	1-5"	No	15'	Utility Line Conflict	Good (61% to 80%)			
SW 1ST AVE	Royal Poinciana	31-40"	No	70'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 1ST AVE	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Gumbo Limbo	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	21-30"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Lines Above	Poor (21% to 40%)	Girdling Roots	Tip Dieback	Epicormic Growth
SW 1ST AVE	Gumbo Limbo	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	16-20"	No	40'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Cracks in Trunk	Stubs with Sprouts
SW 1ST AVE	Maple Leaved Bayur	31-40"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Weeping Fig	31-40"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 1ST AVE	Gumbo Limbo	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Restricted Canopy	Sprouting
SW 1ST AVE	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Mahogany	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	15'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Cabbage Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Royal Poinciana	16-20"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/Included Bark	Suppressed Canopy
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Very Poor/Critical (6% to 20%)	Improperly Mulched	Crown Density - Very Low	Suppressed Canopy
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Dead (0% to 5%)	Improperly Mulched	Dead Wood	Suppressed Canopy
SW 1ST AVE	Royal Poinciana	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Broken Branches
SW 1ST AVE	Live Oak	6-10"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Low
SW 1ST AVE	Live Oak	6-10"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Lifting	Apical Dieback
SW 1ST AVE	Spanish Lime	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Coconut Palm	1-5"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Orange Geiger	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Stubs with Sprouts
SW 1ST AVE	Mango	1-5"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Insect Damage Leaves	Basal Co-Dominant
SW 1ST AVE	Mahogany	16-20"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Montgomery Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Trunk Damage - Major	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Montgomery Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Montgomery Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Trunk Damage - Moderate		
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Bottlebrush	11-15"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Topped	Stubs with Sprouts
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Grafted with Adjacent Tree
SW 1ST AVE	Silver Buttonwood	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Recumbent
SW 1ST AVE	Silver Buttonwood	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Recumbent
SW 1ST AVE	Pygmy Date Palm	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Pygmy Date Palm	6-10"	Yes	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Gumbo Limbo	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Gumbo Limbo	21-30"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Gumbo Limbo	11-15"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Black Olive	11-15"	No	20'	Utility Lines Above	Fair (41% to 60%)	Topped	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Black Olive	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 1ST AVE	Black Olive	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Black Olive	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Lateral Branching - None
SW 1ST AVE	Black Olive	16-20"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 1ST AVE	Black Olive	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 1ST AVE	Mango	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Codominant Leaders/No Included Bark
SW 1ST AVE	Mango	1-5"	Yes	10'		Fair (41% to 60%)	Topped	Suppressed Canopy	Stubs with Sprouts
SW 1ST AVE	Mango	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Suppressed Canopy	Broken Branches
SW 1ST AVE	White Geiger	1-5"	Yes	10'		Fair (41% to 60%)	Codominant Leaders/Included Bark	Topped	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Trunk Damage - Minor	Suppressed Canopy	
SW 1ST AVE	Coconut Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Dracaena sp.	21-30"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)			
SW 1ST AVE	Montgomery Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Live Oak	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Suppressed Canopy		
SW 1ST AVE	Live Oak	21-30"	No	55'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 1ST AVE	Manila Tamarind	1-5"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Manila Tamarind	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Codominant Leaders/No Included Bark
SW 1ST AVE	Mahogany	1-5"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Live Oak	31-40"	No	60'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	White Frangipani	11-15"	Yes	20'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Seasonal Defoliation/Discolored Foliage
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Suppressed Canopy	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Manila Tamarind	6-10"	No	25'		Fair (41% to 60%)	Limb Damage - Moderate	Epicormic Growth	Grafted with Adjacent Tree
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Live Oak	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	
SW 1ST AVE	Mahogany	1-5"	Yes	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Leader - Bent	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Fair (41% to 60%)	Insect Damage Leaves	Restricted Canopy	
SW 1ST AVE	Live Oak	1-5"	No	5'		Good (61% to 80%)	Leaning - Moderate	Epicormic Growth	
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Stubs with Sprouts	
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/Included Bark	
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Sprouting
SW 1ST AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Restricted Canopy	Suppressed Canopy
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Restricted Canopy	Suppressed Canopy
SW 1ST AVE	Live Oak	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 1ST AVE	Pigeon Plum	6-10"	No	15'		Poor (21% to 40%)	Decay Observed	Stubs with Sprouts	Topped
SW 1ST AVE	Washington Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	6-10"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	11-15"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Mahogany	31-40"	No	25'		Very Poor/Critical (6% to 20%)	Decay Observed	Sloughing Bark	Dead Wood
SW 1ST AVE	Coconut Palm	6-10"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Cabbage Palm	16-20"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	11-15"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Mahogany	21-30"	No	30'		Very Poor/Critical (6% to 20%)	Constricted Roots	Decay Observed	Dead Wood
SW 1ST AVE	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Christmas Palm	1-5"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Jacaranda	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Broken Branches	Apical Dieback
SW 1ST AVE	Jacaranda	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Apical Dieback
SW 1ST AVE	Gumbo Limbo	6-10"	No	10'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant with Adjacent Tree(s)	Apical Dieback
SW 1ST AVE	Gumbo Limbo	11-15"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant with Adjacent Tree(s)	Apical Dieback
SW 1ST AVE	Gumbo Limbo	6-10"	No	10'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Leader - Broken
SW 1ST AVE	Pigeon Plum	11-15"	Yes	10'	Utility Lines Above	Very Poor/Critical (6% to 20%)	Sloughing Bark	Decay Observed	Apical Dieback
SW 1ST AVE	Pigeon Plum	6-10"	Yes	10'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Grafted Branches	Apical Dieback
SW 1ST AVE	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	11-15"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Cabbage Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Live Oak	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Restricted Canopy	Leader - Bent	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Black Olive	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Broken Branches
SW 1ST AVE	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	16-20"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Cabbage Palm	11-15"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Christmas Palm	6-10"	No	5'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Christmas Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Live Oak	11-15"	No	25'	Utility Lines Above	Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 1ST AVE	Banana Tree	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Banana Tree	21-30"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Live Oak	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 1ST AVE	Black Olive	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Brazilian Pepper	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Basal Co-Dominant with Adjacent Tree(s)
SW 1ST AVE	Mahogany	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Mahogany	21-30"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Lopsided/Significantly Reduced Canopy

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	White Geiger	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	White Fly	
SW 1ST AVE	Mahogany	21-30"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Major
SW 1ST AVE	Mahogany	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	21-30"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Pink Tabebuia	21-30"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Stubs with Sprouts	
SW 1ST AVE	Pink Tabebuia	6-10"	Yes	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	Pink Tabebuia	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 1ST AVE	Dracaena sp.	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Broken Branches		
SW 1ST AVE	Yellow Poinciana	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Crown Density - Low	Epicormic Growth
SW 1ST AVE	Yellow Poinciana	11-15"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth
SW 1ST AVE	Indian Laurel Fig	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Royal Poinciana	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Dracaena sp.	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Royal Poinciana	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 1ST AVE	Strangler Fig	31-40"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Mahogany	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Unidentified Dead Tree (Defoliated)	6-10"	No	10'		Dead (0% to 5%)	Dead Wood	Sloughing Bark	
SW 1ST AVE	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	Gumbo Limbo	6-10"	No	15'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 1ST AVE	Gumbo Limbo	6-10"	No	10'		Fair (41% to 60%)	Constricted Roots	Cavities	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Cabbage Palm	11-15"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	Ficus Growing on Tree
SW 1ST AVE	Queen Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 1ST AVE	Queen Palm	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Gumbo Limbo	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Leader - Broken	Stubs with Sprouts
SW 1ST AVE	Live Oak	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)
SW 1ST AVE	Live Oak	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Trunk Damage - Moderate	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Live Oak	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Leader - Bent	Epicormic Growth	Apical Dieback
SW 1ST AVE	Live Oak	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Apical Dieback
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Foxtail Palm	11-15"	Yes	20'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Foxtail Palm	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Gumbo Limbo	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Grafted Branches
SW 1ST AVE	Montgomery Palm	11-15"	Yes	20'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Grafted Branches	Epicormic Growth
SW 1ST AVE	Japanese Privet	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Epicormic Growth	Pruned Into Shrub	
SW 1ST AVE	Hibiscus sp.	1-5"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Codominant Leaders/Included Bark	Pruned Into Shrub
SW 1ST AVE	Black Olive	21-30"	No	35'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Black Olive	21-30"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Cavities
SW 1ST AVE	Mahogany	31-40"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Broken Branches	Dead Wood
SW 1ST AVE	Java Bishopwood	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Trunk Damage - Minor
SW 1ST AVE	Paradise Tree	6-10"	No	10'		Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Mahogany	31-40"	No	45'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 1ST AVE	Mahogany	41-50"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Grafted Branches
SW 1ST AVE	Mahogany	21-30"	No	10'		Fair (41% to 60%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark
SW 1ST AVE	Pink Tabebuia	11-15"	No	15'		Fair (41% to 60%)	Trunk Damage - Moderate	Broken Branches	Epicormic Growth
SW 1ST AVE	Crepe Myrtle	11-15"	Yes	5'		Fair (41% to 60%)	Topped	Seasonal Defoliation/Discolored Foliage	Stubs with Sprouts
SW 1ST AVE	Crepe Myrtle	11-15"	Yes	5'		Fair (41% to 60%)	Topped	Seasonal Defoliation/Discolored Foliage	Epicormic Growth
SW 1ST AVE	Banyan	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	White Fly	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)			
SW 1ST AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 1ST AVE	Yellow Tabebuia	11-15"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Leader - Broken
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Solitaire Palm	1-5"	No	Negligible		Dead (0% to 5%)	Dead Meristem		
SW 1ST AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 1ST AVE	Cabbage Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Banyan	41-50"	No	40'		Fair (41% to 60%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Hibiscus sp.	11-15"	Yes	15'		Good (61% to 80%)	Grafted Branches	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Live Oak	11-15"	No	20'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Reduced Canopy - Moderate	Epicormic Growth
SW 1ST AVE	Black Olive	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 1ST AVE	White Frangipani	1-5"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Broken Branches	
SW 1ST AVE	White Frangipani	6-10"	No	15'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Dead Wood	Codominant Leaders/No Included Bark
SW 1ST AVE	Tree of Heaven	11-15"	No	20'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Suppressed Canopy
SW 1ST AVE	Camphor Tree	11-15"	No	20'		Poor (21% to 40%)	Basal Co-Dominant	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Spindle Palm	1-5"	No	5'		Poor (21% to 40%)	Nutrient Deficiency		
SW 1ST AVE	Spindle Palm	6-10"	No	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Spindle Palm	6-10"	No	5'		Poor (21% to 40%)	Nutrient Deficiency		
SW 1ST AVE	Spindle Palm	6-10"	No	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 1ST AVE	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 1ST AVE	Weeping Fig	16-20"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 1ST AVE	Weeping Fig	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Chinaberry	11-15"	Yes	20'		Fair (41% to 60%)	Apical Dieback	Dead Wood	Codominant Leaders/No Included Bark
SW 1ST AVE	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Canary Island Date Palm	41-50"	No	25'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	Vine Cover - Heavy
SW 1ST AVE	Canary Island Date Palm	21-30"	No	5'		Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	Strap Constricting Fronds
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	
SW 1ST AVE	Queen Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Damaged Fronds		
SW 1ST AVE	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Insect Damage Leaves		
SW 1ST AVE	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Insect Damage Leaves		
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Sprouting	
SW 1ST AVE	Weeping Fig	6-10"	No	5'		Poor (21% to 40%)	Basal Co-Dominant	White Fly	Pruned Into Shrub

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 1ST AVE	Black Olive	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 1ST AVE	Pigeon Plum	6-10"	No	10'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	

SW 2nd Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 2ND AVE	Chinese Fan Palm	16-20"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 2ND AVE	Chinese Fan Palm	11-15"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 2ND AVE	Chinese Fan Palm	16-20"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 2ND AVE	Chinese Fan Palm	16-20"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 2ND AVE	White Frangipani	1-5"	No	5'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Sprouting
SW 2ND AVE	Live Oak	1-5"	No	5'		Poor (21% to 40%)	Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Tip Dieback
SW 2ND AVE	Spindle Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Live Oak	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Epicormic Growth
SW 2ND AVE	Live Oak	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Epicormic Growth
SW 2ND AVE	Jerusaelm Thorn	1-5"	No	5'		Poor (21% to 40%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 2ND AVE	Jerusaelm Thorn	1-5"	No	5'		Poor (21% to 40%)	Basal Co-Dominant	Topped	Limb Damage - Moderate
SW 2ND AVE	Live Oak	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 2ND AVE	Tamarind	16-20"	No	20'		Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Tip Dieback
SW 2ND AVE	White Frangipani	1-5"	No	5'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Sprouting	
SW 2ND AVE	White Frangipani	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Seasonal Defoliation/Discolored Foliage
SW 2ND AVE	White Frangipani	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Sprouting	Seasonal Defoliation/Discolored Foliage
SW 2ND AVE	Gumbo Limbo	6-10"	No	15'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Lopsided/Reduced Canopy - Moderate
SW 2ND AVE	Gumbo Limbo	6-10"	No	15'		Poor (21% to 40%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Lopsided/Reduced Canopy - Major
SW 2ND AVE	Gumbo Limbo	6-10"	No	15'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Lopsided/Reduced Canopy - Moderate
SW 2ND AVE	Royal Poinciana	31-40"	No	75'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Dead Wood
SW 2ND AVE	Jacaranda	21-30"	No	40'		Poor (21% to 40%)	Trunk Damage - Major	Lopsided/Reduced Canopy - Major	Epicormic Growth
SW 2ND AVE	Mahogany	11-15"	No	35'		Poor (21% to 40%)	Leader - Broken	Lopsided/Reduced Canopy - Moderate	Epicormic Growth
SW 2ND AVE	Mahogany	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 2ND AVE	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 2ND AVE	Mahogany	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 2ND AVE	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 2ND AVE	Mahogany	11-15"	No	25'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Insect Damage Leaves
SW 2ND AVE	Mahogany	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 2ND AVE	Live Oak	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Tip Dieback	Epicormic Growth
SW 2ND AVE	Silver Buttonwood	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Broken Branches
SW 2ND AVE	Washington Palm	11-15"	No	15'		Good (61% to 80%)			
SW 2ND AVE	Washington Palm	11-15"	No	15'		Good (61% to 80%)			
SW 2ND AVE	Silver Buttonwood	11-15"	No	20'		Good (61% to 80%)	Codominant Leaders/Included Bark	Stubs with Sprouts	Restricted Canopy

(Continued on Next Page)

Street Tree Inventory

SW 2nd Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 2ND AVE	Japanese Privet	6-10"	Yes	15'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Limb Damage - Minor
SW 2ND AVE	Silver Buttonwood	11-15"	No	20'		Good (61% to 80%)	Codominant Leaders/Included Bark	Stubs with Sprouts	
SW 2ND AVE	Japanese Privet	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Sloughing Bark	Dead Wood
SW 2ND AVE	Silver Buttonwood	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 2ND AVE	Bismark Palm	16-20"	No	20'		Good (61% to 80%)			
SW 2ND AVE	Bismark Palm	11-15"	No	15'		Good (61% to 80%)	Strap Constricting Tree		
SW 2ND AVE	Bismark Palm	16-20"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 2ND AVE	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Vine Cover - Heavy
SW 2ND AVE	Gumbo Limbo	6-10"	No	10'		Poor (21% to 40%)	Constricted Roots	Ficus Growing on Tree	Reduced Canopy - Moderate
SW 2ND AVE	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Vine Cover - Heavy
SW 2ND AVE	Mahogany	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 2ND AVE	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 2ND AVE	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 2ND AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 2ND AVE	Gumbo Limbo	31-40"	Yes	25'		Poor (21% to 40%)	Basal Co-Dominant	Tip Dieback	Stubs with Sprouts
SW 2ND AVE	Coconut Palm	11-15"	No	25'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 2ND AVE	Gumbo Limbo	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 2ND AVE	Black Olive	11-15"	No	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 2ND AVE	Black Olive	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 2ND AVE	Black Olive	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 2ND AVE	Black Olive	16-20"	No	20'	Utility Lines Adjacent (laterally)	Very Poor/Critical (6% to 20%)	Sloughing Bark	Decay Observed	Crown Density - Very Low
SW 2ND AVE	Black Olive	6-10"	No	15'		Fair (41% to 60%)	Decay Observed	Dead Wood	Stubs with Sprouts
SW 2ND AVE	Coconut Palm	6-10"	No	25'		Good (61% to 80%)			
SW 2ND AVE	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 2ND AVE	Coconut Palm	11-15"	No	25'		Good (61% to 80%)	Nutrient Deficiency	Damaged Fronds	Restricted Canopy
SW 2ND AVE	Bismark Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Bismark Palm	16-20"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Strap Constricting Tree
SW 2ND AVE	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Tip Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 2ND AVE	Vera Wood	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	
SW 2ND AVE	Vera Wood	1-5"	No	5'		Fair (41% to 60%)	Tip Dieback	Strap Constricting Tree	Codominant Leaders/No Included Bark
SW 2ND AVE	Washington Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Mahogany	31-40"	No	35'	Utility Lines Adjacent (laterally)	Very Poor/Critical (6% to 20%)	Crown Density - Very Low	Decay Observed	Epicormic Growth
SW 2ND AVE	Gumbo Limbo	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	
SW 2ND AVE	Peregrina	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 2ND AVE	Peregrina	1-5"	Yes	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 2ND AVE	Bismark Palm	16-20"	No	25'		Good (61% to 80%)			
SW 2ND AVE	Bismark Palm	16-20"	No	25'		Good (61% to 80%)			
SW 2ND AVE	Sapodilla	41-50"	No	60'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 2ND AVE	Sapodilla	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 2ND AVE	Mahogany	16-20"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 2ND AVE	Mahogany	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 2ND AVE	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 2ND AVE	Gumbo Limbo	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Leader - Broken	Stubs with Sprouts
SW 2ND AVE	Black Olive	6-10"	No	5'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Decay Observed	Pruned Into Shrub
SW 2ND AVE	Silver Buttonwood	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Sprouting		
SW 2ND AVE	Silver Buttonwood	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Sprouting	Broken Branches	
SW 2ND AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 2ND AVE	Umbrella Tree	16-20"	No	10'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 2ND AVE	Umbrella Tree	21-30"	No	10'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 2ND AVE	Umbrella Tree	16-20"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Decay Observed

(Continued on Next Page)

Street Tree Inventory

SW 2nd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 2ND AVE	Cabbage Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Cabbage Palm	11-15"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 2ND AVE	Live Oak	21-30"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Stubs with Sprouts
SW 2ND AVE	Dracaena sp.	11-15"	Yes	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Grafted Branches	
SW 2ND AVE	Dracaena sp.	11-15"	Yes	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Grafted Branches	
SW 2ND AVE	Spindle Palm	11-15"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Spindle Palm	16-20"	No	5'		Good (61% to 80%)			
SW 2ND AVE	Spindle Palm	11-15"	No	5'		Good (61% to 80%)			
SW 2ND AVE	Royal Palm	16-20"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 2ND AVE	Royal Poinciana	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 2ND AVE	Solitaire Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 2ND AVE	Dracaena sp.	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 2ND AVE	Dracaena sp.	6-10"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 2ND AVE	Dracaena sp.	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 2ND AVE	Live Oak	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 2ND AVE	Mahogany	16-20"	No	40'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 2ND AVE	Areca Palm	41-50"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Areca Palm	51-60"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Gumbo Limbo	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lifting	Codominant Leaders/No Included Bark	
SW 2ND AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Discolored Foliage	Codominant Leaders/Included Bark	Restricted Canopy
SW 2ND AVE	Foxtail Palm	6-10"	No	5'	Utility Lines Above	Poor (21% to 40%)	Nutrient Deficiency	Frizzled Fronds	Reduced Canopy - Moderate
SW 2ND AVE	Foxtail Palm	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 2ND AVE	Foxtail Palm	6-10"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 2ND AVE	Cabbage Palm	16-20"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 2ND AVE	Foxtail Palm	6-10"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 2ND AVE	Cabbage Palm	16-20"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 2ND AVE	Mahogany	21-30"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Lopsided/Reduced Canopy - Moderate	Broken Branches
SW 2ND AVE	Mahogany	31-40"	No	35'		Poor (21% to 40%)	Girdling Roots	Lopsided/Reduced Canopy - Major	Trunk Damage - Major
SW 2ND AVE	Mahogany	31-40"	No	40'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 2ND AVE	Royal Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 2ND AVE	Dracaena sp.	21-30"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 2ND AVE	Royal Poinciana	21-30"	Yes	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Grafted Branches	Dead Wood
SW 2ND AVE	Umbrella Tree	6-10"	No	15'		Good (61% to 80%)	Trunk Damage - Minor	Codominant Leaders/No Included Bark	Restricted Canopy
SW 2ND AVE	Royal Poinciana	21-30"	No	35'		Fair (41% to 60%)	Constricted Roots	Basal Co-Dominant	Decay Observed
SW 2ND AVE	Royal Poinciana	21-30"	Yes	50'		Fair (41% to 60%)	Decay Observed	Grafted Branches	Stubs with Sprouts
SW 2ND AVE	Dracaena sp.	21-30"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 2ND AVE	Hong Kong Orchid	6-10"	No	10'		Poor (21% to 40%)	Decay Observed	Sloughing Bark	Leader - Broken
SW 2ND AVE	Mahogany	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 2ND AVE	Mahogany	6-10"	No	10'		Good (61% to 80%)	Trunk Damage - Minor	Codominant Leaders/No Included Bark	Restricted Canopy
SW 2ND AVE	Mahogany	21-30"	No	45'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 2ND AVE	Pongam	21-30"	No	35'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Cavities	Stubs with Sprouts
SW 2ND AVE	Hong Kong Orchid	1-5"	No	10'		Very Poor/Critical (6% to 20%)	Decay Observed	Sprouting	Trunk Damage - Major
SW 2ND AVE	Royal Poinciana	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 2ND AVE	Royal Poinciana	11-15"	No	45'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 2ND AVE	Yellow Tabebuia	11-15"	No	20'		Fair (41% to 60%)	Root Flair - None	Dead Wood	Stubs with Sprouts
SW 2ND AVE	Mahogany	16-20"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 2ND AVE	Vera Wood	6-10"	No	20'		Fair (41% to 60%)	Tip Dieback	Codominant Leaders/No Included Bark	Epicormic Growth
SW 2ND AVE	Vera Wood	6-10"	No	20'		Poor (21% to 40%)	Girdling Roots	Lopsided/Reduced Canopy - Moderate	Dead Wood
SW 2ND AVE	Vera Wood	6-10"	No	20'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 2ND AVE	Vera Wood	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Crown Density - Excessive (Due to Epicormic Growth)	Broken Branches	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 2nd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 2ND AVE	Carrotwood	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Tip Dieback	Decay Observed
SW 2ND AVE	Green Buttonwood	11-15"	No	25'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 2ND AVE	Hong Kong Orchid	16-20"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 2ND AVE	Green Buttonwood	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Trunk Damage - Minor
SW 2ND AVE	Royal Poinciana	11-15"	No	40'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Dead Wood
SW 2ND AVE	Hong Kong Orchid	11-15"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Tip Dieback	Stubs with Sprouts
SW 2ND AVE	Green Buttonwood	6-10"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 2ND AVE	Green Buttonwood	11-15"	No	30'		Fair (41% to 60%)	Tip Dieback	Epicormic Growth	Codominant Leaders/No Included Bark
SW 2ND AVE	Vera Wood	6-10"	No	20'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 2ND AVE	Green Buttonwood	6-10"	No	20'		Fair (41% to 60%)	Galls	Codominant Leaders/No Included Bark	Epicormic Growth
SW 2ND AVE	Pongam	31-40"	No	35'		Poor (21% to 40%)	Reduced Canopy - Moderate	Tip Dieback	Dead Wood
SW 2ND AVE	Sapodilla	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 2ND AVE	Pygmy Date Palm	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 2ND AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/Included Bark	Strap Constricting Tree	
SW 2ND AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	Sprouting
SW 2ND AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	Sprouting
SW 2ND AVE	Mahogany	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Trunk Damage - Minor	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 2ND AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 2ND AVE	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Tip Dieback	Epicormic Growth
SW 2ND AVE	Pink Tabebuia	6-10"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Topped	Stubs with Sprouts
SW 2ND AVE	Pink Tabebuia	6-10"	No	10'		Fair (41% to 60%)	Topped	Restricted Canopy	Sprouting
SW 2ND AVE	Pink Tabebuia	6-10"	No	15'		Fair (41% to 60%)	Girdling Roots	Restricted Canopy	Sprouting
SW 2ND AVE	Pink Tabebuia	6-10"	No	15'		Fair (41% to 60%)	Topped	Restricted Canopy	Stubs with Sprouts
SW 2ND AVE	Pink Tabebuia	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Sprouting
SW 2ND AVE	Pink Tabebuia	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Grafted Branches	Sprouting
SW 2ND AVE	Areca Palm	21-30"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Tip Dieback	Epicormic Growth
SW 2ND AVE	Mango	1-5"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Strap Constricting Tree	
SW 2ND AVE	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Tip Dieback	Epicormic Growth
SW 2ND AVE	Vera Wood	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Tip Dieback	Epicormic Growth
SW 2ND AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 2ND AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 2ND AVE	Vera Wood	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Tip Dieback	Epicormic Growth
SW 2ND AVE	Vera Wood	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Tip Dieback	Epicormic Growth
SW 2ND AVE	Canary Island Date Palm	21-30"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Ficus Growing on Tree		
SW 2ND AVE	Royal Palm	6-10"	No	Negligible	Utility Lines Adjacent (laterally)	Dead (0% to 5%)	Dead Meristem		
SW 2ND AVE	Starburst Clerodendron	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/Included Bark	Grafted Branches	Stubs with Sprouts
SW 2ND AVE	Live Oak	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Over Extended Limb(s)	Dead Wood
SW 2ND AVE	Yellow Tabebuia	6-10"	No	15'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 2ND AVE	Yellow Tabebuia	16-20"	No	20'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 2ND AVE	Royal Palm	11-15"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Mahogany	6-10"	No	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 2ND AVE	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 2ND AVE	Cabada Palm	31-40"	Yes	10'		Good (61% to 80%)			
SW 2ND AVE	Mahogany	21-30"	No	45'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 2nd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 2ND AVE	Mahogany	21-30"	No	45'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 2ND AVE	Mahogany	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 2ND AVE	Carolina Cherry Laurel	6-10"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Sprouting	Restricted Canopy
SW 2ND AVE	Carolina Cherry Laurel	6-10"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Sprouting	Restricted Canopy
SW 2ND AVE	Hong Kong Orchid	21-30"	No	5'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Decay Observed	Crown Density - Very Low	Dead Wood
SW 2ND AVE	Gumbo Limbo	6-10"	No	15'	Utility Lines Above	Fair (41% to 60%)	Tip Dieback	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 2ND AVE	Mahogany	16-20"	No	20'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Decay Observed	Crown Density - Very Low	Dead Wood
SW 2ND AVE	Mahogany	21-30"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 2ND AVE	Mahogany	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 2ND AVE	Mahogany	31-40"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 2ND AVE	Mahogany	31-40"	No	60'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 2ND AVE	Mahogany	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 2ND AVE	Mahogany	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Tip Dieback	Stubs with Sprouts
SW 2ND AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Topped	Stubs with Sprouts	Basal Co-Dominant
SW 2ND AVE	Weeping Fig	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Trunk Damage - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 2ND AVE	Weeping Fig	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Decay Observed	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 2ND AVE	Weeping Fig	6-10"	No	10'	Utility Lines Above	Very Poor/Critical (6% to 20%)	Decay Observed	Dead Wood	Crown Density - Very Low
SW 2ND AVE	Weeping Fig	6-10"	No	10'	Utility Lines Above	Poor (21% to 40%)	Galls	Crown Density - Low	Pruned Into Shrub
SW 2ND AVE	Weeping Fig	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Broken Branches	Crown Density - Low	Pruned Into Shrub
SW 2ND AVE	Weeping Fig	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Broken Branches	Crown Density - Low	Pruned Into Shrub
SW 2ND AVE	Spindle Palm	11-15"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 2ND AVE	Spindle Palm	16-20"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 2ND AVE	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 2ND AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 2ND AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 2ND AVE	White Frangipani	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Seasonal Defoliation/Discolored Foliage
SW 2ND AVE	Black Olive	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 2ND AVE	White Frangipani	6-10"	No	15'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Sprouting	Seasonal Defoliation/Discolored Foliage
SW 2ND AVE	Norfolk Pine	6-10"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 2ND AVE	Florida Thatch Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Reduced Canopy - Minor	
SW 2ND AVE	Foxtail Palm	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)			
SW 2ND AVE	Spindle Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 2ND AVE	Foxtail Palm	6-10"	No	15'	Utility Lines Above	Poor (21% to 40%)	Nutrient Deficiency	Frizzled Fronds	
SW 2ND AVE	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Spindle Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Mahogany	16-20"	No	35'	Utility Line Conflict	Good (61% to 80%)	Dead Wood	Broken Branches	Stubs with Sprouts
SW 2ND AVE	Mahogany	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Moderate	Decay Observed	Stubs with Sprouts
SW 2ND AVE	Weeping Fig	11-15"	No	20'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Grafted Branches	Epicormic Growth
SW 2ND AVE	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 2ND AVE	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 2ND AVE	White Frangipani	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Grafted Branches	Sprouting
SW 2ND AVE	Weeping Fig	11-15"	No	20'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Epicormic Growth
SW 2ND AVE	Mahogany	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 2ND AVE	Mahogany	21-30"	No	50'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 2ND AVE	Avocado	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Cavities	Stubs with Sprouts
SW 2ND AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 2ND AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 2ND AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 2ND AVE	Japanese Privet	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Sprouting	Pruned Into Shrub
SW 2ND AVE	Japanese Privet	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Stubs with Sprouts	Pruned Into Shrub

(Continued on Next Page)

Street Tree Inventory

SW 2nd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 2ND AVE	Japanese Privet	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Broken Branches	Epicormic Growth	Pruned Into Shrub
SW 2ND AVE	Japanese Privet	11-15"	No	15'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Grafted Branches	Pruned Into Shrub
SW 2ND AVE	Japanese Privet	16-20"	No	15'	Utility Lines Above	Good (61% to 80%)	Stubs with Sprouts	Restricted Canopy	Pruned Into Shrub
SW 2ND AVE	Pigeon Plum	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Plunged	Apical Dieback	Discolored Foliage
SW 2ND AVE	Pigeon Plum	1-5"	No	5'	Utility Lines Above	Dead (0% to 5%)	Plunged	Dead Wood	Sloughing Bark
SW 2ND AVE	Pygmy Date Palm	6-10"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 2ND AVE	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 2ND AVE	Christmas Palm	16-20"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 2ND AVE	Royal Poinciana	16-20"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Grafted with Adjacent Tree
SW 2ND AVE	Royal Poinciana	21-30"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Adjacent Asphalt Damage	Stubs with Sprouts	Grafted with Adjacent Tree
SW 2ND AVE	Foxtail Palm	1-5"	No	15'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 2ND AVE	Triangle Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 2ND AVE	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 2ND AVE	Black Olive	6-10"	No	30'		Poor (21% to 40%)	Plunged	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 2ND AVE	Black Olive	16-20"	No	30'		Poor (21% to 40%)	Topped	Crown Density - Excessive (Due to Epicormic Growth)	Decay Observed
SW 2ND AVE	Black Olive	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 2ND AVE	Mahogany	41-50"	No	40'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Vine Cover - Heavy
SW 2ND AVE	Weeping Fig	6-10"	No	10'		Fair (41% to 60%)	Leader - Broken	Pruned Into Shrub	Stubs with Sprouts
SW 2ND AVE	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Crown Density - Excessive (Due to Epicormic Growth)
SW 2ND AVE	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Crown Density - Low
SW 2ND AVE	Royal Poinciana	11-15"	No	30'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Grafted Branches	Stubs with Sprouts
SW 2ND AVE	Gumbo Limbo	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Grafted with Adjacent Tree
SW 2ND AVE	Gumbo Limbo	16-20"	No	20'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Grafted with Adjacent Tree
SW 2ND AVE	Weeping Fig	6-10"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Epicormic Growth

Avenues | Courts



Looking Northeast - SW 19th Road



Looking Northeast - Mid-Street



Looking Northeast - SW 16th Avenue



Looking Northeast - SW 12th Avenue



Looking Southwest - Mid-Street



Looking Southwest - SW 18th Road



Looking Southwest - SW 24th Road



Looking Southwest - SW 17th Road

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 2nd Court	1	Roads	3	50	600	No	No	No	2	City	Some	Few	10	No	Yes	Mostly on NW	Grass swales show sings of being parked on. Utility lines cross back and forth.
SW 3rd Avenue	1	Roads	3	120	8000	Yes	No	Some	4	State	Yes	Yes	8	NE of 22nd Street	Yes	No	Banyan trees provide dense canopy along median. Bike lanes going both directions.

SW 2nd Court

TYPOLOGY A

SW 3rd Avenue

TYPOLOGY H

Street Tree Inventory

SW 2nd Court

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 2ND CT	Mahogany	11-15"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant	Basal Co-Dominant with Adjacent Tree(s)	Stubs with Sprouts
SW 2ND CT	Live Oak	11-15"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant with Adjacent Tree(s)	Topped	Stubs with Sprouts
SW 2ND CT	Queen Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 2ND CT	Black Olive	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 2ND CT	Black Olive	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 2ND CT	Solitaire Palm	6-10"	Yes	15'	Utility Line Conflict	Good (61% to 80%)			
SW 2ND CT	Silver Buttonwood	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Pruned Into Shrub
SW 2ND CT	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 2ND CT	Simpson's Stopper	6-10"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Epicormic Growth	Grafted Branches
SW 2ND CT	Christmas Palm	16-20"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 2ND CT	Simpson's Stopper	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Epicormic Growth	
SW 2ND CT	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 2ND CT	Coconut Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 2ND CT	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 2ND CT	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 2ND CT	Gumbo Limbo	16-20"	No	30'		Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 2ND CT	Mahogany	31-40"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 2ND CT	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 2ND CT	Vera Wood	1-5"	No	20'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 2ND CT	Vera Wood	1-5"	No	15'		Poor (21% to 40%)	Leader - Broken	Decay Observed	Epicormic Growth
SW 2ND CT	Vera Wood	11-15"	No	35'		Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	Epicormic Growth
SW 2ND CT	Vera Wood	6-10"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Plunged	Apical Dieback	Discolored Foliage
SW 2ND CT	Mahogany	16-20"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Trunk Damage - Moderate	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 2ND CT	Mahogany	16-20"	No	50'		Fair (41% to 60%)	Girdling Roots	Broken Branches	Dead Wood
SW 2ND CT	Vera Wood	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Epicormic Growth

SW 3rd Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 3RD AVE	Banyan	60+"	No	90'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Restricted Canopy
SW 3RD AVE	Coconut Palm	11-15"	No	5'		Poor (21% to 40%)	Reduced Canopy - Major	Nutrient Deficiency	Over Pruned
SW 3RD AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Over Pruned		
SW 3RD AVE	Strangler Fig	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 3RD AVE	Mahogany	31-40"	No	55'		Poor (21% to 40%)	Constricted Roots	Tip Dieback	Decay Observed
SW 3RD AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 3RD AVE	Pink Tabebuia	6-10"	No	20'		Fair (41% to 60%)	Leader - Broken	Trunk Damage - Moderate	Stubs with Sprouts
SW 3RD AVE	Queen Palm	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 3RD AVE	Banyan	60+"	Yes	75'		Fair (41% to 60%)	Decay Observed	Grafted Branches	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	Yes	60'		Fair (41% to 60%)	Decay Observed	Broken Branches	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	Yes	70'		Poor (21% to 40%)	Decay Observed	Broken Branches	Cavities
SW 3RD AVE	Banyan	16-20"	No	25'		Good (61% to 80%)	Broken Branches	Restricted Canopy	Encasing Parking Sign
SW 3RD AVE	Banyan	60+"	Yes	60'		Fair (41% to 60%)	Broken Branches	Decay Observed	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	70'		Poor (21% to 40%)	Limb Damage - Major	Cavities	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	No	65'		Fair (41% to 60%)	Decay Observed	Cavities	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	65'		Fair (41% to 60%)	Cavities	Epicormic Growth	Broken Branches
SW 3RD AVE	Banyan	60+"	Yes	65'		Fair (41% to 60%)	Cavities	Epicormic Growth	Grafted Branches
SW 3RD AVE	Banyan	60+"	Yes	55'		Fair (41% to 60%)	Decay Observed	Grafted Branches	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	No	65'		Fair (41% to 60%)	Limb Damage - Moderate	Grafted Branches	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	Yes	65'		Poor (21% to 40%)	Limb Damage - Major	Broken Branches	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	Yes	70'		Fair (41% to 60%)	Decay Observed	Broken Branches	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 3rd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 3RD AVE	Banyan	60+"	Yes	80'		Fair (41% to 60%)	Decay Observed	Cavities	Broken Branches
SW 3RD AVE	Banyan	60+"	Yes	80'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Cavities	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	40'		Good (61% to 80%)	Cavities	Epicormic Growth	Limb Damage - Minor
SW 3RD AVE	Banyan	41-50"	No	35'		Fair (41% to 60%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 3RD AVE	Banyan	31-40"	No	30'		Fair (41% to 60%)	Limb Damage - Moderate	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 3RD AVE	Banyan	21-30"	No	30'		Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	No	50'		Fair (41% to 60%)	Decay Observed	Epicormic Growth	Grafted Branches
SW 3RD AVE	Banyan	41-50"	Yes	35'		Fair (41% to 60%)	Decay Observed	Epicormic Growth	Broken Branches
SW 3RD AVE	Banyan	60+"	No	70'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Cavities
SW 3RD AVE	Banyan	60+"	No	75'		Fair (41% to 60%)	Decay Observed	Epicormic Growth	Restricted Canopy
SW 3RD AVE	Banyan	60+"	Yes	75'		Fair (41% to 60%)	Decay Observed	Epicormic Growth	Grafted Branches
SW 3RD AVE	Banyan	60+"	Yes	80'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Cavities
SW 3RD AVE	Banyan	41-50"	No	40'		Fair (41% to 60%)	Cavities	Epicormic Growth	Limb Damage - Minor
SW 3RD AVE	Banyan	60+"	Yes	65'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 3RD AVE	Banyan	60+"	Yes	75'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	40'		Fair (41% to 60%)	Decay Observed	Stubs with Sprouts	Broken Branches
SW 3RD AVE	Banyan	60+"	Yes	75'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Cavities	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	85'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	Yes	85'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	Yes	70'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 3RD AVE	Banyan	41-50"	Yes	50'		Poor (21% to 40%)	Limb Damage - Moderate	Epicormic Growth	Discolored Foliage
SW 3RD AVE	Banyan	60+"	No	60'		Poor (21% to 40%)	Decay Observed	Epicormic Growth	Discolored Foliage
SW 3RD AVE	Banyan	60+"	Yes	75'		Poor (21% to 40%)	Decay Observed	Tip Dieback	Epicormic Growth
SW 3RD AVE	Banyan	31-40"	Yes	35'		Fair (41% to 60%)	Trunk Damage - Moderate	Stubs with Sprouts	Grafted Branches
SW 3RD AVE	Banyan	60+"	Yes	60'		Fair (41% to 60%)	Decay Observed	Broken Branches	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	65'		Good (61% to 80%)	Limb Damage - Minor	Broken Branches	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	Yes	75'		Poor (21% to 40%)	Root Damage/Decay	Decay Observed	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	Yes	80'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 3RD AVE	Banyan	31-40"	No	25'		Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Restricted Canopy
SW 3RD AVE	Banyan	60+"	Yes	60'		Poor (21% to 40%)	Decay Observed	Tip Dieback	Epicormic Growth
SW 3RD AVE	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Damaged Fronds
SW 3RD AVE	Banyan	60+"	No	55'		Good (61% to 80%)	Cavities	Epicormic Growth	Restricted Canopy
SW 3RD AVE	Banyan	60+"	No	70'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Decay Observed
SW 3RD AVE	Banyan	60+"	No	60'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Broken Branches
SW 3RD AVE	Banyan	60+"	No	35'		Fair (41% to 60%)	Decay Observed	Cavities	Stubs with Sprouts
SW 3RD AVE	Banyan	31-40"	No	35'		Fair (41% to 60%)	Decay Observed	Broken Branches	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	No	45'		Fair (41% to 60%)	Cavities	Epicormic Growth	Broken Branches
SW 3RD AVE	Banyan	60+"	No	55'		Poor (21% to 40%)	Basal Co-Dominant with Adjacent Tree(s)	Decay Observed	Stubs with Sprouts
SW 3RD AVE	Gumbo Limbo	21-30"	No	30'		Poor (21% to 40%)	Basal Co-Dominant with Adjacent Tree(s)	Lifting	Codominant Leaders/No Included Bark
SW 3RD AVE	Banyan	60+"	Yes	30'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Decay Observed	Stubs with Sprouts	Broken Branches
SW 3RD AVE	Banyan	31-40"	Yes	35'		Fair (41% to 60%)	Decay Observed	Epicormic Growth	Broken Branches
SW 3RD AVE	Banyan	41-50"	Yes	35'		Poor (21% to 40%)	Basal Co-Dominant with Adjacent Tree(s)	Decay Observed	Epicormic Growth
SW 3RD AVE	Gumbo Limbo	16-20"	No	15'		Poor (21% to 40%)	Basal Co-Dominant with Adjacent Tree(s)	Basal Co-Dominant	Lifting
SW 3RD AVE	Banyan	60+"	No	35'		Poor (21% to 40%)	Limb Damage - Major	Epicormic Growth	Broken Branches
SW 3RD AVE	Banyan	60+"	No	60'		Fair (41% to 60%)	Cavities	Epicormic Growth	Broken Branches
SW 3RD AVE	Banyan	41-50"	No	65'		Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Limb Damage - Minor
SW 3RD AVE	Banyan	21-30"	No	45'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 3RD AVE	Banyan	60+"	Yes	75'		Poor (21% to 40%)	Decay Observed	Epicormic Growth	Discolored Foliage

(Continued on Next Page)

Street Tree Inventory

SW 3rd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 3RD AVE	Banyan	60+"	No	75'		Poor (21% to 40%)	Decay Observed	Basal Co-Dominant with Adjacent Tree(s)	Stubs with Sprouts
SW 3RD AVE	Gumbo Limbo	16-20"	No	15'		Poor (21% to 40%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Lifting
SW 3RD AVE	Banyan	60+"	No	70'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 3RD AVE	Banyan	60+"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Epicormic Growth	Broken Branches
SW 3RD AVE	Banyan	60+"	No	75'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	60'		Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts	Broken Branches
SW 3RD AVE	Banyan	41-50"	No	45'		Fair (41% to 60%)	Tip Dieback	Epicormic Growth	Cavities
SW 3RD AVE	Banyan	60+"	No	95'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Decay Observed
SW 3RD AVE	Banyan	60+"	Yes	70'		Fair (41% to 60%)	Decay Observed	Broken Branches	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	Yes	80'		Fair (41% to 60%)	Decay Observed	Cavities	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	80'		Poor (21% to 40%)	Constricted Roots	Tip Dieback	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	75'		Fair (41% to 60%)	Decay Observed	Broken Branches	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	65'	Utility Line Conflict	Good (61% to 80%)	Limb Damage - Minor	Epicormic Growth	Broken Branches
SW 3RD AVE	Banyan	60+"	Yes	75'		Fair (41% to 60%)	Compromised Tension Roots	Epicormic Growth	Broken Branches
SW 3RD AVE	Banyan	60+"	Yes	80'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	55'		Fair (41% to 60%)	Decay Observed	Broken Branches	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	60'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 3RD AVE	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 3RD AVE	Banyan	41-50"	Yes	35'		Fair (41% to 60%)	Limb Damage - Moderate	Cavities	Stubs with Sprouts
SW 3RD AVE	Banyan	41-50"	No	50'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Cavities	Stubs with Sprouts
SW 3RD AVE	Banyan	51-60"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	65'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Tip Dieback
SW 3RD AVE	Banyan	60+"	Yes	65'		Fair (41% to 60%)	Cavities	Tip Dieback	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	85'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	70'		Poor (21% to 40%)	Decay Observed	Tip Dieback	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	55'		Poor (21% to 40%)	Decay Observed	Tip Dieback	Epicormic Growth
SW 3RD AVE	Banyan	41-50"	No	55'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	No	80'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Cavities
SW 3RD AVE	Brazilian Beauty Leaf	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 3RD AVE	Banyan	60+"	No	80'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 3RD AVE	Black Olive	31-40"	No	45'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	55'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 3RD AVE	Banyan	60+"	No	60'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 3RD AVE	Foxtail Palm	6-10"	No	10'		Poor (21% to 40%)	Nutrient Deficiency	Ficus Growing on Tree	Cracks in Trunk
SW 3RD AVE	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 3RD AVE	Weeping Fig	16-20"	No	20'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Lopsided/Significantly Reduced Canopy
SW 3RD AVE	Weeping Fig	11-15"	No	30'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Codominant Leaders/No Included Bark	Epicormic Growth
SW 3RD AVE	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 3RD AVE	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 3RD AVE	Gumbo Limbo	16-20"	No	30'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 3RD AVE	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Apical Dieback	Improperly Mulched	Epicormic Growth
SW 3RD AVE	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Apical Dieback	Improperly Mulched	Epicormic Growth
SW 3RD AVE	Mahogany	21-30"	No	40'		Good (61% to 80%)	Codominant Leaders/Included Bark	Broken Branches	Stubs with Sprouts
SW 3RD AVE	Mahogany	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 3RD AVE	Strangler Fig	60+"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 3RD AVE	Mahogany	11-15"	No	25'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Epicormic Growth
SW 3RD AVE	Strangler Fig	41-50"	No	45'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	100'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Sprouting
SW 3RD AVE	Areca Palm	31-40"	Yes	15'		Good (61% to 80%)	Suppressed Canopy	Nutrient Deficiency	

(Continued on Next Page)

Street Tree Inventory

SW 3rd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION [illegible]	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 3RD AVE	Areca Palm	21-30"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 3RD AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 3RD AVE	Banyan	60+"	No	110'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 3RD AVE	Umbrella Tree	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)	
SW 3RD AVE	Carolina Cherry Laurel	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 3RD AVE	Brazilian Pepper	1-5"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 3RD AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 3RD AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 3RD AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 3RD AVE	White Indigo Berry	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Codominant Leaders/No Included Bark
SW 3RD AVE	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 3RD AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 3RD AVE	Banyan	60+"	No	90'		Poor (21% to 40%)	Constricted Roots	Leader - Broken	Decay Observed
SW 3RD AVE	Mahogany	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 3RD AVE	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Crown Density - Low	Epicormic Growth	Dead Wood
SW 3RD AVE	Yellow Tabebuia	11-15"	No	20'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Lopsided/Reduced Canopy - Major
SW 3RD AVE	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Nutrient Deficiency	Over Pruned	Damaged Fronds
SW 3RD AVE	Live Oak	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 3RD AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 3RD AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 3RD AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 3RD AVE	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 3RD AVE	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 3RD AVE	Mahogany	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Utility Pruned	Stubs with Sprouts
SW 3RD AVE	Mahogany	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 3RD AVE	Mahogany	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 3RD AVE	Canary Island Date Palm	21-30"	No	15'		Poor (21% to 40%)	Reduced Canopy - Major	Nutrient Deficiency	Damaged Fronds
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Ficus Growing on Tree		
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Ficus Growing on Tree		
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)			
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Frizzled Fronds	Damaged Fronds	
SW 3RD AVE	Canary Island Date Palm	31-40"	No	20'		Fair (41% to 60%)	Reduced Canopy - Moderate	Nutrient Deficiency	Split Canopy
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 3RD AVE	Canary Island Date Palm	16-20"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	White Fly	Ficus Growing on Tree
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 3RD AVE	Canary Island Date Palm	31-40"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'	Utility Lines Above	Good (61% to 80%)	Ficus Growing on Tree		
SW 3RD AVE	Canary Island Date Palm	16-20"	No	20'	Utility Lines Above	Good (61% to 80%)	Ficus Growing on Tree		
SW 3RD AVE	Canary Island Date Palm	16-20"	No	20'	Utility Lines Above	Good (61% to 80%)	Ficus Growing on Tree		
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'	Utility Line Conflict	Good (61% to 80%)	Ficus Growing on Tree		
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'	Utility Lines Above	Good (61% to 80%)	Ficus Growing on Tree	Vine Cover - Heavy	
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Ficus Growing on Tree		
SW 3RD AVE	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)	Ficus Growing on Tree	Vine Cover - Heavy	Nutrient Deficiency
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Ficus Growing on Tree	Vine Cover - Heavy	
SW 3RD AVE	Canary Island Date Palm	21-30"	No	5'		Fair (41% to 60%)	Restricted Canopy	Strap Constricting Tree	Fronds Constricted by Rope
SW 3RD AVE	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)	Ficus Growing on Tree	Vine Cover - Heavy	
SW 3RD AVE	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)			
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Fair (41% to 60%)	Reduced Canopy - Moderate	Damaged Fronds	Ficus Growing on Tree
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)			

(Continued on Next Page)

Street Tree Inventory

SW 3rd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 3RD AVE	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)	Ficus Growing on Tree	Adjacent Light Pole	
SW 3RD AVE	Canary Island Date Palm	21-30"	No	10'		Poor (21% to 40%)	Nutrient Deficiency	Restricted Canopy	Damaged Fronds
SW 3RD AVE	Canary Island Date Palm	31-40"	No	20'	Split Canopy	Poor (21% to 40%)	Reduced Canopy - Moderate	Nutrient Deficiency	Damaged Fronds
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Over Pruned	Vine Cover - Heavy
SW 3RD AVE	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)			
SW 3RD AVE	Canary Island Date Palm	21-30"	No	10'		Fair (41% to 60%)	Restricted Canopy	Strap Constricting Fronds	
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Vine Cover - Heavy	Ficus Growing on Tree
SW 3RD AVE	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Vine Cover - Heavy	
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Ficus Growing on Tree	Vine Cover - Heavy	
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Vine Cover - Heavy	Nutrient Deficiency	
SW 3RD AVE	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)	Vine Cover - Heavy	Nutrient Deficiency	Ficus Growing on Tree
SW 3RD AVE	Canary Island Date Palm	16-20"	No	10'		Poor (21% to 40%)	Reduced Canopy - Moderate	Trunk Damage - Major	Nutrient Deficiency
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Ficus Growing on Tree		
SW 3RD AVE	Gumbo Limbo	11-15"	Yes	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Vine Cover - Heavy
SW 3RD AVE	Gumbo Limbo	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 3RD AVE	Gumbo Limbo	41-50"	Yes	30'		Fair (41% to 60%)	Constricted Roots	Grafted Branches	Sprouting
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 3RD AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 3RD AVE	Banyan	60+"	No	75'		Poor (21% to 40%)	Constricted Roots	Decay Observed	White Fly
SW 3RD AVE	Banyan	60+"	No	90'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	85'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	75'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 3RD AVE	Weeping Fig	31-40"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 3RD AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 3RD AVE	Queen Palm	16-20"	Yes	5'		Very Poor/Critical (6% to 20%)	Nutrient Deficiency	Reduced Canopy - Major	Frizzled Fronds
SW 3RD AVE	Areca Palm	31-40"	Yes	20'		Good (61% to 80%)			
SW 3RD AVE	Spindle Palm	11-15"	No	10'		Good (61% to 80%)	Trunk Damage - Minor		
SW 3RD AVE	Black Olive	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders - Multi	Epicormic Growth
SW 3RD AVE	Banyan	60+"	Yes	90'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	No	85'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 3RD AVE	Mahogany	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	
SW 3RD AVE	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Suppressed Canopy		
SW 3RD AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 3RD AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 3RD AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 3RD AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 3RD AVE	Banyan	60+"	No	85'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 3RD AVE	Banyan	60+"	No	95'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Epicormic Growth
SW 3RD AVE	Banyan	60+"	No	85'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 3RD AVE	Spindle Palm	11-15"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 3RD AVE	Live Oak	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 3RD AVE	Live Oak	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Codominant Leaders/No Included Bark	Apical Dieback	Epicormic Growth
SW 3RD AVE	Triangle Palm	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 3RD AVE	Triangle Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 3RD AVE	Banyan	60+"	No	95'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 3RD AVE	Banyan	60+"	No	95'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Crown Density - Excessive (Due to Epicormic Growth)
SW 3RD AVE	Live Oak	1-5"	Yes	5'		Fair (41% to 60%)	Basal Co-Dominant with Adjacent Tree(s)	Grafted Branches	Crown Density - Excessive (Due to Epicormic Growth)
SW 3RD AVE	Washington Palm	16-20"	No	10'		Good (61% to 80%)	Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 3rd Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 3RD AVE	Banyan	60+"	Yes	75'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Apical Dieback
SW 3RD AVE	Mahogany	1-5"	No	10'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Basal Co-Dominant with Adjacent Tree(s)	Discolored Foliage
SW 3RD AVE	Brazilian Pepper	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Broken Branches
SW 3RD AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 3RD AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 3RD AVE	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 3RD AVE	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Strap Constricting Tree	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 3RD AVE	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)

Avenues




Looking Northeast - SW 31st Road



Looking Southwest - SW 21st Road



Looking Northeast - SW 30th Road



Looking Northeast - SW 27th Road



Looking Southwest - SW 18th Terrace



Looking Southwest - SW 17th Road



Looking Southwest - SW 23rd Road



Looking Southwest - SW 11th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 4th Avenue	1	Roads	3	70	5450	Some, btw 17th and 27th Road	No	Yes	2	City	Yes	Few	10 (5 btw 17th and 27th Road)	Yes	Yes	Mostly on SE	Dense canopy alongareas with median. Roundabouts at 25th, 27th, and 31st Roads.
SW 5th Avenue	1	Roads	3	70	4800	No	No	Yes	2	City	Yes	Few	10	Intermittent	Yes	between 20th and 22nd road on SE	No curbs along Southeast side, except for block between 21st and 22nd Road. Roundabouts at 20th, 22nd, 25th, and 28th Roads

SW 4th Avenue

TYPOLOGY G and B

SW 5th Avenue

TYPOLOGY B

Street Tree Inventory

SW 4th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 4TH AVE	Sylvester Date Palm	11-15"	No	15'		Good (61% to 80%)	Ficus Growing on Tree		
SW 4TH AVE	Bismark Palm	16-20"	No	10'		Poor (21% to 40%)	Reduced Canopy - Major	Nutrient Deficiency	Damaged Fronds
SW 4TH AVE	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 4TH AVE	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 4TH AVE	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 4TH AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 4TH AVE	Vera Wood	6-10"	No	15'		Fair (41% to 60%)	Uprooted - Partially	Codominant Leaders/Included Bark	Sprouting
SW 4TH AVE	Vera Wood	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 4TH AVE	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 4TH AVE	Weeping Fig	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 4TH AVE	Mahogany	11-15"	No	15'		Poor (21% to 40%)	Lopsided/Reduced Canopy - Major	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Mahogany	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Stubs with Sprouts
SW 4TH AVE	Mahogany	6-10"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Stubs with Sprouts
SW 4TH AVE	Mahogany	11-15"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Stubs with Sprouts
SW 4TH AVE	Royal Poinciana	16-20"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Cavities	Broken Branches
SW 4TH AVE	Live Oak	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth
SW 4TH AVE	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 4TH AVE	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 4TH AVE	Mahogany	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 4TH AVE	Mahogany	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 4TH AVE	Mahogany	6-10"	No	20'		Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	Epicormic Growth
SW 4TH AVE	Royal Poinciana	31-40"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Basal Co-Dominant	Grafted Branches
SW 4TH AVE	Spanish Cherry	21-30"	No	25'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 4TH AVE	Royal Poinciana	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Dead Wood	Leader - Broken
SW 4TH AVE	Mahogany	21-30"	No	35'		Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Sprouting
SW 4TH AVE	Mahogany	21-30"	No	45'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 4TH AVE	Mahogany	6-10"	No	15'		Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	Restricted Canopy
SW 4TH AVE	Mahogany	11-15"	No	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Live Oak	6-10"	No	10'		Very Poor/Critical (6% to 20%)	Girdling Roots	Sloughing Bark	Topped
SW 4TH AVE	Silk Floss Tree	6-10"	No	5'		Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	Dead Wood
SW 4TH AVE	Black Olive	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Sprouting
SW 4TH AVE	Black Olive	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 4TH AVE	Black Olive	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Sprouting
SW 4TH AVE	Mahogany	41-50"	No	55'		Poor (21% to 40%)	Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 4TH AVE	Mahogany	6-10"	No	15'		Poor (21% to 40%)	Constricted Roots	Dead Wood	Tip Dieback
SW 4TH AVE	Mahogany	21-30"	No	20'		Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Broken Branches
SW 4TH AVE	Mahogany	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Dead Wood
SW 4TH AVE	Mahogany	21-30"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lateral Branching - None	Sprouting
SW 4TH AVE	Bismark Palm	16-20"	No	20'		Good (61% to 80%)			
SW 4TH AVE	Bismark Palm	16-20"	No	20'		Good (61% to 80%)			
SW 4TH AVE	Black Olive	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 4TH AVE	Black Olive	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 4TH AVE	Black Olive	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Cavities	Stubs with Sprouts
SW 4TH AVE	Black Olive	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 4TH AVE	Black Olive	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 4th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 4TH AVE	Black Olive	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Sprouting
SW 4TH AVE	Black Olive	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Grafted Branches
SW 4TH AVE	Black Olive	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 4TH AVE	Black Olive	16-20"	No	25'		Fair (41% to 60%)	Girdling Roots	Limb Damage - Minor	Codominant Leaders/No Included Bark
SW 4TH AVE	Black Olive	16-20"	No	35'		Fair (41% to 60%)	Decay Observed	Broken Branches	Codominant Leaders/No Included Bark
SW 4TH AVE	Hong Kong Orchid	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Sprouting
SW 4TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Over Pruned		
SW 4TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 4TH AVE	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 4TH AVE	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 4TH AVE	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 4TH AVE	Vera Wood	6-10"	No	5'		Fair (41% to 60%)	Topped	Pruned Into Shrub	Crown Density - Excessive (Due to Epicormic Growth)
SW 4TH AVE	Vera Wood	6-10"	No	5'		Fair (41% to 60%)	Topped	Pruned Into Shrub	Crown Density - Excessive (Due to Epicormic Growth)
SW 4TH AVE	Vera Wood	11-15"	No	5'		Fair (41% to 60%)	Topped	Pruned Into Shrub	Crown Density - Excessive (Due to Epicormic Growth)
SW 4TH AVE	Pygmy Date Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 4TH AVE	Pygmy Date Palm	11-15"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 4TH AVE	Pygmy Date Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 4TH AVE	Pygmy Date Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 4TH AVE	Pygmy Date Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 4TH AVE	Mahogany	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 4TH AVE	Neem Tree	1-5"	No	5'		Fair (41% to 60%)	Topped	Sprouting	Codominant Leaders/No Included Bark
SW 4TH AVE	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 4TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 4TH AVE	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 4TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 4TH AVE	Coconut Palm	11-15"	No	25'		Good (61% to 80%)	Restricted Canopy		
SW 4TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Restricted Canopy	Over Pruned	
SW 4TH AVE	Coconut Palm	11-15"	No	25'		Good (61% to 80%)	Restricted Canopy		
SW 4TH AVE	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 4TH AVE	Tropical Almond	1-5"	No	25'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 4TH AVE	Tropical Almond	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 4TH AVE	Tropical Almond	6-10"	No	25'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Broken Branches
SW 4TH AVE	Tropical Almond	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 4TH AVE	Gumbo Limbo	21-30"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 4TH AVE	Dracaena sp.	6-10"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 4TH AVE	Umbrella Tree	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 4TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 4TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 4TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 4TH AVE	Pigeon Plum	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Epicormic Growth	
SW 4TH AVE	Tamarind	21-30"	No	25'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 4TH AVE	Starburst Clerodendron	6-10"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 4TH AVE	Gumbo Limbo	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 4TH AVE	Gumbo Limbo	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Sapodilla	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 4TH AVE	Strangler Fig	16-20"	Yes	20'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Restricted Canopy
SW 4TH AVE	Sapodilla	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 4TH AVE	Rubber Tree	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Limb Damage - Major
SW 4TH AVE	Christmas Palm	1-5"	Yes	5'		Fair (41% to 60%)	Restricted Canopy	Reduced Canopy - Moderate	Damaged Fronds
SW 4TH AVE	Christmas Palm	1-5"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Damaged Fronds
SW 4TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Damaged Fronds
SW 4TH AVE	Christmas Palm	1-5"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Damaged Fronds

(Continued on Next Page)

Street Tree Inventory

SW 4th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 4TH AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/Included Bark	Sprouting
SW 4TH AVE	Strangler Fig	16-20"	No	20'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Broken Branches
SW 4TH AVE	Strangler Fig	21-30"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 4TH AVE	Tropical Almond	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 4TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	Nutrient Deficiency
SW 4TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 4TH AVE	Mahogany	41-50"	No	60'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 4TH AVE	Mahogany	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 4TH AVE	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Decay Observed
SW 4TH AVE	Mahogany	21-30"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Leader - Broken	Decay Observed
SW 4TH AVE	Weeping Fig	16-20"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 4TH AVE	Weeping Fig	11-15"	No	20'		Good (61% to 80%)	Codominant Leaders/Included Bark	Dead Wood	Broken Branches
SW 4TH AVE	Umbrella Tree	21-30"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Sprouting	
SW 4TH AVE	Hong Kong Orchid	21-30"	No	20'		Poor (21% to 40%)	Decay Observed	Tip Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 4TH AVE	Mahogany	21-30"	No	20'		Poor (21% to 40%)	Constricted Roots	Topped	Reduced Canopy - Moderate
SW 4TH AVE	Mahogany	31-40"	No	20'		Poor (21% to 40%)	Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 4TH AVE	Mahogany	31-40"	No	25'		Poor (21% to 40%)	Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 4TH AVE	Coconut Palm	6-10"	No	10'		Good (61% to 80%)			
SW 4TH AVE	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 4TH AVE	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 4TH AVE	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Sloughing Bark
SW 4TH AVE	Queen Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/Included Bark	Strap Constricting Tree
SW 4TH AVE	Queen Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/Included Bark	Strap Constricting Tree
SW 4TH AVE	Queen Crepe Myrtle	1-5"	No	5'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 4TH AVE	Queen Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 4TH AVE	Royal Poinciana	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Cavities	Stubs with Sprouts
SW 4TH AVE	Mahogany	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 4TH AVE	Black Olive	31-40"	No	35'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	
SW 4TH AVE	Black Olive	21-30"	No	25'		Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Minor
SW 4TH AVE	Black Olive	21-30"	No	25'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Trunk Damage - Minor
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Trunk Damage - Minor	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	6-10"	No	15'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	6-10"	No	15'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Restricted Canopy
SW 4TH AVE	Mahogany	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Restricted Canopy
SW 4TH AVE	Mahogany	11-15"	No	15'		Poor (21% to 40%)	Girdling Roots	Tip Dieback	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 4th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 4TH AVE	Orange Geiger	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 4TH AVE	Orange Geiger	6-10"	No	15'		Poor (21% to 40%)	Girdling Roots	Lopsided/Reduced Canopy - Major	Codominant Leaders/No Included Bark
SW 4TH AVE	Yellow Poinciana	11-15"	No	40'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Gumbo Limbo	6-10"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Restricted Canopy
SW 4TH AVE	Yellow Poinciana	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Sloughing Bark
SW 4TH AVE	Gumbo Limbo	6-10"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Restricted Canopy
SW 4TH AVE	Orange Geiger	6-10"	Yes	10'		Fair (41% to 60%)	Leader - Broken	Stubs with Sprouts	Trunk Damage - Minor
SW 4TH AVE	Orange Geiger	6-10"	No	10'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Broken Branches
SW 4TH AVE	Orange Geiger	1-5"	No	10'		Good (61% to 80%)	Stubs with Sprouts	Codominant Leaders/No Included Bark	
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 4TH AVE	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/Included Bark
SW 4TH AVE	Mahogany	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	
SW 4TH AVE	Mahogany	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Sprouting	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	16-20"	No	15'		Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Sprouting
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Mahogany	16-20"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Mahogany	16-20"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Yellow Poinciana	1-5"	No	5'		Good (61% to 80%)			
SW 4TH AVE	Mahogany	6-10"	No	15'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth
SW 4TH AVE	Strangler Fig	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 4TH AVE	Gumbo Limbo	6-10"	No	20'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Restricted Canopy
SW 4TH AVE	Gumbo Limbo	6-10"	No	20'		Poor (21% to 40%)	Girdling Roots	White Fly	Codominant Leaders/No Included Bark
SW 4TH AVE	Strangler Fig	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 4TH AVE	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 4TH AVE	Gumbo Limbo	6-10"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	11-15"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Dead Wood
SW 4TH AVE	Mahogany	11-15"	No	20'		Poor (21% to 40%)	Girdling Roots	Leader - Broken	Stubs with Sprouts
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Epicormic Growth
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Restricted Canopy
SW 4TH AVE	Mahogany	16-20"	No	30'		Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 4TH AVE	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Girdling Roots	Tip Dieback	Broken Branches
SW 4TH AVE	Mahogany	6-10"	No	20'		Fair (41% to 60%)	Trunk Damage - Moderate	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 4TH AVE	Mahogany	6-10"	No	10'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Restricted Canopy
SW 4TH AVE	Mahogany	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 4TH AVE	Mahogany	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 4TH AVE	Mahogany	11-15"	No	25'		Poor (21% to 40%)	Leader - Broken	Sloughing Bark	Stubs with Sprouts
SW 4TH AVE	Mahogany	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Restricted Canopy
SW 4TH AVE	Mahogany	16-20"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Mahogany	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Cavities	Epicormic Growth
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 4TH AVE	Mahogany	11-15"	No	10'		Very Poor/Critical (6% to 20%)	Decay Observed	Sloughing Bark	Crown Density - Very Low
SW 4TH AVE	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Mahogany	16-20"	No	25'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/Included Bark	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 4th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 4TH AVE	Mahogany	6-10"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Trunk Damage - Minor
SW 4TH AVE	Mahogany	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Grafted Branches	Codominant Leaders/Included Bark
SW 4TH AVE	Queen Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 4TH AVE	Mahogany	11-15"	No	15'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 4TH AVE	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Epicormic Growth
SW 4TH AVE	Horseflesh Mahogany	41-50"	No	55'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Ficus Growing on Tree	Trunk Damage - Minor
SW 4TH AVE	Horseflesh Mahogany	41-50"	No	55'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Ficus Growing on Tree	Tip Dieback
SW 4TH AVE	Horseflesh Mahogany	41-50"	No	60'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Ficus Growing on Tree	Dead Wood
SW 4TH AVE	Horseflesh Mahogany	21-30"	No	50'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 4TH AVE	Horseflesh Mahogany	21-30"	No	35'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 4TH AVE	Mahogany	21-30"	No	20'		Poor (21% to 40%)	Leader - Broken	Lopsided/Reduced Canopy - Major	Epicormic Growth
SW 4TH AVE	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Cavities	Dead Wood
SW 4TH AVE	Sea Grape	31-40"	Yes	30'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 4TH AVE	Mahogany	21-30"	No	30'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 4TH AVE	Bottlebrush	16-20"	No	20'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Limb Damage - Minor
SW 4TH AVE	Tamarind	21-30"	No	45'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Decay Observed	Stubs with Sprouts	Dead Wood
SW 4TH AVE	Tamarind	11-15"	No	25'		Poor (21% to 40%)	Decay Observed	Cavities	Stubs with Sprouts
SW 4TH AVE	Tamarind	21-30"	No	35'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 4TH AVE	Tamarind	21-30"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Epicormic Growth	Broken Branches
SW 4TH AVE	Tamarind	16-20"	No	45'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Dead Wood
SW 4TH AVE	Tamarind	16-20"	No	40'		Fair (41% to 60%)	Tip Dieback	Epicormic Growth	Restricted Canopy
SW 4TH AVE	Tamarind	21-30"	No	40'		Fair (41% to 60%)	Decay Observed	Stubs with Sprouts	Broken Branches
SW 4TH AVE	Tamarind	6-10"	No	15'		Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 4TH AVE	Tamarind	16-20"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Decay Observed	Epicormic Growth	Dead Wood
SW 4TH AVE	Tamarind	16-20"	No	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Tip Dieback	Codominant Leaders/No Included Bark	Sprouting
SW 4TH AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	
SW 4TH AVE	Mango	16-20"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Topped	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 4TH AVE	Mango	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Topped	Reduced Canopy - Moderate	Stubs with Sprouts
SW 4TH AVE	Mango	16-20"	No	20'	Utility Lines Above	Poor (21% to 40%)	Topped	Reduced Canopy - Moderate	Stubs with Sprouts
SW 4TH AVE	Mango	16-20"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Topped	Reduced Canopy - Minor	Stubs with Sprouts
SW 4TH AVE	Black Olive	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 4TH AVE	Black Olive	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 4TH AVE	Black Olive	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 4TH AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Codominant Leaders/Included Bark
SW 4TH AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood
SW 4TH AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Decay Observed
SW 4TH AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 4TH AVE	Sapodilla	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 4TH AVE	Black Olive	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Decay Observed
SW 4TH AVE	Sapodilla	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Grafted Branches
SW 4TH AVE	Queen Palm	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Restricted Canopy	Nutrient Deficiency	Frizzled Fronds
SW 4TH AVE	Triangle Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 4TH AVE	Triangle Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 4TH AVE	Christmas Palm	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)			

(Continued on Next Page)

Street Tree Inventory

SW 4th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 4TH AVE	Mahogany	6-10"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Trunk Damage - Minor
SW 4TH AVE	Mahogany	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Grafted Branches	Codominant Leaders/Included Bark
SW 4TH AVE	Queen Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 4TH AVE	Mahogany	11-15"	No	15'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 4TH AVE	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Epicormic Growth
SW 4TH AVE	Horseflesh Mahogany	41-50"	No	55'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Ficus Growing on Tree	Trunk Damage - Minor
SW 4TH AVE	Horseflesh Mahogany	41-50"	No	55'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Ficus Growing on Tree	Tip Dieback
SW 4TH AVE	Horseflesh Mahogany	41-50"	No	60'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Ficus Growing on Tree	Dead Wood
SW 4TH AVE	Horseflesh Mahogany	21-30"	No	50'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 4TH AVE	Horseflesh Mahogany	21-30"	No	35'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 4TH AVE	Mahogany	21-30"	No	20'		Poor (21% to 40%)	Leader - Broken	Lopsided/Reduced Canopy - Major	Epicormic Growth
SW 4TH AVE	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Cavities	Dead Wood
SW 4TH AVE	Sea Grape	31-40"	Yes	30'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 4TH AVE	Mahogany	21-30"	No	30'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 4TH AVE	Bottlebrush	16-20"	No	20'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Limb Damage - Minor
SW 4TH AVE	Tamarind	21-30"	No	45'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Decay Observed	Stubs with Sprouts	Dead Wood
SW 4TH AVE	Tamarind	11-15"	No	25'		Poor (21% to 40%)	Decay Observed	Cavities	Stubs with Sprouts
SW 4TH AVE	Tamarind	21-30"	No	35'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 4TH AVE	Tamarind	21-30"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Epicormic Growth	Broken Branches
SW 4TH AVE	Tamarind	16-20"	No	45'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Dead Wood
SW 4TH AVE	Tamarind	16-20"	No	40'		Fair (41% to 60%)	Tip Dieback	Epicormic Growth	Restricted Canopy
SW 4TH AVE	Tamarind	21-30"	No	40'		Fair (41% to 60%)	Decay Observed	Stubs with Sprouts	Broken Branches
SW 4TH AVE	Tamarind	6-10"	No	15'		Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 4TH AVE	Tamarind	16-20"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Decay Observed	Epicormic Growth	Dead Wood
SW 4TH AVE	Tamarind	16-20"	No	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Tip Dieback	Codominant Leaders/No Included Bark	Sprouting
SW 4TH AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	
SW 4TH AVE	Mango	16-20"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Topped	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 4TH AVE	Mango	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Topped	Reduced Canopy - Moderate	Stubs with Sprouts
SW 4TH AVE	Mango	16-20"	No	20'	Utility Lines Above	Poor (21% to 40%)	Topped	Reduced Canopy - Moderate	Stubs with Sprouts
SW 4TH AVE	Mango	16-20"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Topped	Reduced Canopy - Minor	Stubs with Sprouts
SW 4TH AVE	Black Olive	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 4TH AVE	Black Olive	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 4TH AVE	Black Olive	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 4TH AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Codominant Leaders/Included Bark
SW 4TH AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood
SW 4TH AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Decay Observed
SW 4TH AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 4TH AVE	Sapodilla	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 4TH AVE	Black Olive	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Decay Observed
SW 4TH AVE	Sapodilla	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Grafted Branches
SW 4TH AVE	Queen Palm	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Restricted Canopy	Nutrient Deficiency	Frizzled Fronds
SW 4TH AVE	Triangle Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 4TH AVE	Triangle Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 4TH AVE	Christmas Palm	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)			

(Continued on Next Page)

Street Tree Inventory

SW 4th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 4TH AVE	Bottle Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 4TH AVE	Arjun Tree	21-30"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 4TH AVE	Sapodilla	16-20"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Limb Damage - Minor
SW 4TH AVE	Arjun Tree	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Decay Observed
SW 4TH AVE	Sapodilla	16-20"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Arjun Tree	21-30"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Mahogany	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 4TH AVE	Orange Geiger	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 4TH AVE	Neem Tree	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Sprouting	Strap Constricting Tree
SW 4TH AVE	Orange Geiger	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Tip Dieback	Broken Branches	Codominant Leaders/No Included Bark
SW 4TH AVE	Gumbo Limbo	21-30"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 4TH AVE	Orange Geiger	6-10"	No	15'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Lopsided/Reduced Canopy - Moderate	Broken Branches
SW 4TH AVE	Strangler Fig	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Over Extended Limb(s)
SW 4TH AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 4TH AVE	Queen Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 4TH AVE	White Frangipani	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Sprouting	Seasonal Defoliation/Discolored Foliage
SW 4TH AVE	White Frangipani	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Leader - Bent	Seasonal Defoliation/Discolored Foliage
SW 4TH AVE	White Frangipani	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Seasonal Defoliation/Discolored Foliage
SW 4TH AVE	Horseflesh Mahogany	21-30"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 4TH AVE	Live Oak	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Epicormic Growth
SW 4TH AVE	Live Oak	16-20"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 4TH AVE	Live Oak	11-15"	No	30'	Utility Line Conflict	Good (61% to 80%)	Utility Pruned	Epicormic Growth	Codominant Leaders/No Included Bark
SW 4TH AVE	Bottlebrush	21-30"	No	25'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 4TH AVE	Black Olive	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 4TH AVE	Florida Privet	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/Included Bark	Sprouting	Strap Constricting Tree
SW 4TH AVE	Florida Privet	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Tip Dieback	Codominant Leaders/Included Bark	Strap Constricting Tree
SW 4TH AVE	Florida Privet	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/Included Bark	Strap Constricting Tree	Sprouting
SW 4TH AVE	Florida Privet	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/Included Bark	Strap Constricting Tree	Sprouting
SW 4TH AVE	Florida Privet	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	Sprouting
SW 4TH AVE	Florida Privet	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Tip Dieback	Codominant Leaders/Included Bark
SW 4TH AVE	Areca Palm	60+"	Yes	25'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 4TH AVE	Weeping Fig	6-10"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Dead Wood	Grafted Branches	Epicormic Growth
SW 4TH AVE	Weeping Fig	6-10"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Dead Wood	Grafted Branches	Epicormic Growth
SW 4TH AVE	Weeping Fig	6-10"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Dead Wood	Broken Branches	Epicormic Growth
SW 4TH AVE	Weeping Fig	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Sprouting
SW 4TH AVE	Black Olive	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Utility Pruned
SW 4TH AVE	Black Olive	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 4TH AVE	Black Olive	21-30"	No	20'	Utility Lines Above	Poor (21% to 40%)	Decay Observed	Cavities	Reduced Canopy - Moderate
SW 4TH AVE	Black Olive	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Decay Observed
SW 4TH AVE	Yellow Tabebuia	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Topped	Leaning - Moderate	Stubs with Sprouts
SW 4TH AVE	Yellow Tabebuia	11-15"	No	20'	Utility Lines Above	Good (61% to 80%)	Sprouting	Dead Wood	Codominant Leaders/No Included Bark
SW 4TH AVE	Screw Pine	16-20"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Trunk Damage - Minor		
SW 4TH AVE	Starburst Clerodendron	11-15"	Yes	10'	Utility Line Conflict	Fair (41% to 60%)	Tip Dieback	Broken Branches	Sprouting
SW 4TH AVE	Coconut Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Lopsided/Reduced Canopy - Major	Nutrient Deficiency	
SW 4TH AVE	Black Olive	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Utility Pruned

(Continued on Next Page)

Street Tree Inventory

SW 4th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 4TH AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 4TH AVE	Coconut Palm	16-20"	Yes	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Over Pruned	Nutrient Deficiency	Damaged Fronds
SW 4TH AVE	Crepe Myrtle	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Epicormic Growth
SW 4TH AVE	Crepe Myrtle	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Restricted Canopy
SW 4TH AVE	Crepe Myrtle	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 4TH AVE	Live Oak	41-50"	No	60'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Utility Pruned
SW 4TH AVE	Live Oak	31-40"	No	55'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Utility Pruned
SW 4TH AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 4TH AVE	Mahogany	16-20"	No	30'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 4TH AVE	Mahogany	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Utility Pruned	Stubs with Sprouts
SW 4TH AVE	Christmas Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 4TH AVE	Coconut Palm	16-20"	Yes	25'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 4TH AVE	Pongam	31-40"	No	35'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Galls	Decay Observed
SW 4TH AVE	Crepe Myrtle	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Sprouting
SW 4TH AVE	Crepe Myrtle	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Sprouting
SW 4TH AVE	Crepe Myrtle	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/Included Bark	Sprouting
SW 4TH AVE	Crepe Myrtle	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 4TH AVE	White Geiger	16-20"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Cavities	Stubs with Sprouts	Ficus Growing on Tree
SW 4TH AVE	Mahogany	21-30"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Decay Observed
SW 4TH AVE	Mahogany	31-40"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 4TH AVE	Mahogany	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 4TH AVE	Weeping Fig	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 4TH AVE	Weeping Fig	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 4TH AVE	Black Olive	21-30"	No	35'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Broken Branches
SW 4TH AVE	Black Olive	11-15"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Grafted Branches
SW 4TH AVE	Mahogany	21-30"	No	30'		Fair (41% to 60%)	Adjacent Concrete Damage	Leader - Broken	Stubs with Sprouts

SW 5th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 5TH AVE	Coconut Palm	11-15"	No	15'		Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 5TH AVE	Royal Poinciana	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 5TH AVE	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Queen Palm	6-10"	No	15'		Good (61% to 80%)			
SW 5TH AVE	Live Oak	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth
SW 5TH AVE	Live Oak	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 5TH AVE	Live Oak	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Tip Dieback	Stubs with Sprouts
SW 5TH AVE	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Dead Wood
SW 5TH AVE	Mahogany	31-40"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 5th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 5TH AVE	Black Olive	21-30"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 5TH AVE	Black Olive	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 5TH AVE	Java Bishopwood	21-30"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 5TH AVE	Java Bishopwood	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 5TH AVE	Mahogany	31-40"	No	45'		Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Codominant Leaders/Included Bark
SW 5TH AVE	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Girdling Roots	Trunk Damage - Major	Lopsided/Reduced Canopy - Moderate
SW 5TH AVE	Mahogany	31-40"	No	45'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 5TH AVE	Mahogany	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Dead Wood
SW 5TH AVE	Bottle Palm	16-20"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 5TH AVE	Black Olive	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Sloughing Bark
SW 5TH AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/Included Bark	
SW 5TH AVE	Black Olive	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Restricted Canopy
SW 5TH AVE	Live Oak	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Broken Branches
SW 5TH AVE	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 5TH AVE	Pongam	21-30"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Decay Observed
SW 5TH AVE	Pongam	16-20"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 5TH AVE	Queen Palm	6-10"	No	10'		Poor (21% to 40%)	Nutrient Deficiency		
SW 5TH AVE	Queen Palm	6-10"	No	10'		Poor (21% to 40%)	Nutrient Deficiency		
SW 5TH AVE	Bismark Palm	16-20"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 5TH AVE	Bismark Palm	16-20"	No	15'		Good (61% to 80%)			
SW 5TH AVE	Bottlebrush	16-20"	No	25'		Fair (41% to 60%)	Limb Damage - Moderate	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 5TH AVE	Bottlebrush	16-20"	No	20'		Fair (41% to 60%)	Limb Damage - Moderate	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 5TH AVE	Bottlebrush	16-20"	No	20'		Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	Stubs with Sprouts
SW 5TH AVE	Bottlebrush	11-15"	No	15'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Lopsided/Reduced Canopy - Major
SW 5TH AVE	Black Olive	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 5TH AVE	Black Olive	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 5TH AVE	Black Olive	21-30"	No	Negligible		Dead (0% to 5%)	Topped	Dead Wood	Ficus Growing on Tree
SW 5TH AVE	Black Olive	21-30"	No	Negligible		Dead (0% to 5%)	Topped	Dead Wood	Sloughing Bark
SW 5TH AVE	Mahogany	16-20"	No	5'		Very Poor/Critical (6% to 20%)	Girdling Roots	Topped	Stubs with Sprouts
SW 5TH AVE	Live Oak	6-10"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Pruned Into Shrub	
SW 5TH AVE	Live Oak	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Pruned Into Shrub	
SW 5TH AVE	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Pruned Into Shrub	Crown Density - Low
SW 5TH AVE	Live Oak	6-10"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Pruned Into Shrub	
SW 5TH AVE	Bismark Palm	16-20"	No	15'		Good (61% to 80%)	Reduced Canopy - Minor	Strap Constricting Tree	
SW 5TH AVE	Pygmy Date Palm	1-5"	No	10'		Good (61% to 80%)			
SW 5TH AVE	Pygmy Date Palm	6-10"	No	5'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 5TH AVE	Desert Cassia	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders - Multi	Stubs with Sprouts	Leaning - Minor
SW 5TH AVE	Royal Palm	16-20"	No	25'		Good (61% to 80%)			
SW 5TH AVE	Pygmy Date Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 5TH AVE	Pygmy Date Palm	11-15"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 5TH AVE	Royal Palm	11-15"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 5TH AVE	Mahogany	21-30"	No	25'		Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 5TH AVE	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Lopsided/Reduced Canopy - Moderate
SW 5TH AVE	Royal Poinciana	11-15"	Yes	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 5TH AVE	Royal Poinciana	11-15"	No	25'		Poor (21% to 40%)	Basal Co-Dominant	Limb Damage - Moderate	Broken Branches

(Continued on Next Page)

Street Tree Inventory

SW 5th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 5TH AVE	Royal Poinciana	11-15"	No	25'		Poor (21% to 40%)	Basal Co-Dominant	Limb Damage - Moderate	Broken Branches
SW 5TH AVE	Royal Poinciana	21-30"	No	Negligible		Dead (0% to 5%)	Decay Observed	Sloughing Bark	Ficus Growing on Tree
SW 5TH AVE	Weeping Fig	21-30"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Grafted with Adjacent Tree	Growing Around Dead Tree
SW 5TH AVE	Jacaranda	21-30"	No	30'		Fair (41% to 60%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 5TH AVE	Mahogany	31-40"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 5TH AVE	Mahogany	21-30"	No	25'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 5TH AVE	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Broken Branches
SW 5TH AVE	Mahogany	41-50"	No	50'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 5TH AVE	Queen Palm	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 5TH AVE	Montgomery Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 5TH AVE	Montgomery Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 5TH AVE	Java Bishopwood	16-20"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 5TH AVE	Sacred Fig	31-40"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 5TH AVE	Java Bishopwood	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Lateral Branching - None	Dead Wood
SW 5TH AVE	Java Bishopwood	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Restricted Canopy	Decay Observed
SW 5TH AVE	Java Bishopwood	21-30"	No	30'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Tapered Trunk	
SW 5TH AVE	Live Oak	41-50"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 5TH AVE	Royal Poinciana	21-30"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Tip Dieback	Decay Observed	Dead Wood
SW 5TH AVE	Starburst Clerodendron	6-10"	Yes	10'		Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	Restricted Canopy
SW 5TH AVE	Japanese Blueberry	16-20"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Sprouting	
SW 5TH AVE	Starburst Clerodendron	11-15"	Yes	10'		Good (61% to 80%)	Dead Wood		
SW 5TH AVE	Starburst Clerodendron	11-15"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Starburst Clerodendron	6-10"	Yes	5'		Good (61% to 80%)			
SW 5TH AVE	Starburst Clerodendron	6-10"	Yes	5'		Good (61% to 80%)	Trunk Damage - Minor		
SW 5TH AVE	Starburst Clerodendron	11-15"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Queen Palm	11-15"	No	15'		Good (61% to 80%)			
SW 5TH AVE	Royal Poinciana	31-40"	No	55'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Codominant Leaders/No Included Bark
SW 5TH AVE	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	
SW 5TH AVE	Avocado	31-40"	No	30'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Broken Branches
SW 5TH AVE	Eggfruit Tree	16-20"	No	25'		Fair (41% to 60%)	Dead Wood	Codominant Leaders/Included Bark	Broken Branches
SW 5TH AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 5TH AVE	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 5TH AVE	Gumbo Limbo	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Guy Wire Conflict
SW 5TH AVE	Royal Poinciana	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Vine Cover - Heavy	Lopsided/Reduced Canopy - Moderate
SW 5TH AVE	Mahogany	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 5TH AVE	Mahogany	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 5TH AVE	Silver Buttonwood	6-10"	No	15'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 5TH AVE	Washington Palm	16-20"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 5TH AVE	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 5TH AVE	Cabbage Palm	11-15"	No	15'	Utility Line Conflict	Good (61% to 80%)			
SW 5TH AVE	Black Olive	21-30"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Codominant Leaders/Included Bark
SW 5TH AVE	Black Olive	16-20"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/Included Bark
SW 5TH AVE	Umbrella Tree	6-10"	No	10'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Topped	Stubs with Sprouts
SW 5TH AVE	Gumbo Limbo	6-10"	No	20'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 5TH AVE	Coconut Palm	11-15"	No	10'		Poor (21% to 40%)	Over Pruned	Nutrient Deficiency	Damaged Fronds
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 5TH AVE	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Cavities		

(Continued on Next Page)

Street Tree Inventory

SW 5th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 5TH AVE	Royal Poinciana	21-30"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Codominant Leaders/No Included Bark
SW 5TH AVE	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Over Pruned		
SW 5TH AVE	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Over Pruned		
SW 5TH AVE	Black Olive	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Limb Damage - Major
SW 5TH AVE	Black Olive	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 5TH AVE	Royal Poinciana	11-15"	No	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 5TH AVE	Starburst Clerodendron	6-10"	No	10'		Fair (41% to 60%)	Topped	Stubs with Sprouts	
SW 5TH AVE	Oleander	16-20"	No	5'		Poor (21% to 40%)	Basal Co-Dominant	Stubs with Sprouts	Topped
SW 5TH AVE	Live Oak	6-10"	No	15'		Poor (21% to 40%)	Constricted Roots	Tip Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Vine Cover - Heavy		
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Vine Cover - Heavy		
SW 5TH AVE	Solitaire Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 5TH AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 5TH AVE	Solitaire Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 5TH AVE	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 5TH AVE	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency	Dead Wood	
SW 5TH AVE	Strangler Fig	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Dead Wood	Cavities
SW 5TH AVE	Live Oak	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Utility Pruned
SW 5TH AVE	Bismark Palm	21-30"	No	25'		Good (61% to 80%)			
SW 5TH AVE	Bismark Palm	16-20"	No	25'		Good (61% to 80%)			
SW 5TH AVE	Crepe Myrtle	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Tip Dieback	Seasonal Defoliation/Discolored Foliage	Broken Branches
SW 5TH AVE	Crepe Myrtle	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Tip Dieback	Seasonal Defoliation/Discolored Foliage	Sprouting
SW 5TH AVE	Crepe Myrtle	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Tip Dieback	Seasonal Defoliation/Discolored Foliage	Sprouting
SW 5TH AVE	Crepe Myrtle	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Tip Dieback	Seasonal Defoliation/Discolored Foliage	Sprouting
SW 5TH AVE	Royal Poinciana	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Codominant Leaders/No Included Bark
SW 5TH AVE	Foxtail Palm	11-15"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 5TH AVE	Royal Poinciana	16-20"	No	20'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Limb Damage - Moderate	Stubs with Sprouts
SW 5TH AVE	Royal Poinciana	16-20"	No	20'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Stubs with Sprouts
SW 5TH AVE	Live Oak	31-40"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 5TH AVE	Live Oak	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Sloughing Bark
SW 5TH AVE	Florida Thatch Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 5TH AVE	Florida Thatch Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 5TH AVE	Mahogany	31-40"	No	40'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Decay Observed	Lopsided/Reduced Canopy - Major
SW 5TH AVE	Mahogany	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Lopsided/Reduced Canopy - Major
SW 5TH AVE	Mahogany	21-30"	No	35'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Lopsided/Reduced Canopy - Major
SW 5TH AVE	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Leader - Broken	Lopsided/Reduced Canopy - Major
SW 5TH AVE	Crepe Myrtle	31-40"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Grafted Branches	Sprouting
SW 5TH AVE	Crepe Myrtle	31-40"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Grafted Branches	Sprouting
SW 5TH AVE	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 5TH AVE	Royal Poinciana	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 5TH AVE	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Christmas Palm	6-10"	No	5'		Fair (41% to 60%)	Tapered Trunk	Nutrient Deficiency	
SW 5TH AVE	Mahogany	21-30"	No	20'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Lopsided/Reduced Canopy - Major
SW 5TH AVE	Royal Poinciana	16-20"	No	20'		Poor (21% to 40%)	Cavities	Reduced Canopy - Moderate	Stubs with Sprouts
SW 5TH AVE	Black Olive	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 5th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 5TH AVE	Black Olive	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 5TH AVE	Weeping Fig	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 5TH AVE	Weeping Fig	16-20"	No	20'		Fair (41% to 60%)	Decay Observed	Codominant Leaders/No Included Bark	Dead Wood
SW 5TH AVE	Dracaena sp.	16-20"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Trunk Damage - Minor	Dead Wood	
SW 5TH AVE	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 5TH AVE	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Restricted Canopy		
SW 5TH AVE	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 5TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Reduced Canopy - Moderate	Nutrient Deficiency	
SW 5TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 5TH AVE	Coconut Palm	11-15"	No	10'		Good (61% to 80%)			
SW 5TH AVE	Coconut Palm	6-10"	No	15'		Good (61% to 80%)			
SW 5TH AVE	Jacaranda	11-15"	No	15'		Poor (21% to 40%)	Constricted Roots	Tip Dieback	Broken Branches
SW 5TH AVE	Jacaranda	16-20"	No	25'		Poor (21% to 40%)	Girdling Roots	Cavities	Broken Branches
SW 5TH AVE	Jacaranda	11-15"	No	15'		Fair (41% to 60%)	Sloughing Bark	Dead Wood	Stubs with Sprouts
SW 5TH AVE	Royal Poinciana	21-30"	No	50'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Cavities	Sprouting
SW 5TH AVE	Black Olive	21-30"	No	35'		Good (61% to 80%)	Codominant Leaders/Included Bark	Stubs with Sprouts	Broken Branches
SW 5TH AVE	Mango	1-5"	Yes	5'		Good (61% to 80%)			
SW 5TH AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 5TH AVE	Royal Poinciana	21-30"	No	45'		Poor (21% to 40%)	Root Damage/Decay	Tip Dieback	Dead Wood
SW 5TH AVE	Royal Poinciana	16-20"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Tip Dieback	Trunk Damage - Minor
SW 5TH AVE	Java Bishopwood	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/Included Bark		
SW 5TH AVE	Mahogany	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Adjacent Asphalt Damage	Dead Wood
SW 5TH AVE	Gumbo Limbo	11-15"	No	30'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 5TH AVE	Gumbo Limbo	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 5TH AVE	Gumbo Limbo	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 5TH AVE	Noni Tree	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	
SW 5TH AVE	Live Oak	1-5"	No	5'		Very Poor/Critical (6% to 20%)	Topped	Decay Observed	Sprouting
SW 5TH AVE	Live Oak	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Vine Cover - Heavy	Epicormic Growth
SW 5TH AVE	Vera Wood	6-10"	No	20'		Poor (21% to 40%)	Trunk Damage - Major	Sloughing Bark	Codominant Leaders/Included Bark
SW 5TH AVE	Vera Wood	1-5"	No	10'		Good (61% to 80%)	Leaning - Minor	Codominant Leaders/No Included Bark	Grafted Branches
SW 5TH AVE	Vera Wood	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 5TH AVE	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark	Improperly Mulched
SW 5TH AVE	Mahogany	6-10"	No	20'		Good (61% to 80%)	Crown Density - Excessive (Due to Epicormic Growth)	Improperly Mulched	Codominant Leaders/No Included Bark
SW 5TH AVE	Gumbo Limbo	11-15"	No	20'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Restricted Canopy
SW 5TH AVE	Sea Grape	21-30"	No	30'		Fair (41% to 60%)	Constricted Roots	Sprouting	Grafted Branches
SW 5TH AVE	Gumbo Limbo	21-30"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Tip Dieback	Stubs with Sprouts
SW 5TH AVE	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 5TH AVE	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 5TH AVE	Bottlebrush	11-15"	No	20'		Fair (41% to 60%)	Topped	Leaning - Moderate	Stubs with Sprouts
SW 5TH AVE	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 5TH AVE	Coconut Palm	6-10"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 5TH AVE	Coconut Palm	11-15"	No	25'		Good (61% to 80%)	Nutrient Deficiency		

(Continued on Next Page)

Avenues



Looking Northeast - SW 29th Road




Looking Northeast - SW 26th Road



Looking Northeast - 28th Road



Looking Northeast - SW 26th Road



Looking Southwest - SW 23rd Road



Looking Southwest - SW 11th Street



Looking Southwest - SW 23rd Road



Looking Southwest - SW 11th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 7th Avenue	1	Roads	3	70	3500	No	No	Yes	2	City	Some	Some	9	Yes	Yes	Mostly on NW	Roundabouts at 20th, 23rd, 26th and 28th Roads
SW 9th Avenue	1	Roads	3	70	2500	No	No	Yes	2	City	Some	Some	9	Yes	Yes	No	Roundabout at 24th Road

SW 7th Avenue

TYPOLOGY B

SW 9th Avenue

TYPOLOGY B

Street Tree Inventory

SW 7th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 7TH AVE	White Frangipani	6-10"	No	10'		Poor (21% to 40%)	Basal Co-Dominant	Leader - Broken	Seasonal Defoliation/Discolored Foliage
SW 7TH AVE	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 7TH AVE	Live Oak	21-30"	No	55'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 7TH AVE	Live Oak	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Codominant Leaders/No Included Bark
SW 7TH AVE	Live Oak	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Stubs with Sprouts
SW 7TH AVE	Gumbo Limbo	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 7TH AVE	Live Oak	31-40"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 7TH AVE	Live Oak	21-30"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 7TH AVE	Pigeon Plum	11-15"	No	15'		Poor (21% to 40%)	Decay Observed	Sloughing Bark	Crown Density - Low
SW 7TH AVE	Gumbo Limbo	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 7TH AVE	Black Olive	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Trunk Damage - Major	Dead Wood
SW 7TH AVE	Black Olive	16-20"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 7TH AVE	Black Olive	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 7TH AVE	Royal Poinciana	31-40"	No	Negligible		Dead (0% to 5%)	Ficus Growing on Tree	Vine Cover - Heavy	Dead Wood
SW 7TH AVE	Royal Poinciana	31-40"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 7TH AVE	Black Olive	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Codominant Leaders/No Included Bark
SW 7TH AVE	Mahogany	31-40"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 7TH AVE	Mahogany	11-15"	No	25'		Poor (21% to 40%)	Girdling Roots	Limb Damage - Major	Lopsided/Moderately Reduced Canopy
SW 7TH AVE	Live Oak	16-20"	No	30'		Poor (21% to 40%)	Trunk Damage - Major	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 7TH AVE	Bismark Palm	16-20"	No	15'		Good (61% to 80%)			
SW 7TH AVE	Bismark Palm	21-30"	No	15'		Good (61% to 80%)			
SW 7TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 7TH AVE	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Coconut Palm	11-15"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 7TH AVE	Coconut Palm	6-10"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 7TH AVE	Coconut Palm	6-10"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 7TH AVE	Coconut Palm	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 7TH AVE	Coconut Palm	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Nutrient Deficiency	Trunk Damage - Moderate	
SW 7TH AVE	Green Buttonwood	16-20"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 7TH AVE	Ackee Tree	6-10"	No	20'		Good (61% to 80%)	Stubs with Sprouts	Codominant Leaders/No Included Bark	Limb Damage - Minor
SW 7TH AVE	Royal Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Frizzled Fronds		
SW 7TH AVE	Royal Poinciana	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Broken Branches
SW 7TH AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 7TH AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 7TH AVE	Christmas Palm	6-10"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 7TH AVE	Christmas Palm	6-10"	No	5'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Christmas Palm	6-10"	No	5'	Utility Line Conflict	Good (61% to 80%)			
SW 7TH AVE	Christmas Palm	6-10"	No	5'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Christmas Palm	6-10"	No	5'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 7TH AVE	Sylvester Date Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 7TH AVE	Sylvester Date Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 7TH AVE	Royal Palm	16-20"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 7TH AVE	Sylvester Date Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 7TH AVE	Royal Palm	16-20"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 7TH AVE	Royal Palm	16-20"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 7TH AVE	Royal Palm	16-20"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Pencil Top	Frizzled Fronds	
SW 7TH AVE	Royal Palm	16-20"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			

(Continued on Next Page)

Street Tree Inventory

SW 7th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Bismark Palm	16-20"	No	15'		Good (61% to 80%)			
SW 7TH AVE	Bismark Palm	11-15"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Reduced Canopy - Minor	Strap Constricting Tree
SW 7TH AVE	Royal Poinciana	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Broken Branches
SW 7TH AVE	Royal Poinciana	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Codominant Leaders/Included Bark
SW 7TH AVE	Royal Poinciana	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Cavities
SW 7TH AVE	Royal Poinciana	16-20"	No	15'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Lopsided/Significantly Reduced Canopy
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 7TH AVE	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 7TH AVE	Live Oak	11-15"	No	20'		Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 7TH AVE	Live Oak	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 7TH AVE	Live Oak	21-30"	No	45'		Poor (21% to 40%)	Girdling Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 7TH AVE	Starburst Clerodendron	6-10"	No	10'		Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Epicormic Growth
SW 7TH AVE	Starburst Clerodendron	11-15"	No	5'		Poor (21% to 40%)	Basal Co-Dominant	Topped	Epicormic Growth
SW 7TH AVE	Black Olive	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 7TH AVE	Black Olive	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 7TH AVE	Black Olive	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark
SW 7TH AVE	Black Olive	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 7TH AVE	Black Olive	6-10"	No	30'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 7TH AVE	Queen Palm	11-15"	No	15'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 7TH AVE	Queen Palm	11-15"	No	20'		Poor (21% to 40%)	Trunk Damage - Major	Nutrient Deficiency	
SW 7TH AVE	Gumbo Limbo	16-20"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Grafted Branches	Codominant Leaders/No Included Bark
SW 7TH AVE	Bougainvillea sp.	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Sprouting	
SW 7TH AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 7TH AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 7TH AVE	Gumbo Limbo	1-5"	Yes	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant		
SW 7TH AVE	Norfolk Pine	21-30"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 7TH AVE	Green Buttonwood	16-20"	Yes	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Restricted Canopy
SW 7TH AVE	Green Buttonwood	11-15"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Restricted Canopy
SW 7TH AVE	Green Buttonwood	11-15"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Restricted Canopy
SW 7TH AVE	Green Buttonwood	11-15"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Restricted Canopy
SW 7TH AVE	Gumbo Limbo	6-10"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Restricted Canopy
SW 7TH AVE	Gumbo Limbo	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 7TH AVE	Green Buttonwood	11-15"	No	15'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 7TH AVE	Green Buttonwood	11-15"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Epicormic Growth
SW 7TH AVE	Christmas Palm	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 7TH AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 7TH AVE	Royal Poinciana	21-30"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Cavities	Decay Observed
SW 7TH AVE	Christmas Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 7TH AVE	Foxtail Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 7TH AVE	Foxtail Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 7TH AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 7TH AVE	Florida Thatch Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 7TH AVE	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Over Pruned		
SW 7TH AVE	Montgomery Palm	6-10"	No	10'		Good (61% to 80%)			
SW 7TH AVE	Coconut Palm	11-15"	No	25'		Good (61% to 80%)			
SW 7TH AVE	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			

(Continued on Next Page)

Street Tree Inventory

SW 7th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 7TH AVE	Coconut Palm	11-15"	No	25'		Good (61% to 80%)			
SW 7TH AVE	Mango	6-10"	No	15'		Good (61% to 80%)	Restricted Canopy	Trunk Damage - Minor	Codominant Leaders/No Included Bark
SW 7TH AVE	Black Olive	21-30"	No	35'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Decay Observed
SW 7TH AVE	Bougainvillea sp.	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Crown Density - Low	Epicormic Growth	Dead Wood
SW 7TH AVE	Black Olive	21-30"	No	30'		Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	Stubs with Sprouts
SW 7TH AVE	Foxtail Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 7TH AVE	Royal Poinciana	31-40"	No	60'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Vine Cover - Heavy
SW 7TH AVE	Dracaena sp.	11-15"	No	5'		Good (61% to 80%)	Sprouting		
SW 7TH AVE	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Codominant Leaders/No Included Bark
SW 7TH AVE	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 7TH AVE	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Decay Observed	Lopsided/Significantly Reduced Canopy	Codominant Leaders/No Included Bark
SW 7TH AVE	Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 7TH AVE	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Lateral Branching - None
SW 7TH AVE	Mahogany	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Codominant Leaders/No Included Bark
SW 7TH AVE	Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 7TH AVE	Live Oak	31-40"	No	55'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 7TH AVE	Dracaena sp.	6-10"	Yes	5'		Good (61% to 80%)	Ficus Growing on Tree	Restricted Canopy	Dead Wood
SW 7TH AVE	Mahogany	41-50"	No	60'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Codominant Leaders/Included Bark
SW 7TH AVE	Black Olive	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark
SW 7TH AVE	Rubber Tree	60+"	No	65'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 7TH AVE	Mahogany	16-20"	No	45'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 7TH AVE	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Cavities
SW 7TH AVE	Sylvester Date Palm	6-10"	No	5'		Good (61% to 80%)	Sprouting		
SW 7TH AVE	Sylvester Date Palm	11-15"	No	5'		Good (61% to 80%)	Sprouting		
SW 7TH AVE	Black Olive	21-30"	No	35'		Poor (21% to 40%)	Cavities	Limb Damage - Moderate	Stubs with Sprouts
SW 7TH AVE	Black Olive	21-30"	No	25'		Poor (21% to 40%)	Trunk Damage - Moderate	Limb Damage - Major	Reduced Canopy - Moderate
SW 7TH AVE	Live Oak	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 7TH AVE	Mahogany	21-30"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 7TH AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)			
SW 7TH AVE	Solitaire Palm	1-5"	Yes	5'		Good (61% to 80%)			
SW 7TH AVE	Solitaire Palm	1-5"	Yes	5'		Good (61% to 80%)			
SW 7TH AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)			
SW 7TH AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)			
SW 7TH AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)			
SW 7TH AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)			
SW 7TH AVE	Solitaire Palm	6-10"	Yes	5'		Good (61% to 80%)			
SW 7TH AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 7TH AVE	Solitaire Palm	6-10"	Yes	5'		Good (61% to 80%)			
SW 7TH AVE	Live Oak	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 7TH AVE	Live Oak	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 7TH AVE	Live Oak	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 7TH AVE	Mahogany	21-30"	No	45'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 7TH AVE	Mahogany	21-30"	No	35'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 7TH AVE	Black Olive	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Crown Density - Excessive (Due to Epicormic Growth)
SW 7TH AVE	Black Olive	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Codominant Leaders/No Included Bark
SW 7TH AVE	Black Olive	21-30"	No	45'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 7TH AVE	Royal Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 7th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 7TH AVE	Royal Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 7TH AVE	Royal Palm	6-10"	No	20'		Good (61% to 80%)	Frizzled Fronds		
SW 7TH AVE	Paradise Tree	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Apical Dieback
SW 7TH AVE	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 7TH AVE	Indian Laurel Fig	16-20"	No	15'		Fair (41% to 60%)	Decay Observed	Epicormic Growth	Grafted Branches
SW 7TH AVE	Pink Tabebuia	6-10"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Ficus Growing on Tree
SW 7TH AVE	Japanese Fern Tree	6-10"	No	30'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Sprouting

SW 9th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 9TH AVE	Bismark Palm	16-20"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 9TH AVE	Bismark Palm	11-15"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 9TH AVE	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Codominant Leaders/No Included Bark
SW 9TH AVE	Black Olive	21-30"	No	45'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 9TH AVE	Black Olive	21-30"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 9TH AVE	Black Olive	21-30"	No	35'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Dead Wood	Crown Density - Low
SW 9TH AVE	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 9TH AVE	Mahogany	11-15"	No	15'		Poor (21% to 40%)	Crown Density - Very Low	Cavities	Stubs with Sprouts
SW 9TH AVE	Black Olive	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Codominant Leaders/Included Bark
SW 9TH AVE	Black Olive	31-40"	No	45'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Cavities
SW 9TH AVE	Black Olive	31-40"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sloughing Bark
SW 9TH AVE	Black Olive	21-30"	No	45'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 9TH AVE	Black Olive	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Codominant Leaders/Included Bark
SW 9TH AVE	Black Olive	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Dead Wood
SW 9TH AVE	Black Olive	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Codominant Leaders/Included Bark
SW 9TH AVE	Black Olive	21-30"	No	45'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 9TH AVE	Black Olive	21-30"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Reduced Canopy - Moderate
SW 9TH AVE	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 9TH AVE	Pitch Apple	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Dead Wood	Cavities
SW 9TH AVE	Mahogany	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Root Damage/Decay	Limb Damage - Moderate	Stubs with Sprouts
SW 9TH AVE	Queen Crepe Myrtle	6-10"	No	25'		Fair (41% to 60%)	Seasonal Defoliation/Discolored Foliage	Dead Wood	Codominant Leaders/No Included Bark
SW 9TH AVE	Canary Island Date Palm	16-20"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 9TH AVE	Coconut Palm	6-10"	No	25'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	6-10"	No	5'		Good (61% to 80%)	Restricted Canopy	Trunk Damage - Minor	
SW 9TH AVE	Weeping Fig	11-15"	No	15'		Good (61% to 80%)	Epicormic Growth	Vine Cover - Heavy	Restricted Canopy
SW 9TH AVE	Areca Palm	60+"	Yes	15'		Good (61% to 80%)	Ficus Growing on Tree		
SW 9TH AVE	Mahogany	16-20"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark
SW 9TH AVE	Mahogany	11-15"	No	30'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 9TH AVE	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Lopsided/Moderately Reduced Canopy
SW 9TH AVE	Vera Wood	1-5"	No	5'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Discolored Foliage
SW 9TH AVE	Vera Wood	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			

(Continued on Next Page)

Street Tree Inventory

SW 9th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Umbrella Tree	31-40"	No	25'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Trunk Damage - Major
SW 9TH AVE	Umbrella Tree	31-40"	No	25'		Poor (21% to 40%)	Root Damage/Decay	Basal Co-Dominant	Limb Damage - Moderate
SW 9TH AVE	Live Oak	11-15"	No	20'		Poor (21% to 40%)	Girdling Roots	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 9TH AVE	Live Oak	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 9TH AVE	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 9TH AVE	Live Oak	11-15"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 9TH AVE	Live Oak	11-15"	No	30'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 9TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 9TH AVE	Christmas Palm	6-10"	No	10'		Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 9TH AVE	Christmas Palm	6-10"	No	10'		Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Minor	
SW 9TH AVE	Christmas Palm	6-10"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 9TH AVE	Christmas Palm	6-10"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 9TH AVE	Christmas Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 9TH AVE	Mahogany	21-30"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Trunk Damage - Major	Codominant Leaders/Included Bark
SW 9TH AVE	Mahogany	16-20"	No	5'		Poor (21% to 40%)	Girdling Roots	Topped	Reduced Canopy - Major
SW 9TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 9TH AVE	Mahogany	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 9TH AVE	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)			
SW 9TH AVE	Live Oak	11-15"	No	20'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 9TH AVE	Sea Grape	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 9TH AVE	Ombu Tree	16-20"	No	15'		Poor (21% to 40%)	Cavities	Decay Observed	Insect Damage Leaves
SW 9TH AVE	Java Bishopwood	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 9TH AVE	Pink Tabebuia	11-15"	No	15'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Restricted Canopy
SW 9TH AVE	Christmas Palm	21-30"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Ficus Growing on Tree	
SW 9TH AVE	Black Olive	11-15"	No	15'		Fair (41% to 60%)	Reduced Canopy - Moderate	Codominant Leaders/Included Bark	Restricted Canopy
SW 9TH AVE	Australian Pine	31-40"	No	20'		Good (61% to 80%)	Codominant Leaders/Included Bark	Stubs with Sprouts	Restricted Canopy
SW 9TH AVE	Australian Pine	6-10"	No	10'		Fair (41% to 60%)	Decay Observed	Stubs with Sprouts	Restricted Canopy
SW 9TH AVE	Mahogany	21-30"	No	20'		Poor (21% to 40%)	Constricted Roots	Topped	Codominant Leaders/Included Bark
SW 9TH AVE	Christmas Palm	21-30"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 9TH AVE	Queen Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 9TH AVE	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 9TH AVE	Black Olive	16-20"	No	20'		Fair (41% to 60%)	Reduced Canopy - Moderate	Restricted Canopy	Limb Damage - Minor
SW 9TH AVE	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 9TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 9TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 9TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 9TH AVE	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 9TH AVE	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 9TH AVE	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 9TH AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 9TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 9TH AVE	Royal Poinciana	41-50"	Yes	60'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Basal Co-Dominant
SW 9TH AVE	Royal Poinciana	31-40"	No	60'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Codominant Leaders/No Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 9th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 9TH AVE	Royal Poinciana	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 9TH AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 9TH AVE	Solitaire Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 9TH AVE	Weeping Fig	16-20"	No	25'		Fair (41% to 60%)	Decay Observed	Restricted Canopy	Dead Wood
SW 9TH AVE	Weeping Fig	16-20"	No	20'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Decay Observed
SW 9TH AVE	Weeping Fig	11-15"	No	10'		Poor (21% to 40%)	Basal Co-Dominant	Lateral Branching - None	Decay Observed
SW 9TH AVE	Weeping Fig	21-30"	No	20'		Poor (21% to 40%)	Constricted Roots	Leader - Broken	Stubs with Sprouts
SW 9TH AVE	Japanese Blueberry	11-15"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Limb Damage - Major	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 9TH AVE	Japanese Blueberry	16-20"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 9TH AVE	Bottlebrush	21-30"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 9TH AVE	Bottlebrush	11-15"	No	15'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Decay Observed	Epicormic Growth
SW 9TH AVE	Gumbo Limbo	21-30"	No	30'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 9TH AVE	Sylvester Date Palm	11-15"	No	15'		Good (61% to 80%)	Restricted Canopy		
SW 9TH AVE	Chinese Fan Palm	6-10"	No	10'		Good (61% to 80%)			

Avenues



Looking North - SW 9th Avenue




Looking North - SW 12th Street



Looking North - SW 13th Street



Looking North - SW 12th Street



Looking South - SW 12th Street



Looking South - SW 11th Street



Looking South - SW 12th Street



Looking South - SW 11th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 10th Avenue	1	Roads	3	70	675	No	No	Yes	2	City	Yes	Few	5 (west side) 10 (east side)	Yes	Yes	West Side	Traffic island at 12th Street intersection. Valley gutters between road and on-street parking along both sides.
SW 11th Avenue	1	Roads	3	50	750	No	No	Yes	2	City	Some	Few	0	No	Yes	West Side	Vegetated curb extensions (bulb outs) at intersections. Traffic island at 12th Street intersection.

SW 10th Avenue

TYPOLOGY B

SW 11th Avenue

TYPOLOGY D

Street Tree Inventory

SW 10th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 10TH AVE	Queen Palm	6-10"	No	10'		Poor (21% to 40%)	Nutrient Deficiency	Trunk Damage - Moderate	Restricted Canopy
SW 10TH AVE	Spanish Cherry	11-15"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Major	Stubs with Sprouts
SW 10TH AVE	Spanish Cherry	11-15"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 10TH AVE	Spanish Cherry	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Leader - Broken	Decay Observed
SW 10TH AVE	Starburst Clerodendron	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Sprouting
SW 10TH AVE	Starburst Clerodendron	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Pruned Into Shrub	Sprouting
SW 10TH AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 10TH AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Nutrient Deficiency	Leader - Bent	
SW 10TH AVE	Peregrina	6-10"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Crown Density - Low	Stubs with Sprouts
SW 10TH AVE	Spanish Cherry	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 10TH AVE	Spanish Cherry	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Trunk Damage - Moderate
SW 10TH AVE	Spanish Cherry	16-20"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Adjacent Asphalt Damage	Decay Observed	Stubs with Sprouts
SW 10TH AVE	Royal Poinciana	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 10TH AVE	Spanish Cherry	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Apical Dieback
SW 10TH AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 10TH AVE	Christmas Palm	16-20"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 10TH AVE	Christmas Palm	16-20"	Yes	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 10TH AVE	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Trunk Damage - Minor	
SW 10TH AVE	Spanish Cherry	16-20"	No	30'		Fair (41% to 60%)	Decay Observed	Stubs with Sprouts	Restricted Canopy
SW 10TH AVE	Spanish Cherry	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Dead Wood
SW 10TH AVE	Yellow Poinciana	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Sprouting
SW 10TH AVE	Yellow Poinciana	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 10TH AVE	Spanish Cherry	16-20"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 10TH AVE	Spanish Cherry	21-30"	No	35'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 10TH AVE	White Frangipani	11-15"	No	20'		Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 10TH AVE	Spanish Cherry	16-20"	No	30'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 10TH AVE	Spanish Cherry	16-20"	No	40'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 10TH AVE	Bottlebrush	11-15"	No	20'		Good (61% to 80%)	Trunk Damage - Minor	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 10TH AVE	Spanish Cherry	21-30"	No	30'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Broken Branches
SW 10TH AVE	Spanish Cherry	21-30"	Yes	20'		Poor (21% to 40%)	Topped	Apical Dieback	Stubs with Sprouts
SW 10TH AVE	Gumbo Limbo	16-20"	No	20'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 10TH AVE	Black Olive	21-30"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 10TH AVE	Spanish Cherry	16-20"	No	30'		Poor (21% to 40%)	Topped	Decay Observed	Stubs with Sprouts

SW 11th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH AVE	Yellow Poinciana	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 11TH AVE	Yellow Poinciana	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Decay Observed
SW 11TH AVE	Yellow Poinciana	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Broken Branches
SW 11TH AVE	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 11TH AVE	Yellow Poinciana	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Limb Damage - Moderate
SW 11TH AVE	Yellow Poinciana	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 11TH AVE	Yellow Poinciana	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Stubs with Sprouts	Decay Observed

Avenues




Looking North - SW 3rd Avenue



Looking North - Center of Avenue



Looking North - SW 3rd Avenue



Looking North - Center of Avenue



Looking South - Center of Avenue



Looking South - 22nd Street



Looking South - Center of Avenue



Looking South - SW 22nd Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 13th Avenue	1	Roads	3	100	310	No	No	Yes	4	City	Few	No	20 (west side)	Yes	Yes	West Side	Two traffic islands on South end with 22nd Terrace intersecting, making four entry points going north-bound. Pull-in parking on East side, for commercial building. Bike lane on West side.
SW 14th Avenue	1	Roads	3	50	820	No	No	Yes	2	City	Some	Few	5	Yes	Yes	East Side	Traffic island on South end, making two entry points going northbound.

SW 13th Avenue

TYPOLOGY D and B

SW 14th Avenue

TYPOLOGY B

Street Tree Inventory

SW 13th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH AVE	Yellow Tabebuia	11-15"	No	25'	Utility Lines Above	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	Dead Wood
SW 13TH AVE	Black Olive	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 13TH AVE	Live Oak	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 13TH AVE	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 13TH AVE	Silver Buttonwood	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Pruned Into Shrub	Sprouting
SW 13TH AVE	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Sprouting
SW 13TH AVE	Black Olive	51-60"	No	85'	Utility Line Conflict	Poor (21% to 40%)	Sloughing Bark	Decay Observed	Limb Damage - Major

SW 14th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH AVE	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 14TH AVE	Horseflesh Mahogany	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Crown Density - Low	Epicormic Growth	Codominant Leaders/No Included Bark
SW 14TH AVE	Black Olive	6-10"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Plunged	Broken Branches	Stubs with Sprouts
SW 14TH AVE	Black Olive	21-30"	No	45'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 14TH AVE	Black Olive	6-10"	No	15'		Fair (41% to 60%)	Basal Co-Dominant	Broken Branches	Sprouting
SW 14TH AVE	Black Olive	11-15"	No	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 14TH AVE	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Desiccated Foliage	Apical Dieback	Codominant Leaders/No Included Bark
SW 14TH AVE	Royal Poinciana	21-30"	No	55'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 14TH AVE	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Strap Constricting Tree
SW 14TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Trunk Damage - Minor	Nutrient Deficiency	
SW 14TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 14TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Trunk Damage - Minor	Nutrient Deficiency	
SW 14TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 14TH AVE	Coconut Palm	11-15"	No	20'	Utility Line Conflict	Good (61% to 80%)	Damaged Fronds	Nutrient Deficiency	
SW 14TH AVE	Solitaire Palm	6-10"	Yes	20'		Good (61% to 80%)	Restricted Canopy		
SW 14TH AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	Suppressed Canopy
SW 14TH AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)			
SW 14TH AVE	Live Oak	11-15"	No	40'		Poor (21% to 40%)	Plunged	Apical Dieback	Epicormic Growth
SW 14TH AVE	Live Oak	6-10"	No	20'		Fair (41% to 60%)	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark	Restricted Canopy
SW 14TH AVE	Live Oak	16-20"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Adjacent Asphalt Damage
SW 14TH AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 14TH AVE	Live Oak	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Apical Dieback	Restricted Canopy	Epicormic Growth
SW 14TH AVE	Live Oak	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 14TH AVE	Montgomery Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Cracks in Trunk	Restricted Canopy	
SW 14TH AVE	Montgomery Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Damaged Fronds	Suppressed Canopy
SW 14TH AVE	Montgomery Palm	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 14TH AVE	Wild/Cuban Tamarind	6-10"	No	20'	Utility Lines Above	Poor (21% to 40%)	Lifting	Topped	Stubs with Sprouts
SW 14TH AVE	Crepe Myrtle	11-15"	Yes	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Restricted Canopy	Suppressed Canopy
SW 14TH AVE	Mahogany	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Epicormic Growth
SW 14TH AVE	Weeping Fig	6-10"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Dead Wood	Codominant Leaders/Included Bark
SW 14TH AVE	Crepe Myrtle	1-5"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Seasonal Defoliation/Discolored Foliage	Decay Observed
SW 14TH AVE	Crepe Myrtle	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Sprouting	Grafted Branches
SW 14TH AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 14TH AVE	Mahogany	31-40"	No	65'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 14th Avenue (Continuted)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 14TH AVE	Gumbo Limbo	1-5"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Dead Wood
SW 14TH AVE	Gumbo Limbo	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Epicormic Growth
SW 14TH AVE	Satin Leaf	1-5"	No	20'	Utility Lines Above	Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Broken Branches
SW 14TH AVE	Satin Leaf	6-10"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Apical Dieback	Crown Density - Low	Epicormic Growth
SW 14TH AVE	Satin Leaf	6-10"	No	25'	Utility Lines Above	Poor (21% to 40%)	Plunged	Crown Density - Low	Epicormic Growth
SW 14TH AVE	Horseflesh Mahogany	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Crown Density - Low	Epicormic Growth
SW 14TH AVE	Horseflesh Mahogany	1-5"	No	10'	Utility Lines Above	Poor (21% to 40%)	Apical Dieback	Epicormic Growth	Crown Density - Low
SW 14TH AVE	Horseflesh Mahogany	1-5"	No	10'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Low	Epicormic Growth	Apical Dieback
SW 14TH AVE	Horseflesh Mahogany	1-5"	No	10'	Utility Lines Above	Very Poor/Critical (6% to 20%)	Improperly Mulched	Crown Density - Very Low	Dead Wood

Avenues | Courts



Looking North - SW 1st Avenue



Looking North - SW 23rd Street



Looking North - SW 3rd Avenue




Looking North - SW 23rd Street



Looking South - SW 23rd Street



Looking South - SW 22nd Street



Looking South - SW 23rd Street



Looking South - SW 22nd Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 16th Court	1	Roads	3	60	1500	No	No	No	2	City	Few	Few	15	Yes	Yes	Mostly on West	Parking on swales South of 23rd Street. Roundabout at 23rd Street.
SW 16th Avenue	1	Roads	3	50	1200	No	No	No	2	City	Some	Few	10 (west side) 5 (east side)	East side	Yes	Mostly on East	Two large traffic islands on South end, two entry points going Northbound and one going Southbound. Two speed bumps, one just before 23rd Terrace and another after 23rd Street

SW 16th Court

TYPOLOGY C and A

SW 16th Avenue

TYPOLOGY A and C

Street Tree Inventory

SW 16th Court

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH CT	Christmas Palm	16-20"	Yes	20'		Good (61% to 80%)	Restricted Canopy		
SW 16TH CT	Christmas Palm	21-30"	Yes	20'		Good (61% to 80%)	Restricted Canopy		
SW 16TH CT	Queen Crepe Myrtle	6-10"	No	10'	Utility Lines Above	Dead (0% to 5%)	Decay Observed	Dead Wood	
SW 16TH CT	Queen Crepe Myrtle	6-10"	Yes	5'	Utility Lines Above	Very Poor/Critical (6% to 20%)	Decay Observed	Topped	Sprouting
SW 16TH CT	Queen Crepe Myrtle	6-10"	No	10'	Utility Lines Above	Dead (0% to 5%)	Decay Observed	Dead Wood	Topped
SW 16TH CT	Date Palm	11-15"	No	20'	Utility Line Conflict	Good (61% to 80%)	Ficus Growing on Tree		
SW 16TH CT	Date Palm	11-15"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 16TH CT	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Low	Apical Dieback	Sprouting
SW 16TH CT	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Low	Apical Dieback	Codominant Leaders/Included Bark
SW 16TH CT	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Low	Apical Dieback	Codominant Leaders/Included Bark
SW 16TH CT	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Low	Apical Dieback	Sprouting
SW 16TH CT	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Restricted Canopy
SW 16TH CT	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Restricted Canopy
SW 16TH CT	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Restricted Canopy
SW 16TH CT	Hong Kong Orchid	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Leader - Broken	Decay Observed	Sprouting
SW 16TH CT	Hong Kong Orchid	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	Sprouting
SW 16TH CT	Hong Kong Orchid	11-15"	No	30'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Trunk Damage - Major	Decay Observed	Topped
SW 16TH CT	Live Oak	6-10"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark	Grafted Branches
SW 16TH CT	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Low	Apical Dieback	Codominant Leaders/Included Bark
SW 16TH CT	Pygmy Date Palm	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 16TH CT	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Trunk Damage - Moderate	Codominant Leaders/Included Bark
SW 16TH CT	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/Included Bark	Sprouting
SW 16TH CT	Green Buttonwood	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Desiccated Foliage	Strap Constricting Tree
SW 16TH CT	Crepe Myrtle	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Sprouting	Strap Constricting Tree
SW 16TH CT	Crepe Myrtle	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Plunged	Crown Density - Low	Seasonal Defoliation/Discolored Foliage
SW 16TH CT	Live Oak	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 16TH CT	Live Oak	6-10"	No	25'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback
SW 16TH CT	Brazilian Pepper	11-15"	Yes	15'	Utility Lines Above	Fair (41% to 60%)	Trunk Damage - Moderate	Broken Branches	Sprouting
SW 16TH CT	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 16TH CT	Yellow Tabebuia	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Dead Wood
SW 16TH CT	Yellow Tabebuia	11-15"	No	20'		Poor (21% to 40%)	Root Damage/Decay	Apical Dieback	Dead Wood
SW 16TH CT	Green Buttonwood	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Desiccated Foliage	Sprouting
SW 16TH CT	Live Oak	21-30"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Adjacent Concrete Damage	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 16TH CT	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Codominant Leaders/No Included Bark
SW 16TH CT	Live Oak	6-10"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 16TH CT	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Cracks in Trunk
SW 16TH CT	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Strap Constricting Tree
SW 16TH CT	Japanese Privet	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Grafted Branches	Epicormic Growth
SW 16TH CT	Live Oak	41-50"	No	85'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Vine Cover - Heavy
SW 16TH CT	Bridalveil Tree	1-5"	No	15'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 16TH CT	Black Olive	6-10"	No	40'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 16TH CT	Pigeon Plum	1-5"	No	5'		Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	Broken Branches

(Continued on Next Page)

Street Tree Inventory

SW 16th Court (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH CT	Bottlebrush	1-5"	No	5'		Fair (41% to 60%)	Plunged	Codominant Leaders/Included Bark	Strap Constricting Tree
SW 16TH CT	Dahoon Holly	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 16TH CT	Pygmy Date Palm	11-15"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 16TH CT	Japanese Fern Tree	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Plunged	Trunk Damage - Minor	Codominant Leaders/No Included Bark
SW 16TH CT	Crepe Myrtle	6-10"	Yes	10'		Fair (41% to 60%)	Seasonal Defoliation/Discolored Foliage	Crown Density - Low	Epicormic Growth
SW 16TH CT	Bottlebrush	1-5"	No	5'		Fair (41% to 60%)	Uprooted - Mostly	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 16TH CT	Yellow Tabebuia	11-15"	No	5'	Utility Lines Above	Poor (21% to 40%)	Plunged	Topped	Stubs with Sprouts
SW 16TH CT	Japanese Privet	6-10"	Yes	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	Pruned Into Shrub
SW 16TH CT	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 16TH CT	Live Oak	16-20"	No	20'	Utility Lines Above	Dead (0% to 5%)	Dead Wood	Sloughing Bark	Vine Cover - Heavy

SW 16th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH AVE	Live Oak	6-10"	No	30'		Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Epicormic Growth
SW 16TH AVE	Banyan	60+"	No	95'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 16TH AVE	Hibiscus sp.	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Stubs with Sprouts
SW 16TH AVE	Gumbo Limbo	6-10"	No	20'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 16TH AVE	Mahogany	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Adjacent Concrete Damage	Decay Observed
SW 16TH AVE	Dahoon Holly	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 16TH AVE	Satin Leaf	1-5"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 16TH AVE	Live Oak	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 16TH AVE	Washington Palm	16-20"	No	15'		Good (61% to 80%)			
SW 16TH AVE	Gumbo Limbo	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 16TH AVE	Gumbo Limbo	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Plunged	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 16TH AVE	Queen Palm	6-10"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 16TH AVE	Green Buttonwood	6-10"	No	25'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Vine Cover - Heavy	Restricted Canopy
SW 16TH AVE	Bougainvillea sp.	16-20"	Yes	25'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Grafted with Adjacent Tree
SW 16TH AVE	Solitaire Palm	1-5"	Yes	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency	Damaged Fronds	Restricted Canopy
SW 16TH AVE	Solitaire Palm	1-5"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency	Damaged Fronds	Restricted Canopy
SW 16TH AVE	Solitaire Palm	1-5"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 16TH AVE	Solitaire Palm	1-5"	Yes	10'		Fair (41% to 60%)	Nutrient Deficiency	Damaged Fronds	Restricted Canopy
SW 16TH AVE	Solitaire Palm	1-5"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency	Damaged Fronds	Restricted Canopy
SW 16TH AVE	Mahogany	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 16TH AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Epicormic Growth
SW 16TH AVE	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Epicormic Growth
SW 16TH AVE	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Adjacent Concrete Damage	Trunk Damage - Major	Dead Wood
SW 16TH AVE	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 16TH AVE	Christmas Palm	16-20"	Yes	20'		Good (61% to 80%)			
SW 16TH AVE	Mahogany	16-20"	No	10'	Utility Line Conflict	Poor (21% to 40%)	Root Damage/Decay	Topped	Stubs with Sprouts
SW 16TH AVE	Live Oak	16-20"	No	45'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 16TH AVE	Live Oak	11-15"	No	35'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 16TH AVE	Mahogany	6-10"	No	20'		Poor (21% to 40%)	Trunk Damage - Moderate	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 16TH AVE	Mahogany	31-40"	No	35'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Trunk Damage - Major	Decay Observed	Leader - Broken
SW 16TH AVE	Gumbo Limbo	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Trunk Damage - Minor

(Continued on Next Page)

Street Tree Inventory

SW 16th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 16TH AVE	Gumbo Limbo	6-10"	No	15'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 16TH AVE	Areca Palm	6-10"	Yes	10'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 16TH AVE	Queen Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	Suppressed Canopy
SW 16TH AVE	Weeping Fig	16-20"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Lion's Tailing	Sprouting
SW 16TH AVE	Earleaf Acacia	21-30"	No	45'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Dead Wood
SW 16TH AVE	Earleaf Acacia	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Utility Pruned
SW 16TH AVE	Weeping Fig	21-30"	No	50'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 16TH AVE	Weeping Fig	21-30"	No	Negligible	Utility Lines Adjacent (laterally)	Dead (0% to 5%)	Topped	Dead Wood	Decay Observed
SW 16TH AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 16TH AVE	Solitaire Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Trunk Damage - Moderate	Restricted Canopy	
SW 16TH AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 16TH AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 16TH AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 16TH AVE	Gumbo Limbo	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 16TH AVE	Mahogany	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Utility Pruned	Lopsided/Moderately Reduced Canopy
SW 16TH AVE	Mahogany	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Utility Pruned
SW 16TH AVE	Mahogany	31-40"	No	60'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Lion's Tailing
SW 16TH AVE	Solitaire Palm	1-5"	No	Negligible	Utility Line Conflict	Dead (0% to 5%)	Dead Meristem		
SW 16TH AVE	Solitaire Palm	1-5"	No	Negligible	Utility Lines Adjacent (laterally)	Dead (0% to 5%)	Dead Meristem		
SW 16TH AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 16TH AVE	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Improperly Mulched	Crown Density - Low	Sprouting
SW 16TH AVE	Dahoon Holly	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Strap Constricting Tree	
SW 16TH AVE	Pigeon Plum	6-10"	Yes	15'	Utility Lines Above	Fair (41% to 60%)	Crown Density - Excessive (Due to Epicormic Growth)	Grafted Branches	Codominant Leaders/No Included Bark
SW 16TH AVE	Pigeon Plum	1-5"	No	10'	Utility Lines Above	Poor (21% to 40%)	Cracks in Trunk	Codominant Leaders/No Included Bark	Sloughing Bark
SW 16TH AVE	Pigeon Plum	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Trunk Damage - Moderate	Codominant Leaders/Included Bark	Sprouting
SW 16TH AVE	Solitaire Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 16TH AVE	Solitaire Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 16TH AVE	Pink Tabebuia	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Topped	Galls
SW 16TH AVE	Pink Tabebuia	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Galls	Stubs with Sprouts
SW 16TH AVE	Pigeon Plum	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/Included Bark	Grafted Branches

Roads




Looking Northwest - I-95



Looking Northwest - Center of Road




Looking Northwest - SW 3rd Avenue




Looking Northwest - Center of Road




Looking Southeast - Center of Road



Looking Southeast - SW 11th Street



Looking Southeast - Center of Road



Looking Southeast - SW 4th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 15th Road	1	Roads	3	100	780	Yes	Yes	No	2	City	Yes	No	10(south side)	North side	Yes	No	Large median with no curb. Bike Lanes going both directions.
SW 17th Road	1	Roads	3	70	530	No	No	Yes	2	City	Few	Few	10	Yes	Yes	mostly on SW	Vegetated curb exension (Bulb out) South end, East side.

SW 15th Road

TYPOLOGY H

SW 17th Road

TYPOLOGY B

Street Tree Inventory

SW 15th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 15TH RD	Black Olive	21-30"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 15TH RD	Gumbo Limbo	6-10"	No	20'	Utility Lines Above	Fair (41% to 60%)	Codominant Leaders/No Included Bark	Lopsided/Moderately Reduced Canopy	Sprouting
SW 15TH RD	Crepe Myrtle	11-15"	Yes	20'	Utility Lines Above	Fair (41% to 60%)	Seasonal Defoliation/Discolored Foliage	Crown Density - Low	Vine Cover - Heavy
SW 15TH RD	Pygmy Date Palm	11-15"	Yes	20'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 15TH RD	Unidentified Dead Tree (Defoliated)	21-30"	No	Negligible	Utility Lines Above	Dead (0% to 5%)	Leader - Broken	Decay Observed	Dead Wood
SW 15TH RD	Pop Ash	6-10"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Apical Dieback
SW 15TH RD	Mahogany	31-40"	No	50'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Decay Observed	Utility Pruned
SW 15TH RD	Black Olive	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 15TH RD	Hong Kong Orchid	11-15"	No	25'		Poor (21% to 40%)	Basal Co-Dominant	Discolored Foliage	Apical Dieback
SW 15TH RD	Hong Kong Orchid	11-15"	No	25'		Poor (21% to 40%)	Basal Co-Dominant	Discolored Foliage	Apical Dieback
SW 15TH RD	Royal Poinciana	21-30"	No	40'		Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 15TH RD	Royal Poinciana	16-20"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Galls	Decay Observed	Broken Branches
SW 15TH RD	Gumbo Limbo	1-5"	No	15'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Basal Co-Dominant with Adjacent Tree(s)	Ficus Growing on Tree
SW 15TH RD	Strangler Fig	16-20"	Yes	20'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Stubs with Sprouts
SW 15TH RD	Strangler Fig	21-30"	No	40'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Broken Branches	Epicormic Growth
SW 15TH RD	Areca Palm	21-30"	Yes	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 15TH RD	Royal Poinciana	21-30"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Decay Observed	Crown Density - Low	Stubs with Sprouts
SW 15TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Suppressed Canopy	Trunk Damage - Minor	
SW 15TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 15TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 15TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 15TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 15TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 15TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 15TH RD	Royal Poinciana	21-30"	No	35'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Ficus Growing on Tree
SW 15TH RD	Cabbage Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 15TH RD	Royal Poinciana	11-15"	No	35'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Plunged	Limb Damage - Major	Apical Dieback
SW 15TH RD	Royal Poinciana	16-20"	No	50'		Poor (21% to 40%)	Ficus Growing on Tree	Limb Damage - Major	Stubs with Sprouts
SW 15TH RD	Royal Poinciana	21-30"	No	45'		Poor (21% to 40%)	Plunged	Decay Observed	Stubs with Sprouts
SW 15TH RD	Royal Poinciana	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Plunged	Decay Observed	Lopsided/Moderately Reduced Canopy
SW 15TH RD	Live Oak	21-30"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood
SW 15TH RD	Royal Poinciana	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Decay Observed
SW 15TH RD	Royal Poinciana	16-20"	No	30'		Poor (21% to 40%)	Plunged	Reduced Canopy - Moderate	Stubs with Sprouts
SW 15TH RD	Royal Poinciana	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Strap Constricting Tree
SW 15TH RD	Royal Poinciana	21-30"	No	45'		Fair (41% to 60%)	Constricted Roots	Vine Cover - Heavy	Stubs with Sprouts
SW 15TH RD	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Ficus Growing on Tree
SW 15TH RD	Royal Poinciana	21-30"	No	40'		Fair (41% to 60%)	Decay Observed	Cavities	Broken Branches
SW 15TH RD	Australian Pine	11-15"	No	10'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Dead Wood	Broken Branches
SW 15TH RD	Australian Pine	16-20"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 15TH RD	Royal Poinciana	6-10"	No	25'	Utility Lines Above	Poor (21% to 40%)	Plunged	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 15TH RD	Royal Poinciana	6-10"	No	30'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Strap Constricting Tree
SW 15TH RD	Royal Poinciana	11-15"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 15TH RD	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)			
SW 15TH RD	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Split Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 17th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 17TH RD	Royal Poinciana	21-30"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 17TH RD	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 17TH RD	Christmas Palm	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 17TH RD	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 17TH RD	Live Oak	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Plunged	Apical Dieback	Epicormic Growth
SW 17TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 17TH RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Damaged Fronds	
SW 17TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 17TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	Damaged Fronds
SW 17TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 17TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 17TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 17TH RD	Solitaire Palm	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 17TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 17TH RD	Coconut Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 17TH RD	Coconut Palm	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)			
SW 17TH RD	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 17TH RD	Mahogany	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts


Roads | Terraces



Looking Northwest - SW 3rd Avenue



Looking Northwest - SW 4th Avenue



Looking Northwest - SW 3rd Avenue



Looking Northwest - SW 4th Avenue



Looking Southeast - SW 4th Avenue



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 4th Avenue



Looking Southeast - SW 11th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 18th Road	1	Roads	3	70	1000	No	No	Yes	2	City	Few	Yes	9	Yes	Yes	mostly on NE	Wide intersection on NW end, 5th Avenue and 11 Street join together at angled road, possible opportunity for landscaped traffic island.
SW 18th Terrace	1	Roads	3	70	1330	No	No	Yes	2	City	Some	Some	9	Yes	Yes	mostly on NE	Dense tree canopy on SE end.

SW 18th Road

TYPOLOGY B and A

SW 18th Terrace

TYPOLOGY B

Street Tree Inventory

SW 18th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH RD	Mahogany	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Broken Branches
SW 18TH RD	Vera Wood	1-5"	No	20'		Poor (21% to 40%)	Plunged	Apical Dieback	Epicormic Growth
SW 18TH RD	Live Oak	11-15"	No	35'		Poor (21% to 40%)	Plunged	Constricted Roots	Apical Dieback
SW 18TH RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)			
SW 18TH RD	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 18TH RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 18TH RD	Green Buttonwood	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Sprouting	Codominant Leaders/No Included Bark
SW 18TH RD	Crepe Myrtle	1-5"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Improperly Mulched	Crown Density - Very Low	Seasonal Defoliation/Discolored Foliage
SW 18TH RD	Crepe Myrtle	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Crown Density - Very Low	Seasonal Defoliation/Discolored Foliage
SW 18TH RD	Crepe Myrtle	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Seasonal Defoliation/Discolored Foliage
SW 18TH RD	Crepe Myrtle	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Improperly Mulched	Sprouting	Seasonal Defoliation/Discolored Foliage
SW 18TH RD	Crepe Myrtle	1-5"	No	10'		Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	Seasonal Defoliation/Discolored Foliage
SW 18TH RD	Norfolk Pine	16-20"	No	20'		Good (61% to 80%)	Stubs with Sprouts	Adjacent Light Pole	
SW 18TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 18TH RD	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 18TH RD	Mahogany	11-15"	No	10'		Good (61% to 80%)	Codominant Leaders/Included Bark	Pruned Into Shrub	Stubs with Sprouts
SW 18TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 18TH RD	Coconut Palm	11-15"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 18TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 18TH RD	Coconut Palm	6-10"	No	25'		Good (61% to 80%)	Nutrient Deficiency		
SW 18TH RD	Coconut Palm	6-10"	No	25'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 18TH RD	Coconut Palm	6-10"	No	25'		Good (61% to 80%)	Restricted Canopy		
SW 18TH RD	Coconut Palm	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 18TH RD	Black Olive	16-20"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Broken Branches
SW 18TH RD	Black Olive	11-15"	No	30'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Broken Branches
SW 18TH RD	Christmas Palm	6-10"	No	10'		Fair (41% to 60%)	Tapered Trunk	Restricted Canopy	Suppressed Canopy
SW 18TH RD	Coconut Palm	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 18TH RD	Coconut Palm	11-15"	No	25'		Good (61% to 80%)	Restricted Canopy		
SW 18TH RD	Coconut Palm	11-15"	No	25'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 18TH RD	Coconut Palm	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 18TH RD	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 18TH RD	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 18TH RD	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency	Trunk Damage - Minor	Frizzled Fronds
SW 18TH RD	Areca Palm	16-20"	Yes	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 18TH RD	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 18TH RD	Canary Island Date Palm	21-30"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Nutrient Deficiency	Reduced Canopy - Moderate	Ficus Growing on Tree
SW 18TH RD	Crepe Myrtle	16-20"	Yes	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Galls	Seasonal Defoliation/Discolored Foliage	Crown Density - Very Low
SW 18TH RD	Sapodilla	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Trunk Damage - Major
SW 18TH RD	Allspice	11-15"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Moderate	Decay Observed	Stubs with Sprouts
SW 18TH RD	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)			
SW 18TH RD	Sylvester Date Palm	16-20"	No	20'		Good (61% to 80%)	Ficus Growing on Tree	Restricted Canopy	
SW 18TH RD	Sylvester Date Palm	11-15"	No	15'		Fair (41% to 60%)	Over Pruned	Restricted Canopy	Ficus Growing on Tree
SW 18TH RD	Sylvester Date Palm	16-20"	No	15'		Fair (41% to 60%)	Over Pruned	Restricted Canopy	Ficus Growing on Tree
SW 18TH RD	Sylvester Date Palm	16-20"	No	15'		Fair (41% to 60%)	Over Pruned	Restricted Canopy	Ficus Growing on Tree
SW 18TH RD	Sylvester Date Palm	16-20"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Ficus Growing on Tree
SW 18TH RD	Sylvester Date Palm	21-30"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 18TH RD	Sylvester Date Palm	16-20"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Ficus Growing on Tree

(Continued on Next Page)

Street Tree Inventory

SW 18th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH RD	Pygmy Date Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 18TH RD	Pygmy Date Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 18TH RD	Pygmy Date Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 18TH RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Damaged Fronds
SW 18TH RD	Coconut Palm	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Damaged Fronds
SW 18TH RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	Damaged Fronds
SW 18TH RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 18TH RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 18TH RD	Royal Palm	11-15"	No	5'	Utility Line Conflict	Poor (21% to 40%)	Nutrient Deficiency	Frizzled Fronds	Reduced Canopy - Major
SW 18TH RD	Oriental Arborvitae	11-15"	No	15'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	
SW 18TH RD	Queen Crepe Myrtle	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 18TH RD	Queen Crepe Myrtle	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Leaning - Moderate	Seasonal Defoliation/Discolored Foliage	Grafted Branches
SW 18TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 18TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 18TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 18TH RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 18TH RD	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 18TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 18TH RD	Mahogany	31-40"	No	60'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Epicormic Growth
SW 18TH RD	Mahogany	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Utility Pruned	Limb Damage - Moderate
SW 18TH RD	Japanese Fern Tree	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Epicormic Growth
SW 18TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 18TH RD	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 18TH RD	Spanish Lime	1-5"	Yes	5'		Good (61% to 80%)	Sprouting	Codominant Leaders/No Included Bark	
SW 18TH RD	Umbrella Tree	6-10"	No	5'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 18TH RD	Umbrella Tree	6-10"	No	10'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Sprouting
SW 18TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Damaged Fronds	

SW 18th Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH TER	Live Oak	6-10"	No	30'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Broken Branches
SW 18TH TER	Bottlebrush	16-20"	No	30'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Decay Observed	Dead Wood
SW 18TH TER	Royal Poinciana	31-40"	No	60'		Poor (21% to 40%)	Basal Co-Dominant	Crown Density - Low	Stubs with Sprouts
SW 18TH TER	Yellow Tabebuia	11-15"	No	25'		Poor (21% to 40%)	Girdling Roots	Lifting	Epicormic Growth
SW 18TH TER	Queen Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 18TH TER	Royal Poinciana	21-30"	No	50'		Fair (41% to 60%)	Decay Observed	Broken Branches	Stubs with Sprouts
SW 18TH TER	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Tapered Trunk	Nutrient Deficiency	Restricted Canopy
SW 18TH TER	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 18TH TER	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 18TH TER	Live Oak	21-30"	No	60'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 18TH TER	Gumbo Limbo	11-15"	No	25'		Fair (41% to 60%)	Plunged	Grafted Branches	Codominant Leaders/No Included Bark
SW 18TH TER	Royal Poinciana	21-30"	No	65'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 18TH TER	Royal Palm	16-20"	No	20'		Good (61% to 80%)			
SW 18TH TER	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 18TH TER	White Frangipani	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Crown Density - Low	Sprouting	
SW 18TH TER	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 18TH TER	Bottle Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 18th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH TER	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 18TH TER	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 18TH TER	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 18TH TER	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 18TH TER	Live Oak	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Adjacent Asphalt Damage	Crown Density - Excessive (Due to Epicormic Growth)	Broken Branches
SW 18TH TER	Live Oak	6-10"	No	20'		Poor (21% to 40%)	Apical Dieback	Crown Density - Low	Epicormic Growth
SW 18TH TER	Coconut Palm	6-10"	No	10'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 18TH TER	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Restricted Canopy		
SW 18TH TER	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 18TH TER	Areca Palm	21-30"	Yes	15'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 18TH TER	Areca Palm	16-20"	Yes	10'		Good (61% to 80%)			
SW 18TH TER	Areca Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 18TH TER	Areca Palm	11-15"	Yes	5'		Good (61% to 80%)	Restricted Canopy		
SW 18TH TER	Areca Palm	11-15"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 18TH TER	Areca Palm	11-15"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 18TH TER	Areca Palm	6-10"	Yes	5'		Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	
SW 18TH TER	Areca Palm	11-15"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 18TH TER	Areca Palm	6-10"	Yes	5'		Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	
SW 18TH TER	Areca Palm	11-15"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 18TH TER	Areca Palm	11-15"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 18TH TER	Black Olive	11-15"	No	30'		Fair (41% to 60%)	Limb Damage - Moderate	Sprouting	Restricted Canopy
SW 18TH TER	Black Olive	16-20"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Limb Damage - Moderate	Stubs with Sprouts	Broken Branches
SW 18TH TER	Mahogany	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Epicormic Growth
SW 18TH TER	Mahogany	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 18TH TER	Crepe Myrtle	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Crown Density - Very Low
SW 18TH TER	Crepe Myrtle	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Crown Density - Low
SW 18TH TER	Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Sprouting
SW 18TH TER	Weeping Fig	60+"	Yes	45'	Utility Line Conflict	Poor (21% to 40%)	Topped	Decay Observed	Stubs with Sprouts
SW 18TH TER	Black Olive	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Utility Pruned	Stubs with Sprouts
SW 18TH TER	Black Olive	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 18TH TER	Black Olive	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 18TH TER	Black Olive	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 18TH TER	Black Olive	16-20"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 18TH TER	Black Olive	6-10"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Decay Observed	Crown Density - Low	Limb Damage - Major
SW 18TH TER	Black Olive	11-15"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Decay Observed	Dead Wood	Lopsided/Moderately Reduced Canopy
SW 18TH TER	Black Olive	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 18TH TER	Black Olive	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Decay Observed	Basal Co-Dominant	Cavities
SW 18TH TER	Black Olive	11-15"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Root Damage/Decay	Broken Branches	Stubs with Sprouts
SW 18TH TER	Black Olive	16-20"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 18TH TER	Black Olive	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Utility Pruned	Stubs with Sprouts
SW 18TH TER	Black Olive	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Topped	Decay Observed
SW 18TH TER	Mahogany	21-30"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 18TH TER	Mahogany	31-40"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 18TH TER	Longan	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	
SW 18TH TER	Longan	21-30"	Yes	15'	Utility Line Conflict	Fair (41% to 60%)	Topped	Stubs with Sprouts	Dead Wood
SW 18TH TER	Longan	16-20"	Yes	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Broken Branches
SW 18TH TER	Longan	6-10"	No	25'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Sprouting	Restricted Canopy
SW 18TH TER	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Nutrient Deficiency	Frizzled Fronds	
SW 18TH TER	Black Olive	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Sprouting
SW 18TH TER	Black Olive	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Utility Pruned

(Continued on Next Page)

Street Tree Inventory

SW 18th Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 18TH TER	Sapodilla	21-30"	No	35'	Utility Lines Above	Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Stubs with Sprouts
SW 18TH TER	Royal Poinciana	16-20"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 18TH TER	Royal Poinciana	16-20"	No	45'	Utility Line Conflict	Good (61% to 80%)	Adjacent Asphalt Damage	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 18TH TER	Royal Poinciana	6-10"	No	25'	Utility Lines Above	Fair (41% to 60%)	Cracks in Trunk	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 18TH TER	Black Olive	31-40"	No	50'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 18TH TER	Fishtail Palm	21-30"	Yes	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 18TH TER	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Lifting
SW 18TH TER	Live Oak	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 18TH TER	Live Oak	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark	Stubs
SW 18TH TER	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 18TH TER	Starburst Clerodendron	6-10"	No	10'	Utility Line Conflict	Poor (21% to 40%)	Plunged	Basal Co-Dominant	Epicormic Growth
SW 18TH TER	Starburst Clerodendron	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Stubs with Sprouts		
SW 18TH TER	Starburst Clerodendron	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	
SW 18TH TER	Starburst Clerodendron	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Stubs with Sprouts
SW 18TH TER	Starburst Clerodendron	16-20"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Pruned Into Shrub	Stubs with Sprouts
SW 18TH TER	Starburst Clerodendron	1-5"	Yes	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Pruned Into Shrub	Stubs with Sprouts
SW 18TH TER	Starburst Clerodendron	1-5"	No	5'	Utility Lines Above	Dead (0% to 5%)	Dead Wood	Crown Density - Very Low	
SW 18TH TER	Starburst Clerodendron	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Stubs with Sprouts	
SW 18TH TER	Starburst Clerodendron	6-10"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Stubs with Sprouts
SW 18TH TER	Royal Poinciana	31-40"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Adjacent Concrete Damage	Galls	Stubs with Sprouts
SW 18TH TER	Royal Poinciana	6-10"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Adjacent Concrete Damage	Girdling Roots	Restricted Canopy

Roads



Looking Northwest - SW 1st Avenue



Looking Northwest - SW 4th Avenue



Looking Northwest - SW 1st Avenue



Looking Northwest - SW 4th Avenue



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 11th Street



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 7th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 19th Road	1	Roads	3	70	2750	No	No	Yes	2	City	Few	Some	9	NW of 3rd Avenue	Yes	mostly on NE	Dense tree canopy SE of 3rd Avenue
SW 20th Road	1	Roads	3	70	3000	No	No	Yes	2	City	Some	Some	9	NW of 3rd Avenue	Yes	South of 7th Ave mostly on NE	Large segments with no tree canopy. Roundabouts at 5th and 7th Avenue.

SW 19th Road

TYPOLOGY B and A

SW 20th Road

TYPOLOGY B and A

Street Tree Inventory

SW 19th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH RD	Royal Poinciana	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Galls	Stubs with Sprouts
SW 19TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Vine Cover - Heavy	Restricted Canopy	
SW 19TH RD	Black Olive	41-50"	No	65'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Codominant Leaders/No Included Bark
SW 19TH RD	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Ficus Growing on Tree
SW 19TH RD	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 19TH RD	Live Oak	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 19TH RD	Jacaranda	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Stubs with Sprouts	Apical Dieback
SW 19TH RD	Live Oak	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Plunged	Apical Dieback
SW 19TH RD	Pygmy Date Palm	6-10"	Yes	5'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 19TH RD	Pygmy Date Palm	1-5"	No	5'		Good (61% to 80%)			
SW 19TH RD	Black Olive	21-30"	No	30'		Poor (21% to 40%)	Girdling Roots	Reduced Canopy - Moderate	Crown Density - Excessive (Due to Epicormic Growth)
SW 19TH RD	Christmas Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 19TH RD	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 19TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 19TH RD	Solitaire Palm	1-5"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 19TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 19TH RD	Queen Palm	11-15"	No	25'		Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 19TH RD	Queen Palm	11-15"	No	25'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 19TH RD	Java Bishopwood	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 19TH RD	Glaucous Cassia	6-10"	No	15'		Poor (21% to 40%)	Plunged	Sloughing Bark	Apical Dieback
SW 19TH RD	Weeping Fig	31-40"	No	20'		Poor (21% to 40%)	Topped	Reduced Canopy - Moderate	Crown Density - Excessive (Due to Epicormic Growth)
SW 19TH RD	Black Olive	21-30"	No	20'		Poor (21% to 40%)	Galls	Topped	Reduced Canopy - Moderate
SW 19TH RD	Christmas Palm	11-15"	No	15'		Good (61% to 80%)			
SW 19TH RD	Christmas Palm	11-15"	No	15'		Good (61% to 80%)			
SW 19TH RD	Christmas Palm	16-20"	No	20'		Good (61% to 80%)			
SW 19TH RD	Christmas Palm	16-20"	No	20'		Good (61% to 80%)			
SW 19TH RD	Christmas Palm	16-20"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 19TH RD	Christmas Palm	11-15"	No	15'		Good (61% to 80%)			
SW 19TH RD	Black Olive	21-30"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 19TH RD	Black Olive	31-40"	No	55'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 19TH RD	Mahogany	16-20"	Yes	15'		Fair (41% to 60%)	Discolored Foliage	Grafted Branches	Epicormic Growth
SW 19TH RD	Christmas Palm	1-5"	Yes	5'		Poor (21% to 40%)	Nutrient Deficiency	Frizzled Fronds	Reduced Canopy - Moderate
SW 19TH RD	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency	Trunk Damage - Minor	
SW 19TH RD	Black Olive	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 19TH RD	Christmas Palm	11-15"	Yes	10'		Fair (41% to 60%)	Dead Meristem	Suppressed Canopy	One Dead Trunk
SW 19TH RD	Live Oak	41-50"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Utility Pruned
SW 19TH RD	Solitaire Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 19TH RD	Solitaire Palm	6-10"	Yes	10'	Utility Line Conflict	Good (61% to 80%)			
SW 19TH RD	Weeping Fig	6-10"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Grafted Branches
SW 19TH RD	Weeping Fig	6-10"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Dead Wood	Pruned Into Shrub	Grafted Branches
SW 19TH RD	Weeping Fig	11-15"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Dead Wood	Pruned Into Shrub	Grafted Branches
SW 19TH RD	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 19TH RD	Mahogany	11-15"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 19TH RD	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 19TH RD	Mahogany	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 19TH RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 19TH RD	Coconut Palm	6-10"	No	25'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 19TH RD	Mahogany	6-10"	No	30'		Fair (41% to 60%)	Root Damage/Decay	Codominant Leaders/No Included Bark	Epicormic Growth
SW 19TH RD	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 19TH RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 19th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH RD	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 19TH RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 19TH RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 19TH RD	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 19TH RD	Royal Poinciana	16-20"	No	50'		Poor (21% to 40%)	Constricted Roots	Galls	Stubs with Sprouts
SW 19TH RD	Mahogany	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 19TH RD	Mahogany	21-30"	No	55'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Adjacent Asphalt Damage	Basal Co-Dominant	Stubs with Sprouts
SW 19TH RD	Royal Poinciana	16-20"	No	30'		Poor (21% to 40%)	Adjacent Asphalt Damage	Limb Damage - Major	Dead Wood
SW 19TH RD	Royal Poinciana	6-10"	No	25'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Grafted Branches
SW 19TH RD	Royal Poinciana	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 19TH RD	Mahogany	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 19TH RD	Mahogany	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 19TH RD	Royal Poinciana	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Broken Branches
SW 19TH RD	Sacred Fig	51-60"	No	60'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Cavities	Stubs with Sprouts
SW 19TH RD	Live Oak	16-20"	Yes	20'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 19TH RD	Brazilian Beauty Leaf	16-20"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 19TH RD	Brazilian Beauty Leaf	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 19TH RD	Brazilian Beauty Leaf	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 19TH RD	Pygmy Date Palm	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 19TH RD	Pygmy Date Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 19TH RD	Black Olive	16-20"	No	45'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Utility Pruned	Stubs with Sprouts
SW 19TH RD	Black Olive	16-20"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 19TH RD	Royal Poinciana	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Crown Density - Very Low	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 19TH RD	Sacred Fig	60+"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 19TH RD	Sacred Fig	60+"	Yes	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 19TH RD	Orange Geiger	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Leader - Broken	Stubs with Sprouts
SW 19TH RD	Royal Poinciana	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 19TH RD	Sacred Fig	60+"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Stubs with Sprouts	Broken Branches
SW 19TH RD	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 19TH RD	Hong Kong Orchid	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Sprouting
SW 19TH RD	Live Oak	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 19TH RD	Norfolk Pine	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 19TH RD	Norfolk Pine	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 19TH RD	Dracaena sp.	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 19TH RD	Dracaena sp.	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Grafted Branches		
SW 19TH RD	Cocoplum	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Stubs with Sprouts	Grafted Branches
SW 19TH RD	Pigeon Plum	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	Broken Branches
SW 19TH RD	Gumbo Limbo	16-20"	No	5'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant with Adjacent Tree(s)	Topped	Stubs with Sprouts
SW 19TH RD	Black Olive	16-20"	No	5'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant with Adjacent Tree(s)	Topped	Stubs with Sprouts
SW 19TH RD	Sacred Fig	31-40"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Utility Pruned	Stubs with Sprouts
SW 19TH RD	Pink Tabebuia	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Insect Damage Leaves	Codominant Leaders/No Included Bark
SW 19TH RD	Pink Tabebuia	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Insect Damage Leaves	Codominant Leaders/No Included Bark
SW 19TH RD	Pink Tabebuia	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Improperly Mulched	Epicormic Growth	Codominant Leaders/No Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 19th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 19TH RD	Royal Poinciana	11-15"	No	35'	Utility Line Conflict	Dead (0% to 5%)	Dead Wood	Crown Density - Very Low	Sloughing Bark
SW 19TH RD	Oriental Arborvitae	6-10"	No	15'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Dead Wood
SW 19TH RD	Weeping Fig	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 19TH RD	Royal Poinciana	6-10"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 19TH RD	Royal Poinciana	21-30"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Stubs with Sprouts
SW 19TH RD	Pygmy Date Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 19TH RD	Laurel Oak	21-30"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Ficus Growing on Tree
SW 19TH RD	Banyan	51-60"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 19TH RD	Laurel Oak	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Suppressed Canopy	Restricted Canopy
SW 19TH RD	Laurel Oak	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Suppressed Canopy	Restricted Canopy
SW 19TH RD	Laurel Oak	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Suppressed Canopy	Restricted Canopy
SW 19TH RD	Montgomery Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 19TH RD	Montgomery Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 19TH RD	Montgomery Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Nutrient Deficiency	Trunk Damage - Moderate	
SW 19TH RD	Screw Pine	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 19TH RD	Yellow Tabebuia	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Topped	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 19TH RD	Starburst Clerodendron	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Pruned Into Shrub
SW 19TH RD	Starburst Clerodendron	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Pruned Into Shrub
SW 19TH RD	Starburst Clerodendron	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/Included Bark	Sprouting	Pruned Into Shrub
SW 19TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 19TH RD	Christmas Palm	6-10"	No	10'		Fair (41% to 60%)	Nutrient Deficiency	Tapered Trunk	
SW 19TH RD	Royal Poinciana	21-30"	No	50'		Poor (21% to 40%)	Leader - Broken	Decay Observed	Apical Dieback
SW 19TH RD	Royal Poinciana	21-30"	No	60'		Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Stubs with Sprouts
SW 19TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 19TH RD	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 19TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Trunk Damage - Minor		
SW 19TH RD	Bismark Palm	21-30"	No	20'		Good (61% to 80%)			
SW 19TH RD	Bismark Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 19TH RD	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Plunged	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 19TH RD	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark

SW 20th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH RD	Black Olive	6-10"	No	20'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark
SW 20TH RD	Gumbo Limbo	11-15"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Reduced Canopy - Moderate	Stubs with Sprouts	Grafted Branches
SW 20TH RD	Royal Poinciana	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 20TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 20TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 20TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 20TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Adjacent Light Pole	Nutrient Deficiency	
SW 20TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 20TH RD	Queen Palm	11-15"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 20TH RD	Queen Palm	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 20th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH RD	Gumbo Limbo	21-30"	No	30'		Fair (41% to 60%)	Constricted Roots	Cavities	Stubs with Sprouts
SW 20TH RD	Peregrina	16-20"	Yes	15'		Good (61% to 80%)	Grafted Branches	Epicormic Growth	Pruned Into Shrub
SW 20TH RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)		
SW 20TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 20TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 20TH RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 20TH RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 20TH RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 20TH RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 20TH RD	Java Bishopwood	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Stubs with Sprouts
SW 20TH RD	Java Bishopwood	31-40"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 20TH RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 20TH RD	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 20TH RD	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 20TH RD	Royal Poinciana	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Limb Damage - Major
SW 20TH RD	Crepe Myrtle	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 20TH RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 20TH RD	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 20TH RD	Canary Island Date Palm	21-30"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 20TH RD	Yellow Tabebuia	16-20"	No	35'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Utility Pruned	Stubs with Sprouts
SW 20TH RD	Crepe Myrtle	16-20"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Cracks in Trunk	Grafted Branches	Seasonal Defoliation/Discolored Foliage
SW 20TH RD	Crepe Myrtle	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Crown Density - Very Low	Grafted Branches	Seasonal Defoliation/Discolored Foliage
SW 20TH RD	Jacaranda	16-20"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 20TH RD	Weeping Fig	21-30"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Major	Decay Observed
SW 20TH RD	Royal Poinciana	16-20"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Trunk Damage - Moderate	Broken Branches	Stubs with Sprouts
SW 20TH RD	Tropical Almond	16-20"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Seasonal Defoliation/Discolored Foliage	Dead Wood
SW 20TH RD	Mahogany	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Adjacent Asphalt Damage	Limb Damage - Moderate
SW 20TH RD	Norfolk Pine	11-15"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Trunk Damage - Minor	
SW 20TH RD	Weeping Fig	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Pruned Into Shrub
SW 20TH RD	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)			
SW 20TH RD	Live Oak	6-10"	No	15'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Broken Branches
SW 20TH RD	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)	Ficus Growing on Tree		
SW 20TH RD	Cabbage Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 20TH RD	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)			
SW 20TH RD	Live Oak	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 20TH RD	Live Oak	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 20TH RD	Live Oak	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 20TH RD	Gumbo Limbo	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 20TH RD	Cabbage Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Ficus Growing on Tree	Nutrient Deficiency	Restricted Canopy
SW 20TH RD	Royal Poinciana	16-20"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 20TH RD	Live Oak	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Crown Density - Excessive (Due to Epicormic Growth)
SW 20TH RD	Live Oak	6-10"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Plunged	Restricted Canopy	Crown Density - Excessive (Due to Epicormic Growth)

(Continued on Next Page)

Street Tree Inventory

SW 20th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH RD	Live Oak	31-40"	No	65'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 20TH RD	Christmas Palm	16-20"	Yes	20'	Utility Line Conflict	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 20TH RD	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Tapered Trunk
SW 20TH RD	Christmas Palm	6-10"	No	Negligible	Utility Lines Adjacent (laterally)	Dead (0% to 5%)	Trunk Damage - Moderate	Dead Meristem	
SW 20TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 20TH RD	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 20TH RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 20TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 20TH RD	West Indian Ficus	31-40"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	Cavities
SW 20TH RD	Live Oak	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 20TH RD	Christmas Palm	16-20"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 20TH RD	Christmas Palm	16-20"	Yes	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 20TH RD	Canary Island Date Palm	16-20"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Over Pruned		
SW 20TH RD	Canary Island Date Palm	21-30"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Over Pruned		
SW 20TH RD	Christmas Palm	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 20TH RD	Rainbow Eucalyptus	1-5"	No	5'		Good (61% to 80%)	Improperly Mulched		
SW 20TH RD	West Indian Ficus	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Cavities	Stubs with Sprouts
SW 20TH RD	Cabbage Palm	11-15"	No	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	White Fly
SW 20TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 20TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 20TH RD	Royal Poinciana	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 20TH RD	West Indian Ficus	31-40"	No	35'	Utility Lines Above	Poor (21% to 40%)	Vine Cover - Heavy	Topped	Discolored Foliage
SW 20TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Vine Cover - Heavy	Restricted Canopy	Leaning - Moderate
SW 20TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Vine Cover - Heavy	Restricted Canopy	Leaning - Moderate
SW 20TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Vine Cover - Heavy	Restricted Canopy	Leaning - Moderate
SW 20TH RD	Brazilian Pepper	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Vine Cover - Heavy	Restricted Canopy	Leaning - Moderate
SW 20TH RD	Gumbo Limbo	6-10"	No	15'	Utility Lines Above	Fair (41% to 60%)	Vine Cover - Heavy	Lifting	Restricted Canopy
SW 20TH RD	Banyan	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Vine Cover - Heavy	Suppressed Canopy	Restricted Canopy
SW 20TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Vine Cover - Heavy	Suppressed Canopy	Restricted Canopy
SW 20TH RD	Weeping Fig	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	Epicormic Growth
SW 20TH RD	West Indian Ficus	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Decay Observed	Apical Dieback	Discolored Foliage
SW 20TH RD	West Indian Ficus	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Decay Observed	Limb Damage - Moderate	Stubs with Sprouts
SW 20TH RD	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 20TH RD	Weeping Fig	6-10"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Epicormic Growth
SW 20TH RD	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Plunged	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 20TH RD	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Plunged	Epicormic Growth	Codominant Leaders/No Included Bark
SW 20TH RD	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Plunged	Crown Density - Low	Epicormic Growth
SW 20TH RD	Live Oak	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 20TH RD	Live Oak	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory


SW 20th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 20TH RD	Live Oak	11-15"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback
SW 20TH RD	Live Oak	11-15"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood
SW 20TH RD	Gumbo Limbo	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 20TH RD	Gumbo Limbo	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	Epicormic Growth
SW 20TH RD	Mahogany	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Epicormic Growth
SW 20TH RD	Mahogany	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 20TH RD	Coconut Palm	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)			
SW 20TH RD	Dracaena sp.	21-30"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 20TH RD	Dracaena sp.	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 20TH RD	Live Oak	16-20"	No	30'	Utility Lines Above	Fair (41% to 60%)	Crown Density - Excessive (Due to Epicormic Growth)	Pruned Into Shrub	Codominant Leaders/No Included Bark
SW 20TH RD	Mahogany	41-50"	No	75'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 20TH RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 20TH RD	Black Olive	21-30"	No	50'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 20TH RD	Black Olive	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 20TH RD	Black Olive	16-20"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 20TH RD	Coconut Palm	16-20"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 20TH RD	Royal Poinciana	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 20TH RD	Royal Poinciana	6-10"	No	30'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Grafted Branches
SW 20TH RD	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)			
SW 20TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency	Damaged Fronds	
SW 20TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 20TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 20TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 20TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 20TH RD	Weeping Fig	6-10"	Yes	10'		Fair (41% to 60%)	Girdling Roots	Pruned Into Shrub	Restricted Canopy
SW 20TH RD	Weeping Fig	6-10"	Yes	10'		Good (61% to 80%)	Epicormic Growth	Pruned Into Shrub	Restricted Canopy
SW 20TH RD	Weeping Fig	11-15"	Yes	10'		Good (61% to 80%)	Epicormic Growth	Pruned Into Shrub	Restricted Canopy
SW 20TH RD	Weeping Fig	11-15"	Yes	10'		Good (61% to 80%)	Epicormic Growth	Pruned Into Shrub	Restricted Canopy
SW 20TH RD	Weeping Fig	6-10"	Yes	10'		Good (61% to 80%)	Epicormic Growth	Pruned Into Shrub	Restricted Canopy
SW 20TH RD	Royal Poinciana	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Cavities
SW 20TH RD	Japanese Fern Tree	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 20TH RD	Japanese Fern Tree	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 20TH RD	Live Oak	21-30"	No	45'		Fair (41% to 60%)	Girdling Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 20TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 20TH RD	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 20TH RD	Royal Poinciana	1-5"	No	5'		Fair (41% to 60%)	Crown Density - Low	Suppressed Canopy	
SW 20TH RD	Royal Poinciana	6-10"	No	20'		Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Restricted Canopy
SW 20TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 20TH RD	Royal Poinciana	1-5"	No	5'		Fair (41% to 60%)	Topped	Stubs with Sprouts	
SW 20TH RD	Royal Poinciana	6-10"	No	30'		Fair (41% to 60%)	Limb Damage - Moderate	Broken Branches	Dead Wood
SW 20TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 20TH RD	Weeping Fig	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 20TH RD	Norfolk Pine	6-10"	Yes	10'		Good (61% to 80%)			

Roads




Looking Northwest - SW 3rd Avenue



Looking Northwest - SW 5th Avenue




Looking Northwest - SW 1st Avenue



Looking Northwest - SW 4th Avenue



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 11th Street



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 11th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 21st Road	1	Roads	3	70	3250	No	No	Yes	2	City	Yes	Some	9	NW of 3rd Avenue	Yes	South of 7th Ave mostly on NE	Paved swale for parking on SW corner of 3rd Avenue intersection. Freshly paved road between 4th and 5th Avenue, with striped lines for on street parking. Vegetated curb extension on NW end.
SW 22nd Road	1	Roads	3	70	3480	No	No	Yes	2	City	Yes	Some	9	NW of 3rd Avenue	Yes	South of 7th Ave mostly on NE	Parking on swale SW corner of 3rd Avenue. Round-about at 5th Avenue

SW 21st Road
TYPOLOGY B and A

SW 22nd Road
TYPOLOGY B and A

Street Tree Inventory

SW 21st Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST RD	Pitch Apple	60+"	No	35'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Vine Cover - Heavy
SW 21ST RD	Pitch Apple	60+"	No	35'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Vine Cover - Heavy
SW 21ST RD	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)			
SW 21ST RD	Royal Palm	16-20"	No	Negligible		Dead (0% to 5%)	Dead Meristem		
SW 21ST RD	Umbrella Tree	16-20"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 21ST RD	Laurel Oak	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 21ST RD	Laurel Oak	6-10"	No	10'		Good (61% to 80%)	Codominant Leaders/Included Bark	Grafted Branches	
SW 21ST RD	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 21ST RD	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)	Ficus Growing on Tree		
SW 21ST RD	Royal Poinciana	16-20"	No	45'		Good (61% to 80%)	Broken Branches	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 21ST RD	Oriental Arborvitae	41-50"	Yes	25'		Good (61% to 80%)	Dead Wood	Stubs	
SW 21ST RD	Weeping Fig	11-15"	No	15'		Fair (41% to 60%)	Basal Co-Dominant	Dead Wood	Epicormic Growth
SW 21ST RD	Royal Poinciana	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 21ST RD	Tropical Almond	6-10"	No	30'		Fair (41% to 60%)	Constricted Roots	Seasonal Defoliation/Discolored Foliage	Epicormic Growth
SW 21ST RD	Tropical Almond	11-15"	No	45'		Fair (41% to 60%)	Constricted Roots	Grafted Branches	Seasonal Defoliation/Discolored Foliage
SW 21ST RD	Tropical Almond	6-10"	No	40'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Epicormic Growth	Codominant Leaders/No Included Bark
SW 21ST RD	Green Buttonwood	11-15"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Epicormic Growth
SW 21ST RD	Green Buttonwood	16-20"	Yes	20'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Restricted Canopy
SW 21ST RD	Green Buttonwood	11-15"	No	20'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 21ST RD	Gumbo Limbo	11-15"	No	20'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Grafted Branches
SW 21ST RD	Bougainvillea sp.	11-15"	Yes	10'		Good (61% to 80%)	Grafted Branches	Epicormic Growth	Pruned Into Shrub
SW 21ST RD	Gumbo Limbo	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/Included Bark	Stubs with Sprouts	Grafted Branches
SW 21ST RD	Sapodilla	21-30"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Stubs
SW 21ST RD	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Codominant Leaders/Included Bark
SW 21ST RD	Live Oak	16-20"	No	40'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Utility Pruned
SW 21ST RD	Live Oak	16-20"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback
SW 21ST RD	Live Oak	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Topped
SW 21ST RD	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Over Pruned		
SW 21ST RD	Mahogany	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 21ST RD	Mahogany	16-20"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Dead Wood
SW 21ST RD	Mahogany	16-20"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 21ST RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 21ST RD	Small Leaf Clusia	16-20"	Yes	20'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Pruned Into Shrub	
SW 21ST RD	Rubber Tree	21-30"	Yes	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 21ST RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Codominant Leaders/Included Bark
SW 21ST RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Codominant Leaders/Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 21st Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST RD	Mahogany	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Codominant Leaders/No Included Bark
SW 21ST RD	Mahogany	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant with Adjacent Tree(s)	Basal Co-Dominant	Restricted Canopy
SW 21ST RD	Black Olive	21-30"	No	60'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 21ST RD	Gumbo Limbo	6-10"	No	25'		Poor (21% to 40%)	Girdling Roots	Lifting	Codominant Leaders/No Included Bark
SW 21ST RD	Black Olive	16-20"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 21ST RD	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 21ST RD	Glaucous Cassia	11-15"	Yes	20'	Utility Lines Above	Poor (21% to 40%)	Decay Observed	Sloughing Bark	Epicormic Growth
SW 21ST RD	Florida Thatch Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 21ST RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 21ST RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 21ST RD	Live Oak	11-15"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Lopsided/Moderately Reduced Canopy
SW 21ST RD	Live Oak	6-10"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 21ST RD	Black Olive	11-15"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 21ST RD	Velvet Apple	21-30"	Yes	25'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Sprouting	Broken Branches	
SW 21ST RD	Royal Palm	51-60"	Yes	40'		Good (61% to 80%)	Restricted Canopy	Ficus Growing on Tree	
SW 21ST RD	Mahogany	6-10"	No	25'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 21ST RD	Coconut Palm	11-15"	No	25'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 21ST RD	Coconut Palm	11-15"	No	25'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 21ST RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 21ST RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 21ST RD	Sapodilla	31-40"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 21ST RD	Live Oak	6-10"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Crown Density - Low	Apical Dieback
SW 21ST RD	Live Oak	31-40"	No	65'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Limb Damage - Minor
SW 21ST RD	Weeping Fig	41-50"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 21ST RD	Pink Tabebuia	6-10"	No	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Restricted Canopy
SW 21ST RD	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 21ST RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 21ST RD	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency	Damaged Fronds	
SW 21ST RD	Yellow Elder	16-20"	Yes	20'	Utility Lines Above	Fair (41% to 60%)	Crown Density - Low	Stubs with Sprouts	Broken Branches
SW 21ST RD	Crepe Myrtle	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Sprouting	Restricted Canopy
SW 21ST RD	Royal Palm	11-15"	No	5'	Utility Lines Above	Very Poor/Critical (6% to 20%)	Reduced Canopy - Major	Nutrient Deficiency	Frizzled Fronds
SW 21ST RD	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Trunk Damage - Moderate	Nutrient Deficiency	
SW 21ST RD	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 21ST RD	Queen Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 21ST RD	Weeping Fig	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Girdling Roots	Pruned Into Shrub	Codominant Leaders/No Included Bark
SW 21ST RD	White Frangipani	6-10"	Yes	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Sprouting	
SW 21ST RD	Weeping Fig	41-50"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 21st Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 21ST RD	Christmas Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 21ST RD	Queen Palm	1-5"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 21ST RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 21ST RD	Japanese Fern Tree	6-10"	No	15'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Limb Damage - Moderate
SW 21ST RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 21ST RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 21ST RD	Gumbo Limbo	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Discolored Foliage	Codominant Leaders/No Included Bark	Grafted Branches
SW 21ST RD	Gumbo Limbo	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Stubs with Sprouts	Codominant Leaders/No Included Bark	Broken Branches
SW 21ST RD	Gumbo Limbo	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Discolored Foliage	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 21ST RD	Coconut Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 21ST RD	Coconut Palm	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned		
SW 21ST RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 21ST RD	Bridalveil Tree	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 21ST RD	Bridalveil Tree	6-10"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Plunged	Apical Dieback
SW 21ST RD	Black Olive	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood
SW 21ST RD	Mahogany	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Leader - Broken	Lopsided/Significantly Reduced Canopy
SW 21ST RD	Weeping Fig	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Adjacent Asphalt Damage	Decay Observed	Stubs with Sprouts
SW 21ST RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 21ST RD	Black Olive	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 21ST RD	Mahogany	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 21ST RD	Mahogany	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 21ST RD	Mahogany	41-50"	No	65'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 21ST RD	Mahogany	31-40"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 21ST RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned		
SW 21ST RD	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Over Pruned		
SW 21ST RD	Black Olive	31-40"	No	60'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Dead Wood

SW 22nd Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 22ND RD	Bismark Palm	16-20"	No	25'		Good (61% to 80%)			
SW 22ND RD	Royal Poinciana	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 22ND RD	Vera Wood	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Strap Constricting Tree
SW 22ND RD	Vera Wood	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 22ND RD	Vera Wood	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 22ND RD	Montgomery Palm	6-10"	No	15'		Good (61% to 80%)			
SW 22ND RD	Montgomery Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Live Oak	11-15"	No	30'		Poor (21% to 40%)	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark	Apical Dieback
SW 22ND RD	Live Oak	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Apical Dieback
SW 22ND RD	Live Oak	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Apical Dieback
SW 22ND RD	Live Oak	16-20"	No	40'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Codominant Leaders/No Included Bark
SW 22ND RD	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Coconut Palm	11-15"	No	20'		Poor (21% to 40%)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 22nd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND RD	Coconut Palm	11-15"	No	15'		Poor (21% to 40%)	Nutrient Deficiency	Over Pruned	Damaged Fronds
SW 22ND RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 22ND RD	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 22ND RD	Weeping Fig	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Pruned Into Shrub
SW 22ND RD	Weeping Fig	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Trunk Damage - Minor	Pruned Into Shrub
SW 22ND RD	Royal Palm	16-20"	No	25'		Good (61% to 80%)			
SW 22ND RD	Yucca sp.	1-5"	No	5'		Good (61% to 80%)			
SW 22ND RD	Yucca sp.	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 22ND RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)			
SW 22ND RD	Queen Palm	6-10"	No	15'		Good (61% to 80%)			
SW 22ND RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 22ND RD	Canary Island Date Palm	11-15"	No	10'		Good (61% to 80%)			
SW 22ND RD	Royal Palm	11-15"	No	20'		Good (61% to 80%)			
SW 22ND RD	Canary Island Date Palm	11-15"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Canary Island Date Palm	11-15"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 22ND RD	Washington Palm	16-20"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 22ND RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 22ND RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 22ND RD	Pygmy Date Palm	6-10"	Yes	10'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 22ND RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 22ND RD	Pygmy Date Palm	6-10"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Canary Island Date Palm	21-30"	No	15'		Good (61% to 80%)			
SW 22ND RD	Pygmy Date Palm	6-10"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Canary Island Date Palm	21-30"	No	15'		Good (61% to 80%)			
SW 22ND RD	Date Palm	21-30"	No	25'		Good (61% to 80%)			
SW 22ND RD	Christmas Palm	16-20"	Yes	20'		Good (61% to 80%)			
SW 22ND RD	Yellow Tabebuia	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 22ND RD	Black Olive	31-40"	No	55'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 22ND RD	Black Olive	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 22ND RD	Mango	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 22ND RD	Jacaranda	6-10"	No	10'		Poor (21% to 40%)	Basal Co-Dominant	Dead Wood	Discolored Foliage
SW 22ND RD	Black Olive	31-40"	No	60'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 22ND RD	Black Olive	31-40"	No	55'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 22ND RD	Mahogany	11-15"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 22ND RD	Mahogany	11-15"	No	30'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts	Broken Branches
SW 22ND RD	Sacred Fig	31-40"	No	60'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Lopsided/Moderately Reduced Canopy
SW 22ND RD	Black Olive	31-40"	No	60'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 22ND RD	Black Olive	21-30"	No	55'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 22ND RD	Christmas Palm	21-30"	Yes	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 22ND RD	Dracaena sp.	11-15"	Yes	20'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 22ND RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 22ND RD	Shaving Brush Tree	21-30"	No	25'		Poor (21% to 40%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 22ND RD	Solitaire Palm	11-15"	Yes	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 22ND RD	Christmas Palm	6-10"	Yes	15'		Good (61% to 80%)			
SW 22ND RD	Black Olive	21-30"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 22ND RD	Montgomery Palm	21-30"	Yes	25'		Good (61% to 80%)			
SW 22ND RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Norfolk Pine	16-20"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Sprouting		

(Continued on Next Page)

Street Tree Inventory

SW 22nd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND RD	Pygmy Date Palm	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 22ND RD	Pygmy Date Palm	16-20"	Yes	15'		Good (61% to 80%)			
SW 22ND RD	Pygmy Date Palm	1-5"	No	5'		Poor (21% to 40%)	Nutrient Deficiency	Frizzled Fronds	
SW 22ND RD	Pygmy Date Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 22ND RD	Pygmy Date Palm	1-5"	No	10'		Good (61% to 80%)			
SW 22ND RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 22ND RD	Live Oak	31-40"	No	60'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood
SW 22ND RD	Weeping Fig	31-40"	No	50'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 22ND RD	Mahogany	16-20"	No	30'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Sloughing Bark	Epicormic Growth
SW 22ND RD	Live Oak	6-10"	No	30'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Codominant Leaders/No Included Bark
SW 22ND RD	Black Olive	21-30"	No	60'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 22ND RD	Black Olive	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Stubs with Sprouts	Limb Damage - Moderate
SW 22ND RD	Mahogany	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Lopsided/Moderately Reduced Canopy
SW 22ND RD	Weeping Fig	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Grafted with Adjacent Tree
SW 22ND RD	Weeping Fig	16-20"	No	35'		Fair (41% to 60%)	Decay Observed	Epicormic Growth	Grafted with Adjacent Tree
SW 22ND RD	Weeping Fig	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 22ND RD	Mahogany	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Epicormic Growth	Utility Pruned
SW 22ND RD	Gumbo Limbo	21-30"	No	25'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Sprouting
SW 22ND RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Restricted Canopy	Suppressed Canopy
SW 22ND RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Broken Branches
SW 22ND RD	Umbrella Tree	6-10"	Yes	15'		Good (61% to 80%)	Grafted Branches	Restricted Canopy	Ficus Growing on Tree
SW 22ND RD	Mahogany	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Utility Pruned
SW 22ND RD	Areca Palm	41-50"	Yes	25'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 22ND RD	Sapodilla	21-30"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 22ND RD	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 22ND RD	Orange Jasmine	11-15"	Yes	10'		Good (61% to 80%)	Grafted Branches	Sprouting	
SW 22ND RD	Orange Jasmine	11-15"	Yes	10'		Good (61% to 80%)	Grafted Branches	Sprouting	
SW 22ND RD	Orange Jasmine	16-20"	Yes	10'		Good (61% to 80%)	Grafted Branches	Sprouting	
SW 22ND RD	Royal Poinciana	16-20"	No	55'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 22ND RD	Pygmy Date Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Pygmy Date Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 22ND RD	Royal Poinciana	31-40"	Yes	75'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 22ND RD	Royal Poinciana	31-40"	No	60'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Decay Observed
SW 22ND RD	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Codominant Leaders/No Included Bark	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 22ND RD	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Codominant Leaders/No Included Bark	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 22ND RD	Live Oak	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 22ND RD	Christmas Palm	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 22ND RD	Royal Poinciana	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Lopsided/Moderately Reduced Canopy
SW 22ND RD	Royal Poinciana	21-30"	No	60'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 22ND RD	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 22ND RD	Gumbo Limbo	11-15"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Cracks in Trunk	Stubs with Sprouts
SW 22ND RD	Royal Poinciana	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Stubs with Sprouts
SW 22ND RD	Sapodilla	31-40"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 22ND RD	Royal Poinciana	31-40"	Yes	65'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 22nd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND RD	Southern Magnolia	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Crown Density - Low	Sprouting	Broken Branches
SW 22ND RD	Southern Magnolia	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant	Sprouting	
SW 22ND RD	Royal Poinciana	16-20"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Ficus Growing on Tree
SW 22ND RD	Christmas Palm	6-10"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 22ND RD	Christmas Palm	6-10"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 22ND RD	Weeping Fig	11-15"	No	20'		Good (61% to 80%)	Pruned Into Shrub		
SW 22ND RD	Black Olive	21-30"	No	45'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 22ND RD	Black Olive	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 22ND RD	Black Olive	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 22ND RD	Sapodilla	31-40"	No	45'	Utility Line Conflict	Good (61% to 80%)	Utility Pruned	Broken Branches	Sprouting
SW 22ND RD	Crepe Myrtle	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Grafted Branches	Dead Wood
SW 22ND RD	Mahogany	21-30"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Utility Pruned	Epicormic Growth
SW 22ND RD	Gumbo Limbo	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 22ND RD	Queen Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 22ND RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 22ND RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 22ND RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 22ND RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Spindle Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Spindle Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 22ND RD	Spindle Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 22ND RD	Spindle Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Bottlebrush	16-20"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Trunk Damage - Minor
SW 22ND RD	Christmas Palm	16-20"	Yes	20'	Utility Line Conflict	Good (61% to 80%)			
SW 22ND RD	Christmas Palm	11-15"	Yes	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 22ND RD	Black Olive	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 22ND RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 22ND RD	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 22ND RD	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 22ND RD	Black Olive	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Root Damage/Decay	Utility Pruned	Stubs with Sprouts
SW 22ND RD	Black Olive	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 22ND RD	Black Olive	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 22ND RD	Black Olive	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Topped	Lateral Branching - None	Epicormic Growth
SW 22ND RD	Mahogany	21-30"	No	40'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Constricted Roots	Decay Observed	Lopsided/Significantly Reduced Canopy
SW 22ND RD	Mahogany	11-15"	No	20'	Utility Lines Above	Poor (21% to 40%)	Apical Dieback	Epicormic Growth	Lopsided/Significantly Reduced Canopy
SW 22ND RD	Mahogany	31-40"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Limb Damage - Moderate
SW 22ND RD	Mahogany	21-30"	No	50'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 22ND RD	Mahogany	21-30"	No	65'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 22ND RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 22ND RD	Willow Bustic	31-40"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 22ND RD	Orange Geiger	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Leader - Broken	Stubs with Sprouts
SW 22ND RD	Orange Geiger	1-5"	Yes	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Leader - Broken	Dead Wood
SW 22ND RD	Pigeon Plum	11-15"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Dead Wood
SW 22ND RD	Pink Tabebuia	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Topped	Stubs with Sprouts
SW 22ND RD	Crepe Myrtle	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Stubs
SW 22ND RD	Crepe Myrtle	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Sprouting

(Continued on Next Page)

Street Tree Inventory

SW 22nd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND RD	Solitaire Palm	1-5"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 22ND RD	Solitaire Palm	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 22ND RD	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 22ND RD	Christmas Palm	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Live Oak	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 22ND RD	Mango	11-15"	No	20'	Utility Lines Above	Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 22ND RD	Black Olive	31-40"	No	55'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Epicormic Growth
SW 22ND RD	Orange Geiger	6-10"	No	15'	Utility Lines Above	Fair (41% to 60%)	Plunged	Pruned Into Shrub	Stubs with Sprouts
SW 22ND RD	Black Olive	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Lopsided/Moderately Reduced Canopy
SW 22ND RD	Canary Island Date Palm	21-30"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 22ND RD	Canary Island Date Palm	21-30"	No	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Foxtail Palm	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 22ND RD	Florida Thatch Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND RD	Sapodilla	16-20"	No	35'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 22ND RD	Live Oak	6-10"	No	25'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 22ND RD	Live Oak	11-15"	No	20'		Poor (21% to 40%)	Girdling Roots	Crown Density - Excessive (Due to Epicormic Growth)	Topped
SW 22ND RD	Coconut Palm	6-10"	Yes	10'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 22ND RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)			
SW 22ND RD	Live Oak	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 22ND RD	Live Oak	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Plunged	Epicormic Growth
SW 22ND RD	Live Oak	16-20"	No	40'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 22ND RD	Live Oak	16-20"	No	45'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth

Roads



Looking Northwest - SW 1st Avenue



Looking Northwest - SW 4th Avenue



Looking Northwest - SW 1st Avenue



Looking Northwest - SW 4th Avenue



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 11th Street



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 12th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 23rd Road	1	Roads	3	75	3750	SE of 5th Ave	No	Yes	2	City	Yes	Yes	7	Yes	Yes	South of 5th Ave mostly on NE	Canopy on median provides dense tree canopy. Sparse tree canopy between 5th and 7th avenue. Roundabout at 7th Avenue.
SW 24th Road	1	Roads	3	75	3750	SE of 5th Ave	No	Yes	2	City	Yes	Some	7	Yes	Yes	South of 5th Ave mostly on NE	New tree plantings along median between 3rd and 4th Avenue. Roundabout at 9th Avenue. Road splits on NW end into 12th Street and 10th Avenue. Traffic island on NW end.

SW 23rd Road

TYPOLOGY F and B

SW 24th Road

TYPOLOGY F and B

Street Tree Inventory

SW 23rd Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD RD	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 23RD RD	Royal Palm	16-20"	No	Negligible		Dead (0% to 5%)	Dead Meristem		
SW 23RD RD	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)			
SW 23RD RD	Umbrella Tree	21-30"	Yes	20'		Good (61% to 80%)	Stubs with Sprouts	Broken Branches	
SW 23RD RD	Silver Buttonwood	21-30"	Yes	20'		Fair (41% to 60%)	Stubs with Sprouts	Grafted Branches	Limb Damage - Moderate
SW 23RD RD	Royal Poinciana	21-30"	No	50'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Decay Observed
SW 23RD RD	Royal Poinciana	11-15"	No	40'		Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 23RD RD	Weeping Fig	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 23RD RD	Weeping Fig	31-40"	No	25'		Very Poor/Critical (6% to 20%)	Decay Observed	Dead Wood	Epicormic Growth
SW 23RD RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Suppressed Canopy		
SW 23RD RD	Mahogany	41-50"	No	55'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Broken Branches
SW 23RD RD	Christmas Palm	31-40"	Yes	25'		Good (61% to 80%)			
SW 23RD RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Suppressed Canopy	
SW 23RD RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 23RD RD	Yellow Poinciana	6-10"	Yes	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Restricted Canopy
SW 23RD RD	Yellow Poinciana	11-15"	No	35'		Fair (41% to 60%)	Crown Density - Low	Broken Branches	Decay Observed
SW 23RD RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 23RD RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 23RD RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 23RD RD	Christmas Palm	31-40"	Yes	20'		Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 23RD RD	Mango	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 23RD RD	Royal Palm	11-15"	No	25'	Strap Causing Decay and Taper	Fair (41% to 60%)	Tapered Trunk	Strap Constricting Tree	Decay Observed
SW 23RD RD	Royal Palm	11-15"	No	25'		Good (61% to 80%)	Restricted Canopy		
SW 23RD RD	Royal Poinciana	41-50"	No	35'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Vine Cover - Heavy
SW 23RD RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 23RD RD	Mahogany	31-40"	No	45'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 23RD RD	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Trunk Damage - Major	Epicormic Growth	Decay Observed
SW 23RD RD	Royal Palm	11-15"	No	20'		Poor (21% to 40%)	Nutrient Deficiency	Frizzled Fronds	Reduced Canopy - Moderate
SW 23RD RD	Crepe Myrtle	1-5"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Seasonal Defoliation/Discolored Foliage	Crown Density - Very Low
SW 23RD RD	White Frangipani	1-5"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Leaning - Minor	Sprouting
SW 23RD RD	Royal Poinciana	31-40"	No	55'		Poor (21% to 40%)	Basal Co-Dominant	Crown Density - Low	Epicormic Growth
SW 23RD RD	Royal Poinciana	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Crown Density - Very Low	Epicormic Growth
SW 23RD RD	Norfolk Pine	16-20"	No	15'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Sprouting
SW 23RD RD	Cashew	16-20"	No	40'		Fair (41% to 60%)	Girdling Roots	Restricted Canopy	Stubs with Sprouts
SW 23RD RD	Queen Palm	6-10"	No	5'		Very Poor/Critical (6% to 20%)	Nutrient Deficiency	Reduced Canopy - Major	Frizzled Fronds
SW 23RD RD	Royal Poinciana	11-15"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Dead Wood
SW 23RD RD	White Frangipani	1-5"	Yes	5'		Good (61% to 80%)			
SW 23RD RD	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Epicormic Growth
SW 23RD RD	Mahogany	21-30"	No	35'		Poor (21% to 40%)	Girdling Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 23RD RD	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lateral Branching - None	Stubs with Sprouts
SW 23RD RD	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 23RD RD	Royal Poinciana	21-30"	No	60'		Fair (41% to 60%)	Constricted Roots	Adjacent Asphalt Damage	Stubs with Sprouts
SW 23RD RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Codominant Leaders/No Included Bark	Restricted Canopy

(Continued on Next Page)

Street Tree Inventory

SW 23rd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)			
SW 23RD RD	Spindle Palm	11-15"	No	5'		Very Poor/Critical (6% to 20%)	Trunk Damage - Major	Reduced Canopy - Major	Nutrient Deficiency
SW 23RD RD	Spindle Palm	11-15"	No	10'		Poor (21% to 40%)	Nutrient Deficiency		
SW 23RD RD	Spindle Palm	11-15"	No	10'		Poor (21% to 40%)	Trunk Damage - Major	Cavities	Nutrient Deficiency
SW 23RD RD	Jacaranda	16-20"	No	35'		Fair (41% to 60%)	Basal Co-Dominant	Broken Branches	Stubs with Sprouts
SW 23RD RD	Royal Poinciana	21-30"	No	55'		Poor (21% to 40%)	Apical Dieback	Vine Cover - Heavy	Decay Observed
SW 23RD RD	Royal Poinciana	21-30"	No	60'		Poor (21% to 40%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 23RD RD	Royal Palm	11-15"	No	20'		Good (61% to 80%)			
SW 23RD RD	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Moderate	Damaged Fronds
SW 23RD RD	Royal Palm	11-15"	No	25'		Good (61% to 80%)			
SW 23RD RD	Royal Palm	16-20"	No	25'		Good (61% to 80%)			
SW 23RD RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Pygmy Date Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 23RD RD	Pygmy Date Palm	6-10"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Pygmy Date Palm	11-15"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Pygmy Date Palm	6-10"	Yes	15'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)			
SW 23RD RD	Orange Geiger	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Sprouting
SW 23RD RD	Orange Geiger	1-5"	No	10'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Leaning - Moderate
SW 23RD RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 23RD RD	Royal Palm	11-15"	No	5'		Very Poor/Critical (6% to 20%)	Nutrient Deficiency	Reduced Canopy - Major	Frizzled Fronds
SW 23RD RD	Royal Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 23RD RD	Royal Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 23RD RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD RD	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 23RD RD	Queen Palm	6-10"	No	20'		Good (61% to 80%)			
SW 23RD RD	Black Olive	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 23RD RD	Black Olive	11-15"	No	20'		Poor (21% to 40%)	Lateral Branching - None	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 23RD RD	Black Olive	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Topped
SW 23RD RD	Coconut Palm	6-10"	No	10'		Good (61% to 80%)			
SW 23RD RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Coconut Palm	6-10"	No	10'		Good (61% to 80%)			
SW 23RD RD	Spindle Palm	6-10"	No	5'		Good (61% to 80%)			
SW 23RD RD	Spindle Palm	11-15"	No	10'		Good (61% to 80%)			
SW 23RD RD	Spindle Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency	Damaged Fronds	
SW 23RD RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 23RD RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Coconut Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Insect Damage Leaves		
SW 23RD RD	Coconut Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 23RD RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Coconut Palm	1-5"	No	5'		Poor (21% to 40%)	Nutrient Deficiency		
SW 23RD RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)			
SW 23RD RD	Oriental Arborvitae	21-30"	Yes	20'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Epicormic Growth	Broken Branches
SW 23RD RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 23rd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD RD	Oriental Arborvitae	21-30"	Yes	20'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Epicormic Growth	Broken Branches
SW 23RD RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 23RD RD	Black Olive	31-40"	No	55'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Epicormic Growth
SW 23RD RD	Canary Island Date Palm	21-30"	No	25'		Good (61% to 80%)	Ficus Growing on Tree	Vine Cover - Heavy	
SW 23RD RD	Dracaena sp.	1-5"	No	5'		Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Grafted Branches
SW 23RD RD	Royal Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 23RD RD	Royal Poinciana	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 23RD RD	Royal Poinciana	6-10"	No	25'		Poor (21% to 40%)	Crown Density - Low	Trunk Damage - Major	Epicormic Growth
SW 23RD RD	Royal Poinciana	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 23RD RD	Bismark Palm	6-10"	No	10'		Good (61% to 80%)	Leader - Bent		
SW 23RD RD	Coconut Palm	6-10"	No	10'		Good (61% to 80%)			
SW 23RD RD	Bismark Palm	16-20"	No	20'		Good (61% to 80%)			
SW 23RD RD	Royal Poinciana	11-15"	No	40'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 23RD RD	Pongam	31-40"	No	55'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 23RD RD	Royal Poinciana	1-5"	No	5'		Good (61% to 80%)			
SW 23RD RD	Royal Poinciana	31-40"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Restricted Canopy
SW 23RD RD	Live Oak	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 23RD RD	Mahogany	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Grafted Branches
SW 23RD RD	Silk Floss Tree	6-10"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Adjacent Asphalt Damage
SW 23RD RD	Live Oak	11-15"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 23RD RD	Gumbo Limbo	16-20"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 23RD RD	Gumbo Limbo	16-20"	No	35'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 23RD RD	Areca Palm	6-10"	Yes	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 23RD RD	Live Oak	11-15"	No	25'		Poor (21% to 40%)	Girdling Roots	Plunged	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD RD	Gumbo Limbo	11-15"	No	20'		Poor (21% to 40%)	Girdling Roots	Crown Density - Low	Trunk Damage - Moderate
SW 23RD RD	Strangler Fig	21-30"	No	25'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 23RD RD	Ackee Tree	6-10"	No	20'		Fair (41% to 60%)	Insect Damage Leaves	Trunk Damage - Moderate	Suppressed Canopy
SW 23RD RD	Live Oak	11-15"	No	30'		Poor (21% to 40%)	Girdling Roots	Plunged	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD RD	Royal Poinciana	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 23RD RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 23RD RD	Arjun Tree	41-50"	No	65'	Utility Line Conflict	Good (61% to 80%)	Broken Branches	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 23RD RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	Suppressed Canopy
SW 23RD RD	Arjun Tree	21-30"	No	40'		Fair (41% to 60%)	Apical Dieback	Dead Wood	Epicormic Growth
SW 23RD RD	Arjun Tree	31-40"	No	55'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 23RD RD	Arjun Tree	21-30"	No	60'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 23RD RD	Vera Wood	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD RD	Arjun Tree	21-30"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 23RD RD	Arjun Tree	11-15"	No	40'	Utility Line Conflict	Good (61% to 80%)	Stubs with Sprouts	Broken Branches	Suppressed Canopy
SW 23RD RD	Arjun Tree	31-40"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 23RD RD	Arjun Tree	11-15"	No	30'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Apical Dieback
SW 23RD RD	Arjun Tree	31-40"	No	65'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 23RD RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 23RD RD	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)	Ficus Growing on Tree	Restricted Canopy	Suppressed Canopy

(Continued on Next Page)

Street Tree Inventory

SW 23rd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency	Damaged Fronds	
SW 23RD RD	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency	Insect Damage Leaves	
SW 23RD RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Arjun Tree	21-30"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Grafted Branches
SW 23RD RD	Arjun Tree	21-30"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 23RD RD	Banana Tree	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 23RD RD	Mahogany	31-40"	No	60'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 23RD RD	Mahogany	21-30"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Limb Damage - Moderate	Dead Wood
SW 23RD RD	Mahogany	31-40"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Limb Damage - Minor	Dead Wood
SW 23RD RD	Mahogany	41-50"	No	65'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Lopsided/Moderately Reduced Canopy
SW 23RD RD	Mahogany	6-10"	No	15'	Utility Lines Above	Very Poor/Critical (6% to 20%)	Plunged	Limb Damage - Moderate	Epicormic Growth
SW 23RD RD	Mahogany	31-40"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Limb Damage - Moderate	Epicormic Growth	Cavities
SW 23RD RD	Mahogany	6-10"	No	25'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 23RD RD	Mahogany	6-10"	No	20'		Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 23RD RD	Mahogany	41-50"	No	70'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 23RD RD	Mahogany	41-50"	No	65'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Dead Wood	Ficus Growing on Tree
SW 23RD RD	Black Olive	6-10"	No	25'		Poor (21% to 40%)	Plunged	Decay Observed	Epicormic Growth
SW 23RD RD	Black Olive	21-30"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Restricted Canopy
SW 23RD RD	Black Olive	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 23RD RD	Mahogany	6-10"	No	20'		Poor (21% to 40%)	Girdling Roots	Trunk Damage - Moderate	Epicormic Growth
SW 23RD RD	Black Olive	6-10"	No	25'		Poor (21% to 40%)	Improperly Mulched	Limb Damage - Major	Epicormic Growth
SW 23RD RD	Black Olive	11-15"	No	30'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Stubs with Sprouts
SW 23RD RD	Hong Kong Orchid	16-20"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Cavities	Epicormic Growth
SW 23RD RD	Black Olive	11-15"	No	30'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 23RD RD	Black Olive	11-15"	No	30'		Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Broken Branches
SW 23RD RD	Black Olive	16-20"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 23RD RD	Black Olive	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Plunged	Stubs with Sprouts	Broken Branches
SW 23RD RD	Black Olive	11-15"	No	35'		Good (61% to 80%)	Codominant Leaders/Included Bark	Stubs with Sprouts	Broken Branches
SW 23RD RD	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)			
SW 23RD RD	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)			
SW 23RD RD	Royal Poinciana	16-20"	No	35'		Fair (41% to 60%)	Crown Density - Low	Epicormic Growth	Broken Branches
SW 23RD RD	Foxtail Palm	11-15"	No	20'		Good (61% to 80%)			
SW 23RD RD	Foxtail Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Foxtail Palm	11-15"	No	20'		Good (61% to 80%)			
SW 23RD RD	Foxtail Palm	6-10"	No	20'		Good (61% to 80%)			
SW 23RD RD	Foxtail Palm	11-15"	No	20'		Good (61% to 80%)			
SW 23RD RD	Royal Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 23RD RD	Royal Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Royal Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 23RD RD	Royal Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 23RD RD	Royal Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 23RD RD	Queen Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Queen Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Queen Palm	6-10"	No	20'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	16-20"	Yes	10'		Fair (41% to 60%)	Leader - Broken	One Dead Trunk	
SW 23RD RD	Royal Poinciana	21-30"	No	55'		Fair (41% to 60%)	Decay Observed	Cavities	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 23rd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD RD	Royal Poinciana	16-20"	No	55'		Good (61% to 80%)	Limb Damage - Minor	Broken Branches	Dead Wood
SW 23RD RD	Royal Poinciana	16-20"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Vine Cover - Heavy
SW 23RD RD	Royal Poinciana	11-15"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 23RD RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 23RD RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 23RD RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Royal Palm	21-30"	No	20'		Good (61% to 80%)	Pencil Top		
SW 23RD RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 23RD RD	Royal Palm	21-30"	No	20'		Good (61% to 80%)			
SW 23RD RD	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Over Pruned		
SW 23RD RD	Canary Island Date Palm	21-30"	No	20'		Poor (21% to 40%)	Over Pruned	Nutrient Deficiency	Tapered Trunk
SW 23RD RD	Royal Poinciana	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 23RD RD	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 23RD RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)			
SW 23RD RD	Mahogany	31-40"	No	55'		Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Dead Wood
SW 23RD RD	Royal Palm	31-40"	Yes	35'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 23RD RD	Queen Palm	1-5"	No	10'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 23RD RD	Mahogany	31-40"	No	60'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 23RD RD	Royal Palm	31-40"	Yes	30'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)		
SW 23RD RD	Royal Palm	31-40"	Yes	30'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)		
SW 23RD RD	Royal Palm	11-15"	No	Negligible		Dead (0% to 5%)	Basal Co-Dominant with Adjacent Tree(s)	Dead Meristem	
SW 23RD RD	Royal Palm	16-20"	No	Negligible		Dead (0% to 5%)	Basal Co-Dominant with Adjacent Tree(s)	Dead Meristem	
SW 23RD RD	Spindle Palm	11-15"	No	Negligible	Utility Lines Above	Dead (0% to 5%)	Dead Meristem		
SW 23RD RD	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 23RD RD	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)			
SW 23RD RD	Spindle Palm	6-10"	No	5'	Utility Lines Above	Poor (21% to 40%)	Nutrient Deficiency	Trunk Damage - Major	Cavities
SW 23RD RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 23RD RD	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Pruned Into Shrub	Codominant Leaders/No Included Bark
SW 23RD RD	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Pruned Into Shrub	Codominant Leaders/No Included Bark
SW 23RD RD	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Pruned Into Shrub	Sprouting
SW 23RD RD	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Pruned Into Shrub	Sprouting
SW 23RD RD	Black Olive	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD RD	Black Olive	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 23RD RD	Black Olive	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 23RD RD	Vera Wood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Pruned Into Shrub	Codominant Leaders/No Included Bark
SW 23RD RD	Vera Wood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Epicormic Growth	Pruned Into Shrub	Codominant Leaders/No Included Bark
SW 23RD RD	White Frangipani	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 23RD RD	White Frangipani	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Sprouting	
SW 23RD RD	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 23RD RD	Christmas Palm	16-20"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Adjacent Light Pole	

(Continued on Next Page)

Street Tree Inventory

SW 23rd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD RD	Black Olive	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Topped	Decay Observed	Stubs with Sprouts
SW 23RD RD	Royal Poinciana	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Cavities
SW 23RD RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Lion's Tailing	Restricted Canopy	Suppressed Canopy
SW 23RD RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)	Trunk Damage - Minor		
SW 23RD RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Trunk Damage - Moderate		
SW 23RD RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 23RD RD	Mahogany	11-15"	No	35'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Utility Pruned
SW 23RD RD	Mahogany	16-20"	No	45'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Utility Pruned
SW 23RD RD	Florida Privet	16-20"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Stubs with Sprouts	Dead Wood
SW 23RD RD	Royal Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 23RD RD	Royal Palm	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 23RD RD	Solitaire Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 23RD RD	Solitaire Palm	1-5"	No	5'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 23RD RD	Solitaire Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 23RD RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	

SW 24th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH RD	Hong Kong Orchid	31-40"	No	15'		Poor (21% to 40%)	Basal Co-Dominant	Trunk Damage - Major	Sloughing Bark
SW 24TH RD	Spanish Cherry	16-20"	No	35'		Fair (41% to 60%)	Limb Damage - Moderate	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 24TH RD	Spanish Cherry	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Codominant Leaders/No Included Bark
SW 24TH RD	Pili Tree	21-30"	No	25'		Poor (21% to 40%)	Leader - Broken	Decay Observed	Sprouting
SW 24TH RD	Christmas Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 24TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Dracaena sp.	6-10"	No	5'		Good (61% to 80%)	Trunk Damage - Minor		
SW 24TH RD	Jacaranda	11-15"	No	10'		Poor (21% to 40%)	Trunk Damage - Major	Topped	Lopsided/Significantly Reduced Canopy
SW 24TH RD	Spanish Cherry	6-10"	No	20'		Good (61% to 80%)	Stubs with Sprouts	Restricted Canopy	
SW 24TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Queen Crepe Myrtle	1-5"	No	15'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Sprouting
SW 24TH RD	Queen Crepe Myrtle	1-5"	No	5'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 24TH RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Areca Palm	16-20"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Areca Palm	16-20"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Areca Palm	16-20"	Yes	5'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Areca Palm	16-20"	Yes	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Corn Plant	16-20"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Oriental Arborvitae	6-10"	Yes	10'		Good (61% to 80%)	Pruned Into Shrub		
SW 24TH RD	Starburst Clerodendron	6-10"	Yes	5'		Good (61% to 80%)	Grafted Branches	Dead Wood	Pruned Into Shrub
SW 24TH RD	Spanish Cherry	6-10"	Yes	10'		Fair (41% to 60%)	Leader - Broken	Stubs with Sprouts	Restricted Canopy
SW 24TH RD	Spanish Cherry	11-15"	No	15'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Restricted Canopy
SW 24TH RD	Pink Tabebuia	6-10"	Yes	10'		Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	
SW 24TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 24TH RD	Solitaire Palm	11-15"	Yes	20'		Good (61% to 80%)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 24th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 24TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 24TH RD	Bottle Palm	16-20"	No	10'		Good (61% to 80%)			
SW 24TH RD	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 24TH RD	Royal Poinciana	16-20"	No	45'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 24TH RD	Yellow Poinciana	11-15"	No	25'		Poor (21% to 40%)	Girdling Roots	Topped	Stubs with Sprouts
SW 24TH RD	Yellow Poinciana	16-20"	No	40'		Poor (21% to 40%)	Girdling Roots	Topped	Stubs with Sprouts
SW 24TH RD	Royal Poinciana	21-30"	No	60'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 24TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)			
SW 24TH RD	Royal Palm	11-15"	No	20'		Good (61% to 80%)			
SW 24TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Royal Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 24TH RD	Jacaranda	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Sloughing Bark
SW 24TH RD	Pink Tabebuia	16-20"	No	30'		Fair (41% to 60%)	Galls	Codominant Leaders/Included Bark	Epicormic Growth
SW 24TH RD	Live Oak	16-20"	No	45'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 24TH RD	Live Oak	16-20"	No	45'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 24TH RD	Live Oak	16-20"	No	45'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 24TH RD	Crepe Myrtle	6-10"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Grafted Branches
SW 24TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned		
SW 24TH RD	Mango	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 24TH RD	Coconut Palm	11-15"	No	25'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Live Oak	6-10"	No	15'		Poor (21% to 40%)	Basal Co-Dominant	Pruned Into Shrub	Crown Density - Very Low
SW 24TH RD	Live Oak	6-10"	No	20'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Pruned Into Shrub	Crown Density - Excessive (Due to Epicormic Growth)
SW 24TH RD	Live Oak	6-10"	No	15'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Pruned Into Shrub	Crown Density - Excessive (Due to Epicormic Growth)
SW 24TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Pongam	31-40"	No	35'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Apical Dieback
SW 24TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 24TH RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 24TH RD	Solitaire Palm	11-15"	Yes	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Solitaire Palm	6-10"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Podocarpus	6-10"	Yes	5'		Good (61% to 80%)	Pruned Into Shrub		
SW 24TH RD	Podocarpus	6-10"	Yes	5'		Good (61% to 80%)	Pruned Into Shrub		
SW 24TH RD	Podocarpus	1-5"	Yes	5'		Good (61% to 80%)	Pruned Into Shrub		
SW 24TH RD	Spindle Palm	6-10"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Spindle Palm	6-10"	No	5'		Good (61% to 80%)			
SW 24TH RD	Spindle Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Black Olive	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Broken Branches
SW 24TH RD	Black Olive	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Limb Damage - Minor
SW 24TH RD	Spindle Palm	11-15"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Chinese Fan Palm	6-10"	No	10'		Good (61% to 80%)			
SW 24TH RD	Chinese Fan Palm	16-20"	Yes	20'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Chinese Fan Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Chinese Fan Palm	16-20"	Yes	20'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Chinese Fan Palm	16-20"	Yes	15'		Good (61% to 80%)	Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 24th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH RD	Pygmy Date Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Cabbage Palm	16-20"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Ficus Growing on Tree	
SW 24TH RD	Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 24TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Gumbo Limbo	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Mahogany	11-15"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Galls	Epicormic Growth
SW 24TH RD	Mahogany	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 24TH RD	Tamarind	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	
SW 24TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Mahogany	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 24TH RD	Mahogany	31-40"	No	60'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 24TH RD	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Apical Dieback	Dead Wood	Stubs with Sprouts
SW 24TH RD	Mahogany	31-40"	No	60'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 24TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 24TH RD	Royal Poinciana	21-30"	No	60'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 24TH RD	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Cracks in Trunk	
SW 24TH RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)			
SW 24TH RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)			
SW 24TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Christmas Palm	16-20"	Yes	20'		Good (61% to 80%)			
SW 24TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 24TH RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 24TH RD	Sapodilla	21-30"	No	40'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 24TH RD	Fishtail Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Sapodilla	31-40"	No	50'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Limb Damage - Minor
SW 24TH RD	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 24TH RD	Live Oak	16-20"	No	35'		Poor (21% to 40%)	Girdling Roots	Crown Density - Low	Epicormic Growth
SW 24TH RD	Mahogany	6-10"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Trunk Damage - Moderate	Lopsided/Moderately Reduced Canopy	Apical Dieback
SW 24TH RD	Live Oak	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback
SW 24TH RD	Sapodilla	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Grafted Branches
SW 24TH RD	Sapodilla	21-30"	No	40'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	Broken Branches
SW 24TH RD	Strangler Fig	60+"	No	55'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Sprouting
SW 24TH RD	Live Oak	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Broken Branches
SW 24TH RD	Mahogany	16-20"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 24TH RD	Live Oak	16-20"	No	35'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 24TH RD	Tamarind	31-40"	No	50'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 24TH RD	Tamarind	21-30"	No	50'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Dead Wood

(Continued on Next Page)

Street Tree Inventory

SW 24th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH RD	Tamarind	21-30"	No	50'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Codominant Leaders/No Included Bark
SW 24TH RD	Tamarind	31-40"	No	60'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/Included Bark	Stubs with Sprouts	Broken Branches
SW 24TH RD	Tamarind	21-30"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Broken Branches
SW 24TH RD	Tamarind	21-30"	No	50'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Dead Wood
SW 24TH RD	Royal Poinciana	16-20"	No	45'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Crown Density - Low	Lion's Tailing	Limb Damage - Moderate
SW 24TH RD	Gumbo Limbo	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 24TH RD	Tamarind	21-30"	No	45'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Limb Damage - Minor
SW 24TH RD	Weeping Fig	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 24TH RD	Gumbo Limbo	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Epicormic Growth
SW 24TH RD	Bottlebrush	6-10"	No	15'		Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Restricted Canopy
SW 24TH RD	Mahogany	11-15"	No	35'		Good (61% to 80%)	Broken Branches	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 24TH RD	Mahogany	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Epicormic Growth
SW 24TH RD	Yellow Poinciana	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Strap Constricting Tree
SW 24TH RD	Crepe Myrtle	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Sprouting
SW 24TH RD	Yellow Poinciana	6-10"	No	25'		Fair (41% to 60%)	Cracks in Trunk	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 24TH RD	Crepe Myrtle	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Sprouting
SW 24TH RD	Yellow Poinciana	6-10"	No	25'		Fair (41% to 60%)	Improperly Mulched	Cracks in Trunk	Epicormic Growth
SW 24TH RD	Crepe Myrtle	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 24TH RD	Yellow Poinciana	6-10"	No	25'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 24TH RD	Crepe Myrtle	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Sprouting
SW 24TH RD	Yellow Poinciana	6-10"	No	25'		Fair (41% to 60%)	Basal Co-Dominant	Limb Damage - Minor	Sprouting
SW 24TH RD	Yellow Poinciana	6-10"	No	30'		Good (61% to 80%)	Broken Branches	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 24TH RD	Yellow Poinciana	6-10"	No	25'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 24TH RD	Yellow Poinciana	6-10"	No	30'		Good (61% to 80%)	Limb Damage - Minor	Codominant Leaders/No Included Bark	Sprouting
SW 24TH RD	Yellow Poinciana	6-10"	No	30'		Fair (41% to 60%)	Limb Damage - Moderate	Codominant Leaders/No Included Bark	Broken Branches
SW 24TH RD	Yellow Poinciana	6-10"	No	25'		Good (61% to 80%)	Limb Damage - Minor	Codominant Leaders/No Included Bark	Sprouting
SW 24TH RD	Crepe Myrtle	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Crown Density - Very Low	Seasonal Defoliation/Discolored Foliage
SW 24TH RD	Weeping Fig	21-30"	No	30'		Fair (41% to 60%)	Apical Dieback	Broken Branches	Stubs with Sprouts
SW 24TH RD	Pink Tabebuia	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Stubs with Sprouts
SW 24TH RD	Pink Tabebuia	11-15"	No	20'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Epicormic Growth
SW 24TH RD	Christmas Palm	6-10"	No	25'		Good (61% to 80%)			
SW 24TH RD	Pink Tabebuia	16-20"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 24TH RD	Mahogany	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Epicormic Growth
SW 24TH RD	Mahogany	6-10"	No	35'		Fair (41% to 60%)	Discolored Foliage	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 24TH RD	Pink Tabebuia	11-15"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 24TH RD	Pink Tabebuia	6-10"	No	15'		Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	Stubs
SW 24TH RD	Pink Tabebuia	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/Included Bark	Stubs with Sprouts	Restricted Canopy
SW 24TH RD	Tropical Almond	31-40"	No	55'		Fair (41% to 60%)	Constricted Roots	Seasonal Defoliation/Discolored Foliage	Sprouting
SW 24TH RD	Pink Tabebuia	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Restricted Canopy
SW 24TH RD	Washington Palm	16-20"	No	10'		Good (61% to 80%)			
SW 24TH RD	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency	Damaged Fronds	

(Continued on Next Page)

Street Tree Inventory

SW 24th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH RD	Black Olive	21-30"	No	55'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 24TH RD	Black Olive	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 24TH RD	Black Olive	16-20"	No	30'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Epicormic Growth	Limb Damage - Moderate
SW 24TH RD	Black Olive	16-20"	No	40'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Grafted Branches
SW 24TH RD	Black Olive	11-15"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 24TH RD	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Discolored Foliage	Epicormic Growth
SW 24TH RD	Mahogany	11-15"	No	25'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Discolored Foliage	Epicormic Growth
SW 24TH RD	Mahogany	41-50"	No	50'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Epicormic Growth
SW 24TH RD	Royal Palm	31-40"	Yes	25'		Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 24TH RD	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Girdling Roots	Trunk Damage - Major	Stubs with Sprouts
SW 24TH RD	Mahogany	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Cavities	Stubs with Sprouts
SW 24TH RD	Areca Palm	21-30"	Yes	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 24TH RD	Areca Palm	21-30"	Yes	10'		Good (61% to 80%)			
SW 24TH RD	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 24TH RD	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 24TH RD	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Galls	Dead Wood
SW 24TH RD	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Epicormic Growth
SW 24TH RD	Fishtail Palm	21-30"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	Suppressed Canopy
SW 24TH RD	Royal Palm	11-15"	No	20'		Good (61% to 80%)			
SW 24TH RD	Bottlebrush	6-10"	No	15'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 24TH RD	Pongam	51-60"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 24TH RD	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)			
SW 24TH RD	Christmas Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Christmas Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Dracaena sp.	31-40"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Sprouting	
SW 24TH RD	Yellow Tabebuia	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 24TH RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Christmas Palm	6-10"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Insect Damage Leaves	Nutrient Deficiency	
SW 24TH RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 24TH RD	Pygmy Date Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Black Olive	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Plunged	Broken Branches	Stubs with Sprouts
SW 24TH RD	Neem Tree	16-20"	No	Negligible	Utility Line Conflict	Dead (0% to 5%)	Decay Observed	Dead Wood	Ficus Growing on Tree
SW 24TH RD	Neem Tree	16-20"	Yes	10'		Very Poor/Critical (6% to 20%)	Crown Density - Very Low	Dead Wood	Sprouting
SW 24TH RD	Areca Palm	41-50"	Yes	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 24TH RD	Areca Palm	41-50"	Yes	20'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 24TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 24TH RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 24TH RD	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Pruned Into Shrub	Codominant Leaders/No Included Bark
SW 24TH RD	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Pruned Into Shrub	Codominant Leaders/Included Bark
SW 24TH RD	Royal Poinciana	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 24TH RD	Umbrella Tree	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Stubs with Sprouts
SW 24TH RD	Live Oak	16-20"	No	40'		Poor (21% to 40%)	Plunged	Apical Dieback	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory


SW 24th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 24TH RD	Live Oak	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 24TH RD	Pygmy Date Palm	16-20"	Yes	15'		Good (61% to 80%)			
SW 24TH RD	Bottle Palm	6-10"	No	5'		Fair (41% to 60%)	Reduced Canopy - Moderate	Nutrient Deficiency	
SW 24TH RD	Peregrina	6-10"	Yes	5'	Utility Line Conflict	Good (61% to 80%)	Grafted Branches	Codominant Leaders/No Included Bark	Broken Branches
SW 24TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	

Roads




Looking Northwest - SW 1st Avenue



Looking Northwest - SW 4th Avenue



Looking Northwest - SW 1st Avenue



Looking Northwest - SW 4th Avenue



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 9th Avenue



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 9th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 25th Road	1	Roads	3	100	3280	SE of 5th Ave	No	Yes	2	City	Yes	Yes	12 (20 NW of 5th Ave)	Yes	Yes	South of 3rd Ave mostly on NE	Large ROW makes for wide roads beyond where median ends. Date palms along median between 4th and 5th Street. Roundabouts at 2nd, 4th, and 5th Streets. Large intersection at NW end.
SW 26th Road	1	Roads	3	75	3500	SE of 5th Ave	No	Yes	2	City	Yes	Yes	7 (11 NW of 5th Ave)	Yes	Yes	No	Roundabout at 2nd and 7th Avenue.

SW 25th Road

TYPOLOGY F and B

SW 26th Road

TYPOLOGY F and B

Street Tree Inventory

SW 25th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH RD	Tamarind	16-20"	No	20'		Poor (21% to 40%)	Reduced Canopy - Moderate	Decay Observed	Epicormic Growth
SW 25TH RD	Mahogany	51-60"	No	65'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 25TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 25TH RD	Starburst Clerodendron	11-15"	Yes	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Pruned Into Shrub
SW 25TH RD	Christmas Palm	41-50"	Yes	25'		Good (61% to 80%)	Restricted Canopy		
SW 25TH RD	Christmas Palm	21-30"	Yes	20'		Good (61% to 80%)	Restricted Canopy		
SW 25TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 25TH RD	White Frangipani	1-5"	No	5'		Fair (41% to 60%)	Crown Density - Low		
SW 25TH RD	White Frangipani	1-5"	No	5'		Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	
SW 25TH RD	White Frangipani	1-5"	Yes	5'		Good (61% to 80%)			
SW 25TH RD	White Frangipani	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant		
SW 25TH RD	White Frangipani	1-5"	No	5'		Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	
SW 25TH RD	White Frangipani	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 25TH RD	Jacaranda	11-15"	No	30'		Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Cavities
SW 25TH RD	Royal Poinciana	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Stubs with Sprouts	Decay Observed
SW 25TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Over Pruned		
SW 25TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Over Pruned		
SW 25TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Over Pruned	Nutrient Deficiency	
SW 25TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Over Pruned		
SW 25TH RD	Coconut Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 25TH RD	Strangler Fig	31-40"	No	75'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Vine Cover - Heavy	Epicormic Growth
SW 25TH RD	Black Olive	31-40"	No	50'		Fair (41% to 60%)	Constricted Roots	Vine Cover - Heavy	Stubs with Sprouts
SW 25TH RD	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Trunk Damage - Moderate	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 25TH RD	Mahogany	51-60"	No	70'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 25TH RD	Mahogany	41-50"	No	80'		Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Stubs with Sprouts
SW 25TH RD	Norfolk Pine	21-30"	No	20'		Poor (21% to 40%)	Trunk Damage - Major	Leader - Broken	Ficus Growing on Tree
SW 25TH RD	Pink Tabebuia	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Codominant Leaders/No Included Bark	Restricted Canopy
SW 25TH RD	White Frangipani	16-20"	Yes	10'		Fair (41% to 60%)	Crown Density - Low	Grafted Branches	Sprouting
SW 25TH RD	Live Oak	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 25TH RD	Pink Tabebuia	6-10"	No	25'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 25TH RD	Pink Tabebuia	6-10"	No	20'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 25TH RD	Mahogany	31-40"	No	65'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 25TH RD	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 25TH RD	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Dead Wood	Epicormic Growth
SW 25TH RD	Mahogany	16-20"	No	45'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 25TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 25TH RD	Solitaire Palm	11-15"	Yes	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 25TH RD	Yellow Poinciana	1-5"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Stubs
SW 25TH RD	Pink Tabebuia	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Stubs with Sprouts
SW 25TH RD	Pink Tabebuia	6-10"	No	15'		Poor (21% to 40%)	Girdling Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 25TH RD	Norfolk Pine	21-30"	No	20'		Fair (41% to 60%)	Constricted Roots		
SW 25TH RD	Norfolk Pine	16-20"	No	20'		Fair (41% to 60%)	Constricted Roots		
SW 25TH RD	Norfolk Pine	21-30"	No	20'		Fair (41% to 60%)	Constricted Roots		

(Continued on Next Page)

Street Tree Inventory

SW 25th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH RD	Live Oak	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Epicormic Growth
SW 25TH RD	Live Oak	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 25TH RD	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Ficus Growing on Tree
SW 25TH RD	Washington Palm	11-15"	No	10'		Good (61% to 80%)			
SW 25TH RD	Washington Palm	11-15"	No	10'		Good (61% to 80%)			
SW 25TH RD	Washington Palm	11-15"	No	10'		Good (61% to 80%)			
SW 25TH RD	Black Olive	16-20"	No	35'		Fair (41% to 60%)	Decay Observed	Limb Damage - Moderate	Dead Wood
SW 25TH RD	Gumbo Limbo	11-15"	No	20'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark
SW 25TH RD	Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 25TH RD	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Restricted Canopy
SW 25TH RD	Mahogany	31-40"	No	60'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 25TH RD	Mahogany	31-40"	No	35'		Poor (21% to 40%)	Constricted Roots	Stubs with Sprouts	Limb Damage - Major
SW 25TH RD	Gumbo Limbo	1-5"	Yes	5'		Good (61% to 80%)	Grafted Branches		
SW 25TH RD	Gumbo Limbo	1-5"	Yes	5'		Good (61% to 80%)	Grafted Branches		
SW 25TH RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)			
SW 25TH RD	Gumbo Limbo	1-5"	Yes	5'		Good (61% to 80%)	Grafted Branches		
SW 25TH RD	Gumbo Limbo	1-5"	Yes	5'		Good (61% to 80%)	Grafted Branches		
SW 25TH RD	Oriental Arborvitae	16-20"	No	25'		Fair (41% to 60%)	Basal Co-Dominant	Sprouting	Broken Branches
SW 25TH RD	Oriental Arborvitae	16-20"	No	25'		Poor (21% to 40%)	Basal Co-Dominant	Sprouting	Trunk Damage - Moderate
SW 25TH RD	Mexican Lilac	1-5"	No	15'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Dead Wood
SW 25TH RD	Mexican Lilac	1-5"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Suppressed Canopy
SW 25TH RD	Royal Poinciana	16-20"	No	50'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 25TH RD	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 25TH RD	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 25TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 25TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 25TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 25TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 25TH RD	Solitaire Palm	1-5"	No	10'		Poor (21% to 40%)	Nutrient Deficiency		
SW 25TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 25TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 25TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 25TH RD	Coconut Palm	6-10"	No	15'		Good (61% to 80%)			
SW 25TH RD	Christmas Palm	11-15"	Yes	20'		Good (61% to 80%)			
SW 25TH RD	Starburst Clerodendron	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 25TH RD	Weeping Fig	11-15"	No	20'		Poor (21% to 40%)	Decay Observed	Crown Density - Low	Epicormic Growth
SW 25TH RD	Tamarind	21-30"	No	40'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Trunk Damage - Minor	Codominant Leaders/No Included Bark	Epicormic Growth
SW 25TH RD	Tamarind	21-30"	No	40'		Good (61% to 80%)	Dead Wood	Codominant Leaders/No Included Bark	Epicormic Growth
SW 25TH RD	Gumbo Limbo	1-5"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Grafted Branches	Vine Cover - Heavy
SW 25TH RD	Gumbo Limbo	1-5"	Yes	10'		Good (61% to 80%)	Suppressed Canopy	Broken Branches	Vine Cover - Heavy
SW 25TH RD	Gumbo Limbo	1-5"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Suppressed Canopy
SW 25TH RD	Tamarind	21-30"	No	45'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Epicormic Growth
SW 25TH RD	Tamarind	31-40"	No	55'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 25TH RD	Tamarind	16-20"	No	40'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Codominant Leaders/No Included Bark
SW 25TH RD	Tamarind	21-30"	No	45'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Dead Wood
SW 25TH RD	Tamarind	21-30"	No	45'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Codominant Leaders/No Included Bark
SW 25TH RD	Tamarind	16-20"	No	40'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Dead Wood
SW 25TH RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Stubs with Sprouts	Basal Co-Dominant with Adjacent Tree(s)	Suppressed Canopy

(Continued on Next Page)

Street Tree Inventory

SW 25th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH RD	Tamarind	11-15"	No	30'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Trunk Damage - Minor
SW 25TH RD	Tamarind	21-30"	No	45'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Grafted Branches
SW 25TH RD	Black Olive	21-30"	No	50'		Good (61% to 80%)	Dead Wood	Epicormic Growth	Codominant Leaders/No Included Bark
SW 25TH RD	Black Olive	21-30"	No	50'		Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 25TH RD	Black Olive	21-30"	No	55'		Fair (41% to 60%)	Limb Damage - Moderate	Dead Wood	Stubs with Sprouts
SW 25TH RD	Mahogany	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant		
SW 25TH RD	Mahogany	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant		
SW 25TH RD	Mahogany	1-5"	No	5'		Good (61% to 80%)			
SW 25TH RD	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Suppressed Canopy
SW 25TH RD	Gumbo Limbo	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Suppressed Canopy
SW 25TH RD	Black Olive	16-20"	No	40'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Dead Wood
SW 25TH RD	Black Olive	31-40"	No	65'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 25TH RD	Black Olive	31-40"	No	50'		Fair (41% to 60%)	Girdling Roots	Dead Wood	Stubs with Sprouts
SW 25TH RD	Black Olive	21-30"	No	50'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Stubs with Sprouts
SW 25TH RD	Banyan	6-10"	No	20'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Epicormic Growth	Restricted Canopy
SW 25TH RD	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Ficus Growing on Tree		
SW 25TH RD	Canary Island Date Palm	21-30"	No	20'		Fair (41% to 60%)	Ficus Growing on Tree	Nutrient Deficiency	
SW 25TH RD	Silk Floss Tree	1-5"	No	15'		Fair (41% to 60%)	Discolored Foliage	Codominant Leaders/No Included Bark	
SW 25TH RD	Mahogany	21-30"	No	40'		Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 25TH RD	Weeping Fig	31-40"	No	30'		Poor (21% to 40%)	Topped	Reduced Canopy - Moderate	Stubs with Sprouts
SW 25TH RD	Weeping Fig	41-50"	No	45'		Poor (21% to 40%)	Apical Dieback	Decay Observed	Dead Wood
SW 25TH RD	Weeping Fig	60+"	No	65'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Dead Wood
SW 25TH RD	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Suppressed Canopy
SW 25TH RD	Mahogany	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Suppressed Canopy
SW 25TH RD	Mahogany	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Suppressed Canopy
SW 25TH RD	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Damaged Fronds	Restricted Canopy	Suppressed Canopy
SW 25TH RD	Weeping Fig	21-30"	No	30'		Fair (41% to 60%)	Decay Observed	Broken Branches	Epicormic Growth
SW 25TH RD	Weeping Fig	21-30"	No	30'		Poor (21% to 40%)	Apical Dieback	Sloughing Bark	Epicormic Growth
SW 25TH RD	Weeping Fig	21-30"	No	35'		Poor (21% to 40%)	Apical Dieback	Sloughing Bark	Decay Observed
SW 25TH RD	Weeping Fig	21-30"	No	40'		Poor (21% to 40%)	Cracks in Trunk	Sloughing Bark	Stubs with Sprouts
SW 25TH RD	Weeping Fig	41-50"	No	50'		Poor (21% to 40%)	Decay Observed	Sloughing Bark	Stubs with Sprouts
SW 25TH RD	Weeping Fig	51-60"	No	55'		Poor (21% to 40%)	Decay Observed	Apical Dieback	Stubs with Sprouts
SW 25TH RD	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 25TH RD	Canary Island Date Palm	21-30"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Ficus Growing on Tree	Frizzled Fronds
SW 25TH RD	Canary Island Date Palm	31-40"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 25TH RD	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 25TH RD	Canary Island Date Palm	21-30"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 25TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 25TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 25TH RD	Royal Poinciana	11-15"	No	30'		Fair (41% to 60%)	Crown Density - Low	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 25TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 25TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 25TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 25th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH RD	Norfolk Pine	16-20"	No	15'		Good (61% to 80%)	Leaning - Minor		
SW 25TH RD	Jacaranda	11-15"	No	35'		Fair (41% to 60%)	Galls	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 25TH RD	Green Buttonwood	6-10"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 25TH RD	Green Buttonwood	11-15"	No	30'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 25TH RD	Green Buttonwood	11-15"	No	30'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 25TH RD	Green Buttonwood	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 25TH RD	Mahogany	11-15"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 25TH RD	Mahogany	41-50"	No	70'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 25TH RD	Mahogany	31-40"	No	60'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 25TH RD	Mahogany	41-50"	No	70'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 25TH RD	Washington Palm	11-15"	No	10'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 25TH RD	Mahogany	41-50"	No	70'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 25TH RD	Mahogany	21-30"	No	55'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 25TH RD	Mahogany	31-40"	No	55'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Dead Wood
SW 25TH RD	Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 25TH RD	Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 25TH RD	Gumbo Limbo	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 25TH RD	Gumbo Limbo	16-20"	No	20'		Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 25TH RD	Spindle Palm	6-10"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 25TH RD	Spindle Palm	11-15"	No	5'		Good (61% to 80%)			
SW 25TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 25TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 25TH RD	Bottlebrush	16-20"	No	30'		Poor (21% to 40%)	Trunk Damage - Major	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 25TH RD	Bottlebrush	16-20"	No	30'		Poor (21% to 40%)	Leader - Broken	Decay Observed	Stubs with Sprouts
SW 25TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 25TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 25TH RD	White Frangipani	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant		
SW 25TH RD	Black Olive	21-30"	No	55'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 25TH RD	Jacaranda	1-5"	No	5'		Good (61% to 80%)			
SW 25TH RD	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 25TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 25TH RD	Black Olive	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Cavities
SW 25TH RD	Royal Poinciana	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	
SW 25TH RD	Crepe Myrtle	11-15"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Grafted Branches	
SW 25TH RD	Live Oak	11-15"	No	40'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback
SW 25TH RD	Indian Laurel Fig	41-50"	No	40'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 25TH RD	Australian Pine	16-20"	No	45'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Broken Branches	Dead Wood
SW 25TH RD	Queen Palm	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 25TH RD	Queen Palm	11-15"	No	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 25TH RD	Queen Palm	11-15"	No	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 25TH RD	Royal Poinciana	21-30"	No	60'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 25TH RD	Royal Poinciana	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 25TH RD	Royal Poinciana	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Crown Density - Low	Dead Wood
SW 25TH RD	Hong Kong Orchid	6-10"	Yes	10'	Utility Lines Above	Poor (21% to 40%)	Desiccated Foliage	Crown Density - Very Low	Epicormic Growth
SW 25TH RD	Hong Kong Orchid	11-15"	Yes	15'	Utility Lines Above	Poor (21% to 40%)	Discolored Foliage	Apical Dieback	Epicormic Growth
SW 25TH RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)			
SW 25TH RD	Orange Geiger	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Broken Branches
SW 25TH RD	Royal Poinciana	11-15"	No	30'	Utility Line Conflict	Good (61% to 80%)	Adjacent Asphalt Damage	Codominant Leaders/No Included Bark	Broken Branches

(Continued on Next Page)

Street Tree Inventory

SW 25th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 25TH RD	Pongam	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 25TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 25TH RD	Bougainvillea sp.	6-10"	Yes	10'	Utility Line Conflict	Good (61% to 80%)	Grafted Branches	Epicormic Growth	Basal Co-Dominant with Adjacent Tree(s)
SW 25TH RD	Starburst Clerodendron	11-15"	Yes	10'	Utility Line Conflict	Fair (41% to 60%)	Topped	Stubs with Sprouts	Dead Wood
SW 25TH RD	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 25TH RD	Christmas Palm	16-20"	Yes	20'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 25TH RD	Mahogany	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Trunk Damage - Moderate	Sloughing Bark
SW 25TH RD	Mahogany	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)
SW 25TH RD	Mahogany	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Topped
SW 25TH RD	Mahogany	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 25TH RD	Spanish Cherry	1-5"	No	15'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/Included Bark	Pruned Into Shrub	
SW 25TH RD	Red Bay	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy

SW 26th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 26TH RD	Royal Poinciana	21-30"	No	60'		Poor (21% to 40%)	Constricted Roots	Cavities	Crown Density - Low
SW 26TH RD	Black Olive	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 26TH RD	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 26TH RD	Weeping Fig	1-5"	No	10'		Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Epicormic Growth
SW 26TH RD	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 26TH RD	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 26TH RD	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 26TH RD	Live Oak	6-10"	No	15'		Poor (21% to 40%)	Uprooted - Mostly	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback
SW 26TH RD	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 26TH RD	Black Olive	31-40"	No	65'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 26TH RD	Black Olive	21-30"	No	55'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 26TH RD	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 26TH RD	Black Olive	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 26TH RD	Black Olive	21-30"	No	50'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 26TH RD	White Frangipani	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Dead Wood	Suppressed Canopy
SW 26TH RD	Christmas Palm	1-5"	No	10'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 26TH RD	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 26TH RD	Mahogany	31-40"	No	60'		Fair (41% to 60%)	Constricted Roots	Ficus Growing on Tree	Stubs with Sprouts
SW 26TH RD	Royal Poinciana	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 26TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 26TH RD	Royal Poinciana	16-20"	No	50'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Cavities
SW 26TH RD	Royal Poinciana	21-30"	No	45'		Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Dead Wood
SW 26TH RD	Queen Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 26TH RD	Queen Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 26TH RD	Queen Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 26TH RD	Black Olive	21-30"	No	45'		Fair (41% to 60%)	Codominant Leaders/Included Bark	Stubs with Sprouts	Limb Damage - Moderate

(Continued on Next Page)

Street Tree Inventory

SW 26th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 26TH RD	Black Olive	31-40"	No	60'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 26TH RD	Live Oak	11-15"	No	30'		Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	Epicormic Growth
SW 26TH RD	Live Oak	11-15"	No	30'		Poor (21% to 40%)	Plunged	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 26TH RD	Royal Poinciana	21-30"	No	35'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 26TH RD	Areca Palm	11-15"	Yes	5'		Good (61% to 80%)			
SW 26TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 26TH RD	Areca Palm	11-15"	Yes	5'		Good (61% to 80%)			
SW 26TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned		
SW 26TH RD	Mahogany	16-20"	No	30'		Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 26TH RD	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Epicormic Growth
SW 26TH RD	Royal Poinciana	11-15"	No	30'		Very Poor/Critical (6% to 20%)	Crown Density - Very Low	Dead Wood	Epicormic Growth
SW 26TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 26TH RD	Black Olive	41-50"	No	45'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Dead Wood
SW 26TH RD	Live Oak	6-10"	No	15'		Poor (21% to 40%)	Plunged	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 26TH RD	Jacaranda	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Dead Wood
SW 26TH RD	Christmas Palm	11-15"	Yes	15'		Fair (41% to 60%)	Damaged Fronds	Nutrient Deficiency	Over Pruned
SW 26TH RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)			
SW 26TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 26TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 26TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 26TH RD	Montgomery Palm	6-10"	No	15'		Good (61% to 80%)			
SW 26TH RD	Montgomery Palm	6-10"	No	15'		Good (61% to 80%)			
SW 26TH RD	Royal Poinciana	21-30"	Yes	45'		Good (61% to 80%)	Cavities	Dead Wood	Restricted Canopy
SW 26TH RD	Coconut Palm	6-10"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Insect Damage Leaves		
SW 26TH RD	Coconut Palm	6-10"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Insect Damage Leaves		
SW 26TH RD	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 26TH RD	Coconut Palm	11-15"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Sea Grape	1-5"	No	5'		Fair (41% to 60%)	Topped	Stubs with Sprouts	
SW 26TH RD	Crepe Myrtle	6-10"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Pruned Into Shrub
SW 26TH RD	Crepe Myrtle	11-15"	Yes	5'		Good (61% to 80%)	Pruned Into Shrub	Stubs with Sprouts	
SW 26TH RD	Yucca sp.	16-20"	Yes	10'		Good (61% to 80%)			
SW 26TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 26TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Shaving Brush Tree	6-10"	No	10'		Good (61% to 80%)	Stubs with Sprouts	Broken Branches	Codominant Leaders/No Included Bark
SW 26TH RD	Black Olive	6-10"	No	5'		Poor (21% to 40%)	Girdling Roots	Topped	Stubs with Sprouts
SW 26TH RD	Red Maple	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark		
SW 26TH RD	Live Oak	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 26TH RD	Live Oak	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 26TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 26TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 26TH RD	Pink Tabebuia	6-10"	Yes	10'		Fair (41% to 60%)	Discolored Foliage	Codominant Leaders/No Included Bark	
SW 26TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Solitaire Palm	6-10"	Yes	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 26TH RD	Royal Palm	16-20"	No	25'		Good (61% to 80%)			
SW 26TH RD	Royal Palm	11-15"	No	20'		Good (61% to 80%)			

(Continued on Next Page)

Street Tree Inventory

SW 26th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 26TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 26TH RD	Day Blooming Jasmine	6-10"	Yes	5'		Fair (41% to 60%)	Trunk Damage - Minor	Insect Damage Leaves	Pruned Into Shrub
SW 26TH RD	Black Olive	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Dead Wood
SW 26TH RD	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 26TH RD	Black Olive	21-30"	No	25'		Poor (21% to 40%)	Topped	Reduced Canopy - Moderate	Decay Observed
SW 26TH RD	Mahogany	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Ficus Growing on Tree
SW 26TH RD	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 26TH RD	Mahogany	21-30"	No	55'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 26TH RD	Black Olive	16-20"	No	15'		Very Poor/Critical (6% to 20%)	Reduced Canopy - Major	Decay Observed	Ficus Growing on Tree
SW 26TH RD	Black Olive	11-15"	No	25'		Poor (21% to 40%)	Leader - Broken	Reduced Canopy - Moderate	Trunk Damage - Moderate
SW 26TH RD	Weeping Fig	6-10"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Stubs with Sprouts
SW 26TH RD	Weeping Fig	6-10"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Stubs with Sprouts
SW 26TH RD	Weeping Fig	11-15"	Yes	10'		Good (61% to 80%)	Dead Wood	Pruned Into Shrub	Stubs with Sprouts
SW 26TH RD	Weeping Fig	11-15"	Yes	10'		Good (61% to 80%)	Dead Wood	Pruned Into Shrub	Epicormic Growth
SW 26TH RD	Weeping Fig	6-10"	Yes	10'		Good (61% to 80%)	Dead Wood	Pruned Into Shrub	Stubs with Sprouts
SW 26TH RD	Weeping Fig	6-10"	Yes	10'		Good (61% to 80%)	Grafted Branches	Pruned Into Shrub	Stubs with Sprouts
SW 26TH RD	Live Oak	1-5"	No	10'	Utility Lines Above	Poor (21% to 40%)	Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback
SW 26TH RD	Canary Island Date Palm	11-15"	No	15'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Vera Wood	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Improperly Mulched	Crown Density - Low	Apical Dieback
SW 26TH RD	Sylvester Date Palm	11-15"	No	20'	Utility Lines Above	Good (61% to 80%)			
SW 26TH RD	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 26TH RD	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 26TH RD	Simpson's Stopper	1-5"	No	5'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Suppressed Canopy
SW 26TH RD	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 26TH RD	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 26TH RD	Tropical Almond	16-20"	No	40'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 26TH RD	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 26TH RD	Tropical Almond	16-20"	No	20'		Fair (41% to 60%)	Seasonal Defoliation/Discolored Foliage	Leader - Broken	Dead Wood
SW 26TH RD	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 26TH RD	Turkey Oak	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Seasonal Defoliation/Discolored Foliage
SW 26TH RD	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 26TH RD	Tropical Almond	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Seasonal Defoliation/Discolored Foliage	Decay Observed
SW 26TH RD	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Grafted Branches
SW 26TH RD	Tropical Almond	11-15"	No	25'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Broken Branches	Stubs with Sprouts
SW 26TH RD	Mahogany	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Improperly Mulched	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 26TH RD	Mahogany	21-30"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 26TH RD	Mahogany	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 26TH RD	Tropical Almond	21-30"	No	30'		Fair (41% to 60%)	Constricted Roots	Seasonal Defoliation/Discolored Foliage	Dead Wood
SW 26TH RD	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 26TH RD	Tropical Almond	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Seasonal Defoliation/Discolored Foliage	Galls
SW 26TH RD	Tropical Almond	11-15"	No	25'		Fair (41% to 60%)	Seasonal Defoliation/Discolored Foliage	Broken Branches	Galls
SW 26TH RD	Green Buttonwood	11-15"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 26th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 26TH RD	Green Buttonwood	6-10"	No	20'		Poor (21% to 40%)	Leader - Bent	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 26TH RD	Tropical Almond	11-15"	No	35'		Poor (21% to 40%)	Galls	Seasonal Defoliation/Discolored Foliage	Dead Wood
SW 26TH RD	Green Buttonwood	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Broken Branches
SW 26TH RD	Tropical Almond	6-10"	No	20'		Fair (41% to 60%)	Galls	Seasonal Defoliation/Discolored Foliage	Stubs with Sprouts
SW 26TH RD	Green Buttonwood	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 26TH RD	Tropical Almond	11-15"	No	30'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Broken Branches	Dead Wood
SW 26TH RD	Green Buttonwood	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 26TH RD	Green Buttonwood	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Dead Wood
SW 26TH RD	Green Buttonwood	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 26TH RD	Green Buttonwood	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 26TH RD	Green Buttonwood	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 26TH RD	Tropical Almond	11-15"	No	20'		Fair (41% to 60%)	Seasonal Defoliation/Discolored Foliage	Leader - Broken	Trunk Damage - Minor
SW 26TH RD	Mahogany	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 26TH RD	Tropical Almond	21-30"	No	35'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Broken Branches	Stubs with Sprouts
SW 26TH RD	Tropical Almond	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Seasonal Defoliation/Discolored Foliage
SW 26TH RD	Live Oak	6-10"	No	25'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Restricted Canopy
SW 26TH RD	Mahogany	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 26TH RD	Green Buttonwood	6-10"	No	15'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Epicormic Growth
SW 26TH RD	Tropical Almond	16-20"	No	40'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Seasonal Defoliation/Discolored Foliage
SW 26TH RD	Mahogany	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Stubs with Sprouts
SW 26TH RD	Hong Kong Orchid	16-20"	No	30'		Fair (41% to 60%)	Basal Co-Dominant	Broken Branches	Stubs with Sprouts
SW 26TH RD	Mahogany	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 26TH RD	Hong Kong Orchid	16-20"	No	30'		Poor (21% to 40%)	Basal Co-Dominant	Limb Damage - Moderate	Stubs with Sprouts
SW 26TH RD	Mahogany	6-10"	No	25'		Good (61% to 80%)	Trunk Damage - Minor	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 26TH RD	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 26TH RD	Tropical Almond	21-30"	No	45'		Good (61% to 80%)	Dead Wood	Seasonal Defoliation/Discolored Foliage	Stubs with Sprouts
SW 26TH RD	Mahogany	6-10"	No	20'		Fair (41% to 60%)	Crown Density - Low	Dead Wood	Epicormic Growth
SW 26TH RD	Tropical Almond	11-15"	No	40'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Stubs with Sprouts	Broken Branches
SW 26TH RD	Mahogany	6-10"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 26TH RD	Tropical Almond	21-30"	No	45'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 26TH RD	Mahogany	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 26TH RD	Tropical Almond	21-30"	No	45'		Fair (41% to 60%)	Seasonal Defoliation/Discolored Foliage	Decay Observed	Dead Wood
SW 26TH RD	Pink Tabebuia	21-30"	No	25'		Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 26th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 26TH RD	Pink Tabebuia	16-20"	No	20'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Broken Branches
SW 26TH RD	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 26TH RD	Vera Wood	6-10"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Stubs with Sprouts
SW 26TH RD	Mahogany	6-10"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Stubs with Sprouts
SW 26TH RD	Mahogany	11-15"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Stubs with Sprouts
SW 26TH RD	Vera Wood	6-10"	No	30'		Poor (21% to 40%)	Crown Density - Low	Decay Observed	Limb Damage - Major
SW 26TH RD	Mahogany	11-15"	No	40'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Broken Branches
SW 26TH RD	Vera Wood	6-10"	No	25'		Fair (41% to 60%)	Limb Damage - Moderate	Epicormic Growth	Codominant Leaders/No Included Bark
SW 26TH RD	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Limb Damage - Moderate	Broken Branches	Sprouting
SW 26TH RD	Green Buttonwood	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 26TH RD	Coconut Palm	11-15"	No	25'		Good (61% to 80%)			
SW 26TH RD	Pigeon Plum	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Pruned Into Shrub
SW 26TH RD	Pigeon Plum	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Pruned Into Shrub
SW 26TH RD	Royal Poinciana	16-20"	No	30'		Fair (41% to 60%)	Basal Co-Dominant	Grafted Branches	Stubs with Sprouts
SW 26TH RD	White Frangipani	6-10"	Yes	5'		Good (61% to 80%)	Grafted Branches	Sprouting	Suppressed Canopy
SW 26TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Over Pruned	Frizzled Fronds
SW 26TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 26TH RD	Pigeon Plum	1-5"	No	15'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Pruned Into Shrub
SW 26TH RD	Pigeon Plum	1-5"	No	15'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Pruned Into Shrub
SW 26TH RD	Black Olive	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Topped
SW 26TH RD	Black Olive	21-30"	No	20'		Very Poor/Critical (6% to 20%)	Constricted Roots	Trunk Damage - Major	Topped
SW 26TH RD	Black Olive	21-30"	No	30'		Very Poor/Critical (6% to 20%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Topped
SW 26TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 26TH RD	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 26TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Split Canopy	
SW 26TH RD	Queen Palm	11-15"	No	20'		Good (61% to 80%)			
SW 26TH RD	Queen Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Queen Palm	6-10"	No	20'		Good (61% to 80%)			
SW 26TH RD	Mahogany	21-30"	No	60'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/Included Bark
SW 26TH RD	Royal Poinciana	11-15"	No	35'		Fair (41% to 60%)	Crown Density - Low	Stubs with Sprouts	Broken Branches
SW 26TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Coconut Palm	6-10"	No	25'		Good (61% to 80%)	Nutrient Deficiency	Split Canopy	
SW 26TH RD	Coconut Palm	11-15"	No	25'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 26TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)			
SW 26TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 26TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Coconut Palm	11-15"	No	10'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 26TH RD	Coconut Palm	11-15"	No	15'		Fair (41% to 60%)	Over Pruned		
SW 26TH RD	Coconut Palm	6-10"	No	25'		Good (61% to 80%)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 26th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 26TH RD	Coconut Palm	11-15"	No	25'		Good (61% to 80%)	Over Pruned	Restricted Canopy	
SW 26TH RD	Coconut Palm	11-15"	No	10'		Fair (41% to 60%)	Over Pruned	Restricted Canopy	
SW 26TH RD	Coconut Palm	1-5"	No	10'		Poor (21% to 40%)	Over Pruned	Nutrient Deficiency	Tapered Trunk
SW 26TH RD	Coconut Palm	21-30"	Yes	30'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Restricted Canopy
SW 26TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Christmas Palm	21-30"	Yes	20'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Christmas Palm	16-20"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 26TH RD	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 26TH RD	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 26TH RD	Black Olive	21-30"	No	35'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 26TH RD	Black Olive	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Dead Wood	Lopsided/Significantly Reduced Canopy
SW 26TH RD	Black Olive	16-20"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 26TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 26TH RD	Coconut Palm	6-10"	No	25'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Pink Tabebuia	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 26TH RD	Coconut Palm	6-10"	No	25'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Tropical Almond	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Seasonal Defoliation/Discolored Foliage
SW 26TH RD	Spindle Palm	11-15"	No	10'		Good (61% to 80%)			
SW 26TH RD	Spindle Palm	11-15"	No	10'		Good (61% to 80%)			
SW 26TH RD	Spindle Palm	11-15"	No	10'		Good (61% to 80%)			
SW 26TH RD	Spindle Palm	11-15"	No	10'		Good (61% to 80%)			
SW 26TH RD	Spindle Palm	11-15"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Spindle Palm	11-15"	No	10'		Good (61% to 80%)			
SW 26TH RD	Spindle Palm	11-15"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Gardenia sp.	11-15"	No	10'		Poor (21% to 40%)	Basal Co-Dominant	Dead Wood	Crown Density - Low
SW 26TH RD	Weeping Fig	11-15"	No	15'		Fair (41% to 60%)	Basal Co-Dominant	Grafted Branches	Epicormic Growth
SW 26TH RD	White Geiger	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Grafted Branches
SW 26TH RD	White Geiger	1-5"	No	10'		Good (61% to 80%)	Stubs with Sprouts	Codominant Leaders/Included Bark	Grafted Branches
SW 26TH RD	Mahogany	21-30"	No	55'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 26TH RD	Mahogany	16-20"	No	50'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 26TH RD	Royal Poinciana	16-20"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 26TH RD	Royal Poinciana	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 26TH RD	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 26TH RD	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 26TH RD	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 26TH RD	Areca Palm	21-30"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 26TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 26TH RD	Areca Palm	41-50"	Yes	20'	Utility Lines Above	Good (61% to 80%)			
SW 26TH RD	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 26TH RD	Japanese Privet	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Pruned Into Shrub	
SW 26TH RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 26TH RD	Solitaire Palm	1-5"	No	10'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 26TH RD	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth

Roads



Looking Northwest - SW 1st Avenue



Looking Northwest - SW 4th Avenue



Looking Northwest - SW 1st Avenue



Looking Northwest - SW 4th Avenue



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 9th Avenue



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 9th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 27th Road	1	Roads	3	75	3280	SE of 5th Ave	No	Yes	2	City	Yes	Some	7 (11 NW of 5th Ave)	Yes	Yes	No	Sparse tree canopy NW of 5th Avenue
SW 28th Road	1	Roads	3	70	3280	No	No	Yes	2	City	Yes	Few	9	Yes	Yes	South of 3rd Ave mostly on SW	Freshly paved road between 3rd and 4th Avenue. Wide intersection on NW end. No tree canopy on NW end. Roundabouts on 2nd, 5th, and 7th Avenue.

SW 27th Road

TYPOLOGY F and B

SW 28th Road

TYPOLOGY B

Street Tree Inventory

SW 27th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH RD	Bismark Palm	16-20"	No	20'		Poor (21% to 40%)	Nutrient Deficiency		
SW 27TH RD	Bismark Palm	11-15"	No	10'		Poor (21% to 40%)	Nutrient Deficiency	Pencil Top	Reduced Canopy - Moderate
SW 27TH RD	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 27TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 27TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Frizzled Fronds	Nutrient Deficiency	
SW 27TH RD	Crepe Myrtle	1-5"	No	5'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	
SW 27TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 27TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 27TH RD	Queen Palm	11-15"	No	20'		Good (61% to 80%)			
SW 27TH RD	Queen Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 27TH RD	Sea Grape	16-20"	Yes	10'		Good (61% to 80%)	Grafted Branches	Pruned Into Shrub	Stubs with Sprouts
SW 27TH RD	Gumbo Limbo	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 27TH RD	Black Olive	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 27TH RD	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Basal Co-Dominant	Limb Damage - Minor	Epicormic Growth
SW 27TH RD	Coconut Palm	11-15"	No	25'		Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 27TH RD	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 27TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Over Pruned		
SW 27TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 27TH RD	Queen Palm	6-10"	No	25'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 27TH RD	Royal Poinciana	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 27TH RD	Mahogany	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Restricted Canopy
SW 27TH RD	Black Olive	21-30"	No	50'		Poor (21% to 40%)	Decay Observed	Sloughing Bark	Dead Wood
SW 27TH RD	Mahogany	31-40"	No	55'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 27TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 27TH RD	Mahogany	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Apical Dieback
SW 27TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 27TH RD	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	Damaged Fronds
SW 27TH RD	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 27TH RD	Black Olive	16-20"	No	30'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Broken Branches	Stubs with Sprouts
SW 27TH RD	Black Olive	16-20"	No	45'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 27TH RD	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 27TH RD	Mahogany	21-30"	No	20'		Very Poor/Critical (6% to 20%)	Constricted Roots	Trunk Damage - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 27TH RD	Sapodilla	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	
SW 27TH RD	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 27TH RD	Jacaranda	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Restricted Canopy
SW 27TH RD	White Stopper	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 27TH RD	White Stopper	1-5"	No	10'		Poor (21% to 40%)	Crown Density - Low	Apical Dieback	Epicormic Growth
SW 27TH RD	Gumbo Limbo	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Grafted Branches
SW 27TH RD	Blolly	11-15"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Grafted Branches
SW 27TH RD	Pigeon Plum	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Limb Damage - Minor	Restricted Canopy
SW 27TH RD	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Codominant Leaders/Included Bark	Epicormic Growth
SW 27TH RD	Live Oak	11-15"	No	30'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Epicormic Growth
SW 27TH RD	Gumbo Limbo	16-20"	No	40'		Good (61% to 80%)	Adjacent Asphalt Damage	Codominant Leaders/No Included Bark	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 27th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH RD	Black Olive	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 27TH RD	Black Olive	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 27TH RD	Solitaire Palm	1-5"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 27TH RD	Solitaire Palm	1-5"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 27TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 27TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 27TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 27TH RD	Queen Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	Reduced Canopy - Moderate
SW 27TH RD	Solitaire Palm	1-5"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 27TH RD	Gumbo Limbo	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Plunged	Trunk Damage - Major
SW 27TH RD	Mahogany	16-20"	No	30'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Epicormic Growth
SW 27TH RD	Bougainvillea sp.	16-20"	Yes	20'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Basal Co-Dominant with Adjacent Tree(s)
SW 27TH RD	Gumbo Limbo	16-20"	No	25'		Poor (21% to 40%)	Plunged	Lopsided/Significantly Reduced Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 27TH RD	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 27TH RD	Japanese Blueberry	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Codominant Leaders/Included Bark
SW 27TH RD	Live Oak	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 27TH RD	Live Oak	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 27TH RD	Bottlebrush	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders - Multi
SW 27TH RD	Bottlebrush	11-15"	No	5'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Pruned Into Shrub
SW 27TH RD	Bottlebrush	11-15"	No	5'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Pruned Into Shrub
SW 27TH RD	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 27TH RD	Peregrina	11-15"	Yes	10'		Fair (41% to 60%)	Crown Density - Low	Suppressed Canopy	Sprouting
SW 27TH RD	Mahogany	11-15"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Stubs with Sprouts
SW 27TH RD	Royal Poinciana	11-15"	No	35'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Broken Branches
SW 27TH RD	Mahogany	11-15"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 27TH RD	Royal Poinciana	21-30"	No	25'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Lopsided/Significantly Reduced Canopy
SW 27TH RD	Royal Poinciana	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 27TH RD	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 27TH RD	Royal Poinciana	11-15"	No	20'		Fair (41% to 60%)	Decay Observed	Epicormic Growth	Broken Branches
SW 27TH RD	Pink Tabebuia	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 27TH RD	Mahogany	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 27TH RD	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Limb Damage - Minor
SW 27TH RD	Mahogany	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Adjacent Light Pole
SW 27TH RD	Mahogany	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 27TH RD	Mahogany	11-15"	No	30'		Poor (21% to 40%)	Girdling Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 27TH RD	Mahogany	11-15"	No	30'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 27TH RD	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Girdling Roots	Limb Damage - Minor	Epicormic Growth
SW 27TH RD	Green Buttonwood	6-10"	No	10'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Epicormic Growth
SW 27TH RD	Gumbo Limbo	16-20"	No	25'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Grafted Branches
SW 27TH RD	Green Buttonwood	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 27TH RD	Green Buttonwood	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy

(Continued on Next Page)

Street Tree Inventory

SW 27th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH RD	Gumbo Limbo	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Cavities	Stubs with Sprouts
SW 27TH RD	Strangler Fig	16-20"	No	30'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Dead Wood
SW 27TH RD	Rose Apple	16-20"	No	30'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Broken Branches
SW 27TH RD	Green Buttonwood	6-10"	No	30'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Epicormic Growth
SW 27TH RD	Green Buttonwood	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Epicormic Growth
SW 27TH RD	Gumbo Limbo	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 27TH RD	Gumbo Limbo	16-20"	No	30'		Poor (21% to 40%)	Insect Damage Leaves	Apical Dieback	Stubs with Sprouts
SW 27TH RD	Green Buttonwood	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 27TH RD	Hong Kong Orchid	11-15"	No	10'		Very Poor/Critical (6% to 20%)	Basal Co-Dominant	Sloughing Bark	Decay Observed
SW 27TH RD	Green Buttonwood	11-15"	No	30'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 27TH RD	Green Buttonwood	16-20"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 27TH RD	Green Buttonwood	6-10"	No	20'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Epicormic Growth	Codominant Leaders/No Included Bark
SW 27TH RD	Green Buttonwood	11-15"	No	25'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Epicormic Growth	Codominant Leaders/No Included Bark
SW 27TH RD	Green Buttonwood	6-10"	No	25'		Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Broken Branches
SW 27TH RD	Green Buttonwood	6-10"	No	20'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 27TH RD	Hong Kong Orchid	11-15"	No	25'		Poor (21% to 40%)	Apical Dieback	Decay Observed	Epicormic Growth
SW 27TH RD	Green Buttonwood	6-10"	No	20'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 27TH RD	Hong Kong Orchid	16-20"	No	25'		Fair (41% to 60%)	Decay Observed	Broken Branches	Stubs with Sprouts
SW 27TH RD	Green Buttonwood	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 27TH RD	Green Buttonwood	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Lopsided/Moderately Reduced Canopy
SW 27TH RD	Gumbo Limbo	11-15"	No	25'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 27TH RD	Gumbo Limbo	6-10"	No	10'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 27TH RD	Green Buttonwood	6-10"	No	15'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 27TH RD	Green Buttonwood	6-10"	No	20'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 27TH RD	Orange Geiger	6-10"	No	15'		Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Restricted Canopy
SW 27TH RD	Green Buttonwood	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 27TH RD	Brazilian Beauty Leaf	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 27TH RD	Green Buttonwood	6-10"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Limb Damage - Minor
SW 27TH RD	Brazilian Beauty Leaf	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 27TH RD	Green Buttonwood	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 27TH RD	Orange Geiger	1-5"	No	15'		Fair (41% to 60%)	Trunk Damage - Moderate	Codominant Leaders/No Included Bark	Restricted Canopy
SW 27TH RD	Green Buttonwood	6-10"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 27TH RD	Orange Geiger	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Stubs with Sprouts
SW 27TH RD	Green Buttonwood	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Limb Damage - Minor
SW 27TH RD	Brazilian Beauty Leaf	6-10"	No	30'		Good (61% to 80%)	Leaning - Minor	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 27TH RD	Black Olive	16-20"	No	45'		Fair (41% to 60%)	Girdling Roots	Limb Damage - Minor	Stubs with Sprouts
SW 27TH RD	Vera Wood	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Decay Observed	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 27th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH RD	Mahogany	11-15"	No	30'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 27TH RD	Hong Kong Orchid	21-30"	Yes	20'		Very Poor/Critical (6% to 20%)	Decay Observed	Sloughing Bark	Stubs with Sprouts
SW 27TH RD	Green Buttonwood	6-10"	No	25'		Fair (41% to 60%)	Crown Density - Low	Epicormic Growth	Codominant Leaders/No Included Bark
SW 27TH RD	Green Buttonwood	6-10"	No	25'		Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Codominant Leaders/No Included Bark
SW 27TH RD	Christmas Palm	11-15"	No	20'		Good (61% to 80%)			
SW 27TH RD	Green Buttonwood	6-10"	No	15'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Epicormic Growth	Codominant Leaders/No Included Bark
SW 27TH RD	Green Buttonwood	6-10"	No	15'		Fair (41% to 60%)	Lateral Branching - None	Epicormic Growth	Broken Branches
SW 27TH RD	Brazilian Beauty Leaf	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 27TH RD	Green Buttonwood	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Broken Branches
SW 27TH RD	Green Buttonwood	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Broken Branches
SW 27TH RD	Green Buttonwood	6-10"	No	20'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Epicormic Growth	Restricted Canopy
SW 27TH RD	Gumbo Limbo	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Grafted Branches
SW 27TH RD	Mahogany	41-50"	No	55'		Fair (41% to 60%)	Limb Damage - Moderate	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 27TH RD	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Girdling Roots	Stubs with Sprouts	Decay Observed
SW 27TH RD	Mahogany	16-20"	No	25'		Fair (41% to 60%)	Plunged	Epicormic Growth	Dead Wood
SW 27TH RD	Royal Poinciana	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 27TH RD	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 27TH RD	Royal Poinciana	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 27TH RD	Mahogany	21-30"	No	40'		Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 27TH RD	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 27TH RD	Mahogany	31-40"	No	45'		Good (61% to 80%)	Codominant Leaders/Included Bark	Dead Wood	Stubs with Sprouts
SW 27TH RD	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Girdling Roots	Decay Observed	Apical Dieback
SW 27TH RD	Mahogany	31-40"	No	45'		Good (61% to 80%)	Codominant Leaders/Included Bark	Dead Wood	Stubs with Sprouts
SW 27TH RD	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Girdling Roots	Decay Observed	Apical Dieback
SW 27TH RD	Mahogany	31-40"	No	50'		Good (61% to 80%)	Codominant Leaders - Multi	Dead Wood	Epicormic Growth
SW 27TH RD	Gumbo Limbo	1-5"	No	10'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Codominant Leaders/No Included Bark
SW 27TH RD	Gumbo Limbo	1-5"	No	15'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Sprouting
SW 27TH RD	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Girdling Roots	Plunged	Decay Observed
SW 27TH RD	Mahogany	21-30"	No	45'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 27TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 27TH RD	Royal Poinciana	16-20"	No	40'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Stubs with Sprouts
SW 27TH RD	Gumbo Limbo	11-15"	No	30'		Poor (21% to 40%)	Girdling Roots	Crown Density - Low	Epicormic Growth
SW 27TH RD	Royal Poinciana	41-50"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Ficus Growing on Tree
SW 27TH RD	Jacaranda	11-15"	No	20'		Fair (41% to 60%)	Basal Co-Dominant	Dead Wood	Stubs with Sprouts
SW 27TH RD	Jacaranda	11-15"	No	20'		Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Stubs with Sprouts
SW 27TH RD	Jacaranda	6-10"	No	15'		Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Epicormic Growth
SW 27TH RD	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Lopsided/Significantly Reduced Canopy
SW 27TH RD	Mahogany	41-50"	No	55'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Ficus Growing on Tree
SW 27TH RD	Queen Palm	11-15"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 27TH RD	Banana Tree	21-30"	Yes	10'		Good (61% to 80%)			
SW 27TH RD	Banana Tree	11-15"	Yes	5'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 27TH RD	Banana Tree	31-40"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 27TH RD	Rose Apple	31-40"	No	20'		Poor (21% to 40%)	Constricted Roots	Topped	Crown Density - Excessive (Due to Epicormic Growth)
SW 27TH RD	Sapodilla	31-40"	No	30'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 27th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 27TH RD	Jacaranda	21-30"	No	20'		Poor (21% to 40%)	Root Damage/Decay	Reduced Canopy - Moderate	Decay Observed
SW 27TH RD	Gumbo Limbo	1-5"	No	5'		Fair (41% to 60%)	Topped	Stubs with Sprouts	
SW 27TH RD	Jacaranda	16-20"	No	20'		Poor (21% to 40%)	Girdling Roots	Topped	Decay Observed
SW 27TH RD	Jacaranda	6-10"	No	5'		Poor (21% to 40%)	Topped	Reduced Canopy - Major	Stubs with Sprouts
SW 27TH RD	Black Olive	16-20"	No	35'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 27TH RD	Black Olive	31-40"	No	55'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Sprouting
SW 27TH RD	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 27TH RD	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Epicormic Growth
SW 27TH RD	Live Oak	6-10"	No	20'		Poor (21% to 40%)	Lopsided/Moderately Reduced Canopy	Apical Dieback	Epicormic Growth
SW 27TH RD	Live Oak	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Apical Dieback
SW 27TH RD	Live Oak	6-10"	No	20'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)
SW 27TH RD	Rubber Tree	1-5"	Yes	5'		Good (61% to 80%)	Strap Constricting Tree		
SW 27TH RD	Umbrella Tree	21-30"	No	20'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Broken Branches
SW 27TH RD	Jacaranda	11-15"	No	20'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Limb Damage - Minor
SW 27TH RD	Umbrella Tree	16-20"	No	20'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 27TH RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 27TH RD	Black Olive	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 27TH RD	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 27TH RD	Black Olive	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Limb Damage - Major
SW 27TH RD	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 27TH RD	Black Olive	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Cracks in Trunk	Stubs with Sprouts
SW 27TH RD	Coconut Palm	6-10"	No	10'		Poor (21% to 40%)	Nutrient Deficiency	Reduced Canopy - Moderate	Over Pruned
SW 27TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Over Pruned	
SW 27TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 27TH RD	Black Olive	41-50"	No	40'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Decay Observed
SW 27TH RD	Weeping Fig	6-10"	No	5'		Poor (21% to 40%)	Crown Density - Very Low	Epicormic Growth	Pruned Into Shrub
SW 27TH RD	Weeping Fig	6-10"	No	5'		Poor (21% to 40%)	Crown Density - Low	Galls	Pruned Into Shrub
SW 27TH RD	Weeping Fig	6-10"	No	5'		Fair (41% to 60%)	Trunk Damage - Moderate	Epicormic Growth	Pruned Into Shrub
SW 27TH RD	Live Oak	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Broken Branches
SW 27TH RD	Live Oak	6-10"	No	20'		Poor (21% to 40%)	Plunged	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 27TH RD	Hibiscus sp.	11-15"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 27TH RD	Hibiscus sp.	11-15"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 27TH RD	Royal Poinciana	41-50"	No	60'	Ficus on Tree	Poor (21% to 40%)	Constricted Roots	Crown Density - Very Low	Sprouting
SW 27TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 27TH RD	Solitaire Palm	1-5"	No	Negligible		Dead (0% to 5%)	Dead Meristem		
SW 27TH RD	Pygmy Date Palm	1-5"	No	10'		Poor (21% to 40%)	Nutrient Deficiency		
SW 27TH RD	Pink Tabebuia	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Codominant Leaders/No Included Bark
SW 27TH RD	Pink Tabebuia	11-15"	No	20'		Poor (21% to 40%)	Constricted Roots	Topped	Grafted Branches

Street Tree Inventory

SW 28th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 28TH RD	Gumbo Limbo	6-10"	No	20'		Poor (21% to 40%)	Lifting	Crown Density - Very Low	Epicormic Growth
SW 28TH RD	Pigeon Plum	6-10"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Sprouting	Codominant Leaders/No Included Bark
SW 28TH RD	Brazilian Beauty Leaf	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 28TH RD	Bismark Palm	21-30"	No	15'		Good (61% to 80%)	Sap on Trunk		
SW 28TH RD	Bismark Palm	16-20"	No	15'		Good (61% to 80%)			
SW 28TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Over Pruned		
SW 28TH RD	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 28TH RD	Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 28TH RD	Coconut Palm	6-10"	No	5'		Good (61% to 80%)			
SW 28TH RD	Mahogany	51-60"	No	65'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Dead Wood
SW 28TH RD	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 28TH RD	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 28TH RD	Live Oak	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 28TH RD	Live Oak	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 28TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 28TH RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 28TH RD	Canary Island Date Palm	16-20"	No	20'		Good (61% to 80%)	Over Pruned		
SW 28TH RD	Canary Island Date Palm	21-30"	No	20'		Good (61% to 80%)	Over Pruned		
SW 28TH RD	Black Olive	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 28TH RD	Black Olive	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 28TH RD	Black Olive	21-30"	No	45'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 28TH RD	Live Oak	31-40"	No	70'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Limb Damage - Minor
SW 28TH RD	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 28TH RD	Mahogany	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 28TH RD	Mahogany	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 28TH RD	Mahogany	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 28TH RD	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Broken Branches
SW 28TH RD	Mahogany	16-20"	No	45'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 28TH RD	Washington Palm	11-15"	No	10'		Good (61% to 80%)			
SW 28TH RD	Live Oak	41-50"	No	70'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 28TH RD	Black Olive	31-40"	No	50'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 28TH RD	Black Olive	31-40"	No	45'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 28TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 28TH RD	Black Olive	16-20"	No	35'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 28TH RD	Black Olive	21-30"	No	35'		Poor (21% to 40%)	Root Damage/Decay	Basal Co-Dominant	Stubs with Sprouts
SW 28TH RD	Black Olive	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Root Damage/Decay	Galls	Decay Observed
SW 28TH RD	Black Olive	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 28TH RD	Areca Palm	31-40"	Yes	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 28TH RD	Foxtail Palm	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Nutrient Deficiency	Frizzled Fronds	
SW 28TH RD	Foxtail Palm	6-10"	No	Negligible	Utility Lines Above	Dead (0% to 5%)	Dead Meristem	Cavities	
SW 28TH RD	Foxtail Palm	6-10"	No	5'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Nutrient Deficiency	Frizzled Fronds	Reduced Canopy - Moderate
SW 28TH RD	Foxtail Palm	6-10"	No	Negligible	Utility Lines Above	Dead (0% to 5%)	Dead Meristem	Cavities	
SW 28TH RD	Live Oak	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Utility Pruned
SW 28TH RD	Gumbo Limbo	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Utility Pruned

(Continued on Next Page)

Street Tree Inventory

SW 28th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 28TH RD	Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Topped	Lateral Branching - None	Epicormic Growth
SW 28TH RD	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 28TH RD	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 28TH RD	Live Oak	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/Included Bark		
SW 28TH RD	Live Oak	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Topped	Stubs with Sprouts	
SW 28TH RD	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/Included Bark	Epicormic Growth	
SW 28TH RD	Gumbo Limbo	1-5"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Leader - Broken	Epicormic Growth	Codominant Leaders/No Included Bark
SW 28TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/Included Bark		
SW 28TH RD	Weeping Fig	1-5"	Yes	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Dead Wood	Epicormic Growth
SW 28TH RD	Weeping Fig	1-5"	Yes	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Dead Wood	Epicormic Growth
SW 28TH RD	Weeping Fig	1-5"	Yes	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Dead Wood	Epicormic Growth
SW 28TH RD	Weeping Fig	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Dead Wood	Epicormic Growth
SW 28TH RD	Weeping Fig	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Dead Wood	Epicormic Growth
SW 28TH RD	Weeping Fig	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Dead Wood	Epicormic Growth
SW 28TH RD	Weeping Fig	1-5"	Yes	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Dead Wood	Epicormic Growth
SW 28TH RD	Weeping Fig	1-5"	Yes	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Dead Wood	Epicormic Growth
SW 28TH RD	Weeping Fig	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Basal Co-Dominant	Epicormic Growth
SW 28TH RD	Weeping Fig	1-5"	Yes	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Dead Wood	Epicormic Growth
SW 28TH RD	Christmas Palm	1-5"	No	Negligible	Utility Lines Above	Dead (0% to 5%)	Topped	Dead Meristem	
SW 28TH RD	Christmas Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Restricted Canopy	Damaged Fronds	Reduced Canopy - Moderate
SW 28TH RD	Queen Palm	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Restricted Canopy	Damaged Fronds	Nutrient Deficiency
SW 28TH RD	Queen Palm	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Restricted Canopy	Damaged Fronds	Reduced Canopy - Moderate
SW 28TH RD	Mahogany	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Dead Wood
SW 28TH RD	Mahogany	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Improperly Mulched	Trunk Damage - Major	Stubs with Sprouts
SW 28TH RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Nutrient Deficiency	
SW 28TH RD	Christmas Palm	1-5"	No	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 28TH RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Nutrient Deficiency	
SW 28TH RD	Christmas Palm	1-5"	No	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 28TH RD	Live Oak	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Topped	Epicormic Growth	Suppressed Canopy
SW 28TH RD	Live Oak	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Topped	Epicormic Growth	Suppressed Canopy
SW 28TH RD	Royal Poinciana	31-40"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 28TH RD	Weeping Fig	60+"	No	75'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Dead Wood
SW 28TH RD	Weeping Fig	31-40"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Topped	Decay Observed	Epicormic Growth
SW 28TH RD	Mahogany	31-40"	No	60'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 28TH RD	Live Oak	6-10"	No	15'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Epicormic Growth
SW 28TH RD	Live Oak	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Epicormic Growth
SW 28TH RD	Live Oak	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Epicormic Growth
SW 28TH RD	Live Oak	1-5"	Yes	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Epicormic Growth
SW 28TH RD	Live Oak	1-5"	No	5'		Good (61% to 80%)			
SW 28TH RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)			
SW 28TH RD	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 28TH RD	Pigeon Plum	1-5"	No	5'		Good (61% to 80%)			
SW 28TH RD	Pigeon Plum	1-5"	No	5'		Good (61% to 80%)			
SW 28TH RD	Pigeon Plum	1-5"	No	5'		Good (61% to 80%)			
SW 28TH RD	Pink Tabebuia	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark		

(Continued on Next Page)

Street Tree Inventory

SW 28th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 28TH RD	Live Oak	1-5"	Yes	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Epicormic Growth
SW 28TH RD	Live Oak	1-5"	No	5'		Good (61% to 80%)			
SW 28TH RD	Live Oak	1-5"	No	5'		Good (61% to 80%)			
SW 28TH RD	Gumbo Limbo	1-5"	No	5'		Fair (41% to 60%)	White Fly		
SW 28TH RD	Gumbo Limbo	1-5"	No	5'		Fair (41% to 60%)	Lifting		
SW 28TH RD	Live Oak	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Sprouting	
SW 28TH RD	Pigeon Plum	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 28TH RD	Pigeon Plum	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 28TH RD	Gumbo Limbo	1-5"	No	15'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/Included Bark	Sprouting	Suppressed Canopy
SW 28TH RD	Pink Tabebuia	1-5"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Sprouting	Suppressed Canopy
SW 28TH RD	Pink Tabebuia	1-5"	No	5'		Good (61% to 80%)			
SW 28TH RD	Pigeon Plum	1-5"	No	5'		Good (61% to 80%)			
SW 28TH RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 28TH RD	Pigeon Plum	6-10"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Trunk Damage - Minor
SW 28TH RD	Yellow Tabebuia	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 28TH RD	Mahogany	41-50"	No	60'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Dead Wood
SW 28TH RD	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Epicormic Growth
SW 28TH RD	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 28TH RD	Mahogany	16-20"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Broken Branches
SW 28TH RD	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 28TH RD	Black Olive	31-40"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 28TH RD	Black Olive	21-30"	No	60'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 28TH RD	Tamarind	16-20"	No	30'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Restricted Canopy
SW 28TH RD	Gumbo Limbo	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Lifting
SW 28TH RD	Gumbo Limbo	21-30"	No	35'		Fair (41% to 60%)	Girdling Roots	Restricted Canopy	Stubs with Sprouts
SW 28TH RD	Mahogany	51-60"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Vine Cover - Heavy
SW 28TH RD	Live Oak	6-10"	No	10'		Poor (21% to 40%)	Improperly Mulched	Basal Co-Dominant	Crown Density - Excessive (Due to Epicormic Growth)
SW 28TH RD	Royal Poinciana	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Grafted Branches	Stubs with Sprouts
SW 28TH RD	Mahogany	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/Included Bark
SW 28TH RD	Royal Poinciana	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 28TH RD	Gumbo Limbo	16-20"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Restricted Canopy
SW 28TH RD	Royal Poinciana	31-40"	No	70'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	Ficus Growing on Tree
SW 28TH RD	Black Olive	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 28TH RD	Rainbow Eucalyptus	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 28TH RD	Washington Palm	16-20"	No	15'		Good (61% to 80%)			
SW 28TH RD	Live Oak	1-5"	No	5'		Very Poor/Critical (6% to 20%)	Improperly Mulched	Crown Density - Very Low	Epicormic Growth
SW 28TH RD	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Crown Density - Low	Apical Dieback	Epicormic Growth
SW 28TH RD	Silver Buttonwood	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 28TH RD	Mahogany	16-20"	No	20'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 28TH RD	Black Olive	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Discolored Foliage	Stubs with Sprouts
SW 28TH RD	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 28th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 28TH RD	Mahogany	6-10"	No	15'		Poor (21% to 40%)	Apical Dieback	Discolored Foliage	Epicormic Growth
SW 28TH RD	Mahogany	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Dead Wood
SW 28TH RD	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 28TH RD	Live Oak	11-15"	No	35'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 28TH RD	Live Oak	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Dead Wood
SW 28TH RD	Live Oak	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Limb Damage - Major
SW 28TH RD	Mahogany	41-50"	No	60'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 28TH RD	Mahogany	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth
SW 28TH RD	Mahogany	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 28TH RD	Gumbo Limbo	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Plunged	Stubs with Sprouts
SW 28TH RD	Mahogany	31-40"	No	35'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 28TH RD	Mahogany	41-50"	No	40'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Epicormic Growth
SW 28TH RD	Mahogany	51-60"	No	55'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 28TH RD	Mahogany	60+"	No	65'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 28TH RD	Mahogany	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 28TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 28TH RD	Umbrella Tree	6-10"	No	10'		Good (61% to 80%)	Trunk Damage - Minor	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 28TH RD	Live Oak	16-20"	No	30'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 28TH RD	Live Oak	16-20"	No	30'		Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	Epicormic Growth
SW 28TH RD	Paradise Tree	16-20"	No	20'		Poor (21% to 40%)	Constricted Roots	Lifting	Reduced Canopy - Moderate
SW 28TH RD	Crepe Myrtle	11-15"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Pruned Into Shrub
SW 28TH RD	Crepe Myrtle	1-5"	Yes	5'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Pruned Into Shrub
SW 28TH RD	Live Oak	16-20"	No	35'		Fair (41% to 60%)	Plunged	Apical Dieback	Epicormic Growth
SW 28TH RD	Live Oak	11-15"	No	30'		Fair (41% to 60%)	Plunged	Apical Dieback	Epicormic Growth
SW 28TH RD	Live Oak	11-15"	No	35'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Apical Dieback	Epicormic Growth
SW 28TH RD	Pigeon Plum	1-5"	No	10'		Good (61% to 80%)	Plunged	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 28TH RD	Black Olive	16-20"	No	40'		Fair (41% to 60%)	Decay Observed	Restricted Canopy	Stubs with Sprouts
SW 28TH RD	Black Olive	16-20"	No	40'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Stubs with Sprouts
SW 28TH RD	Gumbo Limbo	16-20"	No	25'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 28TH RD	Gumbo Limbo	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 28TH RD	Mahogany	21-30"	No	30'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 28TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 28TH RD	Sylvester Date Palm	11-15"	No	15'		Good (61% to 80%)	Restricted Canopy		


Roads



Looking Northwest - SW 3rd Avenue



Looking Northwest - SW 4th Avenue



Looking Northwest - SW 1st Avenue



Looking Northwest - SW 4th Avenue



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 7th Avenue



Looking Southeast - SW 5th Avenue



Looking Southeast - SW 4th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 29th Road	1	Roads	3	70	2600	No	No	Yes	2	City	Some	Yes	9	Yes	Yes	South of 3rd Ave mostly on SW	Dense tree canopy on SE end. Roundbout at 4th Avenue. Wide intersection on NW end.
SW 30th Road	1	Roads	3	70	2020	No	No	Yes	2	City	Some	Few	9	Yes	Yes	Mostly on NE	Sparse tree canopy on NW end. Wide intersection on NW end.

SW 29th Road
TYPOLOGY B

SW 30th Road
TYPOLOGY B

Street Tree Inventory

SW 29th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH RD	Foxtail Palm	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 29TH RD	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Tip Dieback	Dead Wood
SW 29TH RD	Bismark Palm	16-20"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Damaged Fronds	
SW 29TH RD	Bismark Palm	11-15"	No	15'		Good (61% to 80%)	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 29TH RD	Bottlebrush	11-15"	No	15'		Poor (21% to 40%)	Limb Damage - Major	Stubs with Sprouts	Sloughing Bark
SW 29TH RD	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 29TH RD	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 29TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 29TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Frizzled Fronds		
SW 29TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Frizzled Fronds		
SW 29TH RD	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Tapered Trunk	Nutrient Deficiency	Frizzled Fronds
SW 29TH RD	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Tapered Trunk	Nutrient Deficiency	Frizzled Fronds
SW 29TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Frizzled Fronds		
SW 29TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Frizzled Fronds	Nutrient Deficiency	
SW 29TH RD	Royal Palm	21-30"	No	20'		Fair (41% to 60%)	Frizzled Fronds	Nutrient Deficiency	
SW 29TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 29TH RD	Crepe Myrtle	16-20"	Yes	5'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Reduced Canopy - Moderate
SW 29TH RD	Crepe Myrtle	16-20"	No	10'		Poor (21% to 40%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 29TH RD	Solitaire Palm	1-5"	No	5'		Poor (21% to 40%)	Nutrient Deficiency	Damaged Fronds	Reduced Canopy - Moderate
SW 29TH RD	Frangipani	16-20"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Sprouting	
SW 29TH RD	Frangipani	16-20"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Sprouting	
SW 29TH RD	Dracaena sp.	11-15"	Yes	10'		Good (61% to 80%)			
SW 29TH RD	Queen Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Tamarind	11-15"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Grafted Branches
SW 29TH RD	Mahogany	6-10"	No	20'		Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	Epicormic Growth
SW 29TH RD	Mahogany	6-10"	No	20'		Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	Epicormic Growth
SW 29TH RD	Mahogany	6-10"	No	20'		Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	Epicormic Growth
SW 29TH RD	Queen Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 29TH RD	Queen Palm	11-15"	No	15'		Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Moderate	
SW 29TH RD	Coconut Palm	6-10"	No	25'		Good (61% to 80%)			
SW 29TH RD	Mahogany	1-5"	No	5'		Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	
SW 29TH RD	Gumbo Limbo	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 29TH RD	Black Olive	21-30"	No	55'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Decay Observed
SW 29TH RD	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Leader - Broken	Decay Observed
SW 29TH RD	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Tapered Trunk	Nutrient Deficiency	
SW 29TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Cavities	
SW 29TH RD	Coconut Palm	6-10"	No	15'		Poor (21% to 40%)	Nutrient Deficiency		
SW 29TH RD	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 29TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 29TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Coconut Palm	6-10"	No	25'		Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Peacock Flower	1-5"	Yes	10'		Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Epicormic Growth
SW 29TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 29TH RD	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 29TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 29th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH RD	Royal Poinciana	11-15"	No	35'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Epicormic Growth
SW 29TH RD	Royal Poinciana	16-20"	No	50'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 29TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 29TH RD	Mahogany	21-30"	No	55'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Decay Observed
SW 29TH RD	Mahogany	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Discolored Foliage
SW 29TH RD	Gumbo Limbo	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Cracks in Trunk	Stubs with Sprouts
SW 29TH RD	Mahogany	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Utility Pruned
SW 29TH RD	Mahogany	21-30"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Utility Pruned
SW 29TH RD	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)			
SW 29TH RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Trunk Damage - Moderate		
SW 29TH RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 29TH RD	Mahogany	31-40"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Dead Wood
SW 29TH RD	Black Olive	11-15"	No	30'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Topped	Epicormic Growth
SW 29TH RD	Black Olive	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 29TH RD	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 29TH RD	Sapodilla	21-30"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Utility Pruned	Decay Observed	Stubs with Sprouts
SW 29TH RD	Royal Poinciana	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Stubs with Sprouts
SW 29TH RD	Mahogany	31-40"	No	65'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Dead Wood
SW 29TH RD	Mahogany	31-40"	No	70'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 29TH RD	Foxtail Palm	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 29TH RD	Foxtail Palm	6-10"	No	10'	Utility Lines Above	Poor (21% to 40%)	Nutrient Deficiency	Reduced Canopy - Moderate	Frizzled Fronds
SW 29TH RD	Foxtail Palm	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Nutrient Deficiency	Reduced Canopy - Moderate	Frizzled Fronds
SW 29TH RD	Triangle Palm	16-20"	No	20'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Triangle Palm	16-20"	No	20'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Triangle Palm	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 29TH RD	Fishtail Palm	21-30"	Yes	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	Dead Wood
SW 29TH RD	Live Oak	16-20"	No	35'	Utility Lines Above	Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)	Grafted with Adjacent Tree
SW 29TH RD	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Damaged Fronds
SW 29TH RD	Christmas Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Live Oak	6-10"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Plunged	Restricted Canopy	Epicormic Growth
SW 29TH RD	Japanese Cheesewood	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Epicormic Growth
SW 29TH RD	Live Oak	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Insect Damage Leaves	Restricted Canopy	Epicormic Growth
SW 29TH RD	Gumbo Limbo	6-10"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Lifting	Reduced Canopy - Moderate	Grafted with Adjacent Tree
SW 29TH RD	Live Oak	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Plunged	Crown Density - Low	Grafted with Adjacent Tree
SW 29TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Epicormic Growth
SW 29TH RD	Mahogany	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Epicormic Growth
SW 29TH RD	Fishtail Palm	11-15"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Fishtail Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Fishtail Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 29TH RD	Fishtail Palm	6-10"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Fishtail Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Fishtail Palm	31-40"	Yes	30'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Fishtail Palm	31-40"	Yes	30'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Fishtail Palm	11-15"	Yes	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 29th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH RD	Fishtail Palm	11-15"	Yes	5'	Utility Line Conflict	Fair (41% to 60%)	Restricted Canopy	Suppressed Canopy	Dead Wood
SW 29TH RD	Fishtail Palm	16-20"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 29TH RD	Fishtail Palm	6-10"	Yes	Negligible	Utility Lines Adjacent (laterally)	Dead (0% to 5%)	Dead Meristem		
SW 29TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Live Oak	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Restricted Canopy	Apical Dieback	Epicormic Growth
SW 29TH RD	Gumbo Limbo	11-15"	No	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Topped	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 29TH RD	Gumbo Limbo	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Dead Wood	Epicormic Growth
SW 29TH RD	Gumbo Limbo	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Grafted with Adjacent Tree	Lifting	Epicormic Growth
SW 29TH RD	Gumbo Limbo	16-20"	No	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Grafted with Adjacent Tree	Lifting	Epicormic Growth
SW 29TH RD	Umbrella Tree	16-20"	Yes	20'	Utility Lines Above	Poor (21% to 40%)	Topped	Decay Observed	Stubs with Sprouts
SW 29TH RD	Gumbo Limbo	6-10"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Lifting	Broken Branches	Stubs with Sprouts
SW 29TH RD	Cabbage Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Live Oak	21-30"	No	55'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Epicormic Growth
SW 29TH RD	Live Oak	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 29TH RD	Live Oak	1-5"	No	Negligible	Utility Lines Above	Dead (0% to 5%)	Dead Wood	Crown Density - Very Low	Decay Observed
SW 29TH RD	Mahogany	1-5"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Epicormic Growth
SW 29TH RD	Live Oak	1-5"	No	5'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Plunged	Desiccated Foliage	Crown Density - Very Low
SW 29TH RD	Simpson's Stopper	11-15"	Yes	15'	Utility Lines Above	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Epicormic Growth
SW 29TH RD	Simpson's Stopper	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Epicormic Growth
SW 29TH RD	Simpson's Stopper	6-10"	Yes	15'	Utility Lines Above	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Epicormic Growth
SW 29TH RD	Mahogany	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Leader - Broken	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 29TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 29TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Damaged Fronds
SW 29TH RD	Mahogany	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Epicormic Growth	Restricted Canopy
SW 29TH RD	Bamboo Palm	21-30"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 29TH RD	Cabbage Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 29TH RD	Mahogany	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	Grafted with Adjacent Tree
SW 29TH RD	Mahogany	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 29TH RD	Mahogany	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Codominant Leaders/No Included Bark
SW 29TH RD	Black Olive	1-5"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Epicormic Growth
SW 29TH RD	Solitaire Palm	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	Suppressed Canopy
SW 29TH RD	Solitaire Palm	1-5"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 29TH RD	Solitaire Palm	1-5"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	Damaged Fronds
SW 29TH RD	Live Oak	16-20"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Lopsided/Moderately Reduced Canopy	Dead Wood	Crown Density - Excessive (Due to Epicormic Growth)
SW 29TH RD	Live Oak	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 29TH RD	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 29TH RD	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 29th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH RD	Solitaire Palm	1-5"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 29TH RD	Banana Tree	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 29TH RD	Pigeon Plum	11-15"	No	20'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Sprouting
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	Suppressed Canopy
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 29TH RD	Solitaire Palm	6-10"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 29TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 29TH RD	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	Suppressed Canopy
SW 29TH RD	Coconut Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	Suppressed Canopy
SW 29TH RD	Washington Palm	11-15"	No	5'		Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 29TH RD	Mahogany	21-30"	No	20'		Poor (21% to 40%)	Reduced Canopy - Major	Decay Observed	Epicormic Growth
SW 29TH RD	Pigeon Plum	6-10"	No	20'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Stubs with Sprouts
SW 29TH RD	Pigeon Plum	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 29TH RD	Live Oak	21-30"	No	45'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 29TH RD	Royal Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	Reduced Canopy - Moderate
SW 29TH RD	Live Oak	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Crown Density - Excessive (Due to Epicormic Growth)
SW 29TH RD	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 29TH RD	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 29TH RD	Mahogany	16-20"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/Included Bark
SW 29TH RD	Green Buttonwood	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	
SW 29TH RD	Mango	21-30"	No	30'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Utility Pruned
SW 29TH RD	Mahogany	6-10"	No	15'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 29TH RD	Mahogany	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 29TH RD	Mahogany	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Lopsided/Moderately Reduced Canopy
SW 29TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 29TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 29TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Horseflesh Mahogany	1-5"	No	10'		Fair (41% to 60%)	Crown Density - Low	Apical Dieback	Epicormic Growth
SW 29TH RD	Royal Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 29TH RD	Horseflesh Mahogany	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 29TH RD	Green Buttonwood	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	
SW 29TH RD	Horseflesh Mahogany	1-5"	No	10'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Epicormic Growth
SW 29TH RD	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Discolored Foliage
SW 29TH RD	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Apical Dieback
SW 29TH RD	Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Apical Dieback

(Continued on Next Page)

Street Tree Inventory

SW 29th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 29TH RD	Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Apical Dieback
SW 29TH RD	Mahogany	11-15"	No	20'		Poor (21% to 40%)	Trunk Damage - Major	Limb Damage - Moderate	Epicormic Growth
SW 29TH RD	Mahogany	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 29TH RD	Black Olive	21-30"	No	55'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 29TH RD	Black Olive	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 29TH RD	Black Olive	21-30"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 29TH RD	Black Olive	21-30"	No	55'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 29TH RD	Black Olive	41-50"	No	65'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 29TH RD	Black Olive	21-30"	No	60'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 29TH RD	Mahogany	21-30"	No	40'		Fair (41% to 60%)	Trunk Damage - Moderate	Cavities	Epicormic Growth
SW 29TH RD	Mahogany	11-15"	No	20'		Poor (21% to 40%)	Crown Density - Low	Lopsided/Moderately Reduced Canopy	Dead Wood
SW 29TH RD	Mahogany	16-20"	No	35'		Poor (21% to 40%)	Discolored Foliage	Apical Dieback	Epicormic Growth
SW 29TH RD	Mahogany	21-30"	No	45'		Fair (41% to 60%)	Discolored Foliage	Apical Dieback	Vine Cover - Heavy
SW 29TH RD	Pongam	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Insect Damage Leaves	Epicormic Growth
SW 29TH RD	Pongam	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Insect Damage Leaves	Sprouting
SW 29TH RD	Mahogany	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Dead Wood
SW 29TH RD	Vera Wood	6-10"	No	20'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 29TH RD	Vera Wood	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Leaning - Moderate
SW 29TH RD	Vera Wood	6-10"	No	15'		Fair (41% to 60%)	Discolored Foliage	Codominant Leaders/No Included Bark	Epicormic Growth
SW 29TH RD	Pink Tabebuia	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 29TH RD	Live Oak	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 29TH RD	Live Oak	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 29TH RD	Live Oak	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 29TH RD	Frangipani	6-10"	No	15'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Trunk Damage - Minor	Restricted Canopy
SW 29TH RD	Mango	21-30"	No	40'		Fair (41% to 60%)	Basal Co-Dominant	Adjacent Concrete Damage	Stubs with Sprouts
SW 29TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 29TH RD	Hong Kong Orchid	21-30"	Yes	20'		Poor (21% to 40%)	Leader - Broken	Stubs with Sprouts	Decay Observed
SW 29TH RD	Black Olive	31-40"	No	55'		Fair (41% to 60%)	Root Damage/Decay	Stubs with Sprouts	Broken Branches
SW 29TH RD	Black Olive	31-40"	No	60'		Poor (21% to 40%)	Constricted Roots	Stubs with Sprouts	Decay Observed
SW 29TH RD	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Adjacent Concrete Damage	Trunk Damage - Major	Decay Observed

SW 30th Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 30TH RD	Gumbo Limbo	11-15"	No	20'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Restricted Canopy
SW 30TH RD	Gumbo Limbo	6-10"	No	10'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 30TH RD	Royal Poinciana	21-30"	No	60'	Utility Line Conflict	Fair (41% to 60%)	Limb Damage - Moderate	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 30TH RD	Royal Poinciana	21-30"	No	60'		Poor (21% to 40%)	Girdling Roots	Trunk Damage - Major	Crown Density - Very Low
SW 30TH RD	Royal Poinciana	16-20"	No	40'		Fair (41% to 60%)	Lifting	Cavities	Stubs with Sprouts
SW 30TH RD	Royal Poinciana	21-30"	No	45'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Cavities	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 30th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 30TH RD	Gumbo Limbo	1-5"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Grafted with Adjacent Tree	Restricted Canopy
SW 30TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 30TH RD	Starburst Clerodendron	1-5"	No	5'		Poor (21% to 40%)	Basal Co-Dominant	Crown Density - Low	Grafted Branches
SW 30TH RD	Starburst Clerodendron	1-5"	Yes	10'		Good (61% to 80%)	Dead Wood	Grafted Branches	Restricted Canopy
SW 30TH RD	Starburst Clerodendron	1-5"	No	5'		Good (61% to 80%)	Broken Branches	Stubs with Sprouts	Restricted Canopy
SW 30TH RD	Starburst Clerodendron	6-10"	Yes	10'		Good (61% to 80%)	Grafted Branches	Restricted Canopy	
SW 30TH RD	Frangipani	1-5"	No	5'		Fair (41% to 60%)	Crown Density - Low	Sprouting	Restricted Canopy
SW 30TH RD	Frangipani	1-5"	No	10'		Fair (41% to 60%)	Crown Density - Low	Sprouting	
SW 30TH RD	Frangipani	1-5"	No	10'		Poor (21% to 40%)	Crown Density - Very Low	Sprouting	Broken Branches
SW 30TH RD	Jacaranda	6-10"	No	30'		Fair (41% to 60%)	Broken Branches	Stubs with Sprouts	Discolored Foliage
SW 30TH RD	Mahogany	41-50"	No	55'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 30TH RD	Vera Wood	1-5"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Trunk Damage - Minor
SW 30TH RD	Mahogany	1-5"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Trunk Damage - Minor
SW 30TH RD	Japanese Fern Tree	1-5"	No	5'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 30TH RD	Japanese Fern Tree	1-5"	No	5'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 30TH RD	Japanese Fern Tree	1-5"	No	5'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 30TH RD	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 30TH RD	Mulberry	60+"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Restricted Canopy	Stubs with Sprouts
SW 30TH RD	Frangipani	6-10"	No	5'		Fair (41% to 60%)	Crown Density - Low	Sprouting	Restricted Canopy
SW 30TH RD	Peregrina	6-10"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 30TH RD	Gumbo Limbo	1-5"	No	5'		Fair (41% to 60%)	Lifting	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 30TH RD	Gumbo Limbo	1-5"	No	5'		Fair (41% to 60%)	Lifting	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 30TH RD	Gumbo Limbo	1-5"	No	5'		Fair (41% to 60%)	Lifting	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 30TH RD	Gumbo Limbo	1-5"	No	10'		Fair (41% to 60%)	Lifting	Codominant Leaders/No Included Bark	Restricted Canopy
SW 30TH RD	Live Oak	11-15"	No	35'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Grafted Branches
SW 30TH RD	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Epicormic Growth
SW 30TH RD	Manila Tamarind	1-5"	No	15'		Good (61% to 80%)	Codominant Leaders/Included Bark	Restricted Canopy	Epicormic Growth
SW 30TH RD	Gumbo Limbo	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Epicormic Growth
SW 30TH RD	Peregrina	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Limb Damage - Moderate
SW 30TH RD	Peregrina	6-10"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Stubs with Sprouts	Grafted with Adjacent Tree
SW 30TH RD	Peregrina	11-15"	Yes	10'		Good (61% to 80%)	Grafted Branches	Restricted Canopy	Sprouting
SW 30TH RD	Live Oak	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth
SW 30TH RD	Solitaire Palm	6-10"	Yes	15'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 30TH RD	Solitaire Palm	6-10"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 30TH RD	Solitaire Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 30TH RD	Solitaire Palm	6-10"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 30TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 30TH RD	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Damaged Fronds
SW 30TH RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		

(Continued on Next Page)

Street Tree Inventory

SW 30th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 30TH RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 30TH RD	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 30TH RD	Indian Laurel Fig	51-60"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts	Broken Branches
SW 30TH RD	Mahogany	16-20"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 30TH RD	Mahogany	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 30TH RD	Brazilian Beauty Leaf	11-15"	No	20'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 30TH RD	Brazilian Beauty Leaf	11-15"	No	20'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 30TH RD	Royal Poinciana	21-30"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 30TH RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 30TH RD	Royal Poinciana	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 30TH RD	Green Buttonwood	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Pruned Into Shrub	Codominant Leaders/No Included Bark	Epicormic Growth
SW 30TH RD	Green Buttonwood	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Codominant Leaders/No Included Bark	Epicormic Growth
SW 30TH RD	Weeping Fig	41-50"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Grafted Branches
SW 30TH RD	Vera Wood	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 30TH RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 30TH RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 30TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 30TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 30TH RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 30TH RD	Frangipani	1-5"	No	10'		Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	Sprouting
SW 30TH RD	Frangipani	1-5"	No	15'		Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	Sprouting
SW 30TH RD	Gumbo Limbo	6-10"	No	5'		Poor (21% to 40%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 30TH RD	Sylvester Date Palm	16-20"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 30TH RD	Sylvester Date Palm	11-15"	No	20'		Good (61% to 80%)			
SW 30TH RD	Bamboo Palm	1-5"	Yes	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 30TH RD	Bamboo Palm	1-5"	Yes	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 30TH RD	Bamboo Palm	6-10"	Yes	5'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 30TH RD	Tamarind	21-30"	No	40'		Good (61% to 80%)	Stubs with Sprouts	Codominant Leaders/No Included Bark	Grafted Branches
SW 30TH RD	Bottlebrush	31-40"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Decay Observed	Sprouting	Ficus Growing on Tree
SW 30TH RD	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Low
SW 30TH RD	Horseflesh Mahogany	1-5"	No	5'		Poor (21% to 40%)	Crown Density - Low	Apical Dieback	Epicormic Growth
SW 30TH RD	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 30TH RD	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 30TH RD	Coconut Palm	11-15"	No	15'		Fair (41% to 60%)	Nutrient Deficiency	Reduced Canopy - Minor	
SW 30TH RD	Frangipani	6-10"	No	20'		Fair (41% to 60%)	Basal Co-Dominant	Crown Density - Low	Sprouting
SW 30TH RD	Frangipani	6-10"	No	20'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Crown Density - Low	Sprouting
SW 30TH RD	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 30TH RD	Gumbo Limbo	21-30"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Stubs with Sprouts
SW 30TH RD	Black Olive	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Topped	Decay Observed
SW 30TH RD	Black Olive	21-30"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Dead Wood	Topped	Stubs with Sprouts
SW 30TH RD	Coconut Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 30TH RD	Jacaranda	6-10"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Topped	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 30TH RD	Royal Poinciana	11-15"	No	50'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 30TH RD	Mahogany	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Discolored Foliage
SW 30TH RD	Mahogany	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Topped	Stubs with Sprouts	Discolored Foliage
SW 30TH RD	Mahogany	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 30th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 30TH RD	Japanese Privet	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Strap Constricting Tree	Codominant Leaders/No Included Bark	
SW 30TH RD	Gumbo Limbo	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 30TH RD	Gumbo Limbo	6-10"	No	30'	Utility Line Conflict	Good (61% to 80%)	Utility Pruned	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 30TH RD	Gumbo Limbo	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Topped	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 30TH RD	Gumbo Limbo	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 30TH RD	Areca Palm	31-40"	Yes	10'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 30TH RD	Areca Palm	41-50"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 30TH RD	Areca Palm	41-50"	Yes	15'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 30TH RD	Weeping Fig	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 30TH RD	Weeping Fig	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Compromised Tension Roots	Decay Observed	Stubs with Sprouts
SW 30TH RD	Cabbage Palm	21-30"	No	5'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Nutrient Deficiency	Ficus Growing on Tree	Lopsided/Significantly Reduced Canopy
SW 30TH RD	Simpson's Stopper	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 30TH RD	Simpson's Stopper	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/Included Bark	Strap Constricting Tree
SW 30TH RD	Weeping Fig	16-20"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 30TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 30TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 30TH RD	Gumbo Limbo	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Grafted with Adjacent Tree
SW 30TH RD	Cabbage Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 30TH RD	Christmas Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 30TH RD	Royal Poinciana	6-10"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Cracks in Trunk	Broken Branches	Stubs with Sprouts
SW 30TH RD	Live Oak	16-20"	No	30'	Utility Lines Above	Poor (21% to 40%)	Girdling Roots	Crown Density - Excessive (Due to Epicormic Growth)	Lopsided/Moderately Reduced Canopy
SW 30TH RD	Gumbo Limbo	6-10"	No	20'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 30TH RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Adjacent Light Pole		
SW 30TH RD	Green Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 30TH RD	Green Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/Included Bark	Epicormic Growth
SW 30TH RD	Live Oak	31-40"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Trunk Damage - Major	Epicormic Growth
SW 30TH RD	Black Olive	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 30TH RD	Podocarpus	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Adjacent Light Pole	
SW 30TH RD	Orange Geiger	6-10"	No	10'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Epicormic Growth
SW 30TH RD	Queen Crepe Myrtle	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Seasonal Defoliation/Discolored Foliage	Epicormic Growth
SW 30TH RD	Queen Crepe Myrtle	6-10"	No	15'	Utility Lines Above	Fair (41% to 60%)	Trunk Damage - Moderate	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 30TH RD	Queen Crepe Myrtle	1-5"	No	15'	Utility Lines Above	Fair (41% to 60%)	Plunged	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 30TH RD	Queen Crepe Myrtle	1-5"	No	15'	Utility Lines Above	Fair (41% to 60%)	Plunged	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 30TH RD	Mahogany	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 30TH RD	Mahogany	6-10"	No	20'		Poor (21% to 40%)	Plunged	Epicormic Growth	Lopsided/Moderately Reduced Canopy
SW 30TH RD	Weeping Fig	21-30"	No	50'		Fair (41% to 60%)	Decay Observed	Epicormic Growth	Restricted Canopy
SW 30TH RD	Dotted Lancepod	1-5"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 30TH RD	Hurricane Palm	6-10"	No	10'		Good (61% to 80%)			
SW 30TH RD	Royal Poinciana	21-30"	No	50'		Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 30TH RD	Royal Palm	16-20"	No	20'		Good (61% to 80%)			
SW 30TH RD	Royal Palm	16-20"	No	25'		Good (61% to 80%)			

(Continued on Next Page)

Street Tree Inventory

SW 30th Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 30TH RD	Vera Wood	1-5"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 30TH RD	Vera Wood	1-5"	No	10'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 30TH RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 30TH RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 30TH RD	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			

Roads



Looking Northwest - SW 1st Avenue



Looking Northwest - SW 3rd Avenue



Looking Northwest - SW 1st Avenue



Looking Northwest - SW 3rd Avenue



Looking Southeast - SW 3rd Avenue



Looking Southeast - SW 12th Avenue



Looking Southeast - SW 3rd Avenue



Looking Southeast - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 31st Road	1	Roads	3	50	1700	No	No	Yes	2	City	Some	Some	5	Yes	Yes	Mostly on SW	One-way NW on south side of 3rd Avenue.Round-about at 4th Avenue.
SW 32nd Road	1	Roads	3	50	750	No	Yes	No	2	City	Yes	Yes	5 (15 S of 3rd Ave)	Yes	Yes	Mostly on NE	Segmented at 3rd Avenue. Viscaya metrorail station on SE end.

SW 31st Road
TYPOLOGY B

SW 32nd Road
TYPOLOGY B

Street Tree Inventory

SW 31st Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 31ST RD	Bismark Palm	16-20"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 31ST RD	Live Oak	11-15"	No	20'		Poor (21% to 40%)	Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Tip Dieback
SW 31ST RD	Live Oak	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Improperly Mulched	Lopsided/Reduced Canopy - Major	Tip Dieback
SW 31ST RD	Mahogany	11-15"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 31ST RD	Japanese Privet	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Tip Dieback	Epicormic Growth	Pruned Into Shrub
SW 31ST RD	Chinese Fan Palm	16-20"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 31ST RD	Mahogany	31-40"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 31ST RD	Sylvester Date Palm	11-15"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 31ST RD	Christmas Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 31ST RD	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 31ST RD	Black Olive	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 31ST RD	Black Olive	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 31ST RD	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 31ST RD	Black Olive	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Topped
SW 31ST RD	Mahogany	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Topped
SW 31ST RD	Crepe Myrtle	1-5"	Yes	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Seasonal Defoliation/Discolored Foliage	Desiccated Foliage
SW 31ST RD	Crepe Myrtle	1-5"	Yes	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Very Low	Seasonal Defoliation/Discolored Foliage	Desiccated Foliage
SW 31ST RD	Crepe Myrtle	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	
SW 31ST RD	Gumbo Limbo	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Grafted with Adjacent Tree	Codominant Leaders/No Included Bark	Epicormic Growth
SW 31ST RD	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Grafted with Adjacent Tree		
SW 31ST RD	Papaya	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Vine Cover - Heavy
SW 31ST RD	Hibiscus sp.	11-15"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Uprooted - Partially	Leaning - Moderate	Epicormic Growth
SW 31ST RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 31ST RD	Solitaire Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 31ST RD	Frangipani	6-10"	Yes	5'	Utility Lines Above	Fair (41% to 60%)	Crown Density - Low	Sprouting	
SW 31ST RD	Japanese Privet	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Grafted Branches	Sprouting
SW 31ST RD	Japanese Privet	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Grafted Branches	Suppressed Canopy
SW 31ST RD	Mahogany	21-30"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 31ST RD	Mahogany	31-40"	No	50'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 31ST RD	Black Olive	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 31ST RD	Black Olive	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 31ST RD	Areca Palm	16-20"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 31ST RD	Areca Palm	16-20"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 31ST RD	Areca Palm	16-20"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 31ST RD	Areca Palm	16-20"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 31ST RD	Areca Palm	16-20"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 31ST RD	Christmas Palm	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 31ST RD	Christmas Palm	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 31ST RD	Live Oak	11-15"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 31ST RD	Royal Palm	11-15"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency	Lopsided/Significantly Reduced Canopy	Frizzled Fronds
SW 31ST RD	Live Oak	6-10"	No	25'	Utility Lines Above	Poor (21% to 40%)	Improperly Mulched	Lopsided/Significantly Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)
SW 31ST RD	Live Oak	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Improperly Mulched	Lopsided/Significantly Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)
SW 31ST RD	Live Oak	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 31ST RD	Live Oak	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Plunged	Crown Density - Excessive (Due to Epicormic Growth)

(Continued on Next Page)

Street Tree Inventory

SW 31st Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 31ST RD	Live Oak	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Plunged	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 31ST RD	Coconut Palm	21-30"	Yes	30'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Damaged Fronds	
SW 31ST RD	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 31ST RD	Coconut Palm	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned	Damaged Fronds	Nutrient Deficiency
SW 31ST RD	Royal Poinciana	16-20"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth
SW 31ST RD	Royal Poinciana	21-30"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Adjacent Concrete Damage	Cavities
SW 31ST RD	Royal Poinciana	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Stubs with Sprouts
SW 31ST RD	Mahogany	6-10"	No	25'		Poor (21% to 40%)	Constricted Roots	Lateral Branching - None	Epicormic Growth
SW 31ST RD	Gumbo Limbo	6-10"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 31ST RD	Royal Poinciana	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 31ST RD	Live Oak	11-15"	No	30'		Fair (41% to 60%)	Plunged	Codominant Leaders/No Included Bark	Epicormic Growth
SW 31ST RD	Cabada Palm	31-40"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 31ST RD	Japanese Privet	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Pruned Into Shrub	Stubs with Sprouts	Grafted Branches
SW 31ST RD	Japanese Privet	6-10"	Yes	10'		Fair (41% to 60%)	Pruned Into Shrub	Stubs with Sprouts	Crown Density - Low
SW 31ST RD	Japanese Privet	11-15"	Yes	10'		Good (61% to 80%)	Pruned Into Shrub	Stubs with Sprouts	Dead Wood
SW 31ST RD	Japanese Privet	6-10"	Yes	5'		Fair (41% to 60%)	Pruned Into Shrub	Discolored Foliage	Epicormic Growth
SW 31ST RD	Coconut Palm	6-10"	No	10'		Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	
SW 31ST RD	Chinese Fan Palm	16-20"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 31ST RD	Chinese Fan Palm	11-15"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 31ST RD	Areca Palm	60+"	Yes	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 31ST RD	Vera Wood	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Strap Constricting Tree
SW 31ST RD	Areca Palm	21-30"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 31ST RD	Areca Palm	41-50"	Yes	20'		Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 31ST RD	Bottle Palm	11-15"	No	10'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 31ST RD	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 31ST RD	Pink Tabebuia	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Insect Damage Leaves	Codominant Leaders/No Included Bark
SW 31ST RD	Pink Tabebuia	1-5"	No	5'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/Included Bark	
SW 31ST RD	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 31ST RD	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 31ST RD	Mahogany	41-50"	No	60'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 31ST RD	Mahogany	41-50"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 31ST RD	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 31ST RD	Black Olive	21-30"	No	55'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Grafted Branches	Broken Branches
SW 31ST RD	Coconut Palm	16-20"	No	25'		Good (61% to 80%)			
SW 31ST RD	Coconut Palm	11-15"	No	25'		Good (61% to 80%)			
SW 31ST RD	Pink Tabebuia	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 31ST RD	Mahogany	31-40"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 31ST RD	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 31ST RD	Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 31ST RD	Black Olive	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Epicormic Growth
SW 31ST RD	Black Olive	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Root Damage/Decay	Decay Observed	Stubs with Sprouts
SW 31ST RD	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Over Pruned		
SW 31ST RD	Coconut Palm	11-15"	No	20'		Poor (21% to 40%)	Over Pruned	Nutrient Deficiency	Frizzled Fronds
SW 31ST RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Frizzled Fronds
SW 31ST RD	Pygmy Date Palm	1-5"	No	10'		Good (61% to 80%)			
SW 31ST RD	Pygmy Date Palm	11-15"	Yes	15'		Good (61% to 80%)			
SW 31ST RD	Pygmy Date Palm	6-10"	Yes	15'		Good (61% to 80%)			
SW 31ST RD	Pygmy Date Palm	1-5"	No	10'		Good (61% to 80%)			
SW 31ST RD	Sylvester Date Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency		

Street Tree Inventory

SW 32nd Road

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 32ND RD	Live Oak	11-15"	Yes	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Stubs with Sprouts
SW 32ND RD	Live Oak	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Epicormic Growth
SW 32ND RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 32ND RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 32ND RD	Live Oak	6-10"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 32ND RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 32ND RD	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 32ND RD	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Over Pruned	Nutrient Deficiency	
SW 32ND RD	Live Oak	6-10"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback	Codominant Leaders/No Included Bark
SW 32ND RD	Live Oak	6-10"	No	20'		Fair (41% to 60%)	Epicormic Growth	Apical Dieback	Codominant Leaders/No Included Bark
SW 32ND RD	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 32ND RD	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 32ND RD	Mahogany	51-60"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Leader - Broken	Lopsided/Significantly Reduced Canopy
SW 32ND RD	Cabbage Palm	21-30"	No	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Damaged Fronds	Ficus Growing on Tree
SW 32ND RD	Weeping Fig	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Codominant Leaders/No Included Bark	Epicormic Growth
SW 32ND RD	Weeping Fig	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Pruned Into Shrub	Basal Co-Dominant	Epicormic Growth
SW 32ND RD	Weeping Fig	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Pruned Into Shrub	Leader - Broken	Decay Observed
SW 32ND RD	Weeping Fig	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Codominant Leaders/No Included Bark	Epicormic Growth
SW 32ND RD	Weeping Fig	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Suppressed Canopy	Epicormic Growth
SW 32ND RD	Live Oak	31-40"	No	65'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Epicormic Growth
SW 32ND RD	Green Buttonwood	1-5"	No	15'	Utility Lines Above	Fair (41% to 60%)	Plunged	Sprouting	Codominant Leaders/No Included Bark
SW 32ND RD	Green Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Strap Constricting Tree	Sprouting	Codominant Leaders/No Included Bark
SW 32ND RD	Green Buttonwood	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Plunged	Sprouting	Codominant Leaders/No Included Bark
SW 32ND RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted with Adjacent Tree	Vine Cover - Heavy	
SW 32ND RD	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	Adjacent Light Pole
SW 32ND RD	Brazilian Pepper	6-10"	No	30'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Vine Cover - Heavy
SW 32ND RD	Weeping Fig	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Decay Observed	Sprouting	Restricted Canopy
SW 32ND RD	Weeping Fig	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Decay Observed	Sprouting	Restricted Canopy
SW 32ND RD	Unidentified Dead Tree (Defoliated)	11-15"	No	Negligible		Dead (0% to 5%)	Decay Observed	Dead Wood	Disease
SW 32ND RD	Mahogany	11-15"	No	40'		Poor (21% to 40%)	Limb Damage - Moderate	Discolored Foliage	Epicormic Growth
SW 32ND RD	Gumbo Limbo	6-10"	No	15'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 32ND RD	Gumbo Limbo	11-15"	No	25'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 32ND RD	Gumbo Limbo	11-15"	No	30'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Epicormic Growth
SW 32ND RD	Gumbo Limbo	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Broken Branches
SW 32ND RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 32ND RD	Chinese Fan Palm	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 32ND RD	Gumbo Limbo	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 32ND RD	Mahogany	6-10"	Yes	5'	Utility Lines Above	Fair (41% to 60%)	Topped	Stubs with Sprouts	Restricted Canopy
SW 32ND RD	Gumbo Limbo	16-20"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Vine Cover - Heavy
SW 32ND RD	Mahogany	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Grafted with Adjacent Tree	Stubs with Sprouts
SW 32ND RD	Mahogany	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Topped	Vine Cover - Heavy	Stubs with Sprouts
SW 32ND RD	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	Suppressed Canopy
SW 32ND RD	Polyscias sp.	6-10"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	
SW 32ND RD	Polyscias sp.	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Vine Cover - Heavy		

(Continued on Next Page)

Street Tree Inventory

SW 32nd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 32ND RD	Advocado	21-30"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Leader - Broken	Vine Cover - Heavy	Epicormic Growth
SW 32ND RD	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 32ND RD	Christmas Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 32ND RD	Banana Tree	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 32ND RD	Banana Tree	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	Leaning - Minor
SW 32ND RD	Banana Tree	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	Reduced Canopy - Moderate
SW 32ND RD	Banana Tree	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	
SW 32ND RD	Cabbage Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Damaged Fronds	Suppressed Canopy
SW 32ND RD	Washington Palm	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Damaged Fronds	Suppressed Canopy
SW 32ND RD	Washington Palm	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Damaged Fronds	Suppressed Canopy
SW 32ND RD	Washington Palm	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Damaged Fronds	Grafted with Adjacent Tree
SW 32ND RD	Washington Palm	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Damaged Fronds	Suppressed Canopy
SW 32ND RD	Black Olive	21-30"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Vine Cover - Heavy	Decay Observed	Stubs with Sprouts
SW 32ND RD	Black Olive	31-40"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Limb Damage - Major	Decay Observed	Dead Wood
SW 32ND RD	Brazilian Pepper	16-20"	Yes	20'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Limb Damage - Major	Sprouting
SW 32ND RD	Mahogany	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Topped	Stubs with Sprouts	Restricted Canopy
SW 32ND RD	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Suppressed Canopy
SW 32ND RD	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Suppressed Canopy
SW 32ND RD	Mahogany	1-5"	No	15'	Utility Lines Above	Fair (41% to 60%)	Restricted Canopy	Epicormic Growth	Lopsided/Moderately Reduced Canopy
SW 32ND RD	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lifting	Restricted Canopy	Suppressed Canopy
SW 32ND RD	Aralia sp.	11-15"	Yes	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Grafted with Adjacent Tree
SW 32ND RD	Aralia sp.	6-10"	No	5'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Restricted Canopy
SW 32ND RD	Aralia sp.	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Insect Damage Leaves	Restricted Canopy	Suppressed Canopy
SW 32ND RD	Aralia sp.	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Insect Damage Leaves	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 32ND RD	Aralia sp.	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Suppressed Canopy
SW 32ND RD	Aralia sp.	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Suppressed Canopy
SW 32ND RD	Aralia sp.	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Suppressed Canopy
SW 32ND RD	Aralia sp.	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Epicormic Growth
SW 32ND RD	Aralia sp.	6-10"	Yes	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted with Adjacent Tree	Restricted Canopy	Epicormic Growth
SW 32ND RD	Aralia sp.	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Epicormic Growth
SW 32ND RD	Aralia sp.	6-10"	Yes	5'	Utility Lines Above	Fair (41% to 60%)	Decay Observed	Restricted Canopy	Epicormic Growth
SW 32ND RD	Aralia sp.	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Restricted Canopy	Epicormic Growth
SW 32ND RD	Aralia sp.	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Restricted Canopy	Epicormic Growth
SW 32ND RD	Aralia sp.	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Restricted Canopy	Epicormic Growth
SW 32ND RD	Aralia sp.	6-10"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted with Adjacent Tree	Restricted Canopy	Epicormic Growth
SW 32ND RD	Aralia sp.	6-10"	No	5'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Epicormic Growth
SW 32ND RD	Christmas Palm	16-20"	Yes	20'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 32ND RD	Pongam	6-10"	No	15'	Utility Lines Above	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Epicormic Growth
SW 32ND RD	Pongam	6-10"	No	15'	Utility Lines Above	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Restricted Canopy	Epicormic Growth
SW 32ND RD	Mahogany	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Epicormic Growth	Restricted Canopy	
SW 32ND RD	Mahogany	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Epicormic Growth	Restricted Canopy	Codominant Leaders/No Included Bark
SW 32ND RD	Live Oak	31-40"	Yes	60'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Vine Cover - Heavy
SW 32ND RD	Mahogany	31-40"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Lopsided/Significantly Reduced Canopy	Ficus Growing on Tree
SW 32ND RD	Mahogany	6-10"	No	15'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant with Adjacent Tree(s)	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 32ND RD	Gumbo Limbo	1-5"	No	20'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant with Adjacent Tree(s)	Basal Co-Dominant	Epicormic Growth
SW 32ND RD	Coconut Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 32nd Road (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 32ND RD	Coconut Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 32ND RD	Coconut Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 32ND RD	Coconut Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 32ND RD	Mahogany	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Root Damage/Decay	Decay Observed	Stubs with Sprouts
SW 32ND RD	Mahogany	31-40"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 32ND RD	Mahogany	51-60"	No	70'		Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Stubs with Sprouts
SW 32ND RD	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Damaged Fronds	Suppressed Canopy
SW 32ND RD	Pink Tabebuia	1-5"	No	15'	Utility Lines Above	Poor (21% to 40%)	Apical Dieback	Galls	Epicormic Growth
SW 32ND RD	Pink Tabebuia	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Apical Dieback	Galls	Stubs with Sprouts
SW 32ND RD	Longan	11-15"	No	40'	Utility Line Conflict	Good (61% to 80%)	Adjacent Concrete Damage	Grafted Branches	Stubs with Sprouts
SW 32ND RD	Christmas Palm	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)			
SW 32ND RD	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 32ND RD	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 32ND RD	Cabbage Palm	11-15"	No	5'	Utility Line Conflict	Poor (21% to 40%)	Reduced Canopy - Moderate	Nutrient Deficiency	Ficus Growing on Tree
SW 32ND RD	Mahogany	31-40"	No	55'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches

Streets



Looking West - SW 10th Avenue



Looking West - SW 11th Avenue



Looking West - SW 9th Avenue



Looking West - SW 11th Avenue



Looking East - SW 11th Avenue



Looking East - SW 12th Avenue



Looking East - SW 11th Avenue



Looking East - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 12th Street	1	Roads	3	50	970	No	No	Yes	2	City	Few	No	6 (Only at intersections)	No	Yes	Mostly on North	Lacking tree canopy. Vegetated curb extensions (bulb outs) at intersections. Valley gutters between street and parking East of 11th Avenue
SW 13th Street	1	Roads	3	65	875	No	No	Yes	2	City	Some	Few	9 (south side) 4 (north side)	Yes	Yes	Mostly on North	Vegetated curb extensions (bulb outs) at intersections

SW 12th Street
TYPOLOGY D

SW 13th Street
TYPOLOGY B

Street Tree Inventory

SW 12th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH ST	Jamaican Dogwood	11-15"	No	15'		Fair (41% to 60%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed
SW 12TH ST	Jamaican Dogwood	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Limb Damage - Moderate
SW 12TH ST	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 12TH ST	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)			
SW 12TH ST	Gumbo Limbo	16-20"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Grafted Branches	Sprouting
SW 12TH ST	Jamaican Dogwood	16-20"	No	25'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Trunk Damage - Moderate	Decay Observed	Lopsided/Reduced Canopy - Moderate
SW 12TH ST	Rubber Tree	41-50"	No	25'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Grafted Branches
SW 12TH ST	Weeping Fig	41-50"	No	30'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed

SW 13th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Queen Palm	6-10"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 13TH ST	Washington Palm	11-15"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 13TH ST	Washington Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency	Damaged Fronds	
SW 13TH ST	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Damaged Fronds
SW 13TH ST	Christmas Palm	11-15"	Yes	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Damaged Fronds
SW 13TH ST	Silver Buttonwood	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Pruned Into Shrub	Codominant Leaders/No Included Bark
SW 13TH ST	Silver Buttonwood	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Pruned Into Shrub	Codominant Leaders/No Included Bark
SW 13TH ST	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 13TH ST	White Frangipani	16-20"	Yes	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Topped	Stubs with Sprouts	Decay Observed
SW 13TH ST	Royal Poinciana	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 13TH ST	Mahogany	31-40"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)
SW 13TH ST	Mahogany	21-30"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 13TH ST	Mahogany	21-30"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 13TH ST	Coconut Palm	11-15"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Over Pruned	Nutrient Deficiency	Damaged Fronds
SW 13TH ST	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Over Pruned		
SW 13TH ST	Starburst Clerodendron	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Dead Wood
SW 13TH ST	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 13TH ST	Spanish Cherry	21-30"	No	30'		Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Stubs with Sprouts
SW 13TH ST	Pitch Apple	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Leader - Broken	Epicormic Growth
SW 13TH ST	Pitch Apple	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Grafted with Adjacent Tree
SW 13TH ST	Black Olive	31-40"	No	55'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 13TH ST	Black Olive	21-30"	No	45'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 13TH ST	Black Olive	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Lopsided/Moderately Reduced Canopy
SW 13TH ST	Black Olive	21-30"	No	45'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Ficus Growing on Tree
SW 13TH ST	Black Olive	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 13TH ST	Black Olive	31-40"	No	50'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 13TH ST	Pitch Apple	6-10"	No	25'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 13TH ST	Pitch Apple	11-15"	No	30'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Restricted Canopy
SW 13TH ST	Silver Buttonwood	6-10"	No	10'		Poor (21% to 40%)	Basal Co-Dominant	Trunk Damage - Major	Pruned Into Shrub
SW 13TH ST	Silver Buttonwood	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/Included Bark	Sprouting	Leaning - Moderate
SW 13TH ST	Black Olive	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 13TH ST	Black Olive	21-30"	No	45'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 13TH ST	Black Olive	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 13TH ST	Mahogany	31-40"	No	55'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 13TH ST	Mahogany	31-40"	No	55'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Stubs with Sprouts
SW 13TH ST	Silver Buttonwood	11-15"	No	15'		Good (61% to 80%)	Codominant Leaders/Included Bark	Epicormic Growth	Leaning - Moderate

(Continued on Next Page)

Street Tree Inventory

SW 13th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 13TH ST	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 13TH ST	Weeping Fig	21-30"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Decay Observed	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 13TH ST	Queen Palm	6-10"	No	5'		Poor (21% to 40%)	Nutrient Deficiency	Reduced Canopy - Moderate	Suppressed Canopy
SW 13TH ST	Silk Floss Tree	6-10"	No	15'		Fair (41% to 60%)	Crown Density - Low	Sprouting	Codominant Leaders/No Included Bark
SW 13TH ST	Wax Myrtle	1-5"	No	10'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Sprouting

Streets | Terraces



Looking West - SW 1st Avenue



Looking West - SW 16th Avenue



Looking West - SW 3rd Avenue



Looking West - Center of Terrace




Looking East - SW 16th Avenue



Looking East - SW 17th Avenue



Looking East - Center of Terrace



Looking East - SW 16th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 23rd Street	1	Roads	3	50	1750	No	No	Yes	2	City	Some	Some	5	Yes	Yes	Mostly on North	No Curbs between 17th and 16th Ave
SW 23rd Terrace	1	Roads	3	50	420	No	No	Yes	2	City	Some	Few	5	Yes	Yes	Some	Traffic islands on both segments facing 3rd Avenue. West end merges with 1st Avenue

SW 23rd Street

TYPOLOGY B

SW 23rd Terrace

TYPOLOGY B

Street Tree Inventory

SW 23rd Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD ST	Black Olive	11-15"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 23RD ST	Pigeon Plum	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Strap Constricting Tree
SW 23RD ST	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD ST	Mahogany	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD ST	Mahogany	41-50"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Ficus Growing on Tree
SW 23RD ST	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Apical Dieback	Crown Density - Low	Epicormic Growth
SW 23RD ST	Yellow Tabebuia	11-15"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 23RD ST	Yellow Tabebuia	11-15"	No	15'	Utility Lines Above	Fair (41% to 60%)	Codominant Leaders/Included Bark	Limb Damage - Moderate	Stubs with Sprouts
SW 23RD ST	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Improperly Mulched	Crown Density - Low	Apical Dieback
SW 23RD ST	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Improperly Mulched	Crown Density - Low	Apical Dieback
SW 23RD ST	Bottlebrush	11-15"	Yes	10'	Utility Line Conflict	Good (61% to 80%)	Grafted Branches	Epicormic Growth	Pruned Into Shrub
SW 23RD ST	Bottlebrush	21-30"	Yes	10'	Utility Line Conflict	Good (61% to 80%)	Grafted Branches	Epicormic Growth	Pruned Into Shrub
SW 23RD ST	Bottlebrush	16-20"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Epicormic Growth	Pruned Into Shrub
SW 23RD ST	Sea Island Cotton	1-5"	Yes	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Seasonal Defoliation/Discolored Foliage	Epicormic Growth
SW 23RD ST	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 23RD ST	Coconut Palm	6-10"	No	20'	Utility Lines Above	Fair (41% to 60%)	Tapered Trunk	Over Pruned	Nutrient Deficiency
SW 23RD ST	Coconut Palm	11-15"	No	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency	Damaged Fronds	
SW 23RD ST	Frangipani	1-5"	No	5'	Utility Lines Above	Very Poor/Critical (6% to 20%)	Improperly Mulched	Topped	Crown Density - Very Low
SW 23RD ST	Crepe Myrtle	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Epicormic Growth	Pruned Into Shrub
SW 23RD ST	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 23RD ST	Yellow Tabebuia	16-20"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Apical Dieback	Stubs with Sprouts	Broken Branches
SW 23RD ST	Yellow Tabebuia	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Leader - Bent	Sprouting	Broken Branches
SW 23RD ST	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Crown Density - Low	Apical Dieback	Desiccated Foliage
SW 23RD ST	Fiddle Leaf Fig	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Codominant Leaders/Included Bark	Insect Damage Leaves	Sprouting
SW 23RD ST	Frangipani	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 23RD ST	Coconut Palm	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 23RD ST	Mahogany	6-10"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 23RD ST	Starburst Clerodendron	6-10"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Grafted with Adjacent Tree	Dead Wood	Pruned Into Shrub
SW 23RD ST	Starburst Clerodendron	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Grafted with Adjacent Tree	Sprouting	Pruned Into Shrub
SW 23RD ST	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 23RD ST	Weeping Fig	21-30"	No	50'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Root Damage/Decay	Decay Observed	Epicormic Growth
SW 23RD ST	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	
SW 23RD ST	Mahogany	16-20"	No	40'		Poor (21% to 40%)	Root Damage/Decay	Decay Observed	Epicormic Growth
SW 23RD ST	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Root Damage/Decay		
SW 23RD ST	Queen Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 23RD ST	Jacaranda	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Root Damage/Decay	Crown Density - Low	Epicormic Growth
SW 23RD ST	Frangipani	1-5"	No	10'		Fair (41% to 60%)	Root Damage/Decay	Codominant Leaders/No Included Bark	
SW 23RD ST	Satin Leaf	1-5"	No	10'		Poor (21% to 40%)	Root Damage/Decay	Topped	Stubs with Sprouts
SW 23RD ST	Gumbo Limbo	6-10"	No	30'		Poor (21% to 40%)	Root Damage/Decay	Apical Dieback	Dead Wood
SW 23RD ST	Gumbo Limbo	6-10"	No	30'		Fair (41% to 60%)	Root Damage/Decay	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD ST	Pygmy Date Palm	1-5"	No	5'		Fair (41% to 60%)	Leaning - Major	Reduced Canopy - Moderate	Nutrient Deficiency
SW 23RD ST	Pygmy Date Palm	1-5"	No	5'		Good (61% to 80%)			
SW 23RD ST	Montgomery Palm	6-10"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD ST	Live Oak	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Adjacent Concrete Damage
SW 23RD ST	Yellow Tabebuia	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 23RD ST	Weeping Fig	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Pruned Into Shrub	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 23rd Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD ST	Vera Wood	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 23RD ST	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD ST	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD ST	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Codominant Leaders/No Included Bark	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD ST	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Grafted with Adjacent Tree	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD ST	Mahogany	6-10"	No	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Grafted Branches
SW 23RD ST	Royal Poinciana	16-20"	No	60'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Sprouting
SW 23RD ST	Vera Wood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	Sprouting
SW 23RD ST	Vera Wood	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Sprouting
SW 23RD ST	Mahogany	21-30"	No	65'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Dead Wood
SW 23RD ST	Mahogany	21-30"	No	60'	Utility Line Conflict	Poor (21% to 40%)	Utility Pruned	Limb Damage - Major	Crown Density - Excessive (Due to Epicormic Growth)
SW 23RD ST	Mahogany	21-30"	No	65'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 23RD ST	Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Restricted Canopy
SW 23RD ST	Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Sprouting	Restricted Canopy
SW 23RD ST	Crepe Myrtle	6-10"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Sprouting	Restricted Canopy
SW 23RD ST	Black Olive	31-40"	No	60'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Epicormic Growth
SW 23RD ST	Black Olive	31-40"	No	65'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 23RD ST	Live Oak	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Apical Dieback	Epicormic Growth	Crown Density - Low
SW 23RD ST	Gumbo Limbo	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 23RD ST	Gumbo Limbo	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 23RD ST	Gumbo Limbo	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Grafted Branches
SW 23RD ST	Gumbo Limbo	6-10"	Yes	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Grafted Branches
SW 23RD ST	Gumbo Limbo	1-5"	Yes	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Epicormic Growth	
SW 23RD ST	Gumbo Limbo	6-10"	Yes	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Epicormic Growth	Codominant Leaders/No Included Bark
SW 23RD ST	Royal Poinciana	21-30"	No	65'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 23RD ST	Royal Poinciana	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Crown Density - Low
SW 23RD ST	Mahogany	6-10"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Strap Constricting Tree
SW 23RD ST	Weeping Fig	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Pruned Into Shrub
SW 23RD ST	Weeping Fig	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Pruned Into Shrub
SW 23RD ST	Weeping Fig	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Pruned Into Shrub
SW 23RD ST	Weeping Fig	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Pruned Into Shrub
SW 23RD ST	Live Oak	16-20"	No	30'		Poor (21% to 40%)	Apical Dieback	Desiccated Foliage	Crown Density - Low

(Continued on Next Page)

Street Tree Inventory

SW 23rd Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD ST	Christmas Palm	16-20"	Yes	20'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 23RD ST	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 23RD ST	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy		
SW 23RD ST	Black Olive	41-50"	No	70'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 23RD ST	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark		
SW 23RD ST	Pink Tabebuia	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Crown Density - Low	Sprouting
SW 23RD ST	Live Oak	6-10"	No	25'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 23RD ST	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 23RD ST	Pink Tabebuia	16-20"	No	35'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Broken Branches	Epicormic Growth
SW 23RD ST	Royal Poinciana	31-40"	No	70'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 23RD ST	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 23RD ST	Mahogany	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth
SW 23RD ST	Mahogany	21-30"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/Included Bark
SW 23RD ST	Cabbage Palm	11-15"	No	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 23RD ST	Cabbage Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	Ficus Growing on Tree
SW 23RD ST	Cabbage Palm	16-20"	No	10'	Utility Lines Above	Good (61% to 80%)	Ficus Growing on Tree	Restricted Canopy	
SW 23RD ST	Royal Poinciana	21-30"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 23RD ST	Areca Palm	6-10"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 23RD ST	Starburst Clerodendron	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Topped	Stubs with Sprouts	Grafted Branches
SW 23RD ST	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD ST	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 23RD ST	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 23RD ST	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 23RD ST	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 23RD ST	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Apical Dieback	Crown Density - Low	Epicormic Growth
SW 23RD ST	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Improperly Mulched	Crown Density - Very Low	Apical Dieback
SW 23RD ST	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 23RD ST	Christmas Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 23RD ST	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 23RD ST	Christmas Palm	11-15"	Yes	20'	Utility Line Conflict	Good (61% to 80%)			
SW 23RD ST	Cabbage Palm	11-15"	No	10'	Utility Line Conflict	Good (61% to 80%)	Ficus Growing on Tree	Restricted Canopy	
SW 23RD ST	Pigeon Plum	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	
SW 23RD ST	Pigeon Plum	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	
SW 23RD ST	Royal Poinciana	16-20"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 23RD ST	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 23RD ST	Horseflesh Mahogany	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Codominant Leaders/No Included Bark	Apical Dieback	Epicormic Growth
SW 23RD ST	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 23RD ST	Black Olive	21-30"	No	55'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Cavities
SW 23RD ST	Black Olive	31-40"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Sprouting
SW 23RD ST	Live Oak	41-50"	No	75'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD ST	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD ST	Live Oak	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Apical Dieback	Epicormic Growth	Desiccated Foliage
SW 23RD ST	Live Oak	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Desiccated Foliage
SW 23RD ST	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 23RD ST	Live Oak	1-5"	No	5'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Desiccated Foliage

(Continued on Next Page)

Street Tree Inventory

SW 23rd Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD ST	Banana Tree	41-50"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 23RD ST	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 23RD ST	Spindle Palm	11-15"	No	10'		Good (61% to 80%)			
SW 23RD ST	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Strap Constricting Tree
SW 23RD ST	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 23RD ST	Black Olive	41-50"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 23RD ST	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 23RD ST	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 23RD ST	Live Oak	1-5"	No	5'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	Codominant Leaders/No Included Bark
SW 23RD ST	Christmas Palm	6-10"	Yes	15'		Good (61% to 80%)			
SW 23RD ST	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD ST	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD ST	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 23RD ST	Spindle Palm	11-15"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 23RD ST	Royal Poinciana	16-20"	No	40'		Poor (21% to 40%)	Trunk Damage - Major	Crown Density - Low	Dead Wood
SW 23RD ST	Hurricane Palm	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 23RD ST	Hurricane Palm	1-5"	No	10'		Good (61% to 80%)			
SW 23RD ST	Hurricane Palm	6-10"	No	10'		Good (61% to 80%)			
SW 23RD ST	Yellow Tabebuia	11-15"	No	20'		Poor (21% to 40%)	Plunged	Apical Dieback	Limb Damage - Moderate
SW 23RD ST	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		

SW 23rd Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD TER	Gumbo Limbo	21-30"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 23RD TER	Crepe Myrtle	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Grafted Branches	Sprouting
SW 23RD TER	Crepe Myrtle	1-5"	Yes	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Grafted Branches	Sprouting
SW 23RD TER	Dracaena sp.	6-10"	Yes	5'		Good (61% to 80%)	Sprouting		
SW 23RD TER	Pigeon Plum	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD TER	Live Oak	16-20"	No	45'		Poor (21% to 40%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 23RD TER	Desert Cassia	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Epicormic Growth
SW 23RD TER	Gumbo Limbo	11-15"	No	30'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Grafted Branches
SW 23RD TER	Crepe Myrtle	1-5"	Yes	5'		Fair (41% to 60%)	Basal Co-Dominant	Seasonal Defoliation/Discolored Foliage	Grafted Branches
SW 23RD TER	Crepe Myrtle	1-5"	Yes	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Crown Density - Low	Seasonal Defoliation/Discolored Foliage	Grafted Branches
SW 23RD TER	Peacock Flower	11-15"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Apical Dieback	Grafted Branches	Epicormic Growth
SW 23RD TER	Japanese Golden Rain Tree	16-20"	Yes	20'		Fair (41% to 60%)	Crown Density - Low	Grafted Branches	Sprouting
SW 23RD TER	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	Frizzled Fronds
SW 23RD TER	Coconut Palm	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency	Damaged Fronds	
SW 23RD TER	Pongam	11-15"	Yes	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Epicormic Growth
SW 23RD TER	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 23RD TER	Crepe Myrtle	6-10"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 23rd Terrace (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 23RD TER	Crepe Myrtle	6-10"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Grafted Branches
SW 23RD TER	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 23RD TER	Orange Geiger	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	Broken Branches
SW 23RD TER	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Trunk Damage - Minor
SW 23RD TER	Simpson's Stopper	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Strap Constricting Tree
SW 23RD TER	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Leader - Bent	Discolored Foliage
SW 23RD TER	Orange Geiger	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Improperly Mulched	Crown Density - Low	Insect Damage Leaves
SW 23RD TER	Silver Buttonwood	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Cracks in Trunk	Codominant Leaders/Included Bark	Epicormic Growth
SW 23RD TER	Simpson's Stopper	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD TER	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Limb Damage - Minor	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD TER	Orange Geiger	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	Stubs with Sprouts
SW 23RD TER	Silver Buttonwood	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD TER	Simpson's Stopper	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD TER	Silver Buttonwood	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 23RD TER	Orange Geiger	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Grafted Branches
SW 23RD TER	Vera Wood	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Limb Damage - Moderate	Crown Density - Moderate	Epicormic Growth
SW 23RD TER	Sylvester Date Palm	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Reduced Canopy - Moderate	Nutrient Deficiency	
SW 23RD TER	Dahoon Holly	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	
SW 23RD TER	Orange Geiger	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Strap Constricting Tree	
SW 23RD TER	Christmas Palm	6-10"	No	5'	Utility Line Conflict	Fair (41% to 60%)	Pencil Top	Reduced Canopy - Minor	
SW 23RD TER	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 23RD TER	Mahogany	31-40"	No	75'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts


Terraces



Looking West - SW 13th Avenue



Looking West - SW 1st Avenue



Looking East - SW 3rd Avenue



Looking East - SW 16th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 22nd Terrace	1	Roads	3	50	2475	No	No	Yes	2	City	Some	Few	5	Yes	Yes	Mostly on North	Segmented at 3rd Avenue, Traffic islands on both ends facing 3rd avenue. One-way Westbound on Eastern segment.

SW 22nd Terrace

TYPOLOGY B

Street Tree Inventory

SW 22nd Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND TER	Yellow Tabebuia	16-20"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Dead Wood
SW 22ND TER	Yellow Tabebuia	16-20"	No	25'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Codominant Leaders/No Included Bark
SW 22ND TER	Umbrella Tree	21-30"	Yes	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Limb Damage - Moderate	Grafted Branches	
SW 22ND TER	Mahogany	16-20"	No	40'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/Included Bark	Utility Pruned	Stubs with Sprouts
SW 22ND TER	Mahogany	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Stubs with Sprouts
SW 22ND TER	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 22ND TER	Pigeon Plum	1-5"	No	5'	Utility Line Conflict	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 22ND TER	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 22ND TER	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)			
SW 22ND TER	Christmas Palm	16-20"	Yes	20'	Utility Line Conflict	Good (61% to 80%)			
SW 22ND TER	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 22ND TER	Black Olive	16-20"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Trunk Damage - Minor
SW 22ND TER	Black Olive	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 22ND TER	Starburst Clerodendron	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Pruned Into Shrub	Sprouting	Grafted Branches
SW 22ND TER	Starburst Clerodendron	6-10"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Basal Co-Dominant	Pruned Into Shrub	Dead Wood
SW 22ND TER	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND TER	Horseflesh Mahogany	1-5"	No	10'	Utility Lines Above	Poor (21% to 40%)	Apical Dieback	Crown Density - Low	Codominant Leaders/Included Bark
SW 22ND TER	Pigeon Plum	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 22ND TER	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Codominant Leaders/No Included Bark
SW 22ND TER	Silver Buttonwood	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Epicormic Growth	Codominant Leaders/No Included Bark
SW 22ND TER	Royal Poinciana	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Decay Observed
SW 22ND TER	Hong Kong Orchid	6-10"	No	20'	Utility Lines Above	Fair (41% to 60%)	Leader - Broken	Stubs with Sprouts	Grafted Branches
SW 22ND TER	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Leader - Bent	Trunk Damage - Moderate	
SW 22ND TER	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Leader - Bent		
SW 22ND TER	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Leader - Bent	Trunk Damage - Minor	
SW 22ND TER	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Leader - Bent	Trunk Damage - Minor	
SW 22ND TER	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 22ND TER	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Adjacent (laterally)	Very Poor/Critical (6% to 20%)	Improperly Mulched	Crown Density - Very Low	Dead Wood
SW 22ND TER	Solitaire Palm	1-5"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 22ND TER	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 22ND TER	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 22ND TER	Vera Wood	1-5"	No	10'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Epicormic Growth
SW 22ND TER	Vera Wood	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Low
SW 22ND TER	Christmas Palm	6-10"	No	5'		Very Poor/Critical (6% to 20%)	Pencil Top	Nutrient Deficiency	Reduced Canopy - Major
SW 22ND TER	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 22ND TER	Desert Cassia	1-5"	No	10'		Poor (21% to 40%)	Plunged	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 22ND TER	Coconut Palm	6-10"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 22ND TER	Mahogany	31-40"	No	55'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lion's Tailing	Limb Damage - Major
SW 22ND TER	Mahogany	31-40"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Decay Observed
SW 22ND TER	Yellow Tabebuia	6-10"	No	20'		Fair (41% to 60%)	Crown Density - Low	Codominant Leaders/Included Bark	Epicormic Growth
SW 22ND TER	Pink Tabebuia	1-5"	No	10'		Fair (41% to 60%)	Insect Damage Leaves	Codominant Leaders/No Included Bark	Suppressed Canopy
SW 22ND TER	Black Olive	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Dead Wood
SW 22ND TER	Black Olive	11-15"	No	35'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Girdling Roots	Decay Observed	Stubs with Sprouts
SW 22ND TER	Mahogany	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Root Damage/Decay	Lopsided/Moderately Reduced Canopy	Limb Damage - Moderate
SW 22ND TER	Mahogany	21-30"	No	30'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Apical Dieback
SW 22ND TER	Mahogany	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 22ND TER	Pigeon Plum	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 22ND TER	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 22nd Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND TER	Mahogany	31-40"	No	45'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Discolored Foliage	Dead Wood
SW 22ND TER	Mahogany	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 22ND TER	Weeping Fig	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 22ND TER	Jacaranda	6-10"	No	25'		Poor (21% to 40%)	Crown Density - Very Low	Decay Observed	Stubs with Sprouts
SW 22ND TER	Weeping Fig	31-40"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 22ND TER	Royal Poinciana	21-30"	No	50'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 22ND TER	Bottlebrush	21-30"	No	35'		Poor (21% to 40%)	Trunk Damage - Major	Apical Dieback	Stubs with Sprouts
SW 22ND TER	Dahoon Holly	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 22ND TER	Black Olive	21-30"	No	35'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Decay Observed
SW 22ND TER	Black Olive	16-20"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Root Damage/Decay	Utility Pruned	Stubs with Sprouts
SW 22ND TER	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Root Damage/Decay	Topped	Stubs with Sprouts
SW 22ND TER	Royal Poinciana	16-20"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 22ND TER	Royal Poinciana	11-15"	No	30'	Utility Lines Above	Fair (41% to 60%)	Leader - Broken	Broken Branches	Stubs with Sprouts
SW 22ND TER	Royal Poinciana	11-15"	No	15'	Utility Lines Above	Poor (21% to 40%)	Leader - Broken	Decay Observed	Lopsided/Significantly Reduced Canopy
SW 22ND TER	Royal Poinciana	6-10"	No	5'	Utility Lines Above	Poor (21% to 40%)	Leader - Broken	Decay Observed	Reduced Canopy - Moderate
SW 22ND TER	Royal Poinciana	11-15"	No	20'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Lopsided/Moderately Reduced Canopy
SW 22ND TER	Royal Poinciana	16-20"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 22ND TER	Black Olive	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 22ND TER	Pigeon Plum	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/Included Bark	Limb Damage - Minor
SW 22ND TER	Mahogany	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 22ND TER	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Apical Dieback	Crown Density - Low	Codominant Leaders/No Included Bark
SW 22ND TER	Montgomery Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)			
SW 22ND TER	Solitaire Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Reduced Canopy - Moderate	Damaged Fronds	Nutrient Deficiency
SW 22ND TER	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)			
SW 22ND TER	Royal Poinciana	31-40"	No	65'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Utility Pruned	Stubs with Sprouts
SW 22ND TER	Horseflesh Mahogany	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Codominant Leaders/No Included Bark	Apical Dieback	Epicormic Growth
SW 22ND TER	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Epicormic Growth	Apical Dieback	Strap Constricting Tree
SW 22ND TER	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Apical Dieback	Epicormic Growth
SW 22ND TER	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 22ND TER	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 22ND TER	Live Oak	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Codominant Leaders/No Included Bark	Apical Dieback	Epicormic Growth
SW 22ND TER	Royal Poinciana	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 22ND TER	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Over Pruned		
SW 22ND TER	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Over Pruned		
SW 22ND TER	Coconut Palm	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Over Pruned	Nutrient Deficiency	
SW 22ND TER	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Over Pruned	Nutrient Deficiency	
SW 22ND TER	Areca Palm	16-20"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 22ND TER	Orange Geiger	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Grafted Branches	Trunk Damage - Minor
SW 22ND TER	Royal Poinciana	21-30"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Crown Density - Very Low	Decay Observed	Cavities
SW 22ND TER	Gumbo Limbo	11-15"	No	30'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 22ND TER	Gumbo Limbo	11-15"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 22ND TER	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 22ND TER	Mimosa/Silk Tree	21-30"	No	45'		Poor (21% to 40%)	Root Damage/Decay	Apical Dieback	Dead Wood
SW 22ND TER	Gumbo Limbo	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Epicormic Growth
SW 22ND TER	Mahogany	21-30"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts

(Continued on Next Page)


Street Tree Inventory

SW 22nd Terrace

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND TER	Weeping Fig	11-15"	No	40'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Stubs with Sprouts
SW 22ND TER	Gumbo Limbo	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Stubs with Sprouts
SW 22ND TER	Mahogany	6-10"	No	30'		Fair (41% to 60%)	Basal Co-Dominant with Adjacent Tree(s)	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 22ND TER	Strangler Fig	31-40"	No	50'		Fair (41% to 60%)	Constricted Roots	Sprouting	Grafted with Adjacent Tree
SW 22ND TER	Umbrella Tree	16-20"	No	25'		Fair (41% to 60%)	Basal Co-Dominant	Suppressed Canopy	Restricted Canopy
SW 22ND TER	Gumbo Limbo	1-5"	No	5'		Poor (21% to 40%)	Topped	Reduced Canopy - Moderate	Stubs with Sprouts
SW 22ND TER	Umbrella Tree	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Restricted Canopy	Lifting	
SW 22ND TER	Umbrella Tree	11-15"	No	15'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Sprouting
SW 22ND TER	Live Oak	1-5"	No	5'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 22ND TER	Live Oak	1-5"	No	5'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Low
SW 22ND TER	Spindle Palm	11-15"	No	Negligible	Utility Lines Adjacent (laterally)	Dead (0% to 5%)	Dead Meristem		
SW 22ND TER	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 22ND TER	Christmas Palm	1-5"	No	10'		Good (61% to 80%)			
SW 22ND TER	Black Olive	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 22ND TER	Black Olive	21-30"	No	40'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 22ND TER	Horseflesh Mahogany	1-5"	No	5'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Apical Dieback	Epicormic Growth
SW 22ND TER	Live Oak	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Desiccated Foliage
SW 22ND TER	Black Olive	11-15"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 22ND TER	Black Olive	60+"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Vine Cover - Heavy

(Continued on Next Page)

Bordering Streets



Looking Northeast - SW 3rd Avenue



Looking Northeast - SW 21st Road



Looking Southwest - SW 30th Road



Looking Southwest - SW 25th Road



Looking Northeast - SW 25th Road



Looking Northeast - SW 28th Road



Looking Southwest - SW 23rd Street



Looking Southwest - SW 19th Road

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 1st Avenue	1	Roads	3	50	7200	No	Some	No	2	City	Yes	Some	5	Southwest of 23rd Road	Yes	Mostly on NW	Avenue segmented at Viscaya MetroRail station on SW 32nd Road. Avenue comes to dead end and becomes one-way NE between 32 and 31st Road.

SW 1st Avenue

TYPOLOGY A and B

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/Included Bark	Epicormic Growth
SW 1ST AVE	Pink Tabebuia	1-5"	No	10'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Sprouting
SW 1ST AVE	Pink Tabebuia	21-30"	No	35'		Fair (41% to 60%)	Apical Dieback	Codominant Leaders/No Included Bark	Sprouting
SW 1ST AVE	Live Oak	6-10"	No	35'		Poor (21% to 40%)	Trunk Damage - Moderate	Limb Damage - Moderate	Crown Density - Excessive (Due to Epicormic Growth)
SW 1ST AVE	Pigeon Plum	1-5"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 1ST AVE	Pigeon Plum	1-5"	No	5'		Poor (21% to 40%)	Topped	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Pigeon Plum	6-10"	No	10'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Dead Wood
SW 1ST AVE	Fishtail Palm	21-30"	Yes	20'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Paurotis Palm	1-5"	No	5'		Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Paurotis Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Cabbage Palm	6-10"	No	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Ficus Growing on Tree
SW 1ST AVE	Mahogany	21-30"	No	35'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Epicormic Growth
SW 1ST AVE	Pigeon Plum	1-5"	No	5'		Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Suppressed Canopy
SW 1ST AVE	Montgomery Palm	11-15"	Yes	15'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	Suppressed Canopy
SW 1ST AVE	Jamaica Caper	1-5"	Yes	5'		Good (61% to 80%)	Sprouting	Grafted Branches	
SW 1ST AVE	Live Oak	1-5"	Yes	5'		Good (61% to 80%)	Sprouting	Grafted Branches	
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Sprouting	
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Suppressed Canopy	
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark		
SW 1ST AVE	Pigeon Plum	16-20"	Yes	20'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Insect Damage Leaves	Epicormic Growth
SW 1ST AVE	Pigeon Plum	21-30"	Yes	20'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Insect Damage Leaves	Epicormic Growth
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark		
SW 1ST AVE	Live Oak	1-5"	Yes	5'		Good (61% to 80%)	Grafted Branches		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Adjacent Light Pole	
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Adjacent Light Pole	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Live Oak	31-40"	No	70'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Restricted Canopy	
SW 1ST AVE	Live Oak	1-5"	Yes	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Restricted Canopy	Epicormic Growth
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Pigeon Plum	11-15"	No	25'		Poor (21% to 40%)	Basal Co-Dominant	Insect Damage Leaves	Dead Wood
SW 1ST AVE	Jamaica Caper	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Live Oak	6-10"	No	30'	Utility Lines Above	Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Adjacent Light Pole
SW 1ST AVE	Live Oak	1-5"	No	5'		Poor (21% to 40%)	Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Grafted Branches
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Pink Tabebuia	6-10"	No	30'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Dead Wood
SW 1ST AVE	Pink Tabebuia	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Discolored Foliage	Insect Damage Leaves	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Pink Tabebuia	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/Included Bark	Grafted Branches	Stubs with Sprouts
SW 1ST AVE	Pink Tabebuia	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Lopsided/Moderately Reduced Canopy	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	21-30"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	21-30"	No	55'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Limb Damage - Minor
SW 1ST AVE	Royal Poinciana	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Decay Observed
SW 1ST AVE	Royal Poinciana	16-20"	No	45'		Poor (21% to 40%)	Basal Co-Dominant	Crown Density - Low	Broken Branches
SW 1ST AVE	Royal Poinciana	16-20"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Cavities
SW 1ST AVE	Weeping Fig	16-20"	No	15'	Utility Lines Above	Poor (21% to 40%)	Topped	Crown Density - Low	Epicormic Growth
SW 1ST AVE	Jacaranda	6-10"	No	20'	Utility Lines Above	Poor (21% to 40%)	Leader - Broken	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Broken Branches	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Grafted Branches	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	Codominant Leaders/No Included Bark
SW 1ST AVE	Christmas Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Surinam Cherry	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)	Codominant Leaders/Included Bark
SW 1ST AVE	Weeping Fig	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Decay Observed	Restricted Canopy	Sprouting
SW 1ST AVE	Weeping Fig	21-30"	Yes	30'	Utility Lines Above	Fair (41% to 60%)	Discolored Foliage	Restricted Canopy	Dead Wood
SW 1ST AVE	Mahogany	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Grafted with Adjacent Tree	Restricted Canopy	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Mahogany	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Jacaranda	1-5"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Codominant Leaders/Included Bark
SW 1ST AVE	Jacaranda	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Leader - Broken	Epicormic Growth	
SW 1ST AVE	Dracaena sp.	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Grafted with Adjacent Tree	
SW 1ST AVE	Jacaranda	1-5"	No	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Leader - Broken	Epicormic Growth	
SW 1ST AVE	Dracaena sp.	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Grafted with Adjacent Tree	
SW 1ST AVE	Weeping Fig	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Topped	Restricted Canopy	Sprouting
SW 1ST AVE	Dracaena sp.	16-20"	Yes	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Grafted Branches	Pruned Into Shrub	Sprouting
SW 1ST AVE	Mahogany	1-5"	No	15'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lifting	Restricted Canopy	Suppressed Canopy
SW 1ST AVE	Mahogany	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Grafted with Adjacent Tree
SW 1ST AVE	Mahogany	6-10"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Vine Cover - Heavy	Restricted Canopy	Grafted with Adjacent Tree
SW 1ST AVE	Mahogany	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Stubs with Sprouts	Restricted Canopy	Grafted with Adjacent Tree
SW 1ST AVE	Mahogany	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Stubs with Sprouts	Restricted Canopy	Limb Damage - Moderate
SW 1ST AVE	Mahogany	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Epicormic Growth
SW 1ST AVE	Mahogany	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Epicormic Growth	Restricted Canopy	Grafted with Adjacent Tree
SW 1ST AVE	Weeping Fig	31-40"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Crown Density - Low	Restricted Canopy	Epicormic Growth
SW 1ST AVE	Gumbo Limbo	1-5"	No	20'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Lifting	Restricted Canopy	Basal Co-Dominant with Adjacent Tree(s)
SW 1ST AVE	Jacaranda	11-15"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Leader - Broken	Sprouting	Restricted Canopy
SW 1ST AVE	Weeping Fig	6-10"	No	Negligible	Utility Lines Above	Dead (0% to 5%)	Leader - Broken	Dead Wood	Sloughing Bark
SW 1ST AVE	Dracaena sp.	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Mango	1-5"	No	15'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Restricted Canopy
SW 1ST AVE	Gumbo Limbo	11-15"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Gumbo Limbo	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Crown Density - Low
SW 1ST AVE	Gumbo Limbo	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Adjacent Concrete Damage	Trunk Damage - Major	Ficus Growing on Tree
SW 1ST AVE	Coconut Palm	11-15"	No	20'	Utility Line Conflict	Good (61% to 80%)			

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	16-20"	Yes	20'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	16-20"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Damaged Fronds		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Damaged Fronds		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Good (61% to 80%)	Damaged Fronds		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Montgomery Palm	6-10"	Yes	15'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Insect Damage Leaves	
SW 1ST AVE	Montgomery Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Jacaranda	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Codominant Leaders/No Included Bark	Epicormic Growth	Crown Density - Low
SW 1ST AVE	Sapodilla	16-20"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Glaucous Cassia	6-10"	No	15'	Utility Lines Above	Poor (21% to 40%)	Uprooted - Mostly	Sloughing Bark	Topped
SW 1ST AVE	Weeping Fig	11-15"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Pruned Into Shrub
SW 1ST AVE	Weeping Fig	6-10"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Pruned Into Shrub
SW 1ST AVE	Coconut Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Over Pruned	Lopsided/Significantly Reduced Canopy	Nutrient Deficiency
SW 1ST AVE	Solitaire Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Solitaire Palm	6-10"	Yes	15'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Damaged Fronds	
SW 1ST AVE	Solitaire Palm	11-15"	Yes	20'	Utility Lines Above	Good (61% to 80%)	Damaged Fronds		
SW 1ST AVE	Solitaire Palm	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Damaged Fronds	Nutrient Deficiency	Restricted Canopy
SW 1ST AVE	Solitaire Palm	11-15"	Yes	15'	Utility Line Conflict	Fair (41% to 60%)	Damaged Fronds	Restricted Canopy	One Dead Trunk
SW 1ST AVE	Florida Thatch Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Florida Thatch Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Florida Thatch Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Florida Thatch Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Japanese Blueberry	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Topped	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Japanese Blueberry	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Green Buttonwood	6-10"	Yes	10'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 1ST AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Coconut Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Queen Crepe Myrtle	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Seasonal Defoliation/Discolored Foliage	Leader - Broken	Stubs with Sprouts
SW 1ST AVE	Cabbage Palm	31-40"	Yes	20'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	Ficus Growing on Tree
SW 1ST AVE	Cabbage Palm	16-20"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	
SW 1ST AVE	Cabbage Palm	16-20"	Yes	10'	Utility Line Conflict	Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	Damaged Fronds
SW 1ST AVE	Jacaranda	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Leader - Bent	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Jacaranda	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Leader - Bent	Vine Cover - Heavy
SW 1ST AVE	Mahogany	21-30"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Reduced Canopy - Major	Decay Observed	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Reduced Canopy - Moderate	Decay Observed	Topped
SW 1ST AVE	Black Olive	21-30"	No	30'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Trunk Damage - Major	Sloughing Bark	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Mahogany	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Limb Damage - Major	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Gumbo Limbo	11-15"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Utility Pruned	Stubs with Sprouts	Lopsided/Moderately Reduced Canopy
SW 1ST AVE	Horseflesh Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 1ST AVE	Horseflesh Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Broken Branches
SW 1ST AVE	Horseflesh Mahogany	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Girdling Roots	Trunk Damage - Moderate	Stubs with Sprouts
SW 1ST AVE	Yellow Tabebuia	11-15"	No	30'		Poor (21% to 40%)	Topped	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Horseflesh Mahogany	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Mahogany	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Stubs with Sprouts
SW 1ST AVE	Mahogany	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 1ST AVE	Mahogany	21-30"	No	50'		Fair (41% to 60%)	Girdling Roots	Dead Wood	Codominant Leaders/Included Bark
SW 1ST AVE	Mahogany	16-20"	No	30'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 1ST AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Trunk Damage - Minor
SW 1ST AVE	Crepe Myrtle	6-10"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Grafted Branches
SW 1ST AVE	Crepe Myrtle	6-10"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Grafted Branches
SW 1ST AVE	Crepe Myrtle	6-10"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 1ST AVE	Yellow Tabebuia	11-15"	No	20'		Poor (21% to 40%)	Plunged	Crown Density - Low	Stubs with Sprouts
SW 1ST AVE	Mahogany	16-20"	No	35'		Fair (41% to 60%)	Girdling Roots	Adjacent Asphalt Damage	Stubs with Sprouts
SW 1ST AVE	Mahogany	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 1ST AVE	Green Buttonwood	6-10"	No	20'		Good (61% to 80%)	Adjacent Asphalt Damage	Leader - Bent	Stubs with Sprouts
SW 1ST AVE	Green Buttonwood	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Yellow Tabebuia	6-10"	No	10'		Poor (21% to 40%)	Trunk Damage - Moderate	Topped	Galls
SW 1ST AVE	Green Buttonwood	6-10"	No	15'		Fair (41% to 60%)	Galls	Epicormic Growth	Broken Branches
SW 1ST AVE	Green Buttonwood	6-10"	No	10'		Poor (21% to 40%)	Girdling Roots	Galls	Apical Dieback
SW 1ST AVE	Green Buttonwood	6-10"	No	10'		Good (61% to 80%)	Trunk Damage - Minor	Epicormic Growth	Broken Branches
SW 1ST AVE	Brazilian Beauty Leaf	16-20"	No	35'		Poor (21% to 40%)	Limb Damage - Major	Apical Dieback	Decay Observed
SW 1ST AVE	Brazilian Beauty Leaf	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Broken Branches
SW 1ST AVE	Neem Tree	51-60"	No	50'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Decay Observed
SW 1ST AVE	Silk Floss Tree	1-5"	No	15'		Fair (41% to 60%)	Discolored Foliage	Epicormic Growth	Codominant Leaders/Included Bark
SW 1ST AVE	Pink Tabebuia	6-10"	No	15'		Poor (21% to 40%)	Sloughing Bark	Apical Dieback	Stubs with Sprouts
SW 1ST AVE	Pink Tabebuia	11-15"	No	20'		Poor (21% to 40%)	Trunk Damage - Moderate	Apical Dieback	Stubs with Sprouts
SW 1ST AVE	Mahogany	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 1ST AVE	Mahogany	11-15"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 1ST AVE	Mahogany	16-20"	No	25'		Poor (21% to 40%)	Constricted Roots	Discolored Foliage	Apical Dieback
SW 1ST AVE	Mahogany	6-10"	No	25'		Poor (21% to 40%)	Girdling Roots	Discolored Foliage	Apical Dieback
SW 1ST AVE	Mahogany	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Yellow Tabebuia	6-10"	No	15'		Poor (21% to 40%)	Discolored Foliage	Trunk Damage - Major	Limb Damage - Major
SW 1ST AVE	Mahogany	6-10"	No	10'		Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	Apical Dieback
SW 1ST AVE	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Girdling Roots	Dead Wood	Apical Dieback
SW 1ST AVE	Mahogany	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Basal Co-Dominant	Epicormic Growth
SW 1ST AVE	Mahogany	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Galls	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Dead Wood
SW 1ST AVE	Brazilian Beauty Leaf	11-15"	No	25'		Poor (21% to 40%)	Sloughing Bark	Apical Dieback	Epicormic Growth
SW 1ST AVE	Brazilian Beauty Leaf	11-15"	No	30'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Decay Observed
SW 1ST AVE	Live Oak	6-10"	No	30'		Poor (21% to 40%)	Apical Dieback	Crown Density - Low	Epicormic Growth
SW 1ST AVE	Live Oak	16-20"	No	45'		Poor (21% to 40%)	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 1ST AVE	Live Oak	11-15"	No	45'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Live Oak	11-15"	No	40'		Poor (21% to 40%)	Plunged	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 1ST AVE	Royal Poinciana	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Broken Branches
SW 1ST AVE	Royal Poinciana	11-15"	No	40'		Fair (41% to 60%)	Apical Dieback	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Live Oak	11-15"	No	35'		Poor (21% to 40%)	Lopsided/Moderately Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 1ST AVE	Live Oak	16-20"	No	50'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Live Oak	11-15"	No	40'		Poor (21% to 40%)	Lopsided/Moderately Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)	Restricted Canopy
SW 1ST AVE	Royal Poinciana	21-30"	No	60'		Good (61% to 80%)	Adjacent Asphalt Damage	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	Live Oak	11-15"	No	40'		Poor (21% to 40%)	Root Damage/Decay	Apical Dieback	Epicormic Growth
SW 1ST AVE	Live Oak	11-15"	No	35'		Poor (21% to 40%)	Crown Density - Excessive (Due to Epicormic Growth)	Apical Dieback	Codominant Leaders/No Included Bark
SW 1ST AVE	Horseflesh Mahogany	31-40"	No	55'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Trunk Damage - Major
SW 1ST AVE	Horseflesh Mahogany	21-30"	No	50'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Mahogany	31-40"	No	60'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Broken Branches
SW 1ST AVE	Mahogany	21-30"	No	55'		Good (61% to 80%)	Trunk Damage - Minor	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Mahogany	31-40"	No	55'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Mahogany	21-30"	No	45'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)			
SW 1ST AVE	Mahogany	21-30"	No	45'		Good (61% to 80%)	Adjacent Asphalt Damage	Epicormic Growth	Codominant Leaders/No Included Bark
SW 1ST AVE	Mahogany	16-20"	No	45'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Broken Branches
SW 1ST AVE	Mahogany	21-30"	No	45'		Fair (41% to 60%)	Girdling Roots	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Mahogany	21-30"	No	55'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Stubs with Sprouts	Limb Damage - Moderate
SW 1ST AVE	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Girdling Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	45'		Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Dead Wood
SW 1ST AVE	Yellow Poinciana	11-15"	No	35'		Fair (41% to 60%)	Limb Damage - Moderate	Stubs with Sprouts	Trunk Damage - Minor
SW 1ST AVE	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Trunk Damage - Moderate	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Gumbo Limbo	16-20"	No	40'		Good (61% to 80%)	Trunk Damage - Minor	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Mahogany	31-40"	No	55'		Fair (41% to 60%)	Trunk Damage - Moderate	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Mahogany	1-5"	No	10'		Poor (21% to 40%)	Girdling Roots	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Mahogany	21-30"	No	45'		Fair (41% to 60%)	Girdling Roots	Dead Wood	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	6-10"	No	10'	Utility Lines Above	Poor (21% to 40%)	Suppressed Canopy	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Decay Observed

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Gumbo Limbo	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Decay Observed	Dead Wood	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	1-5"	No	15'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	1-5"	No	20'	Utility Lines Above	Fair (41% to 60%)	Improperly Mulched	Lion's Tailing	Codominant Leaders/No Included Bark
SW 1ST AVE	Royal Poinciana	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Stubs
SW 1ST AVE	Royal Poinciana	1-5"	No	20'	Utility Lines Above	Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Leader - Bent
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Areca Palm	21-30"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Pigeon Plum	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Epicormic Growth
SW 1ST AVE	Christmas Palm	6-10"	Yes	15'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Mahogany	21-30"	No	40'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Decay Observed	Utility Pruned
SW 1ST AVE	Mahogany	21-30"	No	45'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Decay Observed	Utility Pruned
SW 1ST AVE	Java Bishopwood	11-15"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Grafted Branches	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Mahogany	31-40"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Washington Palm	6-10"	No	10'	Utility Lines Above	Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 1ST AVE	Mahogany	21-30"	No	15'	Utility Line Conflict	Very Poor/Critical (6% to 20%)	Constricted Roots	Decay Observed	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	25'	Utility Lines Above	Very Poor/Critical (6% to 20%)	Constricted Roots	Decay Observed	Lopsided/Reduced Canopy - Major
SW 1ST AVE	Royal Poinciana	21-30"	No	65'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 1ST AVE	Christmas Palm	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency	Suppressed Canopy	Restricted Canopy
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Line Conflict	Good (61% to 80%)	Damaged Fronds	Suppressed Canopy	Restricted Canopy
SW 1ST AVE	Areca Palm	16-20"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency	Suppressed Canopy	
SW 1ST AVE	Umbrella Tree	6-10"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Restricted Canopy
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Live Oak	31-40"	No	55'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Dead Wood	Utility Pruned
SW 1ST AVE	Australian Pine	1-5"	No	15'	Utility Line Conflict	Good (61% to 80%)			
SW 1ST AVE	Royal Poinciana	31-40"	No	70'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Broken Branches
SW 1ST AVE	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Gumbo Limbo	11-15"	No	30'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	21-30"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Lines Above	Poor (21% to 40%)	Girdling Roots	Tip Dieback	Epicormic Growth
SW 1ST AVE	Gumbo Limbo	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	16-20"	No	40'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Cracks in Trunk	Stubs with Sprouts
SW 1ST AVE	Maple Leaved Bayur	31-40"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Weeping Fig	31-40"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 1ST AVE	Gumbo Limbo	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Restricted Canopy	Sprouting
SW 1ST AVE	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Mahogany	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	15'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Cabbage Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Royal Poinciana	16-20"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/Included Bark	Suppressed Canopy
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Very Poor/Critical (6% to 20%)	Improperly Mulched	Crown Density - Very Low	Suppressed Canopy
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Dead (0% to 5%)	Improperly Mulched	Dead Wood	Suppressed Canopy
SW 1ST AVE	Royal Poinciana	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Broken Branches
SW 1ST AVE	Live Oak	6-10"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Low
SW 1ST AVE	Live Oak	6-10"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Lifting	Apical Dieback
SW 1ST AVE	Spanish Lime	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Coconut Palm	1-5"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Orange Geiger	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Stubs with Sprouts
SW 1ST AVE	Mango	1-5"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Insect Damage Leaves	Basal Co-Dominant
SW 1ST AVE	Mahogany	16-20"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Montgomery Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Trunk Damage - Major	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Montgomery Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Montgomery Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Trunk Damage - Moderate		
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Bottlebrush	11-15"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Topped	Stubs with Sprouts
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Grafted with Adjacent Tree
SW 1ST AVE	Silver Buttonwood	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Recumbent
SW 1ST AVE	Silver Buttonwood	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Recumbent
SW 1ST AVE	Pygmy Date Palm	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Pygmy Date Palm	6-10"	Yes	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Gumbo Limbo	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Gumbo Limbo	21-30"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Gumbo Limbo	11-15"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Black Olive	11-15"	No	20'	Utility Lines Above	Fair (41% to 60%)	Topped	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	21-30"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Lines Above	Poor (21% to 40%)	Girdling Roots	Tip Dieback	Epicormic Growth
SW 1ST AVE	Gumbo Limbo	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	16-20"	No	40'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Cracks in Trunk	Stubs with Sprouts
SW 1ST AVE	Maple Leaved Bayur	31-40"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Decay Observed

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Weeping Fig	31-40"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 1ST AVE	Gumbo Limbo	11-15"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Restricted Canopy	Sprouting
SW 1ST AVE	Coconut Palm	11-15"	No	20'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Mahogany	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	11-15"	No	15'	Utility Lines Above	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Cabbage Palm	11-15"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Royal Poinciana	16-20"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Live Oak	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/Included Bark	Suppressed Canopy
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Very Poor/Critical (6% to 20%)	Improperly Mulched	Crown Density - Very Low	Suppressed Canopy
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Dead (0% to 5%)	Improperly Mulched	Dead Wood	Suppressed Canopy
SW 1ST AVE	Royal Poinciana	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Broken Branches
SW 1ST AVE	Live Oak	6-10"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Low
SW 1ST AVE	Live Oak	6-10"	No	15'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Lifting	Apical Dieback
SW 1ST AVE	Spanish Lime	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Coconut Palm	1-5"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Orange Geiger	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	Stubs with Sprouts
SW 1ST AVE	Mango	1-5"	No	10'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Improperly Mulched	Insect Damage Leaves	Basal Co-Dominant
SW 1ST AVE	Mahogany	16-20"	No	25'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Girdling Roots	Lopsided/Significantly Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Montgomery Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Trunk Damage - Major	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Montgomery Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Montgomery Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Trunk Damage - Moderate		
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Bottlebrush	11-15"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Trunk Damage - Major	Topped	Stubs with Sprouts
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Grafted with Adjacent Tree
SW 1ST AVE	Silver Buttonwood	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Recumbent
SW 1ST AVE	Silver Buttonwood	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	Recumbent
SW 1ST AVE	Pygmy Date Palm	11-15"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Pygmy Date Palm	6-10"	Yes	5'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Gumbo Limbo	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Gumbo Limbo	21-30"	No	30'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Gumbo Limbo	11-15"	No	20'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Lopsided/Significantly Reduced Canopy

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Black Olive	11-15"	No	20'	Utility Lines Above	Fair (41% to 60%)	Topped	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	Black Olive	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Black Olive	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts
SW 1ST AVE	Black Olive	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Black Olive	11-15"	No	25'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Lateral Branching - None
SW 1ST AVE	Black Olive	16-20"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 1ST AVE	Black Olive	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 1ST AVE	Mango	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Codominant Leaders/No Included Bark
SW 1ST AVE	Mango	1-5"	Yes	10'		Fair (41% to 60%)	Topped	Suppressed Canopy	Stubs with Sprouts
SW 1ST AVE	Mango	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Suppressed Canopy	Broken Branches
SW 1ST AVE	White Geiger	1-5"	Yes	10'		Fair (41% to 60%)	Codominant Leaders/Included Bark	Topped	Stubs with Sprouts
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Trunk Damage - Minor	Suppressed Canopy	
SW 1ST AVE	Coconut Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Dracaena sp.	21-30"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)			
SW 1ST AVE	Montgomery Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Live Oak	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Suppressed Canopy		
SW 1ST AVE	Live Oak	21-30"	No	55'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 1ST AVE	Manila Tamarind	1-5"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Manila Tamarind	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy	Epicormic Growth	Codominant Leaders/No Included Bark
SW 1ST AVE	Mahogany	1-5"	No	15'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'		Fair (41% to 60%)	Apical Dieback	Epicormic Growth	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Live Oak	31-40"	No	60'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	White Frangipani	11-15"	Yes	20'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Seasonal Defoliation/Discolored Foliage
SW 1ST AVE	Cabbage Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Suppressed Canopy	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Manila Tamarind	6-10"	No	25'		Fair (41% to 60%)	Limb Damage - Moderate	Epicormic Growth	Grafted with Adjacent Tree
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Live Oak	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Epicormic Growth

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	
SW 1ST AVE	Mahogany	1-5"	Yes	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Leader - Bent	Restricted Canopy
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Restricted Canopy	
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Fair (41% to 60%)	Insect Damage Leaves	Restricted Canopy	
SW 1ST AVE	Live Oak	1-5"	No	5'		Good (61% to 80%)	Leaning - Moderate	Epicormic Growth	
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Stubs with Sprouts	
SW 1ST AVE	Mahogany	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/Included Bark	
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Codominant Leaders/No Included Bark	Sprouting
SW 1ST AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Solitaire Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Nutrient Deficiency
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Restricted Canopy	Suppressed Canopy
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Codominant Leaders/Included Bark	Restricted Canopy	Suppressed Canopy
SW 1ST AVE	Live Oak	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Epicormic Growth
SW 1ST AVE	Pigeon Plum	6-10"	No	15'		Poor (21% to 40%)	Decay Observed	Stubs with Sprouts	Topped
SW 1ST AVE	Washington Palm	6-10"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Montgomery Palm	6-10"	Yes	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Cabbage Palm	11-15"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	11-15"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Mahogany	31-40"	No	25'		Very Poor/Critical (6% to 20%)	Decay Observed	Sloughing Bark	Dead Wood
SW 1ST AVE	Coconut Palm	6-10"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Cabbage Palm	16-20"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	11-15"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Montgomery Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Montgomery Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Mahogany	21-30"	No	30'		Very Poor/Critical (6% to 20%)	Constricted Roots	Decay Observed	Dead Wood
SW 1ST AVE	Mahogany	31-40"	No	40'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 1ST AVE	Mahogany	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Dead Wood
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Christmas Palm	1-5"	Yes	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Jacaranda	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Basal Co-Dominant	Broken Branches	Apical Dieback
SW 1ST AVE	Jacaranda	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Apical Dieback
SW 1ST AVE	Gumbo Limbo	6-10"	No	10'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant with Adjacent Tree(s)	Apical Dieback
SW 1ST AVE	Gumbo Limbo	11-15"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant with Adjacent Tree(s)	Apical Dieback
SW 1ST AVE	Gumbo Limbo	6-10"	No	10'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Leader - Broken
SW 1ST AVE	Pigeon Plum	11-15"	Yes	10'	Utility Lines Above	Very Poor/Critical (6% to 20%)	Sloughing Bark	Decay Observed	Apical Dieback
SW 1ST AVE	Pigeon Plum	6-10"	Yes	10'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Grafted Branches	Apical Dieback
SW 1ST AVE	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	11-15"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Cabbage Palm	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Live Oak	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Restricted Canopy	Leader - Bent	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	Black Olive	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Broken Branches
SW 1ST AVE	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	16-20"	Yes	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Cabbage Palm	11-15"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Christmas Palm	6-10"	No	5'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 1ST AVE	Christmas Palm	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Live Oak	11-15"	No	25'	Utility Lines Above	Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Epicormic Growth
SW 1ST AVE	Banana Tree	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Banana Tree	21-30"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Live Oak	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 1ST AVE	Black Olive	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Brazilian Pepper	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Epicormic Growth	Basal Co-Dominant with Adjacent Tree(s)
SW 1ST AVE	Mahogany	16-20"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Mahogany	21-30"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Lopsided/Significantly Reduced Canopy
SW 1ST AVE	White Geiger	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	6-10"	No	5'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Cabbage Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Restricted Canopy	White Fly	
SW 1ST AVE	Mahogany	21-30"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Limb Damage - Major
SW 1ST AVE	Mahogany	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	21-30"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Pink Tabebuia	21-30"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Epicormic Growth
SW 1ST AVE	Pink Tabebuia	1-5"	No	5'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Stubs with Sprouts	
SW 1ST AVE	Pink Tabebuia	6-10"	Yes	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	Pink Tabebuia	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark		
SW 1ST AVE	Dracaena sp.	1-5"	Yes	5'	Utility Lines Above	Good (61% to 80%)	Broken Branches		
SW 1ST AVE	Yellow Poinciana	16-20"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Girdling Roots	Crown Density - Low	Epicormic Growth
SW 1ST AVE	Yellow Poinciana	11-15"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth
SW 1ST AVE	Indian Laurel Fig	31-40"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 1ST AVE	Royal Poinciana	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Dracaena sp.	6-10"	Yes	10'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Royal Poinciana	16-20"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 1ST AVE	Strangler Fig	31-40"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Restricted Canopy

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Mahogany	11-15"	No	25'	Utility Line Conflict	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	Broken Branches
SW 1ST AVE	Unidentified Dead Tree (Defoliated)	6-10"	No	10'		Dead (0% to 5%)	Dead Wood	Sloughing Bark	
SW 1ST AVE	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Codominant Leaders/No Included Bark
SW 1ST AVE	Gumbo Limbo	6-10"	No	15'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 1ST AVE	Gumbo Limbo	6-10"	No	10'		Fair (41% to 60%)	Constricted Roots	Cavities	Stubs with Sprouts
SW 1ST AVE	Royal Poinciana	21-30"	No	40'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Cabbage Palm	11-15"	No	10'	Utility Line Conflict	Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	Ficus Growing on Tree
SW 1ST AVE	Queen Palm	6-10"	No	20'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency	Frizzled Fronds	
SW 1ST AVE	Queen Palm	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Restricted Canopy	
SW 1ST AVE	Gumbo Limbo	21-30"	No	40'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Leader - Broken	Stubs with Sprouts
SW 1ST AVE	Live Oak	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Significantly Reduced Canopy	Crown Density - Excessive (Due to Epicormic Growth)
SW 1ST AVE	Live Oak	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Trunk Damage - Moderate	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Live Oak	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Leader - Bent	Epicormic Growth	Apical Dieback
SW 1ST AVE	Live Oak	6-10"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Apical Dieback
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Foxtail Palm	11-15"	Yes	20'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Foxtail Palm	6-10"	No	15'	Utility Lines Above	Good (61% to 80%)			
SW 1ST AVE	Gumbo Limbo	11-15"	No	30'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Dead Wood	Grafted Branches
SW 1ST AVE	Montgomery Palm	11-15"	Yes	20'		Good (61% to 80%)	Restricted Canopy		
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Grafted Branches	Epicormic Growth
SW 1ST AVE	Japanese Privet	6-10"	Yes	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Epicormic Growth	Pruned Into Shrub	
SW 1ST AVE	Hibiscus sp.	1-5"	No	10'		Fair (41% to 60%)	Basal Co-Dominant	Codominant Leaders/Included Bark	Pruned Into Shrub
SW 1ST AVE	Black Olive	21-30"	No	35'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Black Olive	21-30"	No	45'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Cavities
SW 1ST AVE	Mahogany	31-40"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Broken Branches	Dead Wood
SW 1ST AVE	Java Bishopwood	16-20"	No	30'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Trunk Damage - Minor
SW 1ST AVE	Paradise Tree	6-10"	No	10'		Fair (41% to 60%)	Girdling Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Mahogany	31-40"	No	45'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 1ST AVE	Mahogany	41-50"	No	50'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 1ST AVE	Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Grafted Branches
SW 1ST AVE	Mahogany	21-30"	No	10'		Fair (41% to 60%)	Constricted Roots	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/Included Bark
SW 1ST AVE	Pink Tabebuia	11-15"	No	15'		Fair (41% to 60%)	Trunk Damage - Moderate	Broken Branches	Epicormic Growth
SW 1ST AVE	Crepe Myrtle	11-15"	Yes	5'		Fair (41% to 60%)	Topped	Seasonal Defoliation/Discolored Foliage	Stubs with Sprouts
SW 1ST AVE	Crepe Myrtle	11-15"	Yes	5'		Fair (41% to 60%)	Topped	Seasonal Defoliation/Discolored Foliage	Epicormic Growth
SW 1ST AVE	Banyan	1-5"	No	10'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	White Fly	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)			
SW 1ST AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 1ST AVE	Yellow Tabebuia	11-15"	No	15'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Leader - Broken
SW 1ST AVE	Christmas Palm	6-10"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 1ST AVE	Solitaire Palm	6-10"	Yes	10'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Solitaire Palm	1-5"	No	Negligible		Dead (0% to 5%)	Dead Meristem		

(Continued on Next Page)

Street Tree Inventory

SW 1st Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 1ST AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 1ST AVE	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 1ST AVE	Cabbage Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 1ST AVE	Banyan	41-50"	No	40'		Fair (41% to 60%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Hibiscus sp.	11-15"	Yes	15'		Good (61% to 80%)	Grafted Branches	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Live Oak	11-15"	No	20'		Poor (21% to 40%)	Lopsided/Significantly Reduced Canopy	Reduced Canopy - Moderate	Epicormic Growth
SW 1ST AVE	Black Olive	31-40"	No	50'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Stubs with Sprouts
SW 1ST AVE	White Frangipani	1-5"	Yes	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Broken Branches	
SW 1ST AVE	White Frangipani	6-10"	No	15'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Dead Wood	Codominant Leaders/No Included Bark
SW 1ST AVE	Tree of Heaven	11-15"	No	20'		Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Suppressed Canopy
SW 1ST AVE	Camphor Tree	11-15"	No	20'		Poor (21% to 40%)	Basal Co-Dominant	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 1ST AVE	Spindle Palm	1-5"	No	5'		Poor (21% to 40%)	Nutrient Deficiency		
SW 1ST AVE	Spindle Palm	6-10"	No	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Spindle Palm	6-10"	No	5'		Poor (21% to 40%)	Nutrient Deficiency		
SW 1ST AVE	Spindle Palm	6-10"	No	5'		Fair (41% to 60%)	Nutrient Deficiency		
SW 1ST AVE	Christmas Palm	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 1ST AVE	Christmas Palm	11-15"	Yes	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 1ST AVE	Christmas Palm	1-5"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Suppressed Canopy	Restricted Canopy	
SW 1ST AVE	Weeping Fig	16-20"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Sprouting
SW 1ST AVE	Weeping Fig	21-30"	No	30'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 1ST AVE	Chinaberry	11-15"	Yes	20'		Fair (41% to 60%)	Apical Dieback	Dead Wood	Codominant Leaders/No Included Bark
SW 1ST AVE	Mahogany	16-20"	No	40'		Fair (41% to 60%)	Girdling Roots	Codominant Leaders/No Included Bark	Epicormic Growth
SW 1ST AVE	Canary Island Date Palm	41-50"	No	25'		Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	Vine Cover - Heavy
SW 1ST AVE	Canary Island Date Palm	21-30"	No	5'		Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	Strap Constricting Fronds
SW 1ST AVE	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Vine Cover - Heavy	
SW 1ST AVE	Queen Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 1ST AVE	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Damaged Fronds		
SW 1ST AVE	Coconut Palm	1-5"	No	5'		Good (61% to 80%)	Insect Damage Leaves		
SW 1ST AVE	Coconut Palm	1-5"	No	5'		Fair (41% to 60%)	Insect Damage Leaves		
SW 1ST AVE	Brazilian Beauty Leaf	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Sprouting	
SW 1ST AVE	Weeping Fig	6-10"	No	5'		Poor (21% to 40%)	Basal Co-Dominant	White Fly	Pruned Into Shrub
SW 1ST AVE	Gumbo Limbo	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 1ST AVE	Black Olive	21-30"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Topped	Stubs with Sprouts
SW 1ST AVE	Pigeon Plum	6-10"	No	10'		Fair (41% to 60%)	Topped	Stubs with Sprouts	Restricted Canopy
SW 1ST AVE	Solitaire Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	

Bordering Streets



Looking North - SW 1st Avenue




Looking North - SW 23rd Street



Looking North - SW 22nd Street



Looking North - SW 17th Street



Looking South - SW 23rd Street



Looking South - SW 22nd Street



Looking South - SW 17th Street



Looking South - SW 11th Street

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 17th Avenue	1	Roads	3	70	1700	Some	No	No	4	County	No	Few	0	Yes	Yes	Both Sides	Major road. Share the lane bike markings, both directions. New tree plantings in areas with median.
SW 12th Avenue	1	Roads	3	80	4200	No	No	Some	4	State	Yes	Yes	9	Yes	Yes	Mostly on West Side	Share the lane bike markings, both directions.

SW 17th Avenue

TYPOLOGY E and I

SW 12th Avenue

TYPOLOGY B and D

Street Tree Inventory

SW 17th Avenue

STREET_NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	CONDITION	OVERHEAD_UTILITY	OBSERVATION_1	OBSERVATION_2	OBSERVATION_3
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	5'	Good (61% to 80%)				
SW 17TH AVE	Pigeon Plum	1-5"	No	10'	Good (61% to 80%)				
SW 17TH AVE	Queen Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Apical Dieback		
SW 17TH AVE	Queen Crepe Myrtle	1-5"	No	10'	Fair (41% to 60%)		Apical Dieback		

SW 12th Avenue

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'	Utility Line Conflict	Good (61% to 80%)	Strap Constricting Tree		
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'	Utility Lines Above	Good (61% to 80%)			
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'	Utility Line Conflict	Good (61% to 80%)			
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'	Utility Line Conflict	Good (61% to 80%)			
SW 12TH AVE	Mahogany	21-30"	No	30'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 12TH AVE	Black Olive	16-20"	No	20'		Poor (21% to 40%)	Girdling Roots	Trunk Damage - Major	Stubs with Sprouts
SW 12TH AVE	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Vine Cover - Heavy	Stubs with Sprouts
SW 12TH AVE	Black Olive	21-30"	No	30'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 12TH AVE	Mahogany	31-40"	No	45'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Epicormic Growth
SW 12TH AVE	Mahogany	41-50"	No	55'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Decay Observed
SW 12TH AVE	Black Olive	21-30"	No	40'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 12TH AVE	Black Olive	21-30"	No	30'	Utility Lines Adjacent (laterally)	Fair (41% to 60%)	Constricted Roots	Dead Wood	Stubs with Sprouts
SW 12TH AVE	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Dead Wood
SW 12TH AVE	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 12TH AVE	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Dead Wood
SW 12TH AVE	Black Olive	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 12TH AVE	Black Olive	21-30"	No	30'		Fair (41% to 60%)	Decay Observed	Codominant Leaders - Multi	Stubs with Sprouts
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'		Good (61% to 80%)			
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'		Good (61% to 80%)			
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'		Good (61% to 80%)			
SW 12TH AVE	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Restricted Canopy		
SW 12TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	
SW 12TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 12TH AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy		
SW 12TH AVE	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Nutrient Deficiency	Damaged Fronds
SW 12TH AVE	Umbrella Tree	6-10"	No	5'		Fair (41% to 60%)	Basal Co-Dominant	Restricted Canopy	
SW 12TH AVE	Royal Poinciana	41-50"	No	60'		Fair (41% to 60%)	Constricted Roots	Ficus Growing on Tree	Dead Wood
SW 12TH AVE	Washington Palm	16-20"	No	10'		Good (61% to 80%)			
SW 12TH AVE	Washington Palm	16-20"	No	10'		Good (61% to 80%)			
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 12TH AVE	Silver Buttonwood	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 12TH AVE	Pygmy Date Palm	1-5"	No	10'		Good (61% to 80%)			
SW 12TH AVE	Mahogany	1-5"	No	10'		Fair (41% to 60%)	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark	Leader - Bent
SW 12TH AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 12TH AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	

(Continued on Next Page)

Street Tree Inventory

SW 12th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Sprouting	
SW 12TH AVE	Mahogany	6-10"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Leaning - Minor	Epicormic Growth
SW 12TH AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	Restricted Canopy
SW 12TH AVE	Christmas Palm	16-20"	Yes	10'		Good (61% to 80%)	Restricted Canopy		
SW 12TH AVE	Sylvester Date Palm	16-20"	No	15'		Good (61% to 80%)	Nutrient Deficiency		
SW 12TH AVE	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 12TH AVE	Royal Palm	11-15"	No	20'		Fair (41% to 60%)	Restricted Canopy	Nutrient Deficiency	Tapered Trunk
SW 12TH AVE	Royal Palm	11-15"	No	10'		Fair (41% to 60%)	Reduced Canopy - Moderate	Nutrient Deficiency	
SW 12TH AVE	Royal Palm	16-20"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 12TH AVE	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Restricted Canopy	Tapered Trunk	Nutrient Deficiency
SW 12TH AVE	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Restricted Canopy	Tapered Trunk	
SW 12TH AVE	Royal Palm	16-20"	No	20'		Fair (41% to 60%)	Restricted Canopy	Tapered Trunk	
SW 12TH AVE	Royal Palm	6-10"	No	5'		Poor (21% to 40%)	Nutrient Deficiency	Frizzled Fronds	Reduced Canopy - Moderate
SW 12TH AVE	Royal Poinciana	11-15"	No	15'		Fair (41% to 60%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 12TH AVE	Orange Geiger	1-5"	No	5'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 12TH AVE	Orange Geiger	1-5"	No	5'		Fair (41% to 60%)	Insect Damage Leaves	Codominant Leaders/No Included Bark	Strap Constricting Tree
SW 12TH AVE	Crepe Myrtle	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark
SW 12TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy	Plunged	
SW 12TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Restricted Canopy	Plunged	
SW 12TH AVE	Orange Geiger	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/Included Bark	Insect Damage Leaves
SW 12TH AVE	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 12TH AVE	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 12TH AVE	Christmas Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 12TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Leaning - Minor	
SW 12TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency		
SW 12TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			
SW 12TH AVE	Mahogany	6-10"	No	10'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 12TH AVE	Mahogany	1-5"	No	10'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 12TH AVE	Mango	1-5"	No	10'		Fair (41% to 60%)	Codominant Leaders/No Included Bark	Discolored Foliage	
SW 12TH AVE	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 12TH AVE	Coconut Palm	6-10"	No	15'		Good (61% to 80%)	Nutrient Deficiency	Over Pruned	
SW 12TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 12TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)			
SW 12TH AVE	Christmas Palm	1-5"	No	10'		Good (61% to 80%)	Trunk Damage - Minor	Nutrient Deficiency	
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'		Good (61% to 80%)			
SW 12TH AVE	Mahogany	6-10"	No	15'		Fair (41% to 60%)	Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 12TH AVE	Sylvester Date Palm	16-20"	No	15'		Good (61% to 80%)	Ficus Growing on Tree		
SW 12TH AVE	Mahogany	21-30"	No	20'		Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Reduced Canopy - Moderate
SW 12TH AVE	Black Olive	21-30"	No	40'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 12TH AVE	Live Oak	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Epicormic Growth	Codominant Leaders/No Included Bark

(Continued on Next Page)

Street Tree Inventory

SW 12th Avenue (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 12TH AVE	Live Oak	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Epicormic Growth	Codominant Leaders/No Included Bark
SW 12TH AVE	Christmas Palm	1-5"	No	5'		Poor (21% to 40%)	Basal Co-Dominant with Adjacent Tree(s)	Nutrient Deficiency	Reduced Canopy - Moderate
SW 12TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)			
SW 12TH AVE	Mahogany	6-10"	No	10'		Good (61% to 80%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 12TH AVE	Coconut Palm	6-10"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 12TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 12TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 12TH AVE	Coconut Palm	6-10"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	Damaged Fronds
SW 12TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 12TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 12TH AVE	Coconut Palm	11-15"	No	20'		Fair (41% to 60%)	Nutrient Deficiency	Over Pruned	
SW 12TH AVE	Coconut Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency		
SW 12TH AVE	Live Oak	6-10"	No	25'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Epicormic Growth
SW 12TH AVE	Live Oak	11-15"	No	20'		Poor (21% to 40%)	Crown Density - Low	Apical Dieback	Epicormic Growth
SW 12TH AVE	Live Oak	11-15"	No	30'		Fair (41% to 60%)	Constricted Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 12TH AVE	Live Oak	16-20"	No	35'	Utility Line Conflict	Fair (41% to 60%)	Girdling Roots	Epicormic Growth	Codominant Leaders/No Included Bark
SW 12TH AVE	Live Oak	11-15"	No	25'	Utility Line Conflict	Poor (21% to 40%)	Crown Density - Low	Epicormic Growth	Uprooted - Partially
SW 12TH AVE	Sylvester Date Palm	11-15"	No	15'		Good (61% to 80%)	Nutrient Deficiency		

Bordering Streets



Looking East - SW 12th Avenue




Looking East - SW 8th Avenue



Looking East - SW 17th Avenue



Looking East - SW 14th Avenue



Looking West - SW 8th Avenue



Looking West - SW 4th Avenue



Looking West - SW 14th Avenue



Looking West - SW 12th Avenue

Street Name	Area	Neighborhood	District	ROW Width	Length (ft)	Median	Parking One Side	Parking Both Sides	Lanes	Ownership	Street Trees	Street Palms	Swale (ft)	Curbs	Sidewalks	Overhead Utilities	Notes
SW 11th Street	1	Roads	3	50 / 60 E of 8ave	4500	No	No	Yes	2	City	Some	Few	6(Intermittent)	Intermittent	Yes	Mostly on North Side	Street slopes down significantly at 11th Avenue intersection. North side mainly consists of on-street parking for apartments, no swales.Valley gutters mostly along northside after 10th avenue.
SW 22nd Street	1	Roads	3	100	2500	Yes	No	Yes	4	State	Yes	Few	10(Intermittent)	Yes	Yes	No	Dense canopy from Banyans. Share the lane bike markings along both sides.

SW 11th Street

TYPOLOGY B and D

SW 22nd Street

TYPOLOGY I

Street Tree Inventory

SW 11th Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH ST	Yellow Tabebuia	16-20"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Sprouting
SW 11TH ST	Black Olive	16-20"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Sprouting
SW 11TH ST	Black Olive	21-30"	No	25'		Fair (41% to 60%)	Constricted Roots	Reduced Canopy - Moderate	Sprouting
SW 11TH ST	Yellow Tabebuia	16-20"	No	15'	Utility Lines Above	Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Sprouting	
SW 11TH ST	Areca Palm	21-30"	Yes	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 11TH ST	Weeping Fig	16-20"	No	20'		Poor (21% to 40%)	Constricted Roots	Reduced Canopy - Moderate	Trunk Damage - Major
SW 11TH ST	Weeping Fig	11-15"	No	20'		Fair (41% to 60%)	Restricted Canopy	Codominant Leaders/Included Bark	Dead Wood
SW 11TH ST	Weeping Fig	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Trunk Damage - Moderate	Decay Observed
SW 11TH ST	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 11TH ST	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 11TH ST	Mahogany	41-50"	No	60'		Very Poor/Critical (6% to 20%)	Constricted Roots	Trunk Damage - Major	Decay Observed
SW 11TH ST	Pigeon Plum	21-30"	No	15'		Poor (21% to 40%)	Basal Co-Dominant	Suppressed Canopy	
SW 11TH ST	Mahogany	41-50"	No	50'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Reduced Canopy - Moderate
SW 11TH ST	Mahogany	31-40"	No	35'		Very Poor/Critical (6% to 20%)	Trunk Damage - Major	Reduced Canopy - Major	Decay Observed
SW 11TH ST	Live Oak	31-40"	No	50'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 11TH ST	Christmas Palm	1-5"	No	5'		Good (61% to 80%)	Suppressed Canopy		
SW 11TH ST	Christmas Palm	1-5"	No	5'		Good (61% to 80%)			
SW 11TH ST	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 11TH ST	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 11TH ST	Christmas Palm	6-10"	No	10'		Good (61% to 80%)			
SW 11TH ST	Christmas Palm	6-10"	No	5'		Good (61% to 80%)			
SW 11TH ST	Yellow Poinciana	31-40"	No	55'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Major	Sprouting
SW 11TH ST	Yellow Tabebuia	11-15"	No	15'		Poor (21% to 40%)	Girdling Roots	Reduced Canopy - Major	Trunk Damage - Moderate
SW 11TH ST	Yellow Tabebuia	11-15"	No	15'		Poor (21% to 40%)	Constricted Roots	Leaning - Moderate	
SW 11TH ST	Yellow Tabebuia	21-30"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	Dead Wood
SW 11TH ST	Yellow Tabebuia	16-20"	No	25'		Poor (21% to 40%)	Trunk Damage - Major	Reduced Canopy - Moderate	Decay Observed
SW 11TH ST	Yellow Tabebuia	16-20"	No	20'		Very Poor/Critical (6% to 20%)	Trunk Damage - Major	Decay Observed	
SW 11TH ST	Yellow Tabebuia	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	
SW 11TH ST	Japanese Golden Rain Tree	21-30"	No	35'		Fair (41% to 60%)	Root Damage/Decay	Codominant Leaders/No Included Bark	Dead Wood
SW 11TH ST	Japanese Golden Rain Tree	16-20"	No	30'		Fair (41% to 60%)	Reduced Canopy - Moderate	Stubs with Sprouts	
SW 11TH ST	Japanese Golden Rain Tree	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 11TH ST	Tropical Almond	6-10"	No	15'		Good (61% to 80%)			
SW 11TH ST	Royal Poinciana	1-5"	No	10'		Poor (21% to 40%)	Reduced Canopy - Moderate	Codominant Leaders/No Included Bark	
SW 11TH ST	Royal Poinciana	1-5"	No	5'		Poor (21% to 40%)	Reduced Canopy - Major		
SW 11TH ST	Royal Poinciana	1-5"	No	5'		Poor (21% to 40%)	Reduced Canopy - Major	Crown Density - Very Low	
SW 11TH ST	Royal Poinciana	1-5"	No	10'		Fair (41% to 60%)	Lopsided/Reduced Canopy - Moderate	Trunk Damage - Moderate	
SW 11TH ST	Avocado	1-5"	No	5'		Poor (21% to 40%)	Basal Co-Dominant	Fungus on Leaves	
SW 11TH ST	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 11TH ST	Coconut Palm	6-10"	No	15'		Fair (41% to 60%)	Nutrient Deficiency		
SW 11TH ST	Christmas Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 11TH ST	Live Oak	1-5"	No	5'		Good (61% to 80%)			
SW 11TH ST	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Crown Density - Moderate	Epicormic Growth	
SW 11TH ST	Live Oak	1-5"	No	10'		Fair (41% to 60%)	Codominant Leaders/Included Bark	Epicormic Growth	
SW 11TH ST	Montgomery Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 11TH ST	Montgomery Palm	6-10"	Yes	10'		Good (61% to 80%)			
SW 11TH ST	Montgomery Palm	1-5"	Yes	5'		Good (61% to 80%)			
SW 11TH ST	Royal Poinciana	16-20"	No	40'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	

(Continued on Next Page)

Street Tree Inventory

SW 11th Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 11TH ST	Starburst Clerodendron	1-5"	No	5'		Fair (41% to 60%)	Crown Density - Moderate		
SW 11TH ST	Starburst Clerodendron	1-5"	No	5'		Good (61% to 80%)			
SW 11TH ST	Mahogany	11-15"	No	25'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	
SW 11TH ST	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Codominant Leaders/No Included Bark
SW 11TH ST	Mahogany	11-15"	No	20'		Poor (21% to 40%)	Constricted Roots	Trunk Damage - Major	Restricted Canopy
SW 11TH ST	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 11TH ST	Mahogany	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Restricted Canopy	Codominant Leaders/Included Bark
SW 11TH ST	Coconut Palm	6-10"	No	15'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency		
SW 11TH ST	Cabbage Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Ficus Growing on Tree Ficus Growing on Tree		
SW 11TH ST	Black Olive	11-15"	No	20'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/No Included Bark	Dead Wood
SW 11TH ST	Live Oak	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Codominant Leaders/Included Bark	
SW 11TH ST	Cabbage Palm	21-30"	No	10'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)		
SW 11TH ST	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 11TH ST	Live Oak	1-5"	Yes	5'		Good (61% to 80%)	Basal Co-Dominant with Adjacent Tree(s)	Restricted Canopy	Suppressed Canopy
SW 11TH ST	Cabbage Palm	31-40"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Ficus Growing on Tree
SW 11TH ST	Black Olive	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Ficus Growing on Tree
SW 11TH ST	Black Olive	16-20"	No	35'		Poor (21% to 40%)	Girdling Roots	Decay Observed	Epicormic Growth
SW 11TH ST	Cabbage Palm	11-15"	No	5'		Good (61% to 80%)	Suppressed Canopy		

SW 22nd Street

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND ST	Mahogany	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 22ND ST	Mahogany	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 22ND ST	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Stubs with Sprouts
SW 22ND ST	Mahogany	21-30"	No	45'		Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Dead Wood
SW 22ND ST	Mahogany	21-30"	No	55'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Codominant Leaders/No Included Bark
SW 22ND ST	Live Oak	21-30"	No	50'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 22ND ST	Mango	1-5"	No	10'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	Codominant Leaders/No Included Bark
SW 22ND ST	Bottlebrush	16-20"	No	25'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 22ND ST	Live Oak	21-30"	No	40'		Poor (21% to 40%)	Constricted Roots	Crown Density - Low	Epicormic Growth
SW 22ND ST	Queen Palm	1-5"	No	5'		Good (61% to 80%)	Restricted Canopy	Suppressed Canopy	
SW 22ND ST	Gumbo Limbo	1-5"	No	5'		Good (61% to 80%)	Suppressed Canopy	Codominant Leaders/Included Bark	
SW 22ND ST	Florida Thatch Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND ST	Florida Thatch Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND ST	Royal Palm	16-20"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Nutrient Deficiency	Frizzled Fronds	Restricted Canopy
SW 22ND ST	Florida Thatch Palm	1-5"	No	5'		Good (61% to 80%)			
SW 22ND ST	Spindle Palm	11-15"	No	10'		Good (61% to 80%)			
SW 22ND ST	Spindle Palm	11-15"	No	10'		Good (61% to 80%)			
SW 22ND ST	Spindle Palm	16-20"	No	10'		Good (61% to 80%)			
SW 22ND ST	Queen Crepe Myrtle	6-10"	No	15'	Utility Line Conflict	Good (61% to 80%)	Seasonal Defoliation/Discolored Foliage	Codominant Leaders/No Included Bark	Stubs with Sprouts
SW 22ND ST	Spindle Palm	11-15"	No	10'		Fair (41% to 60%)	Nutrient Deficiency		

(Continued on Next Page)

Street Tree Inventory

SW 22nd Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND ST	Live Oak	11-15"	No	20'		Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Moderate	Epicormic Growth
SW 22ND ST	Live Oak	6-10"	No	25'		Fair (41% to 60%)	Crown Density - Low	Epicormic Growth	Codominant Leaders/No Included Bark
SW 22ND ST	Live Oak	6-10"	No	15'		Poor (21% to 40%)	Girdling Roots	Tip Dieback	Epicormic Growth
SW 22ND ST	Live Oak	11-15"	No	20'		Poor (21% to 40%)	Girdling Roots	Crown Density - Excessive (Due to Epicormic Growth)	Tip Dieback
SW 22ND ST	Live Oak	11-15"	No	15'		Poor (21% to 40%)	Constricted Roots	Epicormic Growth	Tip Dieback
SW 22ND ST	Royal Palm	11-15"	No	20'		Good (61% to 80%)	Restricted Canopy		
SW 22ND ST	Royal Palm	11-15"	No	20'		Good (61% to 80%)	Nutrient Deficiency	Suppressed Canopy	
SW 22ND ST	Live Oak	6-10"	No	10'		Very Poor/Critical (6% to 20%)	Crown Density - Very Low	Dead Wood	Improperly Mulched
SW 22ND ST	Live Oak	6-10"	No	10'		Poor (21% to 40%)	Improperly Mulched	Crown Density - Excessive (Due to Epicormic Growth)	Tip Dieback
SW 22ND ST	Coconut Palm	6-10"	No	25'	Utility Line Conflict	Good (61% to 80%)	Over Pruned	Restricted Canopy	
SW 22ND ST	Spindle Palm	11-15"	No	10'	Utility Line Conflict	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND ST	Spindle Palm	11-15"	No	10'	Utility Line Conflict	Fair (41% to 60%)	Tapered Trunk		
SW 22ND ST	Spindle Palm	11-15"	No	10'	Utility Line Conflict	Good (61% to 80%)			
SW 22ND ST	Hibiscus sp.	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Pruned Into Shrub
SW 22ND ST	Hibiscus sp.	1-5"	No	5'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Pruned Into Shrub
SW 22ND ST	Hibiscus sp.	1-5"	No	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Stubs with Sprouts	Pruned Into Shrub
SW 22ND ST	Hibiscus sp.	6-10"	Yes	10'	Utility Lines Above	Fair (41% to 60%)	Basal Co-Dominant	Sprouting	Pruned Into Shrub
SW 22ND ST	Live Oak	11-15"	No	25'	Utility Line Conflict	Fair (41% to 60%)	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark	Broken Branches
SW 22ND ST	Live Oak	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Topped	Tip Dieback	Epicormic Growth
SW 22ND ST	Live Oak	6-10"	No	20'	Utility Line Conflict	Fair (41% to 60%)	Plunged	Crown Density - Excessive (Due to Epicormic Growth)	Codominant Leaders/No Included Bark
SW 22ND ST	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)	Nutrient Deficiency		
SW 22ND ST	Spindle Palm	6-10"	No	10'	Utility Lines Above	Fair (41% to 60%)	Nutrient Deficiency		
SW 22ND ST	Spindle Palm	11-15"	No	10'	Utility Lines Above	Good (61% to 80%)			
SW 22ND ST	Gumbo Limbo	1-5"	No	10'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Stubs with Sprouts	
SW 22ND ST	Live Oak	21-30"	No	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Utility Pruned
SW 22ND ST	Pongam	16-20"	No	25'	Utility Lines Above	Poor (21% to 40%)	Constricted Roots	Basal Co-Dominant	Lopsided/Reduced Canopy - Major
SW 22ND ST	Pongam	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 22ND ST	Pongam	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 22ND ST	Pongam	16-20"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Tip Dieback	Stubs with Sprouts
SW 22ND ST	Live Oak	41-50"	Yes	65'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 22ND ST	Live Oak	11-15"	No	35'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lopsided/Reduced Canopy - Major	Stubs with Sprouts
SW 22ND ST	Live Oak	6-10"	No	20'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Lateral Branching - None	Stubs with Sprouts
SW 22ND ST	Live Oak	41-50"	Yes	50'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 22ND ST	Live Oak	6-10"	No	10'		Poor (21% to 40%)	Lopsided/Reduced Canopy - Major	Suppressed Canopy	Stubs with Sprouts
SW 22ND ST	Weeping Fig	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Trunk Damage - Minor	Codominant Leaders/No Included Bark	Pruned Into Shrub
SW 22ND ST	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Poor (21% to 40%)	Basal Co-Dominant	Topped	Stubs with Sprouts
SW 22ND ST	Gumbo Limbo	1-5"	No	5'	Utility Lines Above	Good (61% to 80%)	Codominant Leaders/No Included Bark	Epicormic Growth	
SW 22ND ST	Mahogany	21-30"	No	45'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Decay Observed	Tip Dieback
SW 22ND ST	Live Oak	31-40"	No	55'	Utility Line Conflict	Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Broken Branches
SW 22ND ST	Pygmy Date Palm	1-5"	No	5'	Utility Lines Adjacent (laterally)	Very Poor/Critical (6% to 20%)	Reduced Canopy - Major	Nutrient Deficiency	Frizzled Fronds
SW 22ND ST	Banyan	60+"	Yes	70'		Fair (41% to 60%)	Trunk Damage - Moderate	Broken Branches	Stubs with Sprouts
SW 22ND ST	Banyan	60+"	Yes	45'		Fair (41% to 60%)	Trunk Damage - Moderate	Decay Observed	Stubs with Sprouts
SW 22ND ST	Banyan	60+"	Yes	75'		Fair (41% to 60%)	Cavities	Decay Observed	Stubs with Sprouts
SW 22ND ST	Banyan	41-50"	No	50'		Fair (41% to 60%)	Limb Damage - Moderate	Broken Branches	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 22nd Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND ST	Banyan	60+"	No	70'		Poor (21% to 40%)	Cracks in Trunk	Decay Observed	Epicormic Growth
SW 22ND ST	Banyan	60+"	No	70'		Poor (21% to 40%)	Limb Damage - Major	Cavities	Stubs with Sprouts
SW 22ND ST	Banyan	60+"	No	65'	Utility Line Conflict	Poor (21% to 40%)	Decay Observed	Compromised Tension Roots	Discolored Foliage
SW 22ND ST	Banyan	60+"	No	80'		Poor (21% to 40%)	Root Damage/Decay	Limb Damage - Moderate	Stubs with Sprouts
SW 22ND ST	Banyan	60+"	No	85'		Fair (41% to 60%)	Galls	Cavities	Stubs with Sprouts
SW 22ND ST	Banyan	31-40"	No	40'		Fair (41% to 60%)	Limb Damage - Moderate	Cavities	Epicormic Growth
SW 22ND ST	Banyan	60+"	No	65'		Good (61% to 80%)	Codominant Leaders/No Included Bark	Broken Branches	Epicormic Growth
SW 22ND ST	Banyan	60+"	No	45'		Good (61% to 80%)	Limb Damage - Minor	Cavities	Epicormic Growth
SW 22ND ST	Banyan	60+"	Yes	50'		Poor (21% to 40%)	Decay Observed	Cavities	Limb Damage - Moderate
SW 22ND ST	Banyan	60+"	No	65'		Poor (21% to 40%)	Discolored Foliage	Crown Density - Excessive (Due to Epicormic Growth)	Broken Branches
SW 22ND ST	Banyan	60+"	No	65'	Utility Lines Adjacent (laterally)	Poor (21% to 40%)	Limb Damage - Major	Stubs with Sprouts	Broken Branches
SW 22ND ST	Banyan	51-60"	No	50'		Poor (21% to 40%)	Limb Damage - Major	Broken Branches	Cavities
SW 22ND ST	Banyan	60+"	Yes	85'		Poor (21% to 40%)	Decay Observed	Apical Dieback	Epicormic Growth
SW 22ND ST	Banyan	60+"	Yes	65'		Poor (21% to 40%)	Leader - Broken	Decay Observed	Apical Dieback
SW 22ND ST	Banyan	60+"	Yes	85'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Epicormic Growth
SW 22ND ST	Banyan	60+"	Yes	75'		Poor (21% to 40%)	Trunk Damage - Major	Grafted Branches	Epicormic Growth
SW 22ND ST	Banyan	60+"	Yes	45'		Poor (21% to 40%)	Decay Observed	Apical Dieback	Discolored Foliage
SW 22ND ST	Banyan	60+"	No	60'		Poor (21% to 40%)	Basal Co-Dominant	Limb Damage - Moderate	Epicormic Growth
SW 22ND ST	Banyan	60+"	No	65'		Poor (21% to 40%)	Apical Dieback	Decay Observed	Stubs with Sprouts
SW 22ND ST	Banyan	60+"	No	75'		Fair (41% to 60%)	Cavities	Decay Observed	Stubs with Sprouts
SW 22ND ST	Banyan	60+"	Yes	70'	Utility Line Conflict	Poor (21% to 40%)	Limb Damage - Major	Apical Dieback	Stubs with Sprouts
SW 22ND ST	Banyan	60+"	No	80'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 22ND ST	Banyan	60+"	No	80'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Cavities
SW 22ND ST	Banyan	60+"	No	80'	Utility Line Conflict	Poor (21% to 40%)	Constricted Roots	Apical Dieback	Crown Density - Excessive (Due to Epicormic Growth)
SW 22ND ST	Banyan	60+"	No	65'		Poor (21% to 40%)	Lion's Tailing	Broken Branches	Apical Dieback
SW 22ND ST	Banyan	60+"	No	75'		Fair (41% to 60%)	Decay Observed	Broken Branches	Stubs with Sprouts
SW 22ND ST	Banyan	60+"	No	75'		Poor (21% to 40%)	Crown Density - Excessive (Due to Epicormic Growth)	Discolored Foliage	Apical Dieback
SW 22ND ST	Banyan	60+"	No	75'		Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Epicormic Growth
SW 22ND ST	Banyan	60+"	No	90'		Fair (41% to 60%)	Decay Observed	Cavities	Epicormic Growth
SW 22ND ST	European Fan Palm	11-15"	Yes	10'		Good (61% to 80%)			
SW 22ND ST	Black Olive	16-20"	No	25'		Poor (21% to 40%)	Plunged	Discolored Foliage	Apical Dieback
SW 22ND ST	Black Olive	16-20"	No	45'		Fair (41% to 60%)	Constricted Roots	Grafted Branches	Stubs with Sprouts
SW 22ND ST	Black Olive	21-30"	No	45'		Fair (41% to 60%)	Constricted Roots	Limb Damage - Minor	Stubs with Sprouts
SW 22ND ST	Black Olive	16-20"	No	45'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 22ND ST	Black Olive	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Apical Dieback	Lopsided/Moderately Reduced Canopy
SW 22ND ST	Black Olive	11-15"	No	30'		Poor (21% to 40%)	Girdling Roots	Decay Observed	Stubs with Sprouts
SW 22ND ST	Black Olive	11-15"	No	35'		Fair (41% to 60%)	Constricted Roots	Trunk Damage - Minor	Stubs with Sprouts
SW 22ND ST	Black Olive	16-20"	No	50'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Stubs with Sprouts
SW 22ND ST	Black Olive	21-30"	No	45'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Dead Wood
SW 22ND ST	Black Olive	21-30"	No	60'		Fair (41% to 60%)	Constricted Roots	Stubs with Sprouts	Dead Wood
SW 22ND ST	Pigeon Plum	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 22ND ST	Pigeon Plum	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Epicormic Growth
SW 22ND ST	Pigeon Plum	1-5"	No	5'		Fair (41% to 60%)	Improperly Mulched	Codominant Leaders/No Included Bark	Leaning - Minor
SW 22ND ST	Gumbo Limbo	1-5"	No	10'		Poor (21% to 40%)	Improperly Mulched	Apical Dieback	Crown Density - Low
SW 22ND ST	Black Olive	21-30"	No	60'		Poor (21% to 40%)	Constricted Roots	Limb Damage - Moderate	Stubs with Sprouts

(Continued on Next Page)

Street Tree Inventory

SW 22nd Street (Continued)

STREET NAME	TREE_SPECIES	DBH_CLASS	MULTI_TRUNK	SPREAD	OVERHEAD_UTILITIES	CONDITION	OBSERVATION 1	OBSERVATION 2	OBSERVATION 3
SW 22ND ST	Weeping Fig	21-30"	No	45'		Poor (21% to 40%)	Trunk Damage - Major	Decay Observed	Epicormic Growth
SW 22ND ST	Black Olive	21-30"	No	55'		Poor (21% to 40%)	Constricted Roots	Leader - Broken	Stubs with Sprouts
SW 22ND ST	Black Olive	16-20"	No	35'		Fair (41% to 60%)	Constricted Roots	Broken Branches	Stubs with Sprouts
SW 22ND ST	Black Olive	16-20"	No	40'		Poor (21% to 40%)	Constricted Roots	Decay Observed	Stubs with Sprouts
SW 22ND ST	Black Olive	16-20"	No	35'		Poor (21% to 40%)	Constricted Roots	Lopsided/Moderately Reduced Canopy	Apical Dieback
SW 22ND ST	Black Olive	16-20"	No	45'		Fair (41% to 60%)	Constricted Roots	Dead Wood	Epicormic Growth
SW 22ND ST	Banyan	41-50"	No	70'		Poor (21% to 40%)	Basal Co-Dominant	Apical Dieback	Epicormic Growth
SW 22ND ST	Banyan	41-50"	No	75'		Poor (21% to 40%)	Basal Co-Dominant	Decay Observed	Broken Branches
SW 22ND ST	Cabbage Palm	16-20"	No	10'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Nutrient Deficiency	Ficus Growing on Tree	
SW 22ND ST	Weeping Fig	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)	Pruned Into Shrub	Codominant Leaders/Included Bark	Epicormic Growth
SW 22ND ST	Gumbo Limbo	1-5"	No	5'	Utility Lines Adjacent (laterally)	Good (61% to 80%)			